Available from National Technical Information Service Springfield, Virginia 22161

# of DOCUMENTS MADE PUBLICLY AVAILABLE

May 1 - 31, 1979

Division of Technical Information and Document Control
Office of Administration
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555



# CONTENTS

Preface v
Arrangement of Items by Docket Number ix
Arrangement of Docket 50 Items by Facility Name xviii
Docketed Items
Low Level Radwaste Disposal Sites - Docket 27 1
Domestic Licensing of Source Material - Docket 40 1
Domestic Licensing of Production and Utilization Facilities - Docket 50
Domestic Licensing of Special Nuclear Material - Docket 70
Packaging of Radioactive Material for Transport and Transportation of Radioactive Material Under Certain Conditions - Docket 71
Nondocketed Items
Personal Author Index
Corporate Source Index - By Corporate Types
Citizen Group/Individual/Media
Engineering/Construction/Consultants/Services
Educational Institutions 357
Foreign Governments and Agencies
Legal/Law Firms/Insurance Companies
Local Government and Agencies
Medical Institutions and Laboratories
Manufacturers/Equipment and Supplies
Professional/Industrial Institutions, Societies
State Governments and Agencies
U.S. Federal Government and Agencies
Utilities, Holding Companies, Investor Associations
Research Institutions and Laboratories
U.S. Nuclear Regulatory Commission Organizational Source Index 375
Report Number Index
Appendix A - Definitions of Docket 50 Categories

#### **PREFACE**

The Title List of Documents Made Publicly Available is a monthly publication. It contains descriptions o the information received and generated by the U.S. Nuclear Regulatory Commission (NRC). This informa tion includes (1) docketed material associated with civilian nuclear power plants and other uses of radioamaterials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulator agency. As used here, docketed does not refer to Court dockets; it refers to the system by which NRC maintains its regulatory records. This series of documents is indexed by a Personal Author Index, a Corpa Source Index, and a Report Number Index.

The dock eted information includes the information formerly issued through the Department of Energy's Technical Information Center under the title Power Reactor Docket Information (PRDI) and, in addition information received or generated on other uses of radioactive materials. The last issue of PRDI, publishe in January 1979, was an annual cumulation of the information for 1978. The Title List series initiated by this document replaces PRDI, which will no longer be prepared. Plans for providing microfiche of the docketed material will be announced in a future issue of the Title List and in other mailings and announcements.

We are making the monthly issues produced in 1979 available free to all who subscribed to PRDI in Caler Year 1978. We are doing this to encourage your comments, criticisms, and suggestions. In particular, if there are title descriptions that are not meaningful, please let us know so that we can correct the data bas In so far as possible, we would like this document to be a valuable part of your reference material. Near t end of 1979, subscriptions will be solicited for Calendar Year 1980 at a fee yet to be established.

#### DOCKETED ITEMS

Beginning with Vol. 1, No. 4, the listings within dockets are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories are:

- Application/construction stage documents and correspondence ۸.
- Utility Preliminary Safety Analysis Report (PSAR), amendments В.
- Utility Environmental Report (ER), amendments and correspondence C.
- NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence D,
- NRC Safety Evaluation Report (SER), supplements and correspondence E.
- Security, medical, emergency and fire-protection plans F.
- Adjudicatory correspondence G.
- General correspondence H.
- Financial information I.
- Insurance and indemnity information J.
- Utility Final Safety Analysis Report (FSAR) and amendments K.
- Limited work authorization and related correspondence L.
- Antitrust correspondence М.
- Antitrust hearing transcripts N.
- Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence 0.
- Operating license stage documents and correspondence Ρ.
- Inspection reports, IE Bulletins and correspondence Q.
- Periodic operating reports and related correspondence R.
- Reportable occurrences, LERs and related correspondence S.
- Hearing transcripts on non-antitrust matters Т.

Appendix A sets forth those categories and describes the materials available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the entries in the list are:


Operating license stage documents & correspondence 3 7904170015 Forwards info on TMI: JM Hendrie 790410 testimony, preliminary chronology of NRC actions, description of events & generic consideration of incident. REHM, T.A. Office of the Executive Director for Operations. 79/04/12.

- 1. NRC/PDR Document category (see Appendix A).
- 2. NRC Accession Number
- 3. Description of information contained in the document
- 4. Personal author. An asterisk in this position indicates that there is no personal author.
- 5. Corporate, agency or nonindividual source
- 6. Date of document described
- 7 Pages in document
- 8. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St, N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or "Available at GPO."

The Docketed Items list is arranged sequentially by Docket Number, category, and then by date of principal items. Entries indented and preceded by a dash are items that were submitted as enclosures to principal items. In general, indented items are not in accession number sequence. If the docketed document has a contract (FIN) number or a formal report number, it will appear in the last line of the item following entry 5.

#### NONDOCKETED ITEMS

The principal elements of the nondocketed items are:



- 1. NRC Accession Number
- 2. NRC Report Number
- 3. Title and description of information contained in the document
- 4. Personal author(s). An asterisk in this position indicates that there is no personal author
- 5. Corporate, agency or other nonindividual source
- 6. Contract or financial (FIN) number (if any). If the document has a secondary report number it will appear following this entry.
- 7. Date of document described
- 8. Pages in document
- 9. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or Available at

The Nondocketed Items list is arranged sequentially by Accession Number. Indented items preceded by

# NOTES:

1. The address for NTIS is:

National Technical Information Service Springfield, Virginia 22161

2. The address for GPO is:

Superintendent of Documents Government Printing Office Washington, D.C. 20402

# ARRANGEMENT OF ITEMS BY DOCKET NUMBER

Docket	Name	Page	Docket	Name	Page
27-039	Sheffield, IL., Nuclear Engineering Co., Inc.	1	40-8698	Plateau Resources, Ltd.	5
27-047		1	40-8714	Cleveland Cliffs Iron Co.	6
27*047	Barnwell, SC., Chem-Nuclear Systems, Inc.	1	40-8721	Rocky Mountain Energy Co.	6
40-0299	Union Carbide Corp.	1	40-8722	Brush-Wellman, Inc.	6
40-1162	Western Nuclear	2	50-2	Univ. of Michigan Research Reactor	6
40-2061	Kerr-McGee Corp., West Chicago Facility	2	50-3	Indian Point Station, Unit 1	6
40-2259	Pathfinder Mines Corp.	2	50-5	Pennsylvania State Univ. Research Reactor	7
40-2407	Fellows Medical Manufacturing Co., Inc.	2	50-6	Battelle Memorial Inst. Research Reactor	7
40-3392	Allied Chemical Corp.	3	50-8	North Carolina State Univ. Research Reactor	7
40-3453	Atlas Minerals	4	50-10	Dresden Nuclear Power Station,	7
40-4492	Federal American Partners	4	1	Unit 1	
40-4602	Morton Ranch Uranium Mill	4	50-12	Lynchburg Pool Reactor	9
40-6659	Petrotomics Co.	4	50-13	Babcock & Wilcox Co. Critical Facility	9
40-7086	Army, Dept. of	4	50-14	Battelle Memorial Inst. Critical	9
40-8027	Kerr-McGee Corp.	4	30-1-4	Facility	
40-8035	Cotter Corp.	4	50-16	Enrico Fermi Atomic Power Plant, Unit 1	9
40-8064	Exxon Minerals Co., USA	4	50-18	Vallecitos Boiling Water Reactor	9
40-8102	Exxon Minerals Co., USA, Exxon Corp.	4	50-20	Massachusetts Institute of	9
40-8158	Army, Dept. of, Communications & Electronics Material	4	0.0.20	Technology Research Reactor	•
40-8452	Bear Creek Mining Co.	4	50-22	Westinghouse Test Reactor	9
40-8502	Wyoming Mining Corp., Irigary	5	50-24	General Electric Co. Critical	9
	Mine	·	50-27		
40-8584	Union 76 Exploration Co.	5			
40-8602	United Nuclear Corp.	5	50-29		
40-8663	Nuclear Dynamics	5	50-30		
40-8681	Energy Fuels Nuclear	5	50-32		
40-8693	Ogle Petroleum, Inc.	5	50-37		
40-8697	Rocky Mountain Energy Co.	5	50-47		

Docket	Name	Page	Docket	Name	Page
50-53	Aerojet General Nucleonics	11	50-14	2 UCLA Training Reactor	16
50-54	Pawling Research Reactor	11	50-14		16
50-59	Texas A & M Univ. Research Reactor	11	50-14	Facility  7 Rockwell International Corp, Critical Facility	16
50-62	Univ. of Virginia Research Reactor	11	50-14	,	16
50-70	General Electric Test Reactor	12	50-150	Ohio State Univ. Research Reactor	16
50-72	Univ. of Utah Research Reactor	12	50-151	Univ. of Illinois Research Reactor	16
50-73	General Electric Nuclear Test Reactor	12	50-155		16
50-77	Catholic Univ. of America Research Reactor	12	50-156		17
50-83	Univ. of Florida Training Reactor	12	50-157	Cornell Univ. Research Reactor	10
50-84	Univ. of California Research Reactor	12	50-160	Georgia Institute of Technology Research Reactor	18 18
50-87	Westinghouse Critical Experiment	12	50-166		
50-89	General Atomic Co.	12		Univ. of Maryland Research Reactor	18
50-94	Rockwell International Research Reactor	12	50-170 50-171	National Naval Medical Center Peach Bottom Atomic Power	81 81
50-97	Cornell Univ. Zero Power Reactor	12	#0.400	Station, Unit 1	
50-99	Babcock & Wilcox Test Reactor	13	50-182	Purdue Univ. Research Reactor	18
50-103	Aerojet General Nucleonics	13	50-183	Vallecitos Experimental Superheat Reactor	18
50-106	Oregon State Univ.	13	50-184	National Bureau of Standards	16
50-111	North Carolina State Univ. Research Reactor	13	50-186	Reactor Univ. of Missouri Research Reactor	18
50-112	Univ. of Oklahoma Research Reactor	13	50-187	Space Radiation Research Reactor	18
50-113	Univ. of Arizona Research Reactor		50-188		18
50-116	Iowa State Univ. Research Reactor	13	50-191	Kansas State Univ. Research Reactor	18
50-123	Univ. of Missouri Research Reactor	13	00-131	Babcock & Wilcox Co. Critical Facility	19
50-124	Virginia Polytech Inst, Training	13	50-192	Univ. of Texas Research Reactor	19
	Vereful	14	50-193	Rhode Island & Providence Plants	
	Texas A & M Univ. Research Reactor	14	50-199	Manhattan College Research	19
	Texas A & M Univ. Research Reactor	14	50-200	Reactor  Babcock & Wilcox Test Reactor	19
	Omaha Veterans Administration Hospital Research Reactor	14,	50-201	West Valley Reprocessing Plant	19
	Humboldt Bay Power Plant, Unit 3	14	50-206	San Onofre Nuclear Station	19
	Worcester Polytech Inst. Research Reactor	16	50-208	Unit 1 Columbia Univ. Research Reactor	19
	Univ. of Washington Research			Haddam Nock Plant	21
		16			21
	Stanford Univ. Research Reactor	16	50-220	Oyster Creek Nuclear Power Plant	22
			•	Nine Mile Point Nuclear Station, Unit 1	24

Docket	Name	Page	Docket	Name	Page
50-223	Univ. of Lowell Research Reactor	25	50-267	Fort St. Vrain Nuclear Generating	50
50-224	Univ. of California Research Reactor	25	50.040	Station	
50-225	RPI Critical Experiment	25	50-269	Oconee Nuclear Station, Unit 1	52
50-227	TRIGA Thermionic Prototype Reactor	26	50-270	Осолее Nuclear Station, Unit 2	55
50-228	Aerotest Radiography & Research Reactor	26	50-271	Vermont Yankee Nuclear Power Station	57
50-233	Mexico Research Reactor	26	50-272	Salem Nuclear Generating Station, Unit 1	58
50-234	Tungsten Nuclear Rocket Critical Facility	26	50-273	Bernau Nuclear Station, Unit 1	61
50-235	Accelerator Pulsed Fast Assembly	26	50-274	U.S. Geological Survey Research Reactor	61
50-237	Dresden Nuclear Power Station, Unit 2	26	50-275	Diablo Canyon Nuclear Power Plant, Unit 1	61
50-240	High Temp. Gas Cooled Critical Experiment	28	50-276	Georgia Tech Research Reactor	64
50-241	Mississippi State Univ. Research Reactor	28	50-277	Peach Bottom Atomic Power Station, Unit 2	64
50-243	Oregon State Univ. Research Reactor	28	50-278	Peach Bottom Atomic Power Station, Unit 3	66
50-244	Robert Emmet Ginna Nuclear Plant, Unit 1	28	50-280	Surry Power Station, Unit 1	67
50-245	Millstone Nuclear Power Station,	29	50-281	Surry Power Station, Unit 2	70
	Unit 1		50-282	Prairie Island Nuclear Station, Unit 1	72
50-247	Indian Point Station, Unit 2	31	50-284	Idaho State Univ. Research Reactor	74
50-249	Dresden Nuclear Power Station, Unit 3	32	50-285	Fort Calhoun Station, Unit 1	74
50-250	Turkey Point Plant, Unit 3	34	50-286	Indian Point Station, Unit 3	76
50-251	Turkey Point Plant, Unit 4	36	50-287	Oconee Nuclear Station, Unit 3	77
50-252	Univ. of New Mexico Research Reactor	38	50-288	Reed College Research Reactor	80
50-254	Quad-Cities Station, Unit 1	38	50-289	Three Mile Island Nuclear Station, Unit 1	80
50-255	Palisades Nuclear Plant	39	50-293	Pilgrim Nuclear Power Station,	81
50-259	Browns Ferry Nuclear Power Station, Unit 1	41	50-294	Unit 1  Michigan State Univ. Research	82
50-260	Browns Ferry Nuclear Power Station, Unit 2	42		Reactor	
50-261	•	4.4	50-295	Zion Nuclear Power Station, Unit 1	82
50-262	H.B. Robinson Plant, Unit 2	44	50-296	Browns Ferry Nuclear Power Station, Unit 3	84
	Brigham Young Univ. Research Reactor	46	50-297	North Carolina State Univ. PULSTAR Reactor	85
50-263	Monticello Nuclear Generating Plant	46	50-298	Cooper Nuclear Station	86
50-264	Dow Chemical Co.	47	50-301	Point Beach Nuclear Plant,	87
50-265	Quad-Cities Station, Unit 2	48	, 30-301	Unit 2	01
50-266	Point Beach Nuclear Plant, Unit 1	49	50-302	Crystal River Nuclear Plant, Unit 3	88

	<b>V</b>	Page	Docket	Name	Page
{\$×\$≠#	Name Crystal River Nuclear Plant, Unit 4	91	50-338	North Anna Power Station, Unit 1	154
- F.1	Zin Nuclear Power Station, Unit 2	91	50-339	North Anna Power Station, Unit 2	158
F 36 11 16¶   ₹ 26 1 16¶	Kewaunce Nuclear Power Plant	93	50-341	Enrico Fermi Atomic Power Plant, Unit 2	160
د ساديخ	Praine Island Nuclear Station, Unit 2	94	50-344	Trojan Nuclear Plant, Unit 1	161
eras of	Maine Yankee Atomic Power Plant	95	50-346	Davis-Besse Nuclear Power Station, Unit 1	164
₹ £411	Salem Nuclear Generating Station, Unit 2	97	50-348	Joseph M. Farley Nuclear Plant, Unit 1	166
514 31 2	Rancho Seco Nuclear Generating Station	99	50-352	Limerick Generating Station, Unit 1	168
5 4313	Arkansas Nuclear One, Unit 1	100	50-353	Limerick Generating Station, Unit 2	168
518415	Donald C. Cook Nuclear Power	103	50-354	Hope Creek Nuclear Station, Unit 1	169
	Plant, Unit 1		50-355	Hope Creek Nuclear Station, Unit 2	169
59316	Donald C Cook Nuclear Power Plant, Unit 2	105	50-358	William H. Zimmer Nuclear Station, Unit 1	170
5++317	Calvert Cliffs Nuclear Power Plant, Unit 1	106	50-360	Battelle Memorial Inst. Critical	173
50-318	Calvert Cliffs Nuclear Power Plant, Unit 2	107	50-361	Facility San Onofre Nuclear Station, Unit 2	17,3
50-120	Three Mile Island Nuclear Station, Unit 2	108	50-362	San Onofre Nuclear Station, Unit 3	174
50-321	Edwin I. Hatch Nuclear Plant,	130	50-363	Forked River Nuclear Station, Unit 1	175
	Unit 1	100	50-364	Joseph M, Farley Nuclear Plant, Unit 2	176
50-322	Shoreham Nuclear Power Station	131	50-366		
5U-323	Diablo Canyon Nuclear Power Plant, Unit 2	133		Edwin H. Hatch Nuclear Plant, Unit 2	176
50-324	Brunswick Steam Electric Plant,	135	50-367	Bailly Generating Station	178
50-325	Unit 2		50-368	Arkansas Nucloar One, Unit 2	178
	Brunswick Steam Electric Plant, Unit 1	137	50-369	William B. MacGuire Nuclear Station, Unit 1	180
50-326	Univ. of California at Irvine Res. Reactor	139	50-370	William B. MacGuiro Nuclear	182
50-327	Sequoyah Nuclear Plant, Unit 1	139	80.000	Station, Unit 2	
50-328	Senunyah Nuclear Diane Trus. 2	141	50-373	LaSalle County Station, Unit 1	182
		149	50-374	LaSalle County Station, Unit 2	184
			50-375	Nuclear Examination Reactor	185
			50-376	North Coast Nuclear Plant (Puerto Rico)	185
			50-382	Waterford Generating Station, Unit 3	185
			50-387	Susquehanna Steam Electric Station, Unit 1	186
			50-388	Susquehanna Steam Electric Station, Unit 2	187
			50-389	St. Lucie Plant, Unit 2	188

Docket	Name	Page	Docket	Name	Page
50-390	Watts Bar Nuclear Plant, Unit 1	189	50-440	Perry Nuclear Power Plant, Unit 1	210
50-391	Watts Bar Nuclear Plant, Unit 2	191	50-441	Perry Nuclear Power Plant, Unit 2	211
50-394	California State Polytech College Research Reactor	192	50-443	Seabrook Nuclear Station, Unit 1	211
50-395	Virgil C. Summer Nuclear Station,	192	50-444	Seabrook Nuclear Station, Unit 2	212
	Unit 1		50-445	Comanche Peak Steam Electric Station, Unit 1	213
50-396	Univ. of Virginia Cavalier Reactor	193	50-446	Comanche Peak Steam Electric	216
50-397	WPPSS Nuclear Project, Unit 2	193	40	Station, Unit 2	210
50-400	Shearon Harris Nuclear Power Plant, Unit 1	194	STN-50-447	GESSAR-238	218
50-401	Shearon Harris Nuclear Power Plant, Unit 2	196	50-448	Douglas Point Nuclear Station, Unit 1	218
50-402	Shearon Harris Nuclear Power Plant, Unit 3	197	50-449	Douglas Point Nuclear Station, Unit 2	219
50-403	Shearon Harris Nuclear Power Plant, Unit 4	198	50-450	Summit Nuclear Power Station, Unit 1	219
50-404	North Anna Power Station, Unit 3	199	50-451	Summit Nuclear Power Station, Unit 2	219
50-405	North Anna Power Station, Unit 4	200	50-452	Greenwood Energy Center, Unit 2	219
50-406	Tuskegee Inst. Research Reactor	201	50-453	Greenwood Energy Center, Unit 3	219
50-407	Univ. of Utah Research Reactor	201	50-454	Byron Station, Unit 1	219
50-409	La Crosse Boiling Water Reactor	201	50-455	Byron Station, Unit 2	220
50-410	Nine Mile Point Nuclear Station, Unit 2	202	50-456	Braidwood Station, Unit 1	221
50-412	Beaver Valley Power Station,	203	50-457	Braidwood Station, Unit 2	222
55 112	Unit 2	200	50-458	River Bend Station, Unit 1	223
50-413	Catawba Nuclear Station, Unit 1	203	50-459	River Bend Station, Unit 2	224
50-414	Catawba Nuclear Station, Unit 2	204	50-460	WPPSS Nuclear Project, Unit 1	224
50-416	Grand Gulf Nuclear Station, Unit 1	204	50-461	Clinton Power Station, Unit 1	225
50-417	Grand Gulf Nuclear Station, Unit 2	205	50-462	Clinton Power Station, Unit 2	226
50-423	Millstone Nuclear Power Station, Unit 3	206	50-463	Fulton Generating Station, Unit 1	226
50-424	Alvin W. Vogtle Nuclear Plant, Unit 1	206	50-464	Fulton Generating Station, Unit 2	226
50-425	Alvin W. Vogtle Nuclear Plant, Unit 2	207	50-466	Allens Creek Nuclear Station, Unit 1	227
50-426	Alvin W, Vogtle Nuclear Plant, Unit 3	208	50-467	Allens Creek Nuclear Station, Unit 2	229
50-427	Alvin W. Vogtle Nuclear Plant, Unit 4	208	50-471	Pilgrim Nuclear Power Station, Unit 2	229
50-430	ASCO, Unit 1	208	50-472	Pilgrim Nuclear Power Station, Unit 3	230
50-433	UC-Santa Barbara Research Reactor	208	STN-50-477	Atlantic Generating Station, Unit 1	230
STN-50-437	Floating Nuclear Plant	208	STN-50-478	Atlantic Generating Station, Unit 2	230
50-438	Bellefonte Nuclear Plant, Unit 1	209	STN-50-482	Wolf Creek Generating Station	230
			STN-50-483	Calloway Plant, Unit 1	232
50-439	Bellefonte Nuclear Plant, Unit 2	210	STN-50-484	Tyrone Energy Park, Unit 1	232

Docket	Name	Page	Docket	Name	Page
STN-50-485	Sterling Power Project, Nuclear,	233	STN-50-530	Palo Verde Nuclear Station, Unit 3	258
STN-50-486	Unit 1	224	STN-50-531	GESSAR-251	258
STN-50-488	Calloway Plant, Unit 2	234	STN-50-532	BOP SAR	259
STN-50-489	Perkins Nuclear Station, Unit 1  Perkins Nuclear Station, Unit 2	234	50-537	Clinch River Breeder Reactor	259
STN-50-490	Perkins Nuclear Station, Unit 2	235 236	50-538	Memphis State Univ. Research	259
STN-50-491	Cherokee Nuclear Station, Unit 1	236	ሮሞእነ <u>ጀ</u> ብ <i>ይለር</i>	Reactor  Marble Hill Nuclear Station, Unit 1	2-2
STN-50-492	Cherokee Nuclear Station, Unit 2	237	STN-50-546 STN-50-547	• • •	259
STN-50-493	Cherokee Nuclear Station, Unit 3	238	50-548	Marble Hill Nuclear Station, Unit 2  Fort Calhoun Station, Unit 2	260
STN-50-495	SWESSAR-P1	239	50-549	r	261
STN-50-498	South Texas Project, Unit 1	239	STN-50-550	Greene County Nuclear Power Plant GESSAR-238-BOP Interface	261
STN-50-499	South Texas Project, Unit 2	241	STN-50-553	Phipps Bend Nuclear Plant, Unit 1	262
50-500	Davis-Besse Nuclear Power Station.	244	STN-50-554	,	262
50 500	Unit 2	244	STN-50-556	Phipps Bend Nuclear Plant, Unit 2  Black Fox Station, Unit 1	263
50-501	Davis-Besse Nuclear Power Station, Unit 3	245	STN-50-557	•	263
STN-50-502	Haven Nuclear Plant, Unit 1	245	50-564	Black Fox Station, Unit 2  Nuclear Fuels Recovery and	264
STN-50-503	Haven Nuclear Plant, Unit 2	246	J0-304	Recycle Center	266
STN-50-508	WPPSS Nuclear Project, Unit 3	246	STN-50-566	Yellow Creek Nuclear Plant, Unit 1	266
STN-50-509	WPPSS Nuclear Project, Unit 5		STN-50-567	Yellow Creek Nuclear Plant, Unit 2	266
50-510	Blue Hills Station, Unit 1	247 247	STN-50-568	NEP Nuclear, Unit 1	267
50-511	Blue Hills Station, Unit 2		STN-50-569	NEP Nuclear, Unit 2	267
50-513	WPPSS Nuclear Project, Unit 4	248	STN-50-574	Bagnac Nuclear Power Project	267
50-514	Pebble Springs Nuclear Plant, Unit 1	248	STN-50-580	Erie Nuclear Plant, Unit 1	267
50-51-5	Pebble Springs Nuclear Plant, Unit 2	249	STN-50-581	Erle Nuclear Plant, Unit 2	267
STN-50-516	Jamesport Nuclear Station, Unit 1	249	STN-50-584	GIBBSAR	268
OTN 60 517	Jamesport Nuclear Station, Unit 2	250	STN-50-592	Palo Verde Nuclear Station, Unit 4	268
-,	businesport ridolout diation, Oliff 2	250	STN-50-593	Palo Verde Nuclear Station, Unit 5	268
		251	50-596	New Haven, Unit 1	269
		251	50-597	New Haven, Unit 2	270
		252	50-598	Northwestern Univ.	271
		253 254	50-599	Carroll Facility I	271
		234	50-600	Carroll Facility II	271
		25 <i>5</i>	70-0008	Battelle Columbus Laboratories	272
		256	70-0025	Rockwell International Corp.	272
		256	70-0027	Babcock & Wilcox Co.	272
			70-0033	Texas Instruments, Inc.	272
		256 257	70-0102	Amherst College	272
		437		-	

Docket	Name	Page	Docket	Name	Page
70-0135	Babcock & Wilcox Co.	272	70-2838	Cincinnati Gas & Electric Co.	279
70-0143	Nuclear Fuel Services, Inc.	273	71-0001	ANEFCO, Inc.	279
70-0150	Purdue University	273	71-0002	Chem-Nuclear Systems, Inc.	279
70-0364	Parks Township Site, Babcock &	273	71-0006	United Nuclear Corp.	279
70-0371	Wilcox Co. United Nuclear Corp.	274	71-0008	Commonwealth Edison Co.	279
70-0371	General Atomic Co.	274	71-0024	Hittman Nuclear & Development Corp.	279
70-0754	Vallecitos Nuclear Center, General Electric Co.	274	71-0031	Maryland Shipbuilding & Dry Dock Co.	279
70-0820	United Nuclear Corp.	274	71-0033	Industrial Testing Laboratory	279
70-0824	Babcock & Wilcox Co.	275	m	Services Co.	
70-0984	Pacific Northwest Laboratory	275	71-0034	Babcock & Wilcox Co.	279
70-1007	General Electric Co.	275	71-0036	ITT Grinnell Corp.	279
70-1086	Westinghouse Electric Corp.	275	71-0038	Crane Co.	279
70-1100	Combustion Engineering, Inc.	275	71-0039	Walworth Co.	279
70-1113	General Electric Co.	275	71-0047	Capital International Airways, Inc.	280
70-1143	Westinghouse Electric Corp.	275	71-0048	Intermountain Pipe and Welding	280
70-1151	Westinghouse Electric Corp.	276	71-0050	Midland-Ross Corp.	280
70-1173	Mercyhurst College	276	71-0055	H.R. Inspection Service	280
70-1193	Cimarron Facility, Kerr-McGee Corp.	276	71-0056	Philadelphia Electric Co.	280
70-1201	UF6 Conversion Facility, Babcock &	276	71-0057	Exxon Co. U.S.A., Exxon Corp.	280
	Wilcox Co.		71-0063	Ozark Airlines, Inc.	280
70-1257	Mixed Oxide Fabrication Plant, Exxon Nuclear Co., Inc.	277	71-0065	H.P. & Associates, Inc.	280
70-1308	Morris Operations, General	277	71-0066	Certified Testing Laboratories, Inc.	280
	Electric Co.		71-0068	Yankee Atomic Electric	280
70-1309	Morris Operations, Sources & Standards, General	277	71-0070	General Motors Corp.	280
70-1318		277	71-0072	Babcock & Wilcox Co.	280
70-1319		277	71-0074	Nuclear Welding, Inc.	280
70-1355		278	71-0077	Midstate Testing Laboratory	280
70-1379		278	71-0087	Navy, Dept. of	280
70-1821		278	71-0088	Babcock & Wilcox Co.	280
, , , , , , ,	Allied General Nuclear Service Corp.		71-0089	Navy, Dept. of	280
70-2428		278	71-0090	Combustion Engineering Co., Inc.	280
70 2720	Pittsburgh, PA		71-0099	Foster Wheeler Energy Corp.	281
70-2623	McGuire Spent Fuel Pool, Duke Power Co.	278	71-0103	Twin City Testing & Engineering Laboratory	281
70-2753	Holyoke Hospital, Holyoke, MA	279	71-0104	Chicago Bridge & Iron Co.	281
70-2760	United Nuclear Corp.	279	71-0109	Union Carbide Corp.	281

Docket	Name	Page	Docket	Name	Page
71-0110	Buckeye Steel Castings	281	71-0209	Jacksonville Shipyards, Inc.	282
71-0111	Material Testing Laboratory of	281	71-0213	Intermountain Testing Co.	283
71.0116	Virginia, Inc.	281	71-0214	Gas Rentals, Inc.	283
71-0116	Navy, Dept. of	281	71-0215	Space Science Services	283
71-0119	Ingersoll-Rand Co.	281	71-0216	Nuclear Energy Services, Inc.	283
71-0120	Daniel International Corp.	281	71-0217	Pullman Kellogg, Inc.	283
71-0121 71-0126	Neutron Products, Inc.	281	71-0220	General Dynamics Corp.	283
	Stanwick Corp.	281	71-0222	St. Louis Testing Laboratories, Inc.	283
71-0127	National Annealing Box Co.	281	71-0223	B.F. Shaw, Inc.	283
71-0128	Amoco Oil Co.		71-0225	Navy, Dept. of	283
71-0130	Chicago Bridge & Iron Co.	281 281	71-0226	New York, State Univ. of	283
71-0131	Welding Institute of Alaska		71-0234	X-Ray, Inc.	283
71-0137	Metals Testing Co., Inc.	281	71-0235	Army, Dept. of	283
71-0141	Rockwell International	281	71-0238	Agriculture, Dept. of	283
71-0143	Ranchers Exploration and Development Co.	281	71-0239	Navy, Dept. of	283
71-0151	Hess Oil Virgin Islands Corp.	282	71-0241	United Nuclear Corp.	283
71-0154	General Dynamics	282	71-0251	Westinghouse Electric Corp.	283
71-0156	Industrial Fabricating Co.	282	71-0255	Walworth Co.	283
71-0158	X-Ray Industries, Inc.	282	71-0257	Industrial Laboratories, Inc.	283
71-0161	Curtiss-Wright Corp.	282	71-0260	Astrotech, Inc.	283
71-0162	Ebasco Services, Inc.	282	71-0261	Navy, Dept. of	283
71-0166	New York Testing Laboratories, Inc.	282	71-0266	Duke Power Co.	284
71-0167	Finlay Testing Laboratories	282	71-0268	Navy, Dept. of	284
<b>71-</b> 01 <b>68</b>	Quality Assurance Laboratories	282	71-0273	Navy, Dept. of	284
71-0169	Florida Power & Light Co.	282	71-0277	Allied Chemical Corp.	284
71-0174	Southern California Edison Co.	282	71-0280	ABCO Perforators, Inc.	284
71-0175	QC Services, Inc.	282	71-0282	WKM Wellhead Systems, Inc.	284
71-0178	Energy Products Group	282	71-0286	BPB Instruments, Inc.	284
71-0180	Hartford Steam Boiler Co.	282	71-0287	Carson Non-Destructive Testing	284
71-0181	Consolidated X-Ray Service Co.	282	71-0288	North Dakota State Water	284
71-0188	Maynard Steel Casting Co.	282	21 0000	Commission	
71-0189	Todd Shipyards Corp.	282	71-0290	United Testing Services, Inc.	284
71-0202	Pacific Gas & Electric Co.	282	71-0296	Iowa Electric Light & Phone Co.	284
71-0205	Quality Testing, Inc.	282	71-0297	E. Lewis Cook & Associates	284
71-0207	Connecticut Yankee Atomic Power	282	71-0299	Quality Control Services, Inc.	284
	<b>~U</b> ,		71-0300	Independent Testing Laboratories	284

Docket	Name	Page	Docket	Name	Page
71-0304	Teledyne Brown Engineering Co.	284	71-6697	Model: 8500 PKG, General Electric Co.	286
71-0305	American X-Ray & Inspection, Inc.	284	71-6698	Model: NFS-4, Nuclear Fuel	286
71-0307	Texas Pipe Bending Co. of Puerto Rico	284	/1-0096	Services, Inc.	200
71-0309	Worthington Pump Corp. (U.S.A.)	284	71-6744	Model: Poly Tiger, Nuclear Engineering Co.	287
71-0311	Logwell, Inc.	285	71-6771	Model: SN-1, Nuclear Engineering	287
71-0312	Metalforms, Inc.	285	71 0000	Co.	287
71-0317	Hudson Products Corp.	285	71-9009	Model: FL-10-1, General Electric Co.	407
71-0322	Control Components International	285	71-9010	Model: NLI-1/2, NL Industries, Inc.	287
71-4986	Model: RA-2, Exxon Nuclear Co., Inc.	285	71-9023	Model: NLI-10/24, NL Industries, Inc.	287
71-5026	Model: BC-48-220, Atcor, Inc.	285	71-9033	Model: 660 & 660E, Technical	287
71-5450	Model: RCC-1, -2, -3, Westinghouse Electric Corp.	285	71-9044	Operations, Inc.  Model: GE-1600, General Electric	287
71-5790	Model: A1-M3, Energy, Dept of	285	#1 00 <b>7</b> 0	Co.	207
71-5791	Model: A1-M6, Energy, Dept. of	285	71-9070	Model: N-55, Energy, Dept. of	287
71-5795	Model: None, Energy, Dept. of	285	71-9079	Model: HN-100 Series 2, Hittman Nuclear & Development Corp.	287
71-5805	Model: Atcor VNDB Cask, Atcor, Inc.	285	71-9080	Model: HN-600, Hittman Nuclear & Development Corp.	287
71-5908	Model: DOT-GM Type B, Babcock & Wilcox Co,	285	71-9086	Model: HN-100, Series 1, Hittman Nuclear & Development Corp.	287
71-5926	Model: 100, General Electric Co.	285	71-9089	Model: NH-100 S, Hittman Nuclear	287
71-5957	Model: BMI-1, Energy, Dept. of	285	<b>71 0000</b>	& Development Corp.	904
71-6058	Model: B3-1, Nuclear Engineering Co.	285	71-9090 71-9091	Model: 480M, Allied Chemical Corp.  Model: 30A, General Electric Co.	287 287
71-6144	Model: 6144, Nuclear Engineering	286	71-9092	Model: HN-300, Hittman Nuclear	288
71 0177	Co.	200	71-3032	& Development Corp.	200
71-6244	Model: 6244, Chem-Nuclear Systems, Inc.	286	71-9093	Model: HN-400 Hittman Nuclear & Development Corp.	288
71-6272	Model: Poly Panther, Nuclear Engineering Co.	286	71-9116	Model: CN6-80B, Nuclear Packaging, Inc.	288
71-6273	Model: 48X, F, A, Y, Allied-General Nuclear Services	286	71-9120	Model: TN-12, Transnuclear Corp.	288
71-6346	Model: FSV-1, General Atomic Co.	286	71-9132	Model: T-3, Nuclear Packaging, Inc.	288
71-6386	Model: 235R001, Energy, Dept. of	286	71-9506	Model: MS27684-2, Energy, Dept. of	288
71-6387	Model: 60, Battelle Memorial	286	71-9785	Model: SZW/SZWA, Energy, Dept. of	288
11 (00)	Institute	200	71-9852	Model: DT-14, Energy, Dept. of	288
71-6400	Model: Super Tiger, Westinghouse Electric Corp.	286			
71-6553	Model: Paducah Tiger, Energy, Dept. of	286			
71-6679	Model: 1/2 Super Tiger, Nuclear Engineering Co.	286			

# ALPHABETIC ARRANGEMENT OF DOCKET 50 ITEMS BY FACILITY NAME

Name	Docket	Page	Name	Docket	Page
Accelerator Pulsed Fast Assembly	50-235	26	Battelle Memorial Inst. Critical	50-360	173
Aerojet General Nucleonics	50-32	11	Facility		
Aerojet General Nucleonics	50-53	11	Battelle Memorial Inst. Research Reactor	50-6	7
Aerojet General Nucleonics	50-103	13	Beaver Valley Power Station, Unit 1	50-334	149
Aerotest Radiography & Research Reactor	50-228	26	Beaver Valley Power Station, Unit 2	50-412	203
Allens Creek Nuclear Station, Unit 1	50-466	227	Bellefonte Nuclear Plant, Unit 1	50-438	209
Allens Creek Nuclear Station, Unit 2	50-467	229	Beliefonte Nuclear Plant, Umt 2	50-439	210
Alvin W. Vogtle Nuclear Plant, Unit 1	50-424	206	Bernau Nuclear Station, Unit 1	50-273	61
Alvin W. Vogtle Nuclear Plant, Unit 2	50-425	207	Big Rock Point Nuclear Power Plant	50-155	16
Alvin W. Vogtle Nuclear Plant, Unit 3	50-426	208	Black Fox Station, Unit 1	STN-50-556	263
Alvin W. Vogtle Nuclear Plant, Unit 4	50-427	208	Black Fox Station, Unit 2	STN-50-557	264
Arkansas Nuclear One, Unit 1	50-313	100	Blue Hills Station, Unit 1	50-510	247
Arkansas Nuclear One, Unit 2	50-368	178	Blue Hills Station, Unit 2	50-511	248
Army Materials Research Reactor	50-47	11	BOP SAR, C.F. Braun	STN-50-532	259
ASCO, Unit 1	50-430	208	Braidwood Station, Unit 1	50-456	221
Atlantic Generating Station, Unit 1	STN-50-477	230	Braidwood Station, Unit 2	50-457	222
Atlantic Generating Station, Unit 2	STN-50-478	230	Brigham Young Univ. Research Reactor	50-262	46
Babcock & Wilcox Co. Critical Facility	50-13	9	Browns Ferry Nuclear Power Station, Unit 1	50-259	41
Babcock & Wilcox Co. Critical Facility	50-191	19	Browns Ferry Nuclear Power Station, Unit 2	50-260	42
Babcock & Wilcox Test Reactor	50-99	13	Browns Ferry Nuclear Power Station,	50-296	84
Babcock & Wilcox Test Reactor	50-200	19	Unit 3		
Bagnac Nuclear Power Project	STN-50-574	267	Brunswick Steam Electric Plant, Unit 2	50-324	135
Ballly Generating Station	50-367	178	Brunswick Steam Electric Plant, Unit 1	50-325	137
essing Plant	50-332	148	Byron Station, Unit 1	50-454	219
ı	50-524	256	Byron Station, Unit 2	50-455	220
	50-525	256	California State Polytech College Research Reactor	50-394	192
	50-14	9	Calloway Plant, Unit 1	STN-50-483	232

Name	Docket	Page	Name	Docket	Page
Calloway Plant, Unit 2	STN-50-486	234	Douglas Point Nuclear Station, Unit 2	50-449	219
Calvert Cliffs Nuclear Power Plant,	50-317	106	Dow Chemical Co.	50-264	47
Unit 1	EA 210	107	Dresden Nuclear Power Station, Unit 1	50-10	7
Calvert Cliffs Nuclear Power Plant, Unit 2	50-318	107	Dresden Nuclear Power Station, Unit 2	50-237	26
Carroll Facility I	50-599	271	Dresden Nuclear Power Station, Unit 3	50-249	32
Carroll Facility II	50-600	271	Duane Arnold Energy Center	50-331	146
Catawba Nuclear Station, Unit 1	50-413	203	Edwin I. Hatch Nuclear Plant, Unit 1	50-321	130
Catawba Nuclear Station, Unit 2	50-414	204	Edwin I. Hatch Nuclear Plant, Unit 2	50-366	176
Catholic Univ. of America Research Reactor	50-77	12	Enrico Fermi Atomic Power Plant, Unit-1-	50-16	9
Cherokee Nuclear Station, Unit 1	STN-50-491	236	Enrico Fermi Atomic Power Plant, Unit 2	50-341	160
Cherokee Nuclear Station, Unit 2	STN-50-492	237		STN-50-580	267
Cherokee Nuclear Station, Unit 3 a	STN-50-493	238	Eric Nuclear Plant, Unit 1		
Clinch River Breeder Reactor	50-537	259	Eric Nuclear Plant, Unit 2	STN-50-581	267
Clinton Power Station, Unit 1	50-461	225	Floating Nuclear Plant	STN-50-437	208
Clinton Power Station, Unit 2	50-462	226	Forked River Nuclear Station, Unit 1	50-363	175
Columbia Univ. Research Reactor	50-208	21	Fort Calhoun Station, Unit 1	50-285	74
Comanche Peak Steam Electric Station	n, 50-445	213	Fort Calhoun Station, Unit 2	50-548	261
Unit 1  Comanche Peak Steam Electric Station Unit 2	n, 50-446	216	Fort St. Vrain Nuclear Generating Station	50-267	50
Cooper Nuclear Station	50-298	86	Fulton Generating Station, Unit 1	50-463	226
Cornell Univ. Research Reactor	50-157	18	Fulton Generating Station, Unit 2	50-464	226
Cornell Univ. Zero Power Reactor	50-97	12	General Atomic Co.	50-89	12
Crystal River Nuclear Plant, Unit 3	50-302	88	General Electric Co. Critical Experiment	50-24	9
Crystal River Nuclear Plant, Unit 4	50-303	91	General Electric Test Reactor	50-70	12
Davis-Besse Nuclear Power Station,	50-346	164	General Electric Nuclear Test Reactor		
Unit 1	300.0		Georgia Institute of Technology		
Davis-Besse Nuclear Power Station, Unit 2	50-500	244	Research Reactor		
Davis-Besse Nuclear Power Station, Unit 3	50-501	245	Georgia Institute of Technology Research Reactor		
Diablo Canyon Nuclear Power Plant,	50-275	61	GESSAR-238	STI	
Unit 1	,		GESSAR-238-BOP Interface	STI	
Diablo Canyon Nuclear Power Plant, Unit 2	50-323	133	GESSAR-251		
Donald C. Cook Nuclear Power Plant.	50-315	103	GIBBSAR	STI	
Unit 1		-	Grand Gulf Nuclear Station, Unit 1		
Donald C. Cook Nuclear Power Plant Unit 2	50-316	105	Grand Gulf Nuclear Station, Unit 2  Greene County Nuclear Power Plant		
Douglas Point Nuclear Station, Unit	50-448	218	Official County Maciest Lower Light		

Nam o	Docket	Page	Name	Docket	Page
three award I nargy Center, Unit 2	50-452	219	Marble Hill Nuclear Station, Unit 2	STN-50-547	260
the enwood I norgy Center, Unit 3	50-453	219	Massachusetts Institute of Technology	50-20	9
Riti Robinson Plant, Umi 2	50-261	44	Research Reactor		***
Heldson Nock Plant	50-213	21	Memphis State Univ. Research Reacto	r 50-538	
Hartiville Nuclear Plant, Unit 1	STN-50-518	251	Mexico Research Reactor	50-233	26
Harrysille Nuclear Plant, Unit 2	STN-50-519	251	Michigan State Univ. Research Reactor	50-294	82
Harts-ille Nuclear Plant, Unit 3	STN-50-520	252	Midland Plant, Unit 1	50-329	142
Hartsville Nuclear Plant, Unit 4	STN-50-521	253	Midland Plant, Unit 2	50-330	144
Haven Nuclear Plant, Unit 1	STN-50-502	245	Millstone Nuclear Power Station,	50-245	29
Haven Nuclear Plant, Umt 2	STN-50-503	246	Unit 1	00 245	
High Temp. Gas Cooled Critical Experiment	50-240	28	Millstone Nuclear Power Station, Unit 2	50-336	153
Hope Creek Nuclear Station, Unit 1	50-354	169	Milistone Nuclear Power Station, Unit 3	50-423	206
Hope Creek Nuclear Station, Unit 2	50-355	169	Mississippi State Univ. Research	50-241	28
Humboldt Bay Power Plant, Unit 3	50-133	14	Reactor	30-241	2.13
ldaho State Univ. Research Reactor	50-284	74	Monticello Nuclear Generating Plant	50-263	46
Indian Point Station, Unit 1	50-3	6	National Bureau of Standards Reactor	50-184	18
Indian Point Station, Unit 2	50-247	31	National Naval Medical Center	50-170	18
Indian Point Station, Unit 3	50-286	76	NEP Nuclear, Unit 1	STN-50-568	267
-lowa State Univ. Research Reactor	50-116	13	NEP Nuclear, Unit 2	STN-50-569	267
James A. Fitzpatrick Nuclear Power	50-333	148	New Haven, Unit 1	50-596	269
famesport Nuclear Station, Unit 1	STN-50-516	250	New Haven, Unit 2	50-597	270
Jamesport Nuclear Station, Unit 2	STN-50-517	250	Nine Mile Point Nuclear Station, Unit 1	50-220	24
loseph M. Farley Nuclear Plant	50-348	250	Nine Mile Point Nuclear Station,		
unit (	JU-346	166	Unit 2	50-410	202
Joseph M. Farley Nuclear Plant, Unit 2	50-364	176	North Anna Power Station, Unit 1	50-338	154
-			North Anna Power Station, Unit 2	50-339	158
			North Anna Power Station, Unit 3	50-404	199
			North Anna Power Station, Unit 4	50-405	200
			North Carolina State Univ. PULSTAR Reactor	50-297	85
			North Carolina State Univ. Research Reactor	50-8	7
			volina State Univ. Research or	50-111	13
			ist Nuclear Plant (Puerto Rico)	50-376	185
			ern University	50-598	271
			kamination Reactor	50-375	185
			iels Recovery and Recycle	50-564	266
			•	007	AUU

Name	Docket	Page	Name	Docket	Page
Oconee Nuclear Station, Unit 1	50-269	52	Point Beach Nuclear Plant, Unit 2	50-301	87
Oconee Nuclear Station, Unit 2	50-270	55	Prairie Island Nuclear Station, Unit 1	50-282	72
Oconee Nuclear Station, Unit 3	50-287	77	Prairie Island Nuclear Station, Unit 2	50-306	94
Ohio State Univ. Research Reactor	50-150	16	Purdue Univ. Research Reactor	50-182	18
Omaha Veterans Administration Hospital Research Reactor	50-131	14	Quad-Cities Station, Unit 1	50-254	38
Oregon State Univ.	50-106	13	Quad-Cities Station, Unit 2	50-265	48
Oregon State Univ. Research Reactor	50-243	28	Rancho Seco Nuclear Generating Station	50-312	99
Oyster Creek Nuclear Power Plant	50-219	22	Reed College Research Reactor	50-288	80
Palisades Nuclear Plant	50-255	39	Rhode Island & Providence	50-193	19
Palo Verde Nuclear Station, Unit 1	STN-50-528	256	Plantations AEC	-0.140	222
Palo Verde Nuclear Station, Unit 2	STN-50-529	257	River Bend Station, Unit 1	50-458	223
Palo Verde Nuclear Station, Unit 3	STN-50-530	258	River Bend Station, Unit 2	50-459	224
Palo Verde Nuclear Station, Unit 4	STN-50-592	268 ,	Rockwell International Corp. Critical Facility	50-147	16
Palo Verde Nuclear Station, Unit 5	STN-50-593	268	Rockwell International Research Reactor	r 50-94	12
Pawling Research Reactor	50-54	11	Robert Emmet Ginna Nuclear Plant,	50-244	28
Peach Bottom Atomic Power Station, Unit 1	50-171	18	Unit 1  RPI Critical Experiment	50-225	25
Peach Bottom Atomic Power Station, Unit 2	50-277	64	Salem Nuclear Generating Station, Unit 1	50-272	58
Peach Bottom Atomic Power Station, Unit 3	50-278	66	Salem Nuclear Generating Station, Unit 2	50-311	97
Pebble Springs Nuclear Plant, Unit 1	50-514	249	San Onofre Nuclear Station, Unit 1	50-206	19
Pebble Springs Nuclear Plant, Unit 2	50-515	249	San Onofre Nuclear Station, Unit 2	50-361	173
Pennsylvania State Univ. Research	50-5	7	San Onofre Nuclear Station, Unit 3	50-362	174
Reactor  Perkins Nuclear Station, Unit 1	STN-50-488	234	Saxton Nuclear Experimental Facility	50-146	16
Perkins Nuclear Station, Unit 2	STN-50-489	235	Seabrook Nuclear Station, Unit 1	50-443	211
Perkins Nuclear Station, Unit 3	STN-50-490	236	Seabrook Nuclear Station, Unit 2	50-444	212
Perry Nuclear Power Plant, Unit 1	50-440	210	Sequoyah Nuclear Plant, Unit 1	50-327	139
Perry Nuclear Power Plant, Unit 2	50-441	211	Sequoyah Nuclear Plant, Unit 2	50-328	141
Phipps Bend Nuclear Plant, Unit 1	50-553	262	Shearon Harris Nuclear Power Plant,	50-400	194
Phipps Bend Nuclear Plant, Unit 2	50-554	263	Unit 1		
Pilgrim Nuclear Power Station, Unit 1	50-293	81	Shearon Harris Nuclear Power Plant, Unit 2	50-401	196
Pilgrim Nuclear Power Station, Unit 2	50-471	229	Shearon Harris Nuclear Power Plant,	50-402	197
Pilgrim Nuclear Power Station, Unit 3	50-472	230	Unit 3		
Plum Brook Research Reactor Facility	50-30	11	Shearon Harris Nuclear Power Plant, Unit 4	50-403	198
Point Beach Nuclear Plant, Unit 1	50-266	49	Shoreham Nuclear Power Station	50-322	131

	Dealcat	Page	Name	Docket	Page
78.1 Set	Docket STN-50-522	254	UCLA Training Reactor	50-142	16
** A fact of Power Project, Unit 1	STN-50-522	255	UC-Santa Barbara Research Reactor	50-433	208
Sugart Statiear Power Project, Unit 2		239	Univ. of Arizona Research Reactor	50-113	13
with Texas Project, Unit 1	STN-50-498	241	Univ. of California Research Reactor	50-84	12
% oth Texas Project, Umt 2	STN-50-499	18	Univ. of California Research Reactor	50-224	25
S, p.e. Radiation Research Reactor	50-187	-	Univ. of Florida Training Reactor	50-83	12
Statistical Univ. Research Reactor	50-141	16	Univ. of Illinois Research Reactor	50-151	16
Spling Power Project, Nuclear, Unit 1	STN-50-485	233	Univ. of Kansas Research Reactor	50-148	16
St. Lucte Plant, Unit 1	50-335	151	Univ. of Lowell Research Reactor	50-223	25
M. Lucie Plant, Unit 2	50-389	188	Univ. of Maryland Research Reactor	50-166	18
Samurat Nuclear Power Station,	50-450	219	Univ. of Michigan Research Reactor	50-2	6
Summit Nuclear Power Station,	50-451	219	Univ. of Missouri Research Reactor	50-123	13
Unit 2			Univ. of Missouri Research Reactor	50-186	18
Surry Power Station, Unit 1	50-280	67	Univ. of New Mexico Research	50-252	38
Surry Power Station, Unit 2	50-281	70	Reactor		
Susquehanna Steam Electric Station, Unit 1	50-387	186	Univ. of Oklahoma Research Reactor	50-112	13
Su-quehanna Steam Electric Station,	50-388	187	Univ. of Texas Research Reactor	50-192	19
Cnt 2			Univ. of Utah Research Reactor	50-72	12
SWFSSAR-PI	STN-50-495	239	Univ. of Utah Research Reactor	50-407	201
Texas A & M Univ. Research Reactor	50-59	11	Univ. of Virginia Cavaller Reactor	50-396	191
Texas A & M Univ. Research	50-128	14	Univ. of Virginia Research Reactor	50-62	11
Reactor			Univ. of Washington Research Reactor	50-139	16
Texas A & M Univ. Research Reactor	50-129	14	Univ. of Wisconsin Research Reactor	50-156	17
Three Mile Island Nuclear Station, Unit 1	50-289	80	U.S. Geological Survey Research Reactor	50-274	61
Three Mile Island Nuclear Station, Unit 2	50-320	108	Vallecitos Boiling Water Reactor	50-18	9
Citic 2			Vallecitos Experimental Superheat Reactor	50-183	18
			Vermont Yankee Nuclear Power Station	50-271	57
			Virgil C. Summer Nuclear Station, Unit 1	50-395	192
			Virginia Polytech Inst, Training Reactor	50-124	14
			Washington State Univ. Research Reactor	50-27	10
			Waterford Generating Station, Unit 3	50-382	185
			Watts Bar Nuclear Plant, Unit 1	50-390	189

Name	Docket	Page	Name	Docket	Page
Watts Bar Nuclear Plant, Unit 2	50-391	191	WPPSS Nuclear Project, Unit 1	50-460	224
Westinghouse Critical Experiment	50-87	12	WPPSS Nuclear Project, Unit 2	50-397	193
Westinghouse Test Reactor	50-22	9	WPPSS Nuclear Project, Unit 3	STN-50-508	246
West Valley Reprocessing Plant	50-201	19	WPPSS Nuclear Project, Unit 4	50-513	248
William B. MacGuire Nuclear Station, Unit 1	50-369	180	WPPSS Nuclear Project, Unit 5	STN-50-509	247
William B. MacGuire Nuclear Station, Unit 2	50-370	182	Yankee-Rowe Nuclear Power Station	50-29	10
William H. Zimmer Nuclear Station,	50-358	170	Yellow Creek Nuclear Plant, Unit 1	STN-50-566	266
Unit 1			Yellow Creek Nuclear Plant, Unit 2	STN-50-567	266
Wolf Creek Generating Station	STN-50-482	230	Zion Nuclear Power Station, Unit 1	50-295	82
Worcester Polytech Inst. Research Reactor	50-134	16	Zion Nuclear Power Station, Unit 2	50-304	91

#### LOW LEVEL RADWASTE DISPOSAL SITES

- DOCKET 27-039 SHEFFIELD, IL , NUCLEAR ENGINEERING CO
- 7903100225 Motion by licensee for emergency action to rescind NMSS 790320 order to show cause Seeks to refer matter to ASLB Affidavit of TS Beer encl GONNER. T B , RADER.R Conner, Moore & Corber 79/03/22 19pp
- 7903310010 Response to 790320 order to show cause Order should be found void denies any violation of license Certificate of Svc encl GUNDER, T B Conner Hoore & Corber 79/03/23 9pp
- 7905250372 Response to ASLB 790313 directive Concurs w/NRC 790320 motion that license applications may only be withdrawn per NRC terms & conditions Request to file instanter affidavit of SN Sekuler & Certificate of BCc encl
  SCOTT.W J , SEKULER.S N Illinois, State of 79/03/24 i3pp
- 7905100248 NRC response to licensee's motion for emergency action Urges denial of request to rescind 790320 order to show cause why Ilcansee should not resume obligations under OL Bupporting documentation & Certificate of Suc encl. REIS.E. J Branch 3 79/04/02 26pp.
- 7903030168 Forwards Bureau County Circuit Court.IL.order granting preliminary injunctive relief re operation of facility REIS.E J Branch 3 79/04/03 1p
- --7905030171 Order granting preliminary injunctive relief & ordering licensee to take certain actions re facility + Illinois, State of 79/03/27 7pp
- 7905100237 Post-hearing brisf submitted by licensee re issues arising during 790327 oral argument before ABLB. Responds to positions of NRC & State of IL Certificate of Svc ancl. GUNNER. T B Conner, Muora & Corber. 79/04/03 30pp
- 7905240138 Proposed corrections to transcript of 790327 oral argument in Peoria: IL Certificate of Syc encl CONNER.T B Conner, Moore & Corber 79/04/03 4pp
- 7705140153 FOIA request for all records, studies, correspondence & repts re decommissioning of reactor & shipment of decommissioned matt to Sheffield low level nuclear waste site HANBELL.D. Illinois, State of 79/04/06 2pp.
- 7905150521 Replies to applicant's motion for emergency action & to applicant's answer to show cause. Supporting documentation & Certificate of Evc and HANSELL, D Illinois, State of 79/04/06 94pp
- 7905110172 Responds to 790313 ltr re Nuclear Engineering Co illegal abandonment of Sheffield. IL low level nuclear waste burial ground. Forwards 790320 order to show cause why company should not resume responsibilities & obligations DIRCKS. H J Office of Nuclear Material Bafety & Bafeguards 79/04/09 2pp
- ---7905110181 Expresses concern w/illegal abandonment by Nuclear Engineering Co of its Sheffield. IL nuclear waste sits Requests NRC Intervene to secure site until matter of responsibility is adjudicated.

  DEMUZIG.V Illinois, State of, 79/03/13, 1p.
- 7908240297 Lists conditions by which proceeding may be dismissed relevant to site decommissioning & protection of public health & safety REIS. E. J. Branch G. 79/04/10, Gpp.
- 7903310392 Response by intervenor Bureau County, IL to ABLB 790327 hearing. State of IL licensees are jointly responsible for maint of waste disposal site Certificate of Svc encl HADBON, 8 Illinois, State of 79/04/10, 7pp.
- 7905070364 Forwards 790300 itr discussing insp of License 13-10042-01 on 790309.16,21-23 & 29 Ltr referenced in reply to applicant's motion for emergency action & applicant's order to show cause
  HANGELL, D. Illinois, State of. 79/04/11. ip.

- 7905020197 Responds to 790227 Itr re plans to prepare EIS for low level radioactive waste burial ground EIS has been delayed because applicant has withdrawn its application & has not complied w/requests for add1 info CORNELL,E K Office of the Executive Director for Operations 79/04/12 2pp
- 7905100372 Forwards signed affidavit by MJ Bell of Low Level Waste Branch to be included in NRC response to licensee's motion for emergency action to replace earlier unsigned version REIS,E J Branch 3 79/04/12 6pp
- 7905310273 Discusses conditions precedent to Nuclear Engineering Go withdrawal of application & termination of activities
  Licensee should fulfill obligations Supporting documentation & Certificate of Svc encl
  SEKULER, S N Illinois, State of 79/04/12 43pp
- 7905241004 Cites objections to draft interim branch position re low level waste burial ground site closure & stabilization Most of position is reasonable REYNOLDS, L.E. Chem-Nuclear Systems, Inc. 79/04/13 2pp
- 7905240579 Grants NRC & intervenors' motion to dismiss license amend for site expansion Denies licensee's motion for withdrawal of application for license renewal & motion to dismiss proceedings
  LITTLE, L W . REMICK, F J . OOODHOPE, A C Atomic Bafety and Licensing Board Panel 79/05/03 6pp
- 7905140155 Partial response to FOIA request for records re decommissioning of reactor & shipping of decommissioned math Ltrs forwarded from IL Dept of Public Health dtd 730201,730124,700116,700102,720324 & 720223 enci FEL
- DOCKET 27-047 BARNHELL, SC . CHEM-NUCLEAR SYSTEMS
- 7905220454 Requests that Condition 10 contained in Amend 12 to License 46-13536-01 be retained in future license amends re U-235 waste burial CORBETI.J.S Chem-Nuclear Systems, Inc. 78/01/10 ip
- 7905250232 Discusses request for amend to License 45-13536-10 which would permit local power range monitors containing plutonium Prior to amend issuance, written permission from BC for plutonium burial must be obtained DRAGONETTE.K S. Low Level Waste Branch (Pre 790501) 79/04/04

#### DOMESTIC LICENSING OF SOURCE MATERIAL

- DOCKET 40-0299 UNION CARBIDE CORP
- 7905010501 Requests amend to License SUA-64B to permit receiving & processing of carbonate solution. Shipments are to begin 790515.

  REXEMEYER: P.C. Union Carbide Corp. 79/03/29 1p
- 7905020280 Comments on DES corrects factual errors in rept, Planned monitoring program should be adequate DEXTER, H, D Hyoming, State of 79/03/30 ip
- 7905030132 Forwards 790221 "Environ Assessment of Below Grade U Tailing Disposal in A-9 Open Pit, East Gas Hills U Mine & Mill, HV, for Union Carbide Corp " HURDOCK.L.T Dames & Moore 79/04/10. 1p
- ---7905030136 "Environ Assessment of Below Grade U Tailing Disposal in A-9 Deen Pit, East Gas Hills U Mine & Mill, HY, for Union Carbide Corp." HYRDDCK, L T Dames & Moore 79/02/21 117pp
- 7905130613 Bummary of 790301 meeting w/Union Carbide Corp in Bilver Spring. MD re comments on DEB. LINEHAN, J Assistant Director for Waste Hanagement (Pre 790301) 79704716. 2pp.

- 7905290033 Provides supplemental info requested in 790416 telcom re East Coast Hills heap leach REKEMEYER,P C Union Carbide Corp 79/04/17 App
- 7905100113 Forwards supplementary info re source mati license: drawings of proposed heap leach & decription of reclamation plans & costs Oversized drawings enci
  REDEMEYER, P. C. Union Carbide Corp. 79/04/19 7pp.
- DOCKET 40-1162 WESTERN NUCLEAR, INC.
- 7905170292 Forwards into requested by 790314 telcon re-sediment samples from Green Mountain IX Marsh RESKID.N Hestern Nuclear. Inc. (subs. of Phelps Bodge Corp.), 79/03/29 Spp.
- 7905300147 Requests determination of need for toe frein prior to approval of tailings mgt sys BOQDEN.O. Hestern Nuclear. Inc. (subs. of Pheles Bodge Gorp.). 79/04/06 2pp
- 7905240442 Forwards add1 copies of map showing location of wells & well water moniforing results for 1977-78.

  8000EN 0 Hestern Nuclear, Inc. (408s. of Phalps Dodge Corp. ),
  79/04/16 ip
- --7903240457 Forwards map & chart showing location of wells & wall water monitoring results for 1977-78 BQQDEN.Q Western Nuclear: Inc. (subs of Phelps Dodge Corp.) 79/04/09. App
- DOCKET 40-2041 WEST CHICAGO FACILITY, KERR-MCGEE CORP
- 7905100064 Confirms 780410 discussion re enci comments on decommissioning plan Plan submitted is not acceptable, due to lack of detail for preparation of EIA Outlines major deficiencies W/suggested format for plan CROW, N, T Fuel Process & Fab Branch 79/04/12 14PP
- ---7905100071 Forwards Region III comments on Kerr-McOee decommissioning plan Thickness of "clay substructure" should be stated. environ criteria for radioactivity should be specified & "air scrubber sys" should be elaborated DAVIS.A B Region 3. Chicago, Fuel Facility & Haterials Safety Branch, 79/03/08 3pp
- --7905100078 Forwards comments on Kerr-McGee decommissioning plan 4/o sntl CATALAND, C. R. West Chicago, IL 79/03/14 lp
- --7905100089 Summary of activities of JL State Geological Survey & data collected in attempts to locate suitable site for disposal of thorium-bearing solid wastes from Kerr-McGee facility, CARTWRIGHT, K Illinois, State of 79/01/11 3pp
- --7905100074 Forwards "Liners for Sanitary Landfills & Chemical & Hazardous Waste Disposal Sites," EPA-600/9-78-005, May 1978, in response to 790214 meeting re decommissioning at Kerr-McGee facility M/o enc! GRIGALAUSKI
- 7905240114 Requests emend to 790305 request re thorium residuals in West Chicago Decommissioning plan for West Chicago facility should be resolved within six months of date of ltr. SPELMAN.H J. Wast Chicago. IL 79/04/18 2pp.
- DOCKET 40-2259 PATHFINDER MINES CORP
- 7905220039 Amends License SVA-672 to change name of licensee, modify yellowcake drying & pactaging dust collection syst& barreling area SCARANO.R A Radioisotopes Licensing Branch (Pre 790501) 79/03/22 3pp
- 7905250011 Recommends approval of Pathfinder Hine Corp's request for Amend 4 to License SVA-672 authorizing mode to dust collection sys serving yellowcake dryer & packaging area, 8CARANO,R A. ROSSBACH.L. W. Redictsotopes Licensing Branch (Pre. 790501) 79703722. 4pp

- 7905250176 Review of 790316 responses to requests for info have been completed & determined to be inadequate Forwards request for add1 info re probable max 6-h rainfall value & area draining into pond associated w/proposed Tailings Dam Addition 4 BCARANG.R A Fuel Process & Fab Branch 79/04/09 3pp
- 7905270488 Forwards request for addl info to complete radiological assessment for amend request Requests response by 790804 SCARANO.R A Division of Fuel Cycle & Material Safety 79/04/10
- 7908100025 Responds to 790330 ltr Provides clarification & addl infors tailings mod plans, including area archeological inventory.
  NUGENT.E.L. Pathfinder Mines Corp. 79/04/20 27pp
- DOCKET 40-2407 FELLOWS MEDICAL MFG CO . INC
- 7905230115 Response to FOIA request for info re Thorotrast, its licensing, manufacturers & licensees Forwards records contained in Docket 40-2407 FELTON, J H Division of Rules and Records 79/05/07 lp
- --7905230132 Notifies Source Matl License STB-678 for Fellows Medical Pr Co Inc is terminated Forward's 691110 ltr. radiation survey & evaluation rept on isotope preparation HARMON, D.F. Atomic Energy Commission (Pre 1975) 69/12/09 3pp
- --7905230197 Notifies of issuance of License C-9185 for Testager & Ce authorizing use of therium exalate in mfg of Theretrast & Umbrather DELANEY, U C Atomic Energy Commission (Pre 1975) 66/06/10 18
- --7905230201 Notifies of issuance of License R-152 for Testagar & Co authorizing use of thorium oxalate in mfg of Thorotrast & Umbrator DELANEY, J C Atomic Energy Commission (Pre 1975) 59/03/03 1
- --7905230204 Notifies of issuance of License R-152 for Testager & Co.lr.
  authorizing thorium oxalate for use in mfg of Thorotrast &
  Umbrathor
  UGHNSGN.L Atomic Energy Commission (Pre 1975) 56/12/07 lp
- --7905230214 Requests termination of License GTB-678 Bldg at 1354 H Lafayette Doulevard, Detroit, M1 should be released from license for destruction CARRIGAN, R H Fellows Medical Mfg Co , Inc , Fellows-Testager Div 69/12/03 ip
- --7909230219 Requests rept indicating that radioactivity limits of A806° ltr have been met Application for license amend to be filed re-proposed activities at new locations Encl radioactive limits set

  HARMON: D F Atomic Energy Commission (Pre 1975) 68/08/14 2pp
- ~-7903230255 Requests add1 info on procedures for evaluating personnel exposure to airborne radioactivity, in response to A40911 application for renewal of License STB-678 LAYFIELD,R L. Atomic Energy Commission (Pre 1975). 64/10/22 200
- ---7905230284 Requests renewal of License BTB-670 CARRIGAN,R H Fellows Medical Mfg Co . Inc , Fellows-Testagar Div 64/06/£1 ip
- ---79032303)3 Requests max quantity of sours meth be change from 100 to 300 lb to maintain production levels CARRIQAN,R H Fellows Medical Mfg. Co , Inc , Fellows-Testagar DIV, 63/02/07 ip
- --7905230320 Advises that licensee displied 680831 Merger approved w/Fellows Medical Mfg Co.Inc New name as of 630101 is Fellows-Testagar Co Officers remain same axcept for secretary & treasurer positions Mfg to be done in Detroit CARRIGAN.R H Fellows Medical Mfg Co., Inc., Fellows-Testagar Div 62/12/31. ip
- --7905230342 Repeats 610521 request for info re license renewal to determine if source matl use meets 610213 criteria NUSSRAUMER, D. A. Atomic Energy Commission (Pre 1975) 61/05/23
- ---7905230345 Clarifies that request is for renewal of license.as opposis to application for new license CARRIOAN.R H Fellows Medical Mfg Co . Inc . Fellows-Testager DIV 61/05/05 ip

- ~~7905230348 Requests info necessary for application for renewal of License R~152 Application must include max quantitly of matl to be possessed safeguard procedure. List of survey instruments & methods of radioactive waste disposal NUSSBAUMER, D. A. Atomic Energy Commission (Pre 1975) 61/05/02
- --790523035i Requests renewal of License R-152 CARRIGAN-R H. Feilows Medical Mfg Co , Inc , Fellows-Testagar Div 61/03/28 ip
- --7905230352 Requests renewal of License R-152 CARRIGAN,R H Fellows Medical Mfg Co , Inc , Fellows-Testagar Div 60/06/02 ip
- ---7905230357 Requests renewal of License R-132 CARRIGAN.R H Fellows Medical Mfg Co , Inc , Fellows-Testagar Div 59/02/18 ip
- --7905230370 Responds to 580314 request for info re License R-152 Thorium oxelete to be used for medical profession Personnel handling math wear goums, protective meats & work in isolated rooms Math measured solely by badges
  CARRIOAN:R H Fellows Medical Mfg Co , Inc , Fellows-Testagar
  Div 58/04/10 Zpp
- ---7905230374 Responds to licensee 580320 ltr Requests submittal of info requested in NRC 580314 ltr before renewal of source matl license can be considered DELANEY, J C Atomic Energy Commission (Pre 1975) 58/04/01 ip
- --7905230390 Application for renewal of Licenso R-152 authorizing use of thorium oxalete in k-ray media CARRIGAN,R H Fellows Medical Mfg Co , Inc , Fellows-Testagar Div 56/11/26 3pp
- --7905230137 Forwards renewed Source Matl License STB-678
  HARMON,D F Atomic Energy Commission (Pre 1975) 69/03/05 1p
- --7903230145 Bource Matl License BTB-678 for Fellows Medical Mfg Co, Inc authorizing use of thorium as described in 680216 application HARMON.D F Radioisotopes Licensing Branch (Pre 790501) 68703704 tp
- ---7905230150 Forwards renewed Source Matl License STD-678 NUBSBAUMER, D. A. Atomic Energy Commission (Pre 1975) 69/04/12
- --7905230160 Source Matl License STB-678 for Fellows-Testagar Co authorizing use of thorium as described in 610607 & 610818 applications ,\* Radioisotopes Licensing Branch (Pre 790501) 65/04/12 2pp
- --7905230164 Forwards Bource Matl License STD-678 NUSSBAUMER, D. A. Atomic Energy Commission (Pre 1975) 63/01/23
- --7905230177 Source Matl License STR-678 for Fellows-Testagar Co authorizing use of U & thorium as described in 610607, 610727, & 610818 applications NUSSBAUMER.D A Radioisotopes Licensing Branch (Pre 790501) 63701/23 is
- --7905230183 Forwards Source Matl License 8TB-404 NUBBBAUMER, D. A. Atomic Energy Commission (Pre 1775) 61/08/25
- --7705230193 License ST8-404 for Testagar & Co.Inc authorizing use of thorium as described in 610607.610727, & 610818 application. NUSSBAURR.D.A Radioisotopes Licensing Branch (Pre 770501) 61/08/25 in
- ---7903230226 Notifies of equipment for mfg of Thorotrast to be dismantled, moved, or disposed within next two months CARRIGAN, R H Fellows Medical Mfg Co . Inc . Fellows-Testagar Div 68/08/07 ip
- --7905230233 Application for renewal of License 8TB-678 authorizing use of dxalate in mfg of starile x-ray contrast medium CARRIOAN,R H. Fellows Medical Mfg Co , Inc , Fellows-Testagar Div 68/02/16 2pp
- --7905230250 Approves extension of time for submission of info requested in 641022 ltr LAVFIELD.R L. Atomic Energy Commission (Pre 1975) 64/11/12 lp

- --7905230261 Act receipt of AEC 640818 ltr Evaluation of personnel radiation exposure accomplished by readings of personnel badges & urine analyses Lab wiped down periodically Survey encl
  CARRIGAN.R H Fellows Medical Mfg Co , Inc , Fellows-Testagar
  Div 64/09/11 2pp
- ---7905230270 Requests add1 info on procedures for evaluating personnel exposure to airborne radioactivity & airborne activity in exhaust fam effluent. in response to 640715 application for renewal of License 678-678

  LAYFIELD,R L Atomic Energy Commission (Pre 1975) 64/08/18
- ~-7905230276 Application for renewal of License BT8-678 authorizing use of thorium oxalate in mfg of sterile r-ray contrast CARRIGAN,R H Fellows Medical Mfg Co , Inc , Fellows-Testagar Div 64/07/15 2pp
- --7705230291 Requests replies to AEC 630312 questions Amend to License 8T8-678 to be filed on Form AEC-2. NUSSBAUMER.D A Atomic Energy Commission (Pre 1975). 63/07/29.
- ---7905230299 Inquires whether current source matl license needs to be amended to incorporate handling of Th-320 for ANL.

  CARRIOAN.R H Fellows Medical Mfg Co , Inc , Fellows-Testagar Div 63/07/08 ip
- ---7905230306 Discusses AEC 630312 ltr requesting add1 info re application for amend of License STB-678 Detroit Health Dept called to assist in evaluation.
  CARRIGAN, R H Fellows Medical Mfg Co , Inc., Fellows-Testager Div 63/04/16 ip
- ---7903230312 Requests add1 info re amend of License BTB-678 authorizing use of add1 200 lb of thorium Requires description of procedures for evaluating personnel exposure to airborne activity & decontamination control within lab NUSSBAUMER, D.A. Fellows Medical Mfg. Co., Inc., Fellows-Testagar Div 63/03/12 ip
- --7905230328 Submits info as amend to Parts 1,2 & 3 of 610607 application for License R-132 Max quantity of source mat1 to be possessd is 100 lb Dust inhalation masks contain CR 72292 Comfo Respirator dust filter CARRIGAN,R H Felious Medical Mfg Co , Inc., Fellows-Testagar Div 61/08/18 2pp
- --7905230332 Informs license not yet received Requests issuance of license or reasons for not receiving license. CARRIGAN, R H Fellows Medical Mfg Co , Inc , Fellows-Testagar Div 61/07/27 ip.
- --7905230638 Applies for renewal of License R-152 CARRIGAN,R M Fellows Medical Mfg Co , Inc , Fellows-Testagar Div 61/06/07 2pp
- ---7905230380 Ack receipt of AEC 580314 itr re renewal of License R-152 Insp indicates controls & safety precautions in order Inquires whether written rept of insp desired CARRIGAN. H Fellows Medical Mfg. Co., Inc., Fellows-Testagar Div 58/03/20 ip.
- --7905230386 Requests add1 info on activities, safeguard procedures, survey instrument description & method of waste disposal; in response to 580304 application for renewal of License R-152 DELANEY, J C Atomic Energy Commission (Pre 1975) 58/03/14 ip.
- ---7905230388 Requests renewal of License R-152, CARRIGAN,R,H Fellows Medical Mfg Go , Inc , Fellows-Testagar Div 58/03/04 ip
- DOCKET 40-3392 ALLIED CHEMICAL CORP
- 7903220107 Forwards info requested by NRC 790115 ltr & 790226 memo re compliance of Metropolis. IL Works w/requirements of 40CFR190 Stock emission & lung fluid solubility data encl. NEWMAN, R. I. Allied Chemical Corp. 79/03/22, 28pp
- 7903290655 Ack receipt of 790410 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 40-3392/79-01 DAVIS.A.B Region 3. Chicago, Fuel Facility & Materials Safety Branch 79/04/26 ip

--7905290665 Responds to NRC 790323 ltr re violations noted in IE Insp Rept 40-3392/79-01 Corrective actions preparation of GA manual, new air sampling lines installed & new constant air monitor installed THOMAS.J H Allied Chemical Carp , Nuclear Services Div 79/04/10 3pp

#### BLANSAIN BALTA CERE-OF TENDOD

7903240200 Summary of 790402 meeting w/Atlas Minerals Corp re reclamation surety arrangements Itemized cost breakdown will be conducted to finalize surety posting process Followup meeting scheduled for 790427 to finalize surety arrangement DANIELS.R W Utah, State of 79/04/02 Ip

DOCKET 40-4492 FEDERAL AMERICAN PARTNERS

- 7905230681 Forwards IE Insp Rept 40-4492/79-01 on 790301 No noncompliance noted BROWN, 0 D Region 4. Dailas. Office of the Director 79/03/15
- --7905230693 IE finsp Rept 40-4492/79-01 on 790301 No noncompliance noted Major areas inspected tailings area & retention dam HILBORN,L. : BROWN,O D Region 4, Dallas, Fuel Facility & Haterials Safety Branch 79/03/14 opp
- 7905020222 Hydrologic engineering info requested on 790226 has been sent by consultants, but will be resubmitted second time JACKBON, F. D., WRIGHT, K. H. Federal American Partners 79/04/04
- 7905070032 Forwards rapt on radiological tissue analysis of HY animats & rept of five environ monitoring stations.

  JACKBON, F D Federal American Partners 79/04/04 2pp
- --7905070037 "Radiological Tissue Analysis of Belected Plants & Animals Collected from WY V Districts." KENNINOTON.Q S , DOERGES,J E Wyoming, Univ of 78/10/31 48pp
- 7905240444 Forwards into re radiation monitoring program for total particulates, Rn-222, Th-230, Ra-226, Pb-210 & natural U JACKSON, F D Federal American Partners 79/04/30 19pp
- 7905240752 "Supplemental Quotechnical Investigation & Stability Analysis for Proposed Tailing Dam 2 "Oversized drawings encl # Federal American Partners 79/04/30 47pp

DOCKET 40-4602 MORTON RANCH URANIUM MILL

7905100407 Comments on DES for facility No significant environ impacts in areas of agency's concern HEINEMAND.J M Federal Energy Regulatory Commission 79/03/16 ip

DOCKET 40-6659 PETROTOMICS CO. , GETTY OIL

- 7905150616 Summary of 790220 meeting w/Petrotomics in Silver Spring.MD re upgrading of environ & effluent monitoring program.

  LINEMAN.J J Assistant Director for Weste Management (Pre 790501) 79704715 2pp.
- 7903100284 Forwards requested info to update environ monitoring program One oversized drawing encl.
  PPAFF.S J Petrotomics, Inc. 79/04/20 11pp
- 7905240548 Notifies of withdrawal of request for const mod of tailings dam Mill continue to follow original design approved on 780602.

  MMITMAN.J H Petrotomics, Inc. 79/04/24, tp.

DOCKET 40-7086 ARMY, DEPT. OF

7905310001 IE Insp Findings & Licensee Ack dtd 790286-0301 of License SUB-734. Insp findings:no items of noncompliance found \* Region 4, Dallas. Office of the Director. 79/03/01, ip DOCKET 40-9027 KERR-HCGEE CORP

- 7705090003 Notifies of Amend 3 to License SUB-1010 to include decommissioning plans & financial surety arrangements Requests correction of former amend numbers H/review of decommissioning plan CROH.H T Fuel Process & Feb Branch 79/03/26 2pp
- 790509000B Review of License SUB-1010 amend application for future decommissioning plan
  CROW.H T Fuel Process & Fab Branch 79/03/26 3pp
- 7905090425 Forwards application for Amend 2 to License SUB-1010,444 780303.dekailing plans for newly breated raffinate storage pond 3 Minor amend fee & oversized drawings encl SHELLEY.W J US Nuclear. Inc 79704704 13pp
- 7905290479 Notifies of amend to License SUB-1010, authorizing test distribution of barium treated neutralized solvent extraction raffinate over Kerr-McDee owned land CROM-W T Fuel Process & Fab Branch 79/04/13 2pp

DOCKET 40-8035 COTTER CORP

7905250067 Confirms 790316 request for radiological survey of 8144s 2 is of former Cotter Corp property in Hazelwood.MO Property previously released for unrestricted use Requests additionally samples from Bldg 1 CRON.W T \_\_\_ Fuel Process & Fab. Branch 79/04/16 1p

DOCKET 40-8064 EXXON HINERALS CO USA, EXXON CORP

- 7905250056 Forwards requested info on Monitor Wells 0-9 at new solution mining R&D site. & plot glan of R&D site showing relative location of leach field & monitor wells
  FREEMAN, H D Exzon Minerals Co. USA 79/04/04 3pp
- 7905250518 Rept for first quarter 1979, including plot plan of 850 sits well field, summeries of monitor well valves & sample well analyses
  FREEMAN.H D Exxon Minerals Co .UBA 79/04/19 15pp

DOCKET 40-8102 EXXON MINERALS CO USA, EXXON CORP

- 7905300691 Safety evaluation supporting amend to License 6VA-1139 to permit solution process mining of U COOPERSTEIN'R Fuel Process & Fab. Branch 79/01/25 29pp
- 7903:80070 Confirms 790323 telcon re sandblasting of equipment which caused unrestricted release of airborne soluble U Radioactivity removed from room by wiping Forwards urine analyses from exposed Employees W/o encl.
  ORTLOFF, O D. Exxon Minerals Co , USA 79/03/24 3pp
- DOCKET 40-8158 ARMY, DEPT OF, COMMUNICATIONS & ELECTRONICS MATERIAL
- 79DB100374 IE Into Findings & Licensee Ack, dtd 790306, of Licenses 29-01022-08, 29-01022-11, 29-01022-12, BUB-1150, SMB-1327 & BNK-1327 Insp findings no honcompliance noted FRIEDMANL F. Region 1. Philadelphia, Office of the Director 79/03/04. 1p.

DOCKET 40-8452 BEAR CREEK MINING CO

- 7905230304 Notifies of individual's overexposure to airborne natural U on 790225. Caused by employee carelessness which created large cloud of dust uring vane feeder repair in vallowcake druer enclosure. Supervision of area increased BAKER, JR Bear Creek Mining Co (subs of Kennecott Corp ) 79/03/09 2pp
- 7995100223 Forwards engineering & reclamation drawings which provide details of revised operational & reclamation features of mill tailings disposal sys for License 8UA-1310 ANDREWS.R.D Rocky Mountain Energy Co. 77/04/06

- 7903100233 Forwards oversized drawing showing tailing reservoir after reclamation, per 790406 request Drainage from tailing cover reversed to flow south to diversion out Downstream dam reduced in slope from 3 i to 5 i Oversized drawings encl ANDREWS, R D. Rocky Mountain Energy Co. 79/04/06. 3pp
- 7905240283 Forwards requested flow sheet for mill process Changes relate to process efficiency improvements or necessary additions to handle tolled one Oversized drawing encl ANDREWS, R D. Rocky Mountain Energy Co. 79/04/17 ip
- DOCKET 40-8502 IRIGARY MINE, WYOMING MINING CORP
- 7905150806 Recommende Amend i to Licenso SUA-134i be approved to authorize in situ U solution extraction & recovery of natural U using calcium-magnesium-carbonate/bicarbonate & oxidant sys within licensed solution extraction area COOPERSTEIN-R, BCARAND.R A Radioisotopes Licensing Branch (Pre 790501) 79/04/10 3pp
- 7905240267 Forwards 790405 1tr to DUE requesting mod of WY State Mine Permit 478 BCHENDEL,K R Wyaming Mineral Corp 79/04/26 3pp
- DOCKET 40-8584 UNION 76 MINERALS EXPLORATION CO
- 7905150624 Summary of 790306 meeting w/Minerals Exploration Co in Silver Spring, MD re minor amends to License SUA-1390 & presperational monitoring program LINEMAN, J Assistant Director for Haste Management (Pre 790501) 79/04/16 2pp
- 7905110019 Informs that manpower expenditure required for review of Amend 1 to License BUA-1350 calls for smaller amend fee than fee which was sent Refund will be made MILLER.W O License Fee Management Branch 79/04/24 ip
- DOCKET 40-8602 UNITED NUCLEAR CORP
- 7905140541 Responds to NRC 790409 request Bubmits summary of United Nuclear Corp/Teton Exploration Drilling Co/TVA rept replanned U milling facility at Morton Ranch property WDLFF,C E United Nuclear Corp 79/04/12 2pp
- 7905030363 Responds to 790416 request Forwards revisions & additions to application for U mill license W/four oversized drawings MOLFF,C E United Nuclear Corp 79/04/20 75pp
- 7905270063 Forwards revised application, in response to 790423 request Some mods were made to U milling application in lieu of inclusion in source matl license WOLFF, G E United Nuclear Corp 79/04/23 7pp
- DOCKET 40-8663 NUCLEAR DYNAMICS, INC
- 7905220029 Amends License 8UA-1331 to authorize use of alternate ammonium carbonate/bicarbonate lixiviant sys in R&D U solution extraction program CROM.W T Fuel Process. & Fab Branch 79/03/30 ip
- 7905240835 Evaluates licensee request to authorize in situ U solution extraction field tests w/ammonium carbonate/bicarbonate & oxidant sys.
  COUPERSTEIN, R. CROWL W. T. Radioisotopes Licensing Branch (Pre 790501) 79/03/30 2pp.
- DOCKET 40-8681 ENERGY FUELS NUCLEAR, INC.
- 7905240301 Requests clarification of EIB re air pollution. W/790125 & 781207 internal correspondence
  HANSEN, R C Utah, State of 79/01/31, 4pp.
- 7905300163 Comments on preliminary case rept for Energy Fuels Whita Masa U Mill, DOI memo re professional considerations surrounding nonacqueous burial of archeological site encl REAVEGR Interior, Dapt of 79/04/06, 2pp
- 7905250201 Forwards "Research Design for White Mesa Archaeological Project" CABJENSIL. Utah, State of 79/04/07. 22pp.
- 7905250168 Comments on DES classification of containers as Type A is done by shipper.not DGT.
  RIEDEL.W.R. Coast Guard, Transportation, Dept of 79/04/12 ip.

- 7905300132 Forwards supplemental archeological rept re stockpile area to east of tailings area
  BAKER,C E Energy Fuels Nuclear. Inc 79/04/16 16pp
- 7905240544 Forwards rept re findings of recent archeological survey of eastern half of northeast quarter of Section 33 No further archaological work required

  BAKER.C E Energy Fuels Nuclear, Inc 79/04/25 6pp
- 7905310088 Summary of 790409-11 trip to ORNL to revise DES reflecting finalized NRC comments
  TRAGER: A Radio(sotopes Licensing Branch (Pre 790501)
  79/04/26 1p
- 7705240256 Forwards requested eligibility determination for earth dam in San Juan County, UT to be included in Netl Register of Historic Places Info should be integrated into NEPA analysis MURTAGH.W J Interior, Dept of 79/05/01 14pp
- --7905240592 Requests determination of area eligibility as archaeological district for Natl Register Forwards State of UT 770104 ltr documenting eligibility BGARANO,R A Fuel Process & Fab Branch 79/04/20 3pp
- 7905240425 Approves proposed memo of agreement w/White Mesa, San Juan County, UT, except items re obligations of developer KEENE, J P Utah, State of 79/05/03 ip
- DOCKET 40-8693 DOLE PETROLEUM, INC
- 7905100172 Forwards quarterly rept for License BUA-1336 CATCHPDOLE, G. J. Ogle Petroleum, Inc. 79/04/10 53pp
- DOCKEY 40-8698 PLATEAU RESOURCES: LTD
- 7905090441 Informs of completion of EIS review No comments at this time BARROUB, H L. Agriculture, Dept of 79/03/12 ip
- 7909010577 Offers no specific comments on DES (NUREG-0904) MCMILLAN, Q D Agriculture, Dept of 79/03/30 1p
- 7705250042 Suggests granting source math license; project will help solve problems of economically depressed area COOKE,P 8 Utah, State of 77/03/30 ip
- 7705010618 Comments on DEB, boundaries of Olen Cenyon Natl Recreational Area are incorrectly shown BENNEDRAL M & Woodward-Clyde Consultants 79/04/04 11pp
- 7905150303 Forwards UT state agency comments on DES BRIGOS, K Utah, State of 79/04/04 11pp
- 7905300130 Forwards "Analysis of Shootering Canyon U Project " LOCHSTET, W A Affiliation Unknown 79/04/08 11pp
- 7903300134 Comments on DES recommends NRC contact Regional Director of Fish & Hildlife Bvc.Denver.CD for guidance re endangered American peregrine felcon HEIEROTTO.L E Interior, Dept of 79/04/09 10ap
- 7905240658 Forwards documents containing comments & questions re DES (NUREO-0504), W/o encl ROTHFLEISCH, J. Division of Fuel Cycle & Material Safety 79/04/10
- 7905150061 Requests approval of application for source matl license for Shostering Canyon V Project. Project would be beneficial to economically depressed area MARRIOTT. D House of Rep. 79/04/11. 2pp
- 7905230542 Supports conclusions of DES (NUREO-0504) OARN, J Senate 79/04/12 1p
- 7905250022 Forwards DDI 790419 comments on DEB.Requests appropriate reply ROTHFLEIBCH.JE Uranium Recovery Licensing Branch 79/04/13.
- 7905150594 Forwards 790110 itr describing county economic conditions & significance of mine-mill complex & townsite. Eager to see project underway.
  HIDDLETON. © Carfield County, UT. 79/04/19. 4pp.

7905100060 Forwards response to comments on DES Suggests revised language for FEB SEMELL.R 8 Plateau Resources, Ltd 79/04/24 55pp

DOCKET 40-8714 CLEVELAND CLIFFS IRON CO

7905250032 Summary of 790410 meeting w/Cleveland-Cliffs Iron Co in Bilver Spring, MD re source matl license for Collins Draw, HY site, applicant's draft radiation manual, mine permit application & guidelines for U straction R&D CDOPERSTEIN, R Radioisotopes Licensing Branch (Pre 790501) 79/04/13 200

#### DOCKET 40-8721 ROCKY MOUNTAIN ENERGY CO

7905150634 Summary of 790320 meeting w/Rocty Mountain Energy Co in Silver Spring, MD re commercial scale U solution extraction proposal & environ rept COOPERSTEIN, R Fuel Process & Fab. Branch 79/03/28 29p

DOCKET 40-8722 BRUSH-WELLMAN, INC

7903300505 Responds to 790412 telcon Violation of health stds has never been documented at plant ANDERSON,L F Utah. Stats of 79/04/13 ip

#### DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES

DOCKET 50-2 UNIV OF MICHIGAN RESEARCH. REACTOR

J Insurance & indemnity information

7905160341 Forwards Amend 10 to Indemnity Agreement E-24, per iOCFR140 changes, re increase from 4140 million to 4160 million, effective 790501 Supporting documentation encl SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

### P Operating license stage documents & correspondence

790509029B Requests exemption of small quantities of SNM from proposed upgrade rules for research reactors BURN.R R Michigan Univ of 79/05/04 ip

7905070367 Requests exemption for small quantities of SNM from proposed upgrade rule for research reactors
BURN, R. Kitchigam. Univ of 79/05/04 ip

7905230402 Forwards GA program & procedures for handling BMI-1 shipping package 5927 KERRNM Michigan Univ of 79/05/14 1p

--7905230406 GA program for Ford Nuclear Reactor \* Michigan, Univ of 78/05/14 18pp

#### DOCKET 50-3 INDIAN POINT STATION, UNIT 1

#### © Adjudicatory correspondence

7905170162 Forwards compilation of Board notifications relicensee regulatory performance evaluation for distribution to all appropriate licensing boards
PATON, H D Branch 4 79/02/28 22pp

#### J Insurance & indemnity information

7903070497 Confirms intreased liability limit to \$124.000.000 for policies NF-1.25.43.76,83.100.111.140.146.151.161.164.170.173.174.178.179.180.180.180.180.189.199.192.193.194.195.197.198.200.201.204.205.207.208.210.212.214.215.4 others QUATTROCHHE.J. American Nuclear Insurers 79/05/01 ip

7703070582 Confirms increase in liability limit to \$36,000.000 for policies MF-22,26,29,39,39,44,46,47,49,50,51,52,53,54,55,56,57,58,60,61,64,66,67,69,69,70,71,72,74,76,77,79,79,80,86,87,88,90,91,92,93,94,95 & 96
ROBERTS D. M. Mutual Atomic Energy Liability Underwriters, 79/05/01

7905140407 Forwards Amend 21 to Indemnity Agreement B-17 per 100FR140 changes, re increase in liability insurance from \$140 million to \$160 million.effective 790501. Supporting documentation encl.

SALTIMAN, J. Antitrust & Indemnity Group 79/05/01, 600.

- P Operating license stage documents & correspondence
- 7905070549 Ack receipt of NRC 790412 ltr Willing to cooperate in planned analysis scheduled for week of 790506 CAHILL.N J Consolidated Edison Co of New York 79/04/30 Ip
- B Inspection reports, IE Bulletins & correspondence
- 7905030272 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks "
  ORIER.9 H Region I. Philadelphia. Office of the Director
  79/03/26 ip
- 7905250248 Responds to IE Bulletin 79-03 re longitudinal weld defects in certain pipe spools mfg by Youngstown Welding & Engineering Co Piping not used in Unit 2 Info on Unit 1 will be provided when returned to svc CAHILL.W J Consolidated Edison Co of New York 79/04/13 2pp
- 7905020350 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping " Licensee action required ORIER, B H Region 1. Philadelphia. Office of the Director 79/04/14 ip
- 7905030373 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident " GRIER, B H Region I, Philadelphia, Office of the Director 79/04/14 Ip
- 7905040183 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Hater Power Reactors Identified During TMI Incident " ORIER.8 H Region i. Philadelphia. Office of the Director 79/04/14 ip
- 7905010079 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Bys " Licensee action required ORIER, 8 H Region 1, Philadelphia, Office of the Director 79/04/17 ig
- --7905010083 IE Builatin 77-09, "Failures of GE Type AK-2 Circuit Breater in Bafety-Related Bys " Extract of GE Byc Ltr 175(CPDD)9 3 enc! \* Office of Inspection & Enforcement 79/04/17 10pp
- 7905010636 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Gys Misalignments Identified During TMI Incident" Region 1, Philadelphia, Office of the Director 79/04/i8 ip
- 7905270177 Ack receipt of 790321 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 90-003/78-13 b 50-247/78-38 BMITH of Region 1. Philadelphia, Fuel Facility & Materials Bafety Branch 79/05/04. 2pp
- --7905270185 Responds to NRC 790228 ltr re violation noted in IE Insp Repts 50-003/78-13 & 50-247/78-38 Corrective actions dayeloping techniques to avoid variables leading to badge anomalies CAMILL,W J Consolidated Edison Co. of New York 79/03/21 3pp
- ---7903290188 Forwards IE Insp Repts 50-003/78-13 & 50-247/78-38 on 761227-27 & 790117-18 & notice of violation SMITH.0 H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/02/28 2pp
- --7905290193 Notice of violation from insp on 781227-29 & 790117-18 \* Region 1, Philadelphia. Office of the Director 79/02/28
- --7905290196 IE Insp Rept 50-003/78-13 & 50-247/79-38 on 781227-29 & 790117-18 Noncompliance noted failure to maintain personnel exposure limits in accordance w/10GFR20 101 NEELY,D.R. SERABIAN.J.A. Region i. Philadelphia, Office of the Director. CROCKER,H.W Region i, Philadelphia, Fuel Facility & Materials Safety Branch 79/02/27 12pp
- R Periodic operating reports & related correspondence
- 7905220376 Forwards effluent monitoring & impingement data specified in Section 401 Certification for Apr 1979 MONTI, W.A. Consolidated Edison Co. of New York 79/05/10 17pp
- 7905230392 Forwards daily record of fish collections for Apr 1979 W/daily species breakdown & total weight for Units 2 & 3 ORIER, B. H Region i, Philadelphia, Office of the Director 79/03/14, 5pp

7905230365 Forwards monthly operating rept for Apr 1979 CAHILL.W J Consolidated Edison Co of New York 79/05/15 1p	DOCKET 50-8 NO
	J Insurance 8
7905230367 Monthly operating rept for Apr 1979 KAHULA:L Consolidated Edison Co of New York 79/05/04 7pp	7905300069 For change in 10
8 Reportable occurrences, LERs & related correspondence	from \$140 mi Supporting d SALTZMAN,J
7905220283 LER 79-001 has been voided * Consolidated Edison Co of New York 79/04/01 ip	7905310452 For in addresses BOHANNON, J F
7905220286 LER 79-003 has been voided * Consolidated Edison Co of New York 79/04/01 1p	
7905220288 LER 79-004 has been voided * Consolidated Edison Co of New York 79/04/01 1p	DOCKET 50-10 E
7905220291 LER 79-005 has been voided # Consolidated Edison Co of New York 79/04/01 1p	7905020234 Rec decontaminat radioactive
7905220294 LER 79-006 has been voided * Consolidated Edison Co of New York 79/04/01 lp	radionuelide DREY.K Afr
7905220299 LER 79-007 has been voided * Cansalidated Edison Co of New York 79/04/01, 1p	7905240421 Sun
7905220302 LER 79-008 has been voided * Consolidated Edison Co. of New York 79/04/01 1p	inspected pt equipment, fi Forwards una DERDERIAN, L
7905220305 LER 79-009 has been voided * Consolidated Edison Co of New York 79/04/01 ip	7905250097 Not discuss fire o'CONNOR.P \$
7905220312 LER 79-010 has been voided * Consolidated Edison Co of New York 79/04/01 1p	7905030366 For withheld (re
7905220313 LER 79-011 has been voided * Censolidated Edison Co. of New York 79/04/01 1p	LEE, B Coma
7905190015 Porwards LER 79-012/04X-1 CAHILL,W J Consolidated Edison Co of New York 79/05/10 1p	7905020523 For
7905190018 LER 79-012/04X-1 on 790213 activity of precipitation sample exceeded 10 times control station level Caused by tritium releases from source external to facility Manufacturer in	decontamina: corroxion fi DENTON,H R
area has modified installation to prevent recurrence MASCIULLI, 8 Consolidated Edison Co of New York 79/05/10 3pp 7905190021 Forwards LER 79-015/04T-0	7905020533 F #Kperiment corresion DREY, K, /
CAMILL.W.J Consolidated Edison Ca of New York 79/05/10 1p	H General con
7905170028 LER 79-013/04T-0 on 790405: activity of precipitation sample exceeded to times control station level Caused by tritium releases from source external to facility Manufacturer in area has modified installation to prevent recurrence MASCIVELI, 8 Consolidated Edison Co of New York 79/05/10 2pp	7905150675 For before autho O'BRIEN, O M
DOCKET 50-5 PENNBYLVANIA STATE UNIV. RESEARCH REACTOR	J Insurance
J. Insurance & indemnity information	7905100163 End GERAS: T. No 1p
7903160328 Forwards Amend 14 to Indemnity Agreement E-10.per 10CFR140 changes.re increase from #140 million to #160 million. effective 790301 Supporting documentation enci SALTZMAN.J Antitrust & Indemnity Oroup 79/05/01 Spp	7905070497 Co policies NF
DOCKET 50-6 BATTELLE MEMORIAL INST RESEARCH REACTOR	173:174,178 197:198:200 GUATTROCHHI
######################################	7905070582 Ca
J Insurance & indemnity information	policies MF 57, 58, 60, 61 88, 90, 91, 92
7903300065 Forwards Amend 14 to Indemnity Agreement 8-6.reflecting change in iOCFR140 reflecting increase in primary layer of liability from \$140 million to \$160 million.effective 790301. Supporting documentation encl	ROBERTS, D M
BALTIMAN,J Antitru∉t & Indemnity Group 79/05/01 5pp	7905140404 Fo changes, re to \$160 mil

7905240391 Forwards executed Amend 14 to Indemnity Agreement B-6, effective 790514.

8TALL, D. H. Battelle Memorial Institute, Columbus Laboratories 79/05/14. 2pp.

DOCKET 50-B NORTH CAROLINA STATE UNIV. RESEARCH REACTOR

J Insurance & indomnity information

7905300069 Forwards Amend i5 to Indomnity Agreement E-7. reflecting change in iOCFR140. increasing primary layer of liability from \$140 million to \$160 million.effective 790501. Supporting documentation encl SALTZMAN.J Antitrust & Indomnity Group. 79/05/01 Spp.

7905310452 Forwards Amend 15 to Indomnity Agreement E-7. Requests change in addressee for correspondence BOHANNON.JR North Carolina State Univ 79/05/25 2pp

DOCKET 50-10 DRESDEN NUCLEAR POWER STATION. UNIT 1

D NRC Draft/Final Environmental Statements, suppls & correspondence decontamination experiment Forwards pertiment questions reradioactive corresive products, waste burials & radioactive corresive products, waste burials & radionuclide-chelating agents DREY.K Affiliation Unknown 79/03/30 6pp

F Security, medical, emergency & fire protection plans

7905240421 Summarizes 790320-22 fire protection review trip Areas inspected physical separation of redundant safe shutdown equipment, fire hazards & facility protection features Forwards unanswered questions & positions DERDERIAN.L Plant Systems Branch 79/04/17 1ipp

7905250097 Notification of 790508 meeting w/util in Bethesda. MD to discuss fire protection program O'CONNOR.PW Operating Reactors Branch 2 79/04/25 1p.

7905030366 Forwards modified physical security plan.Revision 5 Plan withheld (ref 10CFR2 790) LEE.B Commonwealth Edison Co 79/04/26 ip

#### O Adjudicatory correspondence

705020523 Forwards petition requesting EIS be prepared on proposed decontamination experiments designed to flush redicactive corrosion from reactor piping. H/FR notice DENTON, H R Office of Nuclear Reactor Regulation. 79/04/09 2pp

---7905020333 Plea for preparation of EIS on proposed decontamination experiments designed to dissolve & flush out radioactive corrosion products from reactor piping DREY, K. Affiliation Unknown 79703/19. Spp.

#### H. Genstal correspondence

7908150675 Forwards K Drey 790319 ltr requesting that EIB be required before authorization is granted to flush piping at facility. O'BRIEN, O M House of Rep. 79/04/04 5pp

#### J Insurance & indemnity information

7905100163 Endorsement 99 to MAELU Policy MF-22 QERAS, T. Nuclear Energy Liability Insurance Association 79/03/27

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,185,186,187,188,189,192,193,194,195,197,198,200,201,204,204,207,207,210,212,214,215,&others.

QUATTROCHHI, J American Nuclear Insurers 79/05/01 ip

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22.26,29.38,39.44,46,47,49.50.51.52.53.54,55.56,57.58,60,61.64,66,67.68,69.70,71,72,74,76,77,78,79,80.86,87,88,90,91,92,93,94,95 & 96
ROBERTS,D M Mutual Atomic Energy Liability Underwriters. 79/05/01.

7905140404 Forwards Amend 21 to Indemnity Agreement 8-10 per 100FR140 , changes, re increase in liability insurance from \$140 million to \$160 million, effective 790501 Supporting documentation enci.

BALTIMAN, J Antitrust & Indemnity Group, 79/05/01, App.

- P Operating license stage documents & correspondence
- 7905030067 Forwards notes on 790302.15 & 33 conference teltons between NRC, consultants & util re builetin "Potential Explosive Qas Mixtures Accumulations Associated u/94R Offgas Sys Uperations " Operating Reactors Branch 3 79/04/16 4pp IPPOLITO T A
- 7905080337 Forwards topics deleted from systematic evaluation program review of facilities Requests review & identification of errors within 30 days from receipt of itr ZIEMANN.D L Operating Reactors Branch 2 79/04/16 7pp
- 7904270366 Summary of 790403 meeting of 22 utils operating 37 nuclear plants re planned use of RETRAN NSSS simulation program Requests meeting w/NRC to assure NRC familiarity w/program REED.C Commonwealth Edison Co 79/04/18 2pp
- 7905250324 Notifies that date for completion of solid waste handling sys has been delayed until 790430 due to lack of manpower for electrical work Commonwealth Edison Co 79/04/20 JANECEK R F
- 7905040482 Notifies of intention to develop safety analysis using existing computer codes Requests addl info
  SCLBRIG.C H Commonwealth Edison Co 79/04/26 1p
- 7905090370 Reviews systematic evaluation program for shared engineered safety features onsite emergency power & svc sys for multiple unit stations multiple unit stations and additionable for the commonwealth Edison Co. 79/05/02 2pp
- 7905140273 Summarizes status of completion of HPCl sys Bidg structure complete & most equipment is on site All concrete poured for north electric duct run, except for Hanhole 4 UANECEK, R. F. Commonwealth Edison Co. 79705/04 2pp
- 790525039: Forwards current licensing open items status list REED.C Commonwealth Edison Co 79/05/18 lipp
- Q Inspection reports. IE Bulletins & correspondence
- 7905020421 Forwards response to IE Bulletins 78-12 & 78-12A, "Atypical Weld Matl in Reactor Pressure Vessel Welds "
  REED.C Commonwealth Edison Co 79/03/22 10pp
- 7708010236 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping" KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/23
- 7903030370 Forwards IE Info Notice 79-07. "Rupture of Radwaste Tanks KEPPLER, J G Region 3. Chicago: Office of the Director 79/03/2
- 7905010155 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Bys w/Byc Air Sys Used as Source of Breathing Air " KEPPLER, J. Q Region 3: Chicago: Office of the Director 79/03/28
- 7905010384 Forwards IE Info Notice 79-09. "Spill of Radioactively Contaminated Resin "
  KEPPLER, J G. Region 3, Chicago: Office of the Director 79/03/30
- 7905030013 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During THI Incident " KEPPLER, J. G Region 3, Chicago: Office of the Director 79/04/11
- 7905240448 Forwards IE Insp Repts 50-010/79-07, 50-237/79-09 & 50-249/79-07 on 790304-07, 0312 & 0323, No noncompliance noted. DAVIS,A.B. Region 3, Chicago, Fuel Facility & Materiale Safety Branch. 79/04/11 2pp.
- --7903240454 IE Insp Repts 50-010/79-07.50-237/79-09 \$ 50-249/79-07 on 790304-07.0312 & 0323 No noncompliance noted Major areas inspected.internal audits, offsite support agency coordination, emergency facilities, training \$ drills GRANT, W B r EBSIOR T Region 9. Chicago, Office of the Director. 79/04/05 5pp
- 7905250280 Responds to IE Builetin 79-03 re welding defects in certain langitudinally welded pipe spools Plents inspected, no pipe found, REED.C. Commonwealth Edison Co. 79/04/12. 2pp.

- 7903010369 Forwards IE Bulletin 79~06A. "Review of Operational Errors! Sys Micallynments Identified During THI Incident "
  KEPPLER, J & Region 3: Chicago, Office of the Director 79/04/14
- 7905040334 Forwards IE Bulletin 79-06B. "Review of Operational Errors's Sys Misalignments Identified During TMI Incident " KEPPLER.J G Region 3. Chicago. Office of the Director 79/04/18
- 7905040529 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During THI Incident " KEPPLER, J & Region 3, Chicago, Office of the Director 79/04/H
- 7905030206 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Ralated Sys " Licensee action required KEPPLER, J & Region 3, Chicago: Office of the Director 79/04/17
- 16
- 7905040142 Forwards IE Bulletin 79-058, "Nuclear Incident at TMI~Suppl. " KEPPLER, J C Region 3. Chicago, Office of the Director 79/04/21
- --7905040138 IE Bulletin 79-038, "Nuclear Incident at TMI-Suppl " Supporting documentation encl
  \* Region 3, Chicago, Diffice of the Director 79/04/21 12pp
- ---7903040170 ACRS recommendations re 790328 incident at TMI Suggests hij priority be placed on development of safety research on behavior of LWRs during anomalous transients a ACRS Advisory Committee on Reactor Safeguards 79/04/17
- --7905040201 Forwards ACRS recommendations re TMI incident, presented 45 790417 FRALEY,R F ACRS — Advisory Committee on Reactor Bafaguards 79/04/18 1p
- --7905040221 In response to NRC 790418 itr.states 790417 ACRS recommendations apply to all PMRs.but were not intended to require immediate changes Plant mods should be made after study of effects on overall safety. TMI excluded CARBON.H X ACRS Advisory Committee on Reactor Safeguards 79/04/20 2pp
- 7905240630 Forwards responses to IE Bulletin 79-07 requesting info re seismic analysis of safety-related piping Reanalysis indicates method of intramodal combination has little effect on pipe stresses & equipment support loads REED, C Commonwealth Edison Co 79/04/24 4pp
- 7905250206 Ack receipt of 790416 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/79-04. 50-237/79-04 & 50-249/79-04 HIND.J A Region 3, Chicago, Safeguards Branch. 79/04/24 lp
- --7905250215 Responds to NRC 790328 ltr re-violations noted in IE into Repts 50-010/79-04, 50-237/79-04 & 50-249/79-04 Corrective actions withheld (ref 10CFR2 790) REED: C Commonwealth Edison Co. 79/04/16 ip
- 790515014B Forwards responses to IE Bulletin 79-06A.Revision i.re
  BHR events identified during TMT-2 Util has formed task
  force to review BHR events & recommend corrective action, as
  required Commonwealth Edison Co 79/04/27 2200 REED, C
- 7905300242 Responds to IE Bulletin 79-04 No 3.4 or 6-inch Velan swing check valves are in use at Dresden or Guad-Cities Review of Zion has identified use of valves in some piping sys but review is incomplete. Will rept later REED.C Commonwealth Edison Co 79/05/01 2pp
- 7905140488 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Recirculation Motor Generator Set Resulted in Reactor Power Increase of KEPPLER, J. D. Region 3. Chicago. Office of the Director 79/05/02
- ---7905140492 IE Circular 79-07. "Unexpected Speed Increase of Reactor Recirculation Motor Generator Bet Resulted in Reactor Power Increase."
  - Region 3. Chicago, Office of the Director. 79/05/GQ 600

#### R Periodic operating reports & related correspondence

7905160354 Forwards monthly operating rept for Apr 1979 BTEPHENSON, B B Commonwealth Edison Co 79/05/08 ip

~~7905160359 Monthly operating rept for Apr 1979 CIESZKIEWICZ, S Commonwealth Edison Co 79/05/03 20pp

DOCKET 50-12 LYNCHBURG POOL REACTOR

J Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,181,140,146,151,161,164,170,173,174,179,189,180,182,185,186,187,188,189,192,193,194,195,197,198,200,201,204,204,207,208,210,212,214,215,5 others QUATTROCHRI,J American Nuclear Insurers 79/05/01 ip

DOCKET 50-13 BABCOCK & WILCOX CO CRITICAL FACILITY

J Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,185,186,187,188,189,192,193,194,195,197,198,200,201,204,206,207,208,210,212,214,215,tothers GUATTROCHHI, J American Nuclear Insurers 79,05701 10

7905300714 Forwards Amend 19 to Indemnity Agreement B-8.per 10CFR140 changes,re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl SALTZMAN,J Antitrust & Indemnity Oroup 79/09/01 Spp

7905290427 Forwards executed Amend 1 to Indomnity Agreement Q-2 & Amend '19 to Indomnity Agreement B-8
OLSEN, A F Babcock & Wilcox Co 79/05/21 3pp

@ Inspection reports, IE Bulletins & correspondence

7905070139 Forwards IE Bulletins 79-05,79-05A \$ 79-06 re nuclear incident at TMI O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/13 in

DOCKET 50-14 BATTELLE MEMORIAL INST CRITICAL FACILITY

J Insurance & indemnity information

7909300065 Forwards Amend 14 to Indemnity Agreement B-6, reflecting change in 10CFR140 reflecting increase in primary layer of liability from \$140 million to \$160 million, effective 790501 Supporting documentation enci.

SALTZMAN, J Antitrust & Indemnity Group 79/05/01 Spp

7905240391 Forwards executed Amend 14 to Indemnity Agreement B-6, effective 790514
BTALL, D H Battelle Memorial Institute, Columbus Laboratories 79709/14
2pp

DOCKET 50-16 ENRIGO FERMI ATOMIC POWER PLANT, UNIT 1 F. Security, medical, emergency & fire protection plans

7905100162 Responds to 790403 telcon & 790405 mailgram re fire protection at facility forwards most recent insp.conducted on 701214 W/o encl.

KEPPLER.J G Region G. Chicago, Office of the Director 79/04/13

J Insurance & indemnity information

7905160353 Forwards Amend 22 to Indemnity Agreement B-20, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl BALTMAN, J Antitrust & Indemnity Group 79/05/01 Spp

7905310451 Forwards Amend 22 to Indomnity Agreement B-20.psr-NRC request
MARGUARDT,P A Detroit Edison Co 79/03/23 2pp

DUCKET 50-18 VALLECITOS BOILING WAYER REACTOR

J Insurance & indemnity information

7905300190 Forwards Amend 20 to Indemnity Agreement 8-11, reflecting change in 10GFR140, increasing primary layer of liability from \$140 million to \$160 million, effective 790501 Supporting documentation encl BALTZMAN, J Antitrust & Indemnity Group 79/05/01 Spp

790515030B Amend 20 to Indemnity Agreement B-11 SALTZMAN,J Antitrust % Indemnity Group 79/05/08 ip

P Operating license stage documents & correspondence

7905090364 Forwards questions of clarification re geologic investigations around test reactor DEVINE, J F Interior, Dept of, Geological Survey 79/05/04 5pp

DUCKET SO-20 MASSACHUSETTS INST OF TECH RES REACTOR

J Insurance & indemnity information

7905160322 Forwards Amend 10 to Indemnity Agreement E-39, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Bupporting documentation encl SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

P Operating license stage documents & correspondence

7905090331 Raises questions as to whether increase in matl science activities are legal Requests advice re required changes to license or Tech Specs before proceeding w/research activities
FECYCH. H Massachusetts Institute of Technology 79/05/04 2pp

8 Reportable occurrences, LERs & related correspondence

7905040480 RO 79-2 on 790410 during completion of startup checklist for less than 100 kW operation.core tank level scram discovered inoperable Caused by shorting between probe conductor lead & casing CLARK.L Massachusetts Institute of Technology 79/04/19 App

DOCKET 50-22 WEST (NOHOUSE TEST REACTOR

J Insurance & indemnity information

7905070497 Confirms in policies NF-1.25,43, 173,174,178,179,180 197,178,200,201,204 GUATTROCHHI,J Ams M4 000 000 844

- DEMART 30-27 MACHINATON STATE UNIV. RESEARCH REACTOR
  Universe & indemnity information
- 74U31A03CO Forwards Amend 12 to Indemnity Agreement E-3B.ppr 10CFR140 khanges.rs increase from 6140 nillion to \$140 nillion. effective 790501 Supporting documentation encl EALTIMAN. J Antitrust & Indemnity Group 79/05/01 Spp
- 7905240472 Forwards accepted Asend 12 to Indennity Agreement E-38 GABE.E. Washington State Univ 79/05/11 2pp
- P Operating license stage documents & correspondence
- 7905310232 Forwards application for renewal of License R-76, revised proposed Tech Specs-EIA, energency plan & univ-financial rept for Fy ended 780630 HILSON W E , NYMAN, C J , SANDE, R D Hashington State Univ-79/03/15 1p
- ~-7909316236 Application for renewal of License R-76
   Washington State Univ 79/05/15 64pp
- --7905310239 Proposed Tech Specs for HA State Univ modified TRIGA reactor w/original Tech Specs & bases
   Washington State Univ 79/05/15 72pp
- ~~7905310242 EIA for continued operation of WA State Univ modified TRIGA reactor
  - \* Washington State Univ 79/05/15 18pp
- --7909310245 HA State Univ Nuclear Radiation Ctr emergency plan

   Washington State Univ 79/05/15 12pp
- DOCKET 30-27 VANKEE-ROWE NUCLEAR POWER STATION

  1 Financial information
- 7905310390 Advises of plan to file annual cash flow statements guarantering payment of retrospective premiums on 790701 VT fankes & CT Yankee will also file statements by 790401 SOUCY. A R Yantee Atomic Electric Co 79/05/23 lp
- J Insurance & indemnity information
- 7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198
- 7905160285 Forwards Amend 12 to Indemnity Agreement B-17.per 10CFR140 changes re increase from \$140 alliion to \$160 million effective 790501 Supporting documentation encl SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp
- 7905160309 Forwards executed Amend 12 to Indemnity Agreement B-17 increasing liability insurance SOUCY.A R Yantee Atomic Electric Co 79/05/09 3pp
- 7905110317 Submits response to NRC 790504 questions re auxiliary

- 7903010327 Forwards IE Info Notice 79-09, "Bpill of Radioactively Contaminated Resin" GRIER, B.H. Region 1. Philadelphia, Office of the Director 79/03/30 ip
- 7905080075 Responds to IE Bulletin 79-03 re langitudinal wold defects
  No action required) seam weld insp requirement in ASME
  Baction III Only plants designed under these rules are
  affected
  MCDDY, D E Yankse Atomic Electric Co 79/04/04 lp
- 7905020114 Forwards IE Bulletin 79-04, "Review of Operational Errors & Sys Misalignments Identified Buring TMI Incident " Licensee action required GRIER.8 H Region 1, Philadelphia, Office of the Director 79/04/11 ip
- P Operating license stage documents & correspondence
- 7905290006 Finds Y00AP-1-A "Operational GA Program," acceptable.tased on review of Revision 6, including Amend 1
  HAAS, W.P. Division of Project Management 79/04/10 2pp
- 7905090022 Forwards topics deleted from systematic evaluation program review of facilities Requests review & identification of errors within 30 days from receipt of ltr
  ZIEMANN,D L Operating Reactors Branch 2 79/04/16 7µp
- 7905020363 Forwards draft evaluation of systematic evaluation prograss Topic IV-1-A. "Operation W/Less than All Loops in Syc " Requests review & response within 30 days ZIEMANN,D L Operating Reactors Branch 2 79/04/18 Upp
- 7903030333 Discusses loss of feedwater transient analysis repurted on 790417 Analysis error was found in inverted GEMINI code & incorrect assumption in analysis of reactor coolant pump operation following trip GROCE, R H Yankee Atomic Electric Co 79/04/23 3pp
- 7905250040 Summary of 790321 mesting w/util & Weston Geophystial reongoing review of systematic evaluation program topics: kydrology, seismic design & pipe breaks inside containment BURGER, A Operating Reactors Branch 2 79/04/24 App
- 7905290058 Responds to 790413 request rs QA program Buggests revision number of YQQAP-1-A not be designated.
  HEIDER.L H Yankee Atomic Electric Co 79/04/24 1p
- 7905070548 Forwards Revision 6.5 Amend 1 to Revision 6 of operational 8A program as requested in 790410 ltr GRGCE,R H. Yankee Atomic Electric Co. 79/04/30 4pp
- --7905070553 Informs that revisions to QA program are acceptable HAASS, H P Quality Assurance Branch. 79/04/10 1/pp
- 7905020311 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required GRIER, B H Region 1, Philadelphia, Office of the Director 79/04/14 ip
- 7905040113 Forwards IE Bulletin 79-06B, "Review of Operational Profe & Bus Missalignments Identified During TMI Incident "
  REIER,B.H Region I. Philadelphia, Office of the Director
  79/04/14 lp
- 7905040301 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Hater Power Reactors Identified During TMI Incident " GRIER.B H Region 1, Philadelphia, Office of the Director 79/04/14, 1p
- 7905030112 Forwards IE Bulletin 79-09, "Failures of GE Type AK 2 circuit Breaker in Safety-Related Bys " Licensee action or CEER.B H Region 1, Philadelphia, Office of the Director 79/04/17 1p
- 7905020341 Forwards IE Bulletin 79-06A.Revision 1. "Review of Operational Errors & Sys Misalignments Identified During TM1 (RIER, B H Region 1, Philadelphia, Office of the Director 79/04/18 1p
- 7905250452 Responds to IE Bulletin 79-07. "Beismic Stress Analysis of Safety-Related Piping " Unit was designed using nondynamic thods of analysis OCE,R H Yankee Atomic Electric Co 79/04/24, ip

- 7905250359 Responds to IE Bulletins 79-06,79-06A & 79-06A,Revision i.re
  TMI errors Outlines changes in operating procedures,
  preventative measures taken Supporting personnel briefing &
  documentation enc!
  MCDBy D E Yantes Atomic Electric Co 79/04/26 9pp
- R Periodic operating reports & related correspondence
- 7905150334 Forwards monthly operating rept for Apr 1979 MODDY.D E Yankee Atomic Electric Co 79/05/12 ip
- --7905150337 Monthly operating rept for Apr 1979 SJOGREN,R M Yankee Atomic Electric Co 79/05/12 Spp
- S Reportable occurrences. LERs & related correspondence
- 7905150422 Forwards LER 78-012/03L-1 AUTIO,H A Yankee Atomic Electric Co 79/05/11 ip
- --7905150428 LER 78-012/03L-1 on 780419 level of primary seal tank found to be decreasing at faster rate than normal Caused by crack in carbon ring of mechanical seal Seal replaced MAY.E L Yankee Abomic Electric Co 79/05/11 ip
- 7905150433 Forwards LER 79-014/O3L-0 AUTIO,H A Yankee Atomic Electric Co 79/05/11 1p
- -~7905150437 LER 79-014/03L-0 on 790412 CA-V-688 valve failed containment leakage rate Causad by crud on valve seating surface Valve isolated, cleaned, retested & returned to svc MAY,E L Yankee Atomic Electric Co 79/05/11 ip
- 7905190126 Forwards LER 79-010/04X-0
  AUTIO, H A Yankee Atomic Electric Co 79/05/14 in
- --7905190128 LER 79-010/04X-0 on 790213 while performing insp on air sample pump station A-3.air sample pump found inoperative Caused by bearing failure on motor shaft Bearing replaced MAY/E L Yankee Atomic Electric Co 79/03/14 ip

DOCKET 50-30 PLUM DROOK REBEARCH REACTOR FACILITY

- J Insurance & indemnity information
- 79051602B0 Forwards Amend 14 to Indomnity Agreement D-3, per iOCFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl BALTZMAN.J Antitrust % Indomnity Group 79/05/01 Spp
- 7905190171 Amend 14 to Indemnity Agreement D-3 between NASA & AEC SALTZMAN.J Antitrust & Indemnity Group 79/05/07 1p

DOCKET 50-32 AEROJET GENERAL NUCLEONICE

- J Insurance & indemnity information
- 7905300059 Forwards Amend 17 to Indemnity Agreement 8-2, reflecting change in 100FR140, increasing primary layer of liability from \$140 million to \$160 million effective 790501 Supporting documentation encl SALTZMAN, J Antitrust & Indemnity Group 79/05/01 Spp
- 7905240357 Forwards executed Amend 17 to Indemnity Agreement 8-2 NEWACHECK, R. L. Aerotest Operations 79/05/15 2pp

DOCKET 50-37 TRIGA-MARK I PROTOTYPE REACTOR

- J Insurance & indemnity information
- 7905300202 Forwards Amendment 31 to Indomnity Agreement 8-9, reflecting change in 10CFR140, increasing primary layer of liability from \$140 million to \$160 million, effective 790901 Supporting documentation encl SALTZMAN, J Antitrust & Indomnity Group 79/05/01 Spp

DOCKET 50-47 ARMY MATERIALS RESEARCH REACTOR

- J Insurance & indemnity information
- 7905160278 Forwards Amend 11 to Indemnity Agreement D-7.per 10CFR140 changes.re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl BALTZMAN.J Antitrust & Indemnity Group 79/05/01 Spp

7905160431 Furwards Amend 11 to Indemnity Agreement D-7 D'KEEFE.A J Army Dept of Hatls & Mechanics Research Center 79/05/09 2pp

DOCKET 50-53 AEROJET GENERAL NUCLEONICS

- J Insurance & indemnity information
- 7905300059 Forwards Amend 17 to Indomnity Agreement B-2, reflecting change in 10CFR140, increasing primary layer of liability from \$140 million, effective 790501 Eupporting documentation enci SALTZMAN, J Antitrust & Indomnity Group 79/05/01 Spp
- 7905240357 Forwards executed Amend 17 to Indemnity Agreement B-2 NEWACHECK.R L Aerotest Operations 79/05/15 2pp

DOCKET 50-94 UNION CARBIDE RESEARCH REACTOR

- J Insurance & indemnity information
- 7905160348 Forwards Amend 11 to Indemnity Agreement B-14.per 10CFR140 thanges.re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl SALTZMAN, J Antitrust & Indemnity Group 79/05/01 Spp
- P Operating license stage documents & correspondence
- 7905010531 Provides responses to proposed Tech Spec items re potential reactivity, organization chart & definition of "unplanned transients"

  OEURCE.K D Union Carbide Corp 79/04/10 9pp
- 7905010495 Ack 790412 telcon re Tech Spec mode Details requested changes re liquid efficent releases
  GEORGE.K D Union Carbide Corp 79/04/16 2pp

DOCKET 50-57 STATE UNIV OF NEW YORK RESEARCH REACTOR

- J Insurance & indemnity information
- 7905160332 Forwards Amend 12 to Indemnity Agreement E-34, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl BALTZMAN, J Antitrust & Indemnity Group 79/05/01 Spp
- P Operating license stage documents & correspondence
- 7905190019 Requests change to Tech Specs re present period reversal & scram GRLOSKY,P M New York, State Univ of Buffalo 79/01/09 2pp

DUCKET 90-99 TEXAS AND UNIV RESEARCH REACTOR

- J Insurance & indomnity information
- 7905160343 Forwards Amend 14 to Indemnity Agreement E-12, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790801 Supporting documentation enci BALIZMAN, J Antitrust & Indemnity Group 79/05/01 Spp

DOCKET 50-62 UNIV OF VIRGINIA RESEARCH REACTOR

- J Insurance & indemnity information
- 7905230456 Forwards Amend 12 to Indemnity Agreement E-28, per iOCFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl BALIZMAN, J Antitrust & Indemnity Group 79/05/01 Spp
- 7905240462 Forwards accepted Amend 12 to Indemnity Agreement E-28. effective 790516

  JENNINOS,D W Virginia, Univ of 79/05/17 2pp
- G. Inspection reports, IE Bulletins & correspondence
- 7905070148 Forwards IE Bulletins 79-03,79-05A & 79-06 re nuclear incident at TMI U'REILLY, P Region 2, Atlanta, Office of the Director 79/04/13 ip

DOCKET 50-70 GENERAL ELECTRIC TEST REACTOR

- E NRC Safety Evaluation Report (SER), supple & correspondence
- 7905160428 Requests review of geologic rept & probability analysis be expedited so SER can be issued DARMITZEL.R W General Electric Co Nuclear Energy Products Div 79/05/09 1p
- J Insurance & indemnity information
- 7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,183,187,188,187,193,194,175,197,179,200,201,204,206,207,208,210,212,214,215,6 others GUATTROCHHI, J American Nuclear Insurers 79/05/01 ip
- 7905070582 Confirms increase in liability limit to \$36.000.000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 50, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96, 80BERTS, D M Mutual Atomic Energy Liability Underwriters 79/05/01 ip
- 7905300190 Forwards Amend 20 to Indemnity Agreement B-fi, reflecting change in EOCFR140, increasing primary layer of tiability from \$140 million to \$160 million, effective 790501 Supporting documentation encl BALTZHAN, J Antitrust & Indemnity Group 79/05/01 Spp
- 7905150308 Amend 20 to Indemnity Agreement 8-11 SALTIMAN, J Antitrust & Indemnity Oroup 79/05/08 tp

DOCKET 50-72 UNIV OF UTAH RESEARCH REACTOR

- J Insurance & indemnity information
- 7905300034 Forwards Amend 10 to Indemnity Agreement E-GI.reflecting change in 10CFR140.increasing primary layer of liability from \$140 million to \$160 million.effective 790501 Supporting documentation encl SALTIMAN.J Antitrust & Indemnity Group 79/05/01 App
- 7905140201 Amend 10 to Indemnity Agreement E-31 BALTZMAN, J Antitrust & Indemnity Group 79/05/07 ip
- Q Inspection reports, IE Bulletins & correspondence
- 7905010695 Ack receipt of 790302 ltr informing NRC of steps taken to correct violations noted in IC Inap Rept 50-072/79-01 MADSEN.O L Region 4. Dallas. Reactor Operations Nuclear Support Branch. 79/03/29 ip
- ---7905010661 Responds to NRC 790208 ltr re violations nated in IE Insp Rept 50-072/79-01 Corrective actions reactor log corrected to include radiation survey around reactor seals TURLEY.R E Utah, Univ of 79/03/02 2pp

DOCKET 50-73 GENERAL ELECTRIC NUCLEAR TEST REACTOR

J Insurance & Information

- 7905300190 Forwards Amend 20 to Indemnity Agreement B-ii, reflecting change in 10CFR140; increasing primary layer of liability from \$140 million to \$160 million, effective 790501 Supporting documentation encl.

  BALTIMAN, J Antitrust & Indemnity Group, 79/05/01 Spp
- P. Operating license stage documents & correspondence
- 7905190154 Notifies that GE will have resources necessary to decommission reactor REATON:R.H. General Electric Co. 79/05/14., ip

DOCKET 50-77 CATHOLIC UNIV OF AMERICA RESEARCH REACTOR

J Insurance & indemnity information

- 7905:60122 Forwards Amend 9 to Indemnity Agreement E-2, per 100FR140 changes.rs [/ability insurance increase from #140 million to #160 million, effective 790501 Bepporting documentation encl SALTZMAN, J Antitrust & Indemnity Group 79/05/01. Spp.
- 7905130479 Forwards Amend 9 to Indemnity Agreement E-2. LOWE, V. P. Catholic Univ 79/05/10. 2pp.

- P Operating license stage documents & correspondence
- 7905090279 Forwards correction to page 16-4 in Amend 7 for License R-31 REID, R W Operating Reactors Branch 4 79/04/09 Jpp
- R Periodic operating reports & related correspondence
- 7905010539 Announces plan to restart AON-201 reactor on 790509 NRC representative invited to attend Forwards "Annual Operating Rapt 1978 "
  UORDAN, E D Catholic Univ 79/04/20 11pp
- --7905010547 "Annual Operating Rept 1978 " EBERT, D D , KEENE, H E , JORDAN, E D Gatholic Univ 79/04/06

DOCKET 50-83 UNIV OF FLORIDA TRAINING REACTOR

J Insurance & indemnity information

1100

- 7905160167 Forwards Amend 9 to Indemnity Agreement E-18, per 10CFR140 changes: re liability insurance increase from #140 million to #160 million effective 790501 Supporting documentation encl. SALTZMAN, J Ancitrust & Indemnity Group 79/05/01 Spp
- @ Inspection reports. IE Bulletins & correspondence
- 7905070142 Forwards IE Bulletins 79-05.79-05A & 79-06 re nuclear incident at TMI O'REILLY, J P Region 2. Atlanta, Office of the Director 79/04/13 lg

DOCKET 50-84 UNIV OF CALIFORNIA RESEARCH REACTOR

J Insurance & indemnity information

7905300032 Forwards Amend i3 to Indemnity Agreement E-15, reflecting change in IOCFR140, increasing primary layer of liability from \$140 million to \$150 million, effective 790501 Supporting documentation entl BALTZMAN, J Antitrust & Indemnity Group 77/05/01 Spp

DOCKET 50-87 WESTINGHOUSE CRITICAL EXPERIMENT

- J Insurance & indemnity information
- 7905;60249 Forwards Amend B to Indemnity Agreement B-56, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790801 Supporting documentation encl SALTZMAN, J Antitrust & Indemnity Oroup 79/05/01 Spp

DOCKET 50-89 GENERAL ATOMIC CO

- J Insurance & indemnity information
- 7905300202 Forwards Amendment 31 to Indemnity Agreement 8-9, reflecting change in iOCFR140, increasing primary layer of liability from \$140 million to \$150 million, effective 790501 Supporting documentation sncl SALTZMAN, J Antitrust & Indemnity Group 79/05/01 Spp

DOCKET 50-74 ROCKWELL INTERNATIONAL RESEARCH REACTOR
J Insurance & indemnity information

7705160320 Forwards Amend 15 to Indemnity Agreement B-13, per 100fR140 changes re increase from \$140 million to \$160 million, effective 770501, Supporting documentation encl.

MALTZMAN.J. Antitrust & Indemnity Group, 79/05/01 5pp

DOCKET 50-97 CORNELL UNIV ZERO POWER REACTOR
J Insurance & Indemnity Information

7903300038 Forwards Amend 11 to Indemnity Agreement E-4, reflecting change in 10CFR140, increasing primary layer of liability from \$140 million to \$160 million, effective 790301. Supporting documentation encl BALTZMAN, J Antitrust & Indemnity Group 79/05/01. Spp

# DOCKET 50-99 BABCOCK & WILCOX TEST REACTOR J Insurance & indemnity information

7905300714 Forwards Amend 19 to Indemnity Agreement B-B.per 10CFR140 changes.re increase from \$140 million to \$160 million. effective 790501 Supporting documentation encl SALTZMAN, J Antitrust & Indemnity Group 79/05/01

# P Operating license stage documents & correspondence

7705140411 Submits annual operations rept for 1975 GLSEN.A F Babcock & Wilcox Co 76/02/24 9pp

790514041A Submits annual operations rept for 1976 GLSEN, A F Babcock & Wilcox Co 77/02/23 Spp

7905140408 Bubmits annual operations rapt for 1977 QUSEN, A F Babcock & Wilcox Co 78/02/27 9pp

7905110309 Forwards additions to License R-47, renewal application & proposed Tech Specs for power limits
OLSEN, A F Babcock & Wilcox Co 79/05/01 2pp

#### Q Inspection reports. IE Bulletins & correspondence

7905070159 Forwards IE Bulletins 79-05, 79-05A & 79-06 re nuclear incident at TMI O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/13 10

## R Periodic operating reports & related correspondence

7905140383 Forwards "Annual Rept 1978 "
OLSEN, A.F. Babcock & Wilcox Co. 79/02/28 1p

--7905140384 "Annual Rept 1976" "
\* Babcock & Wilcox Co 79/02/01 Spp

DOCKET 50-103 AEROJET GENERAL NUCLEONICS
J Insurance & indumnity information

7905300059 Forwards Amend 17 to Indemnity Agreement B-2 reflecting change in 10CFR140 increasing primary layer of liability from \$140 million to \$160 million effective 790501 Supporting documentation encl GALTZMAN. J Antitrust & Indemnity Group 79/05/01. Spp

7905240357 Forwards executed Amend 17 to Indomnity Agreement B-2. NEWAGHECK, R.L. Agratest Operations 79/05/15 2pp

## DUCKET 50-106 OREGIN STATE UNIV

J Insurance & indemnity information

7905160326 Forwards Amend 12 to Indemnity Agreement E-11.per 10CFR140 changes.re increase from \$140 million to \$160 million, effective 790501 Bupporting documentation encl BALTZMAN.J Antitrust & Indemnity Group 79/05/01 5pp

## DOCKET 50-111 NORTH CAROLINA STATE UNIV RESEARCH REACTOR

J Insurance & indomnity information

7905300069 Forwards Amend 15 to Indemnity Agreement E-7, reflecting change in 10CFR140, increasing primary layer of liability from \$140 million to \$160 million, effective 770501 Supporting documentation encl EALTZMAN, J Antitrust & Indemnity Group 79/05/01. Spp

7905310452 Forwards Amend 15 to Indemnity Agreement E-7. Requests change in addressee for correspondence. BOHANNON, J R North Carolina State Univ 79/05/25 2pp

## Q Inspection reports, IE Bulletins & correspondence

7903070146 Forwards IE Builetins 79-05.79-05A & 79-06.re nuclear incident at TMI O'REILLY, J P Region 2, Atlanta, Défice of the Director 79/04/13 is

DOCKET 30-112 UNIV OF OKLAHOMA RESEARCH REACTOR

J Insurance & indemnity information

7905160236 Forwards Amend 9 to Indemnity Agreement E-26, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl SALIZMAN, J. Antitrust & Indemnity Oroup 79/05/01 5pp

## G. Inspection reports, IE Bulletine & correspondence

7905150578 Forwards IE Insp Rept 50-112/79-01 on 790412-13 No noncompilance nated MADSEN Q L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/03/30 2pp

--79031505B4 IE Insp Rept 50-112/79-01 on 790412-13 No noncompliance noted Major areas inspected security organization-physical barriers.access control detection aids & testing of security equipments Details withheld (ref 10CFR2 790)
CALDMELL.R A Region 4, Dallas, Office of the Director.
RADSEN.G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/04/27 1p

DOCKET 50-113 UNIV OF ARIZONA RESEARCH REACTOR

J. Insurance & indemnity information

7905160203 Forwards Amend 9 to Indemnity Agreement E-14, per 10CFR140 changes are liability insurance increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl SALTMAN, J. Antitrust & Indemnity Group 79/05/01 Spp

7905240607 Forwards executed Amend 9 to Indemnity Agreement E-14 CARR.8 E Arizona, Univ of 79/05/10 2pp

## DOCKET 50-116 IOWA STATE UNIV RESEARCH REACTOR

J Insurance & indemnity information

7905160106 Forwards Amend 9 to Indemnity Agreement E-5.per 10GFR140 changes, re liability insurance increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl SALTMAN, J Antitrust & Indemnity Group 79/05/01. Spp

7905160296 Forwards signed Amend 9 to Indemnity Agreement E-5. increasing liability insurance from \$140 to \$160 million 8UDBECK.R R Iowa State Univ 79/05/09. 2pp

## G Inspection reports, IE Bulletins & correspondence

7905160488 Ack receipt of 790404 ltr informing NRC of steps taken to correct violations noted in IE insp on 790222-R3 HIND, J A Region 3, Chicago, Bafeguards Branch, 79/04/18 ip.

--7905160489 Responds to NRC 790313 ltr re violations noted in IE insp on 790222-23 Corrective actions withheld (ref 10CFR2 790). BURNET, Q I cwa State Univ 79/04/04 2pp.

# DOCKET 50-123 UNIV OF MISSOURI RESEARCH REACTOR

J Insurance & Indemnity information

7905160336 Forwards Amend 10 to Indemnity Agreement E-23, per 10CFR140 changes; re increase from \$1.40 million to \$160 million, effective 790501 Bupporting documentation encl BALTZMAN, J Antitrust & Indemnity Oraup. 79/05/01. Spp

7905310401 Forwards executed Amends 10 & 11 to Indemnity Agreements E-23 & E-25, respectively.

8LANBETT, V. Missouri, Univ. of. 79/05/25, Spp

#### R Periodic operating reports & related correspondence

- 7905220089 Forwards progress rept for Apr 1978-Mar 1979 for Rolla nuclear reactor facility EDWARDS, D.R. Missouri, Univ. of 79/04/30 lp
- --7905220090 Progress rept for Apr 1978-Mar 1979 for Folla nuclear reactor facility ELLIGIT.A E Missouri. Univ of 79/04/30 (00pp
- DOCKET 50-124 VERGINIA POLYTECH INST. TRAINING REACTOR

  J. Insurance & indemnity information
- 7905160308 Forwards Amend 12 to Indemnity Agreement E-33.per 10CFR140 changes.re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl SALTZMAN.J Antitrust & Indemnity Group 79705/01 Spp
- 7905150363 Amend 12 to indemnity Agreement E-33, increasing liability coverage from \$140 million to \$160 million SALTZMAN. \$\( \square\) Antitrust & Indemnity Group \( 79/05/t0 \) 1p
- Q inspection reports: IE Bulletins & correspondence
- 7705010193 Forwards IE Insp Rept 50-124/79-01 on 790129-31 No concompliance noted SUTHERLAND, J T Region 2. Atlanta, Fuel Facility & Materials Safety Branch 79/03/16 2pp
- --7905010207 IE Insp Rept 50-124/79-01 on 790129-31 No noncompliance noted Hajor areas inspected radiation protection re procedures, posting, labeling, dosimetery, training, surveys & instrument calibr
  EMALD: S C , Olascus, A F Region 2, Atlanta, Fuel Facility & Hatertals Safaty Branch 79/03/09 7pp
- 7905240474 Forwards [E Insp Rept 50-124/79-04 on 790320-0321 No noncompliance noted LEWIS.R.C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 79/04/04 2pp
- --7905240480 IE Insp Rept 80-124/79-04 on 790320-0321 No noncompliance noted Major areas inspected refueling operations & associated radiological controls
  JULIAN.C A Region 2. Atlanta, Office of the Director MARTIN.R D Region 2. Atlanta, Reactor Operations Nuclear Support Branch 79/04/02 Spp
- 790507013B Forwards 1E Bulletins 79-05,79-05A & 79-06,10 nuclear incident at TMI O'REILLY,J P Region 2: Atlanta, Office of the Director 79/04/13 1p
- POCKET 50-128 TEXAS A&M UNIV RESEARCH REACTOR
  P Operating license stage documents & correspondence
- 7905150772 Requests add1 info to complete review of proposed amend, including effects of blast-part beam strength & transportation of explosive math REID.R U Operating Reactors Branch 4 79/03/30 2pp
- 7905230836 Notifies of pending license aspiration Forwards license renewal review items Application for renewal must be filed at least 30 days prior to expiration REID.R W Operating Reactors Branch 4 79/04/25 10cm

- Q Inspection reports, (E Bullatins & correspondence
- 7905070196 Forwards IE Bulletins 79-05,79-05A & 79-06, ro harlear incident at TMI O'REILLY,J P Region 2, Atlanta, Office of the Director 79/04/13 ip
- DOCKET 50-131 OMAHA VET ADMIN HOSP RESEARCH REACTOR
  F Security, medical, emergency & fire protection plans
- 7905140192 Forwards physical security plan Plan withheld (ref 10CFR2 790) BLOTCKY.A J Vet Admin Hosp NE/OM 79/05/10 1p
- J Insurance & indemnity information
- 7905160297 Amend 8 to Indemnity Agreement D-8, increasing liability coverage from \$140 million to \$160 million SALTZMAN, J Antitrust & Indemnity Group 79/05/09 1p
- P Operating license stage documents & correspondence
- 7905140198 Forwards application for renewal of License R-5/ BLOTCKY, A J Vet Admin Hosp NE/OM 79/05/10 ip
- --7905:40201 Applies for renewal of License R-57 Forwards application supporting documentation MULLON, T.P. Vet Admin Hosp NE/OM, 79/08/10 ip
- --7705140204 Application for renewal of License R-57

  \* Vet Admin Hosp NE/DM 79/05/10 70pp
- DOCKET 50-133 HUMBOLT BAY POWER PLANT, UNIT 3
- 9 Adjudicatory correspondence
- 7905030048 Forwards Lewis Committee rept (NUREO/CR-0400).NHL publics statement on reactor safety study (NASH-1400).its review by Lewis Committee & survey of NRC uses of HASH-1400 MULKEY! M & Branch 2 79/03/30 2pp
- 7703070227 Notification of resignation of DE Pesonen as counset for interviewors Intervenors will continue to be represented by LJ Brown & Bierra Club Legal Defense Fund, PESONEN, DE Garry, Drøyfus, McTernan, Brotsky, Herndon & Pesanetina 79/04/04 ip.
- I Financial information
- 7903300168 Forwards "Annual Financial Rept 1978 " CRANG.P.A Pacific Gas & Ejectric Co 79/05/23 1p
- ---7905300174 "Annual Financial Rept 1978 "
  \* Pacific Gas & Electric Co 78/12/31 40pp
- 7905300510 Forwards "Estimated Internal Fund Generation for CY/V\* t
  "Annual Financial Rept 1978"

  CRANE.P A Pacific Gas & Elactric Co. 79/05/24 3pp
- --7905300529 "Annual Financial Rept 1978"

  \* Pacific Gas & Electric Co. 79/02/29 36pp
- J Insurance & indemnity information
- 7905160278 Forwards Amend 21 to Indemnity Agreement B-21, per 100/Astarchanges, re increase from \$140 million to \$140 million, effective 790501 Supporting documentation encl
  SALTZMAN, J Antitrust & Indemnity Group. 79/05/01 Sap
- 7905140406 Forwards Amends executed Amends 21 & 4 to Indemnity Agreements B-21 & B-75, respectively CRANE, P. A Pacific Gas & Electric Co. 79/05/08 3pp

#### P Operating license stage documents & correspondence

- 7905290011 Responds to 790313 ltr Lists references to specific docketed info describing operational GA program CRANE.P A Pacific Gas & Electric Co 79/04/20 1p
- 7905300208 Forwards summary of EDS Nuclear, Inc resolution/documentation of elbow flexibility error which existed in versions of PISOL piping analysis computer program from Jan-Oct 1969 Review & reanalysis included all work through Dec 1970 PORTER, F L EDS Nuclear, Inc 79/05/21 9pp
- --7905300263 Forwards EDS Nuclear Inc list of BWRs & piping sys which could have been impacted by deficient computer program OE has no record of reanalysis for Cooper piping sys STEPHENS,P W General Electric Co . Nuclear Energy Products Div 79/01/24 iBpp

#### G Inspection reports, IE Bulletins & correspondence

- 7905010287 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping" ENGELKEN,R H Region 4, Dallas, Office of the Director 79/03/23'
- 7905040081 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks "
  ENGELKEN, R H Region 5, San Francisco, Office of the Director
  79/03/24 in
- 7905010216 Forwards IE info Notice 79-08, "Interconnection of Contaminated Bys w/Svc Air Sys Used as Source of Breathing Air " ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/03/28 ip
- 7905010423 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin" ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/03/30 10
- 7905010023 Forwards IE Builetin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "ENGLIKEN,R H Region 5, San Francisco, Office of the Director 7900414 10
- 7905040508 Forwards IE Bulletin 79-068, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/04/14 io

#### G Inspection reports, IE Bulletins & correspondence

- 7703070099 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping " Licensee action required ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/14 is
- 7905030288 Forwards IE Bullstin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " Licensee action required ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/04/17 1p
- 7905150809 Responds to IE Bulletin 79-01, "Environ Qualification of Class IE Equipment" Will provide schedule for submission of info affer seismic issues have been resolved CRANE,P A Pacific Oas & Electric Co. 79/04/20 ip
- 7908080368 Forwards IE Hulletin 79-058, "Nuclear Incident at TMI-Buppl" ENOELKEN,R H Region 5, San Francisco, Office of the Director 79/04/21, ip

# R Periodic operating reports & related correspondence

- 7905090318 Forwards "Quarterly Status Rept of Investigations & Mods." Jan-Mar 1979, Rept 21 CRANE.P A Pacific Gas & Electric Co. 79/05/03. 1p
- 7705190130 Forwards monthly operating rept for Apr 1979 WEEKS,E D Pacific Oas & Electric Co. 79/05/11 ip
- ---7905190132 Monthly operating rept for Apr 1979.
  \* Pacific Gas & Electric Co. 79/05/02 4pp

## 8 Reportable accurrences, LERs & related correspondence

- 7905150060 Forwards PNO-79-67L ENGELKEN.R H Region 5. San Francisco. Office of the Director 79/04/06. ip
- 7903140303 Forwards LER 78-004/03L-1 CRANE,P A Pacific Oas 5 Electric Co 79/04/09 1p
- --7905140304 LER 78-004/03L-1 on 781219 redundant gas treatment sys do fan operated below required design flow & pressure dropped across gas scrubber column Caused by apparent packing blockage in scrubber column Packing replaced GETTY.B C Pacific Gas & Electric Co 79/04/09 ip
- 7905150167 Forwards PNO-79-67R ENGELKEN.R H Region 5, San Francisco, Office of the Director 79/04/11. io
- 7903040123 Forwards PNO-79-678 EMGELKEN, R H Region 3. San Francisco. Office of the Director 79/04/12 1p
- 7905150141 Forwards PND-79-67T EMBELKEN:R H Region 5, San Francisco, Office of the Director 79/04/13 ip
- 7903030045 Forwards PND-79-67U ENGELKEN,R H Region 5. San Francisco. Office of the Director 79/04/14. 1P
- 7905020527 Forwards PNO-79-67AA ENGELKEN:R H Region 5, San Francisco, Office of the Director 79/04/20 ip
- 7905010425 Forwards PNO-79-67AB ENGELKEN,R H Region 5, San Francisco, Office of the Director, 79/04/21 lp
- 7905010444 Forwards PNG-79-67AC & AD ENGELKEN,R H Region 5, San Francisco, Office of the Director. 79/04/23 1p
- 7904300484 Forwards PNO-79-67AE ENGELKEN,R H Region 5, San Francisco, Office of the Director. 79704/24. 1p
- 7905020227 Forwards PNO-79-67AF ENGLIKEN,R H Region 5, San Francisco, Office of the Director. 79/04/25 ip
- ---7905020230 PND-79-67AF, summary of info re nuclear incident as of 790425.Describes plant status & environ status.Highest thermocouple reading 312 F. \* Office of Inspection & Enforcement. 79/04/25 SPP.
- 7905020236 Forwards PNO-79-67AO ENGELKEN, R. H. Region 5: Ban Francisco, Office of the Director.
- --7903020260 PNO-79-67A0: summary of info re nuclear incident as of 790426 Describes plant status & environ status Highest incore temp reading is 311 F PAULUS; R C . THOMPSON, D. Office of Inspection & Enforcement. 79/04/26 2pp.
- 7905090005 Forwards PNG-79-67AM.
  ENGLEKEN:R H Region 5, Ban Francisco, Office of the Director. 79/04/27 in
- 7905040339 Forwards PNO-79-67AI.AJ & AK per NRC 790401 ltr transmitting IE Bulletin 79-05.
  ENGELKEN.R.H Region 5: San Francisco, Office of the Director.
  79/04/30. 10
- --7905040360 PNO-79-67AI summary of info re nuclear incident as of 790428 Describes plant & environ status \* Office of Inspection & Enforcement. 79/04/28. 2pp
- --7905040365 PND-79-67AK summary of info re nuclear incident as of 790429 Describes plant & environ status # Office of Inspection & Enforcement. 79/04/30. 2pp.

7905070007 Forwards PNO-79-67AL.per NRC 790401 itr transmitting IE Bulletin 79-05 ENGELKEN.R H Region 5. San Francisco, Office of the Director 79/05/01 ip

7905170072 Forwards PNO-79-67AM ENGELKEM, R H Region 5, San Francisco, Office of the Director 79/05/07 1p

DOCKET 50-134 MORGESTER POLYTECH INST RESEARCH REACTOR

J Insurance & Indemnity information

7905160205 Forwards Amend 9 to Indemnity Agreement E-36, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN.J Antitrust & Indemnity Group 79/05/01 5pp

7905:10298 Forwards Amend 9 to Idemnity Agreement E-36 LLDYD,D E Worcester Polytechnic Inst 79/05/08 2pp

DOCKET 50-139 UNIV OF WASHINGTON RESEARCH REACTOR

J Insurance & indemnity information

7905160192 Forwards Amend 9 to Indemnity Agreement E-29, per 10CFR140 changes, re liability insurance increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN.J Antitrust & Indemnity Group 79/05/01 5pp

DUCKET 50-141 STANFORD UNIV RESEARCH REACTOR

J Insurance & indemnity information

7905150386 Forwards Amend 9 to Infamnity Agraement E-19, per 10CFR140 changes, reincrease from \$140 million to \$160 million, effective 790501 Supporting documentation encl SALIZHAN, J Antitrust & Indamnity Oroup 79/05/01 Spp

7905240387 Forwards executed Amend 9 to Indomnity Agreement E-19, effective 790514 BETH,R M Stanford Univ 79/05/14 2pp

DOCKET 50-142 UCLA TRAINING REACTOR

J Insurance & indemnity information

7905160235 Forwards Amend 8 to Indemnity Agreement E-16.per 10CFR140 changes re 1;3511fty insurance increase from \$140 million to \$160 million, effective 790801 Supporting documentation encl SALTEMAN.J. Antitrust & Indemnity Oroup 79708701 Spp

G Inspection reports, IE Builetins & correspondence

7905020513 Forwards IE Insp Rept 50-142/79-01 on 790212-15,28 & 0301 No noncompliance noted BOOK, H E Region 5, San Francisco, Fuel Facility & Materials Bafety Branch 79/03/02 2pp

--7905020520 IE Insp Rept 50-142/79-01 on 790212-13,28 t 0301 No noncompliance noted Major areas inspected environ protection, semergency planning, radiation control t independent insp effort
THDMAS,R.D Region 5, San Francisco, Office of the Director BOOK H E Region 5, San Francisco, Fuel Facility & Materials Safety Branch 79/03/02. 7pp

BOCKET 50-146 BAXTON NUCLEAR EXPERIMENTAL FACILITY

J. Insurance & indemnity information

DOCKET 50-148 UNIV OF KANSAS RESEARCH REACTOR

J Insurance & indemnity information

7903140160 Forwards Amend 9 to Indemnity Agreement E-21, per 10CFR140 changes, re liability insurance increase from 4140 million to \$160 million.effective 790301 Supporting documentation encl SALTZMAN, J Antitruet & Indemnity Group 79/03/01 Spp

7905160117 Forwards Amend 9 to Indemnity Agreement E-B, per 10CFR140 changes: re liability insurance increase from \$140 million to \$160 million effective 7905012 Supporting documentation encl SALTEMAN, J Antitrust & Indomnity Group 79/05/01 5pp

DOCKET 50-151 UNIV OF ILLINGIS RESEARCH REACTOR

J Insurance > indemnity information

7905150370 Forwards Amend 12 to Indemnity Agreement E-20, per 10CFR140 changes.re increase from \$140 million to \$160 million, offective 790501 Supporting documentation encl SALTZMAN, J Antitrust & Indemnity Group 79/05/01 Spp

DOCKET 30-155 BIG ROCK POINT NUCLEAR PLANT

C Utility Environmental Report (ER), amends & correspondence

790501049B Forwards add1 info re systematic evaluation program Topic VII-1-A requested by D MacDonald on 790306 Discusses isolation of reactor protection sys inputs from failures in glant computer CASHELL.8 Consumers Power Co 79/04/18 12pp

F Security, medical, emergency & fire protection plans

7905140211 Provides schedule for submittal of addl fire protection inforper NRC 790404 request HOFFMAN.D P Consumers Power Co 79/05/09 2pp

J Insurance & indemnity information

7905160291 Forwards Amend 16 to Indemnity Agreement B-22.per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl BALTZMAN, J Antitrust & Indemnity Group 79/05/01 Spp

7905190484 Forwards executed Amend 16 to Indemnity Agreement 8-22 BORIE, W. R. Consumers Power Co. 79/05/10 2pp

7905250303 Forwards replacement copy of Amend 1 to Indomnity Agreement B-22.Ack 790510 telcon confirming original copy.dtd 620905, was transmitted to NRC BORIS.W R Consumers Power Co 79/05/21 3pp

P Operating license stage documents & correspondence

7905180648 Forwards Amend 27 to License DPR-06 % notice of issuance & availability Security plan evaluation withheld (ref 10CFR2 790)
ZIEMANN, D L Operating Reactors Stanch 2 79/04/10 Jpp.

--7905150707 Amend 27 to License DPR-06, revising security plan ZIEMANN, D L Operating Reactors Branch 2 79/04/10 2pp

--7903150715 Notice of issuance & availability of Amend 27 to License DPR-06 ZIEMANN.D.L. Operating Reactors Branch 2, 79/04/10 2pp

7908240271 Forwards topics deleted from systematic evaluation program review due to parallel review as generic issue or inapplicability. Requests review & comments within 30 days ZIEMANN, D. L. Operating Reactors Branch 2 79/04/16 7pp

- 7905100239 Notification of 790427 meeting w/util to discuss status of investigation into small primary sys coolant leak NQMICKI.S J Operating Reactors Branch 2 79/04/24 ip
- 7903040099 Responds to NRC 790119 request for info Consultant will be utilized to develop seismic design basis which will entail providing dynamic models of structures listed in encl & response spectra at specified locations
  BlXEL.D A Consumers Power Co 79/04/29 3pp
- 7905150489 Forwards revised page 8-4, inadvertently omitted from 790323 Tach Specs for license Amend 24 ZIEMANN,D L Operating Reactors Branch 2 79/04/25 3pp
- 7903250095 Comments on draft evaluation "Station Battery Test Requirements," systematic evaluation program Topic VIII-S,A BIXEL,D,A Consumers Power Co 79/05/22 2pp
- 7905310449 Responds to IE Bulletin 78-12, "Atypical Weld Matl in Reactor Pressure Vessels " Final rept will be submitted by 790731 BIXEL, D.A. Consumers Power Co. 79/05/29 1p
- G Inspection reports: 1E Bulletins & correspondence
- 7905010333 Forwards IE Insa Reat 50~155/79-03 on 790226-0302 No noncompliance noted
  HEISHMAN,R.F Region G. Chicago, Reactor Operations Nuclear
  Bupport Branch 79/03/19 2pp
- ~~7905010336 IE Insp Rept 50-155/79-03 on 790226-0302 No noncompliance noted Major areas inspected design changes mod program procedures & refueling surveillance RIDMMY.KR Region 3. Chicago, Office of the Director 79/03/15
- 7905030041 Forwards IE Insp Rept 50-155/79-02 on 790214-16 No noncompliance noted DAVIS,A B Regis Branch, 79/03/19 Region 3, Chicago, Fuel Facility & Materials Bafety
- --790030046 IE Insp Rept 50-155/79-02 on 790214-16 No noncompliance noted Major areas inspected refueling radiation protection activities, including procedures, advanced planning, training, exposure, matl control & posting SCHUMACHER, M C Region 3, Chicago, Office of the Director FIBHER, W L Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/03/13 7pp
- 7905010247 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
  KEPPLER.J O Region 3. Chicago, Office of the Director 79/03/23
- 7903040026 Forwards IE Info Notice 79-07, "Rupture of Radwasts Tanks "
  KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/26
- 7905010162 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing KEPPLER, J G Region 3, Chicago, Office of the Director 79/03/28
- 7905010390 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin Region 3, Chicago, Office of the Director 79/03/30 KEPPLER, J.O.
- 7905290554 Forwards IE Insp Rept 50-155/79-04 on 790213-14: 0313 & 26-27. FIGHELLIO Region 3. Chicago, Reactor Construction & Engineering Support Branch. 79704/09 2pp
- 7905290569 IE Insp Rept 50-155/79-04 on 790213-14,0313 & 26-27
  No noncompliance noted Major areas inspected inservice insp
  GA/GC program, implementing procedures, work activities,
  hondestructive examination data & repts & core Spray
  WARD, K D , RiDOWAY, K R , DANIELSON, D. H Region 3, Chicago, Office
  of the Director, 79/04/05 10pp
- 7905030025 Forwards IE Bulletin 79-06. "Review of Operational Errors & Syx Misalignments Identified During TMI Incident "
  KEPPLER.J O Region 3. Chicago: Office of the Director, 79/04/11
- 7905010579 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified during TMI Incident "
  KEPPLER, J. O Region 3, Chicago, Office of the Director 79/04/14. 10

- 7905040328 Forwards IE Bulletin 79-068, "Review of Operational Errors & Sys Misalignments Identified During THI Incident "
  KEPPLER.J Q Region 3, Chicago, Office of the Director 79/04/14
- 7905040550 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident" Licensee action required
  KEPPLER.J Q Region 3, Chicago, Office of the Director 79/04/14
- 7905070162 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping " Licenses action required KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14
- 7905030220 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " Licensee action required KEPPLER.J O Region 3, Chicago, Office of the Director 79, Region 3, Chicago, Office of the Director 79/04/17
- 7905080486 Forwards IE Bullstin 79-058, "Nuclear Incident at TMI-Suppl " KEPPLER, J O Region 3. Chicago, Office of the Director 79/04/21
- 7905150355 Responds to 790327 request to allow util to combine reviews of IE Bulletin 79-02 & systematic evaluation program Topic III-5 A Since bulletin involves safety issue.NRC refuses to extend time for review Region 3. Chicago, Office of the Director 79/04/26 KEPPLER, J G
- 7903310090 Informs that response to IE Bulletin 79-08. "Events Relevant to BWR Identified During TMI Incident:" will be delayed one week due to plant outage considerations HOFFMAN. D P Consumers Power Co 79/04/27 ip
- 7905240893 Forwards IE Circular 79-07. "Unexpected Speed Increase of Reactor Recirculation Motor Generator Set Resulted in Reactor Power Increase " Region 3. Chicago, Office of the Director 79/05/02 KEPPLER, J O
- 790527027B Provides addit response to IE Bulletin 79-07 Forwards verification benchmarks used for dynamic piping analyses BIXEL, D. A. Consumers Power Co. 79/05/04 7pp
- 7905210163 Responds to IE Bulletin 79-08 re events relevant to BWRs identified during TMI-2 incident No Tech Epec will be required to implement actions discussed in 790804 itr HOFFMAN.D P Consumers Power Co 79/05/16 ip
- 7905090319 "Quarterly Status Rept of Investigations & Mods:" Jan-Mar 1979: Rept 21 \* Pacific Gas & Electric Co 79/04/20, ip
- 8 Reportable occurrences, LERs & related correspondence
- 7905080480 Forwards LERs 79-019/03L-0 & 79-018/01T-0 BIXEL.D A Consumers Power Co 79/05/02 1p
- ---7905080484 LER 79-019/03L-O on 790418 following scram & during routine primary sys leak rate testing unidentified leakage observed at 1 86 gpm Apparent cause was cooling water temp transients Consumers Power Co 79/05/02 ip
- ---79050B04B8 LER 79-01B/01T-0 on 790402 minor water leakage observed at interface between reactor vessel & F-2 rod drive housing Leak stopped when primary sys pressure was reduced to atmospheric conditions # Consumers Power Co. 79/05/02 3pp.
- 7903150457 Forwards LER 79-017/03L-0
  BIXEL, D. A Consumers Power Co 79/05/10 tp
- --7905150459 LER 79-017/O3L-O on 790410 eight mechanical anubbers on reactor depressurization sys piping appeared inadequately installed during NRC insp Units deemed inoperable w/o proof until mods completed 790426 \* Consumers Power Co 79/05/10 ip

DOCKET 50-156 UNIV OF WISCONSIN RESEARCH REACTOR
J Insurance & Indemnity Information

7905160306 Forwards Amend 12 to Indepnity Agreement E-37-par 10CFR140 changes re increase from \$140 million to \$160 million. effective 790501 Supporting documentation encl SALTZMAN, J Antitrust & Indemnity Group 79/05/01 Sap

7905150495 Forwards executed Amend 12 to Indonnity Agreement E-97 WINTER, R W. Wisconsin, Univ. of, Madison. 79/05/10. 2pp

G Inspection reports, IE Bulletins & correspondence

7905180189 Forwards IE Imap Rept 80-156/79-01 on 790315-16 No noncompliance noted HEIBHMAN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/03/26 2pp

---7905180163 IE Insp Rept S0-156/79-01 on 790318-16 No noncompliance noted Major areas inspected operational experience, maint, surveillance, operator requalification, audits & procedures
LITTLE, N S Region 3, Chicago, Reactor Operations Nuclear Support Branch, MASSE, R E , DANIELS, F T Region 3, Chicago, Office of the Director 79/03/23 3pp

POCKET 50-157 CORNELL UNIV RESEARCH REACTOR

J Insurance & Indemnity information

7908300038 Forwards Amend 11 to Indemnity Agreement E-4, reflecting change in 10CFR140, increasing primary layer of liability from \$140 million to \$160 million, effective 790801 Bugporting documentation enci BALTZHAN, J Antitrust & Indemnity Group 79/08/01 Spp

DUCKEY 50-140 GEORGIA INST OF TECH RESEARCH REACTOR

J Insurance & indemnity information

7905300045 Forwards Amend 12 to Indemnity Agreement E-30 reflecting change in 100FR140 increasing primary layer of liability from \$140 million to \$160 million, effective 790801 Supporting documentation encl SALTIMAN. J Antitrust & Indemnity Group 79/05/01 Spp

G. Inspection reports, IE Bulletins & correspondence

7905070137 Forwards IE Bulletins 79-05,79-05A & 79-06, re nuclear incident at THI O'REILLY.J P Region 2. Atlanta. Office of the Director 79/04/13 1p

DOCKET 50-166 UNIV OF MARYLAND RESEARCH REACTOR
J Insurance & Indomnity Information

7903130374 Forwards Amend 9 to Indemnity Agreement E-22, per 10CFR140 changes re increase from \$140 million to \$160 million, effective 790301 Supporting documentation and SALTZMAN. J Antitrust & Indemnity Group, 79/05/01

DOCKET 50-170 NATIONAL NAVAL MEDICAL CENTER
J. Insurance & Indemnity information

7903130373 Forwards Amend 9 to Indemnity Agreement D-2, per 10CFR140 changes re increase from \$140 million to \$140 million, effective 790501 Supporting documentation encl EALTZMAN. J Antitrust & Indemnity Group 79/05/01, Spp

7905310354 Returns unsigned Amend 9 to Indemnity Agreement 8-2; federal agencies are exempt per 10CFR140-10 MCINDOE, D.N. Defense, Dept of, Defense Nuclear Agency, 79/05/23 200

DOCKET 50-171 PEACH BOTTOM ATOMIC POWER STATION, UNIT 1

J Insurance & indemnity information

7905140415 Forwards Amend 20 to Indemnity Agreement 8-28 per 100FR140 changes re increase in liability incurance from \$140 million to \$160 million, effective 790501 Supporting documentation encl.

BALTZHAN, J. Antitrust & Indemnity Group 79/05/01 6pp

DOCKET 50-182 PURDUE UNIV RESEARCH REACTOR
U Insurance & indemnity information

7905160288 Forwards Amend 7 to Indemnity Agreement E-6.per 10CFR140 changes re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl SALTZMAN. J Antitrust & Indemnity Group 79/05/01 5pp

7905300422 Forwards executed Amend 9 to Indemnity Agreement E-6 8MiTH,R E Purdue Univ 79/05/22 App

@ Inspection reports, IE Bulletins & correspondence

7905110041 Forwards IE Insp Repts 50-182/79-01 & 70-0150/79-02 on 790213-15 Notice of violation withhold (ref 10CFR2 790) e Region 3, Chicago, Safeguards Branch 79/03/26 2pp

DOCKET 50-183 VALLECITOS EXPERIMENTAL SUPERHEAT REACTOR

A Application/construction stage documents & correspondence

7905090275 Summarizes 790403-04 meeting w/NRC in San Jose CA re piping improvement program Progress Rept 6 Forwards requested action Items re piping analysis ORIDLEY/R L General Electric Co Nuclear Energy Products Div 79/04/23 125pp

DOCKET 50-184 NATIONAL BUREAU OF STANDARDS REACTOR

J Insurance & indemnity information

7905160281 Forwards Amend 11 to Indemnity Agreement D-9.per 100FR140 changes.re increase from \$140 million to \$160 million. effective 790801 Bupporting documentation enci SALTZMAN.J Antitrust & Indemnity Group 79/05/01 Spp

7905240354 Forwards executed Amend ii to Indomnity Agreement D-9 AMBLER.E Commerce.Dept of. National Bureau of Standards 79/05/15

DOCKET 50-186 UNIV OF HISSOURI RESEARCH REACTOR

J Insurance & indemnity information

7905160339 Forwards Amend 11 to Indemnity Agreement E-45, per 10CFR140 changes, re increase from \$140 million to \$140 million, effective 790501 Supporting documentation encl SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7903310401 Forwards executed Amends 10 & 11 to Indemnity Agreements E-23 & E-23, respectively BLANSETT.V Missouri, Univ of 79/05/25 3pp

DOCKET 30-187 SPACE RADIATION RESEARCH REACTOR
J Insurance & Indomnity information

7905160345 Forwards Amend 13 to Indemnity Agreement B-26.per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl SALTZMAN, J Antitrust & Indemnity Group, 79/05/01 Spp

BOCKET 50-188 KANSAS STATE UNIV RESEARCH REACTOR

J Insurance & Indemnity information

7905;40282 Forwards Amend 11 to Indemnity Agreement E-1.per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790801 Supporting documentation encl SALTZMAN, J. Antitrust & Indemnity Group 79/08/01 5pp

7905230384 Forwards Amend 11 to Indemnity Agreement E-1 HOFFMAN, W C. Kensas State Univ 79/05/17 2pp

- Q Inspection reports, IE Bullatins & correspondence
- 7905150594 Forwards IE Insp Rept, 50-168/79-01 on 790312-15 No noncompliance noted MADSEN. O L Region 4. Dallas, Reactor Operations Nuclear Support Branch 79/03/28 2pp
- --7905150604 IE Insp Rept 50-188/79-01 on 790312-15 No mancompliance noted Major areas inspected licensee's internal review, operating procedures, radiation protection, environ protection & emergency planning JOHNSON,E H. CONSTABLE, G L. Region 4, Dallas, Office of the Director MADBEN, Q L. Region 4, Dallas, Reactor Operations Nuclear Bupport Branch 79/03/27 9pp

DOCKET 50-191 BABCOCK & WILCOX COMPANY CRITICAL FACILITY

- J Insurance & indemnity information
- 7905300714 Forwards Amend 19 to Indemnity Agreement B-B, per IOCFR140 changes re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl SALTZMAN. J Antitrust & Indemnity Group 79/05/01
- 7905290427 Forwards executed Amend 1 to Indemnity Agreement G-2 & Amend 19 to Indemnity Agreement B-8 OLSEN/A F Babcock & Wilcox Go 79/05/21 3pp

DOCKET 50-192 UNIV OF TEXAS RESEARCH REACTOR

- J Insurance & indemnity information
- 7905160355 Forwards Amend 11 to Indemnity Agreement E-25, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl SALTZMAN.J Antitrust & Indemnity Oroup 79/05/01 Spp

DOCKET 50-193 RHODE ISLAND & PROVIDENCE PLANTATIONS AEC

- J Insurance & indomnity information
- 7903160260 Forwards Amend 9 to Indemnity Agreement E-43, per iOCFR140 changes.re increase from \$140 million to \$160 million, effective 790801 Supporting documentation encl SALTZMAN, J Antitrust & Indemnity Group 79/05/01 Spp
- 7905190049 Amend 9 to Indemnity Agreement E-43
  SALTZMAN, J Antitrust & Indemnity Group 79/05/14 ip

DOCKET 50-199 HANHATTAN COLLEGE RESEARCH REACTOR

- J Insurance & indomnity information
- 7905150377 Forwards Amend 10 to Indemnity Agreement E-41, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl SALTZMANIU Antitrust & Indemnity Oroup 79/05/01 Spp.

DOCKET 50-200 BWW TEST REACTOR

- J Insurance & indemnity information
- 7908300714 Forwards Amend 19 to Indemnity Agreement 8-8,per iOCFR140 changes, re increase from \$140 million to \$160 million, effective 790301 Supporting documentation encl SALTZMAN, J Antitrust & Indemnity Group 79/05/01 Spp
- 7905290427 Forwards executed Amend 1 to Indemnity Agreement 0-2 & Amend 19 to Indemnity Agreement 8-9.
  OLSEN, A.F. Babcock & Hilcox Co. 79/05/21 3pp

DOCKET 50-201 WEST VALLEY REPROCESSING PLANT

- Q Adjudicatory correspondence
- 7905150732 Requests JM Hendrie to appear at 790404 hearing re-safety aspects of high level redwaste tanks at facility Test results showed leak in pan under tank containing 600,000 gallons high level liquid radwaste HGYT, W. B. New York, State of 79/03/21, 1p

- J Insurance & indemnity information
- 7905i603i1 Forwards Amend iO to Indemnity Agreement B-29, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp
- P Operating license stage documents & correspondence
- 79050202(4 Notifies that high level waste stored at West Vallay, NY will not be moved from site 8D-2 to 8D-1, as previously stated Action unwarranted & counterproductive to ongoing NRC studies

  CLARK, J R Nuclear Fuel Services, Inc (subs of Getty Dil Co )
  79/03/27 ip
- 7905030035 Forwards "Evaluation of Safety Associated w/Defect in Pan 8D-2 at West Valley, NY " Defect cause unknown No attempt should be made to repair pan w/o further detailed analysis HAUGHNEY, C J Fuel Reprocess & Recycle Branch 79/03/29 6pp
- 7905230813 Responds to 790322 ltr re radiation levels in Cattaraugus Creek & silts above Springville Power Dam Forwards data re silt samples for 1967-69, 1971, 1977 & 1978 CASHMAN,T J New York, State of 79/04/19 4pp
- 7908290282 Forwards NY Dept of Environ Conservation 790419 ltr to JA Lango of Springville, NY re detection of radioactivity in silt samples at Springville Dam W/data on silt samples for 1967-69, 1971 & 1977-78

  CLARK, A T Fuel Reprocess & Recycle Branch 79/05/01 5p
- G Inspection reports, IE Bulletins & correspondence
- 7905010082 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/8vc Air Sys Used as Source of Breathing Air."

  ORIER, B. H. Region i, Philadelphia, Office of the Director 79/03/28. in
- R Periodic operating reports & related correspondence
- 7905240619 Forwards discharge monitoring rept for Mar 1979
  Radioactivity results re outfails 001 & 003 will be reported
  as data becomes available
  OLDHAMN A Nuclear Fuel Services, Inc (subs of Getty Oil Co)
  79/04/10 5pp
- DOCKET 50-206 SAN DNOFRE NUCLEAR BTATION, UNIT 1

  F Security, medical, emergency & fire protection plans
- 7905230514 Updates status of commitments re operating functions & plant mode of fire protection program Discusses safe shutdown casualty procedure spurious valve actuation & hydrogen seal oil area fire.

  BUSKIN.K P Southern California Edison Co 79/08/15 App
- I Financial information
- 7705150400 Forwards "Annual Financial Rapt 1978" for E Edison Co & San Diego Gas & Electric Co DRAKE,J H Southern California Edison C

- 7905070582 Confirms increase in liability limit to \$36,000.000 for policies HF-22, 26,29,38,39,44,46,47,49,50,51,52,53,54,55,55,56,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,71,72,73,74,75 Mutual Atomic Energy Liability Underwriters 79/05/01 ROBERTS D H
- 7905160314 Forwards Amend 12 to Indemnity Agreement 8-31.per 10CFR140 changes.re increass from \$140 million to \$160 million-effective 790501 Supporting documentation encl SALTZMAN.J Antitrust & Indemnity Group 79/05/01 Spp
- 7903190190 Forwards executed Amend 12 to Indemnity Agreement 8-31 WILLIAMS, F.P. San Diego Gas & Electric Co. 79/05/14 Ip
- P Operating license stage documents & correspondence
- 7905020449 Forwards Amend 40 to License DPR-13, safety evaluation notice of issuance & availability Security plan evaluation withheld <ref 10CFR2 790)
  ZIEMANN, D. L. Operating Reactors Branch 2 79/04/10 3pp
- --7905020457 Notice of issuance & availability of Amend 40 to License Operating Reactors Branch 2 79/04/10 2pp
- 7905240302 Requests licenses provide design mods which will assure safe shutdown can be achieved & maintained using onsite power Plant Systems Branch 79/04/13 2pp
- 7905090020 Forwards topics deleted from systematic evaluation program review of facilities Requests review & identification of errors within 30 days from receipt of ltr ZIEKANN, D.L. Operating Reactors Branch 2 79/04/16 7pp
- 7905020218 Forwards draft evaluation of systematic evaluation program
  Topic VI-10 B Requests review & response within three days
  ZIEMANN-D L Operating Reactors Branch 2 79/04/19 6pp
- 7705160319 Evaluates possible vibration problems re operation of chemical vol & control sys test pump No problems anticipated Southern California Edison Co 79/04/20 3pp
- 7905090347 Forwards Amend 78 to License DPR-13 Affidavit & Certificate of Syc encl DRAKE.J H Southern California Edison Co 79/05/04 7pg
- --7905090361 Amend 78 to License DPR-13 consisting of grogosed Teck Spec Change 79, increasing annual discharge limit of sulphuric acid to allow Units 2 & 3 to discharge startup flushing wastewater directly into Unit 1 Southern California Edison Co 79/05/04 48pp
- 7903130374 Forwards results of util examination of NRC 790315 revised systematic evaluation program topic assessments HAYNES, J Q Bouthern California Edison Co 79/05/04 2pp

- 7905270069 Notifies of inability to meet reply deadline for IE Bulletth 78-12A Awaiting into from Westinghouse HEAD.J T Southern California Edison Co 79/03/23 1p
- 7905010220 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air " ENGELKEN R H Region 5, San Francisco, Office of the Director 79/03/28
- 7905010431 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin "
  ENGELKEN,R H Region 5. San Francisco. Office of the Director 79/03/30
- 7905010020 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Bys Misalignments Identified During THI Incident " ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/04/14
- 7903010025 Forwards IE Bulletin 79-06A. "Review of Operational Errors \$
  Bys Misalignments Identified During TMI Incident " Licensee
  action required
  ENGELERIR H Region 5. San Francisco. Office of the Director 79/04/14
- 7905040511 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident " ENGELKEN.R H Region 5. San Francisco. Office of the Director
- 7905040619 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Hater Power Reactors Identified During TMI Incident " ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/04/14 ip
- 7905070104 Forwards IE Bulletin 79-07. "Beismic Stress Analysis of Bafety-Related Piping " Licensee action required ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/14 ip
- 7905030279 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Bafaty-Related Bys " Licenses action required ENGELKEN R H Region 5. San Francisco, Office of the Director 79/04/17
- 7905290500 Responds to IE Bullstin 79-06A. Item 5, re initiation of auxiliary feedwater sys. Bys initiated by operator action Requests exemption from requirements of item: immediate initiation is not essential HEAD. J T Southern California Edison Co 79/04/19 2pp
- 7905080371 Forwards IE Bulletin 79-058, "Nuclear Incident at TMI-Buppl " ENGELKEN,R H 79/04/21 1p Region 5, Ban Francisco. Office of the Director
- 7905240073 Responds to IE Bulletin 79-07 re seismic stress analysis Computer codes containing algebraic summation errors have not been used in design &/or analysis at facility Computer code confirmation will be forwarded by 790330 HEAD. J Southern California Edison Co 79/04/24 2pp
- R Periodic operating reports & related correspondence
- 7905150409 Forwards monthly operating rept for Apr 1979 CURRAN, J K Bouthern California Edison Co 79/05/04 ip.

- 7905040128 Forwards PND-79-678 ENGELKEN.R H Region 5. San Francisco, Office of the Director 79/04/12 ip
- 7905150145 Forwards PND-79-677 ENGELKEN,R H Region 5. San Francisco, Office of the Director 79/04/13 1p
- 7905030024 Forwards PNO-79-67U ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/04/14 1P
- 7905020332 Forwards PNO-79-67AA ENGELKEN,R H Region 5, Ban Francisco, Office of the Director 79704/20 ip
- 7905010434 Forwards PNO-79-67AB ENGELKEN, RH Region 5, San Francisco, Office of the Director, 79704/21 is
- 7903010449 Forwards PND-79-67AC & AD ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/04/23, ip
- 7903010462 Forwards PND-79-67AE ENGELKEN,R H Ragion 5, San Francisco, Office of the Director 79/04/24 1p
- 7905090041 Forwards PND-79-67AF ENDELKEN, R. H. Region S. San Francisco, Office of the Director 79/04/25 1p.
- 7905090057 Forwards PND-79-67AQ ENGELKEN, R H Region S. San Francisco, Office of the Director 79/04/26 ip.
- 7905040586 Forwards LER 79-005/03L-0. HEAD, J T Southern California Edison Co 79/04/27 2pp
- --7903040592 LER 79-003/03L-0 on 790402 sea temp data from three sensors not obtained for three periods Caused by double film image on cartridge, jammed film cartridge & unit tern from anchorage All units repaired or replaced OTTOSON, H L Southern California Edison Co 79/05/01 tp
- 7705090119 Forwards PNO-77-67AH. ENOLEKEN,R. H. Region 5. San Francisco, Office of the Director 77/04/27. 1p
- 7903070031 Forwards PND-79-67Al, AJ & AK.per NRC 790401 ltr transmitting IE Bulletin 79-05 ENOELKEN,R H Region 5. San Francisco. Office of the Director 79/04/30 1p
- 7905070012 Forwards PNO-79-67AL, per NRC 790401 ltr transmitting IE Bulletin 79-05 ENGELKEN, R H Region 5. Ban Francisco, Office of the Director. 79/05/01 1s
- 7905080418 Forwards LER 79-003/03L-0
  MODRE, J. B. Southern California Edison Co. 79/05/03 2pp.
- ---7905080425 LER 79-003/03L-0 on 790404. during normal operation, isolation valve on cooling water from containment air handling units failed to latch in open position Caused by dislodged wire clip & metal pin Solemoid replaced & pin secured CURRAN, J M Southern California Edison Co 79/05/03. 1p.
- 7905110134 Forwards LER 79-002/03L-0. HEAD, J. T Southern California Edison Co. 79/05/04. 2pp.
- --7905ii0i39 LER 79-002/03L-0 on 790404. feedwater flow indication B rose to 10% above actual flow. Caused by flow straightening tube bundle dislodgement Straighteners B & C replaced & attachment strengthened CURRAN, J. M. Bouthern California Edison Co 79/05/04 ip
- 7903310044 Forwards PNO-79-67AM ENGELKEN,R.H Region 5, Ban Francisco, Office of the Director, 79/05/07 1p.
- 7905150503 Forwards LER 79-006/03L-0.
  HEAD, J.T. Southern California Edison Co. 79/05/11 2pp.
- --7905150512 LER 79-006/03L-0 on 790413. two quarterly & two quarty environ direct radiation TLDs were lost. Caused by vandalism. TLDs now in locked PVG tube & permanently fastened at sample locations
  CURRAN, J M Gouthern California Edison Co. 79/05/11, 1P

- 7703300265 Forwards interim rept of Marine Review Committee re ECCS MONG. B California, State of 77/05/15 ip
- --7905300270 "Interim Rept of Marine Review Committee to CA Coastal Commission:Part I General Bummary of Findings,Predictions & Recommendations Concerning Cooling Eys " CONNELL.J H. MECHALAS,B J., MIHUREKY,JA California, State of 79/05/12 22pp
- --7903300277 "Interim Rept of Marine Review Committee to CA Coastal Commission.Part II App of Technical Evidence in Support of General Summary " CONNELL.J H , MECHALAS.B J. , MIHURSKY, J A California, State of 79/05/12 197pp
- 7905310439 Forwards LER 79-007/03L-0.
  HEAD. J T. Southern California Edison Co 79/05/22 ip
- --7903310444 LER 79-007/03L-0 on 790423 during full power operation: steam flow indicator for steam generator A failed, indicating zard flow Caused by failed power supply in steam flow indication circuitry Failed power supply replaced CURRAN, J M Southern California Edison Co 79/05/22 ip
- DOCKET 50-208 COLUMBIA UNIV RESEARCH REACTOR
- J Insurance & indemnity information
- 7905160238 Forwards Amend 2 to Indemnity Agreement E-60, per 10CFR140 changes, re increase from #140 million to #160 million, effective 790501 Supporting documentation encl SALTZMAN, J Antitrust & Indemnity Group 79/05/01 Spp
- DOCKET 50-213 HADDAM NECK PLANT
- F Security, medical, emergency & fire protection plans
- 7909290073 Forwards response to NRC verbal questions re fire protection Engineering & design of most mods in progress COUNSIL W. G. Northeast Utilities 79/05/18 idep
- J Insurance & indomnity information
- 7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,177,180,182,185,186,187,188,187,192,193,194,175,177,178,200,201,204,206,207,208,210,212,214,215,& others QUATTROCHHI, J American Nuclear Insurers 79,05701 1p
- 7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,54,55,55,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,91,92,93,94,95 & 96 ROBERTS,D M Mutual Atomic Energy Liability Underwriters 79/05/(); 10
- 7905160289 Forwards Amend 12 to Indomnity Agraement 8-32, per 10CFR140 changes, re increase from \$440 million to \$460 million, effective 790501 Supporting documentation encl SALTZMAN, J. Antitrust & Indomnity Group 79/05
- P Operating license stage documents & corresponde
- 7905070016 Forwards topics deleted from systematic review of facilities. Requests review & identifica errors within 30 days from receipt of 1tr ZIEMANN.D L. Operating Reactors Branch 2. 75
- 7705240303 Informs that latest revision to operatic described in Revision 3A to GA rept NU-GA-1.forws on 770424 GDUNSIL.M.9 Connecticut Yankee Atomic Power Co
- G. Inspection reports: IE Bulletins & correspondent
- 7905090142 Forwards IE Insp Rept 50-213/79-05 on 7' noncompilance noted. BRUNNER,E J. Region 1, Philadelphia, Reactor Support Branch 77/03/14. 2pp.
- ---7905090146 IE Insp Rept 50-213/79-05 on 790221-2: noted. Major areas inspected licensee strike colpians & refueling/maint activities. LAZARUS: M. J. Region i. Philadelphia, Office KEIMIO.R. R. Region i. Philadelphia, Reactor Support Branch. 79/03/13. 4pp.

- 7905010103 Forwards IE Info Notice 79-06. "Stress Analysis of 8afety-Related Fiping " GRIER B H Region 1, Philadelphia, Office of the Director 79/03/23 1p
- 7905030276 Forwards IE Info Notice 79-07. "Rupture of Radvaste Tanks "
  ORIER.B H Region 1. Philadelphia. Office of the Director
  79/03/26 ip
- 7905010040 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air " GRIER.B H Region t. Philadelphia, Office of the Director 79/03/28 ip
- 7905010290 Forwards IE Info Notice 79-09. "Spill of Radioactively Contaminated Resin" ORIER, BH Region 1, Philadelphia. Office of the Director 79/03/30 1p
- 7905020036 Forwards IE Bulletin 79-06, "Review of Operational Errors % Bys Hisalignments Identified During TMI Incident " Licensee action required GRIER.B H Region 1, Philadelphia, Office of the Director
- 7905020354 Forwards IE Bulletin 79-07. "Seismic Stress Analysis of Safety-Related Piping" Licenses action required GRIER.B H Ragion 1. Philadelphia. Office of the Director 79/04/14 1p
- 7905040010 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misslignments Identified During TMI Incident " GRIER.B H Region 1, Philadelphia. Office of the Director 79/04/14 10
- 7905040188 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident "CRIER.B M Region 1, Philadelphia, Office of the Director 79/04/14 ig
- 7905250446 Responds to IE Bulletin 79-03 re longitudinal weld defects in ASME SA-312 stainless steel pipe Pipe not in use or planned for use in unit COUNCIL.W O Northeast Utilities 79/04/16 ip
- 7905030059 Forwards IE Bulketin 79-09. "Failures of OE Type AK-2 Circuit Breater in Safety-Related Bys " Licensee action required ORIER. B H Region 1. Philadelphia. Office of the Director 79704/17 1p
- 7905010641 Forwards IE Bullstin 79-06A, Revision 1. "Review of Operational Errors & Sys Misalignments Identified During TMI Incident " Licenses action required ORIER B H Region 1. Philadelphia, Office of the Director 79/04/18 tp
- 7905240392 Responds to IE Bulletins 79-06A & /9-06A, Revision 1.re TMJ errors Discusses changes in operating procedures, preventative measures & instructions to personnel COUNSIL-H O Connecticut Yankee Atomic Power Co 79/04/24 79pp
- 7905310473 Responds to IE Builetin 79-04. "Incorrect Weights for Swing Check Valves Mfg by Velan Engineering Corp." No Velan Valves in use on Seismic Category I piping sys GOUNBIL, W O Connecticut Yankes Atomic Power Co 79/04/26 1p
- 7905070542 Forwards "Inservice Insp & Testing Program," revised Jan 1978 CCUNSIL-W G Connecticut Yankee Atomic Power Co 79/04/27, 2pp
- --7905070544 "Inservice Insp & Testing Program," revised Jan 1978 \* Connecticut Yankee Atomic Power Co. 79/04/3D 69pp.
- 7905300323 Forwards 790131-0223 steam generator tube insp rept COUNSIL.W C Connecticut Yankes Atomic Power Co 79/05/23 ip
- --7905300327 "Eddy Current Examination, Tube Sheat Cleaning & Explosive Plugging," inspired for 790131-0223 
  \* Connecticut Yankas Atamic Power Co. 79/02/23 33pp
- R Periodic operating reports & related correspondence
- 7905210211 Forwards monthly operating rest for Apr 1979
  ORAVES, R. H. Connecticut Yankse Atomic Power Co 79/05/11 ip
- --7905210214 Monthly operating rept for Apr 1979 \* Connecticut Yankse Abonic Power Co 79/05/11 9pp

- B Reportable accurrences, LERs & related correspondence
- 7705040061 Forwards LER 79-006/99X-0
  GRAVES R 16 Connecticut Yankee Atomic Power Co 79/04/26 (b
- --7905040070 LER 79-006/99x-0 on 790118 auxiliary feed pump did dit discharge at rated flow Cause undetermined. New rotor & cooler supply water resulted in acceptable test FLEMING: 8 T Connecticut Yankse Atomic Power Co 79/04/24 &.c
- 7905310446 Notifies of 790517 RO during which 230 gallons of todist hydrochloride were released at river's edge in 6-h period GRΑVΣ8, R H Connecticut Yankee Atomic Power Co 79/05/25 2g)
- DOCKET 50-219 DYSTER CREEK NUCLEAR POWER PLANT
- O Adjudicatory correspondence
- 7905080039 Notifies of GE proposal for reanalysis of equipment effortestiting from a combination of saismic & LOCA loads for Mark II & III plants Adequacy of proposed methodology being reviewed W/supporting documentation

  WOODHEAD. C P Branch 3 79/04/04 1p
- --7705080041 Board notification status of actions re program of reanalysis for Mark II & III sys Evaluation will be included in individual safety evaluation MATTSON:R J Division of Systems Bafety 78/04/03 ip
- ---7905080044 Concludes nothing new was achieved in QE 780301 briefly on safety issues However, structured pattern bringing separate issues together in equipment design program was innovative MATTSON.R. J Division of Systems Safety 78/03/16 4pp
- --7905080048 Forwards handouts & list of attendees for meeting to identify deficiencies in acceptance criteria & combination methods proposed by QE for use in reanalysis of Mark II & III plant equipment
  MATTBON: R J Division of Systems Safety 78/00/06 21pp
- ---7905080051 "Methodology for Combining Dynamic Responses "
  CUDLIN.R , HOSFORD, S , MATTU.R Office of Nuclear Reacter
  Regulation NUREG-0484 78/09/30 26pp Available at NTS
- 7905090417 Forwards HR Denton 780727 memo discussing results of recently conducted fire protection research test by UL for NRC fire protection research program MCOLONEAD, C P Branch 3 79/04/05 1p
- J Insurance & indemnity information
- 7905070497 Confirms increased liability limit to \$124,000,000 far policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,185,186,187,188,189,192,193,194,195,197,198,200,201,204,206,207,208,210,212,214,215,&othere QUATTROCHELJ American Nuclear Insurers, 77/05/01 ip
- 7905160292 Forwards Amend 12 to Indomnity Agreement B-37,ppr 10CFR14; changes,re increase from \$140 million to \$160 million, affective 790501 Supporting documentation encl SALTZMAN, J Antitrust & Indomnity Group 79/05/01 Spp
- 7905290351 Forwards executed Amend 12 to Indemnity Agreement B-37 FINFROCK.I R Jersey Central Power & Light Co 79/05/21 3pp
- 7905290394 Forwards executed Amend 10 to Indemnity Agreement 8-37 FINFROCK, I R Jersey Central Power & Light Co 79/05/21 3pp
- P Operating license stage documents & correspondence
- 7903140370 "Analysis of Populations of Boring & Fouling Organisas to Vicinity of Oyster Creek Nuclear Generating Station." annual progress rapt Sept 1977-Aug 1978 HOAGLAND K. E. CROCKET. L. Leigh Univ. FIN 8-5744 NUREQ/CR-0634 79/03/31 115pp. Available at NTIS \$7.25.
- 7905090024 Forwards topics deleted from systematic evaluation prograe review facilities Requests review & identification of errors & comments within 30 days from receipt of ltr ZIEMANN, D L. Operating Reactors Branch 2 79/04/16 7pp

- 7903070633 Informs of near completion of evaluation to determine impact of operation w/four recirculation pumps on currently docksted LICA analysis & corresponding limits in Amend 33 plant operation festrated until analyses completed FINFROCK, IR Jersey Central Power & Light Co 79/04/30 3pp
- /903210173 Forwards Mar 1979 Mark | containment program activity review 8080N.L. J. General Electric Co. 79/05/10 6pp
- 7905220360 Bubmits info requested in 790501 teleon re proposed mode of operation pending completion of analyses to support four pump operation Discusses backflow through (d)e loop & heat generation rate curves during interim period BUND, G R GPU Service Corp. 79/05/13 3pp
- 7905240347 Informs of no further comment or corrections to NRC revised safety assessment of systematic evaluation program Topic V-10 A FINFROCK, I R. Jursey Central Power & Light Co. 79/05/15 ip
- 7905210174 Forwards "Evaluation of Nyster Creek Reactor Core Liquid Level Following Inadvertent Reactor High Pressure Scram on 790502 " Supplements 79552 submittal of transient analysis Addl info on reactor office servicty encl FINTROCK, I R. Jersey Central Power & Light Co. 79/05/17 2pp
- ---/705210179 "Evaluation of Oyster Creek Reactor Core Liquid Level Following Inadvertent Reactor High Pressure Scram on 790502" prepared by Ekson Nuclear Co. Inc # Jersey Central Power & Light Co. XN-NF-79-47 79/05/15 95pp
- 7909210270 Forwards response to NRC info request re effect of four pump operation upon transient & accident amaiysis other than LOGA BOND, O R GPU Service Corp. 79/09/17 4pp
- /9052200BB Forwards schedule for implementation & resolution of MARK I containment long-term program A1) torus mods will be completed prior to Jan 1981 FINIRECK, I R. Jersey Central Power & Light Co. 79/05/17 2pp
- /905190066 Draft Ibl itr re status & rate of improvement of radiation protection program
  QRIR.B H Region 1, Philadelphia, Office of the Director
  79/05/10 App
- 7905210265 forwards "Bounding Loss of Coplant Inventory Transient for Dyster Creek Plant" & Info clarifying several aspects of original 790502 & 790517 submittals FINERUCK, I. R. Jursey Central Power & Light Co. 79705/19 24pp
- --7905210469 Tech Dipec Change Request 72t, modifying Section 2 1 D to estend applicability of safety limit & adding Section 2 1 F to prevent isolation of at least two recirculation nump icops. Certificate of Byc encl
  # Jersey Central Power & Light Co 79/05/19 Spp
- /40524051() Forwards payment for Tech Spec Change Request 72 TIPTON.Y I. Jersey Central Power & Light Co 79/05/19 ip
- 7905290178 Forwards Tech Bpsc Change Request 72, Addendum Ladding Limiting eafety sys setting Water quality rept & Certificate of Svc enci.
  FINFROCK, I.R. Jersey Central Power & Light Co. 79/05/23 27pp
- ~~7905290198 Tech Bpec Change Request 72. Addendum 1, adding new safety sy setting # Jersey Central Power & Light Co 79/05/23 App.
- 7903270194 Porwards Tach Spec Change Request 72, Addendum 1.re
  Incorporation of new safety sys setting to Section 2 3 of
  App A
  FINTROCK, 1 Jersey Central Power & Light Co. 79/05/23 ip
- 7903290172 Forwards Tach Brec Change Request 73 re incorporation of MAPLHOR curves M/Certificate of Svc & appropriate Class III fee FINFROCK, I R Jersey Central Power & Light Go 79/03/24 3pp

- G Inspection reports, IE Bulletins & correspondence
- 7905110216 Forwards IE Insp Rept 50-219/79-04 on 790221-23 No noncompilance noted BRUNNER.E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/03/20 2pp
- --7905110217 IE Insp Rept 50-219/79-04 on 790221-23 No moπcompliance noted Major areas inspected previous insp findings, in-Office review of periodic repts & LERs & containment spray exchanger review

  BRIGOS, L E Region 1, Philadelphia, Office of the Director MCCABE, E C Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/03/19 Spp
- 7705010110 Forwards IE Info Notice 79-06. "Etress Analy si≤ of Safety-Related Piping "
  QRIER, BH Region 1, Philadelphia, Office of the Disector 79/03/23 1p
- 7905010046 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air " ORIER,B H, Region 1, Philadelphia, Office of the Director 79/03/2B tp
- 7905010278 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin" ORICE.B H Region 1, Philadelphia, Office of the Director 79/03/30 ip
- 7905100321 Forwards summary of 790228,790301 & 790322 re reaction to IE Bulletin 78-03, "Potential Explosive Gas Mixtures Accumulations Associated w/BWR Offgas Sys Operations " ZIEMANN, D.L. Operating Reactors Branch 2 79703/30 4pp
- 7905020045 Forwards IE Bulletin 79-06. "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
  ORIER B H Region 1. Philadelphia. Office of the Director 79/04/11 ip
- 7905250349 Responds to IE Bulletin 79-03. "Longitudinal Weld Defects in ABME 5A-312 Type 304 Stainless Steel Pipe Spools Mfg & y Youngstown Welding & Engineering Co "No plans to use pipes in safety-related sys RISB.D A Jersey Central Power & Light Co 79/04/11 ip
- 7905020337 Forwards IE Bulletin 79-07, "Beismic Stress Analysis of Bafety-Rejated Piping " Licensee action required ORIER.O H Region 1, Philadelphia, Office of the Director 79/04/14 ip
- 7905040025 Forwards IE Bulletin 79-068, "Review of Operational Errors & Gys Misalignments Identified During TMI Incident" GRIER, B H Region 1, Philadelphia, Office of the Director-79/04/14 ip
- 7908040204 Forwards IE Bulletin 79-08. "Events Relevant to Boiling Water Power Reactors Identified During THI Incident " QRIER, B. H Region 1, Philadelphia, Office of the Director 79/04/14 ip

" Hegy-table 7 - e see LEAs & related correspondence \* 145 Farwards #15 219/77/13-19 #54 d T gross Cantral Proof & Light Co 79/04/30 to 7FUSCALATO Forwards LER TOHIGS/COL-O Simplement B. H. Lerse, Central Power & Light Co. 79/05/01. Ip TABLE 41891 LEW TO COME OF 793402 rod worth minimizer not 4. "cataboning & was supersed during third critical low power physis a past fauses by failure to coolete second part of pagazine and ragues test stopped NO 1 C A lersey Lenthal Power & Light Co 79/05/01 App --Troduction of solution of the second of actuation solution of the second of the seco THUBIAGED FO SO-219/79/15-IP on 790302 during recovery period foliculing reactor scraes, pusy was operated in violation of Tech Societ Caused by unusual sec condition Corrective action stall undestangued unusual secondition Corrective action Content of Jarsay Central Power & Light Co 79/05/02 2pp --79051E0472 LER 79-100/03L-0 on 790417 w/D recirc pump out of svc.C recirc pump of the svc.C recirc pump out of svc.C re 7903140369 Forwards LER 79-013/017-0 ROSS. D. A. Jersey Central Power 1 Light Co. 79/05/10 19 7903130273 Forwards "Rapt on 790502 Francient," as required by 1006830 361c1(1) FINEROCK. [ R Jersey Central Power & Light Co 79/05/12 2pp --7905150277 "Rept on 790502 Transient" • Jersey Central Power & Light Co 79/08/12 93pp 7905210210 Ferwards LER 79-007:Q3L-0 FINFROCK. I R Jersey Control Power & Light Co. 79/05/16 ip --7905210217 LER 79-009/03\_-0 pg 790416 air operated reactor bidg to suppression chamber vacuum breater valve V-26-18 failed to operate Caused by faulty solenpid actuator Actuators ROSS, D A Jersey Central Power & Light Co 79/05/16 App 7905260274 Ferwards LER 79-015/01T-0
FINFROCK.I R Jersey Central Power & Light Co 79/05/16 1p --- 7903210281 LER 79-013/01Y-0 on 790302 reactor recirculation pumps C & A wars started when tesp of recirculation loops conclant was over 30 F cooler than rector coolant temp. Caused by lack of communication agrees were annulus & core region ROSS. D A Jersey Central Power & Light Co 79/03/16 3pp

```
7908220381 Forwards LER 79-014/017-0
FINFROCK: I R Jersey Central Power & Light Co 79/01/14
        --7908220388 LER 79-014/017-0 on 790702 while performing test of isocondenser auto-actuation systemation high pressure stress occurred Caused by lack of procedural direction Proceduras reviewed & changed RGSs.D A Jersey Central Power & Light Co 19/09/16 744
       --7905290017 LER 79-012/03L-0 on 790419 oxygen level in supplies than 5% Caused by sensitives of sample flow control value of sampling sys & position of sample flow control value oxygen analyzer recalibrilevel now below 5% ROSS:D A Jersey Central Power & Light Co. 29/03/17 type
       7905290023 Forwards LER 79-011/031-0
FINFROCK, I R Jersey Central Power & Light Co 79/05/1/ Le
      --7905290025 LER 79-011/03L-0 on 790419 core apray nump NfcHA in 844 failed to start upon initiation signal Causad by fine-failers fuse replaced & pump test successfully completes ROBBLD A Jersey Central Power & Light Co /9/05/1/ see
      7905290164 Forwards LER 79-010/031-0
FINFROCK, I.R. Jersey Central Power & Light Co. 19/05/4/
      T Hearing transcripts on non-antitrust matters
    7905270003 Transcript of 790503 brigging in Washington Dr. Park the HENDRIES J. M., GILINSKY, V., KENNEDY, R. T. Commission (1972) - 1
   7905240609 Responds to 790409 ltr to constituent inquiry as is radicactive water stored under facility Water passed through condenser, was decontaminated & returned to condensate storage tank OOSSICK, L. V. Office of Congressional Affairs 79007000 was
   ~7705240626 Requests info re dispusal of 200,000 gallons of racinals date stored under facility near forted River. NJ four or five years app
KOBTMAYER, P. H. House of Rep. /9/04/09 ip
  DOCKET SO-220 NINE MILE POINT NUCLEAR STATION, UNIT 1
  F Security, medical, emergency & fire protection plans
  7905030346 Forwards request for examption Enc] withhwid (ref 10CF82 790)
THOMAS, E 8 LeBosuf, Lamb, Leiby & MacRae 79/05/02
  J insurance & indemnity information
 7905070582 Confirms increase in liability limit to $36,000.0(n) *, * Policies MF-22,26,27,38,39,44,46,47,49,30,51,52,53,54,53,54,53,54,53,54,59,78,86,61,64,66,67,70,71,72,74,76,77,78,79,80,86,81,81,81,81,808873,D.M. Mutual Atomic Energy Liability Underwriters 74,7;
7905160286 Forwards Amend 13 to Indomnity Agreement B-DA.per icresitation to 4660 million. Selective 790501 Supporting documentation enci
SALTIMAN, J Antitrust & Indomnity Group 79/05/Q1 Spp
7905130291 Forwards essented Amend to to Indemnity Agreement # 144.
RUSHMORE Niegara Mohawk Power Corp. 79/05/10 Opp
```

- P Operating license stage documents & correspondence
- 7905020235 Notification of 790402 meeting w/OE to discuss methodolgy for predicting safety relief valve loads for Mark I containments using T-quencher Sustance Susta
- 7905020367 Datailed weld procedures to demonstrate N58 safe-end & elbow replacement PERKINB: T J Niagara Mohawk Power Corp 79/04/24 41pp
- 7905080414 Forwards responses to Hydrology-Meteorology Branch quastions 0372 2 & 0372 3,per 790108 ltr Design interfaces between radwaste reduction & solidification system are not complete Accident analysis to be recalculated RHODE, G K Niagara Mohawk Power Corp 79/05/01 22pp
- 7905230295 Forwards table re torus mods for Epring 1979 refueling outage Analysis is continuing to determine if further mods are required Final analysis for major structural components is expected by end of 1979

  BCHNEIDER, R R Niagara Mohawk Power Corp 79/05/14 3pp
- 7903230478 Responds to NRC 790319 ltr Info re radiation levels is contained in annual environ operating rept SCHNEIDER, R.R. Niagara Mohawk Power Corp. 79/05/16 ip
- 7905310218 Forwards application for amend to License DPR-63 & \$4,000 fee
  THOMAS, E.B. LeBoeuf, Lamb. Leiby & MacRae 79/05/29 2pp
- ---7905310221 Application for amand to License DPR-63 re Tuch Specs changes to safety limmits DISE: DP Niagara Mohauk Power Corp 79/05/29 10pp
- G Inspection reports, IE Bulletins & correspondence

1

-11

- 7905090134 Forwards IC Insp Rept 50-220/79-04 on 790206-09 & 21-23 No noncompliance noted 8MITH.0 H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/03/19 2pp
- --7905090140 IE Insp Rept 50-220/79-04 on 790206-09 & 21-23 No noncompliance noted Major areas inspected radioactive waste sys & radiation protection during refueling THONUS,L H Region 1. Philadelphia, Office of the Director CROCKER,H W Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 79/03/14 Spp
- 7905010126 Forwards IE Info Notice 79-06. "Stress Analysis of Bafety-Related Piping" ORIER.B M Region 1. Philadelphia. Office of the Director 79/03/23 1p
- 7905010055 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air" ORIER.B H Region 1. Philadelphia, Office of the Director 79/03/28 (p
- 7905010307 Forwards IE Info Notice 79-07, "Spill of Radioactively Contaminated Resin " ORIER, B H Region 1. Philadelphia. Office of the Director 79/03/30 ip
- 7905020069 Forwards IE Bullatin 79-06, "Review of Operational Errors & Bys Miwalignments Identified During TMI Incident" (RIER, B.H. Region 1, Philadelphia, Office of the Director 79/04/11 ip
- 7905100421 Responds to IE Bullstin 79-03 re longitudinal weld defects No giping was supplied by Youngstown Welding & Engineering Co. SCHNEIDER, R.R. Niagara Mohawk Power Corp. 79/04/11. ip.
- 7905020332 Forwards IE Bulletin 79-07. "Seismic Strees Analysis of Safety-Related Piping " Licenses action required ORIER: B H Region 1, Philadelphia. Office of the Director. 79/04/14. 1p
- 7905040071 Forwards IE Bulletin 79-048. "Review of Operational Errors & Bys Misalignments Identified During TMI Incident " ORIER, B.H Region i, Philadelphia, Office of the Director 79/04/14. ip
- 7905040237 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident "Licensee action required.
  ORIER, B H Region i: Philadelphia, Diffice of the Director 79/04/14 lp.

- 7905030078 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Bafety-Related Sys " Licensee action required GRIERI H Region 1, Philadelphia, Office of the Director 79/04/17 1p
- 7905020288 Forwards IE Bulletin 79-06A:Revision i, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident" ORIER B H Region I, Philadelphia, Office of the Director 779/04/18 b
- R Periodic operating reports & related correspondence
- 7905150508 Forwards monthly operating rept for Apr 1979 8CHNEIDER, R R Niagera Mohawk Power Corp 79/05/10 1p
- --7705150511 Monthly operating rept for Apr 1979
  PERKINS T J Niegera Mohawk Power Corp 79/03/08 6pp
- B Reportable occurrences, LERs & related correspondence
- 7905070401 Forwards LER 79-005/03L-0 SCHNEIDER, R R Niagara Mohawk Power Corp 79/04/30 1p
- --7905070411 LER 77-005/031-0 on 790401 during periodic Type C leakage test, valves IV-68-06, IV-201-07, IV-201-10 & IV-58 1-02 were found to be in excess of Tech Specs Cause unknown Repairs will be made during outage

  JUTRAS, R Niegara Hohawk Power Corp 79/05/01 1p
- 7905160392 Forwards LER 79-006/03L-0 BCHNEIDER, R R Niagara Mohawk Power Corp 79/05/10 1p
- --7903160394 LER 79-006/03L-0 on 790428 overfrequency relay on motor generatur set 172 could not be callibr Caused by bad potentiomater adjustment. Repairs being made DUDA.E Niagara Hohawk Power Corp 79/05/10 ip
- 7905300486 Forwards LER-010/03L-0 LEMPGES.T E Niagara Mohawk Power Corp 79/09/23 ip
- ~-7905300496 LER 79-010/03L-O on 790424 during refueling outage. containment vacuum relief valve 66 IV-10 flange failed leak rate test 0-rings replaced on flange DUDA.E. Niagara Mohawk Power Corp 79/05/23 Ip
- DOCKET 50-229 UNIV OF LOWELL RESEARCH REACTOR
  J Insurance & indomnity information
- 7905160268 Forwards Amend 8 to Indemnity Agreement E-54, per 10CfR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl SALTZMAN. J Antitrust & Indemnity Group 79/05/01 5pp
- DOCKET 50-224 UNIV OF CALIFORNIA RESEARCH REACTOR
  J Insurance & Indemnity information
- 7908300052 Forwards Amend 13 to Indemnity Agraement E-15, reflecting change in 10CFR140, increasing primary layer of liability from \$140 million to \$160 million, effective 790801 Supporting documentation encl.

  BALIZMAN.J Antitrust & Indemnit, Jroup 79/05/01 Spp
- P Operating license stage documents & correspondence
- 7905210178 Forwards Tech Spec Change 6 Requests info re SNM possession limits, amount exempt & nonexempt KAPLAN, S. N. California, Univ. of, Berkeley 79/05/14 1p
- ---7905210181 Tech Specs Change 6 for Triga Mark III \* Galifornia, Univ. of, Berkeley 79/05/14, 38pp
- DOCKET 50-225 RPI CRITICAL EXPERIMENT
  J Insurance & indomnity information
- 7905160264 Forwards Amend 9 to Indemnity Agreement E-42, per iOCFR140 changes re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl BALIZMAN, J Antitrust & Indemnity Group, 79/05/01

- P Operating license stage documents & correspondence
- 7905220391 Requests renewal of License CX-22 for 25 years Formai application to be subsitted by 790901 JUDD. O Renssalaer Polytechnic Inst 79/05/14 ip
- @ Inspection reports, IE Bullstins & correspondence
- 7905240277 Forwards IE Insp Rept 50-225/79-02 on 790220-23 No noncompliance notes MARTIN.W 0 Region I. Philadelphia, Safeguards Branch 79/03/21
- --7905240287 IE Insp Rept 30-225/79-02 on 790220-23 Na honcompliance noted Major areas inspected physical security plan-including protection of SNA access control-alarm sys & communications surveillance Details withheld (ref locFR2 790) LADW.R H. DEWLINJ W Region 1, Philadelphia, Safeguards Report 79/03/20 ip

DOCKET 30-227 TRIGA THERMIONIC PROTOTYPE REACTOR

- J Insurance & indemnity information
- 7905300202 Forwards Amendment 3: to Indemnity Agreement B-9, reflecting change in IOCFR140, increasing primary layer of l(ability from \$140 million to \$160 million; effective 790501 Supporting documentation encl
  BALTZMAN, J Antitrust & Indemnity Group 79/05/01 Spp

DOCKET 50-228 AEROTEST RADIOGRAPHY & RESEARCH REACTOR

- J Insurance & indepnity information
- 7905300059 Forwards Amend 17 to Indemnity Agreement B-2, reflecting change in 10CFR140, increasing primary layer of liability from \$140 million to \$160 million, effective 790501 Supporting documentation which SALTIMAN, J. Antitrust & Indemnity Group 79/05/01 Spp.
- 7905240357 Forwards accepted Amend 17 to Indemnity Agreement 8-2 NEWACHECK,R L Aerotest Operations 79/03/15 2pp

DOCKET 50-233 MEXICO RESEARCH REACTOR

J Insurance & indemnity information

7905300202 Forwards Amendment 31 to Indemnity Agreement 8-9, reflecting change in 10cFR140, increasing primary layer of liability from \$140 million to \$160 million effective 790301 Bupporting documentation encl BALTZMAN.J Antitrust & Indemnity Group 79/05/01 5pp

DOCKET 50-234 TUNGSTEN NUCLEAR ROCKET CRITICAL FACILITY

- J Insurance & Indomnity information
- 7903900202 Forwards Amendment 31 to Indemnity Agreement B-9, reflecting change in 10CFR140, increasing primary layer of liability from \$140 million of \$160 million affective 790301 Supporting documentation encl shaltzman, J Antitrust & Indemnity Group 79/05/01 5pp

BOCKET 50-235 ACCELERATOR PULSED FAST ASSEMBLY

- J Insurance & indemnity information
- 7903300202 Forwards Amendment 31 to Indemnity Agreement B-9, reflecting change in 10cFR140, increasing primary layer of liability from \$140 million to \$160 million effective 79030;
  Supporting documentation encl
  SALTZMAN. J Antitrust & Indemnity Group 79/05/01 5pp

DOCKET 50-237 DREEDEN MUCLEAR POWER STATION, UNIT &
F Security, medical, marryancy & fire protection plans

- 7905030366 Forwards modified physical security plan, Revision 5 Plan withheld (ref LOCFR2 790)
  LEE, B Commonwealth Edison Co 79/04/26 ip
- 7905040603 Forwards pages of "Implementation of Nuclear Mutual Limited Loss Prevention Program." in response to NRC 780629 request to fire protection administrative controls.

  JAMECEK.R F Germanusalth Edison Co 79/04/30 App

- O Adjudicatory correspondence
- 7905250258 Notifies properly worded contention re sabutage webje be accepted Contention 6.as admitted into Duke Power Coproceeding encompasses aspects of revised Contention II presented by State of IL GODDARD, R J Branch 2 79/04/06 2pp
- J Ingurance & indemnity information
- 7905100163 Endorsement 99 to MAELU Policy MT-22 OERAS.T Nuclear Energy Liability Insurance Association 79/03/2
- 7905070497 Confirms increased liability limit to \$124,000,000 for colicies NF-1, 25,43,75,83,100,111,140,146,151,161,164,170,173,174,178,179,160,182,183,186,187,188,189,197,192,193,194,195,197,198,200,201,204,204,207,208,207,208,210,212,214,213,4 others GUATTROCHHI, J American Nuclear Insurers 79705/01 1p
- 7905140404 Forwards Amend 21 to Indemnity Agreement 8-10 per 10CFF114 changes re increase in liability insurance from \$140 million to \$160 million effective 790901 Supporting documentation and SALTZMAN, J Antitrust & Indemnity Group 79/05/01 //pp
- P Operating license stage documents & correspondence
- 7905020235 Notification of 790402 meeting w/OE to discuss methodology for predicting safety relief valve loads for Mark I containments using T-quancher
  SU.T M Containment Systems Branch 79/03/26 2pp
- 7905230866 Forwards application for license mod to spent fuel purol H sack. ODDDARD.R J Branch 2 79703/26 ipp
- 7905080570 Requests supplemental info re 780511 application for \*p\*\*1 fuel pool mods be sent to ABLB & intervence SN Bekuler ZIEMANN D L. Operating Reactors Branch 2 79/04/12 Jpp
- 7905030067 Forwards notes on 790302,15 % 93 conference telcome between NRC-consultants & util re-bullatin "Potential Explosive Oas Mixtures Accumulations Associated w/BUR Offgas 8ys Operations"
  IPPOLITO, T A Operating Reactors Branch 3 79/04/16 4pp
- 7908080339 Forwards topics deleted from systematic evaluation psogry review of facilities Requests review & identification of strong within 30 days from receipt of itr ZIEMANN.D L Operating Reactors Branch 2 79/04/16 /pp
- 7905080141 Responds to 790305 ltr criticiting application for approp of proposed license amend that would allow shipment of spent fuel between stations Provides into on upcoming hearing IPPOLITO, T A Operating Reactors Branch 3 79704710 in
- --7795080131 Opposes application for approval of proposed license at that would allow shipment of spent fuel between stations HOHENBOKEN.P. Affiliation Unknown. 79703/13 2pp
- 7905040402 Notifies of intention to develop safety analysis using existing computer codes Requests addl info SOLBRIG.C W Commonwealth Edison Co 79/04/26 ip
- 7905090370 Reviews systematic evaluation program for shared anglement safety features; onsite emergency power & avc sys for multiple unit stations

  JANECEKIR F Commonwealth Edison Co 79705/02 2pp
- 7905190016 Forwards current schedule for implementation of Mark & containment long-term mods Discusses constraints inhibiting shorter time frame completion including sys load requirements & current fuel cycles REED, G Commonwealth Edison Co 79/05/11 3pp
- 7905190097 Requests correction of error discovered in 780423 ltm recapacity of Nuclear Assurance Corp NAC-1 truck cask used in spent fuel transfer. Cask hes capacity of two IMAR assemblies JANECEK:R F Commonwealth Edison Co. 79/05/11

- 7905250391 Forwards current licensing open items status list REED, C Commonwealth Edison Co 79/05/18 11pp
- /903300208 Forwards summary of EDS Nuclear, Inc resolution/documentation of albow flexibility error which existed in versions of PIBGL piping analysis computer program from Jan-Oct 1969 Roview & reanalysis included all work through Dec 1970 PORTER, F L EDS Nuclear, Inc 79/05/21 9pp
- --7905300263 Forwards EDB Nuclear, Inc list of BMRs & piping sys which could have been impacted by deficient computer program OE has no record of reanalysis for Cooper piping sys GTEPHICHS, P. W. General Electric Co., Nuclear Energy Products Div 79/01/24 18pp
- 7905310364 Withdraws 781212 request for exemption from 10CFR50 to flood reactor vessel during integrated primary containment leak rate test

  JANECEK,R F Commonwealth Edison Co 79/05/24 2pp
- Q Inspection reports, IE Bulletins & correspondence
- 7909020421 Forwards response to IE Bulletins 78-12 & 78-12A. "Atypical Held Matl in Reactor Pressure Vessel Helds"
  REED.C Commonwealth Edison Co 79/03/22 10pp
- /905010236 Forwards IC Info Natice 79-06, "Stress Analysis of Safety-Related Piping" KEPPUCR: J G Region 3, Chicago, Office of the Director 79/03/23
- /905030370 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks"

  NEPPLER, J O Region 3, Chicago, Office of the Director 79/03/26

  Lp
- //09010135 Forwards IC Info Notice 79-08, "Interconnection of Contaminated Sys w/Syc Air Sys Used as Source of Breathing Air " KEPPLER. J G Region 3, Chicago, Office of the Director 79/03/28
- 7905010384 Forwards IE Info Notice 79-09, "Spiil of Radioactively Contaminated Resin" KCPPLER.J O Region 3, Chicago, Office of the Director 79/03/30
- /905030013 Forwards IF Bullotin 79-06A. "Review of Operational Errors & Bys Misalignments Identified During TMI Incident "
  Region 3, Chicago, Office of the Director 79/04/11
  ip
- 7905240448 Forwards IE Insp Repts 50-010/79-07, 50-237/79-09 & 30-249/79-07 on 790306-07, 0312 & 0323 No noncompliance noted.

  DAVIG.A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/04/11 2pp
- ---7905240434 II. Insp Repts 30-010/79-07.00-237/79-07 & 50-249/79-07 on 790306-07.0312 & 0323 No noncompliance noted Major areas inspected, internal audits, offsite support agency coordination, smorgency facilities, training & drills GRANT.W.B. (18910.T.H. Region G, Chicago, Office of the Director 79/04/05 5pp
- 7909250280 Responds to IE Bulletin 79-03 re welding defects in certain longitudinally welded pipe spools. Plants inspected, no pipe found REED, C Commonwealth Edison Co 79/04/12 2pp
- 7905010369 Forwards IF Bulletin 79-06A, "Review of Operational Errors & Bus Misalignments Identified During TMI Incident "
  KUPPLER. J O Region 3. Chicago, Office of the Director 79/04/14
- 7903040334 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Bys Mis&lignments Identified During THI Incident "
  KEPPLER.J O Region 3, Chicago, Office of the Director 79/04/14
- 7908040529 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Hater Power Reactors Identified During TMI Incident." KEPPLER, J Q Region 3, Chicago, Office of the Director 79/04/14
- 7905030206 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Bafety-Related Sys " Licensee action required. KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/17

- 7905040142 Forwards IE Bulletin 79-058, "Nuclear Incident at TMI-Suppl"

  KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/21
- --7905040158 IE Bulletin 79-05B, "Nuclear Incident at IMJ-Suppl " Supporting documentation encl \* Region 3, Chicago, Offfice of the Director 79/04/21 12pp
- --7905040170 ACRS recommendations re 790328 incident at THI Suggests high priority be placed on development of safety research on behavior of LMRs during anomalous transients \* ACRS - Advisory Committee on Reactor Safeguards 79/04/17
- --7909040201 Forwards ACRS recommendations re TM1 incident, presented on 790417 FRALEY, R F ACRS - Advisory Committee on Reactor Safeguards 72/04/18 in
- --7905040221 In response to NRC 790418 ltr.states 790417 ACRS recommendations apply to all PWRs, but were not intended to require immediate changes Plant mods should be made after study of effects on overall safety. TMI excluded CARBON, M X ACRS Advisory Committee on Reactor Safeguards 79/04/20 2pp
- 7905240633 Forwards responses to IE Bulletin 79-07 requesting info re seismic analysis of safety-related piping Reanalysis indicates method of intramodal combination has little effect on pipe stresses & equipment support load REED.C Commonwealth Edison Co 79/04/24 4pp
- 7909250206 Ack receipt of 790416 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/79-04, 50-237/79-04 & 50-249/79-04 HIND, J A Region 3, Chicago, Safeguards Branch 79/04/26 ip
- --7905250215 Responds to NRC 790328 ltr re violations nated in IE Insp Repts 50-010/79-04.50-237/79-04 & 50-249/79-04 Corrective actions withheld (ref 10CFR2 790) REED.C Commonwealth Edison Co 79/04/16 lp
- 7905150148 Forwards responses to IE Bulletin 79-06A.Revision 1.re
  BMR events identified during TMI-2 Util has formed tast
  force to review BMR events & recommend corrective action.as
  required
  REED.C Commonwealth Edison Co 79/04/27 22pp
- 7705300242 Responds to IE Bulletin 79-04 No 3.4 or 6-inch Velan swing check valves are in use at Dresden or Quad-Cities Review of Zion has identified use of valves in some piping sys but review is incomplete Will rept later REED.C Commonwealth Edison Co 79/09/01 2pp
- 790514048B Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Recirculation Motor Generator Set Resulted in Reactor Power Increase " KEPPLER, J Q Region 3, Chicago, Office of the Director 79/05/02
- R Periodic operating reports & related correspondence
- 7905160354 Forwards monthly operating rapt for Apr 1979 BTEPHENBON.B B Commonwealth Edison Co 79/05/08 ip
- --7905160359 Manthly operating rept for Apr 1979 CIESZKIEWICZ.S Commonwealth Edison Co 79/05/03 20pp
- B Reportable occurrences, LERs & related correspondence
- 7905040432 Forwards LER 79-022/03L-0 STEPHENSON, B B Commonwealth Edison Co 79/04/30 lp
- --790504056: LER 79-022/03L-0 on 79033: during refueiting, diesel generator failed to start due to governor linkage sticking in closed position Solenoid removedino fault found Linkage exercised & diesel started CHAN.J. Commonwealth Edison Co 79/04/30 2pp
- 7905080535 Forwards LER 79-023/03L-0 STEPHENSON, B B Commonwealth Edison Co 79/04/30 1p
- ---7905080540 LER 79-023/03L-0 on 790406 during radioactive insp,lack of fusion noted in weld 4-4 on 4-inch reactor head vent line 2-0215-4 Weld cut out & rewelded per AGHE boiler & pressure vessel code AGME hydrostatic test completed COEN,R Commonwealth Edison Co 79/04/26 ip

- 7905220257 Forwards LER 79-001/03X-1 STEPHENSON B B Commonwealth Edison Co 79/05/03 1p
- SIENHEUSDING TO COmmountering Estatus on 1,1,00,000 15
- --7903220264 LER 79-001/03X-1 on 790103 during steady state operation, torus level exceeded specs Caused by operator oversight Excess torus water pumped to hotwell & operator admonished Surveillance being revised WRIGHT.M Commonwealth Edison Co 79/05/03 ip
- 7905160384 Forwards LER 79-020/03L-0 STEPHENSON.B B Commonwealth Edison Co 79/05/04 1p
- 7705160385 LER 79-020/031-0 on 770413 measured leakage for personnel air lock was 54 63 std cubic ft/h Leakage identified through outer lower handwell Shaft packing was replaced & air lock retested PARCELL.M Commonwealth Edison Co. 79/03/04 1p
- 7905170226 Forwards LER 79-021/03L-0 STEPHENSON, B B Commonwealth Edison Co 79/05/10 [p
- --7905170229 LER 79-021/03L-0 on 790415 2A LPC1 pump was manually stopped but would not restart properly Caused by trip on overcurrent relay Hotor bridged & meggered satisfactorily Pump returned to syc COEN.R Commonwealth Edison Co 79/05/14 (p
- 7905300567 Forwards LER 79-024/03L-0 STEPHENSON, B B Commonwealth Edison Co 79/05/22 1p
- --7903300573 LER 79-024/03L-O on 790424 while in shutdown for refueling, U2 diesel generator failed to start Caused by air lines to upper air motor being reversed Airstart motor was replaced & air lines properly routed CHAN.J Commonwealth Edison Co 79/05/24 ip
- 7908300443 Forwards LER 79-026/03L-0 BTEPHENBON, B B Commonwealth Edison Co 79/05/24 1p
- --- 7903300447 LER 79-026/03L-O on 790428 breaker trip logic testing disclosed motor generator set 28 output breaker would not trip Cause determined to be small piece of bakelite jamming tripping mechanism Breaker cleaned DUNBAR.J Commonwealth Edison Co 79/05/24 ip
- 7905300485 Forwards LER 79-025/03L-0 8TEPHENBON 8 B Commonwealth Edison Co 79/05/24 1p
- ---7905300499 LER 79-029/03L-0 on 790425 during monthly surveillance, switches 500-7,PE 504C & PS 504D tripped at 410 psi Caused by instrument drift during prolonged shutdown period Switches reset

  DURBAR.J Commonwealth Edison Co 79/05/24 1p
- 7905300475 Forwards LER 79-033/03L-0 STEPHENSON, B B Commonwealth Edison Ca 79/05/25 1p
- ---7903300480 LER 79-033/03L-0 on 790428 during primary containment isolation valve surveillance, 20 TIP machine failed to retract Causad by ball valve limit switch which did not deenergize machine control circuitry PARCELL Commonwealth Edison Co 79/05/23 2pp
- DOCKET 50-240 HIGH TEMP GAS COOLED CRITICAL EXPERIMENT

- DOCKET 50-243 OREGON STATE UNIV RESEARCH REACTOR
  P Operating license stage documents & correspondence
- 7905070584 Forwards proposed changes to Tech Specs for TRIGA reacts:
  & justification for mods Desires to upgrade console
  electronics & Change reactivity pulsing limit during
  summer Changes would require about two weeks
  HANO, C H , SMITH, C V Oregon State Univ 79/04/16 14pp
- DOCKET 30-244 ROBERT EMMET GINNA NUCLEAR PLANT, UNIT 1
  F Security, medical, emergency & fire protection plans
- 7905070486 Responds to request for add1 info re 790214 fire protective BER Discusses piping & duct penetrations.const joint, detector testing & electrical cable insulation WHITE,L D Rochester Oas & Electric Corp 79/04/30 3pp
- 7905310395 Advises of steps undertaken re Items 3 2 9 & 3.1 ii of fire protection SER concerning adequacy of fire brigads size b battery from ventilation HMITE, L D Rachester Gas & Electric Corp 79/05/25 fp
- I Financial information
- 7905030397 Forwards "Annual Financial Rept 1978 "
  THOMAS:E B LeBoeuf, Lamb, Leiby & MacRae \_\_79/05/02 1p
- --7908030359 "Annual Financial Rept 1978 "
   Rochester Gas & Electric Corp 79/03/15 32pp
- J Insurance & indomnity information
- 7905070497 Confirms increased liability limit to \$124,000.000 for policies NP-1,29,43,76,83,100,111,140,146,151,161,164,170,179,174,178,179,180,182,185,186,187,188,189,197,192,193,194,195,197,198,200,201,204,206,207,208,210,212,214,215,&others.

  GUATTROCHHI, J American Nuclear Insurers 79/05/01 1p.
- 7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22,26.29,38,39,44.46.47,49,50,51,52,53,54,55,86,57758,40,61,64,46,67,68,67,70,71,72,74,76,77,78,79,80,86,87,88,90,91,92,93,94,95 & 96 ROBERTS,D M Mutual Atomic Energy Liability Underwriters 79/03/01
- 7905140186 Forwards Amend 8 to Indemnity Agreement 8-38, per iOCFR\$40 changes re liability insurance increase from \$140 million to \$140 million.effective 740501 Bupporting documentation enci. SALTZHAN, J. Antitrust & Indemnity Group 79/05/01. Spp.
- 7903230417 Forwards Amend 8 to Indemnity Agreement 8-38 KUSBIE.R R Rochester Gas & Electric Corp. 79/05/17. 3pp
- P Operating license stage documents & correspondence
- 7903030126 Reviews 781012 ltr re sys mod to add new battery chargers Requests addl info
  XIEMANN-D L Operating Reactors Branch 2, 79/04/06, 3pp
- 7905090026 Forwards topics deleted from systematic evaluation program review of facilities. Requests review & identification of errors within 30 days from receipt of ltr.

  ZIEMANN, D L Operating Reactors Branch 2 79/04/16 7pp
- 790502035: Forwards draft evaluation of systematic evaluation progres;
  Topic III-4-8 re turbine missiles.Requests review within 30
  days
  ZIEHANN.D L. Operating Reactors Branch 2, 79/04/18 8pp
- 7703090205 Forwards Amend 26 to License DPR-18, safety evaluation & notice of issuance & availability
  ZIEMANN, D.L. Operating Reactors Branch 2. 79/04/18 2pp.
- ~~7905090207 Amend 26 to License DPR-18 revising Tech Specs to require reactor coolant sys overpressure protection mod.

  ZIEMANN.D L Operating Reactors Branch 2. 79/04/18 14pp.
- ---7905090208 8sfety evaluation supporting Amend 26 to License DPR-18
  \* Office of Nuclear Reactor Regulation, 79/04/18 13pp

- --7903090263 Notice of issuance & availability of Amend 26 to License DPR-18 ZIEMANN.P L Operating Reactors Branch 2 79/04/18 2pp
- 7905070580 Responds to 790125 ltr re analysis of boron dilution methanisms Summarizes results of residual heat removal sys No single failure could result in boron dilution WHITE, L D Rochester Cas & Electric Corp 79704/30
- 7905100149 Provides add1 seismic info requested by NRC seismic review team Forwards info on plant structural design except for datails of containment & internal structures Dynamic model of auxiliary blog & 55 oversized drawings encl
  WHITE, L D Rochester Gas & Electric Corp 79/03/07 11pp
- 7905180393 Submits revised Attachment A.B % C to 780728 submittal amending Tach Specs for charcoal filter testing % iodine removal equipment operability WILKENS.P C Rochester Gas & Electric Corp 79/05/08 24pp
- 7905220377 Comments on NRC 790416 1tr deleting topics for further review from systematic evaluation program Lists other topics to be deleted which are not applicable or have been resolved WHITE, L D. Rochester Oas & Electric Corp 79/05/16 3pp
- 7905220031 Responds to request for addl info re pressure shielding steel diaphragm Submits info summarizing calculated pressure transients which result from breaks in 20-inch feedwater line or 12-inch steam line.

  WHITE:
- 7905300474 Forwards supplemental info to 790507 ltr re systematic evaluation program seismic review Oversided drawings available in Central Files
  WHITE, L.D. Rochester Gas & Electric Corp. 79/05/22 60pp
- G Inspection reports, IE Bulletins & correspondence
- 790501014B Forwards IE Info Notice 79-06, "Stress Analysis of Bafety-Related Piping"
  ORIER, B H Region i, Philadelphia, Office of the Director 79/03/23 ip
- 7905240294 Forwards IE, Insp. Rept 80-244/79-05 on 790305-0308 No noncompliance noted BHITH, O H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/03/23 2pp
- --7905240306 IE Insp Rept 50-244/79-05 on 790305-08 No noncompliance noted Major areas inspected radiation protection program during routine refueling operations, procedures, planning & preparation, training exposure control & posting YUHAS, 0 P. CROCKER, H W. Region 1. Philadelphia, Office of the Director 79/03/22 9pp
- 7905010073 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Syc Air Sys Used as Source of Breathing Air " ORIER, B. H. Region 1, Philadelphia, Office of the Director 79/03/28 ip
- 7705010322 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin" ORIER, B. H. Region 1, Philadelphia, Office of the Director 77/03/30 ip.
- 7703230181 Responds to IE Bulletin 79-03, "Longitudinal Weld Defects in ABME 8A-312 Type 304 Stainless Steel Pipe Spools Mfg by Youngstown Welding & Engineering Co." Class II stainless steel piping say designed to ABA-836 19 & 836 10. WHITE, L D. Rochester Gas & Electric Corp 79/04/06 ip
- 7905290169 Forwards IE Insp Rept 50-244/79-04 on 790226-0302 No noncompliance noted. SRUNNER, E J Region 1, Philadelphia, Office of the Director 79/04/10. 2pp
- ---7905290173 IE Insp Rept 80-244/79-04 on 790226-0302. No noncompliance noted Major areas inspected facility logs & records, plant status, refueling procedures, maint activities & plant tour. BECKMAN, D. A., KALMAN, O. Region 1. Philadelphia, Office of the Director KEIMIO.R R. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 79/04/10 18pp
- 7905020106 Forwards IE Bulletin 79-06, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident " Licensee action required.

  ORIER, B. H. Region 1, Philadelphia, Office of the Director 79/04/11 ip

- 7905020315 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Pining" Licensee action required GRIER,B H Region i, Philadelphia, Office of the Director 79/04/14 ip
- 7905040109 Forwards IE Bulletin 79-06D, "Review of Operational Errors & Sys Missignments Identified During TMI Incident "ORIER.B H Region 1. Philadelphia. Office of the Director 79/04/14 12
- 7905030108 Forwards IE Bulletin 79-09, "Failures of GE Type AM-2 Circuit Breaker in Safety-Related Sys " Licensee action required GRIER, B H Region 1: Philadelphia: Office of the Director 79/04/17 ip
- 7905020335 Forwards IE Bulletin 79-06A, Revision 1. "Review of Operational Errors & Sys Misalignments Identified During TMI Incident" ORIER, BH Region 1, Philadelphia, Office of the Director 79/04/18 ip
- 790S010497 Comments on IE Bulletin 79~06A re Westinghouse PWR facilities implomentation of bistable trip would create situation where safety injection actuation could be susceptible to single bus perturbations
  DEBOER.T K New York, State of 79/04/25 2pp
- R Periodic operating reports & related correspondence
- 7705220223 Forwards monthly operating rept for Apr 1979 SNOW, B A Rothester Gas & Electric Corp 79/03/10 ip
- --7905220227 Monthly operating rept for Apr 1979
  DEPEN.L Rochester Gas & Electric Corp 79/05/08 Spp
- S Reportable occurrences, LERs & related correspondence
- 7905040101 Forwards LER 79-007/03L-0
  WHITE, L D Rochester Gas & Electric Corp 79/04/30 ip
- --7903040147 LER 79-007/03L-0 on 790402 surveillance requirement for nuclear intermediate range channel test within seven days was not performed for two training criticalities Caused by unclear training procedures
  PECK.C Rochester Gas & Electric Corp 79/04/30 ip
- 7905040180 Forwards LER: 79-009/017-0 & 79-010/017-0 WHITE, L D Rochester Gas & Electric Corp 79/04/30 ip
- --7909040187 LER 79-009/01T-0 on 790416 routine sample of boron boric acid tank showed il 8% Reactor power reduction started.

  Caused by possible backflow of makeup water Check valve replaced

  PECK.C H Rochester Oas & Electric Corp 79/04/30 2pp
- ---7903040191 LER 79-010/01T-0 on 790420 routine sample of boric acid storage tanks showed less than 12% Reactor power reduction started Caused by possible backflow of makeup water Check valve replaced PECK.C H Rochester Gas & Electric Corp 79/04/30 2pp
- 7905110101 Forwards LER 79-008/03L-0.
  WHITE, L. D. Rochester 04s & Electric Corp 79/05/07 to
- --7905110104 LER 79-008/OJL-0 on 790406 boric acid flow control valve leak noted on valve outlet one inch nipple Caused by internal wald flow through defects 5 deep external pitting. Nipple replaced w/40 nipple SPECTOR:8 Rochester Gas & Electric Corp 79/05/07 ip
- 7905310431 Forwards LER 79-011/01T-0 WHITE:L D Rochester θas & Electric Corp 79/05/25 ip.
- ---7905310435 LER 79-011/01T-Ocon 790511:notified by manufacturer of pressurizer power operated relief valve that template used to fabricate valve internals not within specs Caused by error in tracer laths templats.

  SPECTOR, S. Rochester Gas & Electric Corp. 79/05/25 2pp

- DOCKET 30-249 MILLSTONE NUCLEAR POWER STATION, UNIT 1

  F Security, medical, emergency & fire protection plans
- 7905290073 Forwards response to NRC verbal questions re fire protection Engineering & design of most mode in progress COUNSIL W O Northeast Utilities 79/05/19 16pp
- H General correspondence
- 7905090150 Responds to 790124 itr expressing concern for faulty const problem associated s/compacted spent fuel racks Venting of boron plates to spent fuel pool water will not alter previous conclusion that use of racks is not dangerous ZIEMANNO L Operating Reactors Branch 2 79/04/03 3pp
- J Insurance & indemnity information
- 7905140422 Forwards Amend 14 to Indemnity Agreement B-37 per (OCFR140 changes) re increase in liability insurance from \$140 million to \$160 million, effective 790501 Supporting documentation encl
  BALTZHAN, J Antitrust & Indemnity Group 79/05/01 App
- 7905190075 Forwards executed Amend 14 to Indomnity Agreement B-39 O'CONNOR, L A Northeast Utilities 79/05/15 4PP
- P Operating license stage documents & correspondence
- 7905080381 Forwards FR notice of proposed issuance of amend to provisional UL ZIEMAN.D L Operating Reactors Branch 2 79/04/06 2pp
- 7903080343 Forwards topics deleted from systematic avaluation program review of facilities Requests review & identification of errors within 30 days from receipt of 1tr IlEMANN.D L. Operating Reactors Branch 2 79/04/16 7pp
- 7705300727 Ack receipt of 790126 plans for insp of feedwater & control rod drive return line noziles in reactor pressure vessel Forwards safety evaluation ZIEMANN.D L. Operating Reactors Branch 2 77/04/21 2pp
- --7905300731 Safety evaluation of proposed nozzle (nsp program \* Operating Reactors Branch 2 79/04/21 4pp
- 7905010485 In 780307 itr to NRC & 780201 itr to DC Switzer, util states it would be preferable to trip control valves in feedwater trains. As opposed to tripping feedwater pumps Impossible to complete installation in Spring 1979

  COUNSIL. H O Northeast Nuclear Energy Co (Northeast Utilities) 79/04/23 ip
- 7905010496 Forwards data & analysis of suppression pool temp transjents COUNSIL-H Q Northeast Nuclear Energy Co (Northeast Utilities) 79/04/24 10pp
- 7905290007 Forwards Amends 60 & 51 to Licenses DPR-21 & DPR-65, respectively.EIA & notice of issuance & negative declaration.

  ZIEMANNID L Operating Reactors Branch 2 79/04/24 3pp
- --7905290012 Amends 60 & 91 to licenses DPR-21 & DPR-65, respectively, revising ET8 to provide more flexibility in sampling schedules & collection for equatic monitoring & reflecting improved & modified program objectives ZIEMANN.D.L Operating Reactors Branch 2 79/04/24 13pp
- --7908290016 EIA supporting Amends 60 & 51 to Licenses BPR-21 & DPR-65, respectively a Office of Nuclear Reactor Regulation 79/04/24 11pp.
- --7903290019 Notice of issuance of Amends 60 & 51 to Licenses DPR-21 & DPR-65, respectively, & negative declaration.

  ZIEMANN, D L Decrating Reactors Branch 2 79/04/24 2pp
- 7905070621 Forwards justification of unlimited purging of primary containment in order to provide flexibility to operators in control of containment oxygen level & drywell pressure COUNSIL:N 0 Northwest Utilities 79/04/27 Spp.
- 7905080562 Informs that NRC draft evaluation of systematic evaluation program needs addit clarification & should be revised accordingly COUNSIL. H O Northeast Utilities 79/04/27 2pp.

- 7905080454 Forwards NEDE-20592-4P.Revision i. "Segmented Test Pig Bundle: Millstons 1.Suppl 4" dtd Apr 1979 Rept withheld (ref 105FR 790) COUNSIL.H Q Northeast Utilities 79/05/02 2pp
- 7908300645 Informs of forthcoming detailed reply to 790807 [tr rs'' nuclear power plants Plants will not start up until all post-TMI items & requirements are implemented & confirmed MENDRIELU M. Commission 79/05/11 1p
- --7905300647 Requests essurance that action required by IE info publications have been implemented before CT plants return to operation Also requests into on other anticipated NRC actions or anticipated problems
  ORASSD.E Connecticut, State of 79/05/07 #2pp
- 7905300005 Responds to V Stello 790309 ltr Forwards bar-chart showing time periods for implementation of long-term program mode Essential completion of program planned for end of 1980 CDUNS(L.W & Northeast Utilities 79/05/18 3pp
- Q Inspection reports, IE Bulletins & correspondence
- 7905240A92 Forwards IE Insp Repts 50-245/78-42 & 50-336/70-39 cn 781208-790105 No moncompliance noted BRUKNER,E J Region 1, Philadelphia, Reactor Operations bulks Support Branch 79/03/21 2pp
- --7905240704 IE Insp Repts 50-245/78-42 & 50-336/78-39 on 701200-7.
  No noncompliance noted Major areas inspected Unit 1 reactor, turbine A radwaste bldgs. Unit 2 auxiliary & turbine bldgs. condensate polishing facility & radiation protection SMEDLOSKY, J T Region 1. Philadelphia, Office of the Direct-MCCABE, E C. Region 1. Philadelphia, Reactor Operations M.S. Support Branch 79/03/20 13pp
- 7705010121 Forwards IE Info Notice 79-06. "Stress Analysis of Safety-Related Piping" ORIER, B H Region 1. Philadelphia. Office of the Director 79/03/23 1p.
- 7905010053 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Syc Air Sys Used as Source of Breathing Air " ORIER, B H Region 1, Philadelphia, Office of the Director 79/03/28 Ip
- 7705010304 Forwards IE Info Notice 79-09, "Spill of Andioactively Contaminated Resin " GRIER, B H Region 1, Philadelphia, Office of the Director 79/03/30, 2pg
- 7905290140 Forwards IE Insp Rept 50-245/79-05 on 790227-0302 No noncompliance noted BRUNNER, E.J. Region 1, Philadelphia: Reactor Operations \*\*..:|6: Support Branch 79/04/03 2pp
- --7903290145 IE Insp Rept 50-245/79-05 on 790227-0302 No noncessing nated Major areas inspected facility procedures revisions per Tach Spec amend 5 action on previous insp findings CONTE.R J. COMPILL.C J. Region i. Philadelphia. Office of the Operations Nuclear Support Branch 79/03/31 11pg
- 7905020066 Forwards IE Bulletin 79-06, "Review of Operational Erreris Sys Miselignments Identified During TMI Incident " ORIER,B H Region 1, Philadelphia, Office of the Director 79/04/11, 1p
- 7905030013 Forwards IE Builetin 79-06A, "Review of Operational Err., Sys Mitalignments Identified During TMI Incident "KEPPLER, J Q Ragion 3, Chicago, Office of the Director 79/61;
- 7908020300 Forwards IE Bulletin 79-07, "Seismic Stress Analysts at Safety-Related Piping "Licensee action required ORIER.B H Region 1, Philadelphia. Office of the Director 79704/14 ip
- 7905040039 Forwards IE Bulletin 79-06B, "Review of Operational Erran Bys Misalignments Identified During TMI Incident " ORIER.B H Region 1, Philadelphia, Office of the Director 79/04/14. ip
- 7903040224 Forwards IE Builetin 79-08, "Events Relevant to Bolling Water Power Reactors Identified During TMI Incident" Licensee action required, ORIER B H Region 1, Philadelphia, Office of the Director 79/04/14. 1p.

- 7905030077 Forwards IC Bulletin 79-09, "Failures of GE Type AX-2 Circuit Breaker in Safety-Related Sys " Licenses action required GRIER, B H
  - Region 1, Philadelphia, Office of the Director
- 7905020284 Forwards IP Bulletin 79-06A, Revision 1, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident
- Region 1. Philadelphia. Office of the Director CRIEB, B N 79/04/18
- R Periodic operating reports & related correspondence
- 7903220395 Forwards monthly operating rept for Apr 1979 CPEKA, J F Northeast Utilities 79/05/15 1p OPEKA, J F
- --7905220404 Monthly operating rept for Apr 1979 YOUNG: R Northeast Utilities 79/05/03 6
- 8 Reportable occurrences. LERs & related correspondence
- 7909300533 Forwards LER 79~012/03L~0 OPEKA, J F Northeast Utilities 79/05/21 ip
- --7905300544 LER 79-012/03L-O on 790423 while performing routine reactor bldg exhaust duct 5 refuel floor high radiation monitor functional surveillance, Channel 1 was out of calibr Caused by instrument drift # Northeast Utilities 79/03/21 2pp
- DOCKET 50-247 INDIAN POINT STATION, UNIT 2
- J Insurance & indemnity information
- 7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,29,43,76,03,100,111,140,146,151,161,164,170,173,174,178,179,190,182,185,186,107,188,189,192,192,193,194,195,197,198,200,201,204,206,207,208,210,212,214,215,\$\$ others, QUATTROCHHI,J American Nuclear Insurers 79/05/01 1p
- /908070582 Confirms increase in liability limit to \$36,000.000 for policies MF-22,26.29.38.39.44.46, 47.49.50.51.52.53.54.55.56.57.58.60.61.64.66.67.48.69.70.71.72.74.76.77.78.79.80.86.87.88.90.91.92.93.94.95 & 68.87.88.90.91.92.93.94.95 & 68.87.88.90.91.92.93.94.95 & 79.88.90.91.92.93.94.95 & 79.88.90.91.92.93.94.95 & 79.88.90.91.92.93.94.95 & 79.88.90.91.92.93.94.95 & 79.88.90.91.92.93.94.95 & 79.88.90.91.92.93.94.95 & 79.88.90.91.92.93.94.95 & 79.88.90.91.92.93.94.95 & 79.88.90.91.92.93.94.95 & 79.88.90.91.92.93.94.95 & 79.88.90.91.92.93.94.95 & 79.88.90.91.92.93.94.95 & 79.88.90.91.92.93.94.95 & 79.88.90.91.92.93.94.95 & 79.88.90.91.92.93.94.95 & 79.88.90.91.92.93.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.95 & 79.88.90.94.90.94.90.94.90.94.90.94.90.94.90.94.90.94.90.94.90.94.90.94.90.94.90.94.90.94.90.94.90.94.90.94.90.94.90.94.90.94.90.94.90.94.90.94.90.94.90.94.90.94.90.94.90.94.90.94.90.94.90.94.90.94.90.94.90.94.90.94.90.94.90.94.90.94.90.94.90.94.90.94.90.94.90.94.90.94.90.94.90.94.90
- 7905140407 Forwards Amend 21 to Indomnity Agreement B-19 per 10CFR140 changes, re increase in liability insurance from \$140 million to \$160 million, effective 790501 Supporting documentation BALTZMAN, J Antitrust & Indemnity Group 79/05/01 App
- P Operating license stage documents & correspondence
- 7905240229 Forwards proposed design criteria to be used in reracking spent fuel pool Requests comments by 790416 NRC comments relayed via telcon on 790410 Licensee should propose change to Tech Specs to provide U-235 loading limit, OLGHAN, L. Operating Reactors Branch 1 79/04/19 1p
- 7905070549 Ack receipt of NRC 790412 ltr Willing to cooperate in planned analysis scheduled for week of 790506 CAHILL, W J Consolidated Edison Co of New York 79/04/30
- 7905090287 Advises of suspension of NY Dapt of EPA permit to construct cooling tower as air containment source, pending EPA review Pertinent itre enci CAHILL, W.J. Consolidated Edison Co. of New York 79/05/04
- 7905170244 Forwards "Evaluation of Effectiveness of Continuously Operating Fine Mash Traveling Borgen for Reducing Ichthyoplankton Entrainment " Affidavit & Certificate of Operation Syc encl.

  CAHILL, W J Consolidated Edison Co. of New York 79/05/14 5pp
- ---7905170249 "Evaluation of Effectiveness of Continuously Operating Fine Mesh Traveling Screen for Reducing Ichthyoplankton Fathragmant" Consolidated Edison Co of New York 79/04/30, 30pp
- 7905300354 Forwards application for amend to License DPR~26 Class FII amend fee 5 Certificate of Evc encl CAHILL, W. J. Consolidated Edison Co. of New York 79/05/29. 2pp

- ---7909300358 Application for amend of License DPR-26 to permit engineered safequards actuation signal on low pressure regardless of pressurizer level Tech Spec page revisions & util safety valuation encl CAHILLIN J Consolidated Edison Co of New York 79/05/29 11pp
- G. Inspection reports: IE Builetins & correspondence
- 7905070189 Forwards IE Insp Rept 50-247/79-03 on 790213-14 No BRUNNER, E J Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 79/03/16 200
- --7905070210 IE Insp Rept 50-247/79-03 on 790213-16 No noncompliance noted Major areas inspected document control, records & recent changes in QA program
  KISTER: H B Region 1. Philadelphia, Reactor Operations Nuclear Support Branch AAPUDA, G, KEHOE, D Region 1. Philadelphia, Office of the Director 79/03/14 17pp
- 7905110362 Forwards IE Insp Rept 50-247/79-01 on 790107-0203 No BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Bupport Branch 79/03/20 2pp
- --7905110371 IE In≤p Rept 50-247/79-01 on 790107-0203 No mancompliance NOSITUATI EL INSP MENT 30-24/1/7-01 On /VOLD-1/2023 NO NORCOMPLIANCE NORCOMPLANCE NORCO
- 7905030272 Forwards IE Info Notice 79-07. "Rugture of Radwaste Tanks "ORIER B H Region i. Philadelphia. Office of the Director 79/03/26 19
- 7905250248 Responds to IE Bulletin 79-03 re longitudinal weld defects in certain pipe specis mfg by Youngstown Helding & Engineering Co Piping not used in Unit 2 Info on Unit 1 will be provided when returned to svc CAMILLE V Consolidated Edison Co of New York 79/04/13 2pp
- 7903020330 Forwards IE Bulletin 79-07, "Beismic Stress Analysis of Bafaty-Related Piping " Licenses action required GRIER.B N. Region 1. Philadelphia, Office of the Director 79704/14 ip
- 7905030373 Forwards IE Bulletin 79-06H. "Review of Operational Errors & Bys Misalignments Identified During TMI Incident " ORIER.B H Region 1, Philadelphia, Office of the Director 79/04/14 1p
- 7903040183 Forwards IE Dulletin 79-08, "Events Relevant to Boiling Mater Power Reactors Identified During IMI Incident " ORIER.B H Region 1. Philadelphia, Office of the Director 79/04/14 ip
- 7905010079 Forwards IE Bulletin 79-09. "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Bys " Licensee action GRIER, BH Region i. Philadelphia, Office of the Director 79/04/17 1 0
- ---79050100B3 IE Builetin 79-09. "Fai) Breaker in Safety-Related Sys " | 175(GPF-----
- 7905010497 Comments on IE Bulletin 79-06A re Westinghouse . .... facilities implementation of bistable trip would crisivation where safety injection actuation could be susceptible to single bus perturbations
  DEBDER, T. K. New York, State of 79/04/25 2pp
- 7903290177 Ack receipt of 790321 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-003/78-13 & 50-247/78-38 SMITH G H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/05/04. 2pp

- --7903290185 Responds to NRC 790228 ltr re violation noted in IE Insp Repts 30-003/78-13 & 50-247/78-38 Corrective actions developing techniques to avoid variables leading to badge anomalies
  - CAHILL.W J Consolidated Edison Co of New York 79/03/21 3pp
- --7905270188 Forwards & Insp Repts 50-003/78-13 & 50-247/78-38 on 781227-29 & 790117-18 & hotice of violation SMITH O H Region 1. Philadelphia. Fuel Facility & Materials Safety Branch 79/02/28 2pp
- --7903290193 Notice of violation from insp on 781227-29 % 790117-18 s Region i. Philadelphia. Office of the Director 79/02/28 io
- --7905290196 IE Insp Rept 50-003/78-13 & 50-247/79-38 on 781227-29 & 79017-18 Noncompliance noted failure to maintain personnel esposure limits in accordance w/t0CFR20 101 NEELY,D R., SERABIAN,J A Region I. Philadelphia, Office of the Director CROCKER,H W Region 1, Philadelphia, Fuel Facility & Haterials Safety Branch 79/02/27 12pp
- 7905310396 Forwards supplemental response to IE Bulletin 79-07 re seismic analysis as requested in 790517 meeting CAHILL.H J Consolidated Edison Co of New York 79/05/22 Spp
- R Periodic operating reports & related correspondence
- 7905220376 Forwards effluent monitoring & impingement data specified in Section 401 Certification for Apr 1979 HONTI.W A Consolidated Edison Co of New York 79/05/10 17pp
- 7905230392 Forwards daily record of fish collections for Apr 1979 W/daily spacies breakdown & total weight for Units 2 & 3 GRIER.B H Region 1. Philadelphia. Office of the Director 79/05/14 Soo
- 7905230365 Forwards monthly operating rept for Apr 1979 CAHILL-H J Consolidated Edison Co of New York 79/05/15 ip
- --7905230367 Monthly operating rapt for Apr 1979
  KAHULA:L Consolidated Edison Co of New York 79/05/04 7pp
- S Reportable occurrences, LERs & related correspondence
- 7905040004 Forwards LERs 79-013/03L-0 5 79-014/03L-0 CAHILL,N J Consolidated Edison Co of New York 79/04/27 1p
- --7905040006 LER 79-013/03L-O on 79032? pinhole leak at socket weld connection on seal injection header (line 402) downstream of seal injection filters Split collar placed around leak Permanent repairs will be made during future outage MAKEPEACE, J N Consolidated Edison Go of New York 79/04/27 to
- --7905040279 LER 79-014/OSL-0 on 790331 electric heat trace 51B found to have inoperable primary circuit Caused by defective Chromolax strip heater elements PT-512 Elements replaced & circuit returned to syc MAKEPEACE, J M Consolidated Edison Co of New York 79/04/27 ip
- 7905190015 Forwards LER 79-012/04X-1 CAHILL.H J Consolidated Edison Co. of New York 79/09/10 1p
- -790519001B LER 79-012/04X-1 on 790213 activity of precipitation sample exceeded 10 times control station level Caused by trition releases from source external to facility Manufacturer in area has modified installation to prevent recurrence MASCIULLI, 8 Consolidated Edison Co of New York 79/05/10 3ρρ
- '905190021 Forwards LER 79-015/04T-0, CAHILL.W J Consolidated Edison Co of New York, 79/05/10 ip
- ---7905190025 LER 79-D15/O4T-O on 790405 activity of precipitation sample exceeded 10 times control station level Caused by tritium releases from source external to facility Manufacturer in area has modified installation to prevent recurrence MASCIULLI. E Consolidated Edison Co of New York 79/05/to 2pp
- OCKET 50-249 DRESDEN NUCLEAR POWER STATION, UNIT 3
- Security, medical, emergency & fire protection plans
- 903030366 Forwards modified physical security plan, Revision 5 Plan withheld (ref 10CFR2. 790)
  LEE, B Commonwealth Edison Co 79/04/26 ip.

- 7903040603 Forwards pages of "Implementation of Nuclear Hutual Limitr Loss Prevention Program" in response to NRC 780629 request re fire protection administrative controls JANECEK, R F Commonwealth Edison Co 79/04/30 6pp
- O Adjudicatory correspondence
- 7905250258 Notifies properly worded contention re sabolage would be accepted Contention 6.es admitted into Duke Power Co proceeding, encompasses aspects of revised Contention 11 presented by State of IL QODDARD, R J Branch 2 79/04/06 2pp
- J Insurance & indomnity information
- 7905100163 Endorsement 99 to MAELU Policy MF-22 QERAS,T Nuclear Energy Liability Insurance Association /9/4+3/2
- 7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,185,186,187,188,189,192,193,194,195,197,198,200,201,204,204,204,207,205,210,212,214,215,& others QUATTROCHHI,J American Nuclear Insurers 79705/01 1p
- 7905070582 Confirms increase in liability limit to \$36,000.000 for policies MF-22,26.29,38.39,44.6,47,49,50.31,32,53,34.50,56.57,57,58.60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86.41,88,90.71,92,93,94,95 & 96 ROBERTS,D M Mutual Atomic Energy Liability Underwriters /9/03
- 7905140404 Forwards Amend 21 to Indemnity Agreement 11-10 per INF #414 changes, reincrease in liability insurance from #140 ms111an to \$160 million, effective 790501 Supporting documentation encl
  SALTZMAN, J Antitrust & Indemnity Group 79705/01 App
- P Operating license stage documents & correspondence
- 7905230866 Forwards application for license mod re spent first purpl benci enci GODDARD, R J Branch 2 79/03/26 1pp
- 7905080570 Requests supplemental info re 780511 application for aps fuel pool mods be sent to ABLB & intervenor 8N Bekuler ZIEMANN.D L Operating Reactors Branch 2 79/04/12 2ps
- 7905030067 Forwards notes on 790302.15 & 30 conference telecos between NRC.consultants & util re bullstin "Potential Explosive Oas Mixtures Accumulations Associated w/DMR ()ffg as 8ys Operations "
  IPPOLITO, T A Operating Reactors Branch 3 79/04/16 4pg
- 7905080141 Responds to 790305 ltr criticizing application for appropriate for appropriate for appropriate for appropriate for appropriate for approximation for approximation provides info on upcoming hearing IPPOLITO, TA Operating Reactors Branch 3 79/04/10 tp
- ---7905080151 Opposes application for approval of proposed lice(se a that would allow shipment of spent fuel between stations NOHENBOKEN.P Affiliation Unknown, 79/03/15, 2pp
- 7905040482 Notifies of intention to develop safety analysis using existing computer codes Requests add1 info
  BOLBRIO,C W Commonwealth Edison Co 79/04/26 ip
- 7905140276 Submits info re slipped refueling outage schedule Gutage will now begin in Mar 1979. All commitments & schedules for work should ref new outage date.

  JANECEK.R F Gommonwealth Edison Co. 79/05/04 ip
- 7905190016 Forwards current schedule for implementation of Mark & containment long-term mode Discusses constraints inhibiting shorter time frame completion; including sys load requirements & current fuel cycles REED, C. Commonwealth Edison Co 79/05/11 Spp
- 7905190097 Requests correction of error discovered in 780427 | % \* \* ; capacity of Nuclear Assurance Corp NAC-1 truck cask used in spent fuel transfer Cask has capacity of two BWR assemblies JANECEK, R F Commonwealth Edison Co 79/05/11 ip
- 7905250391 Forwards current licensing open items status list REED,C Commonwealth Edison Co 79/05/18 lipp.

- 790530020B Forwards summary of EDB Nuclear, Inc resolution/documentation of albow flexibility error which existed in versions of PISQL plping analysis computer program from Jan-Oct 1969 Review & reanalysis included all work through Dac 1970 PDRTER, F L EDS Nuclear, Inc 79/05/21 9pp
- --790300263 Forwards EDS Nuclear, Inc list of BHRs & piping sys which could have been impacted by deficient computer program GE has no record of reanalysis for Cooper piping sys STEPHENG.P M. General Electric Co . Nuclear Energy Products Div 79/01/24 18pp
- 7903310364 Withdraws 781212 request for exemption from 10CFR50 to flood reactor vessel during integrated primary containment leak rate test
  JANECEK,R F Commonwealth Edison Co 79/05/24 2pp
- 9 Inspection reports, IE Bulletins & correspondence
- 7905020421 Forwards response to IE Bulletins 78-12 & 78-12A. "Atypical Weld Matl in Reactor Pressure Vassel Welds"
  REED, C Commonwealth Edison Go 79/03/22 10pp
- 7905010236 Forwards IE Info Notice 79-06, "Stress Analysis of Bafety-Related Piping " KEPPLER, J Q Region 3, Chicago, Office of the Director 77/03/23
- 7905030370 Forwards IE. Info Notice 79-07, "Rupture of Radwaste Tanks "
  KEPPLER, J Q Region 3, Chicago, Office of the Director 79/03/26
- 7905010195 Forwards IE Info Notice 79-08. "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air " KEPPLER, J O. Region 3. Chicago, Office of the Director 79/03/28
- 7905010384 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
  KEPPLER, J Q Region 3, Chicago, Office of the Director 79/03/30 in
- 7905030013 Forwards IE Builetin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMT Incident" KEPPLER.J G Region 3. Chicago: Office of the Director 79/04/11
- 7903240448 Forwards IE Insp Repts 50-010/79-07, 50-237/79-09 \$ 50-249/79-07 on 790306-07, 0312 & 0323 No honcompliance noted DAVIS, A B Region 3. Chicago, Fuel Facility & Materials Safety Branch 79/04/11 2bp
- --7905240454 IE Insp Repts 50-010/79-07, 50-237/79-09 & 50-249/79-07 on 790306-07,0312 & 0323 No noncompliance noted Major areas inspected internal audits, offsite support agency coordination, emergency facilities, training & drills ORANT, W B , ESSIG.T.H ' Region 3, Chicago, Office of the Director 79/04/05 5pp
- 7905250280 Responds to IE Builetin 79-03 re welding defects in certain longitudinally welded pipe spools Plants inspected; no pipe found REED. C. Commonwealth Edison Co. 79/04/12 2pp
- 7905010569 Forwards IE Bulletin 79-066. "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "
  KEPPLER, J G, Region 3, Chicago, Office of the Director 79/04/14
- 7905040334 Forwards IE Bulistin 79-06D. "Review of Operational Errors & Sys Misslignments Identified During TMI Incident " KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14
- 7905040529 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Hater Power Reactors Identified During THI Incident "
  KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/14
- 7905030206 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Bys " Licensee action required KEPPLER.J Q Region G, Chicago, Office of the Director 79/04/17
- 7905040142 Forwards I& Bullstin 79-058, "Nuclear Incident at TMI-Buppl."

  KEPPLER, J. O. Region 3, Chicago, Office of the Director 79/04/21

- --7905040158 IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl "
  Supporting documentation encl
  Region G. Chicago, Office of the Director 79/04/21 12pp
- --7909040170 ACRS recommendations to 790320 incident at TMT Buggests high priority be placed on development of safety research on behavior of LWRs during anomalous transients

  # ACRS Advisory Committee on Reactor Safeguards 79/04/17
  200
- --7905040201 Forwards ACRS recommendations re TMI incident, presented on 790417 FRALEY,R F ACRS - Advisory Committee on Reactor Safeguards 79704/18 ip
- ---7905040221 In response to NRC 790418 ltr.states 790417 ACRB recommendations apply to all PMRs.but were not intended to require immediate changes Plant mods should be made after study of effects on overall safety. TMI excluded CARBON.H X ACRB Advisory Committee on Reactor Safeguards 79/04/20 2pp
- 7905240633 Forwards responses to IE Bulletin 79-07 requesting info re seismic analysis of safety-related piping Reanalysis indicates method of intramodal combination has little effect on pipe stresses & equipment support loads REED.C Commonwealth Edison Co 79/04/24 4pp
- 7905250206 Ack receipt of 790416 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/79-04, 50-237/79-04 & 50-249/79-04 HIND, J A Region 3, Chicago, Safeguards Branch 79/04/26 in
- ---7908250215 Responds to NRC 790328 itr re violations noted in IE Insp. Repts 50--010/79-04, 50-237/79-04 & 50-249/79-04 Corrective actions withheld (ref 10CFR2, 790) REED C Commonwealth Edison Co 79/04/16 ip
- 790513014B Forwards responses to IE Bulletin 79-06A.Revision i.ra BWR events identified during TMI-2 Util has formed task force to review BWR events & recommend corrective action, as required REED.C Commonwealth Edison Co 79/04/27 22pp
- 7905300242 Responds to IE Dulketin 79-04 No 3,4 or 6-inch Velan ewing check valves are in use at Drasden or Quad-Cities Review of Zion has identified use of valves in some piping sys but review is incomplete Will rept later REED.C Commonwealth Edison Co 79/08/01 2pp
- 7905140488 Forwards If Circular 79-07. "Unexpected Speed Increase of Reactor Recirculation Motor Generator Set Resulted in Reactor Rower Increase " KEPPLER, J.O. Region G. Chicago, Office of the Director 79/08/08 in
- R Periodic operating reports & related correspondence
- 7905160354 Forwards menthly operating rept for Apr 1979 STEPHENBON, B B Commonwealth Edison Co 79/09/08 i
- --7905160359 Monthly operating rapt for Apr 1979
  CIESZKIEWICZ.B Commonwealth Edison Co. 79/05/03 20sp
- 8. Reportable occurrences, LERs & related correspondence
- 7905080548 Forwards LER 77~005/03L-0 8TEPHENSON, B B Commonwealth Edison Co 79/05/02 1p.
- --7405080556 LER 79-005/03L-0 on 790418, during routine surveillance, ht isolation condensate flow switch differential pressure 1349 tripped Caused by instrument drift LINDBERGO.C Commonwealth Edison Co 79/05/02 ip
- 7905140319 Forwards LER 79-006/01T-0. STEPHENBON, B B Commonwealth Edison Co 79/05/04. ip
- ---790514D324 LER 79-006/OIT-O on 790424 250 voit battery was not operable. Caused by operator error Battery was recharged after refueling outage discharge test. HOLLAND.P Commonwealth Edison Co 79/09/04 2pp
- 7905300579 Forwards LER 79-009/01T-0 STEPHENBON, B B, Commonwealth Edison Co 79/05/24 keppler, J

-7-057.0583 LER 79-009/017-0 on 790511 review of records indicate valve 14:22-9a to 14:22-98 inside containment have limit switches not qualified qualified for use in LOCA environ Switches not qualified before indication equipment is nonsafety-related to the same indication equipment of the contained provided and the contained of the contained

19353/1997 Forwards LER 79-009/03L-0 STEFFENSON B B Commonwealth Edison Co 79/05/24 1p

--77133CU705 LER 79-00B/03L-0 on 790503 pinhola leak found on cleanup equalizing line Caused by eroston due to thou characteristics & possible cavitation Leak was repaired CANCEN T Corronwealth Edison Co 79/05/24 1p

CCTRET 10-250 TURKEY POINT PLANT, UNIT 3

F. Security, reducal energency & fire protection plans

7505290143 Forwards schedule for plant mods re fire protection & addl info re safety evaluation.per 790321 request undIG R E Florida Power & Light Co 79/05/21 15pp

# G Adjudicatory correspondence

7935300035 Licenser response to MF Oncavage 790209 request for hearing Argues that request is untimely % fails to describe standing Supporting documentation, affidavits & Certificate of Svc encl BAUSER MA Louenstein, Nauman, Reis, Arelfad & Toll COLL, N.A. Affiliation Unknown 79/03/09 22pp

--7905300040 Conveys desire to undertake maint program to repair facilities Describes type of repairs that should be undertaken UHRICR E Florida Power & Light Co 77/09/20 2pp

7733190175 Forwards revision to 790209 partition to intervene OricaVAGE: R P Affiliation Unknown 79/03/19 1p

--7935150182 Revision to 790209 petition to intervene re proposed QL asend to permit steam generator repairs Affidavit.motion for production of documents & Certificate of Svc encl QUGAVAGE. H P Affiliation Unknown 79/03/18

7903130735 Act receipt of 790319 Itr to Board, enci revised petition to intervene.R Daily affidavit, motion for production of documents & entry upon land for insp & other purposes Requests signed & notarized affidavit from R Daily COLL, N A Steel. Hector & Davis 79/03/23 2pp

7903150793 Answer by util in opposition to 790319 motion by MP Encavage for production of documents Certificate of Svc ancl BAUESR. M. A. Lowenstein, Newman, Reis, Azelrad & Foll COLL, N. A. Steel, Hactor & Davis 79/03/30 Opp

--7905100797 Response by util seeking denial on basis of untimeliness of MP Oncavage's petition to intervene Petitioner does not demonstrate standing nor offer admissible contentions BAUSER, M A Louentein, Neuman, Rais, Arelrad & Toll COLL: N A Steel. Hector & Davis 79/03/30 14pp

7905240477 Prehearing conference to rule on petition of MP Uncavage will be held on 790502 in Miami.FL BOARRS E S Atomic Safety and Cicensing Board Panel 79/04/05 2pp

7905270026 Replies to licenses 790330 response & MRC /40404 response to the patitioner's lack of special training or expertise Petitioner does not assert expertise but rather interests as the protected Certificate of Buc enci percentage of Participation Unknown 79/04/24 App.

7908290489 Orants FL Power & Light Co & NRC opportunity to says responses to newly submitted contentions of politioner MP Oncavage, BOMERS E 8 Atomic Safety and Licensing Board Panel 79, 5 (

# H General correspondence

7905220100 Forwards in Purcell talegram requesting granting of MP Oncavage petition for hearing & intervention Hequesia recommendation on appropriate action LEHMAN, W. House of Rep. 79704712 ip

7903240864 Requests comments on correspondence from consists + i.e. in MP Oncavage petition to intervene in hearing on proposed repairs LEMMAN House of Rep. 79704/20 3pp

7905240718 Forwards constituent's request that NRC gravit runing a special properties of the state of the sta

7905300762 Requests response to verious talegrams supposting patis from MP Oncavage to intervene in steam generator repair proceeding Telegrams enci STONE, R Senate 79/05/01 12pp

7903290483 Responds to 790412 ltr requesting consideration or washed in sugart of MP Oncavage petition to intervene Preheasing conference will be held on 790802 in Mlamirit GDSSICK/L V Office of the Executive Director for Openship # 79/05/62 10

--7905290486 Forwards constituent's telox requesting support of MP Oncevage petition for hearing & intervantion to see a generators repair LEHMAN, W. House of Rep. 79/04/12 in

# J Insurance & indomnity information

7909070497 Confirms increased liability limit to \$128.400; confirms limit to \$128.

7905140449 Forwards Amend 10 to Indomnity Agreement B 46 per t campos, re increase in liability insurance from #140 mellen to \$160 million effective 790501. Supporting documentations and SALTZMAN, J Antitrust & Indomnity Group 79/05/01 fee

7905100316 Forwards Endorsement 48 to NELIA Policy NF: 11Ph FIELDER J. Marsh & McLenon, M & M Nuclear Consultants. Fr: 52. 79/05/03 2pp

7905(00307 Forwards Endorsement 47 to NELIA Policy NC-1415 FIELDER, J. Marsh & McLenon, M & M Nuclear Consultants, Fr. 2 1.79/05/04. 2pp

7905250411 Forwards executed Amend 10 to Indemnity Agreement # # 1 increasing coverage to \$160 million
UHRIO,R E Florida Fower & Light Ca 79/05/21 Upp

7903300301 Forwards Endorsement 40 to MAELU Policy MF-35 FIELDER, J. Marsh & McLenon, M & M Nuclear Consultants, Inc. 2 s. 79/05/24 2pp

7905300311 Forwards Endorsement 41 to MAELU Policy MF-35
FIELDER, J. Marsh & McLenon, M & M Nuclear Consultants, Inc. 5 4 4
79/05/24 2pp

#### M Antitrust correspondence

- /905150234 Metion by Ft. Cities seeking antitrust hearing Renews request to argue position re review & consolidation of antitrust issue Certificate of Svc encl
  JANION R A Spiegel & McDiarmid 79/03/28 2pp
- /905190727 Forwards motion for consolidated hearings on behalf of FL Cities JABION.R A. Spiegel & McDiarmid 79/04/02 ip
- /9052.0622 Rusponds to 790328 & 790402 motions filed by Ft Cities to initiate antitrust hearing in response to NRC 780727 order Certificate of Svc encl
  DEMLY, U. CHANANIA: D., EVANB, D.J. Anti-Trust Division 79/04/17
- P Operating licensu stage documents & correspondence
- /9090B0D63 Forwards Amends 45 % 31 to Licenses BPR-31 & DPR-41, respectively, safety evaluation & notice of issuance & availability BCBMI NCI R. A Operating Reactors Branch 2 79/03/21 3pp
- ---79000000049 Amends 45 5 31 to Licenses DPR-31 & 41 respectively, adding licenses conditions or completion of facility mode & implementation of administrative controls for fire protection GGHM-NIER. Operating Reactors Dianch 2 79/03/21 Rpp
- 7905080080 Notice of issuance & availability of Amends 45 & 31 to licenses DPR 31 & DPR-41) respectively BUHWINGER: A Operating Reactors Branch 2 79/03/21 2pp
- 7905070107 forwards Amend 44 to License DPR-31, safety evaluation 5 notice of issuance 5 availability
  OCHMENGER, A Operating Reactors Branch 1 79703/30 2pp
  - 7905070114 Amend 46 to License DPR-31, permitting continued operation of Unit 3 for six equivalent months of operation OCHMENGERIA Operating Reactors Branch 1 79703/30 2pp
- ---/405070119 Sefety evaluation supporting Amend 46 to License DPR-31 # (perating Reactors Branch 1 79/03/30 5pp
  - 7907070124 Notice of issuance & availability of Amend 46 to License
    1008-31
    1008-016 Operating Reactors Branch 1 79703/30 2pp
- /905110050 Gummary of /90413 meeting w/util & Westinghouse re seismic analysis of reaction contant piping THAMMILL G M Operating Reactors Branch 1 79/04/18 Spp
- 7903080412 Forwards request to amend App A of Licenses DPR-31 & DPR-41 repressurties level Affidavit & safety evaluation encl URHIO.R C. Florida Power & Light Co 79/05/02 7pp
- /903140217 Forwards replacement first page for safety evaluation, forwarded 790502, w/Tech Spec change proposal re safety injection trip logic UNRIG.R E Florida Power & Light Co 79/05/04 2pp
- /705140220 Forwards initial response re emergency power sys periodic tests requested in NRC 770307 itr
  UNRIO.R E Florida Power & Light Co 79/05/07 2pp
- --7905140225 Instructions for insp & tests of lockout relays
  TAYLOR.R.L Florida Power & Light Co 79/08/15 App
- 7903240547 Forwards request for amend to App A of Licenses DPR-S1 & DPR-41 Amend Changes Tech Spec limits re ECCS cooling performance, in light of Westinghouse resvaluation URRIGAR E Florida Power & Light Co. 79/03/18 34pp
- 7903250426 Bubmits analysis supporting amend to App A of Licenses DPR-31 & DPR-41 DNBR safety limit of 1 24 is consistent WCOBRA IIIC computer code Forwards "DNBR Safety Limit for COBRA IIIC Analysis" URIG.R E Florida Power & Light Co 79/05/21 8pp

- --7903250430 "DNBR Safety Limit for COBRA 11IC Analysis " IRANI.A., WILSON.W. WYRICK.R Florida Pawer & Light Co 79/03/31 | Lópp
- 7903300208 Forwards summary of EDS Nuclear. Inc resolution/documentation of elbow flexibitity error which existed in versions of PISOL piping analysis computer program from Jan-Oct 1969 Review & reanalysis included all wort through Dec 1970 PORTER, F L EDS Nuclear, Inc 79/05/21 9pp
- --7905300263 Forwards EDS Nuclear Inc list of BWRs & piping sys which could have been impacted by deficient computer program GE has no record of reanalysis for Cooper piping sys STEPHEN8, P W General Electric Co .Nuclear Energy Products Div 79/01/24 | Upp
- G Inspection reports, IE Bulletins & correspondence
- 7905010195 Forwards IE Info Natice 79-06, "Stress Analysis of Safety-Related Piping" O'REILLY,J P Region 2, Atlanta, Office of the Director 79/03/23 | 2pp
- 790S010104 Forwards IE Info Notice 79-08. "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air "
  O'REILLY, J P Region 2. Atlanta, Office of the Director 79/03/28 2pp
- 7903010338 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin" O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/03/30 200
- 7905020127 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident " Licenses action required O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/11 1p
- 7905040212 Forwards IE Bulletin 79~06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident " O'RETILLY, J.P. Region 2. Atlanta. Office of the Director 79/04/14 2pp
- 7905040308 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping " Licensee action required O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 1p
- 7905040404 Forwards IE Bullatin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident "O'RETLLY.J P Region 2. Atlanta. Office of the Director 79/04/14 ip
- 7905030164 Forwards IE Bullatin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Bys " Licenses action required O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/17 2pp

- я periodic operating reports & related correspondence
- 7773393315 Forwards enalysis of annual aerial photograph of Cooling caral sus boundary UNRIG. R E Florida Power & Light Co 79705/11 2pp
- S Reportable occurrences. LERs & related correspondence
- 7905030457 Forwards LER 79-00//03L-0 ECHTIDT, A D Florida Power & Light Co 79/04/20 1p
- --7935030471 LER 79-007/03L-0 on 790321 surveillance test of RHR sys Not performed Caused by misinterpretation of scheduling info relayed from GC to operations personnel Amend proposed to change test interval STHOPPMAN H A Florida Power & Light Co 79/04/20 lp
- 7905090067 Forwards LER 79-009/03L-0 5049107.A D Florida Power & Light Co 79/04/27 in
- ~~7901097072 LEP 79-009/03L-0 on 790328 during refueling shutdown/leak observed from temporary level-indication lane near base of refueling water storage tank About 25 gallons of water leaked out Cause undetermined investigation in progress SCHOPPMAN.M A Florida Power & Light Co 79/04/27 1p
- 7905070074 Forwards LER 79-008/03L-0 ECHMIDT, A D Florada Power & Light Co 79/04/27 ip
- --7935950GEL LER 79-008/03L-0 on 790328 chemical 2 vol control sys holdup tant overfilled creating siphon through vent line 2 header. resulting in fow internal tank pressure 2 tank damage Caused by erroneous level indication SchOPPHAN.M A Floride Power 2 Light Co 79/04/27 2pp
- 7905220103 Forwards LER 79-011/03L-0 SCHMIDT.A D Florida Power & Light Co 79/05/09 ip
- 7903220122 Forwards LER 79-012/03L-0 SCHMIDT, A. D. Florida Power & Light Co. 79/03/14 1p
- --7903220128 LER 79-012/03L-O on 790414 during startup, steam supply stop valves HOV-3-1404 & MOV-3-1409 leading to turbine drives of auritient feedwater pumps failed to open fully Caused by damaged threads on valve operator stem nut Nut replaced JAMES, D.K. Florida Power & Light Co. 79/05/14 2pp
- 7905250388 Forwards LER 79-013/03L-0 SCHMIDT, A D Florida Power & Light Co 79/05/16 ip
- --7905250392 LER 79-013/03L-0 on 790416 left turbine etop valve failed to fully close when turbine was tripped to balance ercitor Cause whenown Valve tested & operated satisfactorily Valve performance will be monitored regularly JAMES.D K Florida Power & Light Co 79/03/16 1p
- T Hearing transcripts on non-antitrust matters
- 7905140567 Transcript of 790502 proceeding in Hiami, FL Pp 1-122 BOWERS, E S . HALL-D B , PARIS, D H Atomic Safety and Licensing Board Panel 79/05/02 123pp
- DOCKET 50-251 TURKEY POINT PLANT, UNIT 4

  F. Security, medical, emergency b fire protection plans
- 7905290143 Forwards tchedule for plant mods re fire protection & addl into re safety evaluation, per 790321 request GARIO,R E Florida Power & Light Co 79705/21 19pp
- @ Adjudicatory correspondence
- 7905300035 Licensee response to MP Oncavage 790209 request for hearing Argues that request is untimely & fails to demonstrate standing Supporting documentation, affidavits & Cartificate of Syc ent.

  SAUSER, A Lowerstein, Newman, Reis, Axelrad & Toll COLL, N A Affiliation Unknown 79/03/09, 22pp

- 7905150175 Forwards revision to 790209 patition to intervena GNCAVAGE, M.P. Affiliation Unknown 79/03/19 1p
- -- 7905150182 Revision to 790209 settition to intervene re proposes amend to permit steam generator repairs Affidavit, motion for production of documents & Certificate of Svc ancl ONGAVAGE.M P Affiliation Unknown 79/03/18
- 7903130753 Ack receipt of 790319 ltr to Board, encl revised position to intervene. R Daily affidavit, motion for production of focuments & entry upon land for imap & other purposes Requests signed & notarized affidavit from R Daily COLL, N A Steel, Hector & Davis 79/03/23 Jpp
- 7909150793 Answer by util in opposition to 790319 motion by MP Oncavage for production of documents Cortificate of Nyc encl
- Uncavage for production of bocoments continued of the encl encl DAUSER. H A Lowerstein, Newman, Reis, Axelrad & Toll COLL, N A Steel, Hector & Davis 79/03/30 3pp
- ~-7905150799 Response by util seeking duntal on basis of untimeliof HP Decawage's petition to intervene fetitional does not demonstrate standing nor offer admissible contentions RAUSER. If A Louenstein, Neuman, Reis, Aceirad & Toll filli, I A Steel, Hector & Davis 79/03/30 14pp
- 7905240479 Prehearing conference to rule on petition of My threavas will be held on 790502 in Miami.FL. BONERS.E S Atomic Gefety and Licensing Board Panel 147.04.05 200
- 7905290481 Requests granting MP Oncavage potition for hearth4x 4 intervention re-facility repairs DAVIG.L , MENDOZA,M Q , SMITH,W R Affillation Unknown FY/04 ifpp
- 7905300722 Response to MP Uncavage 790319 revised petition to intervene in proceeding Certificate of Svc oucl QULOBERG.5 C Branch 2 79/04/06 Bpp
- 7905240973 Requests NA Coll be included on ave list COLL,N A Steel, Hector & Davis /9/04/09 ip
- 7905250060 Forwards various mailgrams requesting granting of petil for hearing & intervention re facility repairs FISHBACK:N Affiliation Unknown 79/04/12 9pp
- 7905220065 Requests greating of MP Oncavage patition for hearable 1 intervene in util proceedings COUSING.R , BILLIG.J , BASTO.8 Affiliation Unknown /////14/19 12ps
- 7903240026 Replies to licenses 790330 response & NRC 746406, response titioner's lack of special training or expertise Patitioner does not assert expertise, but rather interests to be grotected Certificate of Byc encl ONCAVADEM P Affiliation Unknown 79704/24 App
- 7905270489 Grants FL Power & Light Co & NHC opportunity to extent responses to newly submitted contentions of petitioner MP Ducavage BOMERS. E S Atomic Bafety and Licensing Doard Panel 79/03/03-2pp
- H General correspondence
- 7905290486 Forwards constituent's telex requesting support of MP Oncavage petition for hearing & intervention re steem generators repair LEHMAN, W House of Rep. 79/04/12 1p
- 7905220100 Forwards M Purcell telegram requesting granting of MP Oncavage polition for hearing & intervention Requests recommendation on appropriate action LERMAN, of House of Rep. 79/04/12 tp.
- 7903240864 Requests comments on correspondence from constituents of MP Uncavage patition to intervene in hearing on proposed repairs
  LEHMAN, W House of Rep. 79/04/20 3pp
- 7905240718 Porwards constituent's request that NRC grant MP Onceva patition for hearing & intervention re facility repairs STONE:R. Senate 79/04/26 2pp.

- 7705300762 Requests response to various telegrams supporting petition from MP Oncavage to intervene in steam generator repair proceeding Telegrams encl
  STONE.R Senate 79/08/01 12pp
- 7905270483 Responds to 790412 ltr requesting consideration of telegram in support of MP Oncavage patition to intervene Prehearing conference will be held on 790502 in Miami.FL OSSICK,L V Office of the Executive Director for Operations 79/05/02 ip
- J. Insurance & indemnity information
- /90907049/ Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,175,107,160,102,185,186,187,188,189,172,193,194,195,197,198,200,201,204,206,207,208,210,212,214,215,4 others guartmochart. American Nuclear Insurers 79/05/01 ip
- /9050/0592 Confirms increase in liability limit to \$36,000,000 for policies MF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,56,57,58,69,70,71,72,74,76,77,78,79,80,86,87,88,90,71,72,93,74,95,5,76,77,78,79,80,86,87,88,90,71,92,93,94,95,5,66
- 7903140449 Forwards Amend 10 to Indemnity Agreement 8-46 per 10CFR140 changes, re increase in liability insurance from \$140 million to \$160 million effective 790301 Supporting documentation encl

BALTZMAN, J Antitrust & Indomnity Group 79/05/01 6pp

- /905100316 Forwards Endorsoment 48 to NELIA Policy NF-185 FIKLDER, J. March & McLenon, K & M Nuclear Consultants, Inc. Div 79/05/03 2pp
- /900100307 Forwards Endorsement 47 to NELIA Policy NF-185 f [KLDCR.J | Marsh & McLonon, M & M Nuclear Consultants, Inc. Div 79/03/04 | Zpp
- /907050411 Forwards executed Amend 10 to Indemnity Agraement B-46, increasing coverage to \$150 million UNRIO.R E Florida Power & Light Co 79/05/21 3pp
- 7907300001 Forwards Endorsement 40 to MAELU Policy MF-55 FIFLDER, J. March & Mclenon, H & M Nuclear Consultants, Inc. Div 79/03/24. Rpp.
- 7908300011 Forwards Endorsement 41 to MAELU Policy MF-55 FIELDER,J Harsh & McLenon, M & M Nuclear Consultants, Inc. Div 79708724 2pp
- M Antitrust correspondence
- /700130234 Motion by FL Cities seeking antitrust hearing Renews request to argue position re review & consolidation of antitrust issue Certificate of Svc encl
  JANLON, R A Epiegel & McDiarmid 79/03/28 2pp
- /903:50729 Forwards motion for consolidated hearings on behalf of FL Cities JANLON,R A Spiegel & McDiarmid 79/04/02 ip
- --7705150733 Motion for consolidated hearings by FL Cities Certificate of Svc encl
  JANLON, R A Spiegel & McDiarmid 79/04/02 4pp
- 7903230422 Responds to 790328 to 790402 motions filed by FL Cities to initiate antitrust hearing in response to NRC 780727 order Certificate of Evc encl. DEMEY.L., CHANANIA.F.D., EVANB.D J Anti-Trust Division 79/04/17
- P Operating license stage documents & correspondence
- 7705080063 Forwards Amends 45 & 31 to Licenses DPR-31 & DPR-41, respectively, safety evaluation & notice of issuance & availability BCHWENGER, A Operating Reactors Branch 2, 79/03/21 3pp
- --7903080069 Amends 43 & 31 to Licenses DPR-31 & 41.respectively, adding license conditions re-completion of facility mods & implementation of administrative controls for fire protection.

  BCHURNCER.A Operating Reactors Branch 2. 79/03/21 2pp
- --7905080073 Bafety evaluation supporting Amends 45 to 31 to Licenses

  PPR-31 to 41, respectively

  \*\* Operating Reactors Branch 2 79/03/21 47pp.

- ---7909080080 Notice of issuance & availability of Americ 45 & 31 to Licenses DPR-31 & DPR-41, respectively SCHWENCER, A Operating Reactors Branch 2 79/01/21 2pp
- 7905:10058 Summary of 7904:3 meeting w/util & Hestinghouse re seishic analysis of reaction coolant piping
  TRAMMELL.C M Operating Reactors Branch : 79/64/18 Spp
- 7905080412 Forwards request to amend App A of Licenses DPR-31 t CPR-41 re-pressurizer level Affidavit & safety evaluation encl URHIQ-R E Florida Power & Light Co 79/05/02 7pp
- 7905140217 Forwards replacement first page for safety evaluation forwarded 790502:w/Tech Spec change proposal re safety injection trip logic UHRIG:RE Florida Power & Light Co 79/05/04 2pp
- 7905140220 Forwards initial response to emergency power sys particular tests requested in NRC 790309 ltr
  UHRIG.R E Florida Power & Light Co 79/05/07 2pp
- --7905140225 Instructions for insp & tests of lockout relays
  TAYLOR, R L Florida Power & Light Co 79/08/15 App
- 7905240547 Forwards request for amend to App A of Licenses DPR-31 & DPR-41 Amend changes Tech Spec limits re ECCS cooling performance, in light of Hestinghouse reevaluation UHRIG.R E Florida Power & Light Co 79/05/18 34pp
- 7905250426 Submits analysis supporting amend to App A of Licenses DPR-31 & DPR-41 DNBR safety limit of 1 24 is consistent w/COBRA IIIC computer code Forwards "DNBR Safety Limit for COBRA IIIC Analysis" URIQ:R E Florida Power & Light Co 79/03/21 8pp
- --7905250430 "DNBR Safety Limit for COBRA IIIC Analysis " IRANI,A , WILSON,W , WYRICK,R Florida Power & Light Co 79/03/31 14pp
- 790530020B Forwards summary of EDS Nuclear. Inc resolution/documentation of albow floribility error which existed in versions of PISOL piping analysis computer program from Jan-Oct 1969 Review & reanalysis included all work through Dec 1970 PORTER, F L EDS Nuclear, Inc 79/05/21 9pp
- ---7905300263 Forwards EDS Nuclear, Inc list of BHRs & piping sys which could have been impacted by deficient computer program GE has no record of reanalysis for Cooper piping sys STEPHENS, P W General Electric Co , Nuclear Energy Products Div 79/01/24 18pp
- G Inspection reports, IE Bulletine & correspondence
- 7905010199 Forwards IE Info Notice 79-06. "Stress Analysis of Safety-Related Piping" O'REILLY, JP Region 2, Atlanta. Office of the Director 79/03/23 2pp
- 7905030310 Forwards IE Info Notice 79-07, "Rupture of Radwaste " O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/26 2pp
- 7905010104 Fi Contaminati Air " O'REILLY, J i 79/03/28 S
  - 79/03/30 299
- 7905020127 Forwards IE Bulletin 79-06, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident " Licenses action required o'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/11 1p
- 7905040212 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Bys Misslignments Identified During TMI Incident "
  D'REILLYJ,P Region 2, Atlanta, Office of the Director 79/04/14 2pp.
- 790304030B Forwards IE Bulletin 79-07. "Seismic Stress Analysis of Safety-Related Piping " Licensee action required O'REILLY.J P Region 2. Atlanta, Office of the Director 79/04/14 ip

- 7902040404 Forwards 1E Bulletin 79-08. "Events Relevant to Boiling Mater Power Reactors isentified Ouring THI Incident "O'PEILLY, J P. Region 2. Atlanta, Office of the Director
- PPC3030165 Forwards 16 Bulletin 79-09. "Failures of GE Type AK-2 Circuit Breater in Safety-Related Byz " Licensee action required D'REILLY.J P Region 2. Atlanta, Office of the Director 79/04/17 209
- 7905150247 Act receipt of IE Insp Repts 50-250/79-08 & 50-251/79-08 on 790227-0001 No proprietary Info
  UMRIO.R E Florida Power & Light Co 79/04/17 lp
- --7903150251 Forwards (E Insp Repts 50-250/79-08 & 30-251/79-08 on 790227-0301 No noncompliance noted LEWIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 79703/23 2pp
- -7905150257 IE Insp Rapt 50-250/79-08 & 50-251/79-08 on 790227-0301 No noncompliance noted Major areas inspected refueling maint, open items.noncompliance followup.RDs & IE builetin & circular followup Temperature & Region 2. Atjante, Reactor Operations Nuclear Support Branch 79/03/22 App
- 7905240434 Forwards response to IE Bulletin 79-07 None of methods specified are used by A/E in satsaic analysis of safety-reisted piging item 2 not applicable to A/E & HSSS Vendor advises that computer code listings are proprietary UFRFORF Florids Power & Light Co. 79/04/25 2pp
- 7905240486 Forwards "Steam Concretor Insp Program " Insp showed no new ghandeens Verified general pattern of denting is within prestrable limits Requests paraission to return facility to power operation.

  CARIGAR E Fioride Power & Light Co. 79/05/18 200
- --7903240492 "Steam Generator Insp Program "
   Florida Power & Light Co 79/05/18 25pp
- R Periodic operating reports & related correspondence
- 7903300015 Forwards analysis of annual agrical photograph of cooling canal sys boundary
  URRIO.R E Florida Power & Light Co 79/05/11 29p
- S Reportable occurrences, LERs & related correspondence
- 79C5080354 Forwards LER 79-005/03L+0 6CHR(01.A U Florida Power & Light Co 79/04/20 is
- --7903080539 LER 79-005/03L-0 on 790322 process radiation monitors R-i1 & R-i2 wers out of avc Caused by failure of air sampling discoura which supplies monitors Blower replaced & monitors returned to avc SCHOPPMAN.K A Florida Power & Light Co 79/04/20 1p
- 7905080367 Forwards LER 79-006/03L-0 SCHMIDT, A D Florida Power & Light Co. 79/04/20 ip.
- ---7903080371 LER 79-006/03L-0 on 790322 packing leak-off observed on three valves Cause Undetermined for two valves Leaking packing on third due to broten beliabus seel Unit in resling sautdown; rapeirs will be made before return to power BCHOPPHAN, H.A. Florida Power & Light Co. 79/04/20 2pp

- P. Operating license stage documents & correspondence
- 7905240166 Informs that operational portions of operator requalification must be delayed Accepts written to operational portions of requalification program if completed by 790513
  COLLING.P.F. Operator Licensing Branch. 79/04/13 1p
- DOCKET 50-254 GUAD-CITIES STATION, UNIT 1
- F Security, medical, emergency & fire protection plane
- 7903160415 Forwards sections of fire protection BER which require further NRC review valve supervision, air breathing equipment & interior hose stations MALL,R E Brookhavan National Laboratory 79/04/12 3pp
- 7905030366 Forwards modified physical security plan. Revision 5 Plan withheld (ref 10CFR2 790)
  LEE.B Commonwealth Edison Co 79/04/26 1p
- G. Adjudicatory correspondence
- /905250258 Notifies properly worded contention re embotage would be accepted. Contention 6.es admitted into Duke Power Go graceeding, encompasses aspects of revised Contention II presented by State of IL OGDDARD, R J Branch 2 79/04/06 2pp
- J Insurance & indemnity information
- 7905100163 Enforcement 99 to MAELU Policy MF-22 GERAS.T. Nuclear Energy Liebility Insurance Association 79/03/
- 7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,161,164,170,173,174,178,177,180,182,189,186,187,181,181,182,193,194,195,197,198,200,201,204,207,208,210,212,214,215,& others guartrochhi,J American Nuclear Insurers 79/05/01 ip
- 7905140436 Forwards Amend 11 to Indemnity Agreement B-47 per 100FR1 changes, re-increase in liability insurance from \$140 million to \$160 million, effective 770501, Supporting documentation encl
  SALTZMAN, J Antitrust & Indemnity Group 77007/01 6pp
- 7905210262 Forwards Endorsements 38 & 39 to NELIA Policy NF-107 & Endorsements 47 & 48 to NELIA Policy NF-201 OSTER, J. Commonwealth Edison Co. 79/03/16 App.
- P Operating license stage documents & correspondence
- 7903030067 Forwards notes on 790302:13 & RR conference telcons between NRC consultants & util re bulletin "Potential Explosive Gas Mixtures Accumulations Associated w/BMR Defiges Bys Operating Reactors Branch 3 79/04/16 App
- 7903080141 Responds to 790305 ltr criticizing application for appear of proposed license smand that would allow shipment of spent fuel between stations Provides info on Upcoming hearing IPPOLITO, T.A. Operating Reactors Branch 3 79/04/18 1p
- --7903080151 Opposes application for approval of proposed licenst 4 that would allow shipment of spent fuel between stations HOHENBOKEN, P. Affiliation Unknown 79/03/15 2pp
- 7705010526 Forwards response to NRC 781205 request for add1 grifo rinstrument setpoint changes.

  JANECEK, R F Commonwealth Edison Co 77/04/25 Spp
- 7905040402 Notifies of intention to develop safety analysis using existing computer codes. Requests addl info
  BOLBRIG.C. H. Commonwealth Edison Co. 79/04/26. 1p

- 7903190016 Forwards current schedule for implementation of Mark I containment long-term mods Discusses constraints inhibiting shorter time frame completion including sys load requisements & current fuel cycles REED: C Commonwealth Edison Co 79/05/11 3pp
- 7905190097 Requests correction of error discovered in 780423 ltr re capacity of Nuclear Assurance Corp NAC-1 truck cask used in spent fuel transfer Cask has capacity of two BMR assemblies JANECEK.R F Commonwealth Edison Co 79/09/11 lp
- /905250391 Forwards current licensing open items status list REED, C. Commonwealth Edison Co. 79/05/18 11pp
- 7705250533 Forwards "Quad-Cities Nuclear Power Station Unit 1.Gycle 5 Blartup Test Results" JANECEK.R F Commonwealth Edison Co 79/05/21 1p
- --7905250536 "Guad-Cities Nuclear Power Station Unit 1.Reload 4.Cycle 5 Btartup Test Results " " Commonwealth Edison Co. 79/05/21. 15pp
- O Inspection reports, LE Builetins & correspondence
- 7909020421 Forwards response to IE Bulletins 78-12 & 78-12A, "Atypical Wold Hatl in Reactor Pressure Vessel Holds"
  REED, C Commonwealth Edison Co 79/03/22 10pp
- /900010236 Forwards IE Info Natice 79-06, "Stress Analysis of Bafety-Related Piping"
  KEPPLER.J.O Region 3, Chicago, Office of the Director 79/03/23
- 7900003070 Forwards II. Info Notice 79-07. "Rupture of Radwaste Tanks "
  KLPPLER. J O Region 3. Chicago, Dffice of the Director 79/03/26
  is
- 7905010155 Forwards IE Into Notice 79-08. "Interconnection of Contaminated Bys w/Byc Air Bys Used as Cource of Breathing Air "
  KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/28
- /909010384 Forwards IF Info Notice 79-09, "Spill of Radioactively Contaminated Resin" KEPPLER, J.O. Region 3, Chicago, Office of the Director 79/03/30
- 7705250280 Responds to IC Bulletin 79-03 re welding defects in certain langitudinally welded pipe spools Plants inspecteding pipe found RFLD, C Commonwealth Edison Co 79/04/12 2pp
- 7905D10569 Forwards IC Bulletin 79-06A. "Review of Operational Errors & Bys Hiealignments Identified During TMI Incident" KEPPLER.J O Region 3, Chicago, Office of the Director 79/04/14
- 7905040334 Forwards IT Bulletin 79-06B, "Review of Operational Errors & Bya Misalignments Identified During TMI Incident "
  KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14
- 7905040529 Forwards IR Bulletin 79-08, "Events Relevant to Boiling Hater Power Reactors Identified During TMI Incident "
  KLPPLER, J O. Region 3, Chicago, Office of the Director 79/04/14
- 7905030206 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Bafety-Related Bys " Licensee action required. KEPPLER, J O Region G, Chicago, Office of the Director 79/04/17
- 7905040142 Forwards 1E Bulletin 79-05B, "Nuclear Incident at TMI-Bupp1" KEPFLER, J C. Region 3, Chicago, Office of the Director 79/04/21

- ~~7905040201 Forwards ACRS recommendations re TMI incident presented on 790417
  FRALEY.R F ACRS Advisory Committee on Reactor Safeguards 79/04/18 ip
- --7905040221 In response to NRC 790418 ltr.states all AIR9 790417 recommendations apply to all PMRs.but were not intended to require immediate changes Plant mods should be made after study of effects on overall safety. TMI excluded CARBON. M X ACRS Advisory Committee on Reactor Safeguards 79704/20 2pp
- 7905240633 Forwards responses to IE Bulletin 79-07 requesting info re seismic analysis of safety-related piping Reanalysis indicates method of intramodal combination has little effect on pipe stresses & equipment support loads REED.C Commonwealth Edison Co 79/04/24 App
- 7905150148 Forwards responses to 1E Bulletin 79-05A,Revision 1.re BHR events identified during TMI-2 Util has formed task force to review BHR events & recommend corrective action, as required REED.C Commonwealth Edison Co 79/04/27 22pp
- 7903300242 Responds to IE Bulletin 79-04 No 3.4 or 6-inch Velan swing check valves are in use at Dresden or Quad-Cities Review of Zion has identified use of valves in some piping ys but review is incomplete Will rept later REED, C Commonwealth Edison Co 79/05/01 2pp
- 7905140488 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Recirculation Motor Generator Set Resulted in Reactor Power Increase " KEPPLER.J G Region 3, Chicago, Office of the Director 79/05/02
- R Periodic operating reports & related correspondence
- 7905170250 Forwards monthly operating rept for Apr 1979 KALILVIANAKIS,N Commonwealth Edison Co 79/09/17 is
- --7905170260 Monthly operating rept for Apr 1979
  HANNUM, D. Commonwealth Edison Co. 79/05/17 28pp
- S Reportable occurrences, LERs & related correspondence
- 7905100296 Forwards LER 79-017/03L-0 KALIVIANAKIS,N Commonwealth Edison Co 79/04/26 ip
- --7903100297 LER 79-017/03L-O on 790416 leat between RHR water & svc water side of heat exchanger Caused by cract in pipe to flange weld of bellows assembly Pipe repaired VAHRENWALD, J Commonwealth Edison Co 79/04/26 ip
- 7909090389 Informs that release rate of radioiodine & radioactive particulate mati w/half-lives greater than eight days was 2 22 times higher than Tech Spec design objective for first quarter 1979 Caused by steam leaks & "spiking" KALIVIANAKIS,N Commonwealth Edison Co 79/04/30 2pp
- 7905240597 Forwards LER 79-018/017-0 KALIVIANAKIB:N Commonwealth Edison Co 79/05/11 le

--79

- 77051103731 Orders special prehearing conference on 790510 in St Joseph, MI to consider patitions to intervens to identify key issues b to extead a schedule for further actions in proceeding EUTOMOSER, C. Atomic Safety and Licensing Board Panel 79/04/05
- 7905110046 Forwards steam generator repair mept which accompanied 7v3103 license acerd request W/o encl BARTU C A Branch 3 79/04/16 ip
- 7903300140 Forwards steam generator repair rept which constitutes basic documentation by util accompanying 790103 request for literate amend Rept to be used as aid in preparation of gettiton to intervere EARTH C A Branch 3 79/04/16 1p
- 7925230591 Responds to NRC.Consumers Power Co & ASLB re intervention in hearings on steam generator replacement Supporting documentation & Certificate of Svc enci SIMPLAIR M Great Lakes Energy Alliance 79/04/20 19pp
- J Insurance & indennity information
- 7905070497 Confirms increased liability limit to \$124,000,000 for policise hF-1 25,43 76,83,100,111,140,146,151,161,164,170, 173 174 178 179 180, 182,185,186,187,188,189,192,193,194,195, 197,198 200 201 204 206,207,208,210,212,214,215,& others QUATIROCCHI, J American Nuclear Insurers 79/05/01 1p
- 7905160172 Forwards Assend 8 to Indemnity Agreement 8-40, per 100FR140 changes, re liability insurance increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl SALTZMAN, J. Antitrust & Indemnity Group 79/05/01 Spp
- 7905210125 Forwards Endorsements 61 & 62 to NELIA Policy NF-179
  FG3TER S C Consumers Power Co 79/05/15 3pp
- P Operating license stage documents & correspondence
- 7703070027 Forwards topics deleted from systematic evaluation program review of facilities Requests review & identification of errors within 30 days from receipt of itr ZIEMANN. D L Operating Reactors Branch 2 79/04/16 7pp
- 7905230602 Forwards steam generator repair rept Requests addl info to complete evaluation of alternatives in steam generator replacement program

  ZIEMANN.D L Operating Reactors Branch 2 79/04/17 App
- 7905080158 Forwards request for add1 info re steam generator replacement program
  ZIEMANN,D L Deerating Reactors Branch 2 79/04/19 3pp
- 7905250343 Forwards draft evaluation of systematic evaluation program Topic V-10 A. "RHR Sys Heat Exchanger " Requests review & response within 30 days IIEMANN, D.L. Uperating Reactors Branch 2 79/04/21 App
- 7903290162 Notification of 790427 meeting w/Bechtel Consumers Power & Northern States Power Co in Bethesdar HD to discuss status of review of nonconservative value used for elbow stiffness in certain piping stress calculations
  JORDAN. E. E. Division of Reactor Operations Inspections 79/04/24
- 7903250210 Summary of 790425 seeting w/C-E re natural circulation capability for C-E plants
  THADANI.A C Reactor Systems Branch 79/05/02 43pp
- 7903110085 Forwards rapid response to NRC followup questions re THI Responses may not be totally complete DEMITT, R B , HOFFMAN, D P Consumers Power Co 79/05/08 44pp.
- 7905240731 Notifies that request for addl info re degraded grid voltage should be submitted to licenses
  LAINAS. Q C Plant Systems Branch 79/05/08 3pp
- 7903230087 Forwards summary of 790501 meeting w/C-E re natural circulation conditions in C-E operating reactors
  THADANI, A C Reactor Systems Branch 79/03/09 1p
- 7903130309 Forwards addl info requested on 790308 re pressurizer code safety valves & main feedwater sys DEWITT, R B , HOFFMANN, D P Consumers Power Co 79/05/10 3pp
- 7903210150 Submits bimonthly status rept for Mar-Apr 1979 Sechtel Power Corp has been designated as A/E for cooling equipment mod HOFFMAN, D P Consumers Power Co 79/05/13 1p

- 7905220020 Forwards responses to questions re TMI incident delice A Schwencer at 790512 meeting Oversized drawing enci HOFFMAN, D P Consumers Power Co 79/05/15 20pp
- 7905230052 Responds to concerns raised at 790907 meeting Util as make mods necessary to bring piping sys to FSAR stress limits by end of next refueling outage HDFFMAN,D P Consumers Power Co 79/09/16 2pp
- 7905230095 Forwards "Axial Power Distributions from Fourier Fits" Fixed Incore Detector Powers" to clarify Tech Spec change HOFFMAN, D.P. Consumers Power Co. 79/05/17 ip
- ---7905230104 "Axial Power Distributions from Fourier Fitting of Incore Detector Powers." presented at ANS winter mosting in San Francisco.CA on 751116-21 TERREY.W B . MARKS.O H . WILLIAMSON.E A Consumers Power G: 75/11/21 7pp
- 7905300208 Forwards summary of EDS Nuclear, Inc resolution/docume of albow flexibility error which existed in versions of PISOL piping analysis computer program from Jan-Oct 1969 Review & reanalysis included all work through Dec 1970 PORTER, F. L. EDS Nuclear, Inc. 79/05/21 9pp
- --7905300263 Forwards EDS Nuclear, Inc list of DWRs & piping syscould have been impacted by deficient computer program GE has no record of reanalysis for Cooper piping sys STEPHENS, P W Obmeral Electric Co , Nuclear Energy Freducts 79/01/24 18pp
- 7905310449 Responds to IE Bulletin 78-12, "Atypical Weld Hatl i Reactor Pressure Vessels " Final rept will be submitted by 790731 BIXELD A Consumers Power Co 79/05/29 ip
- G. Inspection reports, IE Bulletins & correspondence
- 7905080084 Forwards IE Insp Rept 50-255/79-04 on 790220-23 to no violation
  HEIBHMAN.R F Region 3. Chicago, Reactor Operations Nucle
  Support Branch 79/03/08 2pp
- --7905080086 Notice of violation from insp on 790220 23 \* Region 3. Chicago, Reactor Operations Nuclear Bupport 79/03/08 ip
- --7905080093 IE Insp Rept 50-255/79-04 on 790220-23 Nuncomplian failurs to implement procedures re mods made to filter draft plugs on smergency diesel during maint JURCENSON.B L. WARNICK.R F Region 3, Chicago, Office o Director 79/03/06 Spp
- 7905010247 Forwards IE Info Notice /9-06, "Stress Analysis of Safety-Related Piping" KEPPLER.J.O Region 3. Chicago, Office of the Directos J ip.
- 7905040026 Forwards IE Info Notice 79-07. "Rupture of Radwaste KEPPLER, J O Region G. Chicago, Office of the Director 7 is.
- 7903010162 Forwards IE Info Notice 79~08, "Interconnection of Contaminated Sys w/Syc Air Sys Used as Source of Breathing Air," KEPPLER, J. O Region 3, Chicago, Office of the Director is,
- 7905010390 Forwards IE Info Notice 79-09, "Spill of Radioactive Contaminated Resin" KEPPLER, J.O. Region 3, Chicago, Office of the Director 7 ip
- 7905090167 Act receipt of 790330 ltr informing NRC of steps tab correct violations noted in IE Insp Rept 50-235/79-04 HEISHMAN.R F Region 3. Bupport Branch 79/04/06 ip
- --7905090172 Responds to NRC ltr re violations noted in IE Insp 50-235/79-04 Corrective actions diesel generators inspected & valve drain tap removed. HOFFMAN.B P Consumers Power Co 79/03/30 2pp
- 7905030023 Forwards IE Bulletin 79-06, "Review of Operational E Sys Misalignments Identified During TMI Incident " Licensee action required KEPPLER, J. G. Region 3, Chicago, Office of the Director 7 is

- 7905010579 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified during TMI Incident "
  KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/14
- 7903040324 Forwards IE Bulletin 79-068, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident " Licensee action required
- KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/14
- 7905040548 Forwards IE Builetin 79-08. "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident " KEPPLER, J O Region 3. Chicago. Office of the Director 79/04/14
- 7905070162 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping " Licensee action required KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14
- 790303020 Forwards IE Builetin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " Licensee action required
- KEPPLER, J G Region 3. Chicago, Office of the Director 79/04/17
- 7905080486 Forwards IE Bulletin 79-058. "Nuclear Incident at TMI-Buppl" KEPPLER,J 0 Region 3, Chicago, Office of the Director 79/04/21
- 7905150355 Responds to 790329 request to allow util to combine reviews of IE Bulletin 79-02 t systematic evaluation program Topic III-5 A Since bulletin involves safety issue, NRC refuses to extend time for review
- extend time for review

  KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/24
- 7905240309 Responds to IE Bulletin 79-06B ra TMI errors Conditions & events which led to TMI incident were reviewed w/employees HOFFMAN,D P Consumers Power Co 79/04/27 10pp
- 7905280364 Responds to IE Bulletin 79-01, per 790301 discussion w/HJ Wong Identifies & compares computer program used in seismic analysis of safety-related piping HOFFPMAN.D P Gonsumers Power Co 79/05/03 3pp
- R Periodic operating reports & related correspondence
- 7903130414 Forwards monthly operating rept for Apr 1979 ADAMS,W E Consumers Power Co 79/05/07 1p
- --7905150416 Monthly operating rept for Apr 1979 BODTKE.P J Consumers Power Co 79/05/07 4pp
- 8 Reportable occurrences, LERs & related correspondence
- 7905040384 Forwards LER 79-016/03L-0 HDFFMAN, D P Consumers Power Co 79/04/30 1p
- --7705040407 LER 79-016/03L-0 on 790406 diesel generator gutput breaker has potential to lockout open, Caused by failure of contact on shutdown sequencer to operaty Sequencer repaired \* Consumers Power Co 777/04/20 ip
- 7905080537 Forwards LER 79-017/03L-0 HOFFMAN, D P Consumers Power Co. 79/05/04 1p
- ---7905080537 LER 79-017/03L-0 on 790404 while taking battery voltage readings, two cells in station battery 2 burst due to explosion of hydrogen inside cells. Battery taken out of svc Two replacement cells ordered \* Consumers Power Co 79/04/04 ip
- 7905100249 Forwards LER 79-009/01X-1 HOFFMAN, D P Consumers Power Co 79/05/07 1p
- ---7905100252 LER 79-009/01X-1 on 790R20 design review indicated butterfly valves may not close under accident conditions Caused by vague purchase specs which did not include requirements for closing against pressure.

  \* Consumers Power Co 79/05/07 ip.
- 7905100255 Forwards LER 79-018/03L-0 HDFFMAN, D P Consumers Power Co. 79/05/07 1p

- --7905100259 LER 79-018/03L-0 on 790409 reactor made critical w/o conducting flow test of lines Caused by misinterpretation of Tech Specs Personnel instructed to exercise care when reviewing operability requirements • Consumers Power Co 79/05/07 ip
- 7905150615 Forwards LER 79-019/03L-0 HOFFMAN,D P Consumers Power Co 79/05/10 1p
- --7905150625 LER 79-019/03L-0 on 790331 sump drained to auxiliary bldg floor drains through test connection located between containment bldg isolation valves Caused by communication failure Corrective action still being evaluated \* Consumers Power Co 79/05/10 1P
- 7905220327 Forwards LER 79-020/01T-0 HOFFMAN, D P Consumers Power Co 79/05/15 is
- --7905220335 LER 79-020/01T-0 on 790501 restraints for piping between power conversion sys safety injection tanks B % D not adequate Caused by program error used by consultant to determine hanger placement

  \* Consumers Power Co 79/05/15 ip "
- 7905220340 Forwards LER 79-013/01X-1 HOFFMAN, D P Consumers Power Co 79/05/15 ip
- --7905220343 LER 79-013/01X-1 on 790327 level in T-B2C safety injection tank decreased while draining D tank to permit increase in boron concentration Caused by seal leakage CV 3004 drain valve will be repaired during next refueling outage \* Consumers Power Co 79/05/15 1p
- T Hearing transcripts on non-antitrust matters
- 7905240330 Transcript of 790509 meeting in St Joseph.MI Pp 1-171 BECHMOEFER,C . ANDERSON.G C . LIVINGSTON.S Atomic Safety and Licensing Board Panel 79/05/09 172pp
- DOCKET SO-259 BROWNS FERRY NUCLEAR POWER STATION, UNIT 1

  J Insurance & indomnity information
- 7905140462 Forwards Amend 12 to Indomnity Agreement H-52 per 10CFR140 changes: re increase in liability insurance from \$140 million to \$150 million.effective 790501 Supporting documentation enct
  SALTZMAN, J Antitrust & Indomnity Group 79/05/01 6ns
- 7905080390 Forwards Endorsement 47 to ANI Policy NF-198 FIELDER.J Horsh & McLenon, M & M Nuclear Consultants. Inc Div 79/05/03 2pp
- 7905080394 Forwards Endorsement 48 to ANI Policy NF-198 FIELDER. J Marsh & McLenon, M & M Nuclear Consultants. Inc Div 79/05/03 2pp
- K Utility Final Bafety Analysis Report (FBAR) & amends
- 7905110024 Forwards Amend 68 to FBAR
  OILLELAND, J E Tennessee Valley Authority 79/05/08, 2pp
- --7905110031 Amend 48 to FSAR W/oversized drawings \* Tennessee Valley Authority 79/05/08 100pp
- P. Operating license stage documents & correspondence
- 7903080033 Ack receipt of Class II fee & application for amend to Licenses DPR-33.DPR-52 & DPR-68 Requests payment of addl fee. MILLER.W O License Fee Management Branch 79/04/04 ip
- 7905110177 Submits schedule for torus mods, in response to NRC 790312 ltr to HO Parris GILLELAND, J. E. Tennessee Valley Authority 79/05/04. 3pp
- 7905140371 Forwards "Summary Rept. Refueling Test Program, Cycle 3 " GILLELAND, J. E Tennessee Valley Authority 79/05/07. ip
- --7905140378 "Summary Rept.Refueling Test Program.Cycle 3." \* Tennessee Valley Authority 79/05/07 4pp

- 7905240846 Notification of 790523 meeting w/util in Chattendoga.TN to discuss NRC presentation on results of facility vital area confirmatory analysis Discussion will cover 100FR2 790 info & will be closed to public CLARK.R A Reactor Safeguards Licensing Branch 79/05/08 ip
- 7705300208 Forwards summary of 608 Nuclear. Inc resolution/documentation of elbow flexibility error which existed in versions of PISCL piging analysis computer program from Jan-Oct 1969 Review & reanalysis included all work through Dec 1970 PORTER.F L EDS Nuclear. Inc 79/05/21 7pp
- --790300263 Forwards EDS Nuclear Inc list of BMRs & piping sys which could have been impacted by deficient computer program GE has no record of reanalysis for Cooper piping sys STEPHENS.P W General Electric Co , Nuclear Energy Products Div 79/01/24 18pp
- G Inspection reports, IE Bulletins & correspondence
- 7905180103 Forwards IE Insp Repts 50-259/79-04.50-260/79-04 & 50-276/79-04 on 790102-0202 No nancompliance noted O'REILLY, J P Region 2. Atlanta. Office of the Director 79/03/22 2pp
- --7905150107 IE Insp Repts 50-259/79-04.50-260/79-04.50-296/79-04 on 790102-0202 No noncompliance noted Major areas inspected plant operations refueling & restart of Unit 1.plant tour & liquid raduasts processing SULLIVAN.R F Region 2. Atlanta, Office of the Director DANCE.H C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 79/03/19 7pp
- 7905010211 Forwards IE Info Notice 79-06, "Stress Analysis of Bafety-Related Piping" O'REILLY, J P Region 2. Atlanta, Office of the Director 79/03/23 2pp
- 7905:50:38 Forwards IE Insp Repts 50-259/77-05,50-260/79-05 & 50-276/79-05 on 790226-0302 No noncompliance nated LEMIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/23 2pp
- --7905150147 [E Insp Repts 30-259/79-05.50-260/79-05 & 50-296/79-05 on 790226-0302 No noncompliance noted Major areas inspected reportable secondary containment leak rate testing. IE circulars & builetins PRICE. D 8 Region 2. Atlanta. Office of the Director DANCEH C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 79/03/22 App
- 7905010113 Forwards IE Info Notice 79-08. "Interconnection of Contaminated Sye w/Svc Air Sys Used at Source of Breathing Air "
  O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/03/28 200
- 7908010363 Forwards IE Info Notice 79-09: "Spill of Radioactively Contaminated Resin " O'REILLY, J P Region 2. Atlanta. Office of the Director 79/03/30 2pp
- 7905080175 Responds to 1E Bulletin 79-03 No evidence that any stainless steel pipe mfg by Youngstown Welding & Engineering Ca was used in any ABME Class [.II] or III sefety-related sys GILLELAND.JE Tennossee Valley Authority 79/04/12 1p
- 7903030369 Forwards IE Bulletin 79-07. "Belimic Stress Analysis of Safety-Related Piping " Licenses action required O'REILLY, J.P. Region 2. Atlanta, Office of the Birector 79/04/14 Jpp
- 7903040233 Forwards IE Bulletin 79-068, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident " Region 2, Atlanta, Office of the Director 79/04/14 | Gpp
- 7903150700 Forwards IE Bulletin 79-08, "Events Relevant to BHRs Identified During TMI Incident "Licensee action required. D'REILLY, J P. Region 2, Atlanta, Office of the Director 79/04/14 2pp
- 7905030172 Forwards IE Bulletin 79-09, "Failures of QE Type AK-2 Circuit Breaker in Safety-Related Sys " Licensee action regulred O'REILLY J P Region 2, Atlanta, Office of the Director. 79/04/17. 2pp
- 7905020477 Forwards IE Bulletin 79-96A, Revision 1, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident."

  O'REILLLY, J.P. Region 2, Atlanta, Office of the Director. 79/04/18. 2ab

- 7703250344 Forwards response to Item 7 b of IE Insp Repts 50-259/79-05 50-260/79-05 & 50-296/79-05 re deterioration of Buna-N components (n ASCO solenoids, as followup to IE Bulletin 78-14 OILLELAND, J E Tennessee Valley Authority 79/04/20 3pp
- 7905300745 Forwards response to IE Bulletin 79-08 Plant superintendent will present review of TMI incident to all managers & supervisors w/operational responsibilities Containment isolation design & procedures have been reviewed OILLELAND.J E Tennessee Valley Authority 79/04/25 14pp
- 7905240947 Ack recaipt of 790423 itr informing NRC of steps taken to correct violations moted in IE Insp Repts 50-259/79-07.
  50-260/79-07 & 50-296/79-07
  SUTHERLAND, J T Region 2. Atlanta, Fuel Facility & Materials
  Safety Branch 79/04/30 2pp
- ---7905240972 Responds to NRC 790330 ltr re violations noted in IE [msp Repts 50-259/79-07, 50-260/79-07 & 50-296/79-07 Corrective actions entire radwaste bidg properly posted as radioactive area OILLELAND,F E Tennessee Valley Authority 79/04/23 App
- --7905240992 Forwards IE Insp Repts 50-259/79-07,50-260/79-07 & 50-276/79-07 on 790226-0302 & notice of violation SUTHERLAND. J T Region 2, Atlanta, Fuel Facility & Materials Bafety Branch 79/03/30 2pp
- --7909241003 Notice of violation from insp on 790826-0302

  \* Region 2, Atlanta, Office of the Director 79/03/30 2pp
- --7905241005 IE Insp Repts 50-259/79-07.50-260/79-07 & 50-296/79-07 on 790226-0302 Noncompliance noted failure to post radiation area label containers of radioactive matl & barricade high radiation area JACKEDN.L Region 2. Atlanta. Office of the Director OfBSON.A F Region 2. Atlanta, Fuel Facility & Materials Safety Branch 79/03/29 2pp
- --7905241005 IE Insp Repts 50-259/79-07.50-260/79-07 & 50-276/79-07 on 790226-0302 Noncompliance noted failure to post radiation area, label containers of radioactive matl & barricade high radiation area JACKSON, L Region 2, Atlanta, Office of the Director 79/03/29 200
- 7903240652 Forwards responses to IE Bulletin 79-04 re incorrect swing check valve weights Corrected valve weights do not create any overstressing in pipes, hangers or supports Addl infowill be provided by 790511 OILLELAND. JE Tennessee Valley Authority 79/09/01 App
- R Periodic operating reports & related correspondence
- 7905030343 Forwards "Environ Radioactivity Levels, Annual Rept 1978 " CILLELAND, J E Tennessee Valley Authority 79/04/27 ip
- ---7903030349 "Environ Radioactivity Levels, Annual Rept 1978 "
  \* Tennesses Valley Authority MRM-79-3-8F2 79/04/27 SOpp
- 7905010475 Forwards "Fish Impingement Rept" for first quarter 1979 OILLILAND, J E Tennessee Valley Authority 79/05/01 2pp
- --7903010476 "Fish Impingement Rept" for first quarter 1979 \* Tennessee Valley Authority 79/05/01 14pp
- 7905150346 Forwards monthly operating rept for Apr 1979
  DEMEASE, J Q Tennessee Valley Authority 79/05/09 1;
- --7905150352 Monthly operating rept for Apr 1979
  DEWEASE, J G Tennessee Valley Authority 79/04/30 36pp
- 8 Reportable occurrences: LERs & related correspondence
- 7905090314 Forwards LER 79-007/03L-0 FOX.H 8 Tennesses Valley Authority 79/05/02 ip
- --7905090316 LER 79-007/03L-0 on 790404 one zone of initiation logic for spreadar room sprinkler sys found inoperable Caused by failure of contact on auxiliary relay to make up Relay replaced.

  \* Tennessee Valley Authority 79/05/02 2pp

- DOCKET 30-260 BROWNS FERRY NUCLEAR POWER STATION, UNIT 2 J. Insurance & Indomnity Information
- /905140462 farwards Amend 12 to Indemnity Agreement B 52 per LOCER140 changes, re-increase in liability insurance from \$140 million to \$160 million effective /90501 Supporting documentation end
- 7705080:190 forwards Endorsement 47 to ANI Policy Nf 198 FILDER, J. Harsh & Hittenon, H & H Notlean Consultants, Inc. Div. 77(05/01) dep
- /909000794 forwards Indorsament 48 to ANI Policy NJ 198 f1FIDIR,J Marsh & McLenon, M & M Nuclear Consultants, Inc. Div 79/09/0} dpp
- K Utility I mai Hafety Analysis Report (PBAR) & amonds
- 7905110024 Forwards Amend All to FDAN
  OITLELAND, J. L. Tennesses Valley Authority 79705708 2pp
- 790511003) Amend AB to FBAN Wyoversteed drawings a Tennessee Valley Authority 79705700 100pp
- P Operating license stage documents & correspondence
- 2905000033 Ack receipt of Glass II fee & application for amend to Licenses DPR-35 DPR-82 & DPR-66 Requests payment of addifac
  - Military () Liceuse Fee Hanagement Dranch 79/04/04 to
- /905190104 Natifies of refind of fees, semitted /H0709, for authority to transfer feel between facility 6 Grystal River Unit (Hefund will be sent when processed HILLER, WO License fee Management Branch /9705/0) ip
- 7905110177 Bubmits withedule for turus mode, in temporae to NRC 790312 Iti tu HD Parris OlititaNDD JI Temposses Valley Authority 79705704 Dpp
- 7903240086 Notification of 290321 meeting woutil in Chattenoogs, TN to discuss NRC presentation on results of facility vital area confirmatory analysis Discussion will cover 100582 790 (offo & will be closed to public Chark, R.A. Reactor Habsguards Econsing Dranch 79/05/00 ip
- 790517026H Lorwards addl into re 790209 request for Yech Upec amend to allow one relief valve out of evu w/no decrease in power QHILELAND.J I Tennessee Valley Authority 79705715 19pg
- 790%170269 "Supplemental Helpad Litteraing Submittal for Reload 2 " IRVIN.A H. BRUGGER () - Quieral Flectric Co. Nuclear Energy Products Div. NI DO. 24169A - 79704730 - 24pp
- 7905230378 Responds to 79052) Itr Forwards add1 info re proposed Fech Base changes for startup test program code loading verification & limiting cases after dc power failure Officiano...) & Tennesses Valley Authority 79705716 7pp
- 7905'100208 Forwards summary of PDS Nuclear Inc resolution/documentation of elbow flexibility error which silsted in versions of PISOL piping analysis computer program from Jan-Oct 1969. Review & reamalysis included all work through Dec 1970 PORTER F L EDS Nuclear Inc 19705'221 9pp
- --7405300263 Forwards EDB Nuclear, Inc list of BHRs & piping sys which could have been impacted by deficient computer program OE has no record of reanalysis for Cooper piping sys STEPHENS, P. W. Goneral Flectric Co., Nuclear Energy Products Div 7940124 1080
- Q Inspection reports. IE Bulletins & correspondence
- 7903130103 Forwards IL Insp Repts 50 259/79-04.50 260/79-04 50-296/79-04 on 790102-0202 No noncompliance noted 0'RE-HLLY, J.P. Region 2. Atlanta. Office of the Director 79/03/22 2pp
- --7905150107 JE Insp Repts S0-239779-04.50 260/79-04 & 50-296/79-04 on 790102-0202 No noncompliance noted Major areas inspected plant operations refueling & restart of Unit i, plant tour & liquid radwasts processing SULLIVAN, R. F. Region 2. Atlanta, Office of the Director DANCE, H.C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch /9/03/19 7pp

- 7905010211 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piging" O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/03/23 2pp
- 7905150138 Forwards IE Insp Repts 50-259/77-05, 50-260/79-05 & 50-276/79-05 on 790226-0302 No noncompliance noted. LEWIG.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/23 2pp
- --7905150147 IE insp Repts 50-209/79-05:50-260/79-05 & 50-296/79-05 on 790226-0302 No noncompliance noted Major areas inspected reportable secondary containment leak rate testing. IE circulars & bullstins PRICE, D.B. Region 2. Atlanta, Office of the Director DANCL. H.C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch 79/03/22 6pp
- 7905010113 Forwards IF Info Notice 79-08, "Interconnection of Contaminated Bys W/Bvc Air Bys Used as Bource of Breathing Air" O'REHLY, J P Region 2, Atlanta, Office of the Director 79/07/28 200
- 7705010363 Forwards If Info Notice 79-09: "Spill of Radioactively Contaminated Resin"
  O'REILLY, J P Region 2: Atlanta, Office of the Director 79701/30 2pp
- 7905080176 Responds to IE Builetin 79-03 No evidence that any stainless steel pipe mtg by Youngstown Helding & Engineering Co was used in any ABHF Class I.II or III safety-related sys OILLELAND, J. E. Tennessee Valley Authority 79/04/12 ip
- 7905030368 Forwards IF Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licenses action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79704714 Spp
- /905040233 forwards IE Bulletin /9-06B, "Review of Operational Errors & Bys Hisalignments Identified During THI Incident " O'HEILLY, J.P. Hegion 2, Atlanta, Office of the Director, 79/04/14 | Opp
- /905150700 Forwards IF Bulletin 79-00. "Events Relevant to Biffs Identified During TMI Incident," Licensee action required O'RUILLY J P. Region 2. Atlanta, Office of the Director /7/04/14 | 2pp
- 79030.00174 Forwards IC Bulletin 79-09, "Failures of QE Type AK-2 Circuit Breaker in Gafety-Related Bys." Licenses action required, O'REILLY J.P. Region 2. Atlanta, Office of the Director, 79/04/17 2pp
- 7905020479 Forwards II Bulletin 79-Q6A, Revision i, "Review of Operational Errors' & Dis Misalignments identified During TMI Incident "
  DTREILEY.J P Region 2, Atlanta, Office of the Director 79704/10 Upp
- 7905250344 Forwards response to Itam 7, b of IE Insp Repts 60-259/79-05, 50-260/79-05 t 50-296/79-05 re deterioration of Buna-N components in ASCO eclanoids as followup to IE Bulletin 78-14 OILLELAND, J.F. Tennessee Valley Authority 79/04/20, Sap.
- 7905300745 Forwards response to IE Bulletin 79-08 Plant superintendent will present review of THI incident to all managers & supervisors w/operational responsibilities Containment isolation design & procedures have been reviewed.
  OILLELAND. J. E. Tennessee Valley Authority. 79/04/25, 14pp.
- 7905240947 Ack receipt of 790423 lir informing NRC of steps taken to correct violations noted in IE Insp Repts 50-289/79-07, 50-280/79-07 t 50-296/79-07 BUTERIAND, JT Region 2. Atlanta, Fuel Facility & Materials Bafety Branch 79/04/30. 2pp.
- ---7905240972 Responds to NRC 790330 ltr re violations noted in IE Imap Repts 50-259/79-07, 50-260/79-07 & 50-296/79-07 Corrective actions, antire radwaste bldg properly posted as radioactive area OILLELAND, F. E. Tennesses Valley Authority. 79/04/23 App.
- --7905240992 Forwards IE Insp Repts 50-259/79-07.50-260/79-07 & 50-296/79-07 on 790226-0302 & notice of violation BUTHERLAND, J T. Region 2. Atlanta, Fuel Facility & Materials Bafety Branch. 79/03/30 2pg
- --7903241003 Notice of violation from insp on 790226-0302.

  Region 2: Atlanta: Office of the Director. 79/03/30. 2pp

- --7905241005 IE Insp Repts 50~259/79-07.50-240/79-07 & 50-296/79-07 on 790226~0302 Noncompliance noted failure to post madiation area. Sabel containers of radioactive mat) & barricade high radiation area. JACKSON, L. Region 2. Atlanta, Office of the Director QIBSON.A F. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 79/03/27 2pp
- 7905240652 Forwards responses to IE Bulletin 79-04 re interrect swing check valve weights Corrected valve weights do not create any overstressing in pipes hangers or supports Add1 info will be provided by 790511 QILLELAND.J E Tennesses Valley Authority 79/05/01 App
- R Periodic operating reports & related correspondence
- 7705030343 Forwards "Environ Radioactivity Levels Annual Rept 1978 " OILLELAND, J. E. Tennessee Valley Authority 79/04/27 1p
- --7905030349 "Environ Radioactivity Levels, Annual Rept 1978 "
  \* Tennessee Valley Authority MRH-79-3-BF2 79/04/27 Sopp
- 7905010478 Forwards "Fish [mpingement Rept" for first quarter 1979 OILLILAND, J & Tennessee Valley Authority 79/05/01 2pp
- --7903010476 "Fish Impingement Rept" for first quarter 1979
  \* Tennessee Valley Authority 79/05/01 14pp
- 7905130346 Forwards monthly operating rept for Apr 1979
  DEWEASE, J G Tennesses Valley Authority 79/05/09 ip
- --7905(50392 Honthly operating rept for Apr 1979
  DEWEASE.J O Tennessee Valley Authority 79/04/30 36pp
- S Reportable occurrences, LERs & related correspondence
- 7905110313 Forwards LER 79-004/03L-0 FOX.H S Tennesses Valley Authority 79/05/07 ip
- 7905110318 LER 79-004/031-0 on 790414 reactor bldg turbine bldg & refyeling zone vent exhaust monitor RH-90-250 failed surveillance test SI 4 8 B-4 3.Section 4s Caused by failure of input card for radiation monitor

  \* Tennessee Valley Authority 79/05/07 2pp
- 7905230078 Forwards LFR 79-005/03L-0 FOX:8 & Tennessee Valley Authority 79/05/17 1p
- ~7905230336 LER 79~005/03L~O on 790419 broken terminal discovered on shutdown board D battery Cause unknown Affected calls replaced & personnel instructed in proper tightening methods # Tennesses Valley Authority 79/03/17 2pp
- 7905310352 Forwards LER 79-008/017-0 FOX.H 8 Ternesses Valley Authority 79/05/18 1a

- 7905150328 Notification of change in 780901 submittal Fire protection penetrations filled w/9 inches of foam instead of 12 inches UTLEY,E E Garolina Power & Light Co 79/09/09 ip
- 7905250121 Forwards application for amend to License DPR-23 revising Teth Space re fire protection sys UKLEY, E.E. Caroline Power & Light Co. 79/05/17 1p
- --7905R50124 Application for amend to License DPR-23 revising Tech Space re fire protection sys # Carolina Power & Light Co 79/03/17 12pp
- @ Adjudicatory correspondence
- 7905140174 Forwards TF Carter 790122 memo describing secent draft document re subotage of spent nuclear fuel Info is being assessed ASLAB will be notified upon completion LEWIS.8 H Brench 2 79/03/30 3pp
- 7905240603 Forwards EQ Case 780403 memo to 5 Levine re studies to determine capability of existing personnel neutron dosimetry system another reactor heutron environ LEMIS.8 H Branch 2 79/04/02 7pg
- 7905240771 Advises that Suppl 2 of SER was issued 790330 Recommends conference call to discuss ASUS plans for future action LEMIS:8 H Branch 2 79/04/04 1p
- J Insurance & indemnity information
- 7905070497 Confirms increased liability limit to \$124,000.000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,176,179,180,182,185,186,187,188,189,192,193,194,195,197,198,200,201,204,206,207,208,210,212,214,215,5 others QUATTROCHEL, J American Nuclear Insurers 79/05/01 1p
- 7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,36,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,60,86,617,88,90,91,92,83,94,95 & 76,80
- /905160183 Forwards Amend 8 to Indemnity Agreement 8-43.per 10CF8140 changes,re liability insurance increase from \$140 million to \$160 million.effective 790801 Supporting documentation encl SALTIMAN.J Antitrust & Indemnity Group 79/08/01 Spp
- 7905140337 Forwards Endorsement 46 to MAELU Policy MF-49 GRAHAM, N E Carolina Power & Light Co 79/05/0/ 2pp
- 7905170233 Forwards Ampnd 9 to Indemnity Agreements B-42 & U-/I reflecting increase in primary liability insurance provided by ANI/MAELU BARHAM.C D Bouglass & Barham 79/05/11 3pp
- P Operating license stage documents & correspondence
- 7905040307 Forwards Suppl 2 to 740520 safety evaluation of proposed gower increase SCHMENCER: A Operating Reactors Branch 1 79/03/30 2pp
- --7905040309 Suppl 2 to 740520 safety evaluation of proposed when a License DPR-23, allowing power increase from 2,200 MWt to 2,300 MWt
- \* Operating Reactors Branch i 79/03/30 30pp
- 7903070121 Forwards Amend 36 to License DPR-23, tafety evaluation & notice of issuance & availability
  SCHMENGER, A Deparating Reactors Branch 1 79/04/11 20p
- --7905070125 Amend 36 to License DPR-23 authorizing removal of all part-length control rods from reactor SCH-MCNGER. A Operating Reactors Branch 1 79/04/ii 11pp
- --7905070127 Bafety evaluation supporting Amend 36 to License OFR. \* Office of Nuclear Reactor Regulation 79/04/11 3pp
- --7905070130 Notice of issuance & availability of Amend 36 to 1.5ce BPR-23 SCHWENCER:A Operating Reactors Branch 1 79/04/11 Rpp

- #905150290 Notifies that 790306 application for amend to License DPR-23 has been received w/\$6,400 for two Class 2 % one Class 3 amends Review determined first & second changes each require Class 3 amend fee MILLER,W 0 License Fee Management Branch 79/04/20 1p
- /909030331 Notifies that util will perform extended burnup test for four assemblies during Cycle 7 Forwards program description UTLEY/E E Garolina Power & Light Co 79/04/23 3pp
- \$7905020333 Forwards \$2,800 add1 license fee requested in NRC 790420 ltm UTLEY,E E Carolina Power & Light Co. 79/04/27 ip
- #905080437 Requests extension until 790731 to submit evaluation justifying unlimited purging of containment bldg during normal operation UTLEY/EE Carolina Power & Light Co 79/05/01 ip
- 7905080453 Forwards oversized maps & photo attachments to util 781129 ropt on main dam core trench features W/o Grawings FLOYD:8 D Carolina Power & Light Co 79/05/08 3pp
- #905220346 Requests change in Tech Bpecs to reflect deletion of pressurizer pressure signal W/supporting documentation & Glass III amend fee UTLEY,EE Carolina Power & Light Co 79/03/18 9pp
- #903290374 Forwards telemic reanalysis of RCS in response to 790517 & 790518 telegra Loads & moments meet FBAR criteria UTLEY.E.E Carolina Power & Light Co 79/05/21 4pp
- Inspection reports: TE Bulletins & correspondence
- F905230583 Forwards IE Insp Rept 50-261/79-04 on 790213-16 No noncompilance noted LEMIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/19 2pp
- --7905230592 IE Insp Rept 50-261/79-04 on 790213-16 No noncompliance noted Major areas inspected licenses event followup & plant operations MCHENRY, T J Region 2, Atlanta, Office of the Director DANCE.H C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/15 4pp
- F90901016B Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping " O'REILLY: J P Region 2. Atlanta, Office of the Director 79702723 2pp
- F905030294 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks." O'REILLY, J P Ragion 2, Atlants. Office of the Director 79/03/26 2pp
- \*\*905010095 Forwards IE Info Notice 79-08. "Interconnection of Contaminated Sys w/Svc Air Sys Used &s Source of Breathing Air "
  O'REILLY, J P Region 2. Atlanta. Office of the Director 79/03/28 2pp.
- F903010346 Forwards IE Info Notice 79-09, "Spill of Redioactively Contaminated Resin." O'REILLY, JP Region 2. Atlanta, Office of the Director 79703/30 2pp
- \*\*#705020125 Forwards IE Bulletin 79-06. "Review of Operational Errors & Sys Misslignments Identified During TMI Incident " Licensee action required.

  O'REILLY, J P Region 2. Atlanta. Office of the Director 79/04/11. is
- F905230613 Responds to IE Bulletin 79-03.No pipe spools from Youngstown Helding & Engineering Co are used or planned to be used UTLEY, E. E. Carolina Power & Light Co 79/04/13 ip
- F903040163 Forwards IE Bulletin 79-06B, "Review of Operational Errora & Sys Misalignments Identified During TMI Incident "
  O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14. 2pp
- P905040281 Forwards IE Bulletin 79-07, "Beismic Stress Analysis of Safety-Related Piping." Licenses action required O'REILLY, J P Region 2, Atlanta, Office of the Director, 79/04/14 ip
- →905040329 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident " O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 1p

- 790503014; Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " Licensee action required O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/17 20:
- 7905020426 Forwards IE Bubletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident" O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/04/18 2pp
- 7905230598 Ack receipt of 790414 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-261/79-05 SUTHERLAND, J T Region 2. Atlanta, Fuel Facility & Materials Safety Branch 79/04/19 lp
- --7905230604 Responds to NRC 790323 itr re violation noted in IE Insp Rept 50-261/79-05 Corrective actions only health physics technicians w/proper qualifications will be utilized for back shift coverage BANKS,H R Carolina Power & Light Co 79/04/14 2pp
- --7905230610 Forwards IE Insp Rept 50~261/79-05 on 790226-0302 & notice of violation BUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Branch 79/03/23 2pp
- --7905230614 Notice of violation from insp on 790226-0302 \* Region 2, Atlanta, Office of the Director. 79/03/23 1p
- --7905230623 IE Insp Rept 50-261/79-05 on 790226-0302 Noncompliance noted technicians used in responsible positions w/o sufficient health physics experience JENKINS, O R Region 2, Atlanta, Office of the Director GIBSON, A F Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/03/23 7pp
- 7908010517 Forwards restated paragraph from 770330 ltr.submitted as revision to GA program, in response to IE Insp Repts 50-324/79-02 & 50-325/79-02 Paragraph discusses radiation survey/measuring instruments UTLEY, E E Carolina Power & Light Co 79/04/23 2pp
- 7905040084 Requests that present inservice testing program for pumps 3 valves, conditionally accepted by NRC on 771014, be allowed to continue through 810307

  UTLEY, E Carolina Power & Light Co 79/04/25 ip
- 7905010552 Forwards util 790424 response to IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping " Requests review & reply UTLEY,E E Carolina Power & Light Co 79/04/27 ip
- ---7903010357 Responds to IE Bulletin 77-07 requesting info on seismic stress analysis of safety-related piping Westinghouse reanalysis revealed max stress was well below allowable limit.

  UTLEY.E E Carolina Power & Light Co 79/04/24 2pp
- 7903300276 Responds to IE Bulletin 79-04. Requests extension of response date to 790331
  UTLEY, E E Carolina Power & Light Co 79/05/01 ip
- 7905270388 Preliminary response to IE Bulletin 79-02, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts "Review of records revealed QC documentation not available to sufficiently support proper bolt installation UTLEY.E E Carolina Power & Light Co 79/05/22 3pp
- R Pariodic operating reports & related correspondence
- 7905180418 Forwards monthly operating rept for Apr 1979
  FURR, 8 J Carolina Power & Light Co 79/05/10 ip
- --7903150426 Monthly operating rept for Apr 1979 WATFORD, M L Carolina Power & Light Co. 79/05/02. 4pp.
- B Reportable occurrences, LERs & related correspondence
- 7905040531 Forwards LER 79-004/03L-0 FURR,B.J Carolina Power & Light Co 79/05/01 ip
- ---7905040535 LER 79-006/03L-0 on 790402 boric acid transfer pump 3 tripped due to high temp. Gaused by broken shaft. Pump replaced & tested satisfactorily STARKEY.R 8 Carolina Power & Light Co 79/05/01 2pp

- 7905150450 Forwards LER-79-007/03L-0 FURR: 9 J Carolina Power & Light Co 79/05/10 1p
- 7905150461 Forwards LER 79-011/01T-0 FURR: B J Carolina Power & Light Co 79/05/10 1p
- --7905150463 LER 79-011/01T-0 on 790426 small pin hole leaks found on four canopy seal welds Caused by weld degradation NSSS supplier eramining this type failure STARKEY.R B Carolina Power & Light Co 79/05/10 2pp
- 7905190010 Discusses /90413 operation of overpressure protection sys while proceeding to cold shutdown Requests license amend re overpressure protection Forwards 790413 RD & 771222 request for license amend BANKS, H R Carolina Power & Light Co 79/05/14 1p
- --7905190012 RO on 790413 while proceeding to cold shutdown overpressure protection sys actuated Caused by operator error Event details are being studied 
  -- Carolina Power D Light Co 79/05/14 3pp
- --7905190013 Request for license amend to revise Tech Specs re overpressure protection W/revised pages to implement changes UTLEY.E E. Carolina Power & Light Co. 77/12/22 11pp
- 7905190027 Forwards LER 79-008/03L-0 FURR.B J Carolina Power & Light Co 79/05/15 1p
- ---7905190030 LER 79--008/03L-0 on 790414 safety injection pump A failed to start Cause unknown Pump, its breaker & timing relay were checked electrically no problems observed Pump started locally & returned to svc STARKEY,R B Carolina Power & Light Co 79/05/15 2pp
- 7705170086 Forwards LER 79-009/03L-0 BANKS, H R Carolina Power % Light Co 79/05/15 1p
- ---7905190088 LER 79-009/03L-0 on 790414 diesets failed to assume electrical loadings in required 50-s. Caused by timing relays being set too long, due to instrument drift Timing relays reset Permanent change being considered GTARKEY, R B. Carolina Power & Light Co. 79/05/15. 2pp
- 7905220106 Forwards LER 79-010/03L-0 BANKS H R Carolina Power & Light Co 79/05/16 tp
- --7905220110 LER 79-010/03L-0 on 790415 engine driven fire pump rendered inoperable due to fuel heak Caused by failure of solenoid operated fuel shufoff valler to close fully, due to pieces of slag between valve seating surfaces Slag removed STARKEY, R B Carolina Power & Light Co , 79/05/16 2pp
- 7905290219 Forwards LER 79-012/017-0 BANKS, H R Carolina Power & Light Co. 79/05/22 1p
- --7909290230 LER 79-012/01T-0 on 790508 during normal operation, six of ten supports of cold leg safety injection line failed, allowing section of gipe to rest on floor, Caused by saterhammer New supports to be (natalled, STARKEY, R B Carolina Powor & Light Co 79/05/22 3pp

#### DOCKET 50-262 BRIGHAM YOUNG UNIV RESEARCH REACTOR

- J Insurance & indemnity information
- 7903:50375 Forwards Amend 9 to Indomnity Agreement E-50, per 10CFR140 changes, re increase from \$140 million to \$160 million, affective 790301 Supporting documentation encl SALTZMAN, J Antitrust & Indomnity Group 79/05/01
- DOCKEY 50-263 MONTICELLO NUCLEAR GENERATING PLANT
- G. Adjudicatory correspondence
- 7705220024 Denies 781208 request to prohibit further installation of spent fuel storage racks, pending hearing to determine if license amend should be issued
  DENTON, H R Office of Nuclear Reactor Regulation 79/04/24 to

- ---7903220030 Director's decision per 10CFR2 206 request Proposed spent fuel storage rack mods do not require license amend Request by HN Pollution Control Agency to prohibit installation racks is denied BOYD, R S Office of Nuclear Reactor Regulation 79/04/24 17gs
- --7909220033 Notice or issuance of Director's decision per 10CFR2 206, damying MN Pollution Control Agency's request for suspension of fuel rack installation BOVD.R S Office of Nuclear Reactor Regulation 79/04/24 2pp
- I Financial information
- 7909180225 Forwards "Financial & Statistical Info" as suppl to "Annual Financial Rept 1978 "
  BRUSVEN, A D Northern States Power Co 79/05/10 ip
- --7405150231 "Financial & Statistical Info," submitted as suppl to "Annual Financial Rept 1978 " • Northern States Power Co 79/03/31 21pp
- J Insurance & indemnity information
- 7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,56,57,58,60,61,64,65,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,91,92,93,94,95 & 96
- 7905160170 Forwards Amend 9 to Indemnity Agreement B-42,per 10CFR140 changes, re liability insurance increase from \$140 million to \$160 million; effective 790501 Supporting documentation encl. SALTZMAN.J Antitrust & Indemnity Group 79/05/01 Spp
- 7903230394 Forwards Amend 9 to Indomnity Agreement B-42 & Amend 7 to Indomnity Agreement B-60
  JOHNSON, R G Northern States Power Co 79/03/18 5pp
- 7903270093 Forwards Endorsements 51 & 52.43 & 44 to NELIA Policies MF-174 & MF-51, respectively JOHNSON, R O Northern States Power Co 79/05/23 5pp
- P Operating license stage documents & correspondence
- 7905;50575 Submits status repts on snubber springs, retainer clip replacement & fire deluge extension, in response to TL Harpster's request WACHTER, L.J. Northern States Power Co. 79/04/10 2pp
- 7905040415 Responds to TA Ippolito 790319 itr requesting info re radiation levels attributable to plant operation Forwards plant environ radiation survey prepared by Environ Analysts. MAYER.L O Northern States Power Co 79/04/20, 2pp.
- 7905090367 Comments on QE study of dc power source failure on CCCS performance for operating BMR/3 & 4,dtd 781101.Rept is applicable to facility MAYERL O Northern States Power Co 79/04/24 ip
- 7905290162 Notification of 790427 meeting w/Bechtel, Consumers Power & Northern States Power Co in Bethesda, MD to discuss status of review of nonconservative value used for elbow stiffness in certain piping stress calculations.

  URDAN, E.L., Division of Reactor Operations Inspections 79/04/2
- 7905040604 Potential diesel generator turbocharger problem w/repeated hot starts is being avoided Necessary mod will be available in six months.

  ELIASON:L R Northern States Power Co. 79/04/27 ip.
- 7903080413 Informs of review of OE's failure mode & sffects analysis a proposal to modify reactor protection sys power supply Util plans to modify supply protective circuitry per conceptual design approved in NRC 790223 It. Submits Tech Spec changes MAYER.L G. Northern States Power Co. 79/04/27. ip
- 7905040011 Forwards request for license amend & \$4,000 fee MAYER, L O Northern States Power Co. 79/05/01. 2pp.

- --7909040022 Requests amend to DPR-22 to delete App B. Section 2.4, interim radioactive effluent Tech Opecs & to revise App A Tech Opecs
  - WACHTER, L. J. Northern States Power Co. 79/05/01 71pp
- 7705040530 Forwards \$4,000 for for 770501 license amend request re radioactive efficient Tech Spec changes \* Northern States Power Co 77/05/01 1p
- /909070366 Forwards documents supporting proposed Tech Specs changes, submitted 790901; reflecting requirements re Offsite Dose Galculation Manual & process control program MAVER, L. D. Northern States Power 60 79709702 1p
- --7907070372 "Process Control Program for Waste Solidification" # Northern States Power Co 79/05/01 22pp
- -~7705070300 "Offsite Dose Calculation Manual "
  # Northurn States Power Ca 79/04/30 125pp
- 7908080411 Confirms 790502 telcon & 790514 meeting to discuss spent fuel storage racks Buggests discussion be limited to six technical questions Discussions will be open to public but should not be considered as hearing BTCNBVAAG. J Minnasota. State of 79/05/02 Spp
- 7703080482 Confirms 770302 telcon re possible meeting during week of 770314 w/util.NRC t MN Pollution Control Agency to discuss spent fuel storage racks at facility BTENSVAAG,T Minnesota, State of 79/05/02 3pp
- /905190033 Responds to V Stella 790312 ltr Submits schedule for implementation of Mark I containment long-term program MAYER, L G Northern States Power Co 79/05/15 2pp
- 7709230315 Submits supplemental info to 78113 & 22 ktrs re RHR section piping restraint mode Section Corp used envelope sampaise spectrum method, meeting FSAR requirements for RHR section line HACHTER, L.J. Northern States Power Co. 79/05/17 ip
- 7905240060 Presents summary of results of suppression pool temp transient study in response to NRC 771212 ltr MAYER, L. O Northern States Power Co 79/05/18 4pp
- /903250429 Forwards tabulation of reactor operator & senior reactor operator retraining results for 1976-79, in response to IL Bulletin 70-10 Northern States Power Co 79/05/21 4pp
- 7905300200 Forwards summary of EDS Nuclear, Inc resolution/documentation of without flexibility error which existed in versions of pison piping analysis computer program from Jan-Oct 1969 Review & reanalysis included all work through Dec 1970. PORTER, F. L. EDS Nuclear, Inc 79/05/21 9pp
- --7/08/2002/69 Forwards EDB Nuclear Inc list of BWRs & piping sys which could have been impacted by deficient computer program OF has no record of reanalysis for Cooper piping sys OF the PHENS, P W General Electric Co , Nuclear Energy Products Div 79/01/24 18pp
- Q Inspection reports, IE Bulletins & correspondence
- 7903010262 Forwards IC Info Notice 79-06, "Stress Analysis of Bafety-Related Piping"

  KEPPLER, J Q Region 3, Chicago, Office of the Director 79/03/23
- 7403040040 Forwards IE Info Notice 77-07, "Rupture of Redwaste Tanks "
  KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/26 10
- 7905010174 Forwards IC Info Notice 79-08, "Interconnection of Contaminated Bys w/Ryc Air Bys Used as Bource of Breathing Air." Region 3, Chicago, Office of the Director 79/03/28 KEPPLER, J Q Lp.
- 7905010410 Forwards IE Info Notice 79-09, "Spill of Radioactively Region 3. Chicago, Office of the Director 79/03/30 Contaminated Resin
- 7905270336 Forwards IE Insp Rept 50-263/79-02 on 790319-0323 No nancompilance noted HEISHMAN.R F. Region 3. Chicago, Office of the Director, 79/04/10 Zpp

- -7908290846 IE Insp Rept 50-263/79-02 on 790319-0323 No concempilarie POSSIBLE OF THE DIRECT OF A MARKET T. C. A. C. A
- 7905290321 Informs of investigation resulting from IE Bulletin 79-03 No ASME SA-312. Type 304 or other welded pipe ofg by Youngstown Helding & Engineering Co is in use or planned for WACHTER, L J Northern States Power Co 79/04/12
- 7905010597 Forwards IE Builetin 79-06A. "Review of Operational Extors 5 Bys Misslignments Identified during TMI Incident " KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/14
- 7905040405 forwards IE Bulletin 79-068, "Review of Operational Errors & Sws Misalignments Identified During TMI Incident " KEPPLER.J G Region 3. Chicago, Office of the Director 79/04/14
- 7905040451 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping " Licensee action required KEPPLER, J Q Region 3, Chicago, Office of the Director 79/04/14
- 7905040576 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident "
  KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14
- 7905030237 Forwards IE Bulletin 79-09, "Failures of GE Typs AK-2 Circuit Breaker in Safety-Related Sys " Licensee action regulred KEPPLER.J O Region 3, Chicago, Office of the Director 79, Region 3. Chicago, Office of the Director 79/04/17
- 7905080505 Forwards IE Bulletin 79-058, "Nuclear Incident at Region 3. Chicago, Office of the Director 79/04/21 TM1-Suppl " KEPPLER, J G
- 7905040517 Responds to IE Bulletin 79-01 re stem-mounted limit switch Tupes similar to those described are used on safety-related valves inside containment Qualification data for safety-related electrical equipment encl HACHTER.L J. Northern States Power Co. 79/04/30. 5pp
- 7705240681 Responds to IE Insp Rept 50-263/79-02 re info on high density fuel storage sys Util will not use eight resized fuel storage tubes prior to safety evaluation MAYOR.L O Northern States Power Co 79/05/21 ip
- R Periodic operating reports & related correspondence
- 7905090388 Forwards monthly operating rapt for Apr 1979 MAYER, L O Northern States Power Co 79/05/07 ip
- --7905090392 Monthly operating rept for Apr 1979 \* Northern States Power Co 79/05/02 App
- 8 Reportable occurrences, LERs & related correspondence
- 7905080424 Forwards LER 79-009/03L-0 MAYER.L O Northern States Power Co 79/05/04 ip
- --7905080438 LER 79-009/03L-0 on 790404 steam leak found in 90 degree elbow in i-inch core isolation cooling steam supply drain pot condenser line Caused by erosion due to high velocity steam from leaving valve Hole patched Repairs planned HAMMER. 8 J Northern States Power Co 79/05/04 ip
- 7905160379 Forwards LER 79-010/01T-0 MAYER,L O Northern States Fower Co 79/05/10 ip
- ---7905160381 LER 79-010/01T-0 on 790426 informed by General Motors of potential diesel generator turbocharger problem Causas by inadequate design of lube oil sys Mod being developed PEDERSON, D E Northern States Power Co

DOCKET 50-264 DOW CHEMICAL CO J Insurance & andennity information

7905160357 Forwards Amend 10 to Indemnity Agreement B-34-per 10CFR140 changes.rs increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl SALTZMAN.J Antitrust & Indemnity Group 79/05/01 5pp

7905150359 Forwards elected Amend 10 to Indemnity Agreement 8-34 COALMELL, T N Dow Chemical Co 79/05/09 2pp

DOCKET 50-265 GUAD-CITIES STATION, UNIT 2 F Security, medical, emergency & fire protection plans

7705140413 Forwards sections of fire protection SER which require further NRC review valve supervision, air breathing equipment 6 interior hose stations HALL,R E Broothaven National Laboratory 79/04/12 3pp

7905030366 Forwards modified physical security plan, Revision 5 Plan withheld (ref 10CFR2 790)
LEE.B Commonwealth Edison Co 79/04/26 1p

G Adjudicatory correspondence

7905230238 Notifies properly worded contention addressing contention of sabotage would be accepted into proceeding Contention 6.as admitted into Duke Power Co proceeding, encompasses aspects of revised Contention 11 presented by State of IL GODDARD, R J Branch 2 79/04/06 2pp

J Insurance & indemnity information

7905100163 Endorsement 99 to MAELU Policy MF-22 GERAS, T Nuclear Energy Liability Insurance Association 79/03/27

7905070497 Confirms increased liability limit to \$124,000.000 for policies NF-1.25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,185,186,187,188,189,192,193,194,195,197,198,200,201,204,206,207,208,210,212,214,215,&others GUATTROCHMI,J American Nuclear Insurers 79/05/01 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for 901tciss MF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,56,57,58,60,76,78,70,71,72,74,76,77,78,79,80,86,87,88,70,71,72,74,74,75,79,80,86,87, ROBERTS, D. H. Mutual Atomic Energy Liability Underwriters 79/05/01

7905140436 Forwards Amend 11 to Indemnity Agreement 8-47 per 10CFR140 changes re increase in liability insurance from \$140 million to \$160 million.effective 790501 Supporting documentation SALTZMAN. J Antitrust & Indemnity Group 79/05/01 6pp

P Operating license stage documents & correspondence

7905030067 Forwards notes on 790302.15 & 22 conference telcons between NRC consultants & util re bulletin "Potential Englosive Gas Mixtures Accumulations Associated w/BWR Offgas Sus Operations." Operating Reactors Branch 3 79/04/16 4pp

7905080141 Responds to 790305 ltr criticiring application for approval of proposed license agend that would allow shipment of spent fuel between stations Provides into on upcoming hearing IPPOLITO,T A Operating Reactors Branch 3 79/04/18 ip

--7905080131 Opposes application for approval of proposed license amend that would allow shipment of spent fuel between stations HOHENBOKEN.P Affiliation Unknown 79/03/15 2pp

7905010526 Forwards response to NRC 781205 request for add1 info re instrument sespoint changes JANECEK.R F Commonwealth Edison Co 79/04/25 Spp

7905040482 Notifies of intention to develop safety analysis using effecting computer codes Requests addition for SOLBRIO.C H Commonwealth Edison Co 79/04/26 ip

7903190014 Forwards current schedule for implementation of Mark I containment long-term mods. Discusses constraints inhibiting shorter time frame completion, including sys load requirements & current fuel cycles
REED. C. Commonwealth Edison Co. 79/05/11 3pp

7905190097 Requests correction to error discovered in 700421 ter recepacity of Nuclear Assurance Corp NAC-1 truck cask used in spent fuel transfer Subj truck cask has capacity of two GMR JANECK, R.F. Commonwealth Edison Co 79/05/11 1p

P Operating license stage documents & correspondence

7905250391 Forwards current licensing open items status list REED, C Commonwealth Edison Co 79/05/18 11pp

A. Inspection reports, IE Bulletins & correspondence

7905020421 Forwards response to IE Bulletins 78-12 & 20 12%. "Asgel"4
Weld Math in Reactor Pressure Vessel Wolds "
REED, C. Commonwealth Edison Co. 79703/22 10pp

7705010236 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping "
KEPPLER, JO Region 3, Chicago, Office of the Director 1, 1 = 1

7905030970 Forwards IE Info Notice 79-07. "Rupture of Radwatte 12-09 KEPPLER, J Q Region 3, Chicago, Office of the Director 7, F

7905010155 Forwards IE Info Notice 79~08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing KEPPLER, J Q Region 3, Chicago, Office of the Director 14 - 3 +4

7905010384 Forwards IE Info Notice 79-09, "Spill of Hadioactive; Contaminated Resin Region 3. Chicago, Office of the Director 1107 4 KEPPLER, J G

7705030013 Forwards IE Bulletin 79-06, "Review of Operational Para to Buys Misalignments Identified During TM1 Incident" KEPPLER, J O Region 3, Chicago, Office of the Director '4 L ."

7905250280 Responds to IE Bulletin 79-03 re uniding defeats in 44-70 longitudinally welded pipe apools Plants inspected in pipe

REED.C Commonwealth Edison Co 79/04/12 2pp

7905010569 Forwards IE Bulletin 79-06A, "Review of Operational system & Sys Misalignments Identified During TMI Incident "
KEPPLER, J.G. Region 3, Chicago, Office of the Director (4 % ):

7905040334 Forwards IE Bulletin 79-068. "Review of Operational Process Bys Misalignments Identified During TMI Incident "
KEPPLER, J.G. Region 3. Chicago, Office of the Director 20 1 . k

7905040527 Forwards IE Bulletin 79-08, "Events Relevant to Baising Water Power Reactors Identified During TMI Incident"
KEPPLER/J G Region S, Chicago, Office of the Director 14 4 4

7905030206 Forwards IE Bullstin 79-09. "Failures of QU Type AF - Circuit Breaker in Safety-Related Bys " Licensee action required KEPPLER, J Q Region 3, Chicago, Office of the Director - \*\* da :-

7905040142 Forwards IE Bulletin 79-058, "Nuclear incident at TMT-Suppl "

KEPPLER, J G Region 3, Chicago, Office of the Director Yd = 1

--790504015B IE Bulletin 79-05B, "Nuclear Incident at TMI Nuget Bupporting documentation enel
Region 3, Chicago, Office of the Director 79/04/21 1452

--7903040170 ACRB recommendations to 790328 incident at TMI Supplies to priority be placed on development of safety research on behavior of LWRs during anomalous transients

\* ACRB - Advisory Committee on Reactor Safeguards 79/04/12

- --7905040201 Forwards ACRS recommendations re TMI incident, presented on 790417 FRALEY: R F ACRS - Advisory Committee on Reactor Safeguards
- --7905040221 in response to NRC 790418 ltr.states all ACR8 790417 recommendations apply to all PWRs, but were not intended to require immediate changes Plant mods should be made after study of effects on overall safety, TMI excluded CARBON.H X ACRS Advisory Committee on Reactor Safeguards 79/04/20 2pp
- 7903240633 Forwards responses to IE Bulletin 79-07 requesting info re seismic analysis of safety-related piping Reanalysis indicates method of intramodal combination has little effect on pipe stresses & equipment support loads REED.C Commonwealth Edison Co 79/04/24 4pp
- 7905150148 Forwards responses to IE Bulletin 79-06A.Revision 1.re BWR events identified during TMI-2 Util has formed task force to review BWR events & recommend corrective action as required Communical th Edison Co. 79/04/27
- 7703300242 Responds to IE Bulletin 79-04 No 3,4 or 6-inch Veian swing check valves are in use at Dresden or Guad-Cities Review of Zion has identified use of valves in some piping us but review is incamplete Will rept later REED,C Communwealth Edison Co 79/05/01 2pp
- 7905140488 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Recirculation Motor Generator Set Resulted in Reactor Power Increase " KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/02
- R Periodic operating reports & related correspondence
- 7905170250 Forwards monthly operating rept for Apr 1 KALILVIANAKIS,N Commonwealth Edison Co 79/05/17
- --7905170260 Monthly operating rept for Apr 1979 HANNUM, D Commonwealth Edison Co 79/05/17 28pp
- S Reportable occurrences, LERs & related correspondence
- 7909070389 Informs that release rate of radioiodine & radioactive particulate matl w/half-lives greater than eight days was 2 22 times higher than Tech Spec design objective for first quarter 1979 Caused by steam leaks & "spiking"
  KALIVIANAKIS.N Commonwealth Edison Co. 79/04/30 2pp
- 7905240478 Farwards LER 79-004/03L-0
  KALIVIANAKIS,N Commonwealth Edison Co 79/04/30 1p
- --7905240687 LER 79-004/03L-0 on 790211 while in cold shutdown, suction isolation valve MO 2-1001-50 failed to close from control room Caused by stuck auxiliary centact on valve metor centrol circuit breaker Contact cleaned & proved operable VAHRENWALD, J Commonwealth Edison Co 79/04/30 2pp
- 7905240702 Forwards LER 79-007/03L-0
  KALIVIANAKIS N Commenwealth Edison Co 79/05/02 1p
- --7905240707 LER 79-007/03L-0 on 790405 small leak discovered at weld edge in transition weld Cause unknown teaks filled w/weld mati & penetrant tested to verify removal of indications TIETZ, G Commonwealth Edison Co 79/05/02 3pp
- 7905240691 Forwards LER 79-008/03L-0, Commonwealth Edison Co 79/05/04 in KAL TUTANAKTS. N
- --7905240699 LER 79-008/03L-0 on 790409 suppression chamber level determined to be below Tech Spec min, Caused by instrument setpoint drift Level indicator recalibr & water added to suppression pool SWALES, J Commonwealth Edison Co 79/05/04 3pp
- DOCKET 50-266 POINT BEACH NUCLEAR PLANT, UNIT 1
- F. Security, medical, emergency & fire protection plans
- 7905300446 Submits proposed mods to fire protection plan as set forth in SER Recommends fire hydrant insp & supervision of valves controlling fire water sys HALLAE Brookhaven National Laboratory 79/04/27 Spp

- J Insurance & indemnity information
- 7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,183,186,187,188,187,192,193,194,195,197,198,200,201,204,206,207,208,210,214,214,215,40thers GUATTROCHHI, J American Nuclear Insurers 79/05/01 1p
- 7705070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,56,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,71,92,93,94,95 \$ 96 ROBERTS
- 7905140431 Forwards Amend 11 to Indemnity Agreement B-41 per 10CFR140 changes re increase in liability insurance from \$140 million to \$160 million effective 790501 Supporting documentation SALT ZMAN, J Antitrust & Indemnity Group 79/05/01 6pp
- 7705230463 Forwards executed Amend 11 to Indemnity Agreement B-41, per NRC 790501 request DUNDAS,W J. Wisconsin Electric Power Co. 79705/17 3pp
- P Operating license stage documents & correspondence
- 7905140513 Forwards Amends 35 & 41 to Licenses DPR-24 & DPR-27, respectively, safety evaluation, EIA & notice of issuance & availability Operating Reactors Branch 1 79/04/04 2pp SCHWENCER, A
- ---7905140520 Amends 35 & 41 to Licenses DPR-24 & DPR-27, respectively authorizing installation & use of modified spent fuel storage racks in spent fuel pool, which increases capacity for storage from 351 assemblies to 1.502 assemblies ZIEMANN, D L Assistant Director for Systems & Projects 79/04/04 24pp
- --7905140526 Safety evaluation supporting Amends 35 & 41 to Licenses DPR-24 % DPR-27, respectively \* Office of Nuclear Reactor Regulation 79/04/04 14pp
- --7905140829 EIA of Amends 35 & 41 to Licenses DPR-24 & DPR-27, respectively

  \* Office of Nuclear Reactor Regulation 79/04/04 33pp
- --7905140533 Notice of issuance & availability of Amends 35 & 41 to Licenses DPR-24 & DPR-27, respectively SCHWENCER, A Operating Reactors Branch 1 79/04/04 3PP
- 7905090065 Forwards Amend 36 to License DPR-24, safety evaluation & notice of issuance & availability SCHWENCER, A Operating Reactors Branch 1 79/04/06 2pp
- ---7705070068 Amend 36 to License DPR-24 extending reactor coolant sys pressure-temp heatup & cooldown curves from 7 to 11 effective full power years SCHMENCER.A Operating Reactors Branch 1 79/04/06 Spp.
- ---7905090071 Safety evaluation supporting Amend 36 to License DPR-24
  \* Office of Nuclear Reactor Regulation 79/04/06 3pp
- --7905090076 Notice of issuance & availability of Amend 36 ' DPR-24 BCHUENCER. A Operating Reactors Branch 1 79/04/06
- 7905100439 Forwards Amends 37 & 42 to Licenses DPR-24 & DPR respectively & notice of issuance & availability Security plan evaluation withheld (ref 100FR2, 790).

  80HMRWCER: A Operating Reactors Branch 1 79/04/13 Operating Reactors Branch 1 79/04/13
- ---7905100442 Amends 37 & 42 to Licenses DPR-24 & DPR-27, resimplementing provisions of NRC-approved physical securiplan SCHMENCER, A Dperating Reactors Branch 1 79/04/13
- ---7903100446 Notice of issuance & availability of Amends 37 Licenses DPR-24 & DPR-27, respectively SCHWENCER, A Operating Reactors Branch 1 79/04/13
- 7903130071 Forwards info in response to 790321 request re d plant shutdowns.
  DENTON:H R Office of Nuclear Reactor Regulation 79/04

- 7905020271 Request emends to Licenses DPR-24 & DPR-27, changing Tech Specs re initiation instrument setting limits for engineered safety features Forwards Class III amend fee BURSTEIN,S Hisconsin Electric Power Co 79/04/27 7pp
- 7905240831 Responds to [E Bul]etin 79-04A. Item 3 re TMI errors Pressurfizer law level setpoint bistable returned to untripped position until logic change requested in 790427 license amend is implemented BURSTEIN.S Wisconsin Electric Pawer Co 79/04/30 200
- 7909150202 Forwards addl info re reactor vessel weld & surveillance weld metals
  BURBTEIN, B. Wisconsin Electric Power Co. 79/05/04 5pp
- 7705130448 Forwards addl info re Tech Spec Change Request 62 permitting safety injection actuation circuitry mod to two out of three pressurizer low pressure logic Requests approval by 770511. to permit mods on 770512-13 & 770519-20

  BURSTEIN'S Wisconsin Electric Power Co 77/05/07 3pp
- 7905300208 Forwards summary of EDS Nuclear, Inc resolution/documentation of elbow flexibility error which existed in versions of PISOL piping analysis computer program from Jan-Oct 1969 Review & reanalysis included all work through Dec 1970 PORTER, F L EDS Nuclear, Inc 79/05/21 9pp
- --7905300263 Forwards EDS Nuclear, Inc list of BMRs & piping sys which could have been impacted by deficient computer program GE has no record of reanalysis for Cooper piping sys STEPHENS, P H Gameral Electric Co . Nuclear Energy Products Div 79/01/24 18pp
- 7909310939 Submits formal responses to 790510 questionnaire re pressurizes heater, loss of feedwater event & steam generator BURSTEIN, 8 Wisconsin Electric Power Co 79/05/22 Opp
- 9 Inspection reports, IE Bulletins & correspondence
- 7905010142 Forwards IE Insp Repts 50-266/79-04 & 50-301/79-03 on 790220-23 & natice of violation DAVIS.A B Region 3. Chicago. Fuel Facility & Materials Safety Branch 79/03/22 2pp
- ---79090f0131 Natice of violation from insp on 790220-23

  \* Region 3: Chicago: Office of the Director 79/03/19. 19
- --7909010160 IE (nsp Repts 90-266/79-04 & 30-301/79-03 on 790220-23 Noncompliance noted failure to provide 7-day holdup of radioactive gas before release GREGER, L. R. HIATT, J. W. Region 3: Chicago, Office of the Director FIBHER, W.L. Region 3: Chicago, Fuel Facility & Materials Safety Branch 79/03/19 10pp
- 7705010270 Forwards [E Info Notice 79-06, "Stress Analysis of Safety-Related Piping" KEPPLER.J G Region G. Chicago. Office of the Director 79/03/23
- 7909040060 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks "
  KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/26
- 7905010181 Forwards IE Info Notice 79-08, "Interconnection of Conteminated Sys W/Svc Air Sys Used as Source of Breathing Air " KEPPLER, J G. Region 3. Chicago, Office of the Director 79/03/28 ip
- 7905010417 Forwards IC Info Notice 79-09, "Spit1 of Radioactively Contaminated Resin" KEPPLER.J O Region 3, Chicago, Office of the Director 79/03/30 10
- 7905030062 Forwards IE Bulletin 79-06, "Review of Operational Errors & Bys Mixalignments Identified During TMT Incident " Licenses action required KEPPLER.J.Q Region 3. Chicago. Office of the Director 79/04/11
- 7905010613 Forwards IE Bulletin 79~06A, "Review of Operational Errors & Bys Misalignments Identified during TMI Incident " Licenses action required KEPPLER.J Q Region 3, Chicago, Office of the Director. 79/04/14
- 7905040431 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "
  KEPPLER. J. O Region 3. Chicago, Office of the Director 79/04/14
  19.

- 7905040438 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping " Licensee action required KEPPLER, J G Region 3, Chicago, Office of the Director 79/54.
- 7903040598 Forwards IE Bulletin 79-08. "Events Relevant to Boiling Hater Power Reactors Identified During TMI Incident "
  KEPPLER, J G Region 3. Chicago, Office of the Director 79/Li.
- 7905030253 Forwards IE Bulletin 79~09, "Failures of QE Type AM-2 Circuit Breaker in Safety-Related Sys " Licensee action required KEPPLER, J G Region 3, Chicago, Office of the Director 79/04
- 7905290075 Responds to 1E Bulletin 79-06A Expresses concern re emergency operating procedures for reactor coolant pump b requirement for immediate tripping of low level bistables BURSTEIN, S Wisconsin Electric Power Co 79/04/19 3pp
- 7905080515 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl"

  KEPPLER, J G Region 3, Chicago, Office of the Director 79/ul2
  Lb
- 7905240519 Responds to IE Bulletin 79-07 re computer programs usual Passismic stress analysis of safety-related piping sys No computer codes used which utilized algebraic summation techniques

  BURGTEIN B Wisconsin Electric Power Co 79/04/25 2pp
- 7905240303 Responds to IE Bulletin 79-03 re possibility of longitude weld defects in ASME SA-312 Type 304 stainless steel pipe spools Review of pipe documentation records indicates no use of such tubing BURSTEIN S. Wisconsin Electric Power Co 79/04/26 2pp
- 7905300316 Responds to IE Bulletin 79-06A & 79-06A.Revision 1 Ha.s established task force to facilitate review & understanding of TMI incident & impact on facility
  BURSTEIN.B Wisconsin Electric Power Co 79/04/2/ 13pp
- 7905290284 Responds to IE Bulletin 79~09 re GE Type AK-2 circuit breakers Item not in use at plant BURSTEIN.B Wisconsin Electric Power Co 79/09/07 ip
- R Periodic operating reports & related correspondence
- 7905140362 Forwards monthly operating rept for Apr 1979 BURSTEIN, S. Wisconsin Electric Power Co 79/05/08 ip
- --7905160365 Monthly operating rept for Apr 1979

  \* Wisconsin Electric Power Co 79/05/04 10pp
- 8 Reportable occurrences, LERs & related correspondence
- 7905020310 Forwards LER 79-006/03L-0 BURSTEIN.8 Wisconsin Electric Power Co. 79/04/18 tp
- --7905020318 LER 79-006/03L-0 on 790404 during biweekly testisecersis, heat tracing circuit of boric acid sys Circuit 47 found inoperable Caused by shorted heat tracing cable in circuit Cable replaced 5 circuit returned to operation BURSTEIN, S Wisconsin Electric Power Co 79/04/18 2pp
- 7909240611 Forwards LER 79-007/017-0 BURBTGIN.B Wisconsin Electric Power Co 79/05/07 ip
- --7903240627 LER 79-007/01T-0 on 790424; vendor issued builetin re potential problem w/turbochanger bearing lubrication Administrative controls instituted, Mods to be made as soon as possible BURSTEIN, S Wisconsin Electric Power Co 79/05/07 3pp
- DOCKET 50-267 FORT ST VRAIN NUCLEAR GENERATING STATION
- J. Insurance & indemnity information
- 7905070497 Confirms increased liability limit to \$124,000.000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,185,186,187,188,199,192,193,194,195,197,198,200,201,204,206,207,208,210,212,214,215,5 others GUATTROCHHI, J American Nuclear Insurers 79/05/01 lp

- 7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,54,57,56,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,91,92,93,94,95 & 96 ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/05/01
- , 7905iA0176 Forwards Amend 8 to Indemnity Agreement 8-30, per 10CFR140 thanges, re liability insurance increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl SALTZMAN, J Antitrust & Indemnity Group 79/05/01 Spp
  - 7908220394 Amend 8 to Indomnity Agreement 8-50 changing amount of financial protection BALTZMAN, J Antitrust & Indomnity Group 79/05/18 2pp
  - P Operating license stage documents & correspondence
  - /903010179 Notification of 790502 meeting w/util in Bethesda, MD to discuss status of inservice insp program, primary sys valves, steam generators & agenda items MUZHYCZ. G Advanced Reactors Branch 79/04/17 3pp
  - 7909310160 Forwards Amend 20 to Licenso DPR-34, safety evaluation & notice of issuance & availability
    BPEIB.T P Advanced Reactors Branch 79/04/20 2pp
  - ---7903310171 Amend 20 to License DPR-34 to revise Tech Specs to install eight test fuel elements into reactor core at first refueling & to install graphite surveillance specimens into five bottom transition reflector elements

    SPEIS: T P Advanced Reactors Branch 79/04/20 9pp
  - --7905310180 Safety evaluation supporting Amend 20 to License DPR-34 \* Office of Nuclear Reactor Regulation 79/04/20 22pp
  - --700310106 Notice of issuance & availability of Amend 20 to License DPR-39 SPCIS-TP Advanced Reactors Branch 79/04/20 ip
  - 7905030321 Informs that util will not alter existing Tech Specs to accommodate STS format Format of present Tech Specs is adequate & meets intent of proposed STS FULLER, J. K. Public Service Co. of Colorado 79/04/23 ig
  - 7903300210 Describes proposed mods resulting from various analyses of 761123 power failure of steam/water two loop dump sys SPEIG, T.P. Advanced Reactors Branch. 79/05/04. 3pp
- 7903230204 Responds to 790130 request for temperary alteration to scheduled requalification program in order to correlate planned refueling outage Mod acceptable COLLING.P F Operator Licensing Branch 79/05/07 2pp
- 7705160315 Bubmits outline describing special tests to be performed during startup & rise to power, per 770508 request HAREMHOURG, D. Public Service Co. of Colorado 77/05/11 22pp
- 7903230025 Forwards list of outstanding itrs & requests for Tech Spec Changes Oversized enci available in Cantral Files only HAREMBOURG, D Public Bervice Co. of Colorado 79/05/14 4pp
- G Inspection reports, IE Bulletins & correspondence
- 7905150086 Forwards IE Circular 79-04, "Loose Locking Nut on Limitorque Valve Sperators"

  SEYFRIT, K. V Region 4, Dallas, Office of the Director 79/03/16 to
- 7905010434 Forwards IE Bulletin 78-128, "Atypical Weld Matt in Reactor Pressure Vessel Welds " Licenses action required SEYFRIT, K V Region 4, Dallas, Office of the Director 79/03/19 tp
- 7905020446 Forwards IE Circular 79-05, "Moisture Leakage in Stranded Wire Conductors"

  SEYFRIT, K V Region 4, Dallas, Office of the Director 79/03/20
  ip
- 7905020279 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
  BEYFRIT, K V Region 4, Dallas, Office of the Director 79/03/23 ip
- 7700020411 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks" BEYFRIT.K V Region 4. Dallas, Office of the Director 79/03/26

- 7905020431 Forwards IE Info Notice 79-08. "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air " SEYFRIT,K V Region 4, Dalias, Office of the Director 79/03/28
- 7903230464 Responds to IE Bulletin 78-128 Bulletin was sent to util by mistate & no response is required WARRENBOURG, D Public Service Co of Colorado 79/03/28 1p
- 7905010354 Ack receipt of 790315 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-267/79-03

  HADSEN,O L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/03/29 ip
- ---7905010361 Responds to NRC 790221 ltr re violations noted in 1E Insp Rept 50-267/79-03 Corrective actions Tech Specs requirements reviewed & emphasized w/personnel involved MILLEN.C K Public Service Co of Colorado 79/03/15 2pp
- 7905100261 Forwards IE Insp Rept 50-267/79-05 on 790227-0302 No noncompliance noted MADSEN.O L Region 4. Dallas, Reactor Operations Nuclear Support Branch 79/03/29 2pp
- --7905100266 IE Insp Rept 50-267/79-D5 on 790227-0302 No noncompliance noted Major areas inspected radiation protection program & analytical measurement results HURRAY.B. BROUN.G D Region 4. Dailas, Fuel Facility & Materials Safety Branch 79/03/28 9pp
- 7905140143 Forwards IE Bulletin 79-04, "Incorrect Weights for Swing Check Valves Hfg by Valan Engineering Corp " License action required SRYFRIT, K V Region 4, Dallas, Office of the Director 79/03/30 to
- 7905180051 Forwards IE Info Notice 79-09, "Spiil of Radioactively Contaminated Resin" BEYFRIT.K V Region 4, Dallas, Office of the Director 79/03/30 in
- 7905230637 Responds to IE Bulletin 79-03 Util has no intention of using stainless steel pipe mfg by Youngstwon Welding & Engineering Co FULLER, J K Public Service Co of Colorado 79/04/06 1p
- 7903040498 Forwards IE Bulletin 79-068. "Review of Operational Errors & Sys Misalignments Identified During TMI Incident " SEYFRIT.K V Region 4. Dallas. Office of the Director 79/04/14
- 7905040627 Forwards IE Builetin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident " SEYFRIT.K V Region 4. Dallas, Office of the Director 79/04/14
- 7905070077 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping " Licensee action required SEYFRIT,K V Region 4. Dallas, Office of the Director 79/04/14
- 7905090106 Forwards suppl to IE Bulletin 79-05A, "Nuclear Incident at TMI"
  SEYFRIT.K V Region 4, Dellas, Office of the Director 79/04/16
- 7905030282 Forwards IE Bulletin 79-09, "Failures of GE Type AX-2 Circuit Breaker in Safety-Related Sys " Licensee action required SEYFRIT.K V Region 4, Dailas, Office of the Director 79/04/17
- 7905080355 Forwards IE Bulletin 79-058, "Nuclear Incident at TMI-Buppl,"
  SEYFRIT,K V Region 4. Dallas. Office of the Director 79/04/21
- 7905300222 Requests 30-day extension to respond to IE Bulletin 79-07 SWART,FE Public Service Co of Colorado 79/04/24 ip
- 7908130795 Ack receipt of 790406 ltm informing NRC of steps taken to correct violations noted in IE Insp Rept 50-267/79-04 MADSEN 0 L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/04/26 ip

- --7905150800 Responds to NRC 790315 ltr re violations noted in IE Insp Rept 50-267/79-04 Corrective actions supervisors informed that surveillance tests & other controlled work procedures must be reviewed before being signed off MILLEN.C K Public Service Co of Colorado 79/04/06 1p
- R Periodic operating reports & related correspondence
- 7905010907 Forwards monthly operating rept for Mar 1979
  WAREMBOURG, D. Public Service Co. of Colorado 79/04/25 1p
- --7905010514 Monthly operating rept for Mar 1979
  GAHM.JW Public Service Co of Colorado 79/04/01 10pp
- 7905080455 Forwards monthly operating rept for Apr 1979
  WAREMBOURG, D Public Service Co of Colorado 79/05/02 1p
- --7905080457 Monthly operating rept for Apr 1979
  GAHH, J W Public Service Co of Colorado 79/09/01 Spp
- S Reportable occurrences, LERs & related correspondence
- 7905140288 Forwards LER 78-002/017-0 SWART.F E Public Service Co of Colorado 78/02/01 Lp
- --7905140294 LER 78-002/01Y-0 on 790118 data indicates temp of control rod drives in power operated relief valve top head penetrations greater than expected by analytical model Surveillance fiequency increased HILLYARD. H N Public Service Co of Colorado 78/02/01 5pp
- 7905140319 Forwards LER 78-001/03L-0 SWART.F E Public Service Co of Colorado 78/02/14 [p
- ~-7905140323 LER 78-001/03L-0 on 780115 at 50% thermal level, average core outlet temp exceeded 1.200 F, resulting in operation in degraded mode Caused by moisture ingress into primary coolant sys from steam generator tube leak Oxidents removed HILLYARD, H W Public Service Co of Colorado 78/02/14 5pp
- 7905150110 Forwards PND-79-67R & 79-77(NRR)

  MADSEN.G L. Region 4. Dallas, Reactor Operations Nuclear Support
  Branch 79/04/11 ip
- --7905150111 PNU-79-77(NRR)
  \* Office of Nuclear Reactor Regulation 79/04/10 4pp
- 7905040115 Forwards PND-79-678 MADBEN G L Region 4. Dallas, Reactor Operations Nuclear Support Branch 79/04/12 ip
- 7905150223 Forwards PNO-79-67T correction MADBEN, 9 L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/04/t3 ip
- --7903150245 PNQ-79-67f correction \* Office of Inspection & Enforcement 79/04/13 App
- 7905010535 Forwards PNG-79-67U.V & H MADSEN.Q L Region 4. Dallas, Office of the Director 79/04/16 1p
- 7905010548 Forwards PNO-79-67X & Y
  MADSEN.O L Region 4. Delias. Office of the Director 79/04/18
- 7905010406 Forwards PNU-79-67AA.AB.AC & AD MADSEN.O L Region 4. Dallas, Office of the Director 79/04/24
- 7905040374 Forwards LER 79-010/03L-0 WAREMBQURG, D Public Service Co of Colorado 79/04/27 ip
- --7905040376 LER 79-010/03L-0 on 790330 during routine surveillance of circular speed bistable trips two high speed trip setpoints found higher than max acceptable speeds Caused by bistable instrument drift. Bistable adjusted.

  9AMH.J W Public Service Co. of Colorado. 79/04/27 Spp
- 7905150102 Forwards PNO-77-67AF, AO, AH, AI & AJ re nuclear incident at THI MADBEN, Q L Region 4, Dallas, Reactor Operations Nuclear Support Branch. 79/04/30 10
- 7905080544 Forwards LER 79-011/03L-0 MAREMBOURG, D Public Service Co of Colorado 79/05/01 1p

- --7905080549 LER 79-011/03L-0 on 790402 during post-mod testing, discovered water pressure differential indicating switches inoperable Caused by failure of range adjustment mechanism due to normal wear New movement & terminal ends installed GAHM,J W Public Service Co of Colorado 79/05/01 Spp
- 7905240428 Forwards PNO-77-67AK & AL MADSEM.0 L Region 4. Dallas. Reactor Operations Nuclear Sujj. Branch 79/03/02 1p
- 7909160367 Forwards LER 79-012/03L-0
  WAREMBOURG, D Public Service Co of Colorado 79/05/07 Le
- --7905160371 LER 79-012/03L-0 on 790410 while flushing basin. effluct exceeded for ranc Caused by large amount of sediment GAHM.J W Public Service Co of Colorado 79/05/07 3pp
- 7905160372 Forwards LER 78-027/03X-4
  WAREMBOURG, D Public Service Co of Colorado 79/05/07 to
- ---7905160377 LER 78-027/03X-4 on 790319 five of nine helium circulitseal malfunction differential pressure switches tripped Caused by dirt accumulation in ITT Barton Model 289 pressure differential switches GAHM,J W Public Service Co of Colorado 79/03/07 App
- 7705230393 Forwards LER 79-014/03L-0 WAREMBOURG.D Public Service Co of Colorado 79/05/16 Ip
- --7905230AO3 LER 79-014/O3L-O on 790419 w/reactor bldg sump properties sampler inoperable daily direct samples of sump effluent were not taken, nor was sampler operability verified daily Caused by improper personnel procedures GAHM, J W Public Service Co of Colorado 79/05/16 4pp
- DOCKET 50-269 OCONEE NUCLEAR STATION, UNIT 1

  F Sacurity, medical, emergency b fire protection plans
- 7905290090 Discusses 790213 submission of security plan for storage of spent fuel & 790216 telcon re-requirement for security plan mods Initial plan is subject to withholding from public/record of transmittal is required

  ROUSE.L.C. Fuel Reprocess & Recycle Branch 79/03/29 to
- 7905:40283 Forwards emergency procedure EP/O/A/1800/4, "Loss of Realls Coolant." containing instructions for operator action for small breaks
  PARKER:N O Duke Power Co 79/05/07 29pp
- H General correspondence
- 7905290131 Urges careful review of staff rept before ordering thuld... of facility.since action could cause extensive power curtailments & higher fuel costs for i 2 million customers in Carolina piedmont
  HELMS.J Senata 79/04/26 ip
- 7905020254 Expresses gratitude for decision to close facility THOMPSON, M & Affiliation Unknown 79/04/28 tp
- J Insurance & indemnity information
- 7905070582 Confirms (increase in liability limit to \$36,000,000 for policies NF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,56,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,79,192,93,44,95 to 94
  ROBERTS.0 M Mutual Atomic Energy Liability Underwriters 79/05;
- 790514043B Forwards Amend 13 to Indemnity Agreement 8-44 per 1907ff(4) changes, re increase in liability insurance from \$140 million to \$160 million.effective 790301 Supporting documentation encl
  SALTIMAN, J Antitrust & Indemnity Orong 79/05/01 App
- 7905150361 Submits executed copy of Amend 13 to Indomnity Agraement B-44, reflecting changes in 10CFR140 PARKER, N O Duke Power Co 79/05/08 3pp
- 79053:0348 Forwards replacement copy of Amend 8 to Indemnity Agreement B-44 in response to 790516 request W/copy of util 740412 transmittel ltr.
  PARKER, W O Duke Power Co 79/05/22 3pp

### P Operating license stage documents & correspondence

- 7905110125 Agrees to close block valve RC-66 until approval of wall thickness analyses for electromatic relief valve RC-66 is received However, valve will be opened for reactor transients THIES, A.C. Duke Power Co. 73/10/05 2pp
- 7905110129 On 731217 pressurizer electromatic relief block valvo RC-4 was opened while unit was in transient mode 85% & util have evaluated continued plant operation w/pressurizer spray valve inoperable & found it acceptable
  THIES.A C Duke Power Co 73/12/19 ip
- 7905290014 Forwards Amends 69.69 & 66 to Licenses DPR-3B, DPR-47 & DPR-85, respectively. EIA & notice of issuance & availability REID, R W Operating Reactors Branch 4 77/03/02 3pp
- --7905250018 Amends 69,69 % 66 to licenses DPR-38.DPR-47 & DPR-53. respectively, which revises ETS by deleting equatic surveillance program & special study programs REID.R W Operating Reactors Branch 4 77/03/02 11pp
- --7905250021 EIA supporting Amends 69.69 % 66 to Licenses DPR-38,DPR-47 % DPR-55,respectively # Operating Reactors Branch 4 79/03/02 4pp
- 7905190135 Responds to R Mattson & D Ross concerning value of running natural circulation test on B&W reactor TEDESCO.RL Assistant Director for Plant Systems 79/04/05 4pp
- 7905080130 Responds to 790329 submittal re radiological effluent Tech 8pec.which omitted solid radwaste process control program Requests omitted portion REID.R W Operating Reactors Branch 4 79/04/18 2pp
- 7905010521 Forwards documentation, design info b projected implementation schedules re emergency feedwater sys.as committed in NRC 790425 meeting PARKER.W O Duke Fower Co 79704/25 4pp
- 7905010550 Forwards add1 info re Ofc of Nuclear Reactor Regulation status rept Requests add1 dialogue w/NRC re control sys LEE,W S Duke Power Co 79/04/25 ip
- 7903030371 Informs that util has conducted review of plant design & operation, including goal of improving reliability of normal feedwater sys & added assurance of emergency feedwater supply to steam generators Design adequate CMEN.W H Duke Power Co 79/04/23 2pp
- 7905040047 Corrects error in 790419 ltr to NRC Reported period of facility mode should be Jan-Dec 1979
  PARKER, H O Duke Power Co 79/04/25 1p.
- 7905110068 Informs that small break analyses review is complete Analyses are unacceptable & incomplete ROSZTOCZY, Z R Analysis Branch 79/04/25 1p
- --7905110074 Comments on draft rept received 790420 too lengthy does not concentrate on important issues & has dozens of incorrect & misleading statements Rept should be reorganized ROBZTOCZY, Z Analysis Branch 79/04/25 3pp
- 7905240982 Responds to 790320 ltr requesting advice on allowable time interval for submittal of repts to NRC REID,R W Operating Reactors Branch 4 79/04/26 2pp
- 7905020283 Informs of util position on issuance of formal order recontinued plant operation Written issuance is undesirable as policy & legally unnecessing LEE, N S Dute Power Co 79/04/29 ip
- 7705040332 Forwards response to 780327 request for add1 info re proposed changes to hydraulic shock suppressor Tech Spec PARKER, W O Duke Power Co 79/04/30. 2pp
- 7905080433 Forwards proposed revision to Tech Specs covering reactor bldg hydrogen purge sys-penetration room ventilation sys, reactor bldg purge filters & spent fuel pool ventilation sys PARKER, W O Duke Power Co 79/05/01 11pp
- 7905080566 Forwards proposed revision to Tech Specs, deleting Tech Spec 4 13 which is no longer required PARKER, W.O. Duke Power Co 77/05/01 4pp
- 7905080388 Responds to questions raised at 790501 meeting Forwards add1 info re proposed installation of high capacity storage racks Info supplements 790202 b 790420 submittals.
  PARKER, W O Duke Power Co 79/05/02 3pp

- 7709240466 Documents completion of 761001 proposal to delete Tech Specs re tendon, anchorage & liner plate surveillance programs License fee not required PARKER,W O Duke Power Co 79/05/02 ip
- 79Q5150104 Notifies of refund of fees, remitted 780705, for authority to transfer fuel between facility & Crystal River Unit 3 Refund will be sent when processed
  MILLER, W O License Fee Management Branch 79/05/03
- 7905140189 In response to NRC 790418 request, forwards proposed Tech Spec re plant solid radwaste process control program PARKER, W D Duke Power Co 79/05/07 5pp
- 7905240231 Forwards status on improvements to emergency feedwater sys, per WO Parker 790425 ltr & WS Lee 790426 ltr PARKER.W D Duke Power Co 79/05/07 100pp
- 7905190317 Clarifies 790907 conversation re ALARA program associated w/retacking of spent fuel pool PARKER.W O Duke Power Co 79/05/08 2pp
- 7905140365 Lists drawings used for installation of automatic starting of interconnected emergency feedwater sys, which were sent to NRC on 790503
  PARKER, W D Dute Power Co 79/03/09 ip
- 7905140268 Forwards "Emergency Feedwater Sys. Sys Concept & Analysis "
  Pump installation to be complete by 790825 Oversized drawing
  in Central Files
  PARKER, W Q Dute Power Co 79/05/10 9pp
- 7909160389 Forwards "B&W 177 Fuel Assembly Owners Group Asymmetric LOCA Loads Evaluation Program. Phase 2," dtd 790410 Supersedes program provided on 790111 PARKER.W O Duke Power Co 79/05/10 ip
- --7905160390 "B&W 177 Fuel Assembly Owners Group Asymmetric LOCA Loads Evaluations Program, Phase 2 " \* Duke Power Co 79/04/10 9pp
- 7905220270 Submits request for relief from requirement of ASME Boiler & Pressure Vessel Code, Section 11.re impracticality of doing hydrostatic test on emergency feedwater header due to excessive leskage through boundary isolation valves PARKER, W O Duke Power Co 79/05/11 7pp
- 7703220235 Forwards "Steam Generator Operating History "PARKER.W O Duke Power Co 77/05/14 ip
- ---7905220239 "Steam Generator Operating History " \* Duke Power Cu 79/05/14 30pp
- 7905230543 Forwards revised sys concept & analysis re addition of two motor-driven emergency feedwater pumps Supersedes 790510 submittal Myoversized drawing PARKER, M O Duke Power Co 79705/17 10pp
- 7705240475 Responds to IE Bulletin 79-05B re TMI incident Forwards proposed amend to Tech Spers, changing setpoints of pressurizer electromagnetic relief valve & reactor coolant sys high pressure trip PARKER, W O Duke Power Co 79/05/21 11pp.
- 7908240478 Forwards design description for safety grade anticipatory reactor trip on turbine trip or loss of main feedwater Mods will be installed for each refueling outage following NRC approval PARKER,W O. Duks Power Co 79/05/21. Spp.
- 790530020B Forwards summary of EDS Nuclear Inc resolution/documentation of elbow flexibility error which existed in versions of PISOL piping analysis computer program from Jan-Oct 1769 Review & reanalysis included all work through Dec 1770 PORTER: F L. EDS Nuclear: Inc 79/05/21 9pp
- --7905300263 Forwards EDS Nuclear, Inc list of BWRs & piping sys which could have been impacted by deficient computer program GE has no record of reanalysis for Cooper piping sys STEPHENS, P. W. General Electric Co., Nuclear Energy Products Div. 79/01/24 18pp
- 7905310211 Forwards proposed Tech Spacs revision re limiting conditions for operation & surveillance requirements PARKER.W. O Duke Power Co. 79/05/25, Spp

- G Inspection reports: IE Bulletins & correspondence
- 7905230482 Forwards IE Insp Repts 50-249/79-04.50-270/79-04. & 50-289/79-04 on 790205-07 No noncompilance noted (ENIS, R L Region 2. Atlanta, Reactor Operations Nuclear Support Branch 79/03/12. 2pp
- ---7905230303 IE Insp Repts 50-269/79-04,50-270/79-04,50-287/79-04 on 790205-07 No noncompliance noted Hajor areas inspected fire protection/prevantion programs (As survestiblence, fire insurance repts & administrative control procedures BRADFORD.H H. TAYLOR,P.A. KELLOOO,P.J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/05. 4pp
- --7905230503 IE Insp Repts 50-269/79-04,50-270/79-04,50-287/79-04 on 790203-07, No noncompliance noted Hajor areas inspected fire protection/prevention program GA surveillance fire insurance rapts & administrative control procedures BRADFORD, W H Region 2. Atlanta. Office of the Director 79/03/05 App
- 7905010177 Forwards IE Info Notice 79-06. "Stress Analysis of Safety-Related Piping " O'REILLY, J.P. Region 2. Atlanta, Office of the Birector 79/03/23 2pp
- 7905030307 Forwards IE Info Notice 79~07, "Rupture of Radwasta Tanks " G'RETLLY, J.P. Region 2, Atlanta, Office of the Director 79/03/26. 2pp
- 7905230272 Discusses B&H rept, "Retords Investigation Rept Related to Off-Chemistry Welds in Hatl Surveillance Bestimens & Response to IE Bulletins 78-12 & 78-12A-Suppl: "rept accurately represents data for reactor pressure vessels PARKER, H. O. Duke Power Co. 79/03/27 ip
- 7905010098 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Bys w/Byc Air Sys Used as Bource of Breathing Air "
  O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/28 2pp
- 7705010350 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin" 0'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/03/30 20p.
- 7905R30279 Responds to IE Bulletin 79-02 re longitudinal weld defects No ASHE BA-312. Type 304 piging or any other welding w/o filter metal piping mfg by Youngstown Helding is in use or planned for use PARKER, H. O. Duke Power Co. 79/04/04. 1p
- 7905100278 Forwards responses to IE Bulletins 79-05 & 79-05A, "Nuclear Incident at TMI" PARKER, H O Duke Power Co 79/04/10. Zipp
- ---7905100299 Forwards Abnormal Occurrence Rept AD-287/75-07 PARKER, W O Duke Power Co 75/06/27. 1p.
- --7905100301 A0-287/75-07 on 750613 excessive reactor coolant sys cooldown rate occurred Caused by operator error & failure of power-actuated pressurizer relief valve 3RC-66 to close a Duke Power Co. 73/06/27 ip.
- ---7905100303 Forwards addl into re AO-207/75-07 Corrective actions. shutdown procedures revised relief values will be examined & quench tank rupture disc replaced.

  PARKER, N. O Duke Fower Co 75/08/08 3pp.
- 790502004B Ack receipt of 790326 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/79-03. 50-220/79-03 & 50-287/79-03 KENNA: K.B. Region 2. Atlanta. Bafeguards Branch. 79/04/12. ip
- --7905020064 Responds to NRC 790306 Str re violations noted in IE Insp Repts 50-269/79-03.50-270/79-03 & 50-287/79-03 Corrective actions withheld (ref 10CFR2 790). FARKER, H. O. Duke Power Co. 79/03/26, ip.
- --7905020078 Forwards IE Insp Repts 50-269/79-03.50-270/79-03 & 50-287/79-03 on 790205-06. Notice of violation withheld (ref forers. 790).

  KENNA, W. S. Region 2. Atlanta, Safeguards Branch. 79/03/06.
- --7905020087 IE insp Repts 50-269/79-03.50-270/79-03 & 50-287/79-03 on 790205-06. Noncompliance notad: areas of testing/maint & detection aids. Details withheld (ref 100FR2, 790).
  TOBIN 46. J. Region 2. Atlanta, Office of the Director GILLESPIE, F. P. Region 2: Atlanta, Bafeguards Branch 79/03/06

- 7905100046 Responds to IE Bulletin 79-05A: Items 7:8,10 & 11 re TMI incident All manual valves which could defeat or compromise flow are locked open and 79/04/19 App
- 7903040176 Porwards IE Bulletin 79-06B, "Review of Operational Errors & Bus Misalignments Identified During TMI Incident" O'REILLY, J P Region 2: Atlanta: Office of the Director, 79/04/14 1p
- 7905040263 Forwards IE Bulletin 79-07, "Baismic Stress Analysis of Bafety-Related Piping " Licenses action required O'REILLY.J.P Region 2. Atlanta, Office of the Director 79/04/14 2pp
- 7905040381 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Hater Power Reactors Identified During TMI Incident " O'REILLY, P Region 2, Atlanta, Office of the Director. 79/08/14 ip
- 7905030360 Forwards IE Bulletin 79-09, "Failures of QE Type AK-2 Circuit Breaker in Safety-Related Bys " Licensee action required, O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/17 2pp
- 7905020429 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident."

  O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/18 2pp
- 7905240452 Responds to LE Bulletin 79~05. Item 3, re TMI incident Reacts: protective sys high RCS pressure setpoint lowered to not greater than 2,300 paig Pressurizer power operated relief valve raised nominally to 2,450 paig PARKER, H O Duke Power Co 79/04/21 ip
- 7905240505 Forwards response to IE Bulletin 79-07 re computer prograe used for piping analysis Algebraic summation methods were not used in piping analysis.
  PARKERIN U Dute Power Go 79/04/24 App
- 7905110264 Forwards 790505 response to IE Bulletin 79-058. Items 1.2.4 & 6.re TMI incident, PARKER, H.O. Duke Power Go. 79/05/05 1p.
- --7905110265 Responds to IE Bulletin 79-05N. Items 1,2.4 & 4 Emergency procedures for loss of reactor contant flow, steam supply systemustrum controllable flooding of turbine bidg & loss of normal HPT makeup or letdown have been revised PARKER, W D Duke Power Co. 79/05/05 6pp.
- 7905300541 Forwards inservice insp program PARKER, N. G. Duke Power Co 79/05/15 ip.
- --7905300550 Inservice insp program

  \* Duke Power Co. 79/05/15, 75pp
- 7903220351 Forwards description of post-TMI operator training, per 790515 discussions & IE Bulletin 79-05,79-05A & B. Operating shifts have adequate knowledge to operate reactors in all modes.

  PARKER, H. G. Duke Power Go 79/05/16 4pp.
- R. Periodic operating reports & related correspondence
- 790522035B Forwards monthly operating rept for Apr 1979 PARKER, N D. Duke Power Co. 79/05/15 1p.
- --7905220365 Monthly operating rept for Apr 1979 REAVIS, J A. Dute Power Co 79/05/19 16pp
- 7905110017 RO 269/7827 on 781214 on 781213, reactor coolant temp became arretic Feedwater problem resulted from operation of one or more feedwater valves Power cords have been fitted # Duke Power Co. 79/01/15 2pp.
- 7905140373 Describes RO-269/79-10, which was to have been submitted 790413; re removal from avc of high pressure evo water pump Gaused by leakage from motor cooler, Cooler repaired & raturned to avc.

  PARKER, M. D. Duke Power Co. 79/04/13 ip
- 7905020327 Forwards LER 79-010/03L-0. PARKER, W. Q. Duke Power Co. 79/04/27. 1P.

-7905040340 LFR 79-010/03L-0 on 790315 & 28 redundant high pressure syc major pump A inoportable while pump B was out of eye to repair lankage from pump motor coder Leak source repaired & replacement conserve produce to other works and pressure of the pressure of the pump B was out of eye to 7905110125 Agrees to close block yalve RC-15 of 11 agrees analyses for electronatic relief valve RC-15 of 11 agrees analyses for electronatic relief valve RC-15 of 11 agrees analyses for electronatic relief valve RC-15 of 11 agrees analyses for electronatic relief valve RC-15 of 11 agrees analyses for electronatic relief valve RC-15 of 11 agrees analyses for electronatic relief valve RC-15 of 11 agrees analyses for electronatic relief valve RC-15 of 11 agrees analyses for electronatic relief valve RC-15 of 11 agrees analyses for electronatic relief valve RC-15 of 11 agrees analyses for electronatic relief valve RC-15 of 11 agrees analyses for electronatic relief valve RC-15 of 11 agrees analyses for electronatic relief valve RC-15 of 11 agrees analyses for electronatic relief valve RC-15 of 11 agrees analyses for electronatic relief valve RC-15 of 11 agrees analyses for electronatic relief valve RC-15 of 11 agrees analyses for electronatic relief valve RC-15 of 11 agrees analyses for electronatic relief valve RC-15 of 11 agrees analyses for electronatic relief valve RC-15 of 11 agrees analyses for electronatic relief valve RC-15 of 11 agrees analyses for electronatic relief valve RC-15 of 11 agrees analyses for electronatic relief valve RC-15 of 11 agrees analyses for electronatic relief valve RC-15 of 11 agrees analyses for electronatic relief valve RC-15 of 11 agrees analyses for electronatic relief valve RC-15 of 11 agrees and 11 agrees analyses for electronatic relief valve RC-15 of 11 agrees analyses for electronatic relief valve RC-15 of 11 agrees and 11 agrees analyses for electronatic relief valve RC-15 of 12 agrees and 12 agrees and 12 agrees and 12 agrees and 12 agrees analyses for electronatic relief valve RC-15

//05230303 forwards LER 79-012/03L-0 PARKIR: N Cl. Duke Power Co. 79/05/18 1p

1

PAGE R. W. O. Duke Power Co. 79/05/21 1p

- 7905250400 ttn 79-013/017-0 on 790507 quadrant power tilt exceeded steady state limit w/o nuclear overpower trip setpoint being reduced Caused by difference in one inlet temp which occurred as result of conditions required for feedwater test tiMin R Duke Power to 79/09/21 app

7905250423 | Orwards LUR 79-014/017-0 PARKIR W Cl. | Duke Pawer Co. | 79/09/21 | ip

16/418, G # Duke Power Co 79/05/21 3pp

DOCKET 50-220 DEGINEE NUCLEAR STATION, UNIT 2

p Geourity, medical, emergency & fire protection plans

7905370070 Discusses 790813 submission of sacurity plan for storage of spent fuel & 790816 telean re requirement for security plan made Initial plan is subj to withholding from public record of treasmittal is required.

RECORD & Fuel Reprocess & Recycle Branch 79/03/29 ip

/VONIADABLE Forwards emergency procedure EP/D/A/1800/4, "Loss of Reactor Contact." Containing Instructions for operator action for small breaks
PANKIN, G. Duke Power Co. 79/05/09 25pp

( Ceneral correspondence

190511013% Uiges careful review of staff rept before ordering shutdown of facility, since action could cause extensive power curtailments & higher fuel costs for 1 2 million customers in Caroline piedmont technics flowers.

/YOOOJOJOJ Expressor gratitude for decision to close facility.
historestan M M Affiliation Unknown 79/04/28 ip

J Insurance & indomnity information

790514043B Forwards Amend 13 to Indemnity Agreement 8-44 per 100FR140 changes in increase in limitity insurance from \$140 million to \$140 million, affective 790501. Bupporting documentation Antitrust & Indemnity Group, 79/05/Q1 App enci Baltzman, J

7903160761 Bubmits executed copy of Amend 13 to Indemnity Agreement B-44, reflecting changes in 100FR140. PARKER, N. D. Duke Pawer Go. 79/05/08 Gpp

7903310348 Forwards replacement copy of Amend 8 to Indemnity Agreement 6-44 in response to 790516 request W/copy of util MANAIS transmittel life PARKER, W.D. Duke Power Co. 79/03/22. 3pp

7905110125 Agrees to close block valve RCHeb until approvat if we thickness analyses for electromatic relief valve RCHeb to received However, valve will be opened for reactor transients THIES.A C Dute Power Ca 73/10/05 2pg

--7905250018 Amends 69.69 % &6 to Licenses EPR-38 CFA-41 % LyA-40 respectively, which revises ETS by deleting aquatic surveillance program & special study program and the REID:R N Operating Reactors Branch 4 797-32 1132

--7905250021 EIA supporting Amends 69.69 & 65 to Licenses (AM 1) CFH & b DPR-55, respectively \* Operating Reactors Branch 4 77/03/02 4;p

7905190155 Responds to R Mattaon & D Ross correspond value of resource natural circulation test on BM reactor TEDESCORE Assistant Director for Plant Systems 79 u47,5 42,

7905080130 Responds to 790329 submittal re radiological efficant Term Speciwhich omitted solid radwaste process control program Requests omitted portion REID:R W Operating Reactors Branch 4 79/14/18 Tep

7905010521 Forwards documentation, design into \$ projected implementation schedules re emergency feedwater eye as committed in NRC 790425 meeting PARKER, N D Duke Power Co 79/04/25 4pp

7905010550 Forwards addl info re Ofc of Nuclear Reactor Regulation status rept Requests addl dialogue w/NRC re control sys LEE, M 8 Duke Power Co 79/04/25 ip

7905030371 Informs that util has conducted review of plant design & operation, including goal of improving reliability of normal faedwater sus & added assurance of emergency feeduater supply to steam generators Design adequate OHEN, M H Duke Power Co 79/04/25 2pp

7903040047 Corrects error in 790419 ler to NRC Reported period of facility mode should be Jan-Dec 1979 PARKER, W O Duke Power Co 79/04/25 lp

7909240782 Responds to 790920 itr requesting advice on allowable symp interval for submittal of repts to MRC REID,R W Operating Reactors Branch 4 79/04/26 2pp

7905020283 Informs of util position on issuance of formal order for continued plant operation Written issuance is undesirable as policy & legally unnecessity LEE.W 8 Duke Power Co 79/04/29 19

7908040332 Forwards response to 780329 request for add) snfo re proposed changes to hydraulic shock suppressor Tech Spec PARMER.W C Duke Power Co 79/04/30 2pp

7905080433 Forwards proposed revision to tech Specs covering reactor bldg hydrogen purge sys, penetration room ventilation sys reactor bldg purge filters & spank fuel pool vantilation

SUS PARKER.W C Duke Pawer Co 79/05/01 11ap

7905080566 Forwards proposed revision to Tech Specs.deleting Terh Spec 4 13 which is no longer required PARKER, W.O. Duke Power Co. 79/05/Ol. 4pp

7905080388 Responds to questions raised at 790501 meeting Forwards addition of high capacity storage racks Info supplements 790202 & 790420 submittals PARKER, M. O. Duke Power Co. 79/05/02 3pp

7905240466 Documents completion of 761001 proposal to delete Tech Spece ve tendon, anchorage & liner plate surveillance programs
License fee not required.
PARKER, W. C. Duke Power Co. 79/05/02 19

- 7905140189 In response to NRC 790418 request; forwards proposed Tech Spec re plant solid raduaste process control program PARKER, W.O. Duke Power Co. 79/05/07 5pp
- 7905240231 Forwards status on improvements to emergency feedwater sys, per HO Parter 790425 itr & MS Lee 790424 itr PARKER.H O Duke Power Co 79/05/07 100pp
- 7905150317 Clarifies 790507 conversation re ALARA program associated w/recacking of spent fuel pool PARKER.M 0 Duke Power Co 79/05/08 2pp
- 7903140360 Lists drawings used for installation of automatic starting of interconnected emergency feedwater sys.which were sent to NRC on 790503 PARKER, H O Duke Power Co 79/05/09 1p
- 7903140268 Forwards "Emergency Feedwater Bys, Sys Concept & Analysis " Pump installation to be complete by 790829 Gversized drawing in Central Filet PARKER, H O Dute Power Co 79/05/10 9pp
- 7903140389 Forwards "B&W 177 Fuel Assembly Duners Group Asymmetric LOCA Loads Evaluation Program, Phase 2," dtd 790410 Supersedes program provided on 770111 PARKER, W.O. Duke Power Co. 79/05/10 1p
- --7905160390 "B&W 177 Fuel Assembly Gwners Group Asymmetric LOCA Loads Evaluations Program Phase 2 " Duke Power Co 79/04/10 9pp
- 7905220270 Submits request for relief from requirement of ASME Boiler & Pressure Vessel Code, Section 11, re impracticality of doing hydrostatic test on emergency feedwater header due to excessive leakage through boundary isolation valves PARKER, N O Dute Power Co 79/05/11 7pp
- 7905220235 Forwards "Steam Generator Operating History " PARKER: H G Duke Power Co 79/05/14 1p
- --7905220237 "Steam Generator Operating History " \* Duke Power Co 79/05/14 30pp
- 7905230543 Forwards revised sys concept & analysis re addition of two motor-driven emergency feedwater pumps Supersedes 790510 submittal M/oversized drawing PARKER:N O Duke Power Co. 79/05/17 10pp
- 7905240475 Responds to IE Bulletin 79-058 re THI Incident Forwards proposed amend to Tech Specs.changing setpoints of pressurizer electromagnetic relief valve & reactor coglant sys high pressure trip PARKER.H O Duke Power Co 79/05/21 11pp
- 7905240478 Furwards design description for safety grads anticipatory reactor trip on turbine trip or loss of main feedwater Mods will be instabled for each refueling outage following NRC approval PARKER. N D Duke Power Co. 79/03/21 Spp
- 7905300208 Forwards summary of EDS Nuclear. Inc resolution/documentation of allow flexibility error which existed in versions of PIBCL siping Analysis computer program from Jan-Oct 1769 Review & reanalysis included all work through Dac 1970 PORTER, F L EDS Nuclear, Inc 79/05/21 7pp
- --7905300263 Forwards EDS Nuclear, Inc hist of BHRs & piping sys which could have been impacted by deficient computer program OE has no record of reanalysis for Cooper piping sys STEPHENS, PM General Electric Co . Nuclear Energy Products Div 79/Qt/24 18pp
- 7903310211 Forwards proposed Tech Space revision re limiting conditions for operation & surveillance requirements PARKER, W O Duke Power Co 79/05/25, Spp
  - s, IE Bulletins & correspondence

- 7905010177 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping" ByREILLY, JP Region 2, Atlanta, Office of the Director 79/03/23 2pp
- 7905030307 Forwards IE Info Notice 79-07, "Rupture of Radwasts Table" D'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/03/26 2pp
- 7905230272 Discusses BBW rept, "Records Investigation Rept Related In Off-Chemistry Welds in Matl Burveillance Specimens & Response to IE Bulletins 78-12 & 78-12A-Buppl." rept accurately represents data for reactor pressure vessels PARKER, W. O. Dute Power Co. 79/03/27 19
- 7905010098 Forwards IE Info Notice 79~08, "Interconnection of Contaminated Sys w/Syc Air Sys Used as Source of Breathing Air " O'REILLY, J P 79/03/28 2pp
- 7905010380 Forwards IE Info Notice 79-09. "Spill of Radioactively Contaminated Resin" O'REILLY, J.P. Region 2. Atlanta, Office of the Diructor 79/03/30 2pp
- 7905230279 Responds to IE Bulletin 79-02 re longitudinal weld #efecti No ASME SA-312 Type 304 piping or any other welding w/o filler metal piping mfg by Youngstown Welding is in Use of planned for use. PARKER, NO Duke Power Co 79/04/04 ip
- 7905100298 Forwards responses to IE Bulletins 79-05 & 79-056. "Nucles incident at TMI" PARKER, N O Duke Power Co 79/04/10 21pp
- 7905020048 Ack receipt of 790326 itr informing NRC of steps laber to correct violations noted in IE Insp Repts 50-269/79-0 ), 50-270/79-03 & 50-287/79-03 KENNA, W Region 2, Atlanta, Safeguards Branch 74/04/12 is
- --7908020044 Responds to NRC 790306 ltr re violations noted in 1f from Repts 50-269779-03. 50-270799-03 & 30-287779-03 Corrective actions withheld (ref 10CFR2. 790) PARKER: 4 0 Duke Power Co 79703/26 ip
- --7905020078 Forwards IE Insp Repts 50-267/79-09,50-270//9 ()) t 50-287/79-03 on 790205-06 Notice of violation withheld (ref 100FR2 790) KENNA, W B Region 2. Atlanta, Safeguards Branch /9///)]/35
- ~-7905020087 IE insp Repts 50-269/79-03.50-270/79-03 & 50 JN///V-c3: 790205-06 Noncompliance noted areas of testing/maint & detection aids Details withheld (ref 100FR2 790) TOBIN, W J Region 2, Atlanta, Office of the Director OfficeSP(E,F P Region 2, Atlanta, Safeguards Dranch JV/0) in
- 7705100046 Responds to IE Bulletin 77-05A, Items 7,8,10 % it re fm; incident All manual valves which could defeat or compromise flow are locked open are PARKER, H, O Dute Power Co 77/04/13 Spp
- 7905040176 Forwards IE Bulletin 79-068, "Review of Operational fera Sys Misalignments Identified During THI Incident." O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/04/14 ip
- 7905040263 Forwards IE Bulletin 79-07, "Beismic Btress Analysis of Bafety-Related Piping " Licensee action required O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 2pg
- 79030403B1 Forwards IE Bulletin 79-08, "Events Relevant to Hosling Water Power Reactors Identified During TMI Incident " O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 ip
- 7908030160 Forwards IE Bulletin 79-09: "Feilures of GE Type AM -2 Circuit Breaker in Sefety-Related Bys." Licensee action required.

  0'REILLY: J P Region 2: Atlanta: Office of the Director 79/04/17 20:
- 7905020429 Forwards IE Bylletin 79-06A:Revision 1, "Hevisw of Operational Errors & Sys Hisalignments Identified During Ent Incident " D'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/04/18 2pp

- 793240432 Responds to IE Bulletin 79-03. Item 3. re TMI incident Reactor protective sys high RCS pressure setpoint lowered to not greater than 2.300 psig Pressurizer power operated relief valve raised nominally to 2,450 psig PARKER, W O Duke Power Co 79/04/21 1p
- 7905240505 Furwards rusponse to IF Bullatin 79-07 re computer program used for piping analysis Algebraic summation methods were not used in piping analysis PARKER, N.O. Disk Power Co. 79/04/24. Ppp
- 7900110264 Forwards 790000 response to SE Bulletin 79-058. Items 1.2.4 & 6.re THI incident PARKER. W G Duke Power Co 79/05/05 1p
- --790h10266 Responds to IE Mulletin 79-DBB. Items 1.2.4 to 6 Emergency gracedures for loss of reactor content flow steam supply systrupture, uncontrollable Flaceding of Eurbine bidg to loss of normal HPI makeup or letdown have been revised PARKEU, W O Duke Power to 79/05/05 6pp
- 7905J00541 Furwards inservice insp program PARKCR-W O Duke Power Co. 79/05/15 1p
- --7005000550 Inservice thap program
  \* Dake Power Co 79/05/15 75pp
- PROSPARTI Forwards description of post-Thi operator training per 7/0015 discussions & IC Dulletin 79-05,79-05A & B Operating thifts have adequate knowledge to operate reactors in all modes eARKER, W O Duke Power Cq 79/05/16 4pp
- R Pariodic operating super to & related correspondence
- 1904330038 Forwards monthly sparaling rept for Apr 1979 PMMH R.G C. Buke Power Co. 79/09/15 1p
- ---/905220368 Mentally operating tept for Apr 1979 RPAVID-J A Duke Power Co 79/05/15 14pp
- B Reportable accurrences, LERs & related correspondence
- 7908020 127 Forwards LFR 79-010/03L-0 PARFLR, W O Duke Power Go 79/04/27 IP
- ---7403020340 LER 74-010/031-0 on 740313 \$ 25 redundant high pressure ave water pump A imperable while gump B was out of ave to repair leakage from pump motor cooler Leak source repaired & reglacement coolers ordered LI-WIB: B R Duke Power Co 74/04/21 3pp
- /909150534 Forwards LER 79-002/03L-0 PARKER-J P Quie famor Co 79/09/11 1p
- -- 1905150540 LER 79-002/03L-0 on 790412 during monthly performance test, pressurizer sample valve 280-6 failed to close on activation

- J Insurance & indemnity information
- 7905310261 Forwards GA Carlson itr re Price-Angerson Act retrospective insurance premiums
  BRUE, N. L. Other Mountain Power Corp. 78/G9/15 33p
- 7905070497 Confirms increased liability limit to \$124,050 060 for policies NF-1,25,43,76,83,100,111,140,146,191,161 164 170 173,174,178,179,180,182,185,186,167,188,159,192,193,194,195 177,198,300,201,204,206,207,208,210,212,214,215,6 offers GUATTROCHHI, J American Nuclear Insurars 79/05/01 1p
- 7905070582 Confirms increase in liability limit to \$25 CO3 CO3 for policies MF-22.26.29, 38.39, 44.46.47, 49 50.51, 52 53.54 55 56 57, 58, 60.61, 64.66.67, 69.49, 70.71, 72, 74, 76, 77, 78, 79, 80.85 87, 88.90, 91, 92, 93, 74, 95 & 95 ROBERTS, D. H. Mutual Atomic Energy Liability Underwriters 79/05/01
- 7905140215 Forwards Amend 9 to Indemnity Agreement B-47.per 100FR140 changes.re liability insurance increase from £140 million to \$160 million, effective 790501 Supporting documentation encl SALTZMAN.J Antitrust & Indemnity Group 79705701 Spp
- 7909190361 Forwards Amend 9 to Indeanity Agreement 8-49 re increase in liability insurance effective 790301 CAREY.W W Vermont Yankse Nuclear Power Corp 79/05/11 399
- P Operating license stage documents & correspondence
- 7905080239 Responds to 770429 ltr requesting o-month delay in implementing 10CFR50 55 requirements Review continuing ORIMES B K Assistant Director for Engineers & Projects 79/04/11 2pp
- 7905080423 Supplements 790404 itr re environ qualification of Class (E equipment Limit switches will be replaced w/switches qualified for LOCA environ Conclusion in 790404 ltr remains valid MODDY, D.E. Vermont Yankes Nuclear Power Corp. 79/04/24 ip
- 7903290038 Responds to 790413 request re QA program Suggests revision number of YOGAP-1-A not be designated HEIDER, L. H. Yankee Atomic Riectric Co. 79/04/24 1p
- 7905070548 Forwards Revision & & Amend i to Revision & of operational GA programmas requested in 790410 ltr ORDGE.R H Yankee Atomic Electric Co 79/04/30 49p
- ---7905070553 Informs that revisions to QA program are acceptable HAABS: W P Quelity Assurance Branch 79/04/10 1789
- 7903100319 Responds to NRC 790312 itr requesting schedule for completion of Mart I containment program structural and major mod planned for completion before Dec 1980 GROCE, R H Vermont Vankes Nuclear Power Corp 79/05/04
- 7903140253 Forwards add1 info re Tech Boac changes to average power ratio monitor gain adjustment mnnhv.B E Vermont Yankee Nuclear Power Corp. 79/05/09 2pp

### G. Inspection reports, IE Bulletins & correspondence

- 7905:10388 Forwards IE Insp Rept 50-271/79-04 on 790213-16 & 21-22 No noncompliance noted BRUNNER, E J Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 79/03/20 2pp
- --7908110394 IE Insp Rept 50-271/79-04 on 790213-16 & 21-22 No noncompliance noted Major areas inspected plant operations, organization & administration on site review committee LERs & licensee action on previous findings
  STETKA.T F. FDLEY.T Region 1. Philadelphia. Diffice of the Director MCCABE.E C Region 1. Philadelphia. Reactor Operations Nuclear Support Branch 79/03/19 14pp
- 7705010150 Forwards IE Info Notice 79-05, "Stress Analysis of Safety-Related Piping" GRIER.B H Region 1. Philadelphia, Office of the Director 79/03/23 ip
- 7905010075 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys u/Svc Air Bys Used as Source of Breathing Air " GRIER, B H Region i, Philadelphia, Office of the Director 79/03/28 ip
- 7705010326 Forwards IE Info Notice 77-09, "Spill of Radioactively Contaminated Regin" GRIER, BH Region 1, Philadelphia, Office of the Director 79/03/30 ip
- 7905070693 Responds to IE Bulletin 79-03 re welding defects No further action required since seam weld insp requirement is ASME III Only plants fabricated under these rules are affected MDCOV, P E Vermont Yankee Nuclear Power Corp 79/03/30 19
- 7905020113 Forwards IE Bulletin 79-Dé, "Review of Operational Errors & Bus Misalignments Identified During THI Incident " GRIER, B H Region 1, Philadelphia, Office of the Director 79/04/11 1p
- 7905020308 Forwards IE Builetin 79-07. "Seismic Stress Analysis of Safety-Related Piping " Licensee action required GRIER, B H Region i, Philadelphia, Office of the Director 79/04/14 tp
- 7903040111 Forwards IE Bulletin 79-06B. "Review of Operational Errors & Sign Misalignments Identified During TMI Incident "ORIER.B H Region 1, Philadelphia. Office of the Director 79704/14 tp
- 7903040297 Forwards IE Bulletin 79-08. "Events Relevant to Boiling Mater Power Reactors Identified During THI Incident " Licensee action required ORIER.B H Region i, Philadelphia, Office of the Director 79/04/14 1p
- 7908030111 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " Licenses action required GRIER, B H Region i, Philadelphia, Office of the Director 79/04/17 in
- 790802033B Forwards IE Bullstin 79-06A, Revision 1, "Revise of Operational Errors & Sys Misalignments Identified During TMI Incident" GRIER, B. H. Region 1, Philadelphia, Office of the Director 2004.14
- 7905010500 Submits second request for six month delay, until 800130, for implementation of pump & valve testing portion of updated inservice insp program
  VANDNBURGH.D E Vermont Yankee Nuclear Power Corp 79/04/25 2pp
- 7705010506 Forwards Class III license amend fee for inservice insp changes to Tech Specs Believes fee schedule is Illegal Bobmits fee under protest w/o walving right to contest fee validity GRACE,R,H Vermont Yankes Nuclear Power Corp 79/04/25 3pp
- 7903070455 Forwards proposed "Inservice Insp Program," w/18 sys flow drawings
  GROCE, R H Vermont Yankes Nuclear Power Corp 79/04/30 2pp
- --7903070462 "Inservice Insp Program." exam schedule & sys flow Grawings FLONMAY.W., GUIRGIR.D.C., HOODY.T.E., Vermont Yankse Muclear Power Corp. 79/04/30 388pp
- 7905290088 Submits add1 info to 790427 response to IE Sulletin 79-07 re seismic stress analyses of safety-related piping GROCE, R. H. Vermont Yankee Nuclear Power Corp 79/05/04, 2pp

- R Pariodic operating reports & related correspondence
- 7903010480 Forwards "Ecological Studies of CT River, Vernon, VT." Augi VIII, 1978 VANDENBURGH, D. Vermont Yankes Nuclear Power Corp. 79/04/23
- --7903010482 "Ecological Studies of CT River, Vernon, VT, " Rept VIII.14% \* Vermont Yankee Nuclear Power Corp. 79/04/25 188pp
- 7905070888 Forwards "Hydrothermal & Biological Studies, CT River, Very, VT. Phase V." Oct 1977-May 1978
  MARX.D J Vermont Yankes Nuclear Power Corp. 79/05/01 1p
- 7905070592 "Hydrothermal & Biological Studies, CT River, Vernon, Vt. Phan V, " Oct 1977-May 1978 \* Vermont Yankee Nuclear Power Corp 79/03/31 100pp
- 790515034; Forwards monthly operating rept for Apr 1979
  MOODY, D.E. Vermont Yankee Nuclear Power Caro. 79/05/12 Lp
- ---7905150343 Monthly operating rept for Apr 1979
  SJOGREN.R M Vermont Yankee Nuclear Power Corp 79/05/12 egg
- & Reportable occurrences, LERs & related correspondence
- 7905080552 Forwards LER 79-011/03L-0 CONMAY.W F Vermont Yantse Nuclear Power Corp 79/05/03 lp
- ---7905080553 LER 79-011/03L-0 on 790403 spring plate of actuator was binding on guide staffs Caused by rough surface on guide shafts Surface smoothed & verified operable CONMAY. W F Vermont Yankee Nuclear Power Corp 79/05/03 3pp
- 7905290037 Forwards LER 79-001/03L-1 CONMAY.W F Vermont Yankee Nuclear Power Corp 79/05/23 tp
- ---7905290040 LER 79-001/03L-1 on 790110 through wall leak near restler water cleanup sys suction piping noted. Caused by cracks in weld neck due to intergranular stress corrosion Repairs made & sys returned to syc CONHAY.W F Vermont Yankes Nuclear Power Corp. 79/05/23 ###
- BOCKET 50-272 SALEM NUGLEAR GENERATING STATION, UNIT 1

  E NRC Safety Evaluation Report (BER), suppls & correspondence
- 7905250137 Forwards SER & EJA. W/o encl SMITH: B H Branch 2 79/03/29 1;
- Q Adjudicatory correspondence
- 7905170300 Forwards resolution of storage of spant fuel in lower Alloways Creek Township, NJ.

  MCQQNQUGH, J. A. Pennsyille, NJ. 79/03/04 1p
- --7705170302 Resolution opposing increase in spent fuel storage capacity at plant in Lower Alloways Greek Township, NJ SPARKS, D W , MCDONOUGH, J A Pennsyille, NJ 77/03/D1 2pp
- 7905230653 Answer of intervenor Township of Lower Alloways Creek.NJ seeking denial of licensee motion for summany disposition Statement of matl facts, affidavit & Certificate of Svc enci VALORE.C Lower Alloways Creek, NJ 79/03/12 7pp
- 7905250471 Forwards Amend 42 to FBAR, per 790315 prehearing conference request FRILING.R Public Bervice Electric & Qas Co of New Jersey 79/03/24 1p
- 7909230649 Discusses actions taken at 790315 prehearing conference Possible settlement & consolidation of contentions, identification of witnesses & denial of motion to consolidate conferences discussed. Hearing schedule set. MILHOLLIN. 6 L. Atomic Bafety and Licensing Board Panel 79/03/29
- 7905130180 Response in support of licenses's motion for summary disposition Forwards response to licenses's statement of facts Forwards licenses's memo in support of its motion for summary disposition SMITH-B H , MODRE, J E Branch 2 79/03/30 ip.
- --7909130187 Responds to licensee's statement of matl facts no genuinal issue to be heard SHITH, B.H., MOORE, J.E., Branch 2 79/03/30, 14pp.

- --7705150192 Responds to licensee's memo in support of its 790227 motion for summary disposition Affidavits of JR Weeks, JN Donohew, TJ Carter, AL Toalston & OG Zech enci SMITH B H , MODRE, TF Branch 2 79/03/30 44pp
- --7705150176 "Corrosion of Matls in Spent Fuel Storage Pools"
  WEEKB, J R Brookhaven National Laboratory EY-76-C-02-0016
  BNL-NURE9-23021 77/07/31 20pp
- --7403150201 "Corrogion Considerations in Use of Boron in Spent Fuel Storage Pool Racks" HERKS, J. R. Brookhaven National Laboratory FIN A-3106 DNL-NUREG-29582 78/12/31 26pp
- 7905290102 Informs that listed documents have been requested from paraons making limited appearances at special prohearing conference Requests that Legal Div make appropriate response
  HILIKULLIN,O L Atomic Safety and Licensing Board Panel 79/03/30
- 7905030020 NRC response to 790329 order following prehearing conference Intends to introduce into evidence SER & EIA re mod of spent fuel pool Supporting documentation & Gertificate of Svc encl
  RMITH: B H Branch 2 79/04/02 27pp
- 7903220038 Forwards Figure 9 7-2, fuel handling area Drawing is to be attached to FBAR section filed on 790402 as part of NRC response to 790329 order following prehearing conference MODREJ E Branch 2 79704703 2pp
- 7905110407 Bubmits testimony re Contention 1 Licensee gave inadequate consideration to alternatives to expansion of onsite spent fuel storage Certificate of Byc & professional qualifications encl. Affiliation Unknown 79/04/10 12pp LUCHAK, O
- 7905250235 Testimony of O Luchak Licenses has given inadequate consideration to alternatives to onsite expansion of fuel storage capacity Certificate of Bvc & professional qualifications encl
  LUCHAK. O Lower Alloways Creek, NJ 79/04/10 12pp
- 7905240789 Furwards proposed direct testimony of RM Crockett, witness for Golemans Golemans Join objection of Township of Lower Alloways Creeks NJ to prehearing conference directive recross-examination Certificate of Svc encl VANNKES, C New Jersey, State of. 79/04/11 13pp
- 7903230325 Forwards application by Township of Lower Alloways Creek, NJ for stay of 790329 prehearing conference order recross-estamination VALORE, C Valore, C 79/04/12, 1p
- --7903230332 Application by Township of Lower Alloways Creek,NJ for stay of 790327 prehearing conference order re cross-examination Supporting documentation & Certificate of Svc encl VALORE, C Valore, C, 79704/12 lipp
- 7409130001 Forwards form of order, per 790413 conference call VALORE.C Valors, C 79/04/16 Spp
- 79051506B1 Requests NRC provide statement responding to questione posed at 790515-16 special prehearing conference Topics include error in computer codes, effect of low level radiation & K-eff calculation.
  MILHOLLIN, Q.L. Atomic Safety and Licensing Board Panel 79/04/17
- 7703130068 Objects to testimony of intervenor Township of Lower Alloways Creek, NJ & to proposed testimony offered by intervenors Colemans re Contentions 2 & 6 Certificate of Svc ans l Branch 2, 79/04/23, 7pp BMITH D. H
- 7905130672 Pretrial order of 790329 is amended to provide that on 790625, parties seaking to conduct cross-examination shall file outline of areas of cross-examination to be pursued, w/sstimate of required time HILHOLLIN, O.L. Atomic Safety and Licensing Board Panel 79/04/24
- 7905240094 Forwards nonproprietary version of Exxon's XN-NB-TP-009, "Fuel Storage Racks Correction Program," to minimize need for "in Camera" session W/o enci HETTERHAHN, M J. Conner, Hoore & Corber 79/04/24 1p
- 7905240954 Dutline of cross-examination of witnesses to be conducted at ASLB 790502 hearing. Reserves right to cross-examine on TMI layues raised in ASLB 790418 order Certificate of Svc encl DEONAN, J. J., HLUCHAN, R. M. New Jersey, State of 79/04/25 App.

- 7909250024 Outline of proposed cross-examination of evide e submitted by NRC VALORE, C Lower Alloways Creek, NJ 79/04/25 3pp
  - --7905250028 Outline of proposed cross-eramination of evidence submitted by util Certificate of Svc encl VALORE.C Lower Alloways Creek, NJ 79/04/25 4pp
- 7905230840 Retains Contention 1 & dismisses Contention 3 of intervens VOX20040 Natains Contention 1 & dismisses Contention 3 of inter-Township of Lower Alloways Creek.NJ Retains Contentions 3 & 6 but dismisses Contention 9 % 13 of intervenor Coleman W/dissenting opinion of L Kornblith MILHOLLIN.G L. KORNBLITH.L. Atomic Safety and Licensing Poard Panel 79/04/30 36pp 3600
- H General correspondence
- 7905070450 Ack receipt of 790216 resolution opposing storage of high level radioactive wastes in township Objections should be made at ASLB hearing Expansion of storage pools is unlikely No independent facilities are planned DENTON, H.R. Office of Nuclear Reactor Regulation 79/03/49 550
- 7903140291 Responds to 790312 ltr re resolution adopted on 790216 b; Township of Lower Alioways Creek.NJ Resolution opposes storage of high level wastes Forwards NRC response OBSICK.L V Office of the Elecutive Director for Operations 79/04/11 1 p
- 7905070551 Notifies of change of address for DG Brinderbaugh & RB Hubbard to 1723 Hamilton Ave.Suite K.San Jose.CA 95125 COMPER.K F MHB Technical Associates 79/04/25 ip
- I Financial information
- 7905070647 Forwards "Annual Financial Rept.1978" for Public Sac Electric & Gas Co. Atlantic City Electric Co. Delmarka Power & Light Co & Philadelphia Electric Co FRYLING.R Public Service Electric & Gas Co of New Jersey FRYLING.R Publ 79/04/30 162pp
- J Insurance & indemnity information
- 7905070497 Confirms increased liability limit to \$124 000.000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,185,186,187,188,189,192,193,194,195,197,198,200,201,204,206,207,208,210,212,214,215,3 others American Nuclear Insurers
- Mutual Atomic Energy Liability Underwriters 79/05/01
- 7905130367 Forwards Amend 6 to Indemnity Agreement B-74, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl BALTZMAN. J Antitrust & Indemnity Group 79/05/01
- 7905290089 Forwards Endorsements 33,34 & 35 to ANI Policy NF-230 CORREA.C Marsh & McLenon, M & M Nuclear Consultants, Inc. Div 79/05/22 4pp
- P Operating license stage documents & correspondence
- 7905020490 Discusses 790315 telcon w/R Sero of Westinghouse re incorrect weights for Velan Model C658 6-inch check valves used in safety injection sys SCHWENCER, A Operating Reactors Branch 1 79/04/02 ip
- 7905170263 Submits request for amend of Tech Specs re removal of coincident pressurizer pressure/level logic for safeguards actuation M/Class III amend fee LIBRIZZIF P Public Service Electric & Gas Co of New Jersey 79/05/07 1p
- 7905130280 Submits up-to-date summary of all proposed ETS changes, suggested replacement pages & supporting justifications, to assist preparation of amend to ETS, App B LIBRIZZI, FP Public Service Electric & Gas Co of New Jersey 179/05/09 73pp
- 7905220349 Responds to Westinghouse 790328 notification of potential single dropped rod events which could lead to DNB ratios lower than reported Units are four loop plants & do not have potential problem MITTL.R L. Public Service Electric & Qas Co. of New Jersey 79/05/15 2pp

- Q Inspection reports. IE Bulletins & correspondence
- 790501013B Forwards It Info Notice 79-06. "Stress Analysis of Bafety-Related Piping GRIER: B H Region 1. Philadelphia. Office of the Director 79/03/23 1p
- 7905010069 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Syc Air Sys Used as Source of Breathing Air "
  GRIER, B M Region 1, Philadelphia, Office of the Director 79/03/29 1p
- 7905010320 Forwards IR Info Notice 79-09. "Spill of Radioactively Contaminated Resin" GRIER, B. H. Region 1. Philadelphia. Office of the Director 79703/30 1p
- 7905290065 Responds to JE Bulletin 79-03 No safety-metated pipe assemblies from Youngstown Welding & Engineering Co are used SCHNEIDER.F W Public Service Electric & Gas Co of New Jersey 79/04/04 2pp
- 7905020095 Forwards IR Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident " Licensee action required GRIER, B M Region 1. Philadelphia. Dffice of the Director 79/04/11 19
- 7905070133 Act receipt of 790323 ltr informing NRC of steps baken to correct violations noted in IE Insp Rept 50-272/79-08 BRUNNER, E. J. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch 79704/18 ip
- --7903070140 Responds to NRC 790303 ltr re violation noted in IE Insp. Rept 50-272/79-08 Corrective actions operators reinstructed, reactor engineering manual revised & surveillance procedures revised SCHNEIDER; Public Service Electric & Gas Co. of New Jersey 79/03/23 Spp
- ---7905070145 Forwards IE Insp Rept 50-272/79-00 on 7902/3-16 & notice of violation BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/03/09 2pp
- --7905070149 Notice of violation from insp on 790213-16
  \* Region i. Philadelphia. Diffice of the Director 79/03/05
- --7905070158 IE Insp Rept 50-272/79-08 on 790213-14 Noncompliance noted surveillance procedures for determination of axial flux not performed as required CONTE.R J. BLUMBERG.N Region 1. Philadelphia, Defice of the Director KISTER.H B Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 79/03/02 12pp
- 7905040095 Forwards IE Bullstin 79-04B, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident "GRIER, B H Region 1, Philadelphia, Office of the Director 79/04/14 ip
- 7905040273 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Fower Reactors Identified During THI Incident "
  CRIER. B H Region I, Philadelphia, Office of the Director 79/04/14 ip
- 7905140103 Forwards IE Bulletin 79-07, "Beismic Stress Analysis of Safety-Related Piping " Licensee action required GRIER, B H Region 1, Philadelphia, Office of the Director 79/04/14 1p
- 7905030098 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " Licensee action required ORIER, 8 H. Region 1, Philadelphia, Office of the Director 79/04/17. 10
- 7905020317 Forwards IF Bulletin 79-06A, Revision i. "Review of Operational Errors & Sus Misalignments Identified During TMI Incident "GRIERA H. Region 1. Philadelphia, Office of the Director 79/04/18
- 7905250072 Responds to IE Bulletin 79-07. "Beismic Stress Analysis of Bafety-Related Piping " Provides results of Westinghouse analysis of reactor coolant loop & large hore Class I piping.

  8CHNEIDER. F. W Public Service Electric & Oas Co of New Jersey.

  79/05/03. 27pp

- R Periodic operating reports & related correspondence
- 7905080462 Forwards Mar 1979 operating rept for industrial wasto treatment plant MiDURA: HJ Public Service Electric & Oas Co of New Jersey 79/04/05 2pp
- 79030B0466 Forwards Mar 1979 wastewater treatment rept for sewage treatment plant HIDURA:H J Public Service Electric & Gas Co. of New Jorsey 79/04/12 2pp
- 7905080489 Forwards rept of subsurface water diversion & chloridg analysis of well water for quarter ending 790331 MIDURA: H J Public Bervice Electric & Oas Co of New Jorsey 79/04/16 3pp
- 7905030360 Forwards "Impingement Monitoring Program Rept 24." for Mar 1979 LIBRIZZI,F P Public Service Electric & Qas Co. of New Jersey 79/04/20 73pp
- 7905080421 Forwards Natl Pollution Discharge Climination Sys discharge monitoring rept for Mar 1979 MIDURA, H J Public Service Electric & Gas Co of New Jersey 79/04/20 13pp
- 7905300417 Forwards "Operating Rept for Apr 1979 for Industrial Haste Treatment Plant "
  HIDURA-H J Public Service Electric & Gas Co of New Jersey
  79705708 10
- --7905300421 "Operating Rept for Apr 1979 for Industrial Wasto Treatmer Plant " HIDURA.H J Public Service Electric & Gas Co of New Jersey 79704/30 1p
- 7903150275 Forwards monthly operating rept for Apr 1979 MIDURA:H J Public Service Electric & Gas Co. of New Jersey 79/05/09 ig
- ~-7905150299 Monthly operating tept for Apr 1979
  MILLER, L K Public Service Electric & Gas Co of Now Jersey
  79/05/09 13pp
- 7905300431 Forwards Apr 1979 wastewater treatment ropt for 1swage treatment plant HIDURA:H J Public Service Electric & Gas Co. of New Jorsey 79/05/10 2pp
- 7905300363 Forwards discharge monitoring repts for Apr 1979 MIDURA:H J Public Service Electric & Gas Co of New Jersey 79/05/22 13pp
- 8 Reportable occurrences, LERs & related correspondence
- 7905290070 Confirms 790405 telcon re RQ 79-35/01P W/high pressure fire pump out of svc for planned maint fire suppression water header pressure dropped below 135 psig & fire pump 2 did not start at once
  MIDURA: H J Public Service Electric & Oas Co of New Jersey 79/04/05 1p
- 7905290495 RO-79-36/OIT re apparent design deficiency associated w/seismic qualifications for 4 kV vital bus switchgear differential relay protection Currently evaluating solution involving design change HIDURA-H J Public Service Electric & Oas Co of New Jersey 79/04/11 ip
- 7905010525 Forwards LER 79-036/01T-0 LIBRIZZI,F P Public Service Electric & Qas Co of Naw Jersey 79/04/24 ip
- --7905010559 LER 79-036/01T-O on 790410 util notified of design deficiency re differential relays not meeting salamic design qualifications, Problem exists in both units Relays will be disconnected until design change implemented KAPPLE, A. W. Public Bervice Electric & Qas Co. of Naw Jersey 79/04/24 Spp

- 7905040538 Forwards LER 79-031/03L-0 LIBR1271.F P Public Service Electric & Gas Co of New Jersey 79/04/27 1a
- --7909040541 LER 79-031/03L-0 on 790329 100 elevation containment personnel air lock failed to page leak rate test Caused by split inner door seal snagged by some object passing through door Beal replaced KAPPLE.A W Public Service Electric & Gas Co of New Jersey 79704/27 2pp
- 7905040370 Forwards LER 79-032/03L-0 LIBRIZZI,F P Public Bervice Electric & Gas Co of New Jersey 79/04/30 1p
- --7905040371 LER 79-032/03L-0 on 790330 during normal operation, auxiliary typewriter started printing mountingless messages Caused by failed solid state component circuit board in typewriter togic control cabinet Component board replaced KAPPLE.A W. Public Service Electric & Gas Co. of New Jarsey 79/04/30, 3pp.
- 7905080485 Forwards LER 79-034/03L-0 LIBRIZZI,F P Public Bervice Electric & Gas Co of New Jersey 79/05/01 ip
- --77050B0B25 iCR 79-034/03L-0 on 790331 Loop 12 steamline pressure 100 prig less than Loop it Caused by failed comparator module Comparator calling channel sections verified KAMPLE.A W Public Borvice Electric & Gas Co. of New Jersey 79/05/01 38p
- 7905140227 Folwards LER 79-011/01X-2 LIBRIZZI.R P Public Bervice Electric & Gas Co of New Jersey 79/05/02 ip
- 7905140200 LER 79-011/01X-2 on 790116:RMS channel which had alarmed & cleared had been reset at control console but not at RMS panel Caused by procedure inadequacy Procedure changed initiated to clarify functions MAPPLE,A W. Public Bervice Electric & Gas Co. of New Jersey 79703/29 Spp
- 7905150444 Forwards LER 79-041/01T-0, LIBRITZI, F.P. Public Service Electric & Gas Co. of New Jersey 79/05/09 ip
- --7905130446 LBR 79-041/01T-0 on 790425 loss of addy current template plug assembly inside reactor coolant sys Caused by error of contractor maint supervisor Eupervisor will be properly instructed KAPPLE A H Public Hervice Electric & Gas Co of New Jersey 79705709 Spp
- 7703130462 forwards LER 79-037/03L-0 LIBRIZZI,F P Public Service Electric & Gas Co of New Jersey 79/03/it. 1p
- ---705180464 LER 77-037/03L on 770416 source range nuclear instrumentation channel N-32 indication became erratic Caused by disconnected shield on source range high voltage drawer connector Drawer connection reworked KAPPLEIA W Public Bervice Electric & Gas Co. of New Jersey 79/05/11 Spp
- 7905220127 Forwards LER 79-038/03L-0 LIBRIZILF P Public Barvice Electric & Gas Co of New Jersey 79/05/15 1p
- --7905220132 LER 79-038/03L-0 on 790417-ground fault on station power Transformer 21 resulted in loss of Transformers 1,ii & 21 Caused by failed cable in pothesed supplying transformer Failed cable & pothesed replaced KAPPLE,A W. Public Bervice Electric & Gas Co of New Jersey 79/03/15 Spp
- 7705220308 Forwards LER 79-039/03L-0 LIBRIZZI,R P Public Bervice Electric & Gas Co of New Jersey 79/03/13. 10
- --7905220314 LER 79-039/03L-O on 790416 unit inadvertantly entered Modiwhen work was begun to remove reactor head. Caused by maint supervisor not verifying that RCB had been brought up to refueling status KAPPLE, A W Public Service Electric & Gas Co. of New Jersey 79/05/15. 3pp
- 7905290408 RD 79-43/0iP on 790522 procedure to demonstrate operability of steam driven auxiliary feedwater pump 13 permitted closure of discharge control valves Procedure changed to ensure operability.

  MIDURA: H. J. Public Service Electric & Gas Co of New Jersey 79/05/22 tp.

- T Hearing transcripts on non-antitrust matters
- 790514056B Transcript of 790502 hearing in Salem NJ Pp 317-503 MILHOLLIN,O L , KORNBLITH.L , LAMB.J C Atomic Safety and Licensing Board Panel 79705702 191pp
- 7905140561 Transcript of 790503 hearing in Salen, NJ Pp 507-705 MILHOLLIN, G L , KORNBLITHL L , LAMB, J C Atonic Safety and Licensing Board Panel 7905703 190pp
- 7905140558 Transcript of 790504 hearing in Salem.NJ Pp 701-918
  MILHOLLIN.G L , MORNBLITH.L , LAMB.J C Atomic Safety and Licensing
  Board Panel 79/05/04 208pp
- DOCKET 50-273 BERNAU NUCLEAR STATION, UNIT 1
  G Adjudicatory correspondence
- 7905160227 Reviews impact of TMI on upcoming hearings, lists hearings scheduled for Apr & May CUNNINGHAM.G H Branch 2 79/04/03 2pp
- DOCKET 50-274 U S GEOLOGICAL SURVEY RESEARCH REACTOR
  J Insurance & indemnity information
- 7905160244 Forwards Amend 9 to Indemnity Agreement D-10.per 10CFR140 changes.re increase from \$140 million to \$160 million affective 790501 Supporting documentation encl SALTZMAN.J Antitrust & Indemnity Group 79/05/01 Spp
- 7903150481 Forwards Amend 9 to Indemnity Agreement D-10
  MARRANZING, A P Interior, Dept of, Geological Survey 79/05/09
- DOCKET 50-275 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 1

  A Application/construction stage documents & correspondence
- 7905070674 Forwards replacement pages for Amends 1 & 4 to CPPR-39 & CPPR-69
  STOLZ,JF Light Hater Reactors Branch 1 79/03/29 10pp
- 7905020490 Discusses 790319 telcon w/R Bero of Hestinghouse re incorrect weights for Velan Model C658 6-inch check valves used in safety injection sys BCHWENCER.A Operating Reactors Branch 1 79/04/02 1p
- 7905230578 Extends const completion dates to 790630 for Unit 1 & 800229 for Unit 2 STOLZ, J.F. Light Water Reactors Branch 1 79/04/13 6pp
- --7905230582 FR natice ordering extension of const completion dates to 790630 for Unit 1 & 800229 for Unit 2 BOYD,R S Division of Project Management 79/04/13 2pp

#### Q Adjudicatory correspondence

- 7905030166 Request by intervenors Scenic Shoreline Preservation Conference, San Luis Obispo Mothers for Peace, Ecology Action Club. SA Silver & JJ Foster for late filling of proposed findings of fact & conclusions of law M/Certificate of Svc FLEISCHAKER, D & Fleischater, D & 79/03/25 App
- --7905030174 Proposed findings of fact & conclusions of law by intervenors Scenic Shoreline Preservation Conference. San Luis Obispo Mothers for Peace Ecology Action Club, 8A Silver & JJ Foster FLEISCHAKER, D S Fleischaker, D S PHILLIPS, J R., KRISTOVICH, S Center for Law in the Public Interest 79/03/25 69pp
- 7903250052 Informs of inability to submit proposed findings of fact on adequacy of plant security systemied access to evidence & access to hearing on security plan Certificate of SvC encl BALDHIN.W A San Luís Obispo Mothers for Peace 79/03/29 3pp
- 7908230789 Orgup of 15 ltrs protesting opening of facility MARGOLIS, K R . WYLER: B Affiliation Unknown 79/03/30 19pp
- 7905010115 Forwards request for Board notification re nonsafety-grade equipment to mitigate transients SCINTO. JF Hearings Division 79/04/02 Sipp
- --7905010156 Board motification staff assessment re nonsafety-grade equipment to nitigate transients VASSALLG-D B Assistant Director for Light Water Reactors 79703/29 2pp
- --7705010199 Board notification recent issue on nonsafety-grade equipment to mutigate transients More info is required TEDESCD.R L Assistant Director for Reactor Safety 79/03/16
- 7905240256 Requests info on facility & earthquake, Unhappy w/nuclear power GARCIA. © Affiliation Unknown 79/04/04 Ip
- --7705240279 Requests that facility not be allowed to operate.
  MANZER.N , MANZER.R Affiliation Unknown 79/03/30 1p
- 7903300044 Mation of extension of time until 790410 to file proposed findings of fact & conclusions of law Certificate of Sycentic RETCHEN.E O Branch 3 79/04/04 4pp
- 7905290114 Orants NRC 790404 motion for extension until 790410 in which to file findings of fact SQUERS, E.S. Atomic Safety and Licensing Board Panel 79/04/05 1p
- 7905310104 Errata sheet to joint intervenors' proposed findings of fact b conclusins of law Centificate of Svc and FLEISCHAKER, D S Fleischaker, D S PHILLIPS, J R , KRISTOVICH, S Center for Law in the Public Interest 79/04/05 7pp.
- 7905290330 Responds to 790326 itr re status of facility licensing Evidentiary record in proceeding closed 790312:last pleading scheduled to be filed by 790416 Procise date for initial decision cannot be made VORE, J R Atomic Safety and Licensing Board Panel 79/04/06 ip

- 7905100370 Forwards corrected pages to NRC 790410 proposed findings, changing words "Initial Decision" to "Conclusions of Law" TOURTELLOTTE, J Branch 4 79/04/12 3pp
- 7905130726 Responds to 790216 & 790321 Itrs requesting denial of CLI ASLB will consider issue Views to be included in docket file of proceeding ENOELMARDY.T.F. Deputy Executive Legal Director 79/04/17 13
- 7905150598 Forwards resolution adopted on 790416 Resolution requests deferment of action on license application pending determination that safety sys are adequate to assure public safety MENZEL, H C Santa Barbara County, CA 79/04/18 ip
- --7905150603 Resolution of Board of Supervisors of Santa Darbara Co.\*:,
  CA urging NRC to defer final action on license application
  until facility safety systems are adequate to ensure public
  safety
  YAGER D.M. Santa Barbara County, CA. 79/04/16 ip.
- 7905i50iiB Responds to encl itr opposing operation of facility bacewing proximity to active earthquake fault & concern for disposal of high level radioactive wastes Mattere being considered by ASLB BOYD, R.B. Division of Project Management 79/04/30 3pp
- 7903240564 Requests denial w/o prejudice of joint intervenors' matica to withhold issuance of OL Certificate of Svc encl TOURTELLOTTE. J Branch 4 79/05/02 App
- 7903300007 Response in opposition to joint intervenors' request to withhold issuance of OL Motion is untimely, in wrong form & poorly taken MORRISSEY, J C Pacific Cas & Electric Co OEHR, A C Snell & Hilmer NORTON, S Bruce Norton 79/05/09 App
- 7905300716 Ack recaipt of 790425 % 790426 itrs re opposition to operation of facility due to proximity to Hosgri Fault. Facility designed to withstand seismic event of 7 5 ABLD is preparing decision re licensing based on 790215 hearing. DENTON, H R Office of Nuclear Reactor Regulation 79/05/14. 298
- --7903300719 Expresses opposition to operation of facility due to proximity to Hosgri Fault HATERHOUSE.H Affiliation Unknown 79/04/26 1p
- --7909300720 Expresses oposition to operation of facility dus to proximity to Hosgri Fault WATERHOUSE.E Affiliation Unknown 79/04/25 1p

### H Coneral correspondence

- 7905230452 Requests immediate halt to const of facility. ANDREWS, M House of Rep 79/04/02 ip
- 7905070351 Notifies of change of address for DG Brindenbaugh & RU Hubbard to 1723 Hamilton Ave, Suite K. San Jose, CA 95125 COOPER, K. F. MHB Tachnical Associates 79/04/25 1p
- 7905240713 Requests suspension of OL until necessary safety mods are implemented BRDNN.E G California, State of 79/05/04, 2pp
- 7905240265 Responds to 790320 ltr re constituent concerns re granting of license to facility Seismic event of 7.5 magnitude can be withstood & quality of const is controlled by licenses GA program.
  OBSICK.L. V. Office of the Esecutive Director for Operations. 79/05/08. 3pp

### I Financial information

- of 7905300148 Forwards "Annual Financial Rept 1978." CRANE, P A Pacific Gas & Electric Co 79/05/23 Ip.
  - ---7905300174 "Annual Financial Rept 1978 "
    + Pacific Gas & Electric Co 78/12/31, 40pp.
  - 7903300310 Forwards "Estimated Internal Fund Generation for CY79" & "Annual Financial Rept 1978" CRANE, P.A. Pacific Gas & Electric Co. 79/05/24 3pp
  - --7905300529 "Annual Financial Rept 1978 "
    \* Pacific Oas & Electric Co. 79/02/23 36pp.

### J Insurance & indomnity information

- 7905140512 Forwards Amend 4 to Indemnity Agreement 8-75 per 10CFR140 changes re increase in 11ability insurance from \$140 million to \$160 million.effective 790301 Supporting documentation
  - encl
    GALTZMAN, J Antitrust & Indemnity Group 79/05/01 6p
- 7905140406 Forwards Amends executed Amends 21 & 4 to Indemnity Agreements 0-21 & 0-75, respectively CRANE, P.A. Pacific Oss & Electric Co. 79/05/08 Spp
- O Advisory Committee on Reactor Bafeguards reports & correspondence
- 7905100325 Responds to request for written rept after cancellation of ACRS 790331 meeting re-possibility of problem w/instrument guide tubes Staff rept encl GROCKERL P Division of Project Management 79/03/30 Spp
- P. Operating license stage documents & correspondence
- 7905020244 Responds to NRC 790314 request for add1 info re containment purge valves Forwards results of CEDREVI program to calculate containment purge valve closing data coincident w/LIGA CRANELP A Pacific Oss & Electric Co 79/04/13 45pp
- 7905020302 Forwards \$1.600 Fee to extend CP. in response to NRC 790410
  1tr Requests acknowledgment
  CRANE,P A Pacific Gas & Electric Co 79/04/27 Rpp
- G Inspection reports, IE Bulletins & correspondence
- /908240747 Forwards IC Insp Rept 50-275/79-03 on 790226-23 No moncompilance noted ROOK.H E Region 5. Ban Francisco. Fuel Facility & Materiale Bafely Branch 79/03/19 2pp
- ----7903240740 IE Insp Rept 50-275/79-03 on 790220-23 No noncompliance noted Major areas inspected; emergency planning facilities & equipment, training, radiation protection staffing, radioactive weste sys & Offsite Dose Calculation Manual NORTH, H & . ROOK, H F Region 5, Ban Francisco, Fuel Facility & Haterials Bafety Branch, 79/03/19 5pp
- 7909230617 Forwards II Inep Repts 50-275/79-05 & 50-329/79-03 on 790306-09 & 15. No noncompliance noted. GRUBS J. Region 5, Ban Francisco, Reactor Operations Nuclear Support Branch 79/03/21. 2pp
- --7905230640 IE Insp Repts 50-275/79-05 & 50-323/79-03 on 790306-09 & 15
  No moncompliance noted Major areas inspected preoperational testing, evaluation & varificastion of test results, IE bulletins & circulare followup MORRILL.P.O Region 5. Ban Francisco, Office of the Director SYFRNBERO.D M Region 5. Ban Francisco, Reactor Operations Nuclear Bupport Branch 79/03/20 App
- /705010287 Forwards IF Info Notice 79-04, "Stress Analysis of Safety-Related Piping"
  ENGELKEN.R. H Region 4, Dailas, Office of the Director 79/03/23
- 7905040081 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks "
  ENGELKEN.R II Region 5, Ban Francisco, Office of the Director
  79/03/26 1p
- 7905290147 Forwards IC Insp Rept 50-275/79-08 on 790225-0316 No noncompliance noted. GREMBJ.L. Region 5. Ban Francisco, Reactor Operations Nuclear Bupport Branch. 79/04/13 2pp
- ---7905290152 IE Insp Rept 50-275/77-08 on 790225-0316 No noncompliance noted Major areas inspected preoperational testing plant tour sys verification testing & fuel storage YOUNG.T. Region 5. San Francisco: Office of the Director SYERNBERO, D. M. Region 5. San Francisco: Reactor Operations Nuclear Support Branch 79/04/13 4pp.
- 7905010023 Forwards IE Bulletin 79~06A: "Review of Operational Errors & Bus Misalignments Identified During TMI Incident."
  ENCELKEN, R H Region 5, Ban Francisco, Office of the Director 79/04/14 ip
- 7703040309 Forwards IE Bullstin 79-068, "Review of Operational Errors & Bys Hisalignments Identified During THI Incident."
  ENOELKEN, R H Region 5, Ban Francisco, Office of the Director 79/04/14 lp.

- 7905070099 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping " Licensee action required ENGELKEN.R H Region 5. San Francisco. Diffice of the Director 79704/14 ip
- 7905030291 Forwards IE Bulletin 79-09, "Failures of GE Type Ax-2 Circuit Breaker in Safety-Related Sys " Licensee action required ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/04/17 1p
- '905080366 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl" ENGELKEN.R H Region 5, San Francisco, Office of the Director 79/04/21 ip
- S Reportable occurrences, LERs & related correspondence
- 7905110203 Board notification Seabrook refueling water storage tand design deficiency SCINTO, J Hearings Division 79/03/29 30pp
- 7905150060 Forwards PNO-79-67L ENGELKEN,R H Region 5. San Francisco, Office of the Director 79/04/06 1p
- 7905150167 Forwards PNO-79-67R ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/04/11 ip
- 7905040123 Forwards PND-79-678 ENGELKEN, R H Region 5, San Francisco, Office of the Director 790/04/12 10
- 7905130141 Forwards PND-79-67T ENGELKEN.R H Region 5, San Francisco, Office of the Director 79/04/13 ip
- 7705030045 Forwards PND-79-67U ENGELKEN,R H Region 5, San Francisco, Office of the Director 780/04/14 IP
- 7905020527 Forwards PNO-79-67AA ENGELKEN.R H Region 5, San Francisco. Office of the Director 79/04/20 1p
- 7905010425 Forwards PNO-79-67A9 ENGELKEN, R H Region 5, San Francisco. Office of the Director 79/04/21 1p
- 7905010444 Forwards PNO-79-67AC & AD ENGELKEN.R H Region 5. Ban Francisco, Office of the Director 79/04/23 1p
- 7905020227 Forwards PND-79-67AF ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/04/25 ip
- 7905020256 Forwards PNO-79-67AG ENGELKEN.R H. Region 5. Ban Francisco, Office of the Director 79/04/26. ip
- 7905090005 Forwards PNG-79-67AH ENGLEMEN, R H
- --7905040360 PNO-79-67AI summary of into is notice 79042B Describes plant & environ status 79/04/2B 2pp will office of Inspection & Enforcement 79/04/2B 2pp
- 7905070007 Forwards PNO-79-67AL, per NRC 790401 ltr transmitting IE Bullstin 79-05 ENGELKEN,R. H 79/05/01. 1p
- 79030903B0 Submits followup rept to 790404 notification of RO During progress of routine weld repairs on pipe rupture restraints, cracking discovered in immediate vicinity of repairs Full rept will be submitted GRANE,P A Pacific Oas & Electric Co. 79/05/03 3pp

- 7705170072 Forwards PNO-79-67AM ENGLKEN, R H Region 5. San Francisco. Office of the Director 79/05/07 in
- 7905240651 Ack receipt of 790503 ltr providing preliminary rept recracking found in pipe rupture restraints. ENGELKEN, R H Region S. Ban Francisco. Office of the Director 79/05/16 1p
- ---7903240701 Discusses situation reported to IE on 790404 re cracking in pipe rupture restraints Details program of investigation Guppl on crack severity will be forwarded GRANE,P A Pacific Cas & Electric Co 79705/03 3pp

#### T Hearing transcripts on non-antitrust matters

- 7905030244 Corrections to transcripts from Dec 1978 & Jan 1979 bearings Centificate of Svc enc1 MORRESEY, J C . FURBUSH M H . CRANE, P A Pacific Cas & Electric Co 79704/04 25pp
- 7905240273 Requests info re E Maschke 790315 Ltr of concerns about granting of license to util LAGOMARGINO.R House of Rep. 79/03/20 1p

### DOCKET 50-276 GEORGIA TECH RESEARCH REACTOR

- J Insurance & indemnity information
- 7905300049 Forwards Amend 12 to Indemnity Agreement E-30.reflecting change in 10CFR140.increasing primary layer of 1(ability from \$140 million to \$160 million, effective 790501 Supporting documentation encl SALTZKAN.J Antitrust & Indemnity Group 79/05/01 Spp
- O Inspection reports, IE Bulletins & correspondence
- 7905070137 Forwards IE Bulletine 79-05,79-05A & 79-06,re nuclear incident at YMI O'REILLY,J P Region 2. Atlanta, Office of the Director 79/04/13 1p

### DOCKET 50-277 PEACH BOTTOM ATOMIC POWER STATION, UNIT 2

- @ Adjudicatory correspondence
- 7905230512 Util response to briefs opposing de minimus approach of Perlins proceeding Licensees in Peach Bottom & Hope Creek proceedings conted approach is validing need to consider health affects further M/Ceptificate of Syc CONNER.T B Conner. Moore & Corber 79/04/04 30pp
- 7905110418 Response to ALAB-509 re radon emissions & de minimus theory from Partins record Centificate of Svc encl SCINTO, JF Hearings Division SORDENICK, B M Branch 4 LENIS, B M Branch 2 79/04/ii 45pc
- 7905140519 Response to 790404 brief of Philadelphia Electric Co.Public Byc Electric & Oas.& Atlantic City (NJ) Electric Co re de mindmus theory Certificate of Byc encl. KEPFORD.C P Citizens for Safa Environment 79/04/11 Spp
- 7905140332 Natifies of cansolidation of five intervenor groups re radon amissions issue Parties have until 790525 in which to file for summary disposition DUFLO.M E Atomic Safety and Licensing Appeal Panel 79/04/25
- 7905240585 Hemo & order ALAB-346 Danies applicants' petition for reconsideration of ALAB-540, which consolidates applicants related issue DUFLO, N E Atomic Safety and Licensing Appeal Panel 79/05/08 3os.

### J Insurance & indemnity information

- 7905070497 Confirms increased liability limit to \$124,000.000 for policies NF-1,23,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,185,186,187,188,189,192,193,194,195,197,196,200,201,204,204,207,208,210,212,214,215,&others QUATTROCHHI.J American Nuclear Insurers, 79/05/01 lp
- 7903070582 Confirms increase in liability limit to 436,000,000 for policies HF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,56,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,91,72,93,74,75 % 96 ROBERTS,D M Mutual Atomic Energy Liability Underwriters 79/05/01.

- 7905030349 Forwards application for amend of it. ... \* \* \* fee BRADLEY, E J Philadelphia Electric (o '1 i

- ---7905110076 Application for amound of termines of recording technology of the following technology of the follow
- 7905290345 Forwards schedule for implementations in a seesary for long-term program arrupts. Some completed during Opening 1980 refueleng a signal be Spring 1986 for Unit 3 BOYER, V S Philadelphia Flectric Co 74 . . . .
- 7905300208 Forwards summary of EDS Numiees Described of albow flexibility error which estated to the PISOL piping analysis computer program from the Review & reanalysis included all works? As PORTER, F. L. EDS Nuclear, Inc. 79/05/24
- 0 Inspection reports: IC Bulletine & currence to  $-\omega$
- 7905010131 Forwards IC Info Notice /Y NA. 'Sees' / ...
  Safety-Related Piping "
  GRIER, B H Region 1, Philadelphia, fifth a ...
  79/03/23 tp
- 7905010065 Forwards IC Info Notice /9 (H) '; Ye'.
  Contaminated Bye W/Svc Air Bys Used as Contaminated Are with the Air ''
  Air ''
  ORIER, B H Region I, Philadelphia, Gifter and Top/03/28 ip
- 7903010315 Forwards IE Info Notice 79 04 124 17 4 2 Contaminated Resin " GRIER, B H Region 1, Philadelphia, ##ff.re 17 14 2 79/03/30 1p
- 7905270129 Forwards IC Insp Repts 80 277178 2 2 2 2 7 790220-0001 No noncompliance noted CARLBON, R T Region 1. Philadelphia Per CARLBON, R T R Philadelphia Per CARLBON, R T R R Philadelphia Philadelphia Per CARLBON, R T R Philadelphia Phila

- 7905020082 Forwards IF Bulletin 79-06, "Review of Operational Errors & Bys Misslignments Identified During TMT Incident " CRIER.D H Region 1, Philadelphia, Office of the Director 79/04/11 to
- 7909230694 Ack receipt of 790316 its informing NRC of steps taken to correct violations noted in II Insp Rapts 30-277779-02 & 50-27079-02
  - 50-20779-02 Region 1, Philadelphia, Fuel facility & Materials Safety Branch 79704712 ip
- --7905230710 Responds to NRC 790220 itr re vibiations onted in IE Insp. Repts 50-277779 OZ & 50-278779 OZ Garrettive actions detailed station procedures prepared & approved & surveillance test procedures revised DALTROBS 8 t. Philadelphia Fluctric Co. 29703716. Opp.
- ---7905230724 Forwards IE Insp. Repts 50 277779 02 5 50 270779-02 on 790102-05 5 00 10 5 notice of violation GMITH. O H. Region 1. Philadelphia. Fuel latfity & Materials Gafety Branch. 79702791 5pp
- --7905230712 Notice of violation from inep on 790102 05 & 0f 10 \* Region t, Philadelphia, Office of the Director 79702/14 Spp.
- --7905230/50 II. Insp Repts 30 27/7/9 02 & 50 27/1/79 02 on 790102-5 & 08 10 Noncompliance noted failure to maintain effluent releases within Tech Oper limits & failure to have procedures for task loading & closure
  NELLY,D R : NIMITY,R t Region 1. Philadelphia, Office of the Director. CROCKER/H & Region 1. Philadelphia, Fuel Facility & Materials Bafety Branch 79/02/14 22pp
- 7905290116 Forwards II Insp Repts 50 277779 05 5 50 278779 04 on 790129 0402 No noncompliance noted IRBNNER, L. J. Region I, Philadelphia, Office of the Director 79704713, 2pp
- ~~7905290120 It Insp Repts 50 277779 O5 & 50 270779 O5 on 790129-0202 No noncompliance noted Major areas tospected plant operations, facility tour. It circular follows & IER review in of, & on site
  OREFNIAMLLO Region 1, Philadelphia, Office of the Director McCollect. C. Region 1, Philadelphia, Heactor Operations Nuclear Gupport Branch 79704/11 4pp
- 790502032) Forwards IC Bullstin 79 07. "Delemic Stress Analysis of Safety-Related Piping" Litenses action required ORICH BI Region 1. Philadelphia. Strice of the Director 29704/14 ip
- 7905040007 Corwards If Bulletin 79 OAB, "Having of Operational Errors & Bys Hisalignments Identified During THI Incident."

  ORIER B. H. Region 1, Philadelphia. Office of the Director 79704/14 Ip
- 7905040239 Forwards IK Bulletin 79 OR. "Ivente Relevant to Boiling Water Power Reactors Identified During THI Incident" Licensee action required ORIGER H Region 1, Philadelphia. Office of the Director 79704714 Ip
- 7905030008 Forwards IC Bullatin 79 09, "Failures of GC Type AK 2 Circuit Breaker in Bafety-Related Bys " Licensee action required.
  ORIER-B H. Region I, Philadelphia, Office of the Director 79/04/17 Ip.
- 7905020309 Forwards IE Bullatin 79 OAA, Revision 1. "Review of Operational Errors 4 Bys Hisalignments Identified During THI Incident"
- ORIGN. H Aegion i. Philadelphia, Office of the Director 79/04/10 ip
- 7905150507 Forwards IC Inep Repte 50 277/79-11 to 50-278/79-12 on 790409-13 to notice of violation BRUNNICR.E.J. Region 1. Philadelphie. Reactor Operations Nuclear Bupport Branch 79/24/20 Upp
- ---7905150514 Notice of violation from thep on 790409:13
  \* Region 1: Philadelphia, Office of the Director 79/04/19
  Rpp
- --7905150523 IE Inep Repte 80-277/79-11 & 50-278/79-12 on 790409-13 Noncompliance noted improper valve positioning & positive control improper approval & raview GREENMAN.E J. GRAHAM.P D. Region I. Philadelphia. Office of the Director HCCABE.E C. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch. 79/04/19 26pp

- R Periodic operating reports & related correspondence
- 7905140344 Forwards "Annual Plant Med Rept 1978 " ALDEN, W M Philadelphia Electric Co 79/04/27 ip
- --7905140346 "Annual Plant Mod Rept 1978 " ULRICH: H T Philadelphia Electric Co 78/12/31 12pp
- 7905170236 Forwards monthly operating rept for Apr 1979 COONEY.M J Philadelphia Electric Co 79/05/11 1p
- ---7705170241 Monthly operating rept for Apr 1979 ALDEN,W M Philadelphia Electric Co 79/05/10 9pp
- 6 Reportable occurrences, LERs & related correspondence
- 7905220280 Forwards LER 79-007/01T-0 COUNEY, M J Philadelphia Electric Co 79/02/15 ip
- --7903220204 LER 79-007/017-0 on 790131 standby gas treatment sys sprinkler valve was not reopened following temp sensor test Caused by operator error Operator was reinstructed in proper procedures GOONCY, M J Philadelphia Electric Co 79/02/15 ip
- 7903040578 LER 79-013/031-0 on 790323 C trip logic HPCI area temp switches (TE-4941C,-42C,-43C,-44C)indicated less than ambient during routine surveillance Caused by dirty contacts on power supply for temp switch card units COUNEY, M J Philadelphia Electric Co 79/04/23, 1p
- 7705040077 Forwards LER 77-016/01T-0 COONEY,M J Philadelphia Electric Co 79/04/26 3pp
- ~-7900040072 LER 79-016/01T-0 on 790411 engineering review discovered valving associated w/ssismically qualified emergency svc water sys was normally open Caused by faulty plant design Open valves locked closed COONEY, M J Philadelphia Electric Co 79/04/26 ip
- 7905020347 Forwards LCR 79-017/04T-0 COUNLY: H J Philadelphia Electric Co 79/04/27 2pp
- --7905020356 LER 79-017/04T-0 on 790418, effluent pH of 5 3 identified, acceeding Tech Open Cause could not be determined Assation tank neutralized to bring effluent pH within limits Mod of treatment plant under investigation COUNCY. M J Philadelphia Electric Co 79/04/27 ip
- 7905040501 Forwards LER 79-010/017-1 Discusses results of continuing investigation re design errors in recirculation sys valves COONEY, M. J. Philadelphia Electric Co. 79/04/30 Spp
- --7903080464 (ER 79-010/01T-1 on 790226 power & control cable associated w/recirculation pump discharge valves & bypass valves were found routed in nonsafeguard cable trays Caused by improperly designated cables during design phase GOONCY, N J Philadelphia Electric Co 79/03/12 ip
- 7905[7044] LER 79-015/03L-0 on 790410; limit switch on M failed Cause not found, due to high temp & radiation 1 in MBTV room Appropriate logic channel was placed in condition QDONEY, M J Philadelphia Electric Go 79/05/07, 1p
- 7905230861 RO 2-79-21/iP on 790504 HPCI control cable i w/AD5 cables for short distance in cable spreading ro Caused by failure of supplier to provide proper systimetrface documents to A/E during design phase ULRICH.W T Philadelphia Electric Co 79/05/07 2p
- 7905160363 LER /9-018/03L-0 on 790428.channel D refuel: reactor bldg area ventilation exhaust radiation monif failed downscale while at power Caused by defective a converter in common radiation monitor power supply COONEY.M.J Philadelphia Electric Co. 79/05/11. 1
- 7905290214 Forwards LER 79-021/01T-0. COOMEY.M J Philadelphia Electric Co 79/05/18 3
- --7903290216 LER 79-021/01T-0 on 790504 HPCI cables im Caused by errors in designs Rerouting of cables wi effected during outages COONEY,H J Philadsiphia Electric Co. 79/05/18

- DOCKET 50-278 PEACH BOTTOM ATOMIC POWER STATION, UNIT 3
- 7905220070 Dismisses exceptions to LBP-74-42 Approves stigulation among certain parties & participants & accompanying Tech Specs as fulfilling NRC responsibilities re thermal discharges

  DUFLO.M E Atomic Bafaty and Licensing Appeal Panel 79/03/23
- 7905230812 Util response to briefs opposing de minimus approach of Perkins proceeding Licensees in Paach Bottom & Hope Creek proceedings contad approach is validing need to consider health effects further W/Certificate of Svc CONNER.T B Conner, Moore & Corber 79/04/04 30pp
- 7905:104:8 Response to ALAB-507 re radon emissions & de minimus theory from Perkins record Certificate of Svc encl SCINTO, J F Hearings Division BDRDENICK, B H Branch 4 LEWIS, 8 H Branch 2 79/04/ii 45pp
- 7905140519 Response to 790404 brief of Philadelphia Electric Co.Public Svc Electric & Gas.& Atlantic City (NJ) Electric Co re de minimus theory Certificate of Svc encl KEPFORD.C P Citizens for Safe Environment 79/04/11 Spp
- 7905240585 Memo & order ALAB-546 Denies applicants' petition for reconsideration of ALAB-540, which consolidates applicants re radon issue DUFLO.H E Atomic Safety and Licensing Appeal Panel 79/05/08
- 7905140332 Notifies of consolidation of five intervenor groups re radon emissions issue Parties have until 790525 in which to file for summary disposition

  DUFLO, M E Atomic Safety and Licensing Appeal Panel 79/04/25
  1300
- J. Insurance & indemnity information
- 7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,179,179,180,102,185,186,187,188,189,172,193,194,195,197,198,200,201,204,204,203,203,203,210,212,214,215,&others GUAYTROCHHI,J American Nuclear Insurers 79/05/01 ip
- 7905140415 Forwards Amend 20 to Indemnity Agreement 8-28 per 10CFR140 changes re increase in liability insurance from \$140 million to \$160 million, effective 790501 Supporting documentation encl
  SALTIMAN, J. Antitrust & Indemnity Group 79/05/01 App
- 7905220347 Forwards Endorsement 84 to ANI Policy NF-140 BRADLEY, E. J. Philadelphia Electric Co. 79/05/14 2pp
- P Operating license stage documents & correspondence
- 7905240184 Informs that Amend 35 to FSAR contains existing GA program, in response to NRC 790321 request DALTROFF, 8 L. Philadelphia Electric Co. 79/04/10 1p
- 7905030348 Forwards application for amend of licenses & \$i.600 filing faq BRADLEY, E. J. Philadelphia Electric Co. 79/04/30 1p
- --7905030352 Application for amend of Licenses BPR-44 & DPR-54 to change surveillance frequency to reflect change in refueling cycle from 12 to 8 months Certificate of Svc encl
  BAUER, E 0., BRADLEY, E J Philadelphia Electric Co 79/04/30
- 7905110073 Forwards application for amend of Licenses DPR-44 % DPR-56 BRADLEY, E. J. Philadelphia Electric Co 79/05/08 lp
- ---7905110076 Application for amend of Licenses DPR-44 & BPR-56, changing Tech Specs re reactor vessel matl surveillance program Certificate of Svc encl a Philadelphia Electric Co 79/05/04, 19pp

- 7905290345 Forwards schedule for implementation of major plant sce, necessary for long-term program acceptance criteria Mode to be completed during Spring 1980 refueling outage for Unit 2 & Spring 1981 for Unit 3 BOYER, V S Philadelphia Electric Co 79/05/21 3pp
- 7905300208 Forwards summary of EDS Nuclear, Inc resolution/documentation of elbow flexibility error which existed in versions of PIGCL piping analysis computer program from Jan-Oct 1969 Review & reanalysis included all work through Dec 1970 PORTER, F. L. EDS Nuclear, Inc. 79/05/21 9pp
- ---790300263 Forwards EDS Nuclear. Inc list of BWRs & piping sys white could have been impacted by deficient computer program. GE has no record of reanalysis for Cooper piping sys STEPHENS.P W. General Electric Co. Nuclear Energy Products Div 79/01/24 18pp
- Q Inspection reports, IE Bulletins & correspondence
- 7905010131 Forwards IE Info Natice 79~06. "Stress Analysis of Safety-Related Piping " GRIER:B H Region E, Philadelphia, Office of the Director 79/03/23 Ep
- 7905010065 Forwards IE Info Notice 79~08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air " GRIER, B. H. Region 1. Philadelphia, Office of the Director 79/03/28. to
- 7905010315 Forwards IE Info Notice 79~09, "Spill of Radioactively Contaminated Regin" GRIER.B H Region 1, Philadelphia, Office of the Director 79/03/30 1p
- 7905290127 Forwards IE Insp Repts 50-277/79-03 & 50-278/79-08 on 790228-0301 No noncompliance noted CARLBON, R T Region i, Philadelphia, Reactor Construction & Engineering Support Branch 79/04/03 2pp
- --7905290132 IE Insp Repts 50-277/79-03 & 50-278/79-08 on 790228-033|s noncompliance noted Major areas inspected electrical equipment OA. fire protection & status of IR circulars & bulletins FINKEL: A E . KOLTAY.P S Region 1, Philadelphia, Office of the Director EBNETER.S D Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/03/29 & pp
- 7909250132 Responds to IE Bulletin 79-03 re longitudinal weld defects in ABME BA-312 Type 304 stainless steel pipe spools Two certifications for swam weld piping found Requests additions to locate remaining pipe
  DALTROFF.S L Philadelphia Electric Co 79/04/09 2pp
- 7905020082 Forwards IE Bulletin 79-06, "Review of Operational Errors is Bys Misalignments Identified During THI Incident" GRIER, B. H Region 1, Philadelphia, Office of the Director 79/04/11 ip
- 7909230694 Ack receipt of 790316 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/79-02 & 50-278/79-02 SEMITH. O H Region 1. Philadelphia, Fuel Facility & Meterials Safety Branch 79/04/12, ip
- --7905230710 Responds to NRC 790228 itr re violations noted in 1E traj Repts 50-277/79-02 \$ 50-278/79-02 Corrective actions detailed station procedures prepared & approved & surveillance test procedures revised DALTROBS: S L Philadelphia Electric Co 79/03/16 Opp
- --7905230724 Forwards IE Insp Repts 50-277/79-02 & 50-278/79-02 on 790102-05 & 08-10 & notice of violation BMITH:G H Region i, Philadelphia, Fuel Facility & Materials Bafety Branch 79/02/28 3pp
- --7905230732 Notice of violation from insp on 790102-05 & OR-10
  \* Region 1, Philadelphia, Office of the Director 79/02/14
  3pp
- --7905230750 IE Insp Repts 50-277/79-02 & 50-278/79-02 on 790102~5 & 08-10 Noncompliance noted failure to maintain effluent releases within Tech Spec limits & failure to have procedures for cask leading & closure NEELY.D.R., NIMITZ.R.L. Region i. Philadelphia, Office of the Director CROCKER.HW Region i. Philadelphia, Fuel Factility Materials Safety Brenth. 79/02/14 22pp

- 7905290116 Forwards IE Insp Repts 50-2/7/79-05 & 50-2/8/79-04 on 790129-0202 No noncompliance noted BRUNNER, E J Region i. Philadelphia, Office of the Director 79/04/13 2pp
- --7905290120 IE Insp Repts 50-2///79 05 & 30-2/0//9-05 on 790129-0202 No noncompliance noted Major areas inspected plant operations, facility tour, IC circular followup & ICR review is oft & on site

  OREFNIAN.E O Region 1, Philadelphia, Office of the Director MCCABC, I C Region 1, Philadelphia, Reactor Operations Nuclear Bupport Branch /9/04/11 4pp
- 790502032) forwards If Bulletin 79 07, "Seismic Stress Analysis of Safety-Related Piping " Litensee action required ORICEO B Region 1, Philadelphia, Office of the Director 79704714 tp
- 77050400B7 Forwards IF Bulletin 79 06B. "Review of Operational Errors & Bya Misalignments Identified Duting TMI Incident "ORIFRLB H Region 1: Philadelphia: Office of the Director 77/04/14 1p.
- /905040259 Forwards It Builetin /9 Oft. "Events Relevant to Hotling Water Power Reactors Identified During IMI Incident "Licenses action required ORIER, Bit Region I. Philadelphia. Office of the Director 79/04/14 ip
- 790503000D Forwards II. Bulletin 79 09: "Lattures of GL Type AK-2 Circuit Breaker in Bafety Related Bys "Licenses action requires.
  ORIGIO B. Region 1: Philadelphia: Office of the Director. 79704/17 in
- 7905020109 Forwards If Bulletin 79 OAA, Revision to "Review of Operational Trrors & Bys Misallynmants Identified During TMI Incident," GRIFR B H Region 1. Philadelphia. Office of the Director 79704/10 Ip
- /90919090/ Forwards It Insp Hepts 50 2/9//9 11 6 90 2/6//9:12 on 790409 13 6 notice of violation BRUNNIR: O Region 1: Philadelphia, Reactor Operations Nuclear Bupport Branch /7704720 Upp
- 7905130314 Notice of violation from that on 240404 13
   Region I, Philadelphia, Office of the Director 79704/19
- 7908(8082) It Insp Repts to 277774 to 50 270779 to on 790409 to Noncompliance noted improper valve positioning & positive control, improper approval & review GRITHMAN, C. J., QRAHAM, P. D. Hegton 1, Philadelphia, Office of the Director MCGAN, C. Region 1, Philadelphia, Reactor Operations Nuclear Eupport Branch. 79704719 26pp
- R. Pariodic operating raports & related correspondence
- 7905140244 Forwards "Annual Plant Mod Rept 1978" Albenia H. Philadelphia Clastric Co. 79704727 Ip
- 7905170236 Forwards monthly operating rept for Apr 1979 COONCY:M J. Philadelphia Liestric Co. 79705713 19
- ---7405170241 Hunthly operating mapt for Apt 1979
  ALDENIA M. Philadelphia Clearic Co. 79709/10. Spp
- B. Reportable occurrences, LIRs & related correspondence
- 7905040077 Forwards LER JY-OL6/OIT-O COONCY, H J Philadelphia Electric Co J9/04/26 7ep
- ---7905040092 LER 79-016/01T-0 on 790411 engineering review discovered valving associated w/selsmically qualified emergency svc water sys was normally open Caused by Faulty plant design Open valves locked closed COONEY. H J Philadelphia Electric Co 79/04/26 1p
- 7903040301 Forwards LER 79-010/01T-1 Discusses results of continuing investigation re design errors in recirculation sys valves COONCY: M J Philadelphia Electric Co 79/04/30 5pp

- 7905230861 NO 2-79-21/IP on 790504 HPCI control cable improperly routed w/AD5 cables for short distance in cable spreading room Caused by failure of supplier to provide proper systinterface documents to A/E during design phase ULRICH.W T Philadelphia Electric Co 79/05/07 2pp
- 7905290214 Forwards LER 79-021/01T-0.
  CDQNEY: H J Philadelphia Electric Ca 79/05/18 3pp
- --7903290216 LER 79-021/01T-0 on 790504 HPCI cables improperly routed Caused by errors in designs Rerouting of cables will be effected during outages
  COUNEY, M J Philadelphia Electric Co 79/05/18 lp

#### DOCKET 50~280 SURRY POWER STATION, UNIT 1

- A Application/construction stage documents & correspondence
- 7903290296 Requests NRC reconsider its 3-month moratorium on issuance of new OL because of large addl costs of replacement power RAGONE, 8 Virginia Electric & Power Co 79/05/22 2pp
- O Adjudicatory correspondence
- 7905230646 Orders extension, until 790524, for NRC review of 790404 deniel of enforcement action CHILK.B J. Offics of the Secretary of the Commission 79/04/13
- 7905100262 Forwards petition of Potomac Alliance, et al for emergency 5 remedial action DOUGHERTY, J B Potomac Alliance 79/04/18 2pp
- --7905100328 Petition for emergency & remedial action re NRC violations of NEPA in issuing Amends 46 & 47 to OL.
  DOUGHERTY, J B Potomac Alliance 79/04/18 65pp
- 7905240455 Ack receipt of 790405 ltr requesting NRC to revoke OLs Ltr is currently under consideration Forwards FR notice re Allen 790405 ltr DENTON, H R Office of Nuclear Reactor Regulation 79/05/04 1p
- ---7903240461 FR notice rs J Allen 790409 request for revocation of GLs DENTON.H R Office of Nuclear Reactor Regulation 79/05/04 2pp
- 7905310033 Forwards J Allen 790405 ltr requesting NRC revoke facility OLs & FR notice of revocation request W/790330 ltr to ASLAB ra Wastinghouse EGGS deficiency DENTON.H.R Office of Nuclear Reactor Regulation 79/05/04 3pp
- U Insurance & indemnity information
- 7705110107 Amend to Endorsement 51 to NELIA Policy NF-186 Constitutes Endorsement 54 \* Nuclear Energy Liability Insurance Association 79/04/27 lp
- 7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,144,151,161,164,170, 173,174,176,177,180,182,185,186,187,188,189,172,193,194,195,197,198,200,201,204,206,207,208,210,212,214,215,& others QUATTROCHHI, J American Nuclear Insurers 79/05/01 1p

- P Operating license stage documents & correspondence
- 7905080347 Assigns responsibility for prompt meeting notification re 790313 show cause orders STELLO, V Division of Operating Reactors 79/03/29 3pp
- 7903020490 Discussas 790315 telcon w/R Sero of Hestinghouse re incorrect weights for Velan Model C658 6-inch check valves used in safety injection sys BCHMEMCER, A Operating Reactors Branch 1 79/04/02 ip
- 7905240189 Forwards 790220 ltr requesting NRC to conduct hearing & prepare EIS on proposed replacement of steam generators Related Fr notice encl BENTON: H R Office of Nuclear Reactor Regulation 79/04/04 2pp
- --7905240199 Requests reconsideration of issuance of license Amends 46 & 47 for replacement of steam generators Also requests public hearing & EIS
  BERICK.D., ALVAREZ.B. Environmental Policy Institute 79/02/20
- --7909240204 Notification of "Director's Decision under 10CFR2 205," denying request for public hearing & EIS preparation resteam generator repair program DENTON.H R Office of Nuclear Reactor Regulation 79/04/04 Bpp
- 7903300010 Eummary of 790404 meeting w/S&W & util in Boston,MA re sequential operations of safety sys required to reach shutdown in all conditions & pipe sys stress reanalysis NEIOHBORS.D Operating Reactors Branch 1 79704/06 Spp
- 7905100158 Responds to 790330 ltr re analysis of piping sys per 790313 show cause order Use of soil structure interaction techniques in calculation of amplified response spectra is acceptable if appropriate documentation is included STELLO.V Division of Operating Reactors 79/04/13 2pp
- 7905100073 Requests review, mod & testing plans relaction taken to correct design deficiency identified in electrical load study Suggests application for appropriate license amend be made as soon as possible VOLLMER, R. H. Assistant Director for Systems & Projects 79/04/16
- 7905150789 Summary of 790419 meeting w/S&W & util in Boston, MA re review of gipe stress analyses NEIGHBORS.J D Operating Reactors Branch 1 79/04/24 5pp
- 7905310472 Summary of 790419 meeting w/S&W & util in Boston, MA re review of pipe stress analyses NEIGHBORS, J D Operating Reactors Branch 1 79/04/24 Spp
- 7905040468 Forwards VEP-FRD-32, "Surry Unit 2.Cycle 4 Core Performance Rept " THOMAS, W N Virginia Electric & Power Co 79/04/27 ip
- --7905040472 "Surry Unit 2.Cycle 4 Core Performance Rept "
  ROSS,T K , LEBERSTEIN.J H Virginia Electric & Power Co
  VEP-FRB-32 79/04/30 47pp
- 7905040615 Forwards status rept on 790427 "Plan for Verification of Dynamic Analysis Codes."

  JACOBS, S B Stone & Webster Engineering Corp 79/04/27 2pp
- 7903070473 Notifies that two completed pipe stress problems were sent to contractor subsequent to 790419 meeting Specific info encil SPENCER.W C Virginia Electric & Power Co 79/04/27 2pp.
- 7905040036 Believes recordiseping requirements should be modified to agree w/ASME Section XI Code requirements Change to Tech Specs 6 5 B 7 designated as suppl to encl Change 66 STALLINOS.C M Virginia Electric & Power Co
- 7905040380 Notifies that steam generator replacement program initial progress rept for 790203-0331 is being prepared Reporting period should cover two months rather than 60 days STALLINGS.C.M Virginia Electric & Power Co
- 7703070610 Responds to 770413 ltr Forwards summary of soil structure interaction analyses, summary of subgrade mat1 properties & damping valves which were calculated by Shake Program Summary of sample pips stress analyses

  BPENCER. W C Virginia Electric & Power Co 77/05/02. Sipp
- 7905070637 Requests NRC recommand to Commissioners that Unit 1 be returned to ave immediately Util will supply any supportive technical presentations deemed necessary BTALLINDS, C.M. Virginia Electric & Power Co. 79/05/02

- 7905070460 Responds to NRC 790222 ltr requesting add1 info re environ qualification texting performed on continental instrument cable presently in use

  0'REILLV.J P Virginia Electric & Power Co 79/05/03 19pp
- 7905080538 Forwards additinfo re organizational chart to support proposed Tech Specs Change 71
  STALLINGS.C M Virginia Electric & Power Co 79/05/04 2pp
- 7705300751 Responds to 790320 telegram re shutdown of units NRC ravies of pipe stress levels will be limited to safety considerations
  DENTOR; H R Office of Nuclear Reactor Regulation 77/05/04 2pp
- .....
- ---7905300756 Comments on areas of concern re shutdown units Urgas prequantlysis of effects of shutdown SHARMON.P C Virginia, State of 79/03/20 3pp
- 7905140239 Forwards proprietary documents requested during 790501-C4 special insp ERLEMINE, J.A. Stone & Webster Engineering Corp. 79/05/00 lp
- --7905140243 Requests withholding Technical Guideline EMT0-22-0 & Technical Rept EMTR-612 (ref 100FR2 790) Affidavit and KENNEDY,H J Stone & Hebster Engineering Corp 79/05/04 10);
- 7905140382 Confirms 790504 telcon w/HT Russell re computer deck associated w/SHOCK O program KENNEDY.W J Stone & Webster Engineering Corp 79/05/09 ip
- 7905160335 Notifies that review of computer dack is completed SHOCK 0 program still unrecovered Piping sys conservatively designed & will perform intended function
  KENNEDY.W J Stone & Webster Engineering Corp 79/05/11 lp
- 7705210111 Forwards SHOCK 1 computer program listing Supersedes submittal of 790406 Program listing withheld (ref 10CFR2 790)
  KENNEDY.W J Stone & Webster Engineering Corp 79/05/14 Lp
- 7905290335 Summarizes procedures & calculational techniques used
- 7905290335 Summarizes procedures & calculational techniques used in reanalysis of piping sys designed w/SHDCK II computer program Reanalysis will satisfy 790313 order to show cause KENNEDY. H J Stone & Hebster Engineering Corp 79/03/18 6pp
- 790525010B Submits corrections to 780920 proposed Tech Spac Change 73 re listing of hydraulic shock suppressors
  STALLINGS, C.H. Virginia Electric & Power Co. 79705/22 1p
- 7905250092 Submits response to 790518 request for info concerning review of methodology in use of oil structure interaction EPENGER.W C Virginia Electric & Power Co 79/05/24 33pp
- 7905280132 Submits add1 info in response to 790402 request re safety sys analyzed by SHOCK II code, pipe stresses & verification of dynamic analysis codes Info relates to 790313 order to show cause
  SPENCER, W.C. Virginia Electric & Power Co 79/05/24 9pp
- 7905290001 Resubmits 761230 Tech Spec change request as Change 24 No unraviewed safety question involved STALLINGS,C M Virginia Electric & Pawer Co 79/05/24 16pp
- G Inspection reports. IE Buildtins & correspondence
- 790302004D Forwards IE Insp Repts 80-280/79-10 & 50-281/79-12 on 790214-16 No noncompliance noted LEHIG:R C Region 2. Atlanta, Reactor Operations Nuclear Supecit Branch 79/03/12 2pp.
- --7909020049 IE Insp Repts 50-280/79-10 & 50-281/79-12 on 790214-16 Na noncompliance noted Major areas inspected protection of components in containment, tag out practices, long-term layup & temporary ventilation ELROD, S.A. Region 2, Atlanta, Office of the Director CANTRELL, F S. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/09 App
- 7905020012 Forwards IE Insp Repts 30-280/79-02 & 50-281/79-02 on 790102-0202 No noncompliance noted LEHIS.R C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch 79/03/13 2pp
- ---7905020019 IE Insp Repts 50-280/79-02 5 50-281/79-02 on 790102-0202 w noncompliance noted Hajor areas inspected plant physical barriers & preparations for steam generator replacament BURKE.D. J Region 2: Atlanta, Office of the Director CANTRELL.F 8 Region 2: Atlanta, Reactor Operations Nuclear Bupport Branch. 79/03/12 9pp.

- 7905010224 Forwards If Info Notice 79-06: "Stress Analysis of recordent recorded in them worded 79-06, "Utrass Analysis o Bafety-Related Piping" CYRFILEY.J.P. Region 2, Atlanta, Office of the Disortor 79/03/21 2pp
- 7709010123 Forwards II Info Notice 77 OD, "Interrossection of Contaminated Bys W/Bvc Air Sys Used as Hource of Breathing Air " DACTELYOUR Region 2. Atlanta, Office of the Director
- 7907010 169 Farwards II Info Notice 79 09, "Spill of Hadinactively Contaminated Resin O'REILLY J P Re 79/07/30 2pp Region 2. Atlanta, Office of the Director
- 7903020023 Forwards II first Repts 50 2007/9 to 6 50 2017/9 16 nn 790321 24 No noncompitance moted RENNAR B Region 2, Atlanta, Dafeguards Dranch 79704/11 2pp
- 7909020033 If Insp Rept 70 200779 If 5 70 201779 If on 790321 21 No-moncompliance inited Major area inspected independent insp effort re-1008870 B5 interim measures Details withheld Cref 100182 770)
  HENNIOSLY,N J. Negion & Atlanta, Office of the Director
  TOBINGH J. Region 2: Atlanta, Dafeguarda Branch. 79704
- 7909080534 forwards II Hullstin 79 O.S. "Neview of Operational Piruns & Oys Misalignments identified During TMI Incident " filenses action required D'HERLY, J.P. - Hagion & Atlanta, Office of the Birettor
- 7908040454 forwards it Dulisten 79 Ord, "Neview of Operational Livers & fig. Hisalignments identified During TH3 listident " O'RELLLY, J.P. Hegion J. Atlants, Office of the Director 77704714 Jap
- 7907040271 Potwards II Bulletin 79 02. "Heismir Bittess Analysis of Bafety Related Piping." Licenses action required O'REILLY, J.P. Region 2: Atlanta, Office of the Director 79204714. [p]
- 7908040448 Forwards IV Birklettin 79 OB. "Events Relevant to Botling Hater Power Reacture Identified During THI Incident "O'ULILLY, IP Region & Atlanta, Office of the Director 79704714 Ip
- 79050B0164 Responds to II Bulletin 79 0% "Lungitudinal Held Defects in ASMI DA 312 Type 104 Chainless Steel Pipe Options Hig by Youngstown Helding & Engineering Co \* North Anna Luses no BA 312 piping Shirty 1 & Petrods are \$111 under review OTALLINOSIC M. Virginsa Cleakers & Mower Co. 79704786. Upp
- 7905030191 Forwards II Hullstin 79 (19, "Parluies of Qt Type AK & Circuit Breaker in Bafaty Related Bys " Licensee Action required D'RCILLY: J P 79/04/17 2p Hagion R. Atlanta. Office of the Director
- 7905020496 Furwards IP Bulletin 29-OhAcHevisson I. "Review of Operational Errors & Bys Hisalignments Identified During THI Incident " O'RETLLY, J. P. Hagion J. Atlanta, Office of the Director 79/04/10
- 7705700520 Informs that reponse to EC Bulletin 79:07 re selected analysis of safety related piping will be provided in conjunction wherder to show ceuse did 770713

  BPENCER. H. C. Vinginia Electric 4 Power Co. 79704723 | Ip
- 7905240181 Responds to IC Bullatin 79 OSA. "Neview of Operational Errors & Bys Misationments identified During IM1 Incident "Review Committee was established & detailed review of IM1 OTALLINGS, C.M. Virginia Electric & Power Co. 79/04/36 Yep.
- 7905300706 Porwards response to IR Bulletin 79-04 Value awing check valves of three & sir inches installed in chemical vol & control & safety injection eye BTALLINGS, C.M. Virginia Electric & Power Co. 29/05/03 App
- 79052102/5 Responds to IE Bulletin 74-06A, Revision 1 Provides requested info on design changes to containment sums pump trip valve actuation & safety injection logic STALLINGS.C.H. Virginia Electric & Power Co. 79/05/17 2pp

- 7905220142 Forwards requested relief from inservice insp requirements for Class 1.2 & 3 components & requested relief from inservice testing requirements for pumps W/29 oversized OTALLINGS, C. H. Virginia Flectiic & Power Co. 79/05/17 109ec
- 7905290032 Responds to 1E Bulistin 79-09 QE Type AK-2 circuit breakers not in use or planned for use GTASI INOS: C.H. Virginia Electric & Power Co. 79/05/23 ip
- 7905300010 Responds to IF Bullatin 79-10 Forwards requalification training program statistics. STALLINGULE H. Virginia Flectiic & Power Co. 79705724 Spp.
- 7905700 H2 Responds to If Imap Rept 50-2017/9 30 fiteam generator cutting method & description of decontamination procedure BIALLINGS. C. M. Virginia Fluctric & Pawer Co. 79705/25 Ip
- R Periodic operating reports & related correspondence
- 7905110007 Forwards "Steam Generator Repair Program Progress Rept 1" for 790201 7903 EL UKALLINGO C. M. Virginia fileritric & Power Co. 79705700 1p
  - 790%110000 "Oteam Generator Repair Program Progress Rept 1" for 770201-0111 Virginia Elsitite & Power Co. 7970-3731 13up
- 2905150510 Forwards monthly operating rept for Apr 1979 BIALLINGS: N. Virginia Cleritic & Power Co. 79705710 ip
- 7909190919 Bunthly operating tept for Apr 1979 BTEWARTED Mirginia Liettys & Power Co. 79 79/05/01 30pp

B. Reportable occurrences, Like & related correspondence

- 7905020512 Forwards till 29 0092017 0 BYALLINGS,C N Virginia flattric & Power Co 79204226 ta
- -79050J0519 IER 79 0097017 0 on 790412.00 informed util that potential problem exists in inside restrictiation spray pump motors Gaused by possible overheating of lower hearing due to clearance tolorunces allowed on end shields & shaft dishada. M. Urginia blockets & Power Gr. 29/04/26 Qr.
- 7905010492 Forwards LER 79 OLLYON O HTALLINGS: ( M. Virginia Clerkric & Power Co. 7970472) Ep
- 7905010490 till 79 01170 it 0 on 790°120 while in cold shotdown-gasenus moniture process vent particulate & ventilation vant particulate were w/o gower Gaused by Inose log consection on power supply cable log connection repaired

  Bibliant. Ni. Virginia Electric & Power Co. 77/04/2/ App.
- /905040196 Forwards tin // 012/03(-0)
  HYALLINOSC H. Virginia Lisctric & Power Co. 79/05/03
- 7903040414 LER 79:012/03.-0 on 790402 during function test:21 of 74 enubbers did not meet acceptance criteria stipulated in governing procedure Caused by failure to readjust snubbers to options design condition failed anubbers reset OTHART-MI. Virginia Electric & Power Co. 79/03/02 Opp.
- 7905070655 Forwards "Analysis & Bys Hod for 480 Volt Cmergence Bys." in response to NRC 790416 ltr STALLINGS.C M. Virginia Electric & Power Co. 79705/01
- ---7905070857 "Analysts & Bys Mod for 480 Volt Emergen W Vinginia Slectric & Power Co 29705703 24pr
- /905110157 Forwards LER /9 013/03:-0 BTALLINGS, C.H. Virginia Clectric & Power Co
- -79031(0)64 LER 79:010/03L=0 on 7904(0 100 g recovery test tank 1 BR-7K=20 prior to o' results Caused by improser valve lineup recirculation in preparation for samp! OTEMART.H L. Virginia Electric & Po-
- 7703190119 Forwards LER 79-017/017-

- --7905190123 LER 79-017/017-0 on 790502 problem could develop in thrust bearing of turbocharger for emergency diesel generators under repeat start operating modes Engineering design problem occurs only under restrictive conditions
  STENART.H L Virginia Electric & Power Co 79/05/15 3pp
- 7905250141 Forwardt LER# 79-014/03L-0,79-015/03L-0 & 79-016/03L-0 BTALLINGS: C M Virginia Electric & Power Co 79/05/22 1p
- --7905250150 LER 79-014/03L-0 on 790422 liquid waste disposal radiation POSSOCIOU LER 77-014/051-V on 700422 Hot Wasse Prepared nonftor failed to give high alarm & trip release valve Caused by instrument drift in high alarm setpoint All liquid waste releases were secured & alarm board checked STEMART. H L Virginia Electric & Power Co 79/05/22 2pp
- --7905250154 LER 79-015/03L-0 on 790422 liquid waste disposal radiation monitor failed to give high alarm & trip release valve Caused by procedural (nadequacy Procedures modified STEWART,W L. Virginia Electric & Power Co. 79/05/22 2pp
- --7905250157 LER 79-016/03L-O on 790425 cracks noted in concrete support for 1-RK-E-1A & 1-RH-E-1B Caused by thermal expansion of heaf exchanger Cracks repaired Heat exchanger supports will be modified to alkow for thermal expansion STEHART.H L Virginia Electric & Power Co 79/05/22 2pp
- 7905290005 Forwards LER 79-018/01T-0 STALLINOS.C H Virginia Electric & Power Co. 79/05/23 1p
- --7905270010 LER 79-018/01T-D on 790509 solenoid valve Model 8320A102 mfg
  by Automatic Switch Co found environmentally unqualified &
  reportable per IE Bulletin 79-01 & Tech Specs Valve could
  fail to control admission & venting of air during LOCA
  STENART,N L Virginia Electric & Power Co 79/05/23 2pp

DOCKET 50-281 SURRY POWER STATION, UNIT 2 Q Adjudicatory correspondence

- 7905230646 Orders extension, until 790524, for NRC review of 790404 denial of enforcement action
  CHILK:8 J Office of the Secretary of the Commission 79/04/13
- 7905100262 Forwards petition of Potomac Alliance et al for emergancu & remedial action
  DOUGHERTY, J 8 Potomac Alliance 79/04/18 2pp
- --7905100328 Patition for emergency & remedial action re NRC violations of NEPA in issuing Amends 46 & 47 to OL DOUGHERTY, J B Potomac Alliance 79/04/18 65pp.
- 7905240495 Ack receipt of 790405 ltr requesting NRC to revoke OLs Ltr is currently under consideration Forwards FR notice re Allen 790405 ltr DENTON, H. R. Office of Nuclear Reactor Regulation 79/05/04 1p
- --7905240461 FR notice re J Allen 790405 request for revocation of OLs DENTON: R Office of Nuclear Reactor Regulation. 79/05/04 2pp
- 7905310033 Forwards J Allen 770405 itr requesting NRC revoke facility OLS & FR notice of revocation request W/790330 itr to ASLAH re-Hastinghouse ECGS deficiency DENTON-M.R. Office of Nuclear Reactor Regulation 79/05/04 3pp
- J. Insurance & indemnity information
- 7905110107 Amend to Endorsement S1 to NELIA Policy NF-186 Constitutes Endorsement 54 Nuclear Energy Liability Insurance Association 79/04/27. 1p.
- 7905110107 Amend to Endorsement 51 to NELIA Policy NF-186 Constitutes Endormement 54. • Nuclear Energy Liability Insurance Association 79/04/27. ip
- 7905070497 Confirms increased liability limit to #124,000.000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,185,186,187,188,189,192,193,194,195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, 5 other GUATTROCHHI, J. American Nuclear Insurers 79/05/01.
- 7905070382 Confirms increase in liability limit to 436,000,000 for policies HF-22.26,29.38,39,44,44,47,49,50,51,52,53,54,55,56,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,71,92,93,94,95 & 6, ROBERTS

- 7905110090 Endorsements 16:30.36 & 47 to NELIA Policy NF-186 BARDES.C R Nuclear Energy Liability Insurance Association 79/05/01 ip
- 7903140444 Forwards Amend 10 to Indemnity Agreement 8-45 per ICCFA(t) changes, re increase in liability insurance from \$140 million to \$160 million, effective 790501 Supporting documentation Antitrust & Indemnity Group 79/05/01
- 7903240485 Forwards executed Amend 10 to Indemnity Agreement B-45, affective 790518
  BTALLINGS, C M Virginia Electric & Power Co 79/05/21 3pp
- P. Operating license stage documents & correspondence
- 7905080347 Assigns responsibility for prompt meeting notification re 790313 show cause orders BTELLO,V Division of Operating Reactors 79/03/29 3pp
- 7908020490 Discusses 790315 telcon w/R Sero of Westinghouse re incorrect weights for Velan Model C658 6-inch check valves used in safety injection sys Operating Reactors Branch 1 79/04/02 is
- 7905240189 Forwards 790220 ltr requesting NRC to conduct hearing to prepare EIS on proposed replacement of steam generators Related Fr motice encl DENTON.HR Diffice of Nuclear Reactor Regulation 79/04/04 2pp
- ---7905240199 Requests reconsideration of issuance of license Amends 451
  47 for replacement of steam generators Also requests public
  hearing & EIS BERICK, D . ALVAREZ, B Environmental Policy Institute 79/02/20
- ---7905240204 Notification of "Director's Decision under 10CFR2 204."
  denying request for public hearing & EIS preparation resteam generator repair program
  DENTON:H R Office of Nuclear Reactor Regulation 79/04/04 By
- 7905300010 Summary of 790404 meeting w/S&W & util in Boston HA re sequential operations of safety sys required to reach shutdown in all conditions & pipe sys stress reanalysis. NEIOHBDRS,D Operating Reactors Branch i 79704/06 Spp
- 7905:00:58 Responds to 7903:0 itr re analysis of piping sys per 7903:3 show cause order Use of soil structure interaction techniques in calculation of amplified response spectra is acceptable if appropriate documentation is included STELLO, V Division of Operating Reactors 79/04/13 2pp
- 7903100073 Requests review mod & testing plans relaction taken to correct design deficiency identified in electrical load study Buggests application for appropriate license amend be made as soon as possible VOLLMER.RH Assistant Director for Systems & Projects 79/04/th
- 7905040468 Forwards VEP-FRD-32. "Surry Unit 2. Cycle 4 Core Performants Rept "
  THOMAS: N Virginia Electric & Power Co 79/04/27
- ---7903040472 "Burry Unit 2.Cycle 4 Care Performance Rept "
  ROSS,T K , LEBERSTEIN,J H Virginia Electric & Power Co
  VEP-FRD-32 79/04/30 47pp.
- 7905040615 Forwards status rept on 790427 "Plan for Verification of Dynamic Analysis Codes "
  JACOBS, B. B. Stone & Webster Engineering Corp., 79/04/27 25p
- 7905070473 Notifies that two completed pipe stress problems were sent to contractor subsequent to 790419 meeting. Specific info SPENCER.W.C. Virginia Electric & Power Co. 79/04/27 2pp
- 7705040036 Believes recordkeeping requirements should be modified to agree w/ABME Section XI Code requirements, Change to Tech Specs 6 5.8 7 designated as suppl to encl Change 66 BTALLINGS, C M Virginia Electric & Power Co 79/05/01 4pp
- 7705040380 Notifies that steam generator replacement program initial progress rept for 790203-0331 is being prepared Reporting period should cover two months rather than 60 days BTALLINOS.C M. Virginia Electric & Power Co

- 7905070610 Responds to 790413 ltr Forwards summary of soil structure interaction analysms, summary of subgrade mati properties & damping valves which were calculated by Shake Program Gummary of sample pipe stress analyses

  SPENCER, N C Virginia Electric & Power Co 79/05/02 Sipp
- 7905070637 Requests NRC recommend to Commissioners that Unit 1 be returned to svc immediately Util will supply any supportive technical presentations depmed necessary BTALLINGS.C M Virginia Electric & Power Co 79/05/02 2pp
- 7705270405 Notification of 770303 meeting w/util in Bethesda.MD to discuss startup NEIGHBORE,D Operating Reactors Branch 1 77/05/02 1p
- 7905070460 Responds to NRC 790222 ltr requesting addl info re environ qualification testing performed on continental instrument cable presently in use O'REILLYJP Virginia Electric & Power Co 79/05/03 19pp
- 7903080538 Forwards addl info re organizational chart to support proposed Tech Spacs Change 71
  STALLINOS.C M Virginia Electric & Power Co 79/05/04 2pp
- 7403300751 Responds to 740320 telegram re shutdown of units NRC review of pips strass levels will be limited to safety considerations
  DENTON.H R Office of Nuclear Reactor Regulation 7405/04 2pp
- --7705300756 Comments on areas of concern re shutdown units Urges prompt analysis of effects of shutdown SHANNON.P C Virginia, State of 79/03/20 3pp
- 7905140239 Forwards proprietary documents requested during 790501-04 special intep ERLEMINE, J A Stone & Webster Engineering Corp 79/05/08 1p
- ---7905140245 Requests withholding Technical Guideline EMTG-22-0 & Technical Rept EMTR-612 (ref 10CFR2 790) Affidavit encl KENNEDY: H J Stone & Webster Engineering Corp 79/05/04 10pp
- 7905140382 Confirms 790504 telcon w/HT Russell re computer deck associated w/SHOCK O program KENNEDY.H J. Stone & Webster Engineering Corp 79/05/09 1p
- 7905160335 Notifies that review of computer deck is completed SHOCK O program still unrecovered Piping sys conservatively designed & will perform intended function KENNEDY: W J Stone & Webster Engineering Corp 79/05/11 lp.
- 7905210111 Forwards BHOCK 1 computer program listing Supersedes submittal of 790406 Program listing withheld (ref 10CFR2 790) KENNEDY; W J. Stone & Webster Engineering Corp 79/05/14 1p
- 7903270335 Summarizes procedures & calculational techniques used in reanalysis of piping sys designed w/BHOCK II computer progrem Reanalysis will satisfy 790313 order to show cause KENNEDY, W. J. Stone & Webster Engineering Corp 79/05/18 ópp
- 7905250108 Submits corrections to 780920 proposed Tech Spec Change 70 re listing of hydraulic shock suppressors STALLINGS.C.M. Virginia Electric & Power Co 79/05/22 ip.
- 7908230092 Submits response to 790518 request for info concerning review of methodology in use of oil structure interaction SPENCER, W. C. Virginia Electric & Power Co. 79/05/24. 33pp
- 7705230132 Submits add1 info in response to 770402 request re safety sys analyzed by SHOCK II code pipe stresses & verification of dynamic analysis codes Info relates to 770313 order to show cause.

  SPENCER.W C Virginia Electric & Power Co. 77/05/24. 9pp
- 7905290001 Resubmits 761230 Tech Spec change request as Change 24 No unreviewed safety question involved. BTALLINGS.C M Virginia Electric & Power Co 79/05/24 16pp
- @ Inspection reports, IE Bulletins & correspondence
- 7905020040 Forwards IE Insp Repts 50-280/79-10 & 50-281/79-12 on 790214-16 No noncompliance noted. LEWIB.R.C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch 79/03/12. 2pp.

- --7903020049 IE Insp Repts 50-280/79-10 & 30-281/79-12 on 790214-16 No noncompliance noted Major areas inspected protection of components in containment, tag out practices, long-term layup & temporary ventilation ELROD.8 A Region 2, Atlanta, Office of the Director CANTRELL.F B Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/09 4pp
- 7903020012 Forwards IE Insp Repts 50-280/79-02 & 50-281/79-02 on 790102-0202 No noncompliance noted LEWIB.R C egion 2. Atlanta. Reactor Operations Nuclear Support Branch 77/03/13 2pp
- --7905020019 IE Insp Repts 50-280/79-02 & 50-281/79-02 on 790102-0202 No noncompliance noted Major areas inspected plant physical barriers & preparations for steam generator replacement BURKE,D J Region 2. Atlanta, Office of the Director CANTRELL,F S Region 2. Atlanta, Reactor Operations Nuclear Support Branch 79/03/12 9pp
- 7905070115 Forwards IE Insp Rept 50-281/79-11 on 790213-16 No noncompitance noted MURPHY(C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79703/19 2pp
- ---7905070118 IE Insp Rept 50-281/79-11 on 790213-16 No noncompliance noted Major area inspected steam generator replacement WILCOX, J D , KERDT, A R Region 2. Atlanta. Reactor Construction & Engineering Support Branch 79/03/14 3pp
- 7905010224 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
  O'REILLY, J P Region 2, Atlanta, Office of the Director 79/09/23
- 7705030319 Forwards IE Info Notice 79-07, "Rupture of Radwasta Tanks " O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/26 2pp
- 7905010123 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Bys w/8vc Air Sys Used as Bource of Breathing Air " O'REILLY, J P 79/03/28 2pp
- 7905010369 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin" 0'REILLY, JP Region 2. Atlanta, Office of the Director 79/03/30 2pp
- 7905020025 Forwards IE Insp Repts 50-280/79-13 & 50-281/79-16 on 790321-23 No noncompliance noted KENNA,W B Region 2, Atlanta, Safeguards Branch 79/04/11 2pp
- ---7905020033 IE Insp Rept 50-280/79-13 & 50-281/79-16 on 790321-23 No noncompliance noted Major area inspected independent inspected for the incential state of the inspected (ref incential state) of the Director TOBIN.M J Region 2, Atlanta, Diffice of the Director for No. 10 Region 2, Atlanta, Bafeguards Branch, 79/04/11 ip
- 7905080834 Forwards IE Bullatin 79-06, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident" Licensee action required

  O'REILLLY P Region 2: Atlanta, Office of the Director
  77/04/11. 1p
- 7905040234 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Bys Misalighments Identified During TMI Incident "
  O'REILLLY, J P Region 2. Atlanta, Office of the Director, 79/04/14 2pp
- 7905040271 Forwards IE Bullstin 79-07, "Seismic Stress Analysis of Safety-Related Piping " Licensee action required, O'REILLY, J. P. Region 2, Atlanta, Office of the Director, 79/04/14 ip.
- 7903040448 Forwards IE Bullstin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident " D'REILLY-J.P Region 2. Atlanta. Office of the Director 79/04/14. | 19
- 7905080164 Responds to IE Bulletin 79-03. "Longitudinal Held Defects in ABME 8A-012 Type 304 Stainless Steel Pipe Spools Mfg by Youngstown Helding & Engineering Co." North Anna 1 uses no SA-012 piping, Surry 1 & 2 records are still under review.

  8TALLINGB, C. M. Virginia Electric & Power Co. 79/04/16. 2pp.

- The long of the state of the Bulletin 79-07 "Fasiones of GE Type AK-2 for it fragger in "afely-Related Bye" Litansee action required for the Region 2 Atlanta, Office of the Director related for the state of the director related for the state of the director related for the state of the stat
- re, \_ nain Figure 18 Bulletin 79-06A Revision i, "Revieu of operational Engine % E,a Misalignments Identified During TMS Im iden 1 no process of the Director Ty(4/14) | Zop
- . 11.350 Informs that reponse to IE Builetin 79-07 re seismic analysis of safety-related pigning will be provided in rengalition winder to show cause est 790313 cp. CEM.EF NO. Virginia Electric & Power to 79/04/23 to
- pumbers to the sounds to the Bulletin 79-06A "Revieu of Operational Extens to fix Misalignments Identified Dyring TMI incident" Review rosmattee was established to detailed review of TMI incident has been completed of the stability of TMI through the sound to the sound of TMI STALLINGS IM Virginia Electric to Power Co. 79/04/26 STALLINGS IM.
- Printipolate Ack receipt of 790412 itr informing NRC of steps taken to rings violations noted in IE Insp Rept 50-281/79-08 MCPMY C E Region 2: Atlanta, Reactor Construction & Engineering Bijpart Branch 79/05/01 ip
- 7905190372 Personds to IAC 790320 Itr re violations noted in IE Insp Papt 50-201/79-08 Corrective actions installation of fire protection header is in progress BTALLINGS CN Virginia Electric & Power Co 79/04/12 Opp
- -7535279333 Forwards IE Inso Rept 50-281/79-08 on 790213-18 & notice of \*tolation
  #USPH: C.E. Region 2 Atlenta, Reactor Construction b
  Engineering Support Branch 79/03/20 2pp
- --1435293392 Matice of violation from imag on 790213-16
  Region 2. Atlanta, Office of the Director 79/03/19 1p
- --1935290378 IE Insp Rept 50-281/79-08 on 790213-16 Noncompliance noted idea of fire protection sys & equipment for const area contairment & Jack of organized const site fire brigade for steam generator repair program MILLER, M M Region 2. Atlanta. Office of the Director BRYANT, J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 79/03/19 Spp
- 7403300706 Forwards response to IE Bulletin 79-04 Velan swing check calves of three & six inches installed in cheaical vol & control & safety injection sys

  BTALLINGS C N Virginia Electric & Power Co 79/05/03 4pp
- 7903210275 Responds to IE Bulletin 79-06A, Revision I Provides requested info on design thanges re containment sump pump trip valve actuation & safety injection logic STALLINGS. C. M. Virginia Electric & Power Co. 79/05/17 Zpp

- S Reportable occurrences, LERs & related correspondence
- 7905010484 Forwards LER 79-011/12T-D 8TALLINOS.C H Virginia Electric & Power Co 79/04/27 1p
- ---7905010487 LER 79-011/12T-O on 790414 individual received excession dose while inspecting area beneath vessel Caused by elevated radiation levels due to incore instrumentation refueling status Individual disciplined BTEMART.W L. Virginia Electric & Power Co. 79/04/2/ Spp.
- 7905070655 Forwards "Analysia & Bys Mod for 480 Volt Emergency Fowar Sys," in response to NRC 790416 its BTALLINGS,C M Virginia Electric & Powar Co 79/05/0J tp
- --7903070687 "Analysis & Bys Mod for 480 Voit Emergency Power Eys '

  \* Virginia Electric & Power Co 79/03/03 24pp
- 7905230341 Forwards LER 79-012/08T-0 STALLINGS,C M Virginia Electric & Power Co 79/05/21 1p
- ~-7905230344 LER 79-012/08T-0 on 790507 coustic residua discoverat \*\*
  62 new fuel assemblies Caused by industrial substage
  Fuel removed % assemblies rinsed Investigation continuing
  STEMART.N L Virginia Electric & Power Go 79/05/21 2pp
- 7905290005 Forwards LER 79-018/017-0 STALLINGS,C M Virginia Electric & Power Co 79/08/23 19
- --7905290010 LER 79-018/01T-0 on 790909 malenoid valve Hodel 10127A1C3 14 905290010 LER 79-018/017-0 on 7909009 solenoid valve modes aby Automatic Buitch Co found onvironmentally unqualified by by Automatic Buitch Co found onvironmentally unqualified to reportable per lE Builetin 79-01 & Tach Bpecs Valve could fail to control admission & venting of air during LOCA STEMART, N.L. Virginia Electric & Pawer Co 79/09/23 &p.
- DOCKET 50-282 PRAIRIE ISLAND NUCLEAR STATION, UNIT 1 F Security, medical, emergency & fire protection plans
- 7905070459 Forwards info requested in NRC 790206 ltr re file protection outline encl MAYER.L O Northern States Power Cq 79705702 18pp
- 7905300406 Forwards supplemental info on status of security plan (mplementation info withheld tref IOCFR2 790) MAYER, LD Northern States Power Co 79/03/25 1p
- I Financial information
- 7905150225 Forwards "Financial & Statistical Info" as suppl to "Arc.al Financial Rept 1978 " BRUSVEN.A D Northern States Power Co 79/09/10 ip
- ---7903(30,23) "Financial & Statistical Info," submitted as suppl to "Annual Financial Rept 1978 "

  \* Northern States Power Co 79/03/31 21pp.

1 p

- 7905010474 Forwards application for amend to Licenses DPR-42 & DPR-60, changing Tech Specs re pressurizer initiating signals f mafaty injection signals Amend fee & proposed Tech Spec changes encl Northern States Power Co 79/04/26 10pp
- 7905020462 Forwards ambient sound level survey in response to recent J Lehr request for add1 info re ETS WARD, C C Northern States Power Co 79/04/27 2pp
- 7905010479 Forwards amend fee of \$4,400 for Licenses DPR-42 & DPR-40 \$ Northern States Power Co 79/05/01 1p
- 7905140214 Bubmits Environ Evant Rept 79-03 for 790424-0502 discharge canal gate structure under water, rendering control & monitoring of blowdown flow inoperable WARD, E.C. Northern States Power Co. 79/05/08 ip
- P Operating license stage documents & correspondence
- 7905020490 Discusses 790315 telcon w/R Sero of Westinghouse re incorrect weights for Velan Model C658 6-inch check valves used in safety injection sys SCHMENCER: A Operating Reactors Branch 1 79/04/02 ip
- 7905020236 Forwards PWRPTS computer code input & affidavit requesting exemption from public disclosure Computer code input withheld (ref lOCFR2 790) MAYER.L O Northern States Power Co /9/04/18 35pp
- 7905240300 Forwards Amonds 35 & 29 to Licenses DPR-42 & DPR-60, respectively, safety evaluation & notice of issuance & availability Operating Reactors Branch 1 79/04/20 3pp BCHWENGER, A
- --7905240322 Amends 35 % 27 to Licenses DPR-42 % DPR-60, respectively, changing common station Tech Specs re refueling & incorporating changes to App A Tech Specs to support operation in Gycle 5 w/reload fuel by Exxon Nuclear Co GCHWENCER, A Operating Reactors Branch ( 79/04/20 19pp
- --7905240029 Bafety evaluation supporting Amends 35 & 29 to Licenses DPR-42 & DPR-60 respectively # Office of Nuclear Reactor Regulation 79/04/20 19pp
- --7905240333 Notice of issuance & evaluability of Amends 35 & 29 to Licenses DPR-42 & DPR-60 respectively. SCHWENCER: A Operating Reactors Branch 1 79/04/20 3pp
- O Inspection reports. IE Bulletins & correspondence
- 7905010262 Forwards'IC Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
  KEPPLER, J Q. Region 3, Chicago, Office of the Director 79/03/23.
- 7905040040 Forwards IE info Notice 79-07. "Rupture of Radwaste Tanks "
  KEPPLER, J G. Region 3. Chicago, Office of the Director 79/03/26 La
- 7905090126 Forwards IE Insp Repts 50-282/79-06 \$ 50-306/79-06 on 790227-28 & 0301-02 DAVIG A B. Region 3, Chicago, Fuel Facility & Materials Bafety Branch 79/03/26 2pp
- --7905090131 IE Insp Repts 50-202/79-06 & 50-306/79-06 on 790227-28 & 0301-02. No noncompliance noted Hajor areas inspected emergency plan emergency facilities equipment & supplies, radioactive efficent sys & emergency training DESTMANN.M J. EBSIO.T H. Region 3. Chicago. Office of the Director 79/03/20 App
- 7905010174 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Bys w/Syc Air Bys Used as Source of Breathing Air " Region 3. Chicago. Office of the Director 79/03/28 AIT H KEPPLER, J. G.
- 7705010410 Forwards IE Info Notice 79-09, "Spill of Radioactively Region 3, Chicago, Office of the Director 79/03/30. Contaminated Resin KEPPLER, J. C. Re-
- 7905070344 Responds to IE Bulletin 79-03 All longitudinal welds of ASTM-A31 stainless steel piping 100% radiographed % free of defects. Additesting unnecessary MACHTER.L. J. Northern States Fower Co. 79/04/10 ip

- 7905030040 Forwards IE Bulletin 79-06. "Review of Operational Errors & Bys Misalignments identified During TMI Incident " Licensee action required KEPPLER.J G Region 3. Chicago, Office of the Director 79/04/11
- 7905010600 Forwards IE Bulletin 79-06A. "Review of Operational Errors & Bys Misalignment\* Identified during TMI Incident " Licensee action required (REPPLER.) G Region 3. Chicago, Office of the Director 79/04/14
- 7905040409 Forwards IE Bulletin 79-06B. "Review of Operational Errors & Bys Misslignments Identified During TMI Incident " KEPPLER, J O Region 3. Chicago, Office of the Director 79/04/14
- 7905040451 Forwards IE Bulletin 79-07. "Seismic Stress Analysis of Safety-Related Piping " Licensee action required KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14
- 7903040576 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident "
  KEPPLER, J C Region 3. Chicago, Office of the Director 79/04/14
- 7908030237 Forwards IE Sulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " Licensee action Region 3. Chicago. Office of the Director 79/04/17 KEPPLER J G
- 7905080505 Forwards IC Bulletin 79-058, "Nuclear Incident at TMI-Buppi " KEPPLER, J G Region 3. Chicago: Office of the Director 79/04/21
- 7905140100 Ack receipt of 790410 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-202/79-03 & 90-306/79-03 DAVIS.A B Region 3. Chicago, Fuel Facility & Materials Safety Branch 79/04/25 ip
- --7905140104 Respands to NRC 790323 ltr re violations noted in IE lnsp Repts 50-282/79-03 & 50-306/79-03 Corrective actions torque values were reduced & new bolts were retorqued to specified WACHTER, L J Northern States Power Co 79/04/10 2pp
- 7905290290 Responds to IE Bulletin 79-09 GE Type AX-2 breakers not in WACHTER, L.J. Northern States Power Co. 79/05/04 1p
- R Periodic operating reports & related correspondence
- 7905010509 Forwards monthly operating rept for Feb 1979 MAYER.L O Northern States Power Co 79/04/25 ip
- --7905010311 Monthly operating rept for Feb 1979 HUNSTAD:A A Northern States Power Co 79/03/01 2pp

790 H

- 7905030364 Forwards LER 79-009/01T-0 MAYER,L O Northern States Power Co 79/04/26 19
- --7905030367 LER 79-009/017-0 on 790412 notified by vendor that small break in pressurizer indicator Lp may hang up while Pp decreases, delaying safety injection Westinghouse recommends manually initiating safety injection implements HUNSTAD.A.A Northern States Power Co 79/04/26 ip
- 7905040521 RO 79-14 on 790427 fuel loading pattern of Cycle 5 core is in error. Core has not achieved criticality unit still in refueling shutdown Core loading pattern will be corrected. P Northern States Power Co 79/04/27 ip
- 7905080543 Ferwards LER 79-012/01T-0 MAYER.L O Northern States Power Co 79/05/02 ip

- --7905080569 LER 79-012/01T-0 on 790418 insp of Region 4 assemblies removed during refueling revealed rod bowing greater than previously discharged assemblies All Region 4 fuel has been discharged from core Vendor investigating HVNSTADLA A Northern States Power Co 79/05/02 ip
- 7903110127 Forwards LER 79-008/03L-0 MAYER, L O Northern States Fower Co 79/05/09 1pp
- --7905110131 LER 79-00B/OGL-O on 790408 safety injection pump 11 failed to start automatically started in manual Cause unknown Event could not be repeated Peasibility of monitor light to detect failures being studied HUNSTAD.A A Northern States Power Co 79/05/08 1p
- 7905160352 Forwards LER 79-010/03L-0 MAYER, L O Northern States Power Co 79/05/10 ip
- --7705160358 LER 79-D10/03L-0 on 770410 high head safety injection valve to reactor vessel, MV-32067, failed to open on demand Subsequent opening attempts were successful Cause of failure not found HANSTOD. A A Northern States Power Co 79/05/10 2pp
- 7903130466 Forwards LER 79-014/01T-0 MAYER, L O Northern States Power Co 79/05/11 ip
- --7909130468 LER 79-014/01T-0 on 790427 informed by Exton of error in core loading pattern specifically gaddlinia-bearing assemblies not properly located Assemblies repositioned on 790430 HUNSTAD, A A Northern States Power Co 79/05/11 ip

DOCKET 50-284 IDAMO STATE UNIV RESEARCH REACTOR

- J Insurance & Indemnity information
- 7905160334 Forwards Amend (1 to Indomnity Agreement E-49.per 10CFR140 changes.re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl SALTZMAN, J Antitrust & Indomnity Group 79/05/01, Spp
- 7905240604 Forwards executed Amend 11 to Indemnity Agreement E-49
  EASTMAN.P H Idaho State Univ 79/09/15 2pp

DOCKET 50-285 FORT CALHOUN STATION, UNIT 1

- F Security, medical, emergency & fire protection plans
- 905090046 Forwards revision to physical security plan Revision withheid (ref 100FR2 790) BHORT.TE Omaha Public Power District 79/05/03 1p

Financial information

- 905300349 Forwards "Annual Financial Rept 1978 "
  PETERBEN,H E Omaha Public Power District 79/05/22 ip
- -7908300353 "Annual Financial Rept 1978 "
  \* Omaha Public Power District 79/02/R3 31PP
- I Insurance & indomnity information
- '705070497 Confirms increased liability timit to \$124,000,000 for golicles NF-1,25,43,76,83,100,111,140,145,151,161,164,170,173,174,178,179,180,182,185,186,187,188,189,192,193,174,175,197,198,200,201,204,205,207,208,210,212,214,215,% others.

  GUATERCCHHI, J. American Natlear Insurers 79,05701 is
- '905160164 Forwards Amend 6 to Indemnity Agreement 8-67, per 10CFR140 changes: re liability insurance increase from \$140 million to \$160 million effective 790501 Supporting documentation and SALTZMAN.J Antitrust & Indemnity Group 79/05/01 Spp
- /905160382 Forwards Endorsements 33,36,37,38 & 39 to MAELU Policy MF-63 & Endorsements 39,40,41,42,43 & 44 to NELIA Policy NF-207, PETERSON,H & Omaha Public Power District 79/08/09 12pp.
- 7905160406 Forwards executed Amend & to Indemnity Agreement 8-67 PETERSEN.H E Omaha Public Power District 79/05/09 3pp
- P Operating license stage documents & correspondence
- 7905100251 "Gamma Dose Measurements at Zion & Fort Galhoun Stations" BYER,N C : BUNTING,R,L : NIEGCHMIDT,E B. EG & Q: Inc FIN A-6075 NUREG/CR-0755 79/04/30 137pp Available at NTIS. \$7 25

- 7905090317 Forwards responses to Questions i & 2 re auxiliary feetzal; sys Response to Question 3 will be submitted by 790503 MORRIS.K, J. Omaha Public Power District 79/05/01 2pp
- 7905080446 Forwards response to 790502 request for add1 info restess generator water mass, signals which originate ECCS & setpoint values MORRIS, K J. Omeha Public Power District 79/05/02 6pp
- 7905100312 Responds to 790501 questions re licensee experience w/ pressurfier power operating relief valves lifting due to instrumentation & control failures & transient events MCRRIS.K J Omaha Public Power District 79/05/03 2pp
- 7905090358 Forwards application for amend to License DPR-40 Certification for Svc & amend fee encl MACRAE.C F LeBoouf, Lamb, Leiby & MacRae 79/05/08 3pp
- --7905090363 Application for amend to License DPR-40, deleting conditions which require collection & reporting of nonradiological water quality data or info SHORT. TE Gmaha Public Power District 79/05/04 App
- 7905240562 Submits info re main feedwater sys & pressuritor code safe; valves in response to NRC 790507 telecopy HORRIS,K J Dmaha Public Power District 79/05/10 4pp
- 7905150316 Forwards application for amend to OL Certificate of Git encl \* LeBosuf, Lemb. Leiby & MacRao 79/05/14 3pp
- --7705130317 Application for amend to License DPR-40, changing Tech Ejs to prevent low temp reactor coolant mys overpressurfication SKORT.T E. Omaha Public Power District 79/05/11 Spp
- 7905310243 Forwards application for amend to License DPR-40 Certiff() of 8vc encl
  MACRAE, GF LeBoeuf, Lemb, Leibu & MacRae 79/05/30 3pp
- --790531024B Application for amend to License DPR-40 to change Tech \$,\*
  re fire protection sys
  SHORT.TE Omaha Public Power District 79/05/25 App
- G Inspection reports, IE Bullatins & correspondence
- 7905150085 Forwards IE Gircular 79-04, "Loose Locking Nut on Limitories Valve Operators"

  SEYFRIT.K V Region 4. Dallas, Office of the Director 79/03/15

  19
- 7905010453 Forwards IE Bulletin 78-12B, "Atupical Neld Mati in Resctu-Pressure Vessel Welds" BEYFRIT, K V Region 4, Dailas, Office of the Director 79/03/19
- 7905020440 Forwards IE Circular 79-05, "Moisture Leakage in Stranfaf Wire Conductors "
  SEYFRIT, K V. Region 4, Dallas, Office of the Director 79/03/20
- 7905020268 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping" SEYFRIT.K V. Region 4. Dallas, Office of the Director 79/03/23
- 7905290222 Responds to IE Bulletins 78-12 & 78-12A re atypical wild math in reactor pressure vessel Util currently performing records search & will submit generic rept SHORT, T E Omaha Public Power District 79/03/23 ip
- 7905020413 Forwards IE Info Notice 79-07, "Rupture of Radwests Fants "
  ERYFRIT, K V Region 4, Dallas, Office of the Director 79/03/25
- 7905150306 Forwards IE Insp Rept 50-285/79-04 on 790319-22 No noncompliance noted MADSEN, O. i. Region 4: Dallas, Reactor Operations Nuclear Support Branch 79/03/27, 2pp.
- --7905150310 IE Insp Rept 50-285/79-04 on 790319-22. No noncompliants noted Major areas inspected records program plant operation a plant cours MADSEN.O.L. KELLEY.D L. Region 4. Dallas, Reactor Operations Nuclear Support Branch. 79/03/27, 3pp
- 7905020434 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Byc Air Sys Used as Source of Breathing Air "
  BEYFRIT, K. V Region 4, Dallas, Office of the Director 79/03/28

- 7905140146 Forwards IE Bulletin 79-04, "Incorrect Weights for Swing Check Valves Mfg by Valan Engineering Corp " Licenses action serviced SEYFRIT.K V Region 4. Dallas, Office of the Director 79/03/30
- 7905150049 Forwards IR Info Notice 79~09. "Spill of Radioactively Contaminated Resin" Region 4. Dallas. Office of the Director 79/03/30
- 7903150211 Notifies that C-E informed util that generic response to IE Bulletin 78-12B, re matl in reactor vessel walds, cannot be provided before 790813 Util will submit plant-specific response by 790914
  SHDRT.TE Omaha Public Power District 79/04/03 ip
- 7905230618 Responds to IE Sulletin 79-03 Util has in intention of Using ASME SA-312 Type 304 or other welded pipe mfg by Youngstown Welding & Engineering Co SHORT. T E Omaha Public Power District 79/04/10 1p
- 7905040486 Forwards IE Bulletin 79-068. "Review of Operational Errors to Bus Misalignments Identified During TMI Incident " Licensee action required BEYFRIT.K.V Region 4. Dallas. Office of the Director 79/04/14 ip
- 7704040623 Forwards IE Builetin /9-08, "Events Relevant to Beiling Water Power Reactors Identified During TMI Incident " BEYFRIT.K V Region 4. Dellas, Office of the Director 79/04/14
- 7905070073 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required BLYFRIT, K V Region 4, Dallas, Office of the Director 79/04/14 to
- 7905090104 Forwards suppl to IE Bulletin 79-08A, "Nuclear Incident at TMI"

  SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/16

  1p. -
- 7905030200 Forwards 1E Bulletin 79-09. "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " Liconsee action required SEYFRIT.K. V. Region 4. Dallas: Office of the Director 79/04/17 to.
- 7905080354 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl."
  SEYPRIT, K V Region 4, Dallas, Office of the Director 79/04/21
- 7903100128 Forwards responses to IC Bulletin 79-068 "Review of Operational Errors & Sys Misalignments Identified During YMI "Operators reminded to check confirmatory indication when responding to accident conditions BUORT, T.C. Omahe Public Power District 79/04/23 34pp
- 7900240672 Responds to IE Builstin 79-07 re seismic stress analysis of eaffety-related piping Util does not use methods described in bulletin BiGRT.T.E. Omaka Public Power District 79/04/23, 9pp
- 7909290499 Responds to IE Bulistin 79-04 No Velan swing check valves are installed or scheduled to be installed in Sussmit I piping.
  BHORT-T E Omaha Public Power District 79/04/23 ip
- 7903230237 Forwards IR Insp Rept 50-285/79-08 on 790326-30 Notice of violation withheld (ref 100FRZ 790) MADSEN, G.L. Region 4. Pallas, Reactor Operations Nuclear Support Branch 79/04/24. 2pp
- 7703230438 Notifies that certain safety-related electrical equipment failed to meet environ qualification criteria:per IE Bulletin 79-01 Valves will be replaced BHORT, T. E Omahe Public Power District 79/05/15 2pp
- R. Periodic operating reports & related correspondence
- 7905140238 Forwards monthly operating rept for Apr 1979. BHCRT.T E. Omaka Public Power District 79705/09 1p

- --7905140240 Monthly operating rept for Apr 1979 HICKLE.B J - Omaha Public Power District 79/05/27 - 3pp
- 8 Reportable occurrences, LERs & related corresporten e
- 7905140487 Forwards LER 78-00}/D3L-0 JONES,W C Omaha Public Power District 78/02/01 10
- 7905140494 LER 78-001/03L-0 on 780116 during monthly cality of recirculation actuation signal pressure switches found switch A/LC-383 drifted from setpoint tolerance Static-D-Ring Model 12NN-KKOA.xIV readjusted 5 checked PETERSON, G , CONNOLLEY, J L Omaha Public Power District 78/01/20 2bo
- 7905150122 Forwards PNO-79-67R ½ 79-77(NRR)

  MADSEN, Q L Region 4, Dallas, Reactor Operations Nuclear Support
  Branch 79/04/11 1p
- 7905040112 Forwards PND-79-678 MADSEN.C L Region 4. Dailas, Reactor Operations Nuclear Support Branch 79/04/12 1p
- 7905150261 Forwards PND-79-67T correction

  MADSEN.G L Region 4, Dallas, Reactor Operations Nuclear Support
  Branch 79/04/13 19
- 7905010533 Forwards PNO-79-67U.V & W MADSEN.G L Region 4, Dallas, Office of the Director 79/04/16
- 7905010546 Ferwards PNO-79-67X & Y MADBENIG C Region 4. Dallas, Office of the Director 79/04/t0 1p
- 7905010589 Forwards PNO-79-67Z MADSEN.O L Region 4. Dallas. Office of the Director 79/04/19 ip
- 7705010401 Forwards PNO-79-67AA, AB, AC & AD
  MADSEN. G L. Region 4. Dallas. Office of the Director 79/04/24
  1p
- 7705070541 Forwards LER 79-007/03L-0
  ANDREWS, R L Omaha Public Power District 79/04/30 to
- --7909070545 LER 79-009/03L-0 on 790406 as matrix failed test Caused by failure of mercury wetted relay to break contact Relay exercises & found normal Matrix will continue to be tested CORE.M., PETERSON, G Omaha Public Power District 79/04/19 4pp
- 7905150100 Forwards PNO-79-67AF, AG, AH, AI & AJ, re incident at THJ MADSEN.G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/04/30 ip
- 7905240440 Forwards PNO-79-67AK & AL MADSEN. © L Region 4. Dailas, Reactor Operations Nuclear Support Branch 79/05/02 ip
- 7905210256 Forwards LER 79-011/03L-0
  ANDREWS, R L Omaha Public Power District 79/05/07 ip
- --7905210259 LER 79-011/03L-0 on 790424 channel A do sequencer Sl-1 deenergized matrix lights Caused by OE CR120A 125 volt do relay faulting internally Relay replaced & sequencer tested satisfactorily CONNOLLEY, J. L. PETERSON, Q R. Omaha Public Power District 79/04/26 4pp
- 7903210268 Forwards LER 79-010/03L-0
  ANDREWS:R L Dmaha Public Power District 79/05/16 1p
- 7908220300 Forwards LER 79-012/03L-0 ANDREWB,R L Omaha Public Power District 79/05/14 ip
- ---7905220306 LER 79-012/03L-0 on 790507 during surveillance test.matrix test failed for BC matrix Caused by failure of mercury wetfod relay in matrix circuit.CP Clare Model HOZX 1011.to break contact Relay removed & contacts cleaned CORE.M . PETERSON.G Omaha Public Power District 79/05/16 4pp

- 7905300948 Forwards LER 79-015/01T-0
  ANDREWS.R L Dmaha Public Power District 79/05/25 1p
- ---7905300557 LER 79-015/01T-O on 790511 seismic support appeared imadequate for component cooling water piping-to-containment cooling & filtering unit VA-3A Analyses indicated that clamping piping-to-cooling unit will provide needed support MUELLER.R Omaha Public Power District 79/05/22 App
- DOCKET 50-286 INDIAN POINT STATION, UNIT 3

  F Security, medical, emergency & fire protection plans
- 7905220380 Forwards, under protest, filing fee for NRC review of revised emergency plan EARLY, P J Power Authority State of New York 79/05/14 Ip

### O Adjudicatory correspondence

- 7905250039 Differs to provide Board "Comparison of Simulation Models Used in Assessing Effects of Power Plant-Induced Mortality of Fish Population," by GL Gwartzman, RB Deniso & C Conan of Univ of MA
  LEMIS, S H Branch 2 79/03/30 16
- 7705080198 Forwards "Comparison of Simulation Models Used in Assessing Effects of Power Plant-Induced Mortality on Fish Populations" per telcon request M/o encl MODRE, J E Branch 2 79/04/16 ip

#### J Insurance & indemnity information

- 7705070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,144,151,161,164,170,173,174,178,179,180,182,183,183,183,189,189,192,193,194,195,197,193,200,201,204,206,207,208,210,212,214,215,&others QUATTROCHHI,J American Nuclear Insurers 79/05/01 to
- 7703070582 Confirms increase in liability limit to \$36.000.000 for policies MF-22.26.29.38.39.44.46.47.49.50.51.52.53.54.55.56.57.58.60.61.64.66.67.68.67.70.71.72.74.76.77.78.79.80.86.87.88.90.91.92.93.74.55.56.57.68.69.
- 7905140407 Forwards Amend 21 to Indemnity Agreement B-19 per 10CFR140 changes, re increase in liability insurance from \$140 million to \$160 million, effective 790501 Supporting documentation encil SALTZMAN, J Antitrust & Indemnity Group 79/05/01 App.
- P Operating license stage documents & correspondence
- 7905070311 Forwards Amend 25 to License DPR-64 & notice of issuance & availability 60HWENCER.A Operating Reactors Branch i 79/03/29 4pp
- ---7905070315 Amend 25 to License DPR-64, revising Tech Specs to allow continuous chlorination of plant discharge from new sewage treatment facility

  SCHWENGER.A Operating Reactors Branch 1 79/03/29 6pp
- 7905040513 Forwards "Steam Generator Operating History Questionnaire." Revision 1 EARLYP.J Power Authority State of New York 79/04/30 1p
- --7905040318 "Steam Generator Operating History Guestionnaire,"
  Revision 1
  \* Power Authority State of New York 79/04/30 15pp
- 7905070549 Ack receipt of NRC 790412 ltr Hilling to cooperate in planned analysis scheduled for week of 790806 GAHILL: # J. Consolidated Edison Co of New York 79/04/30 19
- 7905100156 Forwards application to amend License DPR-64, proposed Tech Bpec changes & \$4,000 fee W/o check EARLY,P J Power Authority State of Neu York 79/05/02 3pp
- ---7905100161 Application for amend to License DPR-64,adding definition to Section 1 App A & new specs for limiting conditions for operation & surveillance requirements to radiological effluent Tech Specs.

  \*\* Power Authority State of New York 79/04/30 78pp

- 7905170244 Forwards "Evaluation of Effectiveness of Continuously Operating Fine Mush Traveling Screen for Reducing Ichthyoplankton Entrainment " Affidavit & Cartificate of Byc enci CANILL, y J Convolidated Edison Co of New York 79/05/14 5pp
- --7905170249 "Evaluation of Effectiveness of Continuously Operating Fine Mesh Traveling Screen for Reducing Ichthyoplankton Entrainment " • Consolidated Edison Co of New York 79/04/30 30pp
- 7905230531 Forwards responses to 790510 request for info re heaters, relief valves loss of feedwater events, steam operator & small break analysis

  BAYNE, J P Power Authority State of New York 79/05/18 5pp
- --7905230556 Forwards request for info re ability of currently operating PHRs to safely withstand TMI-2 type events
  SCHWENCER.A Operating Reactors Branch 1 79/05/10 4pp
- O Inspection reports, IE Bulletins & correspondence
- 7905080099 Forwards IE Insp Rept 50-286/79-02 on 790121-0217 No noncompliance noted BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/03/16 2pp
- --7908080110 IE Insp Rept 50-286/79-02 on 790121-0217 No noncompliance noted Major areas inspected log & record reviews.followup on previous insp items & observation of control room personnel during simulated emergency drill REBELOWEKI.T. JOHNSON.D Region i. Philadelphia, Office of the Director KEIMIG.R Region i. Philadelphia, Reactor Operations Nuclear Support Branch 79/03/18 9pp
- 7905010129 Forwards IE Info Notice 79-06. "Stress Analysis of Safety-Related Piping"
  ORIER. 8 H Region 1. Philadelphia. Office of the Director 79/03/23 1p
- 7905030279 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks " GRIER.8 H Region 1, Philadelphia, Office of the Director 79/03/26 1p
- 7903010038 Forwards IE Info Notice 79-08. "Interconnection of Contaminated Sys w/Syc Air Sys Used as Source of Breathing Air " GRIER, B H Region I. Philadelphia, Office of the Director 79/03/28 to
- 7705030181 Requests extension of time to respond to IE Bulletins 78-12-12A. & 12B.due to delay in issuance BAYNE.J.P. Power Authority State of New York 79/03/28 to
- 7905010313 Forwards IE Info Notice 79-D9, "Spill of Radioactively Contaminated Resin" GRIER, B H Region i, Philadelphia, Office of the Director. 79/03/30 2pp
- 79d5020075 Forwards IE Bulletin 79-06, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident " Licensee action required GRIER, B H. Region 1. Philadelphia. Office of the Director 79/04/11 ip
- 7905070161 Ack receipt of 790323 Itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-286/79-04
  BRUNNER,E J Region i. Philadelphia, Reactor Operations Nuclear Support Branch 79/04/11, ip
- --7905070169 Responds to NRC 790301 ltr re violations noted in IE Inap Rept 50-286/79-04 Corrective actions superseded procedures removed from file.procedures & test schedule revised BAYNE.J P Power Authority State of New York 79/03/23 2pp
- --7905070172 Forwards 1E Insp Rept 50-286/79-04 on 790206-09 & notice of violation BRUNNER, E J Region i, Philadelphia, Reactor Operations Nuclea 80pport Branch 79/03/01 2pp
- --7905070177 Notice of violation from insp on 790206-09
  \* Region i, Philadelphia, Office of the Director 79/03/01

- --7905070182 IE Insp Rept 50-286/79-04 on 790206-09. Noncompliance noted failure to use latest revision of procedure & failure to adhere to procedures
  - adhere to procedures

    Adhere to procedures

    BAUNACK, W H. BLUMBERG, N J. Region 1. Philadelphia. Dffice of
    the Director KIGITER-H B. Region 1. Philadelphia. Reactor

    Operations Nuclear Support Branch 79/02/28 13pp
  - 05250241 Responds to IE Bulletin 79-03 re langitudinal weld defects in certain pipe spools off by Youngstown Helding to Englinearing Co Piping used in const. but not w/o filler metal Piping under 4-inches will be investigated by 790525 BAYNE, J P Fower Authority State of New York 79/04/13 2pp
- /05020275 Forwards IC Bulletin 79-07. "Beismic Stress Analysis of Defety-Related Piping" Licensee action required. GRIFR. B M Region 1. Philadelphia. Offics of the Director /9/04/14 ip
- 7050400/0 Forwards It. Bulletin 79-060, "Review of Operational Errors & Bys Misslignments Identified During TMI Incident " ORIFR, 8 H Region 1, Philadelphia, Office of the Director 79/04/14 ip
- 905040245 forwards IC Bulletin 79-08, "Events Relevant to Boiling Mater Power Reactors Identified During TMI Incident " GRIRL Bil Region 1, Philadelphia, Office of the Director 79/04/14 ip
- 905070004 forwards IL Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Bafaty-Related Bys " Licensee action required ONIGN D B Region i, Philadelphia, Office of the Director
- ORIEN, D N Region 1, Philadelphia, Office of the Director 79/04/17 ip
- '90302029B Forwards If Bulletin 79-06A, Revision 1. "Review of Operational Errors & Sys Hisalignments Identified During TMI Incident " Region 1. Philadelphia, Office of the Director, 79/04/18 1p
- /90501049/ Comments on IE Bulletin 79-06A re Westinghouse PWR facilities implementation of bistable trip would create situation where safety injection actuation could be susceptible to usingle bus perturbations
  DEBOLE.T.K. New York, State of 79/04/29 29P
- 7905310 194 Forwards add1 response to IE Bulletin 79-07 re seismic pipe stress resnelysis; as requested by NRG on 790517 Mat1 supplements info in 790424 ltr GCIMILDER, J. R. Power Authority State of New York 79/05/22 36pp
- 7903310443 Forwards add1 info to IE Builetin 79-07 re piping seismic stress analytic method, in response to 790523 request Mati supplements 790424 & 790522 ltrs EARLY.P J Power Authority State of New York 79/05/24 2pp
- A Periodic operating reports & related correspondence
- 7903220176 Forwards effluent monitoring & impingement data specified in Bection 401 Centification for Apr 1979 HONTI, H A Consolidated Edison Co of New York 79/05/10 17pp
- /905150302 Forwards monthly operating rept for Apr 1979
  BAYNE, J P Power Authority State of New York 79/05/11 ip
- ---7909150:104 Monthly operating rept for Apr 1979.
  CONNELL.G Power Authority State of New York 79/05/01 6pp
- 7905230392 Forwards daily record of fish collections for Apr 1979 W/daily species breakdown & total weight for Units 2 & 3 ORIGA, B. II Region 1. Philadelphia, Office of the Director 79705/14. Spp
- 8 Reportable occurrences, LERs & related correspondence
- 7905250172 Describes LER-003-017-0 on 790328 Westinghouse revisure-revealed potential for safety analysis methodology to lead to calculated DNB ratios less conservative than previously reported Constitutes 24-hr required notification 18498. JP Power Authority State of New York 79/03/29 2pp
- 7905220317 LER 79-011 has been voided a Power Authority State of New York 79/04/01. 1p
- 7905220322 LER 79-010 has been voided \* Power Authority State of New York. 79/04/0-1. 1p
- 7905220327 LER 79-007 has been vaided. \* Power Authority Btate of New York 79/04/O1 1p

- 7905220331 LER 79-008 has been voided \* Power Authority State of New York 79/04/01 is
- 7905220334 LER 79-009 has been voided
  \* Pawer Authority State of New York 79/04/01 ip
- 7905220338 LER 79-006 has been voided # Power Authority State of New York 79/04/01 1
- 7905010516 Forwards LER 77-004/03L-0
  BAYNE, J P Power Authority State of New York 79/04/26 1
- --7903010322 LER 79-004/03L-0 on 790327 condensate storage tank level fell below Tech Spec limit during hat shutdown Caused by use of steam generator blowdown sys which was being held at max Onsite demineralization plant to be added GUMBLE.F W Power Authority State of New York 79/04/26 2PP
- 7905090301 Forwards LER 79-005/03L-0
  BAYNE, J P Power Authority State of New York 79/05/04 1p
- --7905090305 LER 79-005/03L-0 on 790405 svc water pump 34 removed due to low discharge pressure;main pump shaft broke, disabling one of three essential header pumps Caused by bearing failures making shaft break Repairs are pending GUMBLE,F Power Authority State of New York 79/05/04 lp
- 7903190015 Forwards LER 79-012/04X-1 CAMILL:N J Consolidated Edison Co of New York 79/05/10 1p
- --7905190018 LER 79-012/04X-1 on 790213 activity of precipitation sample exceeded 10 times control station level Caused by tritium releases from source external to facility Hanufacturer in area has modified installation to prevent recurrence HASCIULLI,8 Consolidated Edison Co of New York 79/05/10 3pp
- 7905190021 Forwards LER 79-015/04T-0 CAHILL:N J Consolidated Edison Co of New York 79/05/10 1p
- --7905190025 LER 79-015/04T-O on 790405 activity of pracipitation sample exceeded 10 times control station level Caused by tritium releases from source external to facility Manufacturer in area has modified installation to prevent recurrence MARCIULLI, S Consolidated Edison Co of New York 79/05/10 2pp
- DOCKET 50-287 DOONEE NUCLEAR STATION, UNIT 3
- F Becurity, medical, emergency & fire protection plans
- 7905270090 Discusses 790213 submission of security plan for storage of spent fuel & 790216 telcon re-requirement for security plan mods Initial plan is subj to withholding from public: record of transmittal is required ROUSE, L C Fuel Reprocess & Recycle Branch 79/03/29 ip
- 7705140283 Forwards emergency procedure EP/O/A/1800/4, "Loss of Reactor Coolant," containing instructions for operator action for small breats PARKER,W O Duke Power Co 79/05/09 29pp
- H General correspondence
- 7905250131 Urges careful review of staff rept before ordering shutdown of facility since action could cause extensive power curtailments & higher fuel costs for 1 2 million customers in Carolina piedmont HELMS, J Senate 79/04/26 ip
- 7905020254 Expresses gratitude for decision to close facility THOMPSON.M W Affiliation Unknown 79/04/28 ip
- J Insurance & indomnity information
- 7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,56,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,58,690,91,92,93,94,75 & 96
  RDBERTS,D M Mutual Atomic Energy Liability Underwriters 79/05/01
- 7905140438 Forwards Amend 13 to Indemnity Agreement 8-44 per 10CFR140 changes, re increase in liability insurance from \$140 million to \$160 million, effective 790501 Supporting documentation encl SALTZMAN, J Antitrust & Indemnity Group 79/05/01 6pp

- 7905160361 Submits executed copy of Amend 13 to Indomnity Agreement 8-44, reflecting changes in 10CFR140 PARKER, N.O. Duke Power Co. 79/05/08 3pp
- 7905310348 Forwards replacement copy of Amend 8 to Indomnity Agreement B-44 in response to 790516 request W/copy of util 740412 transmittal ltr PARKER: H O Duke Power Co 79/05/22 3pp
- P Operating license stage documents & correspondence
- 7905150104 Notifies of refund of fees.remitted 780705.for authority to transfer fuel between facility & Crystal River Unit 3 Refund will be sunt when processed MILLER.W O License Fee Management Branch 79/05/03 ip
- 7905250014 Forwards Amends 69.69 & 66 to Licenses DPR-38.DPR-47 & DPR-55.respectively.EIA & notice of issuence & availability REID.R H Operating Reactors Branch 4 79/03/02 3pp
- --7903250018 Amends 69.69 & 66 to Licenses DPR-38.DPR-47 & DPR-35. respectively, which reviews ETS by deleting aquatic surveillance program & special study programs REID.R W Operating Reactors Branch 4 79/03/02 11pp
- 7905190155 Responds to R Hattson & D Ross concerning value of running natural circulation test on SEW reactor
  TEDESCO.RL Assistant Director for Plant Systems 79/04/05 4sp
- 7903080130 Responds to 790329 submittel re radiological effluent Tech Spec.which omitted solid radwaste process control program Requests omitted portion REID.R W Operating Reactors Branch 4 79/04/18 2pp
- 7905010521 Forwards documentation, design info & projected implementation schedules re emergency feedwater sys, as committed in NRC 790425 meeting PARKER, NO Date Power Co 79/04/28 4pp
- 7905010550 Forwards addl info re Oft of Nuclear Reactor Regulation status rept Requests addl dialogue w/NRG re control sys LEE,W S Duke Power Co 79/04/25 ip
- 7905030371 Informs that util has conducted review of plant design & operation, including goal of improving reliability of normal feedwater sys & added assurance of amergency feedwater supply to steam generators Gasign adequate OHEN.H H Duke Power Co 79/04/25 2pp
- 7905040047 Corrects error in 790417 ltr to NRC Reported period of facility mods should be Jan-Dec 1979 PARKER, H II Duke Power Co 79/04/25 ip
- 790511006B Informs that small break analyses review is complete Analyses are unacceptable & incomplete ROSZTQGZY: Z R Analysis Branch 79/04/25 ip.
- --7905110074 Comments on draft rapt received 790420 too langthy, does not concentrate on important issues & has dozens of incorrect & mislanding statements Rept should be reorganized ROBZTOCZY, Z R Analysis Branch 79/04/25 Spp
- 7903240982 Responds to 790320 ltr requesting advice on allowable time interval for submittal of repts to NRC REID.R W Operating Reactors Branch 4 79/04/26 2pp
- 7903020283 Informs of util position on issuance of formal order recontinued plant operation Written issuance is undesirable as policy & legally unnecessry LEE.WB Duke Power Co 79/04/29 ip.
- 7905040352 Forwards response to 780327 request for addl info re proposed changes to hydraulic shack suppressor Tech Bpec PARKER, W Q Duke Power Co 79704/30 2pp
- 7905080433 Forwards proposed revision to Tech Specs covering reactor bldg hydrogen purge sys.penetration room ventilation sys, reactor bldg purge filters & spent fuel pool ventilation sys PARKER.W.O. Duke Power Co 79/05/01 11pp
- 7903080566 Forwards proposed revision to Tech Specs, deleting Tech Spec 4 13 which is no longer required PARKER, W.O. Duke Power Co 79/05/01 4pp
- 7905240466 Documents completion of 761001 proposal to delete Tech Specs re tendon, anchorage & liner plate surveillance programs.
  License fee not required
  PARKER.W.D Dute Power Go 79/05/02 ip.

- 7905140189 In response to NRC 790418 request forwards proposed Tack Spec re plant solid radwaste process control program PARKER.W O Duke Power Co 79/05/07 5pp
- 7903240231 Forwards status on improvements to emergency feedwater sq. per MO Parker 790425 ltm & MS Lee 790426 ltm PARKER.H O Duke Power Co 79/05/07 100pp
- 7905140365 Lists drawings used for installation of automatic starting of interconnected emergency feedwater sys, which were sent to NRC on 790503
  PARKER, H G Duke Power Co 79/05/09 ip
- 7905140268 Forwards "Emergency Feedwater Sys, Sys Concept & Analysis'
  Pump installation to be complete by 790825 Oversized drawing
  In Central Files
  PARKER, U D Duke Power Co 79/05/10 9pp
- 7905160389 Forwards "B&N 177 Fuel Assembly Dunors Oroup Asymmetric LOZI Loads Evaluation Program Phase 2:" dtd 790410 Bupersedes program provided on 790111 PARKER: U Duke Power Co 79/05/10 1p
- --7905160390 \*B&H 177 Fuel Assembly Owners Group Asymmetric LOCA Latti Evaluations Program. Phase 2 \* \* Dyke Power Co 79704/10 9pp
- 7905230487 Notifies that analyses were performed w/actual Cycle & burnup to ascertain changes required for operation at full rated power during Cycle 5 Results indicate no need for changes in core loading or Tech Spec
  PARKER, W Q Duke Power Co 79/05/17 ip
- 7905230543 Forwards revised sys concept & analysis re-addition of two motor-driven emergency feedwater pumps Supersedes 790510 submittal Woversized drawing PARKER:N 0 Duke Power Co 79/05/17 10pp
- 7903240593 Bubmite results of add1 analyses to 790330 proposed Teck Specs changes for operation at full rated power during Cycle 3 PARKER, W D Duke Power Co 79/05/17 1p
- 7905240478 Responds to IE Builetin 79-058 re TMI incident Forwards proposed amend to Tech Opecs, changing setpoints of pressurizer electromagnetic relief valve & reactor coglant sys high pressure trip PARKER, N D Duke Power Co 79/05/21 11pp
- 7905240478 Forwards design description for safety grade anticipatory reactor trip on turbine trip or loss of main feedwater Mods will be installed for each refueling outage following NRC approval PARKER.W Q Duke Power Co 79/05/21 5pp
- 7905300208 Forwards summary of EDS Nuclear inc resolution/documentation of elbow flexibility error which existed in versions of PISOL piping analysis computer program from Jan-Oct 1969 Review & reanalysis included all work through Dec 1970 PORTER, F L EDS Nuclear, Inc 79/05/21 9pp
- ~~7908300263 Forwards EDS Nuclear, Inc list of BWRs & piping eys which could have been impacted by deficient computer program QE has no record of reanalysis for Cooper piping sys STEPHENS, P H. Oeneral Electric Co , Nuclear Energy Products Div 79/01/24 18pp
- 7905310211 Forwards proposed Tech Specs revision re limiting condition operation & surveillance requirements
  PARKER.W.O Duke Power Co 79/05/25 Spp
- Q Inspection reports, IE Bulletins & correspondence
- 7905230482 Forwards IE Insp Repts 50-269/79-04, 50-270/79-04, 4 80-289/79-04 on 790205-07 No noncompliance noted LEHIS.R L Region 2, Atlanta, Reactor Operations Nuclear Suppl Branch. 79/03/12 2pp
- --7905230503 IE Insp Repts 50-269/79-04.50-270/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-207/79-04.50-2
- 7905010177 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping" 0'REILLY,JP. Region 2, Atlanta, Office of the Director 79/03/23 2pp.

- 7905030307 Forwards It Info Notice 79-07, "Rupture of Radwaste Tanks 'O'RTILLY, J P Region 2, Atlanta, Office of the Director 79/03/26 App
- 79052J0272 Discusses B&W rept. "Records Investigation Rept Related to Off Chamistry Welds in Matl Hurveillance Opecimens & Response to It Hulletins 7D 교육 7B 교육 Hoppl." Tept accurately represents data for reactur pressure vessels PARKER.N O Duke Power Co 79/0 1/2/ ip.
- 7905010090 forwards It info Notice 79 00. "Interconnection of Contaminated Bys w/Bys Air Bys Used as Guerca of Dieathing Air "
  O'RI ILLY, J.P. Region 2. Atlanta, Office of the Director 1970 1/218 Jun
- 7907010390 Forwards II. Info Notice 79.09, "Spill of Radioartively Contaminated Resin."

  O'RETHYOUR. Region 2: Atlanta, Office of the Director
- 7905210279 Responds to II Unitetin 79 OP re longitudinal weld defects No AGML DA JULitype 104 piping or any other welding w/o filter metal piping off by Youngstown Welding is in use or glanned for use PARKIRIM O Duke Cower to 79704704 ip
- 7905100240 forwards responses to 11 Bulletins 79 05 & 79 05A, "Nuclear incident at 161 " PARKER, B O - Duke Power Go - 79704710 - 21pp
- -- 7905100299 Forwards Absormal Disortants Rept AO 207775 OF PARKINGO Disks Power to 79706727 1p
  - 7905100 R94 AH 2027/5 O7 on 790613 escausive captur coolant syscoolanger hate discussed Caused by operator error & failure of pulser-actuated pressurizer relief valve 186 o6 to close 8 Duke Power Go 75706/22 ip
  - 7905100 D 3 forwards addition to All 207725 O7 Corrective actions shitdown procedures revised relief valves will be examined & queuch tank nupture diff replaced PARKIBAN 1) Dute Power to 75700700 ipp
- 7905020040 Aik teretpt of 270326 ltr sufurming RHC of steps taken to correct violations noted in It linep Repts 30 269779 03. 30 270779 03 6 8 mg/77 03 Repts 30 Atlanta: Hafegueids Braint 79704712 [p.
  - 7905020064 Responds to RHC 790 RM, itr is violations noted in IC Insp. Repts 50 247279 0.50 270729 0.5 6 ho 202279 0.6 Corrective actions withheld (set inches 790). PANKIR-B 0. Dute Power Co. 7920328. Ip
  - 7905020070 Forwards II Insp Repts 30 269779 03:50 270779 03 & 80 287779 03:m 790203 06 Notice of Violation withhold Cref 10(182 790) Region 2. Atlanta, Unfequence Branch 79703706 200
- ~79050200H/ If Insp Repts 90 Jb9/79 01.50 J20779 01.5 90 J87779-07 on Y90205 Oh Noncompliance noted areas of testing/maint 5 detection aids Details withheld free 100fAu 7905 TOURN,W J. Region 2. Atlanta, Office of the Director Olliforbise P. Region 2. Atlanta, Office Branch 79703/06 ip
- 7905100046 Responds to II Bullstin 79 0%A: Items 7: 0: 10 & 11 re TRI Incident All Manual valves which could defeat or compromise flow are locked open PARKR:N O Buke Power Co 79704713 Bpp
- 2905040126 Forwards II Bulletin 29 O6B, "Neview of Operational Circus & Bys Hisalignments Identified During THE Incident " O'HELLLY, J.P. Region D. Actanta, Office of the Director 79204214 18
- 7705040267 Forwards IK Bullatin 79 07. "Betsmic Stress Analysis of Bafesy-Related Piping" Licensee Action required O'REILLY, J.P. Region J. Atlanta, Office of the Director 77/04/14 2pp
- 7705040301 Forwards If Bulletin 79 OB. "Events Relevant to Boiling Hater Rower Reactors Identified During THI Incident "O'REILLY, JP Region 2: Atlanta, Office of the Director 79704/14 ip
- 7905030160 Forwards II Builetin 79-09. "Pailures of OE Type AK-2 Circuit Breaker in Bafety Related Bys " Licensee action required O'REILLY, J.P. Region 2. Atlanta. Office of the Director 79/04/17 20s

- 7705020427 Forwards IE Bullatin 77~06A.Revision 1, "Review of Operational Errors & Bys Misalignments Identified During TMI O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/18 2pp
- 7903240452 Responds to IE Bulletin 79-05. Item 3, re TMI incident Reactor protective sys high RCS pressure setpoint lowered to not preater than 2,300 psig Pressurizer power operated relief valve reised nominally to 2,450 psig PARKER, U C Duke Power Co 79/04/21 lp
- 7709240909 Forwards response to IE Bulletin 79-07 re computer program used for piping analysis Algebraic summation methods were not used in piping analysis
  PARKER, N D Duke Power Co 79/04/24 2pp
- 7905110264 Forwards 790505 response to IE Bulletin 79-058, Items 1,2,4 & 6. re TMI incident PARKER, H O Duke Power Co 79/05/05 1p
- ---7903110268 Responds to IE Bulletin 79-058. Items 1.2, 4 & 6 Emergency procedures for loss of reactor coolant flow steam supply sysrupture, uncontrollable flooding of turbine bidg & loss of normal HPI makeup or letdown have been revised PARKER, W O Duke Power Co 79/05/05 dpp
- 7905300541 Forwards inservice insp program PARKER, W D Duke Power Co 79/03/15 1
- --7705300550 Inservice insp program
  \* Duke Power Co 79/05/15 75pp
- 7903220331 Forwards description of post-TMI operator training.per 790313 discussions & IE Bulletin 79-05,79-05A & B Operating shifts have adequate knowledge to operate reactors in all modes PARKER.W O Duke Power Co 79/05/16 4pp
- R Periodic operating reports & related correspondence
- 7905220358 Forwards monthly operating rept for Apr 1979 PARKER, W O Duke Power Co 79/05/15 ip.
- --7905220345 Monthly operating rept for Apr 1979 REAVIS, J A Duke Power Co 79/05/15 16pp
- 8 Reportable occurrences, LERs & related correspondence
- 7905110020 RD 287/78—18 on 781127 while engineered safeguards analog channel A was tripped in order to allow repairs channel B tripped Event not considered to be recurring problem Bys returned to normal operating condition w/o problem P Duke Power Co 79/01/15 2pp
- 7905140506 RO-287/79-4, which was to have been submitted by 790327, will be submitted by 790403, as investigation is still in progress PARKER. W O Duke Power Co 79/03/27 ip

--7905250427 LER 79-014/017-0 on 790507 nuclear instrumentation power indications less than thermal power levels Caused by changes in core characteristics which accompany changes in power

LEHIS, S.R. Duke Power Co. 79/05/21 3pp

- 7905310404 Forwards LER 79-010/03L-0 PARKER.H 0 Duke Power Go 79/05/23 1p
- --7905310410 LER 79-010/03L-0 on 790423 reactor bldg gaseous radiation monitors made (neperable when containment isolation valve on monitor inlat line failed Caused by ruptured operator diaphrage LEWIS.S R Duke Power Co 79/05/23 3pp

DOCKET 50-208 REED COLLEGE RESEARCH REACTOR J Insurance & Indemnity information

- 7905160265 Forwards Agend 9 to Indomnity Agreement E-52.per 10CFR140 changes.re increase from \$140 million to \$160 million: effective 790501 Supporting documentation encl SALTIMAN, J Antitrust & Indomnity Group 79/03/01 5pp
- 7905140341 Forwards Amend 9 to Indemnity Agreement E-52 MCFARLANE, E 0 Reed College 79/05/07 2pp
- DOCKET 50-289 THREE MILE ISLAND NUCLEAR STATION, UNIT 1 F Security, medical, emergency & fire protection plans
- 7905290356 Forwards Suppl 2 to fire protection SER, in response to Operating Reactors Branch 4 79/04/14 2pp
- --7705290559 Suppl 2 to fire protection SER accepting proposed change in completion date for proposed mods to fire barrier penetration & electrical cable penetration seals to 790427 > Office of Nuclear Reactor Regulation 79/04/14 4pp
- 7905240558 Requests approval of plan to eliminate four fire detectors in nuclear (instrumentation & reactor protection systable to the HERBEIN J G Metropolitan Edison Co 79/05/18 1p
- 9 Adjudicatory correspondence
- 7905290285 Forwards class action complaint re TMI accident filed against utils & vendors in C Robert Larson.et all. vs Metropolitan Edison Co.et al CARRIER.W C American Nuclear Insurers 79/05/22 9pp
- J Insurance & indemnity information
- 7905140486 Forwards Amend 8 to Indomnity Agreement 8-64 per 100FR140 changes, re increase in liability insurance from \$140 million to \$160 million affective 790501 SALTZKAN, J Antitrost & Indemnite Group 79/05/01 App
- 7905220362 Returns unsigned Amend 8 to Indemnity Agreement 8-64 Nuclear Liability Insurance Pools will not provide add1 coverage GERETY.H F GPU Service Corp 79/05/16 3pp
- P Operating license stage documents & correspondence
- 7905100420 Forwards "Initial Startup Rept ARNOLD, R C Hetropolitan Edison Co 74 74/11/27 10.
- --7905100425 "initial Startup Rept " # Metropolitan Edison Co 74/11/26 220pp
- 7905110178 Applies for license authorizing util to receive.possess & handle redioactive math at temporary field locations outside site boundaries
  ARNOLD-R C Metropolitan Edison Co 77/04/18 S5pp
- 7905:10173 Forwards addl info on procedures requested in NRC 771219 ltr re application for byproduct matl license HERBEIN.J. G. Hetropolitan Edison Co. 78/01/30 143pp
- 7905250021 EIA supporting Amends 69.69 % 66 to Licenses DPR-38, DPR-47 & DPR-53, respectively

   Operating Reactors Branch 4 79/03/02 4pp

- 7905160141 Forwards personnel exposure & monitoring rept for 1978 HERBEIN, J G Metropolitan Edison Co 79/04/02 2pp
- 7905020294 Confirms 790328 oral commitment to provide advance netset prior to taking unit out of present cold shutdown condition HERBEIN, J O Metropolitan Edison Co 79/04/16 1p
- 7903150486 Notifies that Class III for required for 780830 applicables re ring girder surveillance test has not been received Face should be forwarded within 15 days of receipt of ltr MILLER.# 0 License Fee Hanagement Branch 79/04/26 tp
- 7905070587 Requests 90-day extension to 790415 deadline for submittiful draft radiological affluent Tech Space & Offsite Dose Calculation Manual HERBEIN, J G Metropolitan Edison Co 79/04/28 ip
- 7905090320 Notifies that submission of final rept re impingement/ entrainment monitoring program at TMI will be delayed to HELBISH, J. F., TROFFER, G. J. Metropolitan Edison Co. 79/05/01 1:
- 7905190115 Responds to NRC 790205 itr re potential consequences of postulated fuel handling accident inside containment Consequences of potential accident are within guidelines of IOCFRIGO No further action required HERBEIN J 0 Metropolitan Edison Co 79/05/08 App
- 7905220371 Forwards amend fee for Tech Spec Change Request 77 HERBEIN J G Metropolitan Edison Co 79/05/15 ip
- @ Inspection reports, IE Bulletins & correspondence
- 7905230305 IE Bulletin 78-07, "Protection Afforded by Air-Line Respirators & Supplied-Air Hoods " \* Region 1, Philadelphia, Office of the Director 78/04/12 3;
- 7905020135 Forwards IE Insp Rept 50-289/79-05 on 790215.21.42 t 23 M noncompliance noted CARLEGN.R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/03/20 2pp
- --7905020140 IE Insp Rept 50-289/79-05 on 790215,21,22 & 23 No noncompliance noted Major areas inspected inservice insp program MALTON 0 A , TRIPP.L Region 1, Philadelphia, Office of the Director 79/03/16 7pp
- 7905240430 Forwards IE Insp Rept 50-289/79-06 on 790221-23 4 26 278 H Overvious retrievals to the noncompliance noted
  BRUNNER.E J Region 1. Philadelphia, Reactor Operations Nuclea
  Support Branch 79/03/21 2pp
- --7905240437 IE Insp Rept 50-289/79-06 on 790221-23 & 26-28 No noncompliance noted Major areas inspected refueling activities.preparation for refueling outage related maint. pipe supports & restraints, shift logs & records HAVERKAMP, D. HIGGINS, J.C. KEMMIGIR.R. Region 1, Philadelphi Office of the Director 79/03/20 17pp.
- 7905010118 Forwards IE Info Notice 79-06, "Strass Analysis of Safety-Related Piping " GRIER, B H Region 1, Philadelphia, Office of the Director 79/03/23 1p
- 7905010047 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air " ORIER, B H Region 1, Philadelphia, Office of the Director 79/03/20 1o.
- 7903010300 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin."

  GRIER, B. H. Region I, Philadelphia, Office of the Director 79/03/30 Rep
- 7905020033 Forwards IE Bulletin 79-06, "Review of Operational Error Sys Misalignments Identified During TMI Incident " ORIER, B.H Region 1, Philadelphia, Office of the Director 79/04/11 1p.
- 7905190215 Discusses schedule for completing actions required by 12 Bulletin 79-03 Search of procurement documents to determine use of specified welded pipe will be complete by 790831 HERBEIN.U.O Metropolitan Edison Co. 79/04/13 ip.

- 79090203/7 Forwards IE Bullotin 79-07, "Botsmic Utress Analysis of Bafety-Related Piping" Licenses action required ORIER/B it - Region i. Philadelphia: Dffice of the Director 79/04/14 ip
- 7905040040 Ferwards IE Bulletin 79 06B, "Roytsw of Operational From & Bys Misslignments identified During TMI Incident "ORIER, B H Region I: Philadelphia. Office of the Diswitch 77904744 | 1p
- 7900040210 Forwards IE Bulletin 79 OR: "Events Relevant to Reliting Hater Power Reactors Identified During IMI Incident "GRIER, B H Region L. Philadelphia, Office of the Director 79/04/14 ip
- /903030D72 Forwards II Bulletin /9 09, "Failures of GC Type AK 2 Circuit Breaker in Bafety Related Dys "Licensee action required ORIGE:D II Region i, Philadelphia, Office of the Director 79/04/17 ip
- 7905020275 Forwards II Bulletin 79 O&A.Revision i, "Review of Operational Priors & Bys Hisalignments Identified During TMI Incident" GRIFE, bit Region i, Philadelphia, Office of the Director
- R Periodic operating reports & related correspondence
- /905030338 Forwards monthly operating rept for Mar 1979 W/H enci TROFFER.O J. Metropolitan Edison Co. 79704/27 ip
- 7905230375 Forwards monthly operating rapt for Apr 1979 MCRBLIN, J O Metropolitan Edison Co 79705715 to
- ---7905230376 Henthly operating rapt for Apr 1979
  MITCHELL, D.O. Hatropolitan Edison Co. 79705701 Spp
- B Reportable occurrences, tills & related correspondence
- 7905090227 "LER Dutput on Events at THI-S & THI-2 from 1969 to Present" 4 Health, Education & Helfare, Dept. of 797047tH | Elipp
- 7905000445 Forwards LLH /9 000/00L 0 HERDEIN J Q Hetropolitan Ldison Co /9/04/26 ip
- --7999000481 LER 79 90028:0 on 299100 during refueling frequency local leak rate test, excessive leakage noted across valve AH VIII Caused by local valve sask retaining across to valve librates tiphtened & valve tested satisfactorily BYANEEY, H B Hetropolitan Edison Co 79704726 ip
- 7905000542 Forwards LLB 79 0077017 0 BEGBLING Q Metropolitan Edition Co. 79704786 Ip
- "--/90508034/ LIR 79-00//Oif-O on /903/3 dome of borated water storage tenk found partialty collapsed Caused by failure of vacuum breaker DH-V27 to relieve differential pressure when required Breaker bench tested & reinstalled STANLEY.N S Matropolitan Editon Co 79/04/26 App
- 7705270350 Forwards LER 77-011/031-0 HERBEIN, J G Metropolitan Edison Co. 79/05/01 1p
- --7905290304 LER 79-011/031-0 on /90405 leaks noted in spent fuel pool cooling sys piping Caused by interprenular stress corrosion cracking Areas of leakage isolated, stress analyses will be performed.
  HITCHELLD Q Metropolitan Edison Co. 79/05/16 Sep
- 7905140282 Forwards LFR 79-009/00L-0. HERBEIN, J Q Hat opolitan Edison Co 79/03/02 to
- ---7903140276 LER 79 009/03L-0 on 790410 during surveillance testing on turbina-driven emergency feedpump, steam regulating valve found closed Caused by maint procedure not specifying opening of valve
  BTANLEY.H B Hetropolitan Edison Co 79/00/02 App
- 790022031B Forwards LER 79-010/034-0
  HERBEIN, J. O Hetropolitan Edition Co. 79/00/02 ip
- ---7905220325 LER 79-010/03L-0 on 790411 while in hot shutdown, reassignment of personnel to Unit 2 prevented surveillances re chemistry & radiological analysis at proper frequency Missed surveillances subsequently performed HITCHELL, D. O. Metropolitan Edison Co. 79/05/02 2pp

- DOCKET NO-273 PHIGRIM NUCLEAR POWER GRATION, UNIT 1

  F. Security, medical, amongoncy & fire protection plans
- 7909010942 Forwards Revision 4 of modified physical security plan Plan withheld (ref 10CFR2 790) ANDOORINE G. Buston Edison (n - 79704/23 ) ip
- O Adjudicatory correspondence
- 7907020,000 forwards complaints no new class artion against Boston Edison Co. et al. commenced by Plymouth County Nuclear Into Committee, inc. et al flummons under & class action complaint encl MAZZONE, J. American Nuclear Insurers. 79704726 49pp
- 7905060504 Notifies that claim has been filed against util by Plymouth County Nuclear Info Committee Forwards CA 29 B986, motion for appointment of special process server & summons & order of notice
  AMBOGNIMI, G ( Roston Edison Co 29/05/01 ROUP
- J Insurance & indemnity information
- 7905070497 Confirms increased liability limit to \$124,000,000 for policies H 1,25,41,76,(1),100,115,140,146,151,161,164,170, 173,174,171,179,100,102,103,105,106,107,101,109,107,193,194,179,197,190,200,201,204,207,200,210,212,214,215,5 athers WATTROUBLE J American Nuclear liquid at 72707701 in
- 7905070502 Confirms increase in liability limit to \$36,000,000 for policies MI J2,26,29,500, 94,44,46,47,50,51,52,71,94,55,56,57,60,64,66,67,60,69,70,71,72,74,76,77,70,79,00,06,07,00,91,92,93,94,95,576
  ROBERTG,D M Motual Atomic inergy trability Underwritters 29705701
- 7909160100 Farwards Amond D to Indomnity Agreement D 466 per 10641140 changes, re liability inercance increase from \$140 million to \$160 million-effective 220001 Upporting documentation end BALEZMAN, J Autitiost 5 Indomnity Order 77/05/01 9pp
- 7909290208 torwards executed Amend O to Indemnity Agreement D 49 FOULGHAM, P. A. Doston Edison Co. 29705722 Tpp
- P. Operating license stage documents & correspondence
- /905170210 Hubmits schedule for implementation & resolution of Mark 1 containment long term program model in response to NRC request ANDONINI.9 C. Hoston Edison to 79705709 dep
- 7905150797 Forwards responses to question is comparison of projected population densities in PBAR 5 1978 update to 1974 with selection study BUTIER.R H. Boston Edison Co. 29705719. 14pp
- 7905J0020B Forwards summary of FDB Nuclear, Inc resolution/documentation of albow flexibility error which existed in versions of PIBDs pipting analysis computer program from Jan Oct 1969 Review & reanalysis in load all work through Dec 1970 PORTER, F i FDS Nuclear, Inc 79703/21 9pp
- -7705.100263 Forwards 505 Nuclear, Inc list of BHRs & piping syr could have been impacted by deficient computer program GE has no record of reanalysis for Cooper piping sys STEPHERS, P. W. General Electric Co., Nuclear Energy Product 79701/24 18pp
- G inspection reports: It Dullsting & correspondence
- /905010100 Purwards IE Into Notice /9 Ob. "Stress Analysis Gafety-Related Piping" ORICE: B. H. Regton I. Philadelphia, Office of the Direc /9/03/2J to
- 7905030266 Parwards II. Info Notice 79-07. "Rupture of Radwa ORIER, B. H. Region i. Philadelphia. Office of the Direc /9/03/26. Is
- 7905010034 Forwards IE Into Notice 79 00, "Interconnection Contaminated Bys w/Bvc Air Bys Used as Bourre of Breathii Air "
  Air "
  GRIER.B H Region i. Philadelphia. Office of the Bire.
  79/03/20 is

- 7905010282 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin" ORIER.8 H Region 1, Philadelphia, Office of the Director 79/03/30 1p
- 7905020026 Forwards IE Bulletin 79-06, "Review of Operational Errors & Bus Misalignments Identified During TMI Incident " GRIER B H Region I, Philadelphia, Office of the Director 79/04/11 ip
- 7905020357 Forwards IE Bulletin 79-07. "Seismic Stress Analysis of Safety-Related Piping " Licensee action required ORIER.8 H Region 1, Philadelphia, Office of the Director 79/04/14 1p
- 7905030324 Forwards IE Bulletin 79-06B. "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "ORIER.B H Region I. Philadelphia. Office of the Director 79/04/14 1p
- 7905040167 Forwards IE Bulletin 79-08. "Events Relevant to Boiling Mater Power Reactors Identified During TMI Incident " Licensee action required ORIER, B H Region 1. Philadelphia, Office of the Director 79/04/14 1p
- 7908030052 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Bafety-Related Bys " Licensee action required GRIER, B H Region 1, Philadelphia, Office of the Director 79/04/17 tp
- 7905010532 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TKI Encident "
  ORIER.B H Region 1. Philadelphia, Office of the Director 79/04/18 1p
- 7705310332 Provides supplemental info to initial response to IE Builetin 79-07 & to LER 79-014 Reanalysis of all lines indicates all stresses remain below code allowables All snubbar locations were verified by insitu insp
- R Periodic operating reports & related correspondence
- 7905160420 Forwards monthly operating rept for Apr 1979 MCGUIRE P J Boston Edison Co 79/03/08 1p
- ---7905160423 Monthly operating rept for Apr 1979 MATHIS.C J Boston Edison Co 79/09/08, App
- 8 Reportable occurrences. LERs & related correspondence
- 7905010536 Forwards LER 79-012/01X-0 MCGUIRE, P. J. Boston Edison Co. 79/04/24 ip
- --7900010540 LER 79-012/01X-0 on 790424 util informed that DAPS computer program used by GE for seismic analysis is not consistent w/current requirements. Caused by state-of-the-art applied during design of Pilgrim Affected piping reanalysed MATHIS.C J Boston Edison Co 79/04/24. Ip
- 7905020261 Forwards LER 79-013/03L-0 MCGUIRE, P. J. Boston Edison Co. 79/04/26, ip
- --7903020267 LER 79-013/03L-0 on 790331.during GPER-07 surveillance testing drywell to suppression chamber pressure was less than 1 30 paid on pressure instruments PI-3067 A & B, while greater than 1.30 elsewhere Caused by setpoint drift MATHIS, C J. Boston Edison Co 79/04/26 ip
- 7905140244 Forwards LER 79-012/017-1 MCGUIRE.P J Boston Edison Co 79/05/08 ip
- ~-7905140247 LER 79-012/01T-1 on 790424.seismiz analysis computer program for main steam & recirculation piping gave unsatisfactory results Caused by outdated state-of-the-art. Different program gave satisfactory results MATHIS: C J. Boston Edison Co 79/05/08 2pp
- 7905170235 Requests extension until 790708 for weld & hydrostatic testing program ANDOONINI.O. C Boston Edison Co. 79/05/08 lp.
- 7905150555 Forwards LER 79-014/01X-0, MCGUIRE, P. J. Boston Edison Co. 79/05/09 1p

- --- 7903190508 LER 77-014/01X-0 on 790507 four recirculation systylers, shubbers failed to satisfy Tech Spec requirements for operability under design basis earthquake loading Caused by design error Shubbers will be modified fULTON.J M Boston Edison Co 77/05/09 ip
- 7905180554 Forwards LER 79-015/03L-0 MCGUIRE.P J Boston Edison Co 79/05/11 ip
- --79051505B9 LER 79-013/03L-0 on 790415 reactor core isolation cooling barametric condenser condensate pump tripped Caused by tarnished relay contacts in pump starting logic Contacts clasmed & pump loads successfully tosted FULTON.J M Boston Edison Co 79/05/10 ip
- 7903290075 Forwards LER 79-017/03L-0 MCGUIRE P J Boston Edison Co 79/03/22 1p
- ~~7905290100 LER 79-017/03L-0 on 790429 control rod 26-27 unresponds insert signal Cause undetermined Corrective actions relay contacts & relay socket contacts on relay 3A-KL32 apray cleaned MATHIS, C. J. Boston Edison Co. 79/05/22 ip
- 7905300472 Forward's LER 79-016/03L-0 MCGUIRE,P J Boston Edison Co 79/05/23 1p
- ~~7705300492 LER 79-016/03L-0 on 770511 inagerable snubber inside drywell Caused by snubber 0065 (Bergen-Patterson Model 165 A10-6) being disconnected New snubber installed on 770512 FULTON J M Boston Edison Co 77/09/22 2pp
- 7905300535 Forwards LER 79-018/01X-0 MCQUIRE,P J Boston Edison Co 79/08/23 1p
- --7903300543 LER 79-018/01X-0 on 790519 recirculation pump P-201A Mi. w/reactor coolant temp greater than 212 F.primary containment integrity not maintained & delta temp between loops greater than 50 F Caused by operator error MATHIS.C J. Boston Edison Co. 79/05/23 1p
- DOCKET 50-294 MICHIGAN STATE UNIV RESEARCH REACTOR
  J Insurance & indemnity information
- 7905160240 Forwards Amend 9 to Indemnity Agreement E-51.psr 10CFR140 changes.re increase from \$140 million to \$160 million, affective 790801 Supporting documentation encl SALTZMAN, J Antitrust & Indemnity Oroup 79/05/01 5pp
- Q. Inspection reports. IE Bulletins & correspondence
- 7905040161 Ack receipt of 790404 & 0407 ltrs informing NRC of stays taken to correct noncompliance noted in NRC 790221 ltr HEIBHMAN R F Region 3. Chicago, Reactor Operations Nuclear Support Branch 79704/20 ip
- --7905040165 Responds to NRC 790221 ltr re noncompliance noted in [#1]: 790131-0202 Corrective actions 1979 requalification stam will be given to operators during Apr TERRY,S H. CARRICK,J T. Hichigan State 79/04/07 ip
- --7905040168 Responds to NRC 790221 ltr re 790131-0202 Insp Details Annual audit TERRY,8 H . GARRICK, J. T Michigan State 79/04/04 1p
- DOCKET 50-295 ZION NUCLEAR POWER STATION, UNIT 1 E NRC Safety Evaluation Report (SER), supple & correspondence
- 7905240795 Forwards SER & EIA re plant spant fuel pool mode H/o enti-GDDDARD, R. J. Branch 2 79/04/03, 1p
- F Security, medical, emergency & fire protection plans
- 7909030366 Forwards modified physical security plan, Revision 5 Plan, withheld (ref 10CFR2 790). LEE, B. Commonwealth Edison Co 79/04/26 ip
- 7905290079 Forwards Chemtron drawings FL27652-7, sheets 1 through 5, w/design details for fire suppression sys to be installed for auxiliary feedwater sys & component cooling pumps. Oversize drawings enci.

  NAUGHTON, N. F. Commonwealth Edison Co. 79/05/23 2pp.

- Q Adjudicatory correspondence
- 7905230768 Affidavit of M Hasnikoff is spent fuel issue Professional 70320708 ATTIGATE OF A RESERVED OF EVE SICE Qualifications & Certificate of Eve sice REGNIKOFF, M R - Illinois, State of 79/02/23 12pp
- 7905300711 Responds to Otate of IL's 790221 motion for continuance & request to allow future supplementation of intervenor's affidavits Centificate of fluc end.
  ODDDARD R J. Branch 2 79707/13 4pp
- 7909070194 Ferwards UER & FIA is spent fuel pool mods H/o encl c/MDARD, R J Branch & 79704707 to
- 7905250198 Provides list of witnesses for util in Zion spent fuel case STLPTO(.P. Isham: Lincoln & Beale 79704703 dpp
- 7903300022 Request by util on its own behalf & on behalf of Btate of IL & NRC.fnr ABIII to begin hearings on 790314 Certificate of Bvc encl
- SIELANSKI, A.P. Isham, Lincoln & Deale 79/04/06
- 7905100121 Interrogatories submitted to state of II per AULD 790119 order Certificate of Byc encl QUDDARD R J Branch 2 79704709 4pp
- /905150286 Mution to file supplementary affidavits to response to util & NRC motions for summary disposition Affidavits of DG Bridenbaugh & QC Minor & Gertificate of Ove entil BIRULIN:N 1111nois. Biate of 79704/10 Jipp
- 7905150240 Forwards unexecuted affidavit of M Reenthoff Contificate of Eve encl BURULTRIER | Tilinois | Heate of 79704711 App
- 7905180691 Forwards Chapter i of MAND27 1971. "Brent Fuel Heatup Fullowing loss of Mater During Diorage." which contains info-relevent to util's application to increase spent fuel storage pool capacity Requests to be placed on svc list MEBD.R E. Affiliation Onknown 79704719 40pp
- 7905230367 Hoves for summary disposition of fitate of life Contention 2(a)-(d) for last of genuine issue of mail fact Affidavits, notices of appearance & withdrawal & factificate of five encl qui britro, a c Branch 2 79704727 20pp
- 790518024'l Denies summary disposition of intervenors' Contentions 2(f) (2),2(g),2(h) & 2(i) Grants summary disposition of intervenors' Contention 2(n) to toward Contention 2(n) to toward Panel 79705701 Opp
- H General correspondence
- 7905070014 Responds to 790202 Its requesting info re leakage of water through liner of spent fuel pool at facility NHC is monitoring util's efforts to control seepage GTELLOV Division of Operating Reaction 27/04/19 79pp
- J Insurance & Indomnity information
- 7905100163 Endorsement V4 to HARLU Policy N° 22 OCRAS, Y Nuclear Energy (lability Insurance Association 79/03/27
- 7905070502 Confirmt increase In liability limit to 436.000.000 for policies HF R2.26.27.38.39.44.46.47.49.50.51.52.53.34.55.36.57.88.60.61.64.66.67.69.69.70.71.72.74.76.77.78.74.00.86.97.88.90.91.92.91.94.47.5.76.
- 7905140470 Forwards Amend 9 to Indemnity Agreement 8-59 per 10CFR140 changes, re increase in liability insurance from \$140 million to \$160 million.effective 790501 Hupporting documentation BALTZHAN, J Antitrust & Indomnity Group 79/05/01 App
- 7905160399 Confirms 79050/ & OB agreement w/NRC that Westinghouse need not sign Amend 7 to Indemnity Agreement 8-56 CAMP.Q T. Johnson & Higgins Insurance 79/05/09 1p

- 7905210262 Forwards Endorsements 58 & 39 to NELIA Policy NF-187 & Endorsements 47 & 48 to NELIA Policy NF-201 OSTER.J Commonwealth Edison Co 79/05/16 4pp
- P Operating license stage documents & correspondence
- 7905250103 Amends 47 & 44 to Licenses DPR-39 & DPR-48, respectively, revising Yech Specs re rod drop time
  BCHWENGER, A Operating Reactors Branch 1 79/04/09 App
- --790928010/ Gafaty evaluation supporting Amends 47 & 44 to Licenses DPR-39 & DPR-40/respectively \* Office of Nuclear Reactor Regulation 79/04/09 3pp
- --7905250190 Notice of issuance & availability of Amends 47 & 44 to Licenses DPR-39 & DPR-48 respectively 8CHMTNGER: A Operating Reactors Branch 1 79/04/09 2pp
- 7905040402 Notifies of intention to develop safety analysis using existing computer codes Requests add1 info EOSLIBIO: C W Gommonwealth Edison Co 79/04/26 ip
- 7905040302 Requests amond to Toch Opecs to require actuation of safety injection based on two out of three channels of low pressure pressure & to delete pressurizer level from safeguards logic Class I & II amend fees onc!

  RED.G Commonwealth Edison Co. 79/04/30 9pp
- 7905100251 "Oamma Dose Measurements at Zion & Fort Calhoun Blations " DYFR:N C : BUNTING:R L : NIFBCHMIDT.E B EO & G: Inc FIN A-6075 NUREO/CR-0/55 /9/04/30 137pp Available at NTIE \$7 25
- 7909070396 Forwards response to request for add1 info re review of proposed literae amend to increase allowable LOCA peaking factor limit to 1.9.7 based on ECCB reanalysis NAUQHITON.N F. Commonwealth Edison Co. 79703703 App
- 7905270425 Forwards Amends 49 & 46 to Licenses DPR-39 & DPR-48, respectively, safety evaluation & notice of Issuance & availability Operating Reactors Branch 1 79/05/03 2pg DCHUENCER: A
- --7905250432 Amenda 47 & 46 to Licenses DPR-39 & DPR-4D, respectively DGHARRCER, A Operating Reactors Branch 1 79/05/03 14pp
- 7905200415 Gafaty evaluation supporting Amends 49 & 46 to Licenses DRR 39 & DPR-4D respectively (perating Reactors Branch : 79/04/03 3pp.
- ---/903250440 Notice of issuance & availability of Amends 49 & 46 to [Lenses DPR-39 & DPR-40, respectively GCHBANGERIA Operating Reactors Branch 1 79/05/03, 2pp
- 7905170217 Forwards revised Tuch Specs re heating & cooldown curves & added provision for overpressure protection.

  RIED. C. Commonwealth Edison Co. 79708/11. 2pp
- -- 79051/0255 Revised Tech Hours to heatur & cooldown survey & added provision for overpressure protection \* Commonwealth Edison Co. 79/05/11
- /70525039) Forwards current licensing open items status list RED, C. Commonwealth Edison Co. 79/05/10 tipp
- O Inspection reports, IE Bullatins & correspondence
- 7905020421 Forwards response to IE Bulletins 78-12 & 78-12A: "Atypical Weld Hetl in Reactor Pressure Vessel Welds."

  HEED: C Commonwealth Edison Co 79/03/22. 10pp
- 7905010236 Forwards IC Info Notice 79-06, "Btress Analysis of Bafety-Related Piping"
  KEPPLER.J Q. Region 3, Chicago, Office of the Director 79/03/23
- 7903030370 Forwards IE Info Notice 79-07, "Rupture of Radwasta Tanks " KEPPLER.J O. Region 3. Chicago, Office of the Director. 79/03/26
- 7903010135 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Syc Air Sys Used as Source of Breathing Air " Keppler, J Q Region 3, Chicago, Office of the Director 79/03/28
- 7905140084 Forwards IE Insp Repts 80-295/79-05 & 50-304/79-06 on 790321-23 No noncompliance noted.
  HEIBHMAN.R.F Region 3, Chicago, Reactor Operations Nuclear Support Branch. 79/03/28. 2pp
- --7905140087 IE Insp Repts 50-295/79-05 & 50-304/79-06 on 790321-23 No noncompliance noted Major areas inspected preparations made for refueling & maint during refueling putage DANIELS, F T., LITTLE, H S. BOVD, D C. Region 3. Chicago, Office of the Director 79/03/28 3pp

- 7405010034 Fortands IE Info Notice 79-09, "Spill of Radioactively Contaminated Rain"

  KEFFLER J G Region 3 Chicago, Office of the Director 79/03/30
  16
- 790503DC07 Forwards IE Builetin 79-06, "Review of Operational Errors & Eys Misalijanents Identified During TMI Incident " Licenses action required action required Region 3. Chicago, Office of the Director 79/04/11
- 7709250260 Responds to IE Bulletin 79-03 re welding defects in cortain longitudinally welded pipe apools Plants inspecteding pipe found

REED.C Commonwealth Edison Co 79/04/12 2pp

- 7703010972 Forwards IE Bulletin 79~06A, 'Review of Operational Errors & Sys Misalignments Identified during YMI Incident " Licenses action required #FFFEER.J G Region 3, Chicago, Office of the Director 79/04/14
- 15
  7705040334 Forwards IE Bulletin 79-06B. "Review of Operational Errors:
- 7705040334 Forwards IE Bulletin 79-06B. "Review of Operational Errors & Sys Misalignments Identified During IMI Incident "
  XEPPLER J G Region 3 Chicago, Office of the Director 79/04/14
  1p
- 7905040527 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident "
  KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/14
- 7905030206 Forwards [E Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breater in Safety-Related Sys " Licensee action required KEPPLER.J G Region J. Chicago. Office of the Director 79/04/17
- 7705040142 Forwards IE Bulletin 79-05B, "Nuclear Incident at TM1-Suppl"
  KEPPLER, J G Region 3, Chicago, Dffice of the Director 79/04/21
- --7905040158 IE Bulletin 79-05B, "Nuclear Incident at THI-Suppl"
  Supporting documentation encl
  Region 3. Chicago. Office of the Director 79/04/21 12pp
- --7905040170 ACRS recommendations re 790328 incident at TMI Suggests high priority be placed on development of safety research on behavior of LMRs during amonalous transients

   ACRS Advisory Committee on Reactor Safeguards 79/04/17
- --7905040201 Forwards ACRS recommendations re TMI incident, presented on 790417 FRALEY, RF ACRS - Advisory Committee on Reactor Safeguards 79/04/18 in
- \*\*-7905040221 In response to NRC 790418 itr.states all 790417 ACRS recommendations apply to all PHRs.but were not intended to require immediate changes Plant mods should be made after study of effects on overall safety. THI excluded CARBON.H X ACRS \*\* Advisory Committee on Reactor Safeguards 79704/20 2pp

- --7905090323 "Annual Operating Rept 1978 " \* Commonwealth Edison Co 79/04/26 24pp
- 5 Reportable occurrences, LERs & related correspondence
- 7905020272 Forwards LER 79-024/03L-0
  MANDKE:N E Commonwealth Edison Co 79/04/25 Lp
- --7905020282 LER 79-024/03L-0 on 790326 during normal operations discovered channel IL-538 was 4% higher than other ID state steam generator channels Fischer-Porter transmitter representator unknown reasons Zero reset HANSEN.P Commonwealth Edison Co 79/04/25 (p
- 7905240943 Forwards LER 79-029/03L-0
  HANDKE, N E Commonwealth Edison Co 79/05/08 is
- --- 7905240546 LER 79-029/03L-0 on 790408 during normal operation discovered low reading on pressurizer level channel it 4% Caused by transmitter drift (Barton DP XMTR Model 1864) Adjustment made ROGERS, C. L. Commonwealth Edison Co. 79/05/08 1o.
- 790524053B Forwards LER 79-031/03L-0 WANDXE,N E Commonwealth Edison Co. 79/05/09 19
- --7905240541 LER 79-031/03L-0 on 790416 instrument failure alses for containment purge exhaust iodine monitor repeatedly alarase Event repeated after alarm repaired Caused by poor solder possibly causing short circuit MEYER, B A Commonwealth Edison Co 79/05/09 [p
- DOCKET 50-296 BROWNS FERRY NUCLEAR POWER STATION, UNIT 1
  J Insurance & indemnity information
- 7905140462 Forwards Amend 12 to Indomnity Agreement 8-32 per 1 fracts changes, re increase in liability insurance from \$140 million to \$160 million, affective 790501 Supporting documentation enci
  SALTZMAN. Antitrust & Indomnity Group 79/05/01 489
- 7905080390 Forwards Endorsement 47 to ANI Policy Nr--198 FIELDER, J. Marsh & McLenon, M & H. Nuclear Consultants. Inc. 51: 79/05/03 2pp
- 7905080394 Forwards Endorsement 40 to ANI Policy NF-190 FIELDER,J Marsh & McLanon, M & M Nuclear Consultants. In: Car 79/05/03 2pp
- K Utility Final Safety Analysis Report (FBAR) & amends
- 7905110024 Forwards Amend 68 to FBAR, OILLELAND, J E Tennesses Valley Authority 79/05/00 201
- --7905110031 Amend 68 to FBAR. W/oversized drawings.
  \* Tennessee Valley Authority. 79/05/08 100ee
- P. Operating license stage documents & correspondence
- 7905080033 Ack receipt of Class II fee & application for exert is Licenses DPR-33, DPR-52 & DPR-68 Requests payment of addites fee MILLER, H O License Fee Management Branch 79/04/04 is
- 7905290352 Proposes meeting w/Bandia address final test plan. bited so review of 790216 second draft of Bandia connector test plan. List of items needing resolution enci.

  STELLO, V Division of Operating Reactors 79/04/19 4pp
- 7905110177 Submits schedule for torus mods, in response to PAPC TYPES12 ltr to HO Parris GILLELAND, J.E. Tennessee Valley Authority, 79705/04 Sep
- 7905110211 Confirms plans for feedwater noxile insp during fatt late refusing outage, as well as feedwater sparger final fit mgd. clad removal & ultrasonic test GILLELAND, JE Tennessee Valley Authority, 79/05/07 ip
- 7905300208 Forwards summary of EDB Nuclear, Inc resolution/documents of albow flexibility error which existed in versions of FISOL piping analysis computer program from Jan-Oct 1969 Review & reenalysis included all work through Dec 1970 FORTER, F. L. EDB Nuclear, Inc. 79/03/21 9pp

- --7905300263 Forwards EDS Nuclear Inc list of BHRs & piping sys which could have been impacted by deficient computer program QE has no record of reanalysis for Cooper piping sys STEPHENS.P W General Electric Co , Nuclear Energy Products Div 79/01/24 18pp
- G Inspection reports. IE Bulletins & correspondence
- 7905180103 Forwards IE Insp Repts 50-259/79-04, 90-260/79-04 & \$0-296/79-04 on 790102-0202 No noncompliance noted O'REILLYJ P Region 2. Atlanta, Office of the Director 79/03/22 2pp
- ---7903150107 IE Insp Repts 50-259/79-04.50-260/79-04 & 50-296/79-04 on 790102-0202 No noncompliance noted Major areas inspected plant operations refueling & restart of Unit 1, plant tour & liquid radwaste processing SULLIVAN.R F Region 2. Atlanta, Office of the Director DANCE, H C Region 2. Atlanta, Reactor Operations Nuclear Bupport Branch 79/03/19 7pp
- 7903D10211 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping" O'REILLY.JP Region 2, Atlanta, Office of the Director 79/03/23 2pp
- 790313013B Forwards IE Insp Repts 50-259/79-05.50-260/79-05 & 30-276/79-05 on 790226-0302 No noncompliance noted LEMIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/23 2pp
- --7905180147 IE Insp Repts 50-259/79-05.50-260/79-05 & 50-296/79-05 on 790226-0302 No noncompliance noted Major areas inspected reportable secondary containment leak rate testing. IE circulars & bulletins PRICE.D S Region 2. Atlanta. Office of the Director DANCE.H C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 79/03/22 6pp
- 79050(0113 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys W/Svc Air Sys Used as Source of Breathing Air " O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/28 200
- 7905010363 Forwards IE Info Notice 79-09. "Spill of Radioactively Contaminated Resin" O'REILLY, J.P. Ragion 2, Atlanta, Office of the Director 79/03/30 2pp.
- 79030801/6 Responds to IE Bulletin 79-03 No evidence that any stainless steel pipe mfg by Youngstown Welding & Enginearing Co was Used in any ABME Class I. II or III safety-related sys OILLELAND.JE Tennesses Valley Authority 79/04/12 ip
- 770503036B Forwards IE Bulletin 79-07, "Beismic Stress Analysis of Bafsty-Related Piping." Licenses Action required O'REILLY, J P Region 2, Atlanta, Office of the Director 77/04/14. 3pp
- 7908040233 Forwards IE Bullatin 79-06B, "Review of Ogerational Errors & Sys Misalignments Identified During TM1 Incident "
  O'REFELY, J P Region 2, Atlanta, Office of the Director 79/04/14 3no
- 7905150700 Forwards IE Bulletin 79-08, "Events Relevant to BWRs Identified During TMI Incident " Licensee action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/04/14, 2pp
- 7905030172 Forwards IE Bullstin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " Licenses action required Circuit Region 2, Atlanta, Office of the Director 79/04/17. 2pp
- 7905020479 Forwards IE Bulletin 79-06A, Revision i, "Review of Operational Errors & Sys Misslignments Identified During TMI Incident"
  O'REILLY, J. P. Region 2, Atlanta: Office of the Director 79/04/18, 29p.
- 7905250344 Forwards response to Item 7 b of IE Insp Repts 50-259/79-05, 50-260/79-05 & 50-296/79-05 re deterioration of Buna-N components in ASCO solenoids, as followup to IE Bulietin 78-14. OILLELAND, J. E. Tennessee Valley Authority. 79/04/20. Gpp.
- 7905300745 Forwards response to IE Bulletin 79-08 Plant superintendent will present review of TMI incident to all managers & supervisors w/operational responsibilities Containment isolation design & procedures have been reviewed.

  QILLELAND, J E Yennessee Valley Authority 79/04/25 14pp

- 7905240947 Ack receipt of 790423 itr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-259/79-07, 50-260/79-07 & 50-296/79-07
  SUTHERLAND, J T Repion 2. Atlanta, Fuel Facility & Materials Bafety Branch 79/04/30 2pp
- --7905240972 Responds to NRC 790330 ltr re violations noted in IE Insp. Repts 50-259/79-07, 50-260/79-07 & 50-296/79-07 Corrective actions entire radwaste hidg properly posted as radioactive area GILLELAND, F. E. Tennessee Valley Authority 79/04/23 App.
- --7905240992 Forwards IE Insp Repts 30-259/79-07.30-260/79-07 & 30-296/79-07 on 790226-0302 & notice of violation SUTHERLAND.J T Region 2. Atlanta, Fuel Facility & Materials Bafety Branch 79/03/30 2pp
- --7905241003 Notice of violation from insp on 790226-0302
  \* Region 2, Atlanta, Office of the Director 79/03/30 2pp
- ---7905241005 IE Insp Repts 50-259/79-07,50-260/79-07 & 50-276/79-07 on 790226-0302 Noncompliance noted failure to post radiation area, label containers of radioactive matl & barricade high radiation area

  JACKSON, L Region 2, Atlanta, Office of the Director GIBSON, A F Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/03/29 2pp
- 7905240652 Forwards responses to IE Bulletin 79-04 re incorrect swing check valve weights Corrected valve weights do not create any overstressing in pipes hangers or supports Addl info will be provided by 790811 GILLELAND. J E Tennessee Valley Authority 79/05/01 App
- 7905150322 Forwards addl inservice insp program revisions based on further review & comperison of facility design w/respect to ASME boiler & pressure vessel code requirements GILLELAND.J E Tennessee Valley Authority 79/05/08 21pp
- R Periodic operating reports & related correspondence
- 7905030343 Forwards "Environ Radioactivity Levels, Annual Rept 1978 " OILLELAND, J E Tennessee Valley Authority 79/04/27 1p
- --7905030349 "Environ Radioactivity Levels Annual Rept 1978 "
  \* Tennessee Valley Authority MRH-79-3-BF2 79/04/27 50pp
- 7905010475 Forwards "Fish Impingement Rept" for first quarter 1979 GILLILAND.J E Tennessee Valley Authority 79/03/01 2pp
- --7905010476 "Fish Impingement Rept" for first quarter 1979 \* Tennesses Valley Authority 79/05/01 14pp
- 7905150346 Forwards monthly operating rept for Apr 1979
  DEWEASE, J G Tennessee Valley Authority 79/05/09 1
- --7905150352 Monthly operating rept for Apr 1979
  DENEASE, J Q Tonnesses Valley Authority 79/04/30 36pp
- S Reportable occurrences. LERs & related correspondence
- 7905110196 Forwards LER 79-004/03L-0 FOX.H S Tennessee Valley Authority 79/05/07 is
- ---7905110201 LER 79-004/03L-0 on 790411 during normal operation, heat detector alarmed & would not clear Alarm would have masked signals from other detector, required to be operational Caused by personnel damaging detector \* Tennessee Valley Authority 79/05/07 2pp

790531 FOX

- \* Tennéssee Valley Authority /7/00/10 <- Pp.
- DOCKET 50-297 NORTH CAROLINA STATE UNIV. PULSTAR REACTOR
  G. Inspection reports, IE Bulletins & correspondence
- 7905070146 Forwards IE Bulletins 79-05,79-05A & 79-06,re nuclear incident at TMI. O'REILLY,J P. Region 2. Atlanta, Office of the Director. 79/04/13. 1p

# DOCKET 50-298 COOPER NUCLEAR STATION

- A Application/construction stage documents & correspondence
- 7905140228 Forwards schedule for implementation & resolution of Mark I containment long-term program in response to 790312 ltr PILANT, J M Nebraska Public Power District 79/05/07 Spp
- F Security, medical, emergency & fire protection plans
- 7905230355 Forwards modified physical security plan Plan withheld (ref 100FRZ 790) PILANT, J. H. Nebraska Public Power District 79/05/16 ip
- I Financial information
- 7903080487 Forwards "Annual Financial Rept 1978 "
  PILANT, J K Nebraska Public Power District 79/05/04 ip
- ---7905080495 "Annual Financial Rept 1978 "
  \* Nebraska Public Power District 79/05/04 39pp
- J Insurance & indemnity information
- 7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,185,186,187,188,189,192,192,193,194,195,197,198,200,201,204,206,207,208,210,212,214,215,5 others guatracchill, American Nuclear Insurers 79/03/01 1p
- 7903130365 Forwards Amend 9 to Indomnity Agreement B-57, per 10CFR140 changes re increase from \$140 million to \$160 million effective 790501 Supporting documentation encl
  SALTZMAN, J Antitrust & Indomnity Group 79/05/01 Spp
- 7905150384 Forwards executed Amend 9 to Indemnity Agreement 8-57 PILANT, J M Nebraska Public Power District 79/05/08 3pp
- 7905140127 Forwards Endorsaments 45 & 46 to NELIA Policy NF-200 PILANT, J M Nebraska Public Power District 79/05/11 Spp
- P Operating license stage documents & correspondence
- 7905:10001 Forwards Amend 55 to License DPR-46, safety evaluation & notice of iscuance & availability
  IPFOLITO, T A Operating Reactors Branch 3 79/04/27 2pp.
- --7905110002 Amend 55 to License DPR-46, revising App A & B of Tech Space re primary containment & reactor vassel isolation instrumentation 
  IPPOLITO T A Operating Reactors Branch 3 79/04/27 25pp
- ---7905110003 Safety evaluation supporting Amend 55 to License DPR-46 \* Office of Nuclear Reactor Regulation 79/04/27. 13pp
- ---7905110005 Notice of issuance & availability of Amend 55 to License DPR-46 IPPOLITU.T A Operating Reactors Branch 3 79/04/27. 2pp.
- 7905020269 Forwards fee payment for Amends 39 & 40 to PBAR Disagrees w/imposition of Class III fees
  PILANT, J F Nebraska Public Power District. 79/05/02 1p.
- 7905080478 Requests that GE rept NEDO-25070, "Analytical Model for Estimating Drag Forces on Rigid Submerged Structures Caused by Condensation Decillations & Chugging" be included in docket PILANT, J M. Nebraska Public Power District, 79/05/04, 1p
- 7905300208 Forwards summary of EDS Nuclear, Inc resolution/documentation of elbow flexibility error which existed in versions of PISOL pipling analysis computer program from Jan-Oct 1969 Review & reanalysis included all work through Dec 1970. PORTER, F L. EDS Nuclear, Inc. 79/05/21, 9pp.
- --7905300263 Forwards EDS Nuclear Inc list of BWRs & piping sys which could have been impacted by deficient computer program.

  OE has no record of reanalysis for Cooper piping sys.

  STEPHENS.P W General Electric Co., Nuclear Energy Products Div 79/01/24 18pp

## @ Inspection reports: IE Bulletins & correspondence

- 7905150083 Forwards IE Circular 79-04. "Loose Locking Not on Limitory, Valva Operators "
  BEYRRIT.K V Region 4. Dallas. Office of the Director 79/03/15
  in
- 7905010451 Forwards IE Builetin 78-128, "Atupical Weld Mati in Resitt-Pressure Vessel Welds" SEYFRIT,K V Region 4, Dailas, Office of the Director 79/03/19
- 7905020444 Forwards IE Circular 79-05, "Moisture Leakage in Stranf)f Mire Conductors " SEYFRIT,K V Region 4, Dallas, Office of the Director 79/03/2;
- 7905020273 Forwards IE (nfo Notice 79-06, "Stress Analysis of Safety-Related Piping" SEYFRIT, K V Region 4, Dallas, Office of the Director 79/03/21
- 7905020415 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanit' SEVERIT, K.V. Region 4, Dallas, Office of the Director 79/09/2)
- 7905020428 Forwards IE Info Notice 79-08. "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air " BEYFRIT, K V Region 4. Dallas, Office of the Director 79/03/26
- 7905020122 Ack receipt of 790301 ltr informing NRC of steps taten to correct violations noted in IE Insp Rept 50-298/79-02 HADSEN, O L Region 4, Dallas, Reactor Operations Nuclear Supply Branch 79/03/29 ip
- --7905020127 Responds to NRC 790213 ltr re violations noted in IE Imp. Rept 50-278/79-02 Corrective actions alcohol removed from reactor room floor & importance of procedures stressed to employees
  PILANT.J M Nebraska Public Power District 79/03/01 3pp
- 7705140148 Forwards IE Bulletin 77-04, "Incorrect Weights for Swing Check Valves Mfg by Velan Engineering Corp " Licensee action required SEYFRIT,K V Region 4, Dallas, Office of the Director 79/03/3) in
- 7905150046 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"

  EEVFRIT, K V Region 4, Dallas, Office of the Director 79/03/31
- 7905040557 Forwards IE Bulletin 79-060, "Review of Operational Errord Sys Misslignments Identified During TMI Incident" SEYFRIT.K V Region 4, Dallas, Office of the Director 79/04/11
- 7905040521 Forwards [E Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident "
  SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/11
- 7903070072 Forwards IE Bulletin 79-07, "Beismic Stress Analysis of Safety-Related Piping " Licensee action required BEYFRITIK V. Region 4, Dalles, Office of the Director 79/04/11
- 7905090103 Forwards suppl to IE Bulletin 79-05A, "Nuclear Incident II
  TMI "
  SEYFRIT, K V Region 4, Dailes, Office of the Director 79/04/6
  1s.
- 7905030277 Forwards IE Bulistin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Bys " Licensee action required, SEYFRIT.K.V. Region 4, Dailas, Office of the Director 79/04/17
- 7905080352 Forwards IE Bulletin 79-058, "Nuclear Incident at TMI-Buppl,"
  SEYFRIT, K V Region 4, Dallas, Office of the Director. 79/04/2
- R Periodic operating reports & related correspondence
- 7905150522 Forwards monthly operating rept for Apr 1979 LE68GR,L,C. Nebraska Public Power District 79/05/08. 1p

- --7905150526 Monthly operating rept for Apr 1979
  BORER, P & Nebraska Public Power District 79/05/08 400
- 8 Reportable occurrences, LERs & related correspondence
- 7905150120 Forwards PNO-79-67R & 79-77(NRR)
  MADSEN. 9 L Region 4. Dallas. Reactor Operations Nuclear Support
  Branch. 79/04/11 1p
- 7905040110 Forwards PND-79-678 MADSEN.G L Region 4. Dallas, Reactor Operations Nuclear Support Branch 79/04/12 1p
- 7905130258 Forwards PNO-79-67T correction MADSEN. O L Region 4. Dallas. Reactor Operations Nuclear Support Branch 79/04/13 1p
- 7905010530 Forwards PNO-79-67U, V & W MADSEN, Q L Region 4. Dallas, Office of the Director 79/04/16
- 7905010544 Forwards PNO-79-67X & Y MADSEN.G L. Region 4: Dallas. Office of the Director 79/04/18
- 7905010558 Forwards PNO-79-67Z MADBEN.9 L. Region 4: Dallas. Office of the Director 79/04/19 ip
- 7905140335 Forwards LER 79-007/03L-0 LESBOR.L C Nabraska Public Power District 79/04/20 2pp
- --7905140336 LER 79-007/OGL-0 on 790321 during core spray sys surveillance tesing, CB-MD-11A valve failed to reopen by remote switch Caused by axial movement of worm set clutch collar on limitorque BMB-2 operator FLANNIGAN,R D Nebraska Public Power District 79/04/20 1p
- 7905010375 Forwards PNO-79-676A: AB, AC & AD MADSEN, G L Region 4. Dellas, Office of the Director 79/04/24
- 7905150097 Forwards PNQ-79-67AF.AG.AH.AI & AJ.re nuclear incident at THI MADSEN.G L. Region 4. Dallas, Reactor Operations Nuclear Support Branch 79/04/30 1p.
- 7903240443 Forwards PNO-79-67AK & AL MADBEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/05/02 1p
- DOCKET 50-301 POINT DEACH NUCLEAR PLANT, UNIT 2

  F Security, medical, emergency & fire protection plans
- 7705300466 Submits proposed mods to fire protection plan as set forth in SER Recommends fire hydrant insp 5 supervision of valves controlling fire water sys HALL.R E. Brookhaven Netional Laboratory 79/04/27 3pp
- J Insurance & indemnity information
- 7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,23,43,76,83,100,111,140,145,151,161,164,170,173,174,178,177,180,182,185,186,187,188,187,172,173,174,175,177,178,200,201,204,206,207,208,210,212,214,215,&others QUATRACHHI, J American Nuclear Insurers. 79/05/01. 1p
- 7905140431 Forwards Amend 11 to Indemnity Agreement 8-41 per 10CFR140 changes re increase in liability insurance from \$140 million to \$160 million effective 790501 Bupporting documentation encl BALTZMAN.J Antitrust & Indemnity Group. 79/05/01 6pp
- 7905230463 Forwards executed Amend 11 to Indomnity Agreement B-41, per NRC 790501 request DONDAS, W J. Wisconsin Electric Power Co 79/05/17. 3pp

- P Operating license stage documents & correspondence
- 7905140513 Forwards Amends 35 & 41 to Licenses DPR-24 & DPR-27, respectively safety evaluation.EIA & notice of issuance & availability SCHWENCER.A Operating Reactors Branch i 79/04/04 2pp
- --7905140520 Amends 35 & 41 to Licenses DPR-24 & DPR-27, respectively authorizing installation & use of modified spent fuel storage racks in spent fuel pool, which increases capacity for storage from 351 assemblies to 1.502 assemblies ZEMANN, D L Assistant Director for Systems & Projects 79/04/04 24pp
- --7905140526 Bafety evaluation supporting Amends 35 & 41 to Licenses DPR-24 & DPR-27.respectively \* Office of Nuclear Reactor Regulation 79/04/04 16pp
- --7905140529 EIA of Amends 35 & 41 to Licenses DPR-24 & DPR-27, respectively \* Office of Nuclear Reactor Regulation 79/04/D4 33pp
- --7905140833 Notice of issuance & availability of Amends 35 & 41 to Licanses DPR-24 & DPR-27, respectively SCHWENCER, A Operating Reactors Branch 1 79/04/04 GPP
- 790510D439 Forwards Amends 37 & 42 to Licenses DPR-24 & DPR-27, respectively & notice of issuance & availability Security plan evaluation withheld (raf 10CFR2 790) SCHWENCER. A Operating Reactors Branch 1 79/04/13 3pp
- ---7903100442 Amends 37 & 42 to Licenses DPR-24 & DPR-27, respectively, implementing provisions of NRC-approved physical security plan SCHWENCER, A Operating Reactors Branch 1 79/04/13 4pp
- --7905100444 Notice of issuance & availability of Amends 37 & 42 to Licenses DPR-24 & DPR-27, respectively SCHWENCER, A Operating Reactors Branch i \* 79/04/13 3pp
- 7905150071 Forwards info in response to 790321 request re details of plant shutdowns
  DENTON.H R Office of Nuclear Reactor Regulation 79/04/18 App
- 7905020271 Request amends to Licenses DPR-24 & DPR-27, changing Tech Specs re initiation instrument setting limits for engineered safety features Forwards Class III amend fee, BURSTEIN, 8 Wisconsin Electric Power Co 79/04/27 7pp
- 7905240831 Responds to IE Bulletin 79-06A. Item 3 re TMI errors
  Pressurizer low level setpoint bistable returned to
  untripped position until logic change requested in 790427
  license amend is implemented
  BURBTEIN, B Hisconsin Electric Power Co 79/04/30 2pp
- 7905150202 Forwards addi info re reactor vessel weld & surveill, weld metals BURSTEIN, B Wisconsin Electric Power Co 79/05/04 5pp
- 7905150448 Forwards add1 info re Tech Spec Change Request 6. safety injection actuation circuitry mod to two out of the pressurizer low pressure logic Requests approval by 79051 to permit mods on 790512-13 & 790519-20 BURSTEIN 8 Wisconsin Electric Power Co 79/05/07 3pp
- 7905240397 Forwards drawings for piping & instrumentation f Section 3 of inservice test plan Encl 28 oversized drawin available in Central Files only BURGTEIN B Wisconsin Electric Power Co 79/05/17 7pp
- 7905300208 Forwards summary of EDS Nuclear Inc resolution/d of elbow flexibility error which existed in versions of PISOL piping analysis computer program from Jan-Oct 1969 Review & reanalysis included all work through Dec 1970 •\*\*ORTER.F L EDS Nuclear Inc 79/05/21 9pp
- --7905306263 Forwards EDS Nuclear. Inc list of BWRs & piping could hat been impacted by deficient computer program GE has no record of reanalysis for Cooper piping sys BTEPHENS, P. W. General Electric Co , Nuclear Energy Prod-79/01/24 18pp
- 7905310359 Submits formal responses to 790510 questionnairs pressurizer heater.loss of feedwater event & steam generator BURSTEIN.8 Wisconsin Electric Power Co 79/05/22 Epp

- 7905300453 forwards startup physics testing rapt re rod worth measurements which employ "rod swap" methodology Rept demonstrates adequacy of nuclear design rod worth
  - Wisconsin Electric Power Co 79/05/24
- 7903010142 Forwards IE insp Repts 20-266/79-04 & 50-301/79-03 on 790220-23 & notice of violation DAVIS,A B Region 3. Chicage, Fuel Facility & Materials Safety Branch 79/03/22 2pp
- ---790501015t Notice of violation from insp on 790220-23
  \* Region 3. Chicago, Office of the Director 79 79/03/19 lp
- --7905010160 IE insp Repts 50-266/79-04 & 50-301/79-03 on 790220-23
  Noncompliance noted failure to provide 7-day holdup of
  radioactive gas before release
  OREGER,L R. HIAFT, J W. Region 3, Chicago, Office of the
  Director FISHER, L Region 3, Chicago, Fuel Facility & Region 3, Chicago, Office of the Region 3, Chicago, Fuel Facility & 79/03/19 10pp Materials Safety Branch
- 7905010270 Forwards IE Enfo Notice 79-06. "Stress Analysis of Safety-Related Piping "
  KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/23 1ρ
- 7905040060 Forwards It info Notice 79-07. "Rupture of Radwaste Tanks "
  KEPPLER, J G Region 3, Chicago, Diffice of the Director 79/03/26
- 7705010181 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Syc Air Sys Used as Source of Breathing Air." KEPPLER, J C Ragion 3. Chicago, Office of the Director, 79/03/28
- 7905010417 Forwards IE Info Notice 79-09. "Spill of Radioactively Contaminated Resin " Region 3. Chicago. Office of the Director 79/03/30 KEPPLER, J Q
- 7905030062 Forwards IE Bulletin 79-06. "Review of Operational Errors & Sgs Misalignments Identified During TMI Incident " Licenses action required Region 3. Chicago, Office of the Director 79/04/11 KEPPLER, J C
- 7905010613 Forwards IE Bultetin 79-06A. "Review of Operational Errors & Sys Misalignments Identified during TM! Incident " Licensee action required Region 3, Chicago, Office of the Director. 79/04/14 KEPPLER, J G
- 7905040431 Forwards IE Bulletin 79-06B. "Review of Operational Errore & Sys Misalignments Identified During TMI Incident " KEPPLER.J G Region 3. Chicago. Office of the Director 79/04/14
- 7905040438 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping " Licensee action required KEPPLER, J. G. Region 3. Chicago, Office of the Director 79/04/14
- 7905040598 Forwards IE Bulletin 79-08, "Eyents Relevant to Boiling Water Power Reactors Identified During TMI Incident "
  KEPPLER, J. 6 Region 3, Chicago, Office of the Director 79/04/14
- 7905030253 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " Licensee action required
  KEPPLER, J 0
  - Region 3. Chicago, Office of the Director 79/04/17
- 7905290075 Responds to IE Bullatin 79-06A Expresses concern re emergency operating procedures for reactor coolant pump & requirement for immediate tripping of low level bistables BURSTEIN.S Wisconsin Electric Power Co 79/04/19 Spg
- 7905080515 Forwards 16 Bulletin 79-058. "Nuclear Incident at TMI-Buppl, " KEPPLER, J. D Region 3. Chicago, Office of the Director 79/04/21.
- 7705240517 Responds to IE Bullatin 77-07 re computer programs used in seismic stress analysis of safety-related piping sys No computer codes used which utilized algebraic summetion BURBIEIN.S Wisconsin Electric Power Co 79/04/25. 2pp

- 7905240303 Responds to IE Bulletin 79-03 re possibility of lengthful wald defects in ASME 8A-312 Type 304 stainless steel pipe spools Review of pipe documentation records indicates no use of such tubing BURSTEIN, B Wisconsin Electric Power Co 79/04/26 App
- 7905300316 Responds to IE Bullstin 79-06A & 79-06A Revision | 14., established task force to facilitate review & understanding of TMI incident & impact on facility BURSTEIN.B Misconsin Electric Power Co 79/04/27 13pp
- 7705290284 Responds to IE Bulletin 79-09 re GE Type AK-2 circult breaters Item not in use at plant BURSTEIN,8 Wisconsin Electric Power Co 79/03/07 is
- R Periodic operating reports & related correspondence
- 7905160362 Forwards monthly operating rept for Apr 1979 BURSTEIN:S Wisconsin Electric Power Co 79/05/08
- --7905160365 Monthly operating rapt for Apr 1979 \* Wisconsin Electric Power Co 79/05/04, 10pp
- S Reportable occurrences, LERs & related correspondence
- 7905020289 Forwards LER 79-003/01T-0 BURSTEIN, B Wisconsin Electric Power Co 79/04/17 1p
- --7905020304 LER 79-003/01T-0 on 790410 during refueling leatage soit two valves were found w/excessive leakage Caused by foreign matter accumulations in internals Valves cleaned reassembles & successfully refeated BURSTEIN,S Wisconsin Electric Power Co 79/04/17 2pp
- 7905100254 Forwards LER 79-004/011-0
  BURSTEIN,8 Wisconsin Electric Power Co 79/04/28 to
- ---7905100263 LER 79-004/01T-0 on 790412 overcurrent protection file to dashpots for 2003 safeguards bus supply breaker exhibited erratic long time delay trip time Caused by hairline cracks in dashpot caps Cracked caps will be replaced BURSTEIN,5 Wisconsin Electric Power Co 79/04/26 Upp
- 7905100314 Forwards LER 79-005/017-0 BURGTEIN-8 Wisconsin Electric Power Co 79/04/27 1p
- --7905100315 LER 79-005/01T-0 on 790417 hydraulic snubber 3/1499-14 located on main steam line at top of B steam generator inoperable Caused by piston rod 0 ring leakage Snubber BURSTEIN, S Wisconsin Electric Power Co 79/04/2/ 2pp
- 7905240611 Forwards LER 79-007/01T-0 BURSTEIN:S Wisconsin Electric Power Co 79/05/07
- --7905240627 LER 79-007/01T-0 on 790424 vendor issued bulletin to potential problem w/turbochanger bearing lubrication Administrative controls instituted Mods to be made as soon BURSTEIN, 8 Wisconsin Electric Power Co 79/05/07
- 7905150378 Bubmits addl info on LER 79-004/017-0 re testing of 411111 basis circuit breakers. Margin of about 27-s exists between worst syc condition expected & overload delay setting yearfied by multi-amp calibr test.

  BURGTEIN: 8 Hisconsin Electric Power Co 79/09/10 Jpp.
- DOCKET 50-902 CRYSTAL RIVER NUCLEAR PLANT, UNIT 3
- J Insurance & indemnity information
- QUATTROCHHI.J American Nuclear Insurers. 79/05/01.
- 7905070582 Confirms increase in liability limit to \$36,000,000 fer policies MF-22,26,29,38,39,44,46,47,49,30,51,52,53,54,55,36,57,58,50,61,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,91,72,73,74,75 Mutual Atomic Energy Liability Underwriters. 79/05/4 ROBERTS D M

- 7905160252 Forwards Amend 6 to Indemnity Agreement 8-54.per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation enci BALTZMAN, J Antitrust & Indemnity Group 79/05/01 Spp
- 7905080474 Forwards Endorsement 36 to NELIA Policy NF-195
  FIELDER, J Marsh & McLenon, M & M Nuclear Consultants, Inc Div
  79705703 2pp
- 7905080476 Forwards Endorsement 37 to NELIA Policy NF-195 FIELDER, J Marsh & McLenon, M & M Nuclear Consultants, Inc Div 79/05/03 2pp
- 7903310379 Ack receipt of NRC itr indicating info submitted by util met requirements of iOCFR140 21 Assumes no addl info needed prior to June 1980
  KCKEE, C W Florida Power Corp 77/05/25 1p
- P Operating license stage documents & correspondence
- 7905090200 Forwards request for addl info in order to complete review of proposed change to spray additive sys
  REID:R W Operating Reactors Branch 4 79/04/09 3pp
- 7909020271 Agrees to meet w/NRC to resolve & implement safety concerns identified in 790425 Ofc of Nuclear Reactor Regulation "Status Rept to Commission" re B&M-designed reactors Intends to resolve items before 790601 startup QRIFFIN, B L Florida Power Corp 79/04/27 3pp
- 7905020274 Discusses interim action, in response to 790425 Ofc of Nuclear Reactor Regulation "Status Rept to Commission" re B&H-designed reactor safety Items will be resolved prior to 790401 startup ORIFFIN, B L Florida Power Corp 79/05/01 9pp
- 7705180206 Responds to NRC 770327 ltr re addition of reactor coolant pump power monitors.
  MODRE, C C Florida Power Corp 79/05/07 5pp
- 7903210272 Forwards actions & design mods in response to safety concerns of 790425 status rept to NRC Actions include implementation of hard-wired control-grade reactor trip on loss of main feedwater or turbine trip W/affidavit STEWART, W P Florida Power Corp 79/05/16 20pp
- 7905310298 Forwards Tech Specs Change Requests 40,41,43,44,49 % 48 for amend to Apps A & B of License DPR-72, consisting of changes to administrative controls; emergency feedwator sys & electrical power sys Certificate of Svc encl BTEWART, W P Florida Power Corp 79/05/23 25pp
- 7908300158 Forwards page change for Tech Spec change Request 46 Also forwards "Borated Mater & Sodium Hydroxide Storage Tanks Drawdown Transient Analysis." STEMART, W. P. Florida Power Corp. 79/05/25 5pp
- --7905300164 "Borated Water & Sodium Hydroxide Storage Tanks Drawdown Transient Analysis " \* Florida Power Corp 79/05/30 53pp
- 7905300185 Forwards revised pages to 781127 Tech Spec Change Request 27 & "Test Rept for Seismic Qualification Testing of Potential Transformer Model JVM4 & Current Transformer Model JCM4 " Gertificate of Svc enci STEWART.W P Florida Power Corp 79/05/25 10pp.
- --7905300189 "Test Rept for Seismic Qualification Testing of Potential Transformer Model JVM4 & Current Transformer Model JCM4 " # Florida Power Corp 79/05/10 19pp
- 7905300546 Forwards revised pages to BAW-1521,Feb 1979 Cycle 2 reload rept & to Tech Spec Change Request 39, dtd 790315 Certificate of Svc ancl STEWART,W,P. Florida Power Corp 79/05/25 18pp
- O Inspection reports. IE Bulletins & correspondence
- 7905010192 Forwards IE Info Notice 79-04, "Stress Analysis of Bafety-Related Piping " O'REILLY.J.P Region 2. Atlanta, Office of the Director 79/03/23 200
- 7905020404 Forwards IE Info Notice 79-07. "Rupture of Radwaste Tanks "
  O'REILLY, J P Region 2, Atlanta: Office of the Director
  79/03/26. 1p

- 7905010102 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Syc Air Sys Used as Source of Breathing Air"
  O'REILLY, JP Region 2, Atlanta, Office of the Director 79/03/28 2nd
- 7905010383 Forwards IE Info Notice 79-09. "Spill of Radioactively Contaminated Resin "O'REILLY,J P Region 2. Atlanta, Office of the Director 79/03/30 1p
- 7905080095 Forwards response to Items 1,2,3,4 & 5 in IE Bulletin 79-05A rm TMI incident Review demonstrates that similar events would not result in similar consequesnces at Crystal River STEMART, N P Florida Power Corp 79/04/09 77p
- 7903310017 Forwards IE Insp Rept 50-302/79-14 on 790323 No noncompliance noted Discusses agt meeting O'REILLY,J P Region 2, Atlanta, Office of the Director 79/04/10 2pp
- --7905310024 IE Insp Rept 50-302/79-14 on 790323 No noncompliance noted Major areas inspected enforcement history, licensee reported events, safety performance, radiation protection, environ controls, security & QA DANCE, H C Region 2, Atlanta, Office of the Director 79/04/09
- 7905010403 Ack receipt of 790403 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-302/79-06
  MURPHY.C E Region 2. Atlanta, Office of the Director 79/04/12
- --7905010408 Responds to NRC 790313 ltr re violations noted in IE insp Rept 50-302/79-06 Corrective actions welding rod holding oven temp gauges calibr at regular intervals & calibr stickers displayed STEHART, WP Florida Power Corp 79/04/03 2pp
- --7905010418 Forwards IE Insp Rept 50-302/79-06 on 790206-08 & notice of violation HURPHY,C E Region 2. Atlanta, Office of the Director 79/03/13 2pp
- ---7905010421 Notice of violation from insp on 790206-08
  \* Region 2. Atlanta, Office of the Director 79/03/08 ip
- --7903010471 IE Insp Rept 30-302/79-06 on 790206-08 Noncompliance noted failure to follow calibr control procedure & inadequate welding rod control procedures ECONOMOS(N. CONLON.T E Region 2, Atlanta, Office of the Director 79/03/08 7pp
- 7903040209 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident "O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 2pp
- 7905040306 Forwards IE Bulletin 79-07. "Seismic Stress Analysis of Bafety-Related Piping " Licensee action required O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 1p
- 7905040395 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident " O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 ip
- 770510023B Responds to IE Bulletin 79-03 No welded pipe from Youngstown Welding & Engineering Co is being used BTEWART.W P Florida Power Corp 79/04/16 1p
- 7905030162 Forwards IE Bulletin 79-09, "Failures of GE Tupe AK-2 Circuit Breaker in Safety-Related Sys " Licensee action required O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/17 200
- 7905020463 Forwards IE Bulletin 79-06A.Ravision i, "Ravisw of Operational Errors & Bys Misalignments Identified During TMI Incident."

  O'REILLY, J P Region 2. Atlanta. Office of the Director 79/04/18 2pp
- 7905230628 Ack receipt of 790409 1tr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-302/79-05
  KENNA,W B Region 2, Atlanta, Safeguards Branch 79/04/18 ig

- --- 7903230632 Forwards IE Insp Rept 50-302/79-05 on 790204-08 Notice of violation withheld (ref 10CFR2 790) MENNA, H B Region 2. Atlanta, Bafeguards Branch 79/03/16
- --7905230641 IE Insp Rept 50-302/79-05 on 790204-08 Noncompliance noted deficiency in records & repts re-program for safeguarding nuclear math Details withheld (ref 10CFR2 790) DAVIS,C L , OILLESPIE,F P Region 2, Atlanta, Office of the Director 79/03/15 ip
- 7905240802 Responds to IE Bullstin 79-07.PIPDYN II program used on all project mods.Response based on reviews of analytical methods used to predict strasses in safety-related piping sys. conducted by BAM & Oilbert Associates
  STEMART,M P. Floride Power Corp 79/04/24 4pp
- 790525038: Acf receipt of 790416 itr informing NRC of staps taken to correct violations noted in IE Insp Rept 50-302/79-03 LEMIS.R G. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/01 1p.
- --7905250390 Responds to NRC 790323 tir re violations noted in IE Insp Rept 50-302/79-03 Corrective actions backlog data being reviewed & forwarded in retrograde manner & surveillance procedures being revised -STEMART.N P Florida Power Corp 79/04/16 2pp
- --7905250396 Forwards IE Insp Rept 50-302/79-03 on 790115-19 & notice of violation LEMIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 79/03/23 2pp
- --7905280402 Notice of violation from insp on 790118-19
  + Region 2, Atlanta, Office of the Director 79/03/23 1p
- ---7909230410 IE Insp Rept 50-302/79-03 on 790115-19 Noncompliance noted failure to review & approve radiation chemistry data sheet & failure to document supervisory review of surveillance test results.

  GHAPER, H D . GUICK, D . WHITT, K W Region 2. Atlanta, Office of the Director 79/02/27 7pp
- 7905290493 Responds to IE Bulletin 79~04 Results of reanalysis indicate piping stresses to be very close to original values & well widthin seitmic stress allowable BTEMARY, W.P. Florida Power Corp. 79/05/01 2pp
- 79032900(3 Forwards response to IE Bulletin 79-058 BbH has provided guidelines to assist in writing procedures for establishing & maintaining natural circulation Procedures will describe actions to take in event feedwater flow is lost STEHÁRT. H P Florida Power Corp. 79/05/04 Spp
- R Periodic operating reports & related correspondence
- 7905030351 Forwards revised pages (Suppl 2) to "Annual Environ Operating Rept." Vol 1 STEHART, N.P. Florida Power Corp. 79/04/27, 7pp.
- 7905210153 Forwards monthly operating rept for Apr 1979 BTEWART,W P Florida Power Corp. 79/05/15 Ip.

- --7905040094 LER 79-033/03L-0 on 790404 discovered A decay heat play discharge throttle valve DHV-110 would not control flow in automatic Cause unknown ECCS pump operability demonstration performed w/satisfactory results

  CD0PER:J Florida Power Corp 79/04/23 2pp
- 7903040430 Forwards LER 79-040/03L-0 STEWART: W P Florida Power Corp 79/05/01 1p
- --7905040632 LER 79-040/03L-0 on 790405 containment purge supply value
  ANV-1C would not fully open Caused by cracked right angle
  drive gear case Motor & drive assembly renewed
  COOPER. J Florida Power Corp 79/04/27 2pp
- 7905070537 Forwards supplemental info re LER 79-016/04X-1 on 7903:9 environ sample analyzed w/inadequate procedures Caused by inadequate sample time No corrective action proposed STEMART. M P Plorida Power Corp 79/05/01 3pp
- 7905070597 Forwards LER 79-035/03L-0 STEWART/W P Florida Power Corp 79/05/01, ip
- --7905070602 LER 79-035/03L-0 on 790404 radioactivity monitor RMA-6; to be incorrectly positioned while changing particulate fifters Detector repositioned & returned to svc Personnel reintructed on proper method of installation COOPER. J Florida Power Corp 79/04/23 2pp
- 7905070611 Forwards LER 79-036/03L-0 STEWART, W P Florida Power Corp 79/05/01 1p
- --7905070626 LER 79-096/03L-0 on 790404 failure of meteorological monitoring bower temp monitoring device discovered during reactor bidg purge Caused by loose terminal box at 173 foot elsewation Terminal thoractal tightened & returned to svc on 790407 GOOPER.U Florida Power Corp 79/04/24 2pp
- 7905070624 Forwards supplemental info re LER 79-039/04L-0 on 790th operational & preoperational studies of discharge salt marshes differed more than two std deviations Caused by natural or seasonal variations & unit thermal output STEWART, W P Florida Power Corp 79/05/01 4pp
- 7905070645 Forwards LER 79-037/03L-0 STEHART, W P Florida Power Corp 79/05/01 1p
- ~-7905070648 LER 79-037/03L-0 on 790407:RC8 sample valve CAV-2 worldclose Cause unknown CAV-2 cycled & returned to svc on 790425 CQUPER.J Florida Power Gdrp 79/04/26 2pp
- 7905070652 Forwards LER 79-038/03L-0. STEWART.W P Florida Power Corp 79/05/01 lp
- --7905070654 LER 79-038/03L-0 on 790409 pressurizer water space step's ine isolation valve CAV-3 would not close Gause unknown CAV-3 tested & returned to svc on 790413 COOPER.J Florida Power Corp 79/08/01 2pp
- 7905080427 Forwards supplemental info re LER 79-016/04x-1 in Jan 197 environ samples were not analyzed using procedures required in ETB Caused by inadequate sample time STEWART.W P Florida Power Corp. 79/05/01 ip.
- 7905090278 Forwards LER 79~041/03L-0 STEWART.W P Florida Power Corp 79/05/04 1p
- ---7905090281 LER 79-041/03L-0 on 790409 methyl iodine ramoval efficit was less than 99% Caused by flue gases & other sits airborne pollutants deteriorating charcoal & its impregnant Charcoal will be renewed following plant refueling COOPER.J Plorida Power Carp 79/05/01 2pp
- 7905110241 Forwards LER 79-042/03L-0. STEWART: M. P. Florida Power Corp. 79/05/07. 1p
- ---7905110244 LER 79-042/03L-0 on 790411 storage tank IA level detries to 300,500 gailons. Caused by inproper lineup Tank filled to Tech Epec limit.
  COUPER.J Florida Power Corp 79/05/02 2pp.
- 7905190023 Forwards LER 79-043/03L-0. BTEMART.W P Fiorida Power Corp. 79/05/14. ip.
- --7905190028 LER 79-043/03L-0 on 790420 channel functional & carr, operability of fire protection instrumentation SP-190 not performed in required time. Caused by personnel error in tacheduling surveillance procedure COOPER. J Florida Power Corp. 79/08/08 2pp

- 7905230369 Forwards LER 79-044/03L-0 STEWART, W P Florida Power Corp 79/05/18 1p
- --7905230373 LER 79-044/03L-O on 790423 while attempting to add boric acid to RCS, chemical addition pump 18 would not operate Cause under investigation Corrective actions will be based on evaluation results Fiorida Power Corp 79/05/10 200 COUCER'S
- 7905250375 Ferwards LER 79-016/04X-2 STEWART, W P Florida Power Corp
- --7905250380 LER 79-016/04X-2 on 790511 environ samples not analyzed using procedures providing lowest level detectors equal to or less than Tech Specs requirements Caused by inadequate \* Florida Power Corp 79/05/15 2pp
- 7905250383 Forwards LER 79-046/03L-0 BTEWART: N P Florida Power Corp 779/05/22 ip
- --7903250385 LER 79-046/OSL-0 on 790425 during plant coaldown for refueling outage decay heat romoval valve 4 failed to open upon remote activation Caused by washer binding at stem nut interface & inadequate lubrication & tarque limiter setting COOPER.J Florida Power Corp 79/05/18 2pp
- 7905300497 Forwards LER 79-045/03L-0. BTEWART, W P Florida Power Corp 79/05/22 ip
- --7905300503 LER 79-045/03L-0 on 790424 core flood valve CFV-5 annunciator did not actuate properly Cause unknown Corrective action to be taken prior to accencion into Mode COOPER.J Florida Power Corp 79/05/14 2pp
- 7905300484 Forwards LER 79-048/03L-0 STEWART, W P Florida Power Corp 79/05/25 1p
- --7905300491 LER 79-048/03L-0 on 790501 reactor coolant snubber RCH-90 found inoperable Caused by inadvertant damage to snubber by unknown persons Snubber replaced & spare tested satisfactorily COOPER, J Florida Power Corp 79/05/23, 2pp
- 7905310371 Forwards LER 79-047/03L-0 STEWART, N P Florida Power Corp 79/05/25 1p
- --7905310403 LER 79-047/03L-0 on 790428 boron concentration in boric acid tank exceeded level of Tech Spec Gaused by inadequate design Request for engineering info was initiated to provide corrective measure CDDPER, J. Florida Power Corp. 79/05/25 2pp
- DOCKET 50-303 CRYSTAL RIVER NUCLEAR PLANT, UNIT 4
- P. Operating license stage documents & correspondence
- 7909310298 Forwards Tech Specs Change Requests 40,41,43,44,45 & 48 for amend to Apps A & B of License DPR-72, consisting of changes to administrative controls, emergency feedwater sys & electrical power sys. Certificate of Bvc encl STEWART, W. P. Florida Power Corp. 79/05/23 25pp
- DOCKET 50-304 ZION NUCLEAR POWER STATION, UNIT 2
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 7905240995 Forwards SER & EIA re plant spent fuel pool mods W/o encl QDDDARD.R J Branch 2, 79/04/03 lp
- F Becurity, medical, emergency & fire protection plans
- 7905030346 Forwards modified physical security plan. Revision 5 Plan withheld (ref 100FR2 790)
  LEE, B Commonwealth Edison Co 79/04/24 ip
- 7905290079 Forwards Chemtron drawings FL27652-7, sheets 1 through 5, w/design datails for fire suppression sys to be installed for auxiliary feedwater sys & component cooling pumps Oversite drawings enci.

  NAUOHTON, W F Commonwealth Edison Co. 79/05/23 2pp
- O. Adjudicatory correspondence
- 790523076B Affidavit of M Resnikoff re spent fuel issue, Professional qualifications & Certificate of Svc encl RESNIKOFF, M. R. Illinois, State of 79/02/23, 12pp.

- 7905300711 Responds to State of IL's 790221 motion for continuance & request to allow future supplementation of intervenor's affidavits Certificate of Svc encl GDDDARD.R J Branch 2 79/03/13 4pp
- 7905070154 Forwards SER & EIA re spent fuel pool mods W/o enci GODDARD, R J Branch 2 79/04/03 1p
- 7905250158 Provides list of witnesses for util in Zion spent fuel case STEPTOE.P Isham, Lincoln & Beale 79/04/03 2pp
- 7905300022 Request by util on its own behalf to on behalf of State of IL to NRC. for ASLB to begin hearings on 790514 Certificate of Svc encl
  - BIELAWSKI, A P Isham, Lincoln & Beale 79/04/06 3pp
- 7905100121 Interrogatories submitted to state of IL per ASL8 790119 order Certificate of Svc encl GDDDARD,R J Branch 2 79/04/09 4pp
- 7905150256 Motion to file supplementary affidavits to response to util & NRC motions for summary disposition Affidavits of D9 Bridenbaugh & 9C Minor & Certificate of Bvc encl SEKULER.S N Illinois. State of 79/04/10 23pp
- 7905150248 Forwards unexecuted affidavit of M Resnikoff Certificate of SEKULER, S N Illinois, State of 79/04/13 4pp
- 7905150691 Forwards Chapter 1 of SAND77-1371, "Spent Fuel Heatup Following Loss of Water During Storage," which contains info relevent to util's application to increase spent fuel storage pool capacity Requests to be placed on svc list WEBB.R E Affiliation Unknown 79/04/13 40pp
- 7909250367 Moves for summary disposition of State of IL's Contention 2(a)-(d) for lack of genuine issue of matl fact Affidavits, notices of appearance & withdrawal & Certificate of Svc 1 encl COLDBERG, S C Branch 2 79/04/27 2000
- 7905150243 Denies summary disposition of intervenors' Contentions 2(f) (2),2(g),2(h) & 2(i) Grants summary disposition of intervenors' Contention 2(n) LUTON,E Atomic Safety and Licensing Board Panel 79/08/01 3pp
- H General correspondence
- 7905070014 Responds to 790202 Itr requesting info re leakage of water through liner of spent fuel pool at facility NRC is monitoring util's efforts to control sampage STELLO.V Division of Operating Reactors 79/04/19 79pp
- J Insurance & indemnity information
- 7905100163 Endorsement 99 to MAELU Policy MF-22 GERAB, T Nuclear Energy Liability Insurance Association 79/03/27
- 7903070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,\*7^ 173,174,179,179,180,182,185,186,187,189,189,192,193,15 197,198,200,201,204,206,207,208,210,212,214,215,& oth GWATTROCKHI,J American Nuclear Insurers 79/05/01
- 7905070582 Confirms increase in liability limit to policies MF-22, 26, 29, 3B, 39, 44, 46, 47, 49, 50, 51 -- 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77 88, 90, 91, 92, 93, 94, 93 & 96 ROBERTS, D M

- --7905230632 Forwards IE Insp Rept 50-302/79-05 on 790204-08 Notice of violation withheld (ref 10CFR2 790)
  KENNA.W B Region 2, Atlanta, Safeguards Branch 79/03/16
- --7905230641 IE Insp Rept 50-302/79-05 on 790204-08 Noncompliance noted deficiency in records & repts as program for safeguarding nuclear math Datails withheld (ref 100FR2 790) DAVIS,C.L. OILLESPIE,F.P. Region 2, Atlanta, Office of the Director 79/03/15 ip
- 7905240802 Responds to IE Bulistin 79-07 PIPDYN II program used on all project mode Response based on reviews of analytical methods used to predict stresses in safety-related piping sys. conducted by SAM & Oilbert Associates
  STEMART.M P Florida Power Corp 79/04/24 4pp
- 79052303B1 Ack receipt of 790416 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 80-302/79-03
  LEWIS,R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 79/05/01 ip
- --7903250390 Responds to NRC 790323 ltm re violations noted in IE Insp. Rept 50-302/79-03 Corrective actions backlog data being reviewed 4 forwarded in retrograde manner & surveillance procedures being reviewed --STEWART.W P Florida Power Corp 79/04/16 20p
- --7905250396 Forwards IE Insp Rept 50-302/79-03 on 790115-19 & notice of violation LEMIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 79/03/23 2pp
- --7905280402 Notice of violation from insp on 790115-19
  \* Region 2: Atlanta: Office of the Director 79/03/23 ip
- --7903250410 IE Insp Rept 30-302/77-03 on 770115-19. Noncompliance noted feature to review & approve radiation chemistry data theat & failure to document supervisory review of surveillance test results
  SHAFER.W D . GUICK.D . WHITT.K H Region 2: Atlanta, Office of the Director 79/02/27 7pp
- 7905290493 Responds to IR Builetin 79~04 Results of reenalysis indicate piping atreases to be very close to original values & well within seismic atreas alloweble GEEMART.W P Florida Power Carp 79/05/01. 2pp
- 7905290013 Forwards response to IE Bullatin 79-058 BBN has provided guidelines to assist in writing procedures for establishing & maintaining natural circulation Procedures will describe actions to take in event feedwater flow is lost BTENÁRT. W P Florida Power Corp. 79/05/04 3pp
- R Periodic operating reports & related correspondence
- 7905030351 Forwards revised pages (Suppl 2) to "Annual Environ Operating Rept." Vol 1 BTEWART, M.P. Florida Power Corp. 79/04/27 7pp
- 7905210153 Forwards monthly operating rept for Apr 1979 BTEHART.W P Florida Power Corp 79/05/15 ip
- ---7905210154 Monthly operating rept for Apr 1979
  KENNEDY, R W Florida Power Corp 79/05/07 5pp
- S Reportable occurrences, LERs & related correspondence
- 7905070538 Forwards LER 79-005/01T BTEWART, N P Florida Power Corp 79/03/27 ip.
- ---7905070540 LER 79-003/01T-1 on 790123 util was notified that Rockwell Mfg Go MBIV may not close within Tech Spec 5-e limit during accident. Caused by discovery of add1 forces on valve disc Valves to be modified COUPER.J. Florida Power Corp 79/04/25 10pp
- 7903040043 Forwards LER 79-034/03L-0.
  BTEMART.W P Florida Power Corp 79/04/24 ip
- --7905040050 LER 79-034/03L-0 on 790404 power supply breaker for reactor bldg radioactivity monitor RMA-6 was in tripped position Cause unknown Breaker reset & RMA-6 returned to svc after satisfactory completion of SP-035 test. COOPER, J Florida Power Corp 79/04/R3 2pp
- 7908040088 Forwards LER 79-033/03L-0 STEWART.H.P. Florida Power Corp 79/04/27 ip

- --7905040094 LER 79-033/03L-0 on 790404 discovered A decay heat jug discharge throattle valve DHV-110 would not control flow in automatic Cause unknown ECCS pump operability damonstration performed w/satisfactory results
  COOPER.J Florida Power Corp 79/04/23 2pp
- 7905040630 Forwards ter 79-040/03L-0. STEWART, W P Florida Power Corp 79/05/01 tp
- --7905040632 LER 79-040/03L-0 on 790405 containment purge supply is AHV-1C would not fully open Caused by crecked right angle drive gear case Motor & drive assembly renewed CODPER.J Florida Power Corp 79/04/27 2pp
- 7705070537 Forwards supplemental info re LER 79-016/04X-1 on 79-359 environ sample analyzed w/inadequate procedures Gaused by inadequate sample time No corrective action proposed STEMART.H P. Florida Power Corp 79/05/01 3pp
- 7905070397 Forwards LER 79-035/03L-0 STEWART, W P Florida Power Corp 79/05/01 1p
- --7905070602 LER 79-035/03L-0 on 790404 radioactivity monitor fra-ato be incorrectly positioned while changing particulats filters. Detector repositioned & returned to swc Parsonnel reinstructed on proper method of installation COOPER. J Florida Power Corp 79/04/23 2pp
- 7905070611 Forwards LER 79-036/03L-0 BTEWART.W P Florida Power Corp 79/05/01 1s
- --7905070626 LER 79-036/03L-0 on 790404 failure of meteorological monitoring tower temp monitoring device discovered during reactor bidg purge Caused by loose terminal box at 176 foot elevation Terminal tightened & returned to svc on 790407 COOPER, J Florida Power Corp 79/04/24 2pp
- 7905070624 Forwards supplemental info re LER 79-039/04L-0 on Pages operational & preoperational studies of discharge salt marches differed more than two std deviations Caused by natural or seasonal variations & unit thermal output STEWART. W P Florida Power Corp 79/05/01 4pp
- 7905070645 Forward: LER 79-037/03L-0 STEWART,W P Florida Power Corp 79/05/01 to
- --7705070648 LER 79-037/03L-0 on 770407:RCB sample valve CAV 2 mile-close Cause unknown CAV-2 cycled & returned to evo on 770425 COOPER, J. Florida Power Cdrp 77/04/26, 2pp
- 7905070652 Forwards LER 79-038/03L-0. BTEWART: W P Florids Power Corp. 79/05/01 ip.
- ---7905070654 LER 79-03B/03L-0 on 790409 pressurizer water space ser, line isolation valve CAV-3 would not close Cause untroop CAV-3 tested & returned to svc on 790413. COOPER.J. Florida Power Corp 79/05/01 2pp
- 7905090278 Forwards LER 79-041/03L-0 STEWART, W P Florida Power Corp 79/05/04, 1p
- --7905090281 iER 79-041/03L-0 on 790409 methyl iodine respond ble was less than 99% Caused by flue gases & other site elrhorre pollutants deteriorating charcoal & its impregnant Chardes will be renewed following plant refueling COOPER. J Florida Power Corp 79/05/01. 2pp
- 7905110241 Forwards LER 79-042/03L-0 STEWART.W P Florida Power Corp 79/05/07 ip
- --7905110244 LER 79-042/03L-0 on 790411: storage tast IA less? Es L. to 308,500 gallons. Caused by improper lineup Tank filleg qu Tack Spec limit. COUPER.J Florida Power Corp. 79/05/02. Upp
- 7905190023 Forwards LER 79-043/03L-0. STEWART, W P Florida Power Corp 79/05/14 ip
- --7905190028 LER 79-048/03L-0 on 790420.channel functions: % ell... operability of fire protection instrumentation BP-190 not performed in required time Gaussd by personnel strict two scheduling surveillance procedure.

  COOPER, J. Florida Power Corp. 79/05/08 2pp

- 7903230369 Forwards LER 79-044/03L-0 STEWART.W P Florida Power Corp 79/05/18 ip
- --7905230373 LER 79-044/03L-0 on 790423 while attempting to add boric acid to RCB, chemical addition pump 19 would not operate Cause under investigation Corrective actions will be based on evaluation results
  COOPER, J. Florida Power Corp. 79/05/10 2pp
- 7905250375 Forwards LER 79-016/04X-2 STEWART,W P Florida Power Corp 79/05/19 in
- --7905250360 LER 79-016/04X-2 on 790511 environ samples not analyzed using procedures providing lowest level detectors equal to or less than Tech Bpecs requirements Caused by inadequate sample time Provide Power Corp 79/05/15 2pp
- 7905250383 Forwards LER 79-044/03L-0 STEWART, N P Florida Power Corp 179/05/22 1p
- --7905280385 LER 79-046/03L-0 on 790425 during plant cooldown for refueling outage, decay heat removal valve 4 feiled to open upon remote activation Caused by washer binding at stem nut interface & inadequate lubrication & torque limiter setting COOPER.J. Florida Power Corp 79/05/18 2pp
- 7905300497 Forwards LER 79-045/03L-0. STEWART, W. P. Florida Power Corp. 79/05/22 1p
- ---7905300503 LER 79-045/03L-0 on 790424.core flood valve CFV-5 annunciator did not actuate properly Cause unknown Corrective action to be taken prior to ascencion into Mode 3 COOPER, J. Florida Power Corp. 79/05/14 2pp
- 7903300484 Forwards LER 79-048/03L-0 GTEWART, W P. Florida Power Corp 79/05/25 1p
- --7905300491 LER 79-048/03L-0 on 790501 reactor coolant snubber RCM-90 found inoperable Caused by inadvertent damage to snubber by unknown persons Snubber replaced & spare tested satisfactorily GOOPER, J Florida Power Corp. 79/05/23 2pp
- 7905310391 Forwards LCR 79-047/03L-0 STEWART, M. P. Florida Power Corp. 79/05/25 1p
- --7905310403 LER 79-047/03L-0 on 790428 baron concentration in boric acid tank exceeded level of Tech Spec Caused by inadequate design Request for engineering info was initiated to provide corrective measure.

  COCPER, J Fiorida Power Corp 79/05/25 2pp
- DOCKET 50-303 CRYSTAL RIVER NUCLEAR PLANT, UNIT 4
  P. Operating license stage documents & correspondence
- 7909310278 Forwards Tech Specs Change Requests 40,41,43,44,45 & 48 for amend to Appa A & B of License DPR-72.consisting of changes to administrative controls, emergency feedwater sys & electrical power sys. Certificate of Svc encl SYEMART, W P Florida Power Corp 79/05/23 25pp
- DOCKET 50-304 ZION NUCLEAR POWER STATION, UNIT 2 E NRC Safety Evaluation Report (SER), supple & correspondence
- 7705240995 Forwards SER & EIA re plant spent fuel pool mods W/o encl OODDARD, R J Branch 2, 79/04/03 lp
- F Becurity, medical, emergency & fire protection plans
- 7705030366 Forwards modified physical security plan, Revision 5, Plan withheld (ref 100FR2 770) LEE. 9 Commonwealth Edison Co 79/04/26 1p.
- 7905290079 Forwards Chemtron drawings FL27652-7, sheets 1 through 5, w/design details for fire suppression sys to be installed for auxiliary feedwater sys & component cooling pumps Oversite drawings encl.
  NAUOHTON, W.F. Commonwealth Edison Co. 79/05/23 2pp
- Q Adjudicatory correspondence
- 7905230748 Affidavit of M Resnikoff re spent fuel issue Professional qualifications & Certificate of Svc encl. REBNIKOFF, M. R. Illinois, State of. 79/02/23 12pp

- 7905300711 Responds to State of IL's 790221 motion for continuance & request to allow future supplementation of intervenor's affidavits Certificate of Svc encl GDDDARD:R J Branch 2 79/03/13 4pp
- 7905070154 Forwards SER & EIA re spent fuel pool mods W/o encl GODDARD:R J Branch 2 79/04/03 ip
- 7905250158 Provides list of witnesses for util in Zion spent fuel case STEPTOE.P Isham, Lincoln & Beale 79/04/03 2pp
- 7905300022 Request by util on its own behalf % on behalf of State of IL & NRC.for ASLB to begin hearings on 790514 Certificate of Svc entl
  Svc entl
  BIELAMSKI.A P Isham, Lincoln & Beale 79/04/06 3pp
- 7905100121 Interrogatories submitted to state of IL per ASLB 790119 order Certificate of Svc encl GODDARD,R J Branch 2 79/04/09 4pp
- 7905150256 Motion to file supplementary affidavits to response to util & NRC motions for summany disposition Affidavits of DO Bridenbaugh & QC Minor & Certificate of Svc enci SEKULER:S N Illinois. State of 79/04/10 23pp
- 790515024B Forwards unexecuted affidavit of K Resnitoff Certificate of Svc and REKULER'S N Illinois, State of 79/04/13 4pp
- 7905150691 Forwards Chapter 1 of SAND77-1371, "Spent Fuel Heatup Following Loss of Mater During Storage," which contains info relevent to util's application to increase spent fuel storage pool capacity Requests to be placed on svc list WEBB, R E Affiliation Unknown 79/04/13 40pp
- 7905250367 Moves for summary disposition of State of IL's Contention 2(a)-(d) for lack of genuine issue of matl fact Affidavits, notices of appearance & withdrawal & Certificate of Svc 1 encl GOLDBERO.8 C Branch 2 79/04/27 20pp
- 7905150243 Denies summary disposition of intervenors' Contentions 2(f) (2),2(g),2(h) & 2(1) Grants summary disposition of intervenors' Contention 2(n) LUTON.E Atomic Safety and Licensing Board Panel 79/08/01 3pp
- H General correspondence
- 7908070014 Responds to 790202 ltr requesting info re leakage of water through liner of spent fuel pool at facility NRC is monitoring util's efforts to control seepage STELLO,V Division of Operating Reactors 79/04/19 79pp
- J Insurance & indemnity information
- 7905100163 Endorsement 99 to MAELU Policy MF-22
  OERAS, Y Nuclear Energy Liability Insurance Association 79/03/27
- 7905070497 Confirms increased liability limit to \$124.(
  policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 16,
  173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 187, 192, 193,
  197, 198, 200, 201, 204, 204, 205, 207, 208, 210, 212, 214, 215, & ot.
  QUATTROCHHI, J American Nuclear Insurers 79/05/01
- 7705070582 Confirms increase in liability limit to \$36,0 policies MF-22,26,29,3B,39,44,46,47,49,50,51,52,53,54,57,5B,40,61,64,66,67,6B,69,70,71,72,74,76,77,78,79,80,8B,40,71,92,93,94,93 & 96 ROBERTS,D M Mutual Atomic Energy Liability Underwrit
- 7905140470 Forwards Amend 9 to Indemnity Agreement B-59 changes re increase in liability insurance from \$140 r to \$160 million effective 790801 Supporting documental enci SALTIMAN, J Antitrust & Indemnity Group 79/05/01
- 7905160399 Confirms 790907 & OB agreement w/NRC that He need not sign Amend 7 to Indemnity Agreement B-54 CAMP.O T Johnson & Higgins Insurance 79/05/09 1
- P Operating license stage documents & correspondence
- 7905250183 Amends 47 % 44 to Licenses DPR-39 & DPR-48.r revising Tech Specs re rod drop time SCHWENCER,A Operating Reactors Branch 1 79/04/

# DOCKETED ITEMS

- --7905250187 Safety evaluation supporting Amends 47 & 44 to Licenses DPR-39 & DPR-48, respectively \* Office of Nuclear Reactor Regulation 79/04/09 3pp
- --7909250190 Notice of issuance & availability of Amends 47 & 44 to Licenses DPR-39 & DPR-4B, respectively SCHWENCER, A Operating Reactors Branch 1 79/04/09 2pp
- 7905040492 Natifies of Intention to develop safety analysis using existing computer codes Requests addl info SQLERIG.C W Commonwealth Edison Co 79/04/26 lp
- 7905040502 Requests amend to Tech Specs to require actuation of safety injection based on two out of three channels of low pressurizer pressure & to delete pressurizer level from safeguards logic Class I & JI amend fees encl REED. C Commonwealth Edison Co 79/04/30 9pp
- 790510025: "Gamma Dose Measurements at Zion & Fort Calboun Stations"
  DYER, N.C., BUNTING, R.L., NIESCHMIDT, E.B. EQ & Q. Inc. FIN A-6075
  NUREO/CR-0755 79/04/30 137pp Available at NTIS \$7.25
- 7905070396 Forwards response to request for add1 info re review of proposed license amend to increase allowable LOCA peaking factor limit to 1 93 based on ECCS reanalysis
  NAUGHTON.W F Commonwealth Edison Co 79/05/03 4pp
- 7905280425 Forwards Amends 49 & 46 to Licenses DPR-39 & DPR-48, respectively, safety evaluation & notice of issuance & availability BCHMENGER, A Deersting Reactors Branch 1 79/05/03 2pp
- ---7905250432 Amends 49 & 46 to Licenses DPR-39 & DPR-48 respectively SCHWENCER. A Departing Reactors Branch 1 79/05/03 16pp
- ~~7905250435 Safety evaluation supporting Amends 49 & 46 to Licenses DPR-39 & DPR-48 respectively \* Operating Reactors Branch 1 79/04/03 Spp
- ~~7903250440 Notice of issuance & availability of Amends 49 & 46 to Licenses DPR~39 & DPR~48, respectively 8CHWENCER.A Operating Reactors Branch 1 79/05/03 2pp
- 7905170237 Forwards revised Tech Specs re heating & cooldown curves & added provision for overpressure protection REED.C Commonwealth Edison Co 79/05/11 2pp
- --7905170285 Revised Tech Specs re heatup & cooldown curves & added provision for overpressure protection
  \* Commonwealth Edison Co 79/05/11, 4pp
- 7903250371 Forwards current licensing open items status list. REED.C Commonwealth Edison Co 79/09/18 11pp
- Q Inspection reports, IE Bulletins & correspondence
- 7905020421 Forwards response to IE Bulletins 78-12 & 78-12A. "Atupical Weld Mati in Reactor Pressure Vessel Helds "
  REED.C Commonwealth Edison Co 77/03/22 10pp
- 7905010236 Forwards IE Info Notice 79-06, "Stress Analysis of Bafety-Related Piping" KEPPLER | O Region J. Chicago, Office of the Director 79/03/23
  - wards IE Info Notice 79-07, "Rupture of Raduaste Tanks " Region 3, Chicago, Office of the Director 79/03/26

- 7905010384 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
  KEPPLER.J G Region 3, Chicago: Office of the Director 79/03/3
- 7905030007 Forwards IE Bulletin 79-06, "Review of Operational Errors Sys Misalignments Identified During TMI Incident " Licenses action required KEPPLER.J G Region 3. Chicago. Office of the Director 79/04/1
- 7903250260 Responds to IE Bulletin 79-03 re weiding defects in certa; longitudinally welded pipe spools Plants inspected; no pipe found REED.C. Commonwealth Edison Co. 79/04/12 2pp
- 7905010572 Forwards IE Bulletin 79-06A, "Review of Operational Errors
  Sys Misselignments Identified during TMI Incident " Licenses
  action required
  KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/1
- 7905040334 Forwards IE Bulletin 77-06B, "Review of Operational Errors
  Eys Misalignments Identified During TMI Incident "
  KEPPLER. J O Region 3. Chicago. Office of the Director 79/04/1
- 7903040527 Forwards IE Bulletin 79-08, "Events Relevant to Beiling Hater Power Reactors Identified During TMI Incident "
  KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/:
- 7905030206 Forwards IE Bullotin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Bafety-Related Bys " Licensee action réquired KEPFLER, J. G. Region 3, Chicago, Office of the Director 79/04/ to
- 7905040142 Forwards IE Bulletin 79-05B, "Nuclear Incident at THI-Suppl " KEPPLER, J O Region 3, Chicago, Office of the Director 79/64/. IP
- ---7905040158 IE Bulletin 79-059, "Nuclear Incident at TMI-Suppl"
  Supporting documentation encl
  \* Region 3: Chicago: Office of the Director 79/04/21, 12pp
- --7905040170 ACRS recommendations re 770328 incident at TMI Suggests priority be placed on development of safety research on Behavior of LMRs during anomalous transients

  \* ACRS Advisory Committee on Reactor Safeguards 79/04/17
- --7905040201 Forwards ACRS recommendations re THI incident, presente 790417 FRALEY,R F ACRS - Advisory Committee on Reactor Safeguards 79/04/18. ip
- --7905040221 In response to NRC 790418 ltr.states all 790417 ACRS recommendations apply to all PWRs, but were not intended to require immediate changes Plant mods should be made after study of effects on overall safety. THI excluded CAMBON, M X ACRS Advisory Committee on Reactor Safeguards 79/04/20 Rpp
- 7905240633 forwards responses to IE Bulletin 79-07 requesting info seismic analysis of safety-related piping Reanalysis indicates method of intramodal combination has little affact on pipe stresses & equipment support loads. REED.C Gommonwealth Edison Co 79/04/24. 4pp
- 7905150768 Forwards IE Insp Repts 59-295/79-06 & 50-304/79-07 on 790319-23 Notice of violation withheld (ref 100FR2 790) HIND.J.A Region 3, Chicago, Safeguards Branch 79/04/26 ;
- --7905150775 IE Insp Repts 50-295/79-06 & 50-304/79-07 on 790319-2: Noncompliance details withheld (ref 10CFR2,790) BELANDER, J. L., HOWELL, J. C. Region 3, Chicago, Office of the Director HND, J. A. Region 3, Chicago, Safeguards Branch 79/04/19, 1p
- 7905300242 Responds to IE Bullstin 79-04 No 3.4 or 6-inch Vetan sw check valves are in use at Dresden or Guad Cities. Review of Zion has identified use of subj valves in some piping sys but review is incomplete, Will rept later REED. C Commonwealth Edison Co 79/05/01. 2pp

- R Periodic operating reports & related correspondence
- 7905090322 Forwards "Annual Operating Rept 1978"
  WANDKE,N F Commonwealth Edison Co 79/04/26 ip
- ~~7905090323 "Annual Operating Rept 1978 " \* Commonwealth Edison Co 79/04/26 24pp
- S Reportable occurrences, LERs & related correspondence
- 7905100300 Forwards LER 79-027/03L-0
  WANDKE,N E Commonwealth Edison Co. 79/04/30 1p
- --7905100302 LER 79-027/03L-0 on 790415 2LT-461 found to be 77 higher than other two channels Caused by Barton sealed ref leg level transmitter being out of calibr <sup>†</sup> HANSEN,P W Commonwealth Edison Co 79/04/30 ip
- 7903100306 Forwards LER 79-021/03L-0
  WANDKE,N E Commonwealth Edison Co 79/04/30 1p
- --7905100310 LER 79-021/03L-0 on 790330 transmitters 2FT-444,445 & 446 for reactor codlant flow loop B high by 4 7%, 4 43% & 4 125%, respectively Caused by instrument drift New calibr technique being used CAMPBELL,J Commonwealth Edison Co 79/04/30 to
- 7905240550 Forwards LER 79-025/03L-0 WANDKE.N E Commonwealth Edison Co 79/05/08 ip
- --7905240555 LER 79-025/03L-O on 790412 temp control module TY-45 discovered missing on hydrogen recombiner. Caused by mechanic's failure to notify shift engineer of removal for repair Item reinstalled JOUSTEN.J K. Commonwealth Edison Co. 79/05/08 ip

#### DOCKET 50-309 KEWAUNEE NUCLEAR POWER PLANT-

#### O Adjudicatory correspondence

7905230573 Notifies that prehearing conference & hearing will be held re alleged violations by licenses & imposition of penalties.

CHILK-B J Office of the Becretary of the Commission, 79/04/30

# H Gameral correspondence

- 7905160364 Notifies that ER Mathews is now vice president of company EW James retired on 790301 FOX.8 Wisconsin Public Bervice Corp 79/05/07 ip
- J. Insurance & indemnity information
- 7905070497 Confirms increased liability limit to \$124,000,000 for palicies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,185,186,187,188,189,192,193,194,195,197,198,200,201,204,204,207,200,210,212,214,215,& others QUATTROCHHI, J. American Nuclear Insurers 79/05/01 1p
- 7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22,26,29,38,39,44,46,47,49,80,51,52,53,54,55,56,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,86,87,88,90,91,92,93,94,98 & 96.
  - ROBERTS, D. M. Mutual Atomic Energy Liability Underwriters. 79/09/01 1p
- 7905160273 Forwards Amend 6 to Indemnity Agreement 8-53; per 10CFR140 changes re increase from \$140 million to \$160 million, effective 790501. Supporting documentation encl. SALTZMAN.J Antitrust & Indemnity Group 79/09/01 5pp.
- 7905240384 Forwards accepted Amend 6 to Indemnity Apreement 8-53, effective 790501. MATHEMS.E R Wisconsin Public Service Corp 79/05/19 3pp
- P. Operating license stage documents & correspondence
- 7905020490 Discusses 790315 telcon w/R Bero of Westinghouse re incorrect weights for Velan Model C658 6-inch check valves used in safety injection sys BCHWENCER, A. Operating Reactors Branch 1 79/04/02 ip
- 7905240895 Forwards Amend 27 to License DPR-43 & notice of issuance & availability.

  8CHMENCER, A Operating Reactors Branch i 79/04/05 9pp

- --7905240905 Amend to License DPR-43, changing titles of functional positions & recognizing add1 positions
  SCHWERKER, A Operating Reactors Branch 1 79/04/05 11pp
- --7905240911 Notice of issuance 0 availability of Amend 27 to License DPR-43 SCHMENCER.A Operating Reactors Branch 1 79/04/05 200
- 7905240373 Forwards Amend 28 to License DPR-43 % notice of issuance % availability Socurity plan evaluation withheld (ref 10CFR2 790)
  SCHWENCER.A Departing Reactors Branch 1 79/04/10 3pp
- --7905240378 Amend 28 to License DPR-43, incorporating industrial security
- manual SCHWENCER,A Operating Reactors Branch 1 79/04/10 2pp
- --7908240382 Notice of issuance & availability of Amend 28 to License DPR-43 SCHWENCER.A Operating Reactors Branch 1 79/04/10 Jpp
- 7905150071 Forwards info in response to 790321 request re details of plant shutdowns
  DENTON: R Office of Nuclear Reactor Regulation 79/04/18 4pp
- 7905240471 Discusses draft safety evaluation of mod to drop pressurizer level as required ECCS initiating signal Mod & Tech Spec changes acceptable
  LAIMAB, G Plant Systems Branch 79/04/27 ip
- 7905290050 Forwards Amend 29 to License DPR~43, safety evaluation % notice of issuance % availability
  BCHWENCER.A Operating Reactors Branch 1 79/04/27 2pp
- --7905290054 Amend 29 to License DPR-43 revising Tech Specs to require actuation of safety injection based on two out of three channels of low pressuriter pressure
  SCHWENCER.A Operating Reactors Branch i 79/04/27 6pp
- --7905290060 Safety evaluation supporting Amend 27 to License DPR-43
  \* Office of Nuclear Reactor Regulation 79/04/27 2pp
- ---7905290064 Notice of issuance & availability of Amend 29 to License DPR-43 SCHMENGER,A Operating Reactors Branch 1 79/04/27 2pp
- 7905100289 Forwards Exxon Nuclear Co rept XN-NF-79-27, "Cycle 5 BAR" & WI Nuclear Co repts "Reload Safety Evaluation," dtd 790431, & "Reactor Test Program," dtd 790531
  MATHEWS: E R Wisconsin Public Service Corp 79/05/08 ip
- --7905100290 "Cycle 5 SAR "
  JUHNBUN, B L. CHERNO, J C. SKOGEN, F D Exxon Nucluar Co., Inc.
  (\*subs of Exxon Corp.) XN-NF-79-27 79/04/30 33pp
- --7905100271 "Reactor Test Program"

  \* Wisconsin Public Service Corp 79/05/01 27pp
- --7905100272 "Relead Safety Evaluation " HOLLY,J T , ROPSON,D J , WOZNIAK,S F Wisconsin Public Service Corp 79/04/30 54pp
- 7903300028 Forwards "Reactor Test Program"
  MATHEWS, E R Wisconsin Public Bervice Corp 79/05/22 ip
- --7905300030 "Reactor Yest Program Revision i "
  \* Wisconsin Public Service Corp 79/05/22 30pp.
- G Inspection reports, IE Bulletins & correspondence
- 7905010273 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping "
  KEPPLER.J G Region 3. Chicago, Office of the Director 79/03/23 ip
- 7705040065 Forwards IE Info Notice 79-07. "Rupture of Radwaste Tanks "
  KEPPLER.J. G Region 3. Chicago. Office of the Director 77/03/26
- 7905010186 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys W/Svc Air Sys Used as Source of Breathing Air"
  KEPPLER, J Q Region 3, Chicago, Office of the Director 79/03/28.

- 7905030069 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident " Licenses action required KEPPLER.J O Region 3, Chicago, Office of the Director 79/04/11
- 7905010615 Forwards IE Bulletin 79-06A: "Review of Operational Errors & Bys Misalignments Identified during TMI Incident " Licensee action required KEPPLER: J G Region 3: Chicago: Office of the Director 79/04/14
- 7905040434 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"

  KEPPLER, J O Region 3. Chicago, Office of the Director 79/04/14
- 7905040443 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping " Licensee action required KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14 10
- 7905040600 Forwards IE Builetin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During THI Incident " KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/14
- 7905290501 Responds to IE Bulletin 79-03 Investigation of piping records reveals that welded seam pips mfg by Youngstown Welding & Engineering Co not used in fabrication of safety-related sys at facility

  MATHEMS, E. R. Wisconsin Public Service Corp. 79/04/16 ip
- 7709030255 Forwards IE Bulletin 79-09. "Failures of GE Type AX-Q Circuit Breaker in Safety-Related Sys " Licensee action required KEPPLER, J C Region 3, Chicago, Office of the Director 79/04/17
- 7905080517 Forwards IE Bulletin 79-058, "Nuclear Incident at KEPPLER. J C Region 3, Chicago, Office of the Director 79/04/21
- 7905240289 Responds to IE Bullatin 79-07 re salamic stress analysis of safety-related piping Method used in analysis of selsmic loading its square root of sum of squares, not that mentioned in bullatin MATHEMS, & R Wisconsin Public Service Corp 79/04/25 12pp
- 7905240319 Responds to IE Bulletin 79-04, "Incorrect Weights for Swing Check Valves Mfg by Velan Engineering Corp " Accepted weights reanalyzed & found to be within allowable safety limits. MATHEWS, E. R. Hashington Public Power Supply System 79/04/25 3pp
- R Periodic operating reports & related correspondence
- 7705130330 Forwards monthly operating rept for Apr 1979 MATHEWS, E. R. Wisconsin Public Bervice Corp. 79/05/07 ip
- --7905150335 Monthly operating rept for Apr 1979. WALLACE J J Wisconsin Public Service Corp 79/04/30 4pp

table occurrences, LERs & related correspondence

- --7905300399 LER 79-002/01X-2 on 790221 diesel generator iA manual spasi control fatled on 790221,0302 & 13 Caused by excessive wear to bronze pinion is synchro-motor gear housing due to improper gear alignment RUITER,O H. MARCHI.M.L. Wisconsin Public Service Corp. 79/05/2
- DOCKET 50-306 PRAIRIE ISLAND NUCLEAR STATION, UNIT 2 F Security, medical, emergency & fire protection plans
- 7905070439 Forwards info requested in NRC 790206 ltr re fire protecti program Revision to 780518 fire protection outline encl. MAYER.L D Northern States Power Co 79/05/02 iSpp
- 7905300404 Forwards supplemental info on status of security plan implementation Info withheld (ref 100FR2 790) MAYER, L. D. Northern States Power Co. 79/05/25 1p

## I Financial information

- 7905150225 Forwards "Financial & Statistical Info" as suppl to 'Annua Financial Rept 1978 " BRUSVEN, A.D. Northern States Power Co. 79/05/10 ip
- ---7905150231 "Financial & Statistical Info," submitted as suppl to "Annual Financial Rept 1978 "

  \* Northern States Fower Co 79/03/31 21pp

# J Insurance & indemnity information

- 7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,185,186,187,188,189,192,193,174,175,197,193,200,201,204,206,207,208,210,212,214,215,&others.

  GUATTROCHHI, J American Nuclear Insurers 79/05/01, 1p
- 7905070502 Confirms increase in liability limit to \$36,000,000 for policies MF-22.26.27.38,39,44,46,47,49,50,51,52,53,54,55,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,91,92,93,94,95 & 96
  ROBERTS.D H Mutual Atamic Energy Liability Underwriters 79/03/C
- 7905140477 Forwards Amend 7 to Indemnity Agreement 8-60 per iOCFRi40 changes re increase in liability insurance from \$140 million to \$160 million effective 790501 Bupporting documentation enci BALTZMAN, J Antitrust & Indemnity Group 79/05/01. 600
- 7905230394 Forwards Amend 9 to Indomnity Agreement 8-42 & Amend 7 to Indemnity Agreement 8-60. JDHNSON.R.O Northern States Power Co 79/05/18. Sop

## P Operating license stage documents & correspondence

- 7905020490 Discusses 790315 telcon w/R Sero of Westinghouse reincorrect weights for Velan Model C658 6-inch check valves used in sefety injection sys SCHWENCER.A. Operating Reactors Branch 1 79/04/02 1p.
- 7905020236 Forwards PHRPTS computer code input & affidavit requesting examption from public disclosure Computer code input withheld (ref 10CFR2 790) MAYER, L Q Northern States Power Co 79/04/18 35pp
- 7905240308 Forwards Amends 35 & 29 to Licenses DPR-42 & DPR-60, respectively, safety evaluation & notice of issuance & evaluation to the evaluation of issuance & evaluation & eval SCHHENCER, A Operating Reactors Branch 1 79/04/20. 3sp.
- ---7905240322 Amends 35 & 29 to Licenses DPR-42 & DPR-60, respectively changing common station Tech Specs re refueling & incorporating changes to App A Tech Specs to support operation in Cycle 5 w/relead fuel by Erkon Nuclear Co. 80HWENGER, A. Operating Reactors Branch 1. 79/04/20, 19pp
- --7903240327 Safety evaluation supporting Amends 35 % 29 to Licenses DPR-42 & DPR-60-respectively. \* Office of Nuclear Reactor Regulation 79/04/20 19pp
- ---7903240333 Notice of issuance & availability of Amends 35 & 29 to Licenses DPR-42 & DPR-40.respectively.

  BCHMENCER: A Operating Reactors Branch 1. 79/04/20. 3pp.

- 7905010474 Forwards application for amend to Licenses DPR-42 & DPR-60, changing Tech Specs re pressurizer initiating signals for safety injection signals Amend fee & proposed Tech Spec changes encl MAYERL O Northern States Power Co 79/04/26 10pp
- 7705020462 Forwards ambient sound level survey in response to recent J Lehr request for add1 info re ETS MARD/E C Northern States Power Co 79/04/27 2pp
- 7905010479 Forwards amond fee of \$4,400 for Licenses DPR-42 & DPR-60 \* Northern States Power Co 79/05/01 is
- 7905140214 Submits Environ Event Rept 79-03 for 790424-0502 discharge canal gate structure under water, rendering control & monitoring of blowdown flow inoperable WARD, E C Northern States Power Co 79/05/08 1p
- & Inspection reports, IE Bulletins & correspondence
- 7905010262 Forwards IE Info Notice 79-06, "Stress Analysis of Bafety-Related Piping " KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/23
- 7905040048 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tants" KEPPLER.J G Region 3, Chicago, Office of the Director 79/03/26
- 7905090126 Forwards IE Insp Repts 50-282/79-06 \$ 50-306/79-06 on NOSOVOLEG FORMATO'S AS THEY REPORT TO A CONTROL OF THE STATE OF THE ST
- --7905090131 IE Insp Repts 50-282/79-06 & 50-306/79-06 on 790227-28 & 70301-02 No noncompliance noted Major areas inspected emergency plan, emergency facilities, equipment & supplies, radioactive effluent sys & emergency training GESTHANN, J. ESSIG, T H Region 3, Chicago, Office of the Director 79/03/20 App
- 7905010174 Forwards IE Info Notice 79-08. "Interconnection of Contaminated Sys w/Syc Air Sys Used as Source of Breathing Air
- KEPPLER, J Q Region 3: Chicago: Office of the Director 79/03/28 10
- 7705010410 Forwards IE Info Notice 79-09. "Spill of Radioactively Contaminated Resin Region 3, Chicago, Office of the Director 79/03/30 KEPPLER, J Q
- 7905070344 Responds to IE Bulletin 79-03 All longitudinal welds of ABTM-A31 statiless steel piping 100% radiographed & free of defects Add1 testing unnecessary.

  MACHTER.L J Northern States Power Co 79/04/10. ip
- 7905030040 Forwards IE Bulletin 79-04, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident " Licenses action required KEPPLERIJ O Region 3, Chicago. Office of the Director 79/04/11
- 7905010600 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified during TMI Incident." Licenses action required MEPPLERIJ 0 Region 3, Chicago, Office of the Director 79/04/14.
- 7903040405 Forwards IE Bulletin 79-068, "Review of Operational Errors & Sign Misalignments Identified During TMI Incident,"

  KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/04/14
- 7905040451 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Bafety-Related Piping," Licensee action required, KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/04/14
- 7905040576 Forwards IE Bullstin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident "
  KEPPLER, J Q Region 3, Chicago, Office of the Director. 79/04/14
- 7903030237 Forwards IE Builetin 79-09. "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Bys " Licensee action required, KEPPLER, J G Region 3: Chicago, Office of the Director 79/04/17 10.

- 7905080505 Forwards IE Bulletin 79-058. "Nuclear Incident at TMI-Suppl " KEPPLER,J 0 Region 3, Chicago: Office of the Director 79/04/21
- 7905140100 Ack receipt of 790410 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-282/79-03 & 50-306/79-03 BAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/04/25 lp
- --7905140104 Responds to NRC 7703E3 ltr re violations noted in IE Insp Repts 50-282/77-03 & 50-306/77-03 Corrective actions torque values were reduced & new bolts were retorqued to specified value WACHTER, L.J. Northern States Power Co. 79/04/10 2pp
- DOCKET 50-306 PRAIRIE ISLAND NUCLEAR STATION, UNIT 2 G. Inspection reports, IE Bulletins & correspondence
- 7905290290 Responds to IE Bulletin 79-09 GE Type AK-2 breakers not in WACHTER, L J Northern States Power Co 79/05/04 ip
- R Periodic operating reports & related correspondence
- 7905010509 Forwards monthly operating rept for Feb 1979
  MAYER, L D Northern States Power Co 79/04/25 1p
- --7903010511 Monthly operating rept for Feb 1979 HUNSTAD, A A Northern States Power Co 79/ 79/03/01
- 7905150496 Forwards monthly operating rept for Apr 1979 MAYER, L O Northern States Power Co 79/05/10 1p
- --7905150499 Hunthly operating rept for Apr 1979 HUNBTAD, A A Northern States Power Co 79/05/01
- 8 Reportable occurrences, LERs & related correspondence
- 7909030364 Forwards LER 79-009/01T-0 MAYER, L D Northern States Power Co 79/04/26
- --7905030367 LER 79-009/01T-0 on 790412 notified by vendor that small break in pressurizer indicator Lp may hang up while Pp decreases delaying safety injection Hestinghouse recommends manually initiating safety injection implements HUNSTAD.AA Northern States Power Co 79/04/26 ip
- 7905110127 Forwards LER 79-008/03L-0
  MAYER, L O Northern States Power Co 79/05/08 ipp.
- --7905110131 LER 79-008/03L-0 on 790408 safety injection gump il failed to start automatically:started in manual Cause unknown Event could not be repeated Fessibility of monitor light to detect failures being studied HUNSTAD.AA Northern States Power Co 79/05/08 ip
- 7905210279 Forwards LER 79-011/03L-0.
  MAYER, L O. Northern States Power Co 79/05/16 1p
- --7905210283 LER 79-011/03L-0 on 790416; transformer failed, leaving plan w/one source of offsite power Caused by switching error Transformer replaced prior to restart. Investigation continuina continuing RUETHER.J.C. Northern States Power Co. 79/05/16 ip
- 7905220114 Ferwards LER 79-013/03L-0. MAYER.L C. Northern States Power Co 79/05/17. 1p
- --7905220118 LER 79-013/03L-0 on 790417, during investigation of discrepant status light indication, diesel cooling water pump 22 engine was inadvertently tripped Caused by personnel error. Personnel to review event. HUNGTAD. A A Northern States Power Co 79/05/17. Ip
- DOCKET 50-309 MAINE YANKEE ATOMIC FOWER PLANT Security, medical, emergency & fire protection plans
- 7905300019 Dateils expansion of fire brigade size.
  MOGDY.D.E. Mains Yankse Atomic Power Go 79/05/24. ip.

- G Adjudicatory correspondence
- 7905250044 Forwards Legislative Util Consumers' Council's petition to intervene JUDD,H T New Hampshire, State of 79/04/02 2pp
- --7905250046 Petition to intervene re 790313 order to show cause JUDD.H T New Hampshire. State of 79/04/02 2pp
- 7903230792 Ack receipt of 790314 telegram questioning shutdown of facility Director of Nuclear Reactor Regulation will shortly be in position to reconsider whether continued suspension of operations remains necessary HENDRIE, J M Commission 79/04/12 1p
- --7905230803 Protests show cause order mandating shutdown of facility & requests reconsideration of order THURLOW, E.W. Maine Yankee Atomic Power Co. 79/03/14 1p

#### H General correspondence

- 7905070013 Responds to 790312 request Forwards 790302 submittal re transformer failure & statistical rept for Sept 1978 W/o encl Operating Reactors Branch 4 79/03/16 ip
- 7703010549 Urges NRC to put facility back on line RENY.R H Maine Merchants Association. Inc. 79/03/24 ip
- 7905240819 In response to 790329 ltr, forwards add1 info re control rod tube wear Ongoing reviews of guide tube wear & asymetric LOCA loads do not require plant shutdown at this time REID.R W Operating Reactors Branch 4 79704/19 3pp
- 705300681 Reviews NRC actions taken to expedite returning plant to operation KENDRIE, J M Commission 79/05/02 2pp.
- -7905300686 Reviews untimely energy impact of NRC decision to close plant Orges expeditious review COHEN.W S Senate. 79/03/26 2pp

### Financial information

105230528 Forwards statement of capital requirements & sources for CY79, in response to 780203 request
CRABTREE, R A Maine Yankse Atomic Power Co 79/05/16 2pp

### Insurance & indemnity information

- 705070497 Confirms increased liability limit to \$124,000.000 for policies NF-1,29,43,76,83,100,111,140,146,151,161,164,170,173,174,176,179,180,182,188,189,189,199,193,194,195,197,198,200,201,204,206,207,208,210,212,214,215,& others. QUATTROCHHI. J American Nuclear Insurers 79/05/01
- 705070582 Confirms intrease in liability limit to \$36,000,000 for policies MF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,56,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,91,92,93,94,95,2,6

- 7905030155 Ack receipt of 790402-03 submittals in response to 790313 order to show cause Forwards request for add1 info REID.R W Operating Reactors Branch 4 79/04/10 4pp,
- 7905070373 Notification of 790420 meeting w/util in Bethesda, MD to discuss studies done in support of SHOCK 1 computer code application NEL BON. C. C. Operating Reactors Branch 4 79/04/19
- 7705270038 Responds to 790413 requestire QA program Suggests revision number of YOGAP-1-A not be designated HEIDER, L. H. Yankee Atomic Electric Co. 79/04/24 1p
- 7905240367 Summary of 790420 meeting w/util & S&W in Bethesda, KD rause of PSTRESS/SHOCK I computer code
  NELSON.C C Operating Reactors Branch 4, 79/04/26 3pp
- 7905040615 Forwards status rept on 790427 "Plan for Verification of Dynamic Analysis Codes"

  JACOBS: 8 B Stone & Medister Engineering Corp 79/04/27 2pp.
- 7705090330 Forwards add1 info in response to NRC 790402 ltr re independent review of SHOCK 1 & 2 computer runs & C-E's dynamic seismic analysis of reactor coolant sys GROCE.R H Maine Yankee Atomic Power Co 79/04/27 lipp
- 7905070548 Forwards Revision 6 & Amend 1 to Revision 6 of operational OA programmes requested in 790410 ltr GROCE.R H Yankas Atomic Electric Co 79/04/30 4pp.
- --7905070553 Informs that revisions to GA program are acceptable
  HAASS.W P Guality Assurance Branch 79/04/10 17pp.
- 7905040514 Submits info requested at 790420 meeting on piping systemic relview spectrum curves piping designs & other points Demonstrates satisfactory requirements of 790313 order to show cause Supparting documentation en
- 7905080435 Informs that program will be initiated to update analysis for all safety-related giping sys.consisting of field varification of piping & reanalysis following method detailed in 790601 ltr GRQCE.R H Mains Yankes Atomic Power Co 79/05/02 Ip
- 7905090061 Forwards comparison of pips stress results from SHOCK O/SHOCK 1 & SHOCK O/NUPIPE-SW for identical piping geometries GRUCE, R. H. Maine Yankee Atomic Power Co. 79/05/04, 85pp.
- 7705090372 Forwards "Summery of Design Margins & Criteria for MC Yambu Atomic Power Station" for piping sys seismic review GROCE.R.H Maine Yankee Atomic Power Co 79/05/05 ip
- -7903070373 "Bummary of Design Margins & Criteria for ME Yankee Atcelt Power Station" for piping sys seismic reviaw \* Maine Yankee Atomic Power Co. 79/05/05 37pp,
- 7905090382 Forwards responses to NRC 790504 questionnaire re total less of offsite power, reactor coulant sys leak, major loss of reactor coulant, steam line rupture & engineered safeguards WOOD, E C Maine Yankee Atomic Power Co 79/05/07 69pp
- 7905140239 Forwards proprietary documents requested during 790501-04 special insp ERLEWINE, J. A. Stone & Webster Engineering Corp. 79/05/08 ip
- ~~7905140245 Requests withholding Technical Guideline EMTO-22-0 & Technical Rept EMTR-612 (ref 10CFR2 790), Affidavit enci KENNEDY, W. J. Stone & Webster Engineering Corp. 79/05/Q4 10pp
- 7905140382 Confirms 790504 telcon w/HT Russell re computer deck associated w/SHOCK O program.
  KENNEDY:W J Stone & Webster Engineering Corp. 79/05/09 is
- 7905130494 Details status of piping seismic review of SHOCK O program Program to calculate natural frequencies will be evaluated to determine effects on original stress analysis results OROCE,R.H Maine Yankes Atomic Power Co 79/05/10 1p.
- 7905230467 Forwards response to NRC 790508 request for info re analysis of main feedwater & pressure relief sys
  MDOD.E.C Maine Yankee Atomic Power Co. 79/05/10 3pp
- 7905160335 Notifies that review of computer dack is completed SHOCK O program still unrecovered. Piping sys conservatively designed & will perform intended function.

  KENNEDY W. J. Stone & Webster Engineering Corp 79/05/11. 1p

- 7905190131 Forwards response to 790314 request for info re thermocouple leads mfg by Reuter-Stokes Canada Ltd HOOD.E C Maine Yankse Atomic Power Co 79/05/14 2pp
- 7905210111 Forwards SHOCK 1 computer program listing Supersedes submittal of 790406 Program listing withheld (ref 10CFRZ 790) KENNEDY, H J Stone & Webster Engineering Corp 79/05/14 ip
- 7903220243 Bubmits info re containment isolation sys.purging sys & ECCS.in response to 790809 request WDDD.EC Maine Yankee Atomic Power Co 79/05/14 4pp
- 7903220251 Submits info re pressurizer heaters, feadwater & steam generators, in response to 790510 request WDDD.E G Maine Yankee Atomic Power Co 79/05/14 9pp
- 7905210130 Forwards Bhock O/Shock 1 piping comparisons ORDCE:R H Maine Yankee Atomic Power Co 79/05/15 23pp
- 790521016: Requests 790313 order to show cause be lifted VANDENBURGH, D Mains Yankae Atomic Power Co 79/05/15 4pp
- 7903250137 Submits info restating position re adequacy of good title seismic design & piping Piping strosses within FBAR criteria & in many cases lower than previously calculated JOINBON.M P. Maine Yankee Atomic Power Co 79709/18 2pp
- 7905270335 Bummarizes procedures & calculational techniques used in reanalysis of piping sys designed w/8HOCK II computer program Reanalysis will satisfy 790313 order to show cause KENNEDY, W. J. Stone & Webster Engineering Corp. 79/05/18 App.
- 7905240456 Forwards Offsite Dose Calculation Manual QROCE, P. H. Maine Yankee Atomic Power Co. 79/05/21 1p
- ---7905240459 Offsite Dose Calculation Hanual
  # Haine Yankse Atomic Power Co 79/05/14 43pp
- Q Inspection reports: IE Bulletins & correspondence
- 7903010119 Forwards IE Info Notice 79-06, "Stress Analysis of Bafety-Related Piping" ORIER: BH Region 1, Philadelphia, Office of the Director 79/03/20 1p
- 7903010030 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Bvc Air Sys Used as Bource of Breathing Air."

  GRIER, B H Region 1, Philadelphia, Office of the Director 79/03/28 1p
- 7903030185 Responds to IE Bulletin 79-03 re design & fabrication of piping sys No action necessary by util.
  MODDY/D E Maine Yankee Atomic Power Co. 79/03/28 ip
- 7903010301 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin" ORIER:B H Region 1, Philadelphia: Office of the Director 79/03/30. ip
- 7905020055 Forwards IE Bulletin 79-06, "Review of Operational Errore & Bus Misalignments Identified During THI Incident " Licensed action required ORIER, B. H. Region 1: Philadelphia, Office of the Director 79/04/11. 1p
- 7905290134 Forwards IE Insp Rept 50-309/79-05 on 790404-06 No honcompliance noted. CARLSON,R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/04/13 2pp
- ---7905290137 IE Insp Rept 50-309/79-05 on 790404-06 No noncompliance noted Major areas inspected selamic design concerns, review of as-built drawings for affected sys & walking of affected lines for one sys. FABAND, A. N.; TRIPP, L. Region 1, Philadelphia, Office of the Director 79/04/12 5pp
- 7705020342 Forwards IE Bulletin 77-07, "Beismic Stress Analysis of Bafety-Related Piping," Licensee action required GRIER:B H Region 1, Philadelphia, Office of the Director 79/04/14, 1p.
- 7905040046 Forwards IE Bullatin 79-048, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident," Licenses action required GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/04/14, 1p.

- 7905040211 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Hater Power Reactors Identified During TMI Incident "ORIER, B H Region 1, Philadelphia, Office of the Director 79/04/14 | 12
- 7905030075 Forwards IE Bultetin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " Licensee action required ORIER, B H Region 1. Philadelphia, Office of the Director 79/04/17 1p
- 7903020278 Forwards IE Bulletin 79-06A.Revision 1, "Review of Operational Errors & Sys Hisalignments Identified During TMI Incident "
  ORIER.8 H Region 1, Philadelphia, Office of the Director 79/04/18 1p
- 7905250496 Responds to IE Bulletin 79-07 re seismic analysis of safetyrelated piping Currently addressing bulletin under NRC order to show cause, 464 790313 GROCE,R H Maine Yankee Atomic Power Co 79/04/24 ip
- 7905230353 Responds to [E Bulletin 79-068 re TMI errors Forwards info re review of operational errors & sys misalignments identified during TMI VANDENBURGH.D E Maine Yankee Atomic Power Co 79/04/26 Spp
- 7905210157 Submits add1 info to IE Bulletin 77-068 re TMI errors Will evaluate design change to isolate component cooling to reactor coolant pumps on spray signal ORUCE.R H Maine Yankee Atomic Power Co 79/05/14 1p
- R Periodic operating reports & related correspondence
- 7905180516 Forwards monthly operating rept for Apr 1979 MODDY, D E Maine Yankee Atomic Power Co 79/05/12 10
- --7905150520 Monthly operating rept for Apr 1979 BJDGREN.R M Maine Yankee Atomic Power Co 79/05/12 5pp
- T Hearing transcripts on non-antitrust matters
- 7905270031 Transcript of 790503 briefing in Hashington, DC Pp 1-55 HENDRIE, J M . GILINSKY, V , KENNEDY, R T Commission 79/05/03 55pp
- DOCKET 50-311 BALEM NUCLEAR GENERATING STATION, UNIT 2

  A Application/construction stage documents & correspondence
- 7905300594 Notifies that demonstration of integrity of channelheads must be undertaken through direct monitoring plan should be forwarded promptly PARR.O D Light Water Reactors Branch 3 79/04/23 2pp
- 7905040519 Forwards response to request for addl info re rept on structural integrity containment test & valve data for 36-inch & 10-inch valves associated w/containment purge & pressure vacuum relief sys MITTL,R L Public Bervice Electric & Qas Co of New Jersey 79/04/24 4pp
- 7905150482 Notifies that 790330 application for extension of facility completion date was not accompanied by amend fee Requested action falls into fee Class II Requests prompt submittal of fee MILLER.W.O License Fee Management Branch 79/04/26 1p
- 7905240226 Requests addl info to continue evaluating request for extension of const completion date PARR.O D Light Water Reactors Branch 3 79/05/01 2pp
- 7905080481 Forwards supplemental test data re seismic qualification of SkV switchgear relays to satisfy request for add1 info established by review team during 790226-27 site audit HITTL.R.L. Public Service Electric & Oas Co of New Jersey 79/05/02 2pp
- ---7905080483 "Protective Relay Seismic Data, HFA, IAC & IAV, Ref Documentation for NRC SGRT Review, Response Item 2 " \* Public Service Electric & Gas Co of New Jersay 79/04/23 400pg
- 7905090308 Forwards updated listings of items, including preoperational tests which may not be completed until after initial fuel loading Requests deferral of incomplete test Items MITTL.R L Public Service Electric & Gas Co of New Jersey 79/05/04 App

- 7905220349 Responds to Westinghouse 790328 notification of potential single dropped rod events which could lead to DNB ratios lower than reported Units are four loop plants & do not have potential problem MITTL.R L. Public Service Electric & Oas Co. of New Jersey 79/05/15. 2pp
- 7905250100 Submits additinfore NPSH, available for RHR pump during accident recovery recirculation mode MITTL/R L Public Service Electric & Gas Co of New Jersey 79/05/17 4pp
- 7905250415 Forwards excerpts from Hyle Lebs seismic qualification test repts HITTL,R L. Public Service Electric & Oas Co. of New Jersey 79/05/23 30pp

#### H General correspondence

- 7905070450 Ack receipt of 790216 resolution opposing storage of high level radioactive wastes in township Objections should be made at ABLD hearing Expansion of storage pools is unlikely No independent facilities are planned DENTON, H.R. Office of Nuclear Reactor Regulation 79/03/29 Spp
- 7700140291 Responds to 770312 itr re resolution adopted on 790216 by Township of Lower Alloways Creek.NJ Resolution opposes storage of high level wastes Forwards NRC response OCSSICK.L V Office of the Executive Director for Operations

### I Financial information

- 7905070647 Forwards "Annual Financial Rept.1978" for Public Svc Electric & Cas Co.Atlantic City Electric Co.Delmarva Power & Light Co & Philadelphia Electric Co FRYLING.R Public Service Electric & Cas Co of New Jersey 79/04/30 162pp
- J Insurance & indemnity information
- 7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,102,185,186,187,188,189,182,173,174,175,177,178,200,201,204,206,207,208,210,212,214,215,bothers QUATTROCHHI, J American Nuclear Insurers 79/05/01 ip
- 7905070582 Confirms increase in liability limit to \$36.000.000 for policies MF-22.26.29.38.39.44.46.47.49.50.51.52.53.54.59.56.57.08.60.61.64.66.67.68.69.70.71.72.74.76.77.78.79.80.86.67.88.90.71.72.74.76.77.78.79.80.86.87.
- 7905290089 Forwards Endorsements 33,34 & 35 to ANI Policy NF-230 CORREA, C Marsh & McLenon, K & M Nuclear Consultants, Inc Div 79/05/22 4pp

# G Inspection reports. IE Bulletins & correspondence

- 7705010140 Forwards IE Info Notice 79-06. "Stress Analysis of Safety-Related Piping " GRIER.B H Region 1. Philadelphia. Office of the Director, 79/03/23. 1p.
- 7905300743 Forwards IE Insp Rept 50-311/79-17 on 790306-08 No noncompliance noted BRUNNER.E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branck 79/03/23 2pp
- ---7905300752 IE Insp Rept 50-311/79-17 on 790306-08, No noncompliance noted Major areas inspected startup test program test procedure review & verification.plans for plant operational tests & plant tour BETTENHAUSENL , FASANO.A. N. Region 1, Philadelphia, Office of the Director. CAPHTON D. L. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/03/21 Spp
- 7905290065 Responds to IE Bulletin 79-03 No safety-related pipe assemblies from Youngstown Helding & Engineering Co are used.

  8CHNEIDER, F. W. Public Service Electric & Oas Co of New Jersey 79/04/04, 2pp.
- 7905020100 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TKI Incident."

  ORIER. B. H. Region i, Philadelphia, Office of the Director 79/04/11. 19

- 7905020369 Forwards IE Bulletin 79-07, "Beismic Stress Analysis of Bafety-Related Piping " Licensee action required ORIER B M Region 1, Philadelphia, Office of the Director 79/04/14 1p
- 7905040093 Forwards IE Bulletin 79-04B, "Review of Operational Errand Bys Misalignments Identified During TMI Incident "GRIER.B H Region I. Philadelphia, Office of the Director 79/04/14 ip
- 7905040282 Forwards IE Bulletin 79~08, "Events Relevant to Bolling Mater Power Reactors Identified During TMI Incident " GRIER.B H Region 1, Philadelphia, Office of the Director 79/04/14 1p
- 7905030101 Forwards IE Builetin 79-09, "Failures of QE Type AK-2 Circuit Breaker in Safety-Related Sys " Licenses action required ORIER.B H. Region 1. Philadelphia. Office of the Director 79/04/17 1p
- 7905020322 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During THI Incident "ORIER, B H Region 1, Philadelphia, Office of the Director 79/04/18 1p
- 7905280072 Responds to IE Bulletin 79-07. "Seismic Stress Analysis of Sefety-Related Piping " Provides results of Westinghouse analysis of reactor coolant loop & large bore Class I piping SCHNEIDER, F M. Public Service Electric & Oas Co. of Now Jarssy 79/05/03 27pg
- R Periodic operating reports & related correspondence
- 7905080462 Forwards Mar 1979 operating rept for industrial wastriveatment plant HIDURA.H J Public Service Electric & Que Co of New Jersey 79704705 2pp
- 7905080466 Forwards Mar 1979 wastewater treatment rept for savige treatment plant HIDURA'H J Public Service Electric & Gas Co of New Jersey 79/04/12 2pp
- 7905080489 Forwards rept of subsurface water diversion & chloride analysis of well water for quarter ending 790331 HIBURA.H J Public Service Electric & Oas Co of New Jersey 79704/16 Jpp
- 7905080421 Forwards Natl Pollution Discharge Elimination Sys disthrp monitoring regt for Mar 1979
  MIDURA.H J Public Service Electric & Gas Co of New Jersey
  79/04/20. 13pp
- 7905300417 Forwards "Operating Rept for Apr 1979 for Industrial Walls Treatment Plant" MIDURA-H J Public Service Electric & Gas Co of New Jersey 79/09/08 ip
- --7905300421 "Operating Rept for Apr 1979 for Industrial Wasts Irrain Plant " HIDURA.H J Public Service Electric & Gas Co of New Jersey 79704/30 19.
- 7905300431 Forwards Apr 1979 wastewater treatment rept for sewage treatment plant MIDURA.H J. Public Service Electric & Gas Co of New Jersey 79/05/10. 2pp
- 7905300363 Forwards discharge monitoring repts for Apr 1979 HIDURA:H J Public Service Electric & Oas Co of New Jarsey 79/05/22 13pp
- 7905290408 RD 79-43/01P on 790522, procedure to demonstrate operability of steam driven auxiliary feadwater pump 13 permitted closure of discharge control valves Procedure changed to ensure operability MIDURA:H J Public Service Electric & Gas Co of New Jersey 79/09/22. 1p

- DOCKET 50-312 RANCHO SECO NUCLEAR GENERATING STATION
- H General correspondence
- 7905070143 Requests NRC honor Governor Brown's request to shutdown Rancho Seco STEINER, R , Affiliation Umknown 79/04/02 1p
- 7905140045 Requests closing of plant; respondent & husband are starting family & are concerned about rediation & cancer risk TAVERNIER, S.W. Affiliation Unknown 79/04/02 ip
- 7905020011 Recommends temporary shutdown of Rancho Seco until present uncertainties re TMI-2 incident are clarified MATBUI.R.T House of Rep. 79/04/24 2pp
- 7905100364 Requests temporary shutdown of Rangh Seco in view of incident of TMI-2 BROWN, 도 Q California, State of 79/04/24 ip
- 7905240444 Favors precautionary shutdown of facility in light of TMI-2 MCCARTHY, L. T California, State of 79/04/24 ip
- 7905150053 Notifies that if Rancho Seco is shut down, availability of power from addl sources is subj to transmission limitations & other factors unique in sys

  BHACKELFORD, B Bacramento Municipal Utility District 79/04/26
- 7905020286 Expresses gratitude re concern for safety problems of nuclear power plants
  KNOTT-M Affiliation Unknown 79/04/27 15
- J Insurance & indemnity information
- 7909070497 Confirms increased liability limit to \$124,000,000 for policies NF-1.25,43.76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,183,185,186,187,188,189,192,193,194,195,197,198,200,201,204,206,207,208,210,212,214,215,8 others QUATTROCHHIJ American Nuclear Insurers
- 7905160243 Forwards Amend 6 to Indemnity Agreement 8-66, per 10CFR140 changees re increase from \$140 million to \$160 million. effective 790501 Supporting documentation enci SALTZMAN. J Antitrust & Indemnity Group 79/05/01 Spp
- 7903290369 Forwards executed Amend 6 to Indemnity Agreement 8-66 MATTIMDE: J J Sacramento Municipal Utility District 79/05/21 3pp.
- P. Operating license stage documents & correspondence
- 7905110114 Forwards safety evaluation re lose of nonsafety-grade instrument power supply causing reactor turbine trips on 780320 E 18ENHUT, D. Division of Operating Reactors 78/03/30 ip
- ---7905110117 Bafety evaluation re loss of nonsafety-grade instrument supply causing 780320 reactor & turbine trips B&W & independent staff analyses conducted B&W considered appropriate regions of steam generators Findings acceptable \* Engineering Branch 78/03/20 4pp
- 7905110050 Comments on 780320 cooldown transient points out significant defictionicy in present custom & STB for RCS heatup/cooldown rates & pressure-temp limits STELLO. V Division of Operating Reactors 78/04/07. 1p.
- 7905110004 Forwards committee rept on 780320 transient resulting from loss of non-nuclear instrumentation Y power supply DUNN, J D. Sacramento Municipal Utility District. 78/04/19 11pp
- 7903110133 Informs of intention to return to full power operation on 780701; pending approval of small break LOCA analysis B&W concurs w/continued plant operation MATTIMOE.J J Bacramento Municipal Utility District 78/06/19 ip
- 7905220035 Determines 790316 application involves single safety issue being themselves categorized as Class III fee MILLER. W. O License Fee Management Branch 79/04/19 ip
- 7905300651 Requests addl info re ground motion input DAVIS, J F. California, State of 79/04/24. 2pp

- 7905020306 Responds to IE Bulletin 79-05B Requests extension to reply date due to sys mods underway as described in 790427 ltr Answers will be provided prior to startup following 790428 shutdown MATTIMOE, J J Sacramento Municipal Utility District 79/04/27 ip
- 7905110307 Forwards procedural change approval forms for turbine trip, ions of steam generator feed, loss of reactor coolant flow be auxiliary feedwater systems (CCLOMBO.R W. Sacramento Municipal Utility District. 79/05/04
- 7905190156 Forwards procedural changes re auxiliary feedwater sys, load rejection, condensate & feedwater sys & main feedwater pump Sys Sys MATTIMOE, J J Sacramento Municipal Utility District 79/05/14
- 7905240710 Submits current status of 790427 proposed actions refeadwater sys & load rejection, in response to 790507 order Supporting documentation encl MATTIMGE, J J Sacramento Municipal Utility District 79/05/14
- 7905190134 Forwards revised radiological effluent Tech Specs which include requirements of NUREG-0472
  MATTIMOE, J. J. Sacramento Municipal Utility District 79/05/15 1p
- G Inspection reports, IE Bulletins & correspondence
- 7905110083 Forwards IE Insp Rept 50-312/78-03 on 780321-22,28-31 & 0417 CREWS.JL GREWS, J.L. Region 5, San Francisco, Reactor Operations Nuclear Support Branch 78/04/21 200
- --7905110086 IE Insp Rept 50-312/78-03 on 780321-22,28-31 & 0417 No noncompliance noted Major areas inspected design change control,procurement,procedures, safety limits & limiting conditions for operations

  CANTER: H L . WOESSNER J D Region 5, San Francisco, Office of
  the Director CREWS, J L Region 5, San Francisco, Reactor

  Operations Nuclear Support Branch 78/04/21 12pp
- 7905010291 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping "
  ENGELKEN,R H Region 4. Dallas. Office of the Director 77/03/23
- 7905150533 Forwards IE Insp Rept 50-312/79-05 on 790226-0302:13 & 15 No noncompliance noted CREWS, J L Region 5, San Francisco, Reactor Operations Nuclear Support Branch 79/03/23 2pp
- --7905150539 IE Insp Rept 50-312/79-05 on 790226-0302.13 & 15 No noncompliance noted Major areas inspected calibr, startup testing, maint, followup on LEAs & IE bulletins JUHNSTON, G W. JUHNSON, A D., FAULKENBERRY, B Region 5, San Francisco, Reactor Operations Nuclear Support Branch 79/03/2
- 7905010222 Forwards IE Info Notice 79-08. "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathin Air ENGELKEN, R H Region S. San Francisco. Office of the I

- 7905040622 Forwards IF Bulletin 79-08. "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident" ENGELKEN.R H Region 5. San Francisco. Office of the Director 79/04/14
- 7903070108 Forwards IE Bulletin 79-07. "Seismic Stress Analysis of Safety-Related Piping " Licensee action required ENGELKEN, R H Region 5, San Francisco. Office of the Director 79/04/14 ip
- 7905030300 Forwards [E Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " Licensee action Tequired ENGELKEN,R H
  - Region S. San Francisco, Office of the Director 79/04/17
- 7905080374 Forwards IE Bulletin 79-058. "Nuclear Incident at TMI-Buppl " Licensee action required ENGELKEN R H Region 5. San Francisco. Office of the Director
- 7905220465 Responds to IE Bulletin 79-07 re seismic analysis computer codes No analysis methods apecified in bulletin were used in computer codes tists computer codes which have been used in seismic stress analysis Sacramento Municipal Utility District 79/04/24 WALBRIDGE, W.C.
- 7905100293 Believes proposed Amend 63.dtd 790316.re inservice insp requirements is exempt from license fees.per 100FR170 22 MATTIMORE, J.J. Sacramento Municipal Utility District 79/04/30
- R Periodic operating reports & related correspondence
- 7905100281 Forwards monthly operating rept for Apr 1979 RODRIGUEZ, R J Sacramento Municipal Utility District 79/05/03
- --7905100282 Monthly operating rept for Apr 1979 COLOMBO,R W Sacramento Municipal Utility District 79/04/30
- S Reportable occurrences. LERs & related correspondence
- 7905110006 PNO-78-56 loss of instrument power supply resulting in reactor 5 turbine trips on 780320 Excessive cooldown caused reactor coolant pressure to decrease WHITT, K W. NOLAN, F J . SNIEZEK, J H Office of Inspection & Enforcement 78/03/21 ip
- 7905110023 Discusses load transfer on B&W instrumentation, in response to 780517 request Task definitions encl
  REID,R W Operating Reactors Branch 3 78/06/06 3pp
- --770511002B Transfer of lead responsibility re 780320 non-nuclear instrumentation power loss & overcooling of primary cooling sys Discusses recommendations for generic aspects WOODRUFF, R W Office of Inspection & Enforcement 78/04/25 3pp
- --7905110032 Forwards LER 78-001/01T-0
  MATTIMOE, J J Sacramento Municipal Utility District 78/03/31

- 7903030028 Forwards PNO-79-67U ENGELKEN R H 79/04/14 1P Region S, San Francisco, Office of the Director
- 7905020535 Forwards PND-79-67AA ENGELKEN, R H Region 5. San Francisco, Office of the Director 79/04/20
- 7905010437 Forwards PND-79-67AB ENGELKEN.R H Region 5, San Francisco: Office of the Director 79/04/21 1p
- 7905010450 Forwards PND-79-67AC & AD ENGELKEN, R H Region 5. San Francisco. Office of the Director
- 7905110009 PNO-79-89 on 790422.coolant sys pressure on 790422 resulted in automatic reactor shutdown Caused by failure of A inverter power supply Unit returned to operation on 790423 BRYAN, S.E., KL.INGLER, G.R. Office of Inspection & Enforcement 79/04/23 3pp
- 7905010440 Forwards PNO-77-67AE ENGELKEN,R H Region 5, San Francisco, Office of the Director ENGELKEN, R H 79/04/24 1s
- 7903070045 Forward: PNO-79-67AF ENGELSEN.R H Region 5, 5at 79704/25 ip Region 5, Ban Francisco, Office of the Director
- 7905090038 Forwards PND-79-67AG ENDELKEN,R M Region 5, San Francisco, Office of the Director 79/04/26 1p
- 7905090120 Forwards PNO-79-67AH ENGLEKEN R H 79/04/27 1p Region 5, San Francisco, Office of the Director
- 7903070033 Forwards PND-79-67AI.AJ & AK per NRC 790401 ltr transattir; IE Bulletin 79-05 ENGELKEN.R H Region 5, San Francisco, Office of the Director Region S. Ban Francisco, Office of the Director 79/04/30
- 7905070015 Forwards PNO-79-67AL per NRC 790401 itr transmitting IE Bulletin 79-05 ENGELKENJR M. Region 5, San Francisco, Office of the Director Region 5, San Francisco, Office of the Director 79/05/01
- 7905310050 Forwards PNO-79-67AM
  ENGELWEN,R H Region 5, San Francisco, Office of the Director 79/05/07 19
- 7905250434 Forwards LER'79-003/03L-0 HATTIMOE, J J Bacramento Municipal Utility District 79/05/41
- --7905250437 LER 79-003/03L-0 on 790422 reactor trip occurred when 51% inverter failed, Caused by 150 amp. 125 volts DC inverter input breaker tripping when breaker undervoltage trip coil COLOMBO, R W Sacramento Municipal Utility District 79/05/21
- 7905290004 LER 79-003/03L-0 on 790422 SiA vital power inverter failed twice within four months Caused by underdesigned UV trip coil Resistor added to circuit COLOMBO, R W Secremento Municipal Utility Dietrict 79/05/21 is
- 7905300405 Forwards LER 79-004/03L-0.
  MATTIMOE, J. J. Bacramento Municipal Utility District 79/05/23
- ---7905300409 LER 79-004/03L-0 on 790425 test revealed that bypass velve did not fully close. Caused by maladjustment of mechanical interlock/linkage Linkage adjusted & tested satisfactorily CGLOMBO.R W Bacramento Municipal Utility District 79703/23
- DOCKET 50-313 ARKANSAS NUCLEAR DNE, UNIT 1
- F Security, medical, emergency & fire protection plans
- 7705100318 Requests change in implementation date for complete installation of 3-h rated fire dampers in ventilation ducts Proposes to install dampers by end of fourth refueling outage. RUETER, D. A. Arkansas Power & Light Co. 79/03/13. 2pp

- 7905090300 Responds to 790309 plans for testing cable penetration fire stops installed in metal lath & plaster walls Proposed test acceptable
  - REID, R W Operating Reactors Branch 4 79/04/03 2pp
- 7905020231 Informs that fire protection mode required to be implemented during this refueling outage will be completed as scheduled TRIMBLE.D C Arkansas Power & Light Co 79/04/24 ip
- 7905040008 Forwards second revision to fire protection plan TRIMBLE, D C Arkansas Power & Light Ca 79/04/30 1p
- --7909040019 Revision 2 to fire protection plan
  \* Arkansas Power & Light Co 79/11/14 23pp

#### # General correspondence

- 7905240995 Responds to 790412 ltr to JM Hendrig re nuclear power plant near Russellville, AR Outlines steps for license review Forwards "Transportation of Nuclear Fuel & Waste" & "Disposal of Radioactive Waste" W/o encl DEYOUNG, R C Division of Site Safety & Environmental Analysis 79/05/07 2pp
- --7905240765 Expresses concern re nuclear plants at Russellville, AR Requests public investigation re safety of facility Forwards policy statement of Arkansans for Safe Energy DERKY, J A Affiliation Unknown 79/04/12 2pp

# J Insurance & indemnity information

- 7905070497 Confirms increased liability limit to \$124,000,000 for pulicies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,185,186,187,188,189,192,193,194,195,197,198,200,201,204,206,207,208,210,212,214,215,&others QUATTROCHHI,J American Nuclear Insurers 79/05/01 1p
- 7909070582 Confirms increase in liability limit to \$36,000,000 for golicles MF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,56,57,59,60,61,64,65,67,68,69,70,71,72,74,76,77,78,79,80,84,87,80,90,71,92,93,94,95 & 96 ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/05/01
- 7903140489 Forwards Amend 8 to Indemnity Agreement 8-65 per 10CFR140 changes re increase in liability insurance from \$140 million to \$160 million effective 790501 Supporting documentation encl SALTMAN. J Antitrust & Indemnity Group 79/05/01 App
- 7905170167 Forwards executed Amend 8 to Indomnity Agreement B-65 TRIMBLE.D C Arkansas Power & Light Co 79/05/10 3pp

## P Operating license stage documents & correspondence

- 7905250076 Forwards Amend 41 to License DPR-51, safety evaluation & notice of issuance & availability REID,R W Operating Reactors Branch 4 79/04/11. 2pp.
- --7905250079 Amend 41 to License DPR-51, revising Tech Specs for steam generator tube surveillance REID.R.W Operating Reactors Branch 4 79/04/11 Opp
- --7905250085 Eafety evaluation supporting Amend 41 to License DPR-51 # Office of Nuclear Reactor Regulation 79/04/11 4pp
- --7905250090 Notice of issuance & availability of Amend 41 to License DPR-51. REID.R.W Operating Reactors Branch 4. 79/04/11 2pp
- 7903100294 Agrees to take requested action to resolve problems associated w/85M plants Necessary adjustments will be made re emergency feedwater sys equipment, procedures & operator training.
  PETTI, A. P. Arkansas Power & Light Co 79/04/26. 2pp
- 7903:302:13 Forwards revised response to Question 1 re proposed Tach Specs for Cycle 4 operation TRIMBLE.D.C Arkansas Power & Light Co 79/04/26 2pp
- 7905070483 Responds to 790425 ltr re safety concerns Proposes upgrading emergency feedwater sys & completing sufficient small break LOCA analyses to develop & implement necessary operator instructions in emergency procedures.

  CAVANAUGH: W Arkansas Power & Light Co 79/05/03. 5pp

- 7905250049 Forwards Amends 42 & 11 to Licenses DPR-51 & NPF-6, respectively safety evaluation & notice of issuance & availability
  8TOLZ.J F Light Hater Reactors Branch 1 REID.R W Operating Reactors Branch 4 79/05/03 2pp
- --7905250055 Amends 42 & 11 to Licenses DPR-51 & NPF-6, respectively, modifying App A & B Tech Specs re mgt organization REID,R W Operating Reactors Branch 4 79/05/03 14pp
- ~~7905250058 Safety evaluation supporting Amends 42 & 11 to Licenses DPR-51 & NPF-6, respectively \* Operating Reactors Branch 4 79/05/03 2pp
- --7903250065 Notice of issuance & availability of Amends 42 & 11 to Licenses DPR-51 & NPF-6, respectively REID,R W Operating Reactors Branch 4 79/05/03 2pp
- 7905150389 Requests presence at 790506 annual review meeting in Little Rock, AR re environ monitoring programs SWINDLE, D.L. Arkansas Power & Light Co. 79/05/08 1p
- 7905110082 Resubmits 790503 ltr w/minor wording changes re timeliness & rallability of emergency feedwater sys & increased margins of safety
  CAVANAUGH.W Arkansas Power & Light Co 79/03/09 5pp
- 7908140279 Supersedes 790809 Itr responding to NRC safety concerns expressed in 790428 status rept Proposed corrective actions design change for emergency feedwater sys & implementation of hard-wired control-grade reactor trip CAVANAUGH.W Arkanses Power & Light Co 79/05/10 Spp
- 7905190053 Provides add1 requested info on safety concerns Supersedes 790510 ltr CAVANAUGH,W Arkensas Power & Light Co 79/05/11 Spp
- 7905230020 Provides addl info re mods being used to provide reactor trip upon loss of main feedwater %/or turbine trip.per 790509 meeting request TRIMBLE, D C Arkansas Power & Light Co 79/05/11 Bpp
- 790522024B Discusses util 790i03 ltr re commitment to perform flow test of long-term small break mod following design change Design mod completed & flow test performed to verify required 70/30 flow split TRIMBLE, D C Arkansas Power & Light Co 79/05/14 ip
- 7905210266 Responds to questions from 790515 util/NRC meeting Describes measures taken to assure that anticipatory scram on turbine trip & loss of main feedwater will be reset during power escalation Discusses applicability of B&W repts TRIMBLE,D C Arkansas Power & Light Co 79/05/16 7pp
- 7905240365 Provides update on progress made in implementing commitments contained in 790511 itr re emergency feedwater pump TRIMBLE, D C Arkansas Power & Light Co 79/05/17 3pp
- 7905240712 Responds to NRC 790515 questions re actuation of anticipatory reactor scram.procedural training & existing emergency feedwater pump capacities.
  TRIMBLE, D C. Arkansas Power & Light Co 79/05/17. 3pp
- 7705270155 Updates 770511 ltr re emergency feedwater sy verification of sys & progress of post-TMI operator 'program TRIMBLE D C Arkenses Power & Light Co 77(03/2)
- 7905300208 Forwards summary of EDS Nuclear, Inc resolution/documentation of elbow flexibility error which existed in versions of PISOL piping analysis computer program from Jan-Oct 1969 Review & reanalysis included all work through Dec 1970. PORTER, F L EDS Nuclear, Inc. 79/03/21 700
- --7905300263 Forwards EDS Nuclear, Inc list of BWRs & piping sys which could have been impacted by deficient computer program QE has no record of reanalysis for Cooper piping sys. STEPHENS, P W General Electric Co , Nuclear Energy Products Div. 79/01/24 18pp
- 790530048B Forwards info requested by NRC at 790227 meeting re results of voltage calculations Info is provided to clarify analysis performed to justify existing configuration re safety buses.
  TRIMBLE D C Arkansas Power & Light Co. 79/05/21 11pp

- 7903300001 Updates 790511 ltr re commitments & comments on 790517 order Test on reactor conducted w/o unusual occurrence Other tests on feedwater conducted w/only two reportable failures TRIMBLE.D C Arkensas Power & Light Co 79/05/22 Spp
- 7905310370 Plans to qualify retainer described in BAH-1496. "BRPA Retainer Dasign Rept." for three cycles of operation Some retainers will be reinserted at facility during next refueling TAYLOR.J N Baboott & Wilcox Co 79/05/23 1p
- O Inspection reports, IE Bulletins & correspondence
- 7905010385 Forwards IE Insp Repts 50-313/79-02 & 50-368/79-02 on 790115-0211 & notice of violation MADSEN, 6 L Region 4. Dallas, Reactor Operations Nuclear Support Branch 79/03/01 2pp
- --7905010391 Natice of violation from insp on 790115-0211
  \* Region 4. Dallas, Office of the Director 79/03/01 ip
- --7905010395 IE Insp Repts 50-313/79-02 & 50-368/79-02 on 790115-0211 Noncompliance noted failure to prepare weekly rept of overdue maint HESTERMAN, T.F. Region 4, Dallas, Reactor Operations Nuclear Support Branch BOYTER, N.C. Region 4, Dallas, Office of the Director MADSEN, G.L. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/03/01 15pp
- 7905150079 Forwards IE Circular 79-04, "Loose Locking Nut on Limitorque Valve Operators "
  SEYRRIT, K V Region 4, Dallas, Office of the Director 79/03/16
- 7905010448 Forwards IE Bulletin 78-128. "Atypical Weld Matl in Reactor Pressure Vessel Walds " BEYFRIT.K V Region 4. Dallas, Office of the Director 79/03/19 1p
- 7905020441 Forwards IE Circular 79-05, "Moisture Leakage in Stranded Hire Conductors"
  SEYFRIT, K V Region 4, Dallas, Office of the Director, 79/03/20 to
- 7905020277 Forwards IE Info Notice 79-06. "Stress Analysis of Safety-Related Piping" SEYFRIT.K V Region 4, Dallas, Office of the Director 79/03/23 In
- 7905020419 Forwards IE Info Notice 79-07. "Rupture of Radwaste Tanke" SEYFRIT.K.V Region 4. Dallas, Office of the Director 79/03/26
- 7705020436 Forwards IE Info Notice 77-DB, "Interconnection of Contaminated Sys of Sys Air Sys Used as the Source of Breathing Air "
  8EYFRITIK V. Region 4: Dallas, Office of the Director, 79/03/28 to
- 7705140152 Forwards IE Bulletin 79-04, "Incorrect Heights for Swing Check Valves Mfg by Velan Engineering Corp " Licensee action required SEYFRIT, K V Region 4, Delias, Office of the Director 79/03/30 ip
- 7705150048 Forwards IE Info Notice 79-07. "Spill of Radioactively Contaminated Resin"
  SEYFRIT.K V. Region 4. Dallas, Office of the Director 77/03/30.
- 7905100394 Forwards response to IE Bulletin 79-05A items 1-4b & 5 re IMI-2 errors Remaining responses will be forwarded on or before 790416 TRIMBLE.D.C Arkenses Fower & Light Co. 79/04/11 12pp
- 7705040488 Forwards IE Bullstin 79-048, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
  SEYFRIT.X.V. Region 4, Dallas, Office of the Director. 79/04/14,
- 7905040606 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."

  SEYFRIT.K.V. Region 4, Delias, Office of the Director 79/04/14
- 7905070043 Forwards IE Bulletin 79-07, "Beismic Stress Analysis of Safety-Related Piping," Licenses action required SEYRIT, K. V Region 4, Dallas, Office of the Director 79/04/14

- 7705030128 Forwards responses to Items 4c-d & 6-12 of IE Bulletin 77-05A.& suppl info to response to Item 5 in 770411 itr re reactor bldg & panetration room cooling TRIMBLE.D C Artanuas Power & Light Co 77/04/16 13pp
- 7905090096 Forwards suppl to IE Bulletin 79-05A, "Nuclear Incident at TMI"
  SEYFRIT, K V. Region 4, Dallas, Office of the Director 79/04/25
- 7905030265 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Bys " Licensee action required SEYFRIT.K V Region 4, Dallas, Office of the Director 79/04/LT in
- 7905080346 Forwards IE Bulletin 79-058, "Nuclear Incident at THI-Buppl"
  SEYFRIT.K V Region 4. Dallas, Office of the Director 79/04/21
- 7905290494 Responds to IE Bulletin 79-07 re seismic stress analysis Computer codes specified in Item 1 not used in analysis of safety-related piping TRIMBLE, D.C. Arkansas Power & Light Co. 79/04/24 App.
- 7905210264 Responds to IE Bulletin 79~05A, "Nuclear Incident at TMI-Buppi" Forwards Tech Spec change to provide for rapid placement in cold shutdown mode following gloss of emergency feedwater equipment.

  GAVAMAUGH: H Arkenses Power & Light Co 79/05/16 400
- R. Periodic operating reports & related correspondence
- 7905070490 Forwards "Semiannual Environ Monitoring Rept" for Jul-Dy: 1978 TRIMBLE,D C. Arkansas Power & Light Co 79/04/30 ip
- ---7905070494 "Semiannual Environ Monitoring Rept" for Jul-Dec 1978
  \* Arkaness Power & Light Co 79/04/30 550pp
- 7905110066 Forwards impingement intaks monitoring data for Mar 1979 TRIMBLE.D.C Arkansas Power & Light Co 79/04/30 20pp
- 7905150460 Forwards Nati Poliution Discharge Elimination Sys rept for first quarter 1979 TRIMBLE-D.C. Arkansas Power & Light Co 79/05/04 10pg
- 7905170254 Forwards monthly operating rept for Apr 1979
  TRINBLE.D.C Arkansas Power & Light Co 79/05/10 ip.
- --7905170259 Monthly operating rept for Apr 1979 SHIVELY,C N Arkansas Power & Light Co 79/05/09 5pp
- S Reportable occurrences, LERs & related correspondence
- 7905070280 Responds to generic sepects of SECY-79-90, which assignid abnormal occurrence status to 780916 event re degraded engineered safety sys. All licenses have been notified of potential problems. DENTON: H R Office of Nuclear Reactor Regulation 79/04/06 4pp
- --7905090293 Concurs in staff request of abnormal occurrence determination for degraded engineered safety sys incident RT Kennedy requested identification of generic implications GHILK:B J Office of the Secretary of the Commission. 79/02/23
- ---7905090286 Requests info by 790313 on generic matters identified in 780916 abnormal occurrence involving degraded engineered safety sys STELLO,V. Division of Operating Reactors, 79/02/27 ip.
- 7905150117 Forwards PNO-79-67R & 79-77(NRR)
  MADBEN.O L. Region 4, Dallas, Reactor Operations Nuclear Support
  Branch 79/04/11 1p
- 7905040106 Forwards PNO-79-678

  MADSEN.O.L Region 4, Dallas, Reactor Operations Nuclear Support
  Branch 79/04/12. 1p
- 7905:50174 Operating Experience Hemo 14. unusual sequence of events reported 7809:19 re degraded voltage resulting from onsite causes. One transformer disconnected causing second to overload w/voltage drop on station distribution sys. STELLO.V. Division of Operating Reactors 79/04/12 App.

# **DOCKETED ITEMS**

- 7905150253 Forwards PNO-79-67T correction
  MADSEN.O L Region 4. Dalias, Reactor Operations Nuclear Support
  Branch 79/04/13 1p
- 7905010529 Forwards PND-79-67U,V & W MADSEN,O L Region 4. Dallas, Office of the Director 79/04/16 in
- 7905010538 Forwards PND-79-47X & Y MADSEN,Q L Region 4. Dailas, Office of the Director 79/04/18
- 7905010554 Forwards PND-79-67Z MADSEN,O C. Region 4. Dallas, Office of the Director 79/04/19 is
- 7905010367 Forwards PNO-79-67AA, AB, AC & AD MADSEN, O L Region 4, Dallas, Office of the Director ` 79/04/24
- 7905030008 Forwards PNO-79-67AE MADSEN.G L Region 4. Dallas, Reactor Operations Nuclear Support Branch 79/04/25 tp
- 7905150096 Forwards PNO-79-67AF.AO.AH.AI & AJ.re nuclear incident at TMI
  MADSEN.O L Region 4. Dallas, Reactor Operations Nuclear Support Branch 79/04/30 ip
- 7905240431 Forwards PNO-79-67AK & AL MADSEN.0 L Region 4. Dallas, Fuel Facility & Materials Safety Branch 79/05/02 1p
- 7905140250 Forwards LER 79-003/017-0
  TRIMBLE, D C Arkansas Power & Light Co 79/05/08 1p
- --7905140263 LER 79-003/01T-0 on 790425 leak discovered in heat affected tone of 1 inch drainline socket weld in B decay heat discharge cross connect to a loop Caused by vibration fatigue Outer drainline isolation valves replaced SHIVELY, C N Arkansas Power & Light Co 79/05/08 4pp
- 7905290103 Forwards LER 79-004/03L-0
  TRIMBLE.D C Arkansas Power & Light Co 79/05/22 2pp
- --7905250109 LER 79-004/03L-0 on 790424 reactor bldg spray pump unresponsive to engineered safeguards signal Caused by incorrect Agastat time relay setting Relay adjusted SHIVELY, CN Artansas Power & Light Co 79/05/22 ip
- DOCKET 50-315 DONALD C COOK NUCLEAR POWER PLANT, UNIT 1
- H General correspondence
- 7905240602 Notification of termination of License BOP-3099 due to resignation of employee, JM Randolph MELBON, D D , SHALLER, D V Indiana & Michigan Power Co 79/09/09
- I Financial information
- 7903040036 Forwards Endorsements 2 & 3 to NELIA Binders E8-45 & 64, Endorsements 31 & 32 to MAELU policy MF-79 & Endorsements 38 & 39 to ANI policy NF-206 DDLAN-JE indiana & Michigan Power Co 79/04/26. 8PP
- J Insurance & indemnity information
- 7905020401 Forwards Endorsements 2 % 3 to NELIA policies EB-45 & EB-64, Endorsements 31 % 32 to MAELU policy MF-79 & Endorsements 38 % 39 to ANI policy NF-206 DOLAN, J E. Indiana & Michigan Power Co 79/04/26 Spp
- 7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,144,151,161,164,170,173,174,178,179,180,182,185,186,187,188,187,192,193,194,195,197,198,200,201,204,204,207,208,210,212,213,215,3 others QUATTROCHHI,J American Nuclear Insurers 79/05/01 ip

- 7905140401 Forwards Amend 9 to Indomnity Agreement 8-61 per 100FR140 changes re increase in liability insurance from \$140 million to \$160 million, effective 790501 Supporting documentation encl
  SALTZMAN, J Antitrust & Indomnity Group 79/05/01 6pp
- 7903290366 Forwards executed Amend 9 to Indemnity Agreement 8-61 DDLAN, J E Indiana & Michigan Power Co 79/05/21 4pp
- 7905310440 Forwards Indemnity fee for Unit 1 for 790526-800525 & fee for Unit 2 for 770818-790817 DOLAN, J E Indiana & Michigan Power Co 79/05/21 3pp
- P Operating license stage documents & correspondence
- 7905020470 Discusses 790919 telcon w/R Berd of Westinghouse re incorrect weights for Valan Model C698 6-inch check valves used in safety injection sys BCHMENCER: A Operating Reactors Branch 1 79/04/02 1p
- 7905040611 Forwards operating history info re pressurizer power operated relief valves in response to 790427 request BHALLER.D V Indiana & Michigan Power Co 79/04/27 Rpp
- 7905240100 Ack receipt of 790327 application proposing App A & B Tech Spec changes Application requires two Class III fees & two Class I fees Requests addl fee HILLER.W D License Fee Management Branch 79/04/27 1p
- 7905i10i83 Advises of removal of Foxboro transmitters on pressurizer pressure & steam generator steam flow applications, as identified in 780601 ltr. Transmitters will be replaced during current refueing outage, no later than Oct-Nov 1979 MALONEY, 0 P Indiana & Michigan Power Co 79/05/04 3pp
- 7905230504 Describes correspondence w/NRC re application for expansion of spent fuel storage capacity to 2.050 fuel assemblies Requests addithe retechnical review of related public health & safety matters REIZEN, M 8 Kichigan, State of 79/05/14 ip
- 7905290149 Forwards &4.400 addl fee for 790327 proposed Tech Spec changes DOLAN,J E Indiana & Hichigan Power Co 79/05/21 2pp
- G. Inspection reports, IE Bulletins & correspondence
- 7905020202 Forwards IE Insp Repts 50-319/79-02 & 50-316/79-02 on 790102-05,08-11,15-19,22-26,29-31 & 0201-02, & notice of violation Portions withheld (ref 10CFR2 790) HEISHMAN,R F. Region 3. Chicago, Reactor Operations Nuclear Support Branch 79/03/02 3pp.
- --7905020205 Notice of violation from insp on 790102-05,8-il,15-i9,22-26 29-31 & 0201-02 \* Region 3. Chicago, Office of the Director 79/02/21, ip.
- --7905020208 IE Insp Repts 50-315/79-02 & 50-316/79-02 on 790102-05, 08-11:15-19:22-26:29-31 & 0201-02. Noncompliance noted. failure to rept safety injection event & failure to sample at specified interval 2AKER.K.R. WARNICK.R.F. Region 3. Chicago, Office of the Director. 79/02/21 iipp
- 7905010233 Forwards IE Info Notice 79-04, "Stress Analysis of Safety-Related Piping" KEPPLER, J. O Region 3, Chicago, Office of the Director 79/03/23
- 7905040037 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks " KEPPLER, J. G. Ragion 3, Chicago, Office of the Director 79/03/26 io.
- 7905010171 Forwards IE Info Notice 79-08, "Interconnection of Conteminated Bys w/Svc Air Bys Used as Source of Breathing Air." KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/03/28, is.
- 7905130817 Forwards IE Insp Repts 50-315/79-03 & 50-316/79-03 on 790313-16 & notice of violation DAVIS.A B. Region 3. Chicago, Fuel Facility & Materials Bafety Branch 79/03/28. 2pp.
- ---7905150819 Notice of violation from inep on 790313-16
  \* Region 3, Chicago, Office of the Director 79/03/27. ip.

- --7905150920 IE Insp Repts 50-315/79-03 & 50-316/79-03 on 790313-16 Noncompliance noted failure to conduct required emergency plan drill GREER: R J NRC Regional Offices EBSIG.T H Region 3, Chicago, Office of the Director 79/03/27 App
- 7905010404 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin "
  KEPPLER, J G Region 3. Chicago, Office of the Director 79/03/30
- 7905030006 Forwards IE Bulletin 79-06, "Review of Operational Errors & Bys Misalignments Identified During THI Incident " Licenses action reguired KEPPLER.J O Region 3, Chicago. Office of the Director 79/04/11
- 7905010392 Forwards 1E Bulletin 79-06A, "Review of Operational Errors & Bys Misalignments Identified during TMI Incident " Licansee action required KEPPLER.J O Region 3, Chicago, Office of the Director 79/04/14
- 7909040456 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Bafety-Related Piping " Licensee action required KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14
- 7909040522 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During THI Incident " KEPPLER.J O Region 3. Chicago. Office of the Director 79/04/14
- 7905170089 Forwards IE Bulletin 79-06B. "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "
  KEPPLER.J G Region 3. Chicago, Office of the Director 79/04/14
- 7905030204 Forwards IE Bulletin 79-09, "Failures or GE Type AK-2 Circuit Broaker in Safaty-Related Sys " Licensee action KEPPLER J G Region 3. Chicago, Office of the Director 79/04/17
- 7905080499 Forwards 1E Bulletin 79-058, "Nuclear Incident at KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/21
- 7909300384 Responds to IE Bulletin 79-07, "Seismic Stress Analysis of Bafesty-Related Piping "Forwards description of computer program used in design of safety-related piping DDLAN-J E American Electric Power Co . Inc 79/04/24 Spp
- 7905150152 Ack receipt of 790329 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-315/79-02 & 50-316/79-02 HEIGHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Region 3. Chicago, Reactor Operations Nuclear 79/04/25 ip 79/04/25 Support Branch
- ---7905150156 Responds to NRC 770302 ltr re violations noted in IE Insp Repts 50-315/79-02 \$ 50-316/79-02 Corrective actions withheld (ref 10CFR2 770) DISBROW, R E Indiana & Michigan Power Co 79/04/25 ip
- 7905150345 Forwards responses to IE Bulletin 79-06A.Revision 1. Discusses major differences between Hestinghouse & BAN designs DOLAN, J E Indiana & Michigan Power Co 79/05/01 25pp
- 7905250371 Addi response to IE Bulletin 79-07 Twenty-three piping
- PDS2003/1 Acom response to it outset 77-0, being chief in technique proved capable of withstanding seismic event. Remaining piping sys also groved capable.

  BIEN, F. N. Indiana & Hichigan Power Co. 79/05/04. 4pp
- 7908310466 Responds to 790805 ltr requesting extension of time to respond to IE Bulletins 78-12,78-12e & 78-128 Request denied KEPPLER, J C. Region 3, Chicago, Office of the Director. 79/05/04
- ---7705310469 Requests time extension to respond to IE Bulletine 78-12. 78-128 bollan, J. E. Indiana & Michigan Power Co. 79/05/05 2pp
- R. Periodic operating reports & related correspondence
- 7905070428 Forwards "Annual Environ Op≠rating Rept 1978 " BOLAN, J E. Indiana & Michigan Power Co 79/04/16 2p

- ---7905070437 "Annual Environ Operating Rept 1978" \* Indiana & Michigan Power Co 79/04/16 So
- 7905250352 Forwards revised page 15 to 1978 Annual Radiological Environmentoring Rept. transmitted 790328 Ltr from contractor encl SHALLER, D.V. Indiana & Michigan Power Co. 79/04/26. 3pp
- 790517024B Forwards monthly operating rapt for Apr 1979 8HALLER, D. V. Indiana & Michigan Power Co. 79/05/11
- --7905170252 Monthly operating rept for Apr 1979
  GILLETT,W T Indiana & Michigan Power Co 79/05/03 7pp
- 8 Reportable occurrences, LERs & related correspondence
- 7905070598 Forwards LERs 79-026/03L-0 & 79-025/03L-0 8HALLER, D V Indiana & Michigan Power Co 79/05/ 79/05/02 1c
- ---7905070604 LER 79-026/03L-0 on 790406 during normal operation, 89/4),
  offsite ac electrical supply became inoperable Caused by
  high winds during severe windstorm Damaged jumpar replaced
  & sys returned to operable status
  CHADWELL, H M Indiana & Michigan Power Co 79/05/02 200
- --7903070613 LER 79-025/03L-0 on 790416 time response data not collect; during Apr 1976 refueling outage for low steam pressure engineered safety feature channel Gaused by inadvertant procedural omission Checklist will be used in future BEILMAN, T.P. Indiana & Michigan Power Co 79/05/02 lp
- 7905110120 Forwards LER 79-010/03X-1 SHALLER, D.V. Indiana & Michigan Power Co. 79/05/07
- ---7905110124 LER 79-010/03X-1 on 790223 diesel essential svc witer cir-valves i--ESH-111 & i-ESH-114 not functioning properly Caused by excessive wear at split disc hinge points Discs replaced BROWNIM B Indiana & Michigan Power Co 79/03/07. Ip
- 7905150423 Forwards LERs 79-019/03L-0,79-027/03L-0 & 79-028/03L-0 BHALLER, D V Endiana & Michigan Power Co 79/05/09 1p
- --7903150430 LER 79-019/03L-0 on 790413 while performing hydraulic snubber surveillance insp. snubbers OBD-8573 & OBD-8574 found w/drained reserviors Caused by loose pipe unions between snubbers & remote reservoirs Snubbers replaced BROWN, M 8 Indiana & Michigan Power Co 79/05/09 ip
- ---790513043B LER 79-027/03L-0 on 790416 during refueling w/estigints deisal generator AB inoperable,600 volt bus 11D made inoperable by removal of normal feed breaker Tiil2 for cleaning Caused by personnel error Operators reinstructed LEASE,R S Indiana & Michigan Power Co 79/05/09 (p
- --7905i5044i LER 79-028/O3L-0 on 7904iO torque required to open lower. condensor inlet door 3-R exceeded Tach Specs Caused by sheet metal screws loose at bottom of door Door frame edgs BEILMAN, T.P. Indiana & Michigan Power Co 79/08/09 2pp
- 7905210135 Forwards LER 79-029/03L-0 SHALLER, D V Indiana & Michigan Power Co. 79/05/14 1p
- --7905210142 LER 79-029/03L-0 on 790414 cracks discovered in divider barrier seal Caused by excessive compression of seal math by steel plates Work in progress to replace cracked sections HIINER, D O Indiana & Michigan Power Co. 79/05/14 ip
- 7905220320 Forwards LERs 79-030/03L-0,79-031/03L-0 & 79-032/03L-0 SHALLER,D V Indiana & Michigan Power Co 79/05/16 ip
- ---7905220326 LER 79-D30/O3L-O on 790417 while performing routine surveillance test on AB diesel generator, load conservation circultry did not fully function as design Gause under investigation BEILMAN:T P Indiana & Michigan Power Go 79/O5/16 ip
- --7905220333 LER 79-031/03L-0 on 790419 during routine channel calibritistable trip value discovered nonconservative w/respect to Tech Spec limits Caused by excess drift, Histable will be repaired

  BEILMAN, T P. Indiana & Michigan Power Co 79/05/16. 19
- --7908220339 LER 79-032/03L-0 on 790416 during routine channel taller bistable FB-510B trip point was nonconservative w/respect to Tech Spec limit Caused by excess drift Bistable recallibr BEILMAN.T P Indiana & Michigan Power Co 79/05/16. 1p.

- DOCKET 50-316 DONALD C COOK NUCLEAR POWER PLANT, UNIT 2 H General correspondence
- 7905240602 Notification of termination of License 80P-3099 due to
- resignation of employee, JM Randolph NELBON, D D , SHALLER, D V Indiana & Michigan Power Co 79/05/09
- I Financial information
- 7905040056 Forwards Endorsements 2 & 3 to NELIA Binders EB-45 & 64. Endorsements 31 & 32 to MAELU policy MF-79 & Endorsements 38 & 39 to ANI policy NF-206 DDLAN.J E Indiana & Michigan Power Co 79/04/26 BPP
- J Insurance & indemnity information
- 7903020401 Forwards Endorsements 2 % 3 to NELIA policies EB-45 % EB-64, Endorsements 31 % 32 to MAELU policy MF-79 % Endorsements 38 % 39 to ANI policy NF-206 DDLAN,J E Indiama & Michigan Power Co 79/04/26 8pp
- 7908070497 Confirms increased liability limit to \$124,000.000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,176,179,189,182,183,186,187,188,189,192,193,194,195,197,198,200,201,204,204,207,208,210,212,214,215,5 there GUATTROCHHI, J American Nuclear Insurers 79/05/01 1p
- 7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22,26,29,38,39,44,46,47,49,50,51,52,83,54,53,56,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87, 88, 90, 91, 92, 93, 94, 95 & 98 ROBERTS: D M Mutual Atomic Energy Liability Underwriters 79/05/01
- 7905140481 Forwards Amend 9 to Indemnity Agreement B-61 per iOCFR140 changes re increase in liability insurance from \$140 million to \$160 million.effective 790801 Supporting documentation SALTZMAN.J Antitrust & Indemnity Group 79/05/01 App
- 7905290366 Forwards executed Amend 9 to Indemnity Agraement B-61 BDLAN, J E Indiana & Michigan Power Co 79/05/21 4pp
- 7905310440 Forwards indemnity fee for Unit 1 for 790526-BDQ525 & fee for Unit 2 for 770818-790817 DOLAN, J E Indiana & Michigan Power Co 79/05/21 3pp
- P Operating license stage documents & correspondence
- 7703020490 Discusses 770315 telcon w/R Sero of Westinghouse re incorrect weights for Velan Model C658 6-inch check valves used in safety injection sys BCHMENCER, A Operating Reactors Branch i 77/04/02 ip
- 7905040611 Forwards operating history info re pressurizer power operated relief valves in response to 790427 request SHALLER.D V Indiana & Michigan Power Co 79/04/27 2pp
- 7905240100 Ack receipt of 790327 application proposing App A & B Tech Spec changes Application requires two Class III fees & two Class I fees Requests addit for MILLERAND License Fee Management Branch 79/04/27 ip
- 7905110183 Advises of removal of Foxboro transmitters on pressurizer pressure & steam generator steam flow applications, as identified in 780601 itr Transmitters will be replaced during current refueling outage, no later than Oct-Nov 1979 MALONEY, OP Indiana & Michigan Power Co ' 79/05/04
- 7905230504 Describes correspondence w/NRC re application for expansion of spent fuel storage capacity to 2,050 fuel assemblies. Requests addl info re technical review of related public health & safety matters.

  REIZEN.M 8 Michigan, State of 79/05/14 ip.
- 7905290149 Forwards &4,400 addl fee for 790327 proposed Tech Spec DOLAN, J E Indiana & Michigan Power Co 79/05/21 2pp
- 7905310367 Notifies of leaks discovered 790520 in main feedwater lines to steam generators 1 % 4. Caused by stress concentration due to type of weld & preparation of feedwater line Will completely replace affected pipe section SHALLER, D. V Indiana & Michigan Power Co 79/05/26 2pp
- Q, Inspection reports: IE Bulletins & correspondence
- 7905020202 Forwards IE Insp Repts 50-315/79-02 & 50-316/79-02 on 790102-05,08-11,15-19,22-26,29-31 & 0201-02, & notice of violation Portions withheld (ref 10CFR2.790). HEISHMAN,R,F Region 3, Chicago, Reactor Operations Nuclear Support Branch. 79/03/02, 3pp.

- --7909020208 Notice of violation from insp on 790102-05,8-11,15-19,22-26, 29-31 & 0201-02 \* Region 3, Chicago, Office of the Director 79/02/21 1p
- --7905020208 IE Insp Repts 30-315/79-02 & 50-316/79-02 on 790102-05, OB-11, 15-19, 22-26, 29-31 & 0201-02 Noncompliance noted failure to rept safety injection event & failure to sample at specified interval ac specified interval BAKER, K.R., WARNICK, R.F. Director 79/02/21 11; Region 3, Chicago, Office of the
- 7905010233 Forwards IR Info Notice 79-06, "Stress Analysis of Bafety-Related Piping" KEPPLER.J G Region 3. Chicago, Office of the Director 79/03/23
- 7905040037 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks"
  KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/26 10
- 7905010171 Forwards IR Info Notice 79-08, "Interconnection of Contaminated Sys w/Syc Air Sys Used as Source of Breathing Air " Contaminate Air " KEPPLER, J G Region 3, Chicago, Office of the Director 79/03/28 10
- 7905150817 Forwards IC Insp Repts 50-318/79-03 & 50-316/79-03 on 790313-16 & motice of violation DAVIE, A B Region 3, Chicago, Fuel Facility & Materials Bafety Branch 79/03/28 2pp
- ---7905150819 Notice of violation from insp on 790313-16 \* Region 3, Chicago, Office of the Director 79. 79/03/27 1p
- --7905150820 IE Insp Repts 50-315/79-03 & 50-316/79-03 on 790313-16 Noncompliance noted failure to conduct required emergency plan drill GREER:R J NRC Regional Offices. ESBIG.T H Region 3. Chicago. Office of the Director 79/03/27 6pp
- 7905010404 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
  KEPPLER, J G Region 3, Chicago, Office of the Director 79/03/30
- 7905030006 Forwards IC Bulletin 79-06, "Review of Operational Errors 5 Bys Misalignments Identified During TMI Incident " Licenses action required KEPPLER.J Q Region 3. Chicago. Office of the Director 79/04/11
- 7905010592 Forwards IE Bulletin 79-04A. "Review of Operational Errors & Sys Misalignments Identified during TMI Incident " Licensee action required KEPPLER.J Q Region G, Chicago, Office of the Director 79/04/14
- 7905040456 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required KEPPLER. J 0 Region 3. Chicago, Office of the Director 79/04/14
- 7905040822 Forwards IE Bullstin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident " KEPPLER.J G Region 3, Chicago, Office of the Director 79/04/14
- 7905170089 Forwards IE Bulletin 79-068. "Review of Operational Errors & Sys Misalignments Identified During TMI Incident" KEPPLER.J G Region 3. Chicago: Office of the Director 79/04/14
- 7905030204 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Bys." Licensee action required. KEPPLER.J O Region 3. Chicago: Office of the Director. 79/04/17.
- 7905080499 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Busal KEPPLER J. C. Region 3. Chicago, Office of the Director. 79/04/21
- 7903300386 Responds to IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping," Forwards description of computer program used in design of safety-related piping.
  BOLAN-J.E American Electric Power Co , Inc 79/04/24 Bpp.

- 7905150152 Ack receipt of 790329 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-315/79-02 & 50-316/79-02
  HEISHMAN,R F Region 3. Chicago, Reactor Operations Nuclear Support Branch 79/04/25
  - Bupport Branch 79/04/25 1p
- --7905150456 Responds to NRC 790302 ltr re violations noted in IE Insp Repts 50-315/79-02 & 50-316/79-02 Corrective actions withheld (ref 100FR2 790) DIGBROW R E Indiana & Hichigan Power Co 79/04/25 lp
- 7905150345 Forwards responses to IE Bulletin 79-06A Revision 1 Discusses major differences between Hestinghouse & 8&H designs DDLANJ E Indiana & Michigan Power Co. 79/05/01 25pp
- 790525037; Add1 response to IE Bullstin 79-07 Twenty-three piping lines analyzed using absolute summation technique proved capable of withstanding seismic event Remaining piping systles proved capable
  BIEN.F N Indiana & Michigan Power Co 79/05/04 App
- 7909310466 Responds to 790505 ltr requesting extension of time to respond to IE Bulletins 78-12.78-12a & 78-12B Request denied.

  KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/04
- ---7903310469 Requests time extension to respond to IE Bulletins 78-12, 78-124 & 78-128 DOLAN, J E Indiana & Michigan Power Co 79/05/05 2pp
- R Periodic operating reports & related torrespondence
- 7905070420 Forwards "Annual Environ Operating Rept 1978"
  DOLAN, J E. Indiana & Michigan Power Co 79/04/16 2pp
- ---7905070437 "Annual Environ Operating Rept 1978 "
  \* Indiana & Michigan Power Co 79/04/16 Scopp
- 7905250332 Forwards revised page 15 to 1978 Annual Radiological Environ Monitoring Rept. transmitted 790328 Ltr from contractor encl SHALLER, D. V. Indiana & Michigan Power Co. 79/04/26 3pp
- 7903170261 Forwards monthly operating rept for Apr 1979 BHALLER, D. V. Indiana & Michigan Power Co. 79/05/11 1p
- --7905170262 Monthly operating rept for Apr 1979
  OILLEYT H T Indiana & Michigan Power Co 79/05/03 12pp
- B Reportable occurrences, LERs & related correspondence
- 7905040001 Forwards LER 79-012/03L-0 SHALLER, D V Indiana & Hichigan Power Co 79/04/27 1p
- --7905040002 LER 79-012/03L-O on 790330 hydraulic control values did not return to normal position placing hydraulic lock on operator cylinder Caused by dirt in hydraulic pilot valve. Hydraulic fluid replaced BROWN, M B Indiana & Michigan Power Co 79/04/27. 19
- 7908070583 Forwards LERs 79-013/03L-0 & 79-014/03L-0
  BHALLER, D V Indiana & Michigan Power Co 79/05/02 1p
- ~~7903070390 LER 79~013/03L-0 on 790407 during rapid shutdown, pressure was allowed to drop to 2,190 lb psig. Caused by spray valve which was slow to respond Spray placed in manual & throttled back MURRHY, C E Indiana & Michigan Power Co 79/05/02. 2pp
- ---7905070596 LER 79-014/03L-0 on 790404 on two occasions rod position indication accessed 12-step limit, Gaused by drifting of signal conditioning modules, which were adjusted for proper output RIBCHLIND, J. L. Indiana & Michigan Power Co. 79/05/27. 2pp
- 7905150488 Forwards LERs 79-015/03L-0 & 79-016/03L-0 SHALLER, D. V. Indiana & Hichigan Power Co. 79/05/09. 1p
- --7905150493 LER 79-015/03L-0 on 790409: during plant startup, small crack & pinhole leak found in body of FMO-232, at inlet side of valve adjacent to weld. Cause of crack not determined. Radiographs of area reviewed WIZNER, D.O. Indiane & Michigan Power Co. 79/05/09. ip

- ---7905190301 LER 79-016/03L-0 on 790412 failure of interlock, which prevents opening both containment 650 ft level airlock doors Caused by slack in actuator cables & weak spring One cable & spring replaced HIZNER D O Indiana & Michigan Power Co 79/09/09 ip
- 7905230325 Forwards LER 79-017/03L-0 SHALLER, D. V. Indiana & Hichigan Power Co. 79/05/16 ip
- --7905230330 LER 79-017/03L-0 on 770423 while performing STP 022, assential svc water-142, essential svc valve to 2 CD diesel did not seat properly Caused by excessive wear of split disc hinge points Stainless steel discs were substituted BROWN, M 8 Indiana & Michigan Power Co 79/05/16 ip
- DOCKET 50-317 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1
- J Insurance & indemnity information
- 7905070497 Confirms increased liability limit to \$124.000.000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 182, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others QUATTROCHHLJ American Nuclear Insurers 79/05/01 ip
- 7905070582 Confirms increase in liability limit to #36,000,000 for golicies MF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,55,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,07,88,90,71,92,93,94,95 & 96 ROBERTS,D M Mutual Atomic Energy Liability Underwriters 79/05/21
- 7903140499 Forwards Amond 8 to Indomnity Agreement B-70 per 10CfR(4) changes, re increase in liability insurance from \$140 million to \$160 million, effective 790301 Supporting documentation encl
  SALTZMAN, J Antitrust & Indomnity Oroup 79/05/01 App
- 7905160325 Submits executed copy of Indomnity Agreement B-70, Aseni 8 presponse to 790501 request SHOEMAKER, C.L. Daltimore Gas & Electric Co. 79/05/09 3pp
- P Operating license stage documents & correspondence
- 7705080123 Forwards request for addl info re Cycle 4 reload. In response to submittal REID.R W. Operating Resctors Branch 4 77/04/13 Spp.
- 7903250002 Forwards Amends 38 & 21 to Licenses DPR-59 & DPR-69, respectively, safety evaluation & notice of issuance & availability REID, R W Operating Reactors Branch 4 79/09/24 4pp
- ---7905280003 Amends 38 & 21 to Licenses DPR-53 & DPR-69, respectively limiting mex boron concentration in safety injection & refueling water tanks & allowing reduced shutdown cooling flow when coolant sys is partially drained.

  REID.R.W Operating Reactors Branch 4 79/04/24 64pp
- --7905250005 Safety evaluation supporting Amends 38 & 21 to Licensin BPR-53 & DPR-67, respectively # Office of Nuclear Reactor Regulation. 79/04/24 6pp
- --7905250007 Notice of issuance & availability of Amends 38 5 21 to Licenses DPR-53 & DPR-69, respectively REID.R W Operating Reactors Branch 4. 79/04/24 3pp
- 7705090049 Forwards proprietary & nonproprietary versions of response to Cycle 4 reload questions Proprietary version available in Central Files.

  LUNDVALL, A.E. Baltimore Cas & Electric Co. 79/05/07 5pp
- --7705090035 "Response to NRG Questions on Calvert Cliffs Unit 1.Cyrlet Reload Bubmittal.App 1-NP." 790425.nonproprietary version # Combustion Engineering. Inc. CEN 107-(B)-NP. 79/04/26 23;
- 7705220282 Submits nonroutine radiological environ operating rept on dyster samples, per ETS App B requirements.

  STOUT, J W Baltimore Gas & Electric Co. 79/05/17 2pp.
- 7903300208 Forwards summary of EDS Nuclear, Inc resolution/documentation of sibow flexibility error which existed in versions of PIBOL piping analysis computer program from Jan-Oct 1969. Review & reanalysis included all work through Dec 1970. PDRTER, F L. EDS Nuclear, Inc 79/05/21 9pp.

- ---7909300263 Forwards EDS Nuclear, Inc list of BWRs & piping sys which could have been impacted by deficient computer program OE has no record of reanalysis for Cooper piping sys BTEPHENS, P W General Electric Co , Nuclear Energy Products Div 79/01/24. 18pp
- O Inspection reports. IE Bulletins & correspondence
- 7905140208 Forwards IE Insp Rept 90-317/76-03 on 760315-19
  No noncompliance noted
  BRUNNER,E J Region i, Philadelphia, Office of the Director
  76/04/07 200
- --7903140210 IE Insp Rept 50-317/76-03 on 790315-19 No noncompliance noted Major areas inspected minutes, facility change request & operating & event logs KELLQOG,P J. DAVIS,A B Region 1, Philadelphia, Office of the Director. 76/04/07 2pp.
- 7905010101 Forwards IE Info Notice 79-06, "Stress Analysis of Bafety-Related Piping" GRIER: DH Region 1, Philadelphia, Office of the Director 79/03/23 1p
- 7905030270 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tenks " QRIER, B. H Region 1, Philadelphia, Office of the Director 79/03/26 1p
- 7905010036 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Bys w/Bvc Air Bys Used as Source of Breathing Air " ORIER, B H Region 1, Philadelphia, Office of the Director 79/03/28 ip
- 7903010286 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin" GRIER, B H Region 1, Philadelphia, Office of the Director 79/03/30 ip
- 7905020030 Forwards IE Bulletin 79-06, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident." Licensee action required GRIER, B M Region 1, Philadelphia, Office of the Director 79/04/11 1p
- 7905150372 Notifies that in-pool fuel insp will be performed between 790430-0802 Bits visit can be handled under "Escorted Access to Controlled Area" requirements REID.R.H Operating Reactors Branch 4 79/04/13 2pp
- 7905070389 Forwards IE Bulletin 79-07, "Ssismic Stress Analysis of Bafety-Related Piping " Licensee action required ORIER: BH. Region 1, Philadelphia, Office of the Director 79/04/14, 1p.
- 7903030328 Forwards IE Bulletin 79-068, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident " Licenses action required ORIER, 8. H Region 1, Philadelphia, Office of the Director 79/04/14, ip
- 7903040174 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Mater Power Reactors Identified During TMI Incident " GRIER.B.H. Region 1, Philadelphia, Office of the Director. 79/04/14 ip
- 7705030056 Forwards IE Builetin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required GRIER, B. H Region 1, Philadelphia, Office of the Director 79/04/17 ip
- 7905010633 Forwards IE Bulletin 79-06A.Revision i, "Reviaw of Operational Errors & Bys Misalignments Identified During TMI Incident " GRIER, 9 H. Region i, Philadelphia, Office of the Director 79/04/18, 1p.
- 7908290712 Responds to IE Bullstin 79-06B re changes in operating procedures, preventative measures & briefing of personnel since TMI, Addl info re RGB will be completed by 790430 LUNDVALL, A E. Baltimore Oas & Electric Co. 79/04/26. 11pp.
- 7905300742 Responds to IE Bullstin 79-04. "Incorrect Weights for Swing Check Valves Hfg by Velan Engineering Corp." Should enelysis indicate piping or support overstress supports will be modified to accommodate icressed valve weights.

  LUNDVALL, A. E. Baltimore Gas & Electric Co. 79/04/30 5pp.

- R Periodic operating reports & related correspondence
- 7905230354 Forwards monthly operating rept for Agr 1979 MERSON:8 D Baltimore Gas & Electric Co 79/05/15 ip
- --7905230358 Honthly operating rept for Apr 1979
  MERSON, 8 D Baltimore Gas & Electric Co 79/05/15 16pp
- 8 Reportable occurrences, LERs & related correspondence
- 7905100348 R0-50-317/75/58 on 751203 condensate storage tank supply valve to auxiliary feedwater pumps found shut cutting off water supply Caused by valve mispositioning Valve opened RUSSELL, L B Baltimore Oas & Electric Co 75/12/05 2pp
- 7905110118 Forwards Abnormal Occurrence 50-317/75/58 on 751203 LUNDVALL, A E Baltimore Cas & Electric Co 75/12/16 ip
- ---7905110122 AD-50-317/75/5B on 751203 discovered condensate storage tank supply valve to auxiliary feedwater pumps shut, leaving pumps w/o water supply Caused by administrative error Valve opened Licked valve deviation form will be used RUSSELLL B Baltimore Gas & Electric Co 75/12/16 3pp
- 7905010524 Forwards LER 79-011/03L-0 RUSSELL,L B Baltimore Qas & Electric Co 79/04/26 ip
- --7905010528 LER 79-011/03L-0 on 790411 during surveillance testing, auxiliary high pressure safety injection header isolation valve (81-656) required 29-s to open Operating instructions revised to maintain 81-656 in open modes 1,2 & 3 GARROLL.J T Baltimore Gas & Electric Co 79/04/26 2pp
- 7905080555 Forwards LER 79-013/03L-0 RUSSELL, L B Baltimore Gas & Electric Co 79/05/02 ip
- ---790508056: LER 79-013/03L-0 on 790417 while performing routine surveillance test discovered hydrogen analyzer was inoperable Caused by failure of internal power supply transformer Transformer & two associated capacitors replaced CANOVA.M A , DAVIB.B M Baltimore Qas & Electric Co 79/05/02
- 7905190080 Forwards LER 79-014/01T-0 RUSSELL,L, B Baltimore Oas & Electric Co 79/05/14 1p
- 7903290426 Forwards LER 79-016/03L-0 RUSBELL,L,B Baltimore Qas & Electric Co 79/05/19 ip
- --7905290430 LER 79-016/03L-0 on 790421 one of sight main steam safety valves tested found out of tolerance in conservative direction Gaused by difference in ambient conditions between time when valve last reset & time of test CARROLL.J T., MIERNICKI.J Baltimore Gas & Electric C Rpp.

- 7909160925 Submits executed copy of Indemnity Agreement B-70. Amend 8 in response to 790501 request. 8HDEMAKER.C L Baltimore Oas & Electric Co 79/09/09 3pp
- P Operating license stage documents & correspondence
- 7905080123 Forwards request for add1 info TS Cycle 4 reload in response to submittal REID.R W Operating Reactors Branch 4 79/04/13 5pp
- 7905250002 Forwards Amends OB & 21 to Licenses DPR-53 & DPR-69, respectively, safety evaluation & notice of issuance & availability
  REIO.R W Operating Reactors Branch 4 79/04/24 4pp
- ---7905250003 Amends 38 & 21 to Licenses DPR-53 & DPR-69, respectively, limiting max boron concentration in safety injection & refueling water tanks & allowing reduced shutdown cooling flow when coolant sys is partially drained REID.R W Operating Reactors Branch 4 79/04/24 64pp
- --7905250009 Safety evaluation supporting Amends 38 & 21 to Licenses DPR-53 & DPR-69, respectively + Office of Nuclear Reactor Regulation 79/04/24 App
- --7905250007 Notice of issuance & availability of Amends 38 & 21 to Licenses DPR-53 & DPR-69, respectively REID.R W Operating Reactors Branch 4 79/04/24 3pp
- 7903220202 Submits nonroutine radiological environ operating rept on oyster samples.per ETS App B requirements gTOUT.J W Baltimore Gas & Electric Cb 79/05/17 2pp
- 7905300208 Forwards summary of EDS Nuclear, Inc resplution/documentation of elbow flaxibility error which existed in versions of PISOL piping analysis computer program from Jan-Oct 1969 Review & reanalysis included all work through Dec 1970 PORTER, F L EDS Nuclear, Inc 79/05/21 9pp
- ---7905300263 Forwards EDB Nuclear, Inc list of BHRs & piping sys which could have been impacted by deficient computer program OE has no record of reanalysis for Cooper piping sys STEPHEMB,P W General Electric Co , Nuclear Energy Products Div 79/01/24 Spp
- O Inspection reports, IE Builetins & correspondence
- 7905010101 Forwards IE Info Notice 79-06, "Stress Analysis of Bafety-Related Piping" ORIER.B H Region 1, Philadelphia, Office of the Director 79/03/23 1p
- 7903030270 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks " QRIER, B H Region i, Philadelphia, Office of the Director 79/03/24 is
- 7905010036 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Syc Air Sys Used as Source of Dreathing Air "
  ORIER.B H Region 1. Philadelphia, Office of the Director 79/03/28 1p
- 7908010286 Forwards IE Info Notice 79-09. "Spill of Radioactively Contaminates Resin." GRIER.B M. Region 1. Philadelphia. Office of the Director 79/03/30 ip
- 7903020030 Forwards IE Bulletin 79-06, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident " Licenses action required GRIER.B. H Region i. Philadelphia. Office of the Director 79/04/11 ip
- 7905020389 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping " Licensee action required ORIER.B.H Region 1, Philadelphia, Office of the Director 79/04/14 ip
- 7905030328 Forwards IE Bullstin 79-068, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident," Licenses action required ORIER, B.H. Region 1: Philadelphia, Office of the Director 79/04/14. 1p.
- 7903040174 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident." GRIER, B. H. Region 1. Philadelphia, Office of the Director 79/04/14 1p

- 7903030056 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " Licensee action required GRIER, B H Region 1. Philadelphia, Office of the Director 79704/17 1p
- 7905010633 Forwards IE Bullstin 79-06A.Revision 1, "Review of Operational Errors & Sys Misalignments Identified During THI Incident" GRIER, BH Region 1. Philadelphia, Office of the Director 79/04/18 1p
- 7905290712 Responds to IE Bulletin 79-068 re changes in operating procedures preventative measures & briefing of personnel since TMI Addl info re RCS will be completed by 790430 LUNDVALL,A E Baltimore Cas & Electric Co. 79/04/26 11pp
- 7905300742 Responds to IE Bulletin 79-04, "Incorrect Hoights for Swing Check Valves Mfg by Velan Engineering Corp " Should analysis indicate piping or support overstress supports will be modified to accomposate icreased valve weights
  LUNDVALL, A E Baltimore Cas & Electric Co 79/04/30 Spp
- R Periodic operating reports & related correspondence
- 7905230356 Forwards monthly operating rept for Apr 1979 MERSON, 8 D Baltimore Gas & Electric Co 79/05/15 ip
- --7903230358 Monthly operating rept for Apr 1979
  MERSON, S D Baltimore Gas & Electric Co 79/08/15 16pp
- 8 Reportable occurrences, LERs & related correspondence
- 7405080494 Forwards LER 79-002/03L-0 RUSSELL.L B Baltimore Gas & Electric Co 79/05/02 ip
- 7905090342 LER 79-002/03L-0 on 79040B fused circuit within power typel (N PRODAC 250.PT16) for plant process computer failed. Gaused by internal high current drain Function was restored using lab power supply units

  DAVIS,8 M Baltimore Gas & Electric Co 79/05/02 ip
- DOCKET 50-320 THREE MILE ISLAND NUCLEAR STATION: UNIT 2

  A Application/construction stage documents & correspondence
- 7905300325 Forwards preliminary review of Section 6 2 of FSAR Section not adequately complete to allow initiation of detailed technical review HENDRIE,J M. Atomic Energy Commission (Pre. 1975), 74/02/28, 255
- 7905110374 Forwards milestone & activity list for TMI, status dtd 740814,for period ending 740907 Explains extension of fuel load date & const schadule GUNN.H.T OPU Service Corp 74/09/06 App
- 7905110337 Forwards list of differences identified from review of legi-& activity descriptions between Feb & Mar 1975 issues of "Yellow Book" GUNNUT GPU Service Corp. 75/04/07 4pp
- 7905110370 Forwards milestone & activity list for TMI, status dtd 750400, for pariod ending 750307 GUNN, N T QPU Bervice Corp 75/05/05 4pp
- 7908110367 Forwards milestone & activity list for TMI, status dtd 750930,for period ending 751007 QUNN.N T OPU Service Corp 75/10/03 3pp
- 7903110357 Forwards milestone & activity list for TMI. status 6td 751231. for period ending 760107 OUNN.H T. OPU Bervice Corp. 76/01/14 3pp
- 7905110354 Forwards milestone & activity list for TMI, status dtd 760227, for period ending 760307 OUNN W T OPU Service Corp 76/03/05, 3pp
- 7905110401 Forwards milestone & activity list for TMI. status 4td 760430, for period anding 760507 GUNN.H T. OPU Service Corp. 76/05/06. 2pp
- 7905110397 Forwards milestone & activity list for TMI, status dtd 760531, for period ending 760607 OUNN, H T. GPU Service Corp 76/06/07, 2pp

- 7905:10333 Ack receipt of NRC 760624 1tr re const status rept "Yellow Book " Forwards summary of NRC "Yellow Book" activity dates as submitted by General Public Utils ARNOLD:R C Metropolitan Edison Co 76/06/24 2pp
- 7905110395 Forwards milestone & activity list for TMI.status dtd 760630.for period ending 760707 OUNN.W T GPU Service Corp 76/07/06 2pp
- 7905i10392 Forwards milestone & activity list for TMI.status dtd 760731.for period ending 760807 QUNN.W T QPU Service Corp 76/08/06 2pp
- 7905110165 Forwards application for byproduct matl license ARNOLD,R C Metropolitan Edison Co 76/10/19 ip
- --7905110170 Application for matl/byproduct license by Metropolitan Edison Co for possession of any byproduct matl w/atomic numbers between 1 % 83.Cs-137.Am-De & Pu-139 ARROLD.R C Metropolitan Edison Co 76/10/19 12pp
- 7905110393 Forwards milestone & activity list for TMI,status dtd 761031,for period ending 761107 GUNN,W T GPU Service Corp 76/11/05 2pp
- 7903110406 Forwards milestone & activity list for TMI, status dtd 761130, for period ending 761207 Fuel load date extended because of budgatary restrictions GUNN.W T GPU Service Corp 76/12/03 2pp
- 7905110403 Forwards milestone & activity list for TMI, status dtd 761231.for period ending 770107 QUNN.W T GPU Service Corp 77/01/06 2pp
- 7905110405 Forwards milestone & activity list for TMI.status dtd 770131.for period ending 770207 GUNN.H T GPU Service Corp 77/02/04 2pp
- 7905110402 Forwards milestone & activity list for TMI.status dtd 770228 for period ending 770307 OUNN.W T GPU Service Corp 77/03/04 2pp
- 7905110160 Requests add1 info for processing 761017 application for byproduct mat1 license Forwards mat1 lab use guide BELL, J M Radioisotopes Licensing Branch (Pre 790501) 77/03/25 3pp
- --7709110162 Draft "Ovide for Preparation of Applications for Lab Use of Small Quantities of Syproduct Mat1 " \* Radioisotopes Licensing Branch (Pre 770501) 75/12/31 21pp
- 7905ii040D Forwards milestone & activity list for TME.status dtd 77033i.for period ending 770407.Most recent fuel load date delay rept by util should read Dec 1976 QUNN.W T GPU Bervice Corp 77704/04 2pp
- 7903:10176 Application for matl/byproduct license to authorize possession of any byproduct matl w/atomic numbers 1 through 83 inclusive ARNOLD,R C Metropolitan Edison Co 77/04/18 51pp
- 7905110396 Forwards milestone & activity list for TMI, status dtd 770429, for period anding 770507 QUNN: H T QPU Service Corp 77/05/06 2pp
- 7905110389 Forwards milestone & activity list for TMI.status dtd 770531.for period anding 770607 OUNN.W T OPU Service Corp. 77/06/03. 2pp
- 7903110136 Add1 info requested on 770325 by NRC re application for mati/byproduct license dtd 761019 has not been received Info must be received within 30 days.

  BELL-J.H Radioisotopes Licensing Branch (Pre 790501) 77/06/16
- 7905110149 Forwards add1 info re byproduct mail license requested in MRG 770325 % 770610 ltrs HERBERINJ G. Metropolitan Edison Co. 77/06/29. 75pp.
- 7905110385 Forwards milestone & activity list for TMI.status dtd 770630.for period ending 770707 GUNN.W T QPU Service Corp 77/07/05 2pp
- 7905110384 Forwards milestone & activity list for TMI.status dtd 770831.for period ending 770907 QUNN.W T OPU Service Corp 77/09/02 2pp.

- 7905110144 Matl/Byproduct License 37-17287-01 for Metropolitan Edison Co.authorizing possession of any byproduct matl w/atomic numbers between 1 & 84.0s-137.Am-241 & Pu-139 Radioisotopes Licensing Branch (Pre 790501) 77/09/26 3pp
- 7905110382 Forwards milestone & activity list for TMI.status dtd 770930.for period ending 771007 Lists reasons for extension of fuel load date GUNN.W T GPU Bervice Corp 77/10/07 2pp
- 7905110378 Forwards milestone & activity list for TMI.status dtd 771031.for period ending 773107 GUNN.W T OPU Service Corp 77/11/02 2pp
- 7905110376 Forwards milestone & activity list for TMI, status dtd 771130, for period ending 771207 OUNN, W T GPU Service Corp 77/12/09 2pp
- 7908:10174 Requests add1 info for processing mat1/byproduct license application dtd 770418 M/a enci WRIGHT.E G Radioisotopes Licensing Branch (Pre 790501) 77/12/19 ip
- 7905110373 Forwards milestone & activity list for TMI.status dtd 771231.for period ending 780107 OUNN.H T OPU Service Corp 78/01/09 2pp
- 7908090181 Various update sheets for Blue Book from 720417-780203 \* Cammiesion 78/02/03 279pp
- 7903110368 Forwards milestone & activity list for TMI.status atd 780131.for period ending 780207 GUNN.W T. QPU Bervice Corp 78/02/09 2pp
- E NRC Bafety Evaluation Report (BER), suppls & correspondence
- 7905220432 Bubmits draft input to BER section re degradation to core meltdown CUNNINGHAM, M Office of Nuclear Regulatory Research, 79/04/13 5cc
- 7903160091 Cutline for SER
  MATTSON, R J Division of Bustems Safety 79/05/14 2pp
- F. Security, medical, emergency & fire protection plans
- 7905220423 Notifies of fullfillment of util security packet request BWEENY:M Division of Security 76/08/26 ip
- 7905160166 Forwards \$30 00 security clearance fee from Metropolitan Edison representative.LL Lawyer W/o encl DOPP,R,A Personnel Security Branch 76/11/01 1p
- 7905140190 Forwards 430 00 security clearance fee from Metropolitan Edison representative.WM Creitz W/o enci DOPP.R A Personnel Security Branch 76/11/19 ip
- 7905160174 Forwards requested fingerprint card Provides add1 indo no Form 1 CREITZ:W M Metropolitan Edison Co 76/11/24 ip
- 7908160161 Notification of "L" access authorization for ! Edison representative.LL Lawyer BRADY,R J Personnel Security Branch 77/01/18
- 7905220419 Requests three personnel security packets be . Hetropolitan Edison Co DOPP.R A Division of Security 77/03/17 ip
- 7905160159 Notification of receipt of request for access packet from Metropolitan Edison employee. JA Heverling HIMMELBBACHL Personnel Security Branch. 7770574
- 790516D173 Forwards #30 00 security clearance fee from M Edison representative, JA Heverling, W/o encl. DDPP.R A Personnel Security Branch 77/05/17, 1
- 7905160179 Notification of "L" access authorization for | Edison representative MM Creit: BRADY,R.A. Personnel Security Branch. 77/08/08
- 7905140140 "Emergency Procedure 2202-2.1, Station Blackou version \* Metropolitan Edison Co. 77/12/30. 5pp

- 7908160171 Notification of "L" access authorization to Metropolitan Edition representative. JA Havarling BRADY.R A Personnal Security Branch 78/08/26 ip
- 7903160107 Notes re smergency planning & evacuation \* Commission 79/03/31 9pp
- 7905140046 Discusses emergency procedures for major sequence of events following loss of forced circulation of RG6 # Office of Nuclear Reactor Regulation 79/04/01, 23pp
- 7905220416 Forwards review of salient evacuation points from FBAR & PA Disaster Operations Plan
  ONG.C Office of Policy Evaluations 79/04/01 19pp
- 7905220457 Discusses Emergancy Procedure 5 re loss of letdown w/reactor coolant pump running TEDESCO.R.L Assistant Director for Plant Bustems 79/04/07
- 7703090232 Discusses emergancy preparedness needs in light of TMI incident Urges assignment of 1% persons to State Programs until end of fiscal year & eight permanent positions RYAN-R G Office of State Programs 79/04/10 10pp
- 7903300076 Notifies State of MA that NRC has not received acceptable emergency plan Offers assistance in resolving problem HENDRIE.J M Commission 79/05/09 2pp
- 7905300094 Notifies State of MI that NRC has not received acceptable emergency plan Offers assistance in resolving problem HENDRIE.J M Commission 79/05/09 2pp
- 7905300101 Notifies State of QA that NRC has not received acceptable emergency plan Offers assistance in resolving problem HENDRIE, J M Commission 79/05/09 2pp
- 7705300E03 Notifies State of IL that NRC has not received acceptable emergency plan Offers assistance in resolving problem HENDRIE, J. M. Commission 79/05/09. 2pp
- 7905300107 Notifies State of VA that NRC has not received acceptable amergency plan Offers assistance in resolving problem HENDRIE: J K Commission 79/05/09 2pp
- 7703300115 Notifies State of NE that NRC has not received acceptable emergency plan Offers assistance in resolving problem HENDRIE.J M Gommission 79/05/09, 2pp
- 7905300119 Notifies State of CD that MRC has not received acceptable amergency plan Offers assistance in resolving problem HENDRIE: J H Commission 79/05/09 2pp.
- 7903300120 Notifies State of HN that NRC has not received acceptable emergency plan. Offers assistance in resolving problem HENDRIE, J M Commission 79/05/09 2pp
- 7905300123 Notifies State of MD that NRC has not received acceptable emergency plan Offers assistance in resolving problem HENDRIE; J. H. Commission 79/05/09 2pp
- 7703300124 Notifies State of RI that NRC has not received acceptable emergency plan Offers assistance in resolving problem HENDRIE. J M Commission 79/05/09 2pp
- 7905300126 Notifies State of NC that NRC has not received acceptable emergancy plan Offers assistance in resolving problem HENDRIE: J. K. Gommission 79/05/09 2pp
- 790530012B Notifies State of KY that NRC has not received acceptable emergency plan. Offers assistance in resolving problem HENDRIE, J. M. Commission, 79/05/09 2pp
- 7905300131 Notifies State of HI that NRC has not received acceptable emergency plan. Offers assistance in resolving problem HENDRIE, J. K. Commission. 79/05/09 2pp.
- 7905300134 Notifies State of CH that NRC has not received acceptable emergency plan Offers assistance in resolving problem MENDRIE: J M Commission 7900-700
  - costable

- 7905300139 Notifies State of ME that NRC has not received acceptable emergency plan Offers assistance in resolving problem HENDRIE, J. M. Commission 79/05/09 2pp
- 7905300144 Notifies State of PA that smargency plan must be upfated Requests cooperation during review HENDRIE, J M. Commission 79/05/09 2pp
- 7905160063 Comments on security assistance at TMI ROBERTEON, L. Division of Security 79/05/10 2pg.
- 7905300428 Comments on fire protection & security deficiencies at FFI NOTLEY, D P Engineering Metholology Standards Branch 79/03/18
- Q Adjudicatory correspondence
- 7905090235 Response to stay motion by intervenors Draft order danging intervenors' motion but directing ASLAB to consider Re-222 issue encl
  KELLEY, J L Office of the General Counsel BEGY-A-78-10 78/02/24
- --7905070247 Opposition by util to 780209 request from joint intervi-Citizens for Safe Environ, & York Committee for Safe Environ for stay of initial decision Affidavit of MO Runte & Certificate of Svc end TROMBRIDGE, G. F., BLAKE, E.L. Shaw, Pittman, Potts, & Trowbridge
- 78/02/21 1500
- 7905220426 Forwards requested documents re Chairman Hendrie's participation in review of Board decision.
  8LAGGIE:E L. Office of the General Coursel. 78/02/24 1p
- 7905090246 Reviews ALAB-465, issued by ASLAB on 780327 No petition for review have been filed decision does not warrant Commission raview. KELLEY,J L Office of the General Counsel BECY-A-78-34 78/04/?!
- -7905090249 Remands radon issue to ABLB w/directions to reopen race/d for receipt of new evidence & for further hearings Partial dissent of HR Johnson encl DUFLO,MM E Atomic Bafety and Licensing Appeal Panel 78/03/27
- 7905090222 Informs Commission of ASLAB ALAB-474 decision on whith 11 petitions for review have been filed & does not warrant review on its own merits.

  KELLEY, J. L. Office of the General Counsel BECY-A-78-47 78/04.54 Эрр.
- 7705220434 Forwards 780606 memo re Chairman's participation in tivise of ALAB-474 on TMI CHOPKO,M Office of the General Counsel. 78/06/06. 1p
- ---7905220436 Supplies background info re Chairman's participation in ALAB-474 on THI Since Board decision does not deal w/ substantive issues, no conflict of interest is involved CHOPKO,M Office of the General Counsel 78/06/06 ip
- 7905090226 Informs Commission of ASLAB decision ALAB-486 for which patition for review has been field. Decision concerned emergency plans & risk of heavy aircraft crashing into plant.
  pl
- 7705070221 Provides info re Kepford v NRC: DC Circuit Number 78:1931 Plaintiff seeks judicial review of ALAB-480 insofar as decision affects TMI proceeding. Not likely to be substained by courts EILPERIN.S.F. Office of the General Counsel 78/10/24 RH
- ---7905090225 Provides into re Keptord v NRC, DC Circuit Number 78-1931 Plaintiff seeks judicial review of ALAB-480 only insofar #1 decision affects TMI proceeding Will keep informed. ELLPERIN.S.F. Office of the General Coursel. 78/10/24
- --7909090200 Provides into re Keptord v NRC, DC Circuit Number 78-1731 Plaintiff seeks judicial review of ALAB-480 only insofar 49 decision aftects TMI proceeding, Will keep informed. ELLPERIN.8. F. Office of the General Coursel. 78/10/24 19
- --7705090232 Provides into re Keptord v NRC: DC Circuit Number 79-173]
  Plaintiff seeks judicial review of ALAB-480 only insofer 41
  decision affects TMI proceeding Will keep informed
  EILPERIN:8 F Office of the General Counsel 78/10/24. IF

- 7905100406 Natifies that Ofc of Executive Legal Director will assist in developing response to 790329 petition by Inviron Coalition on Nuclear Power MURRAY, J. P. Rulemaking & Enforcement Division 79/04/04 Spp
- 7905160216 Forwards final evaluation of items discussed in 790228 memors B&W-designed nuclear plants Requests add) info he forwarded to licensing beards (Operations Inspections 79/03/28
- 7905100409 Putition to suspend D.s for all PMRs LOCHOTOTAWA Covironmental Coalition on Nuclear Power 79/03/29
- 790516016G Forwards Board Notification 79 10 on reactor inspector concerns on N&W plants Certificate of Dv. antl. 8CINTO.J F. Hearings Division. 79707/29 1App.
- ---7905160185 Muard notification seartor inspector concerns re B&W plants VABSALLO, D B Assistant Director for Light Water Reactors 77/03/06. Rep
- -- 7005160201 forwards two Moseley to Thomoson memos for Hoard
  - THOMPSON D Office of 1 & 1 trenutive Officer for Operations Support 79/0//49 in
- --7909160209 Informs that preliminary evidation of Item 3 contained in 790928 memo will be reviewed in light of TMI transfent AddI info may cause change in previous assessment MBELY.N C Division of Reactor Operations Inspections 79/03/29 ip
- 7905160050 Comments on delay in processing 790306 Board notification therings Division 7970 t/ 10 App
- 770501011D Forwards request for Board notification to numerfety grade equipment to mitigate transtents. SCINTO J.P. Heatings Division. 77704704 (Upp.
- --7905010356 Board multification staff assessment no moneafoly-grade equipment to miligate transferts
  VAGGALLO D Assistant Director for Light Water Reactors
- ---7905010170 Board motification recent leave on nonsafety grade equipment to mitigate transcents Hore toto te required TEDEGCO.R ( Assistant Director for Reactor Dafety 79703/16
- 7905300079 Forwards draft order to assume 6 confirm direct NRC regulatory authority over emergency situation at THE  $\omega$  0088GK.L V. (Iffice of the Lieutive Director for Operations 79704702. Jpp
- 7903090215 Draft of urder to assume & forfirm direct NRC regulatory authority over emergency situation at TML 2 CHILKS U. Office of the Uscretary of the Commission ... 79704705
- 7905140166 Recommends postponing determination of extraordinary nuclear occurence at THI until end of accident to assessment of consequence, Price Anderson questions should be delayed BICKNIT, L. Office of the General Counsel 79/04/03 to
- 7905160033 Discusses effects of TMI on pending Branch IV hearings OLHSTLAD, N. J. Branch A. 79704701 Rep
- 7905160039 Discusses effects of THI on hearing schedules, lists proceedings scheduled from Apr through June Forwards questions to be answered at 790404 hearing R618, E. J. Branch 3 79704703 2pp
- ~~7905160045 Lists questions to be answered at 790404 hearing re liquid pathway generic study b FFD HOLFE: B Atomic Bafety and Licensing Board Panel 79/0J/29 2pp
- 7905160112 Board notification nuclear incident at THI Recommends boards on cases involving StM reactors be provided w/IR Bullstin 79-05 & PNO-67 & 67A.B.C.D.E.F.O & H VABBALLO.D B Assistant Director for Light Hater Reactors 79/04/03 Rpp
- 7905160227 Reviews impact of THI on upcoming hearings:lists hearings scheduled for Apr & Hay CUNNINOHAN:0 H Branch 2 79704703 2pp

- 7905090218 Details major issues & possible approaches re legal aspects of NRC inquiry into TMI incident.
  STOIBER.C Office of the General Counsel 79/04/04 App
- 7905160191 Reviews delay in processing requests for Board notifications Provides general background & outline of facts re 790306 notice GCINTO, J.F. Hearings Division 79/04/05 6pp
- 7905160208 Forwards latest motion to reopen safety hearings by T Dattilo on behalf of Save the Valley Save Marble Hill. Forwards revisions to draft motions attached to 790402 MURRAY. J. P. Rulemaking & Enforcement Division 79/04/09 2pp
- --7905160212 Motion to suspend & ravoke CP for proposed facility because of THI incident
  DATTILO, T M Metford & Dattile 79/04/04 2pp
- 7905090223 Buggests appropriate response to Hart testimony re-clused outlet valves on auxiliary feedwater pumps STOLBIR, C. R. Office of the Owneral Counsel 79/04/09 1p
- 790°160006 Discusses legal authority to shut down Rancho Boco sister plants due to TM1 incident
  DIXON-P D Office of the General Counsel 79/04/10 App
- 7905110418 Response to ALAB-309 be radon emissions & de minimus theory from Perkins becom Cartificate of Svc encl.
  BCINTO.J Hearings Division BORDLNICK.B M Branch 4 LIMIB.B H Blanch 2 79/04/11, 45pp
- 7905140517 Response to 790404 brief of Philadelphia Electric Co.Public Byc Electric & Qaus & Atlantic City (NJ) Electric Co re de minimus theory Certificate of Byc enci KLPFORD.C P Citizens for Dafe Environment 79/04/11 Opp
- 7900090213 Forwards list of actions underway re TMI-2 GHAPAR, H. K. Office of the Executive togal Director 79/04/13 2pp
- 7905140.332 Notifies of consolidation of five intervenor groups re-radon emissions issue Parties have until 790525 in which to file for summary disposition.

  DUFLO:B I Atomic Bafety and Licensing Appeal Panel 79704725
- /905020274 Lists complaints filed against several utils & companies associated w/TMI.Formal complaint and MARRONF. J. American Nuclear Insurers 79/04/27 LOpp
- 7905188942 Postpones 790404 evidentiary hearing re aircraft crash probability issue Assessment of situation will be made by 791001 DUILO, H.E. Atomic Safety and Licensing Appeal Panel 79/05/02
- /7050B0570 Forwards class action complaint GA /7-520, filed in UB District Court. Hiddle District of PA, brought against utils associated w/THI.
  GARRIER: W C American Nuclear Insurers 79/05/04 14pp
- 7905220352 Porwards class action complaint Emith vs B&H: /9Clv2235;UB District Court for Southern District of NY CARRIER: W C American Nuclear Insurers. 79/05/15 11pp
- 7705270283 Forwards class action complaint to THI accident filed against utils & vendors in C Robert Larson, et all, vs Metropolitan Edison Co. et al CARRIER. H C American Nuclear Insurers 79/05/22 9pp
- H. Qeneral correspondence
- 7903160024 Forwards security packages to be completed by designated employees for access to certain technical repts. H/cencl DOPP.R A Division of Security. 76/08/25 ip
- 7905160026 Forwards extra security packets & fingerprint cards H/o DOPP.R A Division of Security 76/09/09 ip
- 7905070136 Requests immediate closing of nuclear power plants SCHULER, U Affiliation Unknown 79/03/29 ip.

- 790516003B Requests rough estimate of probability of TMI accident computed on basis of mathodology used in reactor safety study BRADFORD,P A Commission 79/03/27 1p
- 7905040277 Public comments on TMI incident.790330-0409 \* Affiliation Unknown 79/03/30 60pp
- ---7905040285 Insists util has placed corporate interests far above concern for public welfare Util presence in area is no longer desired Suggests evacuation
  MYERS.J A Cumberland County, PA 79/04/03 2pp
- ---7903040297 Urges stationing of permanent unsite federal inspectors at nuclear power plants in operation 5 under const in USA DLICKMAN, D. House of Rep. 79/04/04 ip
- 7905110202 Confirms 790329 request for telephone logs re TMI situation HODODON, A Commission 79/03/30 is
- 7905110235 Confirms telcon w/E Fay requesting names of Congressmen who were informed of TM1 situation & at what time HODGDON.A Commission 79/03/30 ip
- 7905160097 Suggests naming outside individuals & NRC members to accident review board AHEARNE.J F Commission 79/03/30 to
- 7905300501 Requests complete investigation of TMI-2 incident Since Licensing Board is to make decision on Diable Canyon, requests comparison of structural & operational designs for both plants
  PANETTALE House of Rep. 79/03/30 ip
- 7905300244 Expresses concern re discharge of hazardous matt from TMI-2 Requests notification of NRC activities & offers assistance MATHIAS.C M Senate 79/03/31 App
- 7704170110 Requests registry of all facility employees for health monitoring Dosimeters or film badges should be issued to all parsonnel CALIFANO.J A Health, Education & Welfare, Dept of 79/04/01 ip
- 7905160113 Notes from Commissioners' 790401 meeting re precautionary evacuation THOMPSON H L. Commission 79/04/01 2pp
- 7705070143 Requests NRC honor Governor Brown's request to shutdown Rancho Seco STEINER:R Affiliation Unknown 79/04/02 1p
- 7905160071 Schedule for 790404 meeting w/ACRS subcommittee.NRC & util representatives in Washington.DC to discuss chronology of TMI incident, current plant status, generic & health aspects MCKINLEY.J C ACRS Advisory Committee on Reactor Safeguards 79704/02 1p
- 7903160072 Suggests no more CRs or QLs should be issued until THI avents have been analyzed BRADFORD P A Commission 79/04/02 ip
- ---7905160077 Press concerns from M Danton's 790402 press conference on TMI conditions CAMPBELLIAM Commission 79/04/03 ip
- 7903160154 Tape of H Denton's press conference should arrive 3 PM on 790402. Expects PND completion same day 01BBDN.T Commission 79704/02 1p
- 7905:40:88 Discusses NRC response to Congressman Preyer 790402 itr.All possible meetings will be upen to public Transcripts of closed meetings will be released w/o proprietary info BIGKMIT.L Office of the General Counsel 79/04/03 ip
- 7905160015 Summary of telcon W/S Cubie re decommissioning costs for THI CALKING, O D Fuel Process Systems Standards Branch 79/04/03.
- 7905160031 Describes teleon between J Calkin of NRC & J Cubic of Kennedy subcommittee re-cost of decommissioning TMI KENT, 8 Commission. 79/04/03. ip
- 79051600B1 Outlines action plan for developing regulatory options on sister B&H operating reactors.

  \* Commission, 79/04/03 2pp.

- 7905140084 Comments on areas which will be covered by NRC reviews & suggests a blue ribbon panel be established AHEARNEL J F Commission 79704703 2pp
- 7905170270 Discusses NRC in-house review plans re TMI incident Suggests president establish blue ribbon panel to study technical issues
  HENDRIE J M Commission 79/04/03 2pp
- VENTRES O II COMMITTALIAN AND AND COLOR
- 7905160111 Forwards Chapter S. "Reactor Coolant Sys" & Chapter 6. "Contingency Safety Features" from FSAR WEISSBERO.S Office of State Programs 79/04/04 1p
- 7905160126 Forwards IE Bulletin 79-05 % PNOs on TMI through 790404 W/a encl. WEIGSBERO. S. Office of State Programs 79/04/04 in
- 7905100201 Requests info re Kr-85, levels of gamma radiation at nuclus facilities & instrument failures as they relate to TMI incident
  BRINKER, W.F. Affiliation Unknown 79/04/05 4gp
- 7905110291 Expresses thanks for assistance relissue of oxygen courses sinks within sys BUDNITZ.R J Office of Nuclear Regulatory Research 79/04/05
- 7905110293 Expresses thanks for suggestions re hydrogen overpressure during incident
  BUDNITZ R J Office of Nuclear Regulatory Research 79/04/05
- 7905110299 Expresses thanks for suggestions re assistance during INI incident BUDNITZR J Office of Nuclear Regulatory Research 79/04/05 ip
- 7905110301 Expresses thanks for assistance re-hydrogen bubble problem during incident
  BUDNITZ,R J Office of Nuclear Regulatory Research 79/04/05 12
- 7905110302 Expresses thanks for assistance during TMI incident BUBNITZ, R J Office of Nuclear Regulatory Research 79/04/05 is
- 7905160073 Recommends formation of accident review commission Requisis meeting
  AHEARNE, J. Commission 79704/05 is
- 7905160432 Expresses thanks for assistance during TMI incident SUDNITZ.R.J Office of Nuclear Regulatory Research 79704/05 ||
- 7905160006 Forwards FBI communications re THI incident W/o small BRADY, R J Division of Security 79/04/06 ip
- 7903160104 Forwards background questions & answers re reactor decontamination & decommissioning to support meeting between Hendrie & Benator Hart ETEYER: K.O. Office of Standards Development 79/04/04 12pp
- 7903160125 Draft chronology of contacts between Commissioners.MSC Lieff & Governor of PA re TMI accident 790330-31.
  01880N:T R Commission 79/04/06 2pp
- 7905300302 Forwards draft late to Secretary Schleminger expressing appreciation for support provided by DOE or TMI incident k requesting continued support 90SBICK.L V Office of the Executive Director for Operations 79/04/08 4pp
- 7905100012 Ack receipt of 790402 ltr re TMI incident Complete responses will be forwarded as soon as possible Forwards NRC press releases & preliminary notifications re incident KAMMERER, C. Office of Congressional Affairs, 79704/09 ip
- --7905100013 Requests info re hypothetical radiation dispersion pattur resulting from possible explosion &/or meltdown at THI WEISS, T , RANGEL, C House of Rep. 79/04/02 3pp
- 7905100040 Forwards 790401 itr from T Franz expressing concern ?# aircraft flight paths over TMI during incident METGENBAUM,H M. Senate, 79/04/09, 4pp.
- 7905100212 Ack recaipt of 790330 itr re THI incident. Complete response will be forwarded as soon as possible. Forwards NRC press releases 5 preliminary notifications re incident.

  KAMMERER, C Office of Congressional Affairs. 79/04/09 3pp

- 7903160023 Forwards backup questions & answers to use in preparation for hearing on TMI before Benate Subcommittee on Nuclear Regulation Office of Congressional Affairs 79/04/09
- --7905160027 Backup questions & answers to use in preparation for hearing on TMI before Genate Bubcommittee on Nuclear Regulation KAMMERER, C Office of Congressional Affairs 79/04/09 3Bpp Meetings on TMI KAMMERER, C Office of Congressional Affairs 79/04/16 1p
- 7909180076 Advises that JM Hendrie thinks it unnecessary to establish position on issuing licenses prior to hearing 91880N,T Commission 79/04/09 1p
- 7905160076 Discusses assessment of radiological doses from TMI accident by ad hoc group PETERSON, H T Office of Standards Development 79/04/09 Bpp
- 7903160110 Notification of time change for 790410 hearing HR Denton will not attend OIBBON:T Commission 79/04/09 1p.
- 7903160134 Forwards proposed addition to JM Hendrie's TMI testimony before Senator Hart re evacuation plans
  BRADFORD, P. A. Commission 79/04/09 2pp
- 770530030/ Forwards "Preliminary Description of Events at THI-2 Facility Accident" & "Generic Considerations of THI-2 Incident" as background info for 770410 Senate hearing KAMMERER.C Office of Congressional Affairs 79/04/09 15pg
- 7909100061 In response to 790930 itr re safety of nuclear power plants in CT in light of TMI forwards JM Hendrie's testimony before Senate Bubcommittee on Nuclear Regulation W/o encl KAMMERER, C Office of Congressional Affairs 79/04/10 2pp
- --7905100075 Requests info re TMI mechanical malfunctions & possibility of similar occurrences at CT nuclear plants
  DDDD-C J. House of Rep. 79/03/30 ip
- 7905160040 Forwards congressional ltrs which NRC has answered w/interim responses but containing questions which require further responses Lists priorities W/o encl KAMMERCR, C Office of Congressional Affairs 79/04/10 1p.
- 7905160041 Comments on informing Congress about TMI situation NAMMERER.C Office of Congressional Affairs 79/04/10 2pp
- 7905160137 Requests that TMI info be sent to J Bewick,MA Secretary for Environ Affairs AMEARNE,J F Commission 79/04/10 ip
- 7709160051 List of individuals chosen to comprise Presidential Commission to investigate TMI KAMMERER: C Office of Congressional Affairs 79/04/11 2pp
- 7905190254 Responds to suggestions to help improve conditions at facility fluggestions considered & appreciated DENTON, H R Office of Nuclear Reactor Regulation 79/04/11 59pp
- 7905100181 Ack receipt of 790410 itr forwarding correspondence from KL Pennsbaker re TMI Response will be forwarded as soon as possible. KAMMERER. C Office of Congressional Affairs 79/04/12 2pp
- 7905140196 Responds to 790412 memo re actions on TMI Lists contact persons in Ofc of Administration for FOIA request processing FELTON, J M Division of Rules and Records, 79/04/12 Gpp
- 7905160047 Comments on conversation w/H Myers, special consultant to House Bubcommittee on Energy & Environ, re transcript of Commission closed meeting on TMI.
  KENT, B. Office of Congressional Affairs, 79/04/12 ip
- 7905110253 Requests statement of basis for providing transcripts of closed TMI meetings to Congress on 790412 QILINGKY, V Commission. 79/04/13 1p
- 7905110285 Requests lists by 790420 of all TMI work LEVINE, S Office of Nuclear Regulatory Research 79/04/13. ip
- 7905210263 Summary of questions raised on inservice insp at TMI during current shutdown. Results of weld testing performed by Nuclear Energy Svcs were questioned by util re credibility Nuclear Energy Svcs were questioned by util 79/04/i3. 3pp
- 7905110246 Recommends editorial review procedure for TMI transcripts QILINBKY. V Commission 79/04/14, 1p.

- 7905110249 Describes status of THI transcripts Records of 790330-31 & 0401-05 are in PDR Transcripts of 790406.09.10 & 13 will be available to Commissioners by 790417 HODODON.A Commission 79704/16 ip
- --7905160046 Responds to request for chronology of events re release of transcripts of closed meetings of Commission during TMI emergency
  FAY, E S Office of Congressional Affairs 79/04/16 App
- 7905160101 Submits chronological environmental monitoring info at TMI BRADFORD, P. A. Commission 79/04/16 2pp
- 7905300175 Confirms 790405 telcon re willingness to attend any meeting re TMI Includes text of telex sent to General Public Utils re familiarity w/reverse osmosis & ion exchange TILBE, H R London Nuclear Decontamination, Ltd 79/04/16 ip
- 7905110190 Expresses appreciation for contribution to NRC efforts at HENDRIE, J.M. Commission 79/04/17 1p
- --7905110194 Expresses appreciation of DF Mossbury's work during TMI incident
  DENTON.H R Office of Nuclear Reactor Regulation 79/04/13 1p
- 7905110308 Forwards LV Gussick 790419 memo directing NRC personnel to keep written record of actions pertaining to TMI Requests copies of all memos BUDNITZ.R J Office of Nuclear Regulatory Research 79/04/17 ip
- 7905100206 Ack receipt of 790411 ltr re THI incident Complete responses will be made as soon as possible Forwards D Eisenhut's Benate testimony summarizing significant events H/o encl KAMMERER.C Office of Congressional Affairs 79/04/18 3pp
- 7905110198 Confirms understanding of 790416 meeting re coordination of NRC response to TMI incident Assigns K Cornell as focal point for info Commission 79/04/18 1p GILINBKY, V
- 7905140020 Ack receipt of 790331 ltr Will consider suggestions in analyzing TMI incident HENDRIE.J M Commission 79/04/18 lp
- 7905140171 Forwards transcripts released 790418 & preceding week More will be sent as they are released W/o encl OILINSKY,V Commission 79/04/18 ip
- 7905140175 Forwards transcripts raleased 790418 & proceding week More will be sent as they are released W/o encl QILINSKY,V Commission 79/04/18 ip
- 7905140178 Forwards transcripts released 790418 per V Gilinsky's directions W/o encl BICKWIT,L Office of the General Counsel 78/04/18 ip
- 7909160023 Ferwards proposed witness list for second Hart hearing on THE KAMMERER, CC Office of Congressional Affairs 79/04/18 2pp
- 7905230135 Lists addl personnel to be authorized for access to turbine bldg STELLO,V Division of Operating Reactors 79/04/18 19
- 7905020246 Believes nuclear power plants should be closed until emergency ctrs for times of crisis are available Hants no plants built pending improved safety assurances WEBSTER, L. Affiliation Unknown 79/04/19 ip
- 7905140258 Responds to 790418 invitation NRC representatives unable to attend European nuclear conference in Hamburg to discuss TMI HENDRIE J M. Commission 79/04/20 1p
- --7905140260 Invites NRC representative to 790509 European nuclear conference in Hamburg rs TMI.
  BECKURTS.K.H European Nuclear Conference 79/04/18 1p
- 7905160146 Notification that GAO will conduct investigation of TMI incident KAMMERER, C Office of Congressional Affairs 79/04/20. 1p

- 7905100338 Forwards update to partial response to Congressmen Ertsl & Goodling's 790209 its to UM Hendrie Update includes shutdown of TMI-2 from "dependable capability" provided by various Reliability Councils
  YUUW88L000,8 J Cost Benefit Analysis Branch 79/04/23 3pp
- 7905160175 Suggests communication sys be upgraded to handle two events simultaneously. & marimize interface between incident response ctr & Commission during unusual events
  KERNEDY.R T Commission 79/04/23 ip
- 7905230154 Requests addition of KE Plumies & RF Fish to NRC Access List dtd 790413 MCOSCARJ J Region i. Philadelphia, Office of the Director 79/04/23 | Jpp
- 7905230163 Request addition of RH Engelten to NRC Access List dtd 790413 MCOSCAR.J J Region 1, Philadelphia, Office of the Director 79/04/23 10
- 7905020011 Recommends temporary shutdown of Rancho Seco until present uncertainties re TMI-2 incident are clarified MATSULR T House of Rep 79/04/24 2pp
- 7905020405 Requests NRC assistance for college survey re average citizen's feelings about nuclear power MILLER, 0 Affiliation Unknown 79/04/24 2pp
- 7705100364 Requests temporary shutdown of Ranch Seco in view of incident of TMI-2 BROWNE G California, State of 79/04/24 ip
- 7905020281 Believes that comst waiting period should be enforced until nuclear cost & waste problems are solved Requests info re 'nuclear safety MOORE, D Affiliation Unknown 79/04/25 ip
- 7905160021 Forwards 790412 itr from AB Feldman to J Carter volunteering to work w/Presidential Commission on THI accident RAMMERER.C Office of Congressional Affairs 79/04/25 17pp
- 7903230165 Requests B Ebert be thanked for excellent job in preparing charts for briefings
  VOLLMER, R H Assistant Director for Site Analysis 79/04/25 in
- 7905300345 Discusses delay in appointing non-NRC individual to head TMI-2 investigation Suggests interim NRC coordinating staff CININSKY, V Commission 79/04/25 ip
- 7905020123 Comments on THI-2 NRC should order all operating B&M designed nuclear facilities shut down pending appropriate design corrections

  HALKER.R S House of Rep 77/04/26 ip
- 7905020265 Expresses appreciation for way in which THI incident was handled PENNER, K.L. Affiliation Unknown 79/04/26 fp.
- 7905150083 Notifies that if Rancho Seco is shut down availability of power from addl sources is subj to transmission limitations & other factors unique in sys SHACKELFORD, 8. Sacramanto Municipal Utility District 79/04/26
- 7905150055 Favors thorough analysis before decision to shut down nine nuclear power plants LIVINOSTON.R L. Congress (Joint & Rotating Committees, etc.) 79/04/26 1p
- 7905160132 Forwards 790420 ltr from Chairman Dingell to E Steats, Comptrollar General of US, requesting GAD initiate comprehensive investigation of TMI incident KAMHERER, C Office of Congressional Affairs 79/04/26 3pp
- 7905300112 Discusses methods of measurement for personnel radiation exposure.cause of radiation leaks & radiation levels prior to TMI incident Info submitted for review & update for Congressional input a Office of Inspection & Enforcement 79/04/26 Spp
- 7905020447 Comments on current nuclear power plant problems in US and safety record at Canadian glanta
  SIMON, H R Affiliation Unknown 79/04/27 ip.
- 7905220414 Discusses bus transportation for 790504 Congressional visit HCOBCAR, J J Region i, Philadelphia, Diffice of the Director 79/04/27, ip

- 7905020031 Public comments re incident at TMI & nuclear power in general & Affiliation Unknown 79/05/01 103pp
- 7905140027 Responds to ancl 790406 ltm documenting earlier suggestion concerning use of oxygen to reduce hydrogen bubble Adding addi oxygen could have adversely affected plant safety DENTON-H R Office of Nuclear Reactor Regulation 79705701 is
- --7905140027 Suggests addition of oxygen to reduce hydrogen b. bhie-ANDERSDN.L Affiliation Unknown 79/04/06 ip
- 7905140073 Forwards response to questions asked by Senator Hart es NRC's FYSO authorization after TMI incident HALLER.N M Office of Hanagement and Program Analysis 79/05/01 lipp
- 7905160052 Advises that Joint Chiefs of Staff assigned nachase "Jarra Purpose" to operations in support of TMI incident QOSSICK.L V Office of the Executive Director for Operations 79/08/10 ip
- 7905160087 Forwards antinuclear flyers \* Commission 79/05/10 6pp
- J Insurance & indemnity information
- 7905140486 Forwards Amend 8 to Indemnity Agreement B-64 per gravely changes, reincrease in liability insurance from \$140 mittien to \$160 million, effective 790501 encl
  SALTZMAN, J Antitrust & Indemnity Oroup 79/05/01 6pp
- 7905220362 Returns unsigned Amend 8 to Indomnity Agreement 8 64 H., star-Liability Insurance Pools will not provide add1 coverage OERETY.H F OPU Service Corp 79/03/16 3pp
- O Advisory Committee on Reactor Safeguards reports & correspondent
- 7905140022 Submits summary of NRC 790329 briefing on THI larries LIBARKIN,M W ACRB Advisory Committee on Reactor Defeguers 79/03/29 5pp
- 7905140021 Forwards portion of Bellefonte Bubcommitte meeting transcript questioning whether operator could diagnose accident & assess core status
  BENDER, M ACRE Advisory Committee on Reactor Gafeguards 13pp
- 7905300378 Discusses ACRB concerns re TMI-2 incident \* ACRB Advisory Committee on Reactor Safeguards. /9/04/03 + F
- 7905140011 Bummary of 790410 hearing by Senate Subcommittee and Regulation re TMI accident Investigation will last sir months & rept issued after one year BESECTED E ACRS Advisory Committee on Reactor Safeguards 79/04/11 Spp
- 7905140026 Bummary of ACRS 790409-14 site visit re plant stable recovery plans 3 core assessment Forwards B&W 790410 rept an natural circulation cooling ACRS Advisory Committee on Reactor Dafeguards 79/04/15. 42pp
- --7905140028 "Summary of Natural Circulation Alternatives for the few in Karraschis A Babcock & Hilcox Co 79/04/10. 33pp
- 7905110274 "Second Interim Rept on Recent Incident at IHI." 4725k Pret to be completed during 790510 meeting \* ACRS - Advisory Committee on Reactor Safeguards 79704/11 to
- 7905140012 Makes recommendations to NRC re TMI Recommends esective of operator training NRC week in chemical expertise SHEMMON, P. G. ACRS Advisory Committee on Reactor Dafeguards 79/04/18 2pp
- 79053003B1 Forwards summary of highlights of special ACRO Asisting Pa on 790416-17 to discuss THI incident. CROCKER, L. P. Division of Project Management. 79/04/18 1332
- --- 790300391 Statement by vice president of Nuclear Power Gererality to ACRS re B&W activities as result of TMI incident Documentation encl HACHILLAN, J H Babcock & Hilcox Co 79/04/16. 30pp

- ---7905300396 Datails topics to be covered at special ACRB meeting on 790416 Topics include small breaks & transients in E&W plants in light of TMI incident GROCKER.L.P Division of Project Management 79/04/12 ip
- 7905040057 Responds to 790418 ltr ACRS 790417 recommendations are generic & apply to all PWRs Procedural changes should be made only after study of effect on overall safety CARBON, M W ACRS Advisory Committee on Reactor Safeguards 79/04/20 2np
- 7905140013 Submits current preliminary chronology package of operational charts & results of interviews w/operators & others re TMI incident LIBARKIN.M W ACRE Advisory Committee on Reactor Safeguards 79/04/25 49pp
- 7905140015 Forwards TE Murley 790413 memo re research program changes resulting from TMI accident
  MCCRELEGB.T ACRB Advisory Committee on Reactor Bafeguards
  79/04/26 ip
- ---7905:400:7 Datails changes in safety research program as result of THI incident MURLEY, T E Division of Reactor Safety Research 79/04/13,
- 7905140014 Invitation for 790511 appearance before ACRS to discuss causes, lessons & corrective actions of TMI accident b whether to shut down other B&H reactors FRALEV:R F ACRS Advisory Committee on Reactor Safeguards 79/04/27 tp
- 7905140184 Forwards 780413 memo re TMI core damage assessment updating 790406 rept based on sarly data Mamo also forwarded to ACRB members attending 790508 meeting on reactor fuel BIOSIMERT, P ACRB Advisory Committee on Reactor Safeguards 79708427 in
- 7905140023 Forwards Metropolitan Edison 790424 ltr w/emergency shutdown procedures & preliminary sequence of TMI-2 accident events MCGRELEGG T O. ACRS Advisory Committee on Reactor Safeguards 200404.09
- --7905140025 Submits emergency procedures 2202-1 l.reactor trip;22021 3, loss of reactor coolant/sys pressure;2202-2 i.station blackout & preliminary sequence of events rept ARNOLD, R C GPU Service Corp 79/04/24 55pp
- 7903250393 Responds to ACRS recommendations re TMI accident as requested in NRC 790517 ltr
  ANDERSON, T M Hestinghouse Electric Corp. 79/05/21 21pp
- 7905300526 Discusses initial review of task force to evaluate safety implications for nuclear plant design & operation of TMI accident Individual ACRS recommendations will be evaluated as part of overall design review program.

  8CHERER, A E C-E Power Systems 79/03/25 2pp
- P Operating license stage documents & correspondence
- 7905110171 Matl/Buproduct License 37-17257-02 for Metropolitan Edison Co, authorizing possession of any byproduct math w/atomic numbers 1-83 inclusive. HRIGHT E Q. Radioisotopes Licensing Branch (Pre 790501) 78/03/16 2pp
- 7905110366 Forwards milestone & activity list for TMI.status dtd 780228 for period ending 780307 QUNN:W T QPU Service Corp 78/03/15 2pp
- 7905110079 Rept on reactor trip/engineered sys of 790423 W/NRC routing SIIP SEELINGER, J. L. Metropolitan Edison Co. 78/04/23 49pp
- 7905230239 "Nuclear Power Plant Evacuation Plans"
  CLEARY, P. G., COMEY, D.D., Citizens for a Better Environment,
  GBE-7865 78/05/31 32pp
- ---7903230242 Forwards statement issued by D Comey of Citizens for Better Environ re emergency planning for nuclear accidents FOUCHARD, J. J. Office of Public Affairs, 78/05/25, 3pp.
- ---790523024B Responds to comments of IL Emergency Bycs representative's reactions to federal radiological emergency response planning effort.

  CDLLING.H.E. Office of State Programs 78/02/21 Spp

- 7905140125 NRC examination results for 1975-1978 power reactor operator applicants; senior operator applicants previously licensed & senior operator applicants initial application # Commission 78/12/31 3pp
- 7905i40i17 "Power Plant Examination Results Summary Sheet" for various plants for 1977-1979 COOLEV.R A Operator Licensing Branch 79/02/13 180pp
- 7905190248 Tech Spec changes re emergency feedwater sys \* Metropolitan Edison Co 79/03/04 6pp
- <sup>1</sup> 7903190099 Notification of breakdown in communication lines for TMI info DAVIES, S New York, State of 79/03/16 20p
  - 7905110361 Updates announcement re 790328 incident no injuries reported & turbine shutdown caused by reduction in flow of feedwater to steam generators 

    Office of Inspection & Enforcement 79/03/28 2pp
  - 7908160194 Commants on TMI morning release of redicartivity CAMPBELL, M Commission 79/03/30 ip
  - 7905300216 Summarizes info re technical experts called to TMI site \* Office of Nuclear Reactor Regulation 79/03/31 ip
  - 7905300288 "Preliminary Test Results, Semiscale Pressurizer Relief Valve Venting from TMI-Type Conditions" + Office of Nuclear Reactor Regulation 79/03/31 16pp
  - 7905110272 Test results of hydragen solubility experiment 1 at Provo.Ut \* Office of Nuclear Regulatory Research 79/04/01 ip.
  - 7905140112 Forwards viewgraphs used at Commission meeting EISENHUT.D 9 Assistant Director for Systems & Projects 79/04/01 7pp
  - 7905190246 Tech Specs for ECCB
    \* Metropolitan Edison Co 79/04/01 4pp
  - 7905300211 Discusses NRC procedures for decision to recommend evacuation \* Commission 79/04/01 7pp
  - 7905090256 Forwards 790402 memo from C Stoiber re issues which NRC should consider in approaching demands for investigation into TMI incident
    BICKNITL Office of the Ceneral Counsel 79/04/02 ip
  - 7905090257 Forwards preliminary thoughts on decontamination of TMI-2 in response to UF Ahearns request KENNEKE; A Office of Policy Evaluations 79/04/02 6pp
  - 7903110138 Board notification recommends IE evaluation of reactor inspector concerns re B&W plants be sent to Boards now VASSALLO,D B Assistant Director for Light Water Reactors 79704702 ip
  - 7905110227 Rept 4 TMI update on situation as of 790402, re evacuation options
    WILCOX.W H. Housing & Urban Development, Dept of 79/04/02 3pp
  - 7903140163 Forwards possible action plan by J Kelley & L Slaggie for consideration of regulatory options on S&W operating sister plants to TMI BICKWITL Office of the General Counsel 79/04/02 3pp
  - 7905160099 Forwards Facilities & Sys Security Branch notes on TMI & Division of Security 79/04/02 3pp
  - 7905160103 Meeting notes re legal issues for TMI MALLORY,R. Office of the General Counsel 79/04/02 ip
  - 7905160141 Forwards personnel exposure & monitoring rept for 1978 HERBEIN.J.O Metropolitan Edison Co. 79/04/02 2pp
  - 7905160177 Outlines methods of accident review for TMI AKEARNE, J.F. Commission 79/04/02. 4pp.

- 7905160204 Summary of info re nuclear incident as of 790402 Describes plant & environ status LAFLEUR, J D Office of International Programs 79/04/02 3pp
- 7905160225 Forwards three sets of TLD data collected near TMI facility W/o encl KAMMERER, C Office of Congressional Affairs 79/04/02 1p
- 790B300403 Discusses possible determination of extraordinary nuclear occurence at TMI-2 re application of Pride-Anderson Act BENTON, HR Office of Nuclear Reactor Regulation SHAPAR, H K Office of the Executive Legal Director SECY-79-235 79/04/02 150n
- 7705090233 Forwards statement of PA Governor Thornburgh re indine in milk & background info on federal guidelines for radioactive levels in milk KENNEKE, A Office of Policy Evaluations 79/04/03 3pp
- 7905090239 Forwards excerpts of documents relevant to emergency planning EPA protective action guides PA action guides & FSAR conditions for general emergency action KENNEKE.A Office of Policy Evaluations 79/04/03 83pp
- 7903090238 Lists points to be included in THI-2 study & forwards proposed public announcement re incident prepared by F Ingram KENNEKE.A Office of Policy Evaluations 79/04/03 (Opp
- 7905110209 Requests background info for Commission re-status of B&W reactors. IE Bulletin 79-05, discription of IE action re-B&W plants & description of task group on feedwater transient EYBYMONTIO Commission 79/04/03 2pp
- 7905116229 Discusses requirements for requalification of TMI pumps & valves & possible changes in Tech Spacs REIFF.D Office of Nuclear Regulatory Research 79/04/03 5pp
- 7905110238 Lists status of B&W reactors as of 790402 \* Commission 79/04/03 ip
- 7905110270 Task results of hydrogen solubility experiments 2 & 3 run at Provo.UT • Office of Nuclear Regulatory Research 79/04/03 ip
- 7905160017 Notifies DELD of telcon numbers % individual to be contacted re TMI inquiries
  SHAPAR.H K Office of the Executive Legal Director 79/04/03 ip
- 7905160035 Forwards three sets of thermoluminescent dosimoter data collected around TMI W/o encl
  KAMMERER.C Office of Congressional Affairs 79/04/03 App
- 7705160096 Buggests actions in response to THI accident Forwards possible series of events at THI & requests comments AHEARNELJ Commission 79704/03 6p
- 7705170137 Bummary of 770403 meeting w/GPU Svc Corp & Ketropolitan Edison re base case \* Commission 77/04/03 4pp
- 7705210328 Comments on reactor pressure oscillations at TMI possibility of real oscillations between two gas vols seems likely MARRIOTT.P W. General Electric Co. 77/04/03 2pp
- 7905220438 Discusses radiation levels in industrial waste treatment sampling & hydrogen recombiner
  LAMYER, S OPU Service Corp 79/04/03 1p
- 7905230017 Forwards organizational chart, prerequisites for reactor coolant recovery & charts of pressure & heat curves BERGER, D.M. Babcock & Wilcox Co. 79/04/03 9pp
- 7905230023 Forwards JO Herbein 790403 memo & agenda for 790404 daily planning meeting VOLLMER.R H Assistant Director for Site Analysis 79/04/03, 609.
- 7905230507 Submits brief summary of results of review of radiochemistry data reported to date, RGY,D,H Sabcock & Wilcox Co 79/04/03 2pp
- 7905300430 Forwards miscellaneous handwritten notes on TMI-2 # Office of Nuclear Reactor Regulation 79/04/03 App

- 7904180377 Suggests program to alleviate concern among pregnant y sensevaluate effects to fetus & develop epidemiologic data base for possible future studies GOLDSHITH, R. PARSONT, M.A. Radiological Health Standards 3rance 79/04/04 2pp
- 7905090229 Notification of devolopment of preliminary plan to conduct series of health impact studies related to TMI incidents TOKUMATA, G K Health, Education & Welfare, Dept of 79/04/04 20p
- 7905110213 Draft text on TMI requested by Vice President Mondalp's Cfc for possible use 8 Commission 79/04/04 3pp
- 7903110290 Recommends change to natural circulation at THI-2 whn present cooling mode becomes untenable TEDESCO, R L Assistant Director for Plant Systems 79/04/04 500
- 7903110316 Notes on 790404 telcon W/R Denning
  HANAUER, S H Assistant Director for Plant Systems 79/04/04 1
- 7905110387 Discusses engineering fit to hydrogen solubility data of Pray, Schweickert & Minnich KELBER.C Assistant Director for Advanced Reactor Safety Research 79/04/04 1p
- 7905140031 Submits background info on TMI-2 incident ETHERINGTON.H , BATES.A ACRS - Advisory Committee on Reactor Bafeguards 79/04/04 5pp
- 7905140032 Summarizes assumptions in SANDIA-ORIGEN calculations of P: operating history Provides fuel composition data, decay phase data & long-term data W/tabulated reactor operating summar BENNETTID E Sandia Laboratories 79/04/04 3pp
- 7905140034 Bubmits background info on TMI-2 incident ETHERINGTON: H . BATES: A ACRS - Advisory Committee on Reactor Safeguards 79/04/04 2pp
- 7905140048 Discusses opinion that scenario surrounding TMI-2 incidera was thoroughly evaluated by WASH-1400 BICKEL, J H ACRS - Advisory Committee on Reactor Safeguards 79/04/04 22pp.
- 7903140136 Handwritten notes of 790404 meeting at TMI GOLDSMITH:R Office of Standards Development 79/04/04 3pa
- 7905140254 Discusses causes for hydrogen levels produced at IME Buggests use of chemical inhibitors in ECCS &/or regular coolent to minimize potential hydrogen production XRAMISH.A R & D Associates 79/04/04 2pp
- 7905160013 Discusses implications of TMI incident for licensed power teactors & reactors undergoing review GRAY, J. R. Branch 1 79/04/04 12pp
- 7905160022 Handwritten notes re schedules as result of TMI \* Office of the Executive Legal Director. 79/04/04 13pp
- 7905160169 Dutlines options for TMI accident review AHEARNE, J. F. Commission 79/04/04 3pp
- 7905160184 Discusses estimated radiological exposure doses & SM plan for cold shutdown OIBBON.T Commission 79/04/04 1p
- 7905160226 Lists licensing actions scheduled to occur between 790401-790601, including evidentiary hearings, prehearing conferences & TMI impact on future actions TREBY, B A, Branch 1 79/04/04 Sp
- 7905190135 Discusses natural recirculation questions/concerns \* Office of Inspection & Enforcement 79/04/04. Spp
- 790517017B Notifies of NRC procedure maintaining telephone logs from outside operations of the Executive Diractor for Oper 79704704 1p

- 7905210047 Discusses problems identified at BLW facilities re TMT accurrence identified problems include pressurizor level instrumentation, integrated control sys & lack of hydrogen LEMIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/04 13pp
- 7905230029 Forwards JO Herbein 790404 memo & agenda for 790405 daily planning meeting VOLLMER:R H Assistant Director for Site Analysis 79/04/04 5pp
- 7905230117 Requests attendance at first meeting of TM1 recovery organization to be held on 790405 in Trailer 23 Organization chart encl
  ARNOLD-R C OPU Service Corp 79/04/04 3pp
- 7905230123 Summary of meetings w/TM1-2 study groups re reaching natural circulation & depressurization status STELLO.V Division of Operating Reactors MATTSON,R Division of Systems Safety 79/04/04 10pp
- 7905230126 Requests info ro daily planning meeting in Trailer 22 Daily planning meeting agenda and!
  VULLMERID Assistant Director for Site Analysis 79/04/04 5pp
- 7905090242 Notifies that Commissioner H Uchida of the Japanese Nuclear Bafety Commission will arrive 790407 to review status & activities of TMI-2 events LAFLEUR:J D Office of International Programs 79/04/05 2pp
- 7905110243 Questions & answers for Vice President Mondale on TMI \* Commission 79/04/05 4pp
- 7905110271 Details efforts re equipment survivability
  \* Office of Nuclear Reactor Regulation 79/04/05 6pp
- 7905110278 Description of proposed organization for NRC operation at TMI-2

   Office of the Executive Director for Operations 79/04/05 5pp
- 7905110280 "Evaluation of Failure Modes for Reactor Pressure Vessels. Containments & Other Safety-Related Equipment Subjected to Internal Explosive Environs " Proposes investigation O'BRIEN.J Office of Nuclear Regulatory Research 79/04/05 ip
- 7905110281 Lists new or augmented research projects suggested as result of TMT incident & shutdown of five plants for seismic reasons Project details encl
  RIGHARDSON.JE Mechanical Engineering Branch 79/04/05. 14pp
- 7905110315 Lists info required from Battelle Columbus Labs
  CUNNINGHAM.M Probabilistic Analysis Branch 79/04/05 ip
- 7908110323 Describes areas where General Reactor Safety Research can provide assistance re TMI incident REIFF.D D Division of Reactor Safety Research 79/04/05 Spp
- 7905110334 Considers value of running natural circulation test on reactor in hopes of obtaining info helpful to TMI-2 situation
  TEDEBCORL Assistant Director for Plant Systems 79/04/05
- 7905140132 Handwritten notes of 790405 meeting at PA State Health Dept OCLDSMITH.R Office of Standards Development 79/04/05 App
- 7905160083 Handouts from 790405 brisking LEVING.8 Office of Nuclear Regulatory Research 79/04/05 10pp
- 7905160259 Suggests steps to be taken following TMI Forwards list of options summary of investigations into civil air accidents, A Kenneke 790404 memo & C Stoiber 790404 memo AHEARNE. J Commission 79/04/05 12pp
- 7905190069 Responds to General Public Utils query re alternative methods for long-term cooling Procedures for natural circulation flow dtd 790404 encl.
  RDY.D H Babcock & Wiicox Co 79/04/05 4pp
- 7905190070 Special Operating Procedure Z-57 re pressure reduction during degassification Operations support plans encl WALLAGE: A. Babcock & Wilcox Go 79/04/05 6pp
- --7903190072 Discusses pressure reduction for head cavity degassification
  KOSIBIR R Babcock & Wilcox Co 79/04/04. 2pp

- --7905190074 Notes re NRC comments on special operating procedure Z-57, re pressure reduction during degassification e Babcock & Wilcox Co 79/04/06 4pp
- 7905190077 Forwards status of B&W procedures & site comments/emergency procedures as of 6 AM on 790405
  WRIGHT,R L Dabcock & Wilcox Co 79/04/05 6pg
- 7905190079 Forwards cross-reference of major B&W contingency procedures w/TMI procedures
  ROY.D H Babcock & Wilcox Co 79/04/05 3pp
- 7905190140 Forwards organization charts for TMI-2 recovery DIECKAMP. H. M. OPU Service Corp. 79/04/05 2pp
- 7903190193 Responds to R Mattson & D Ross concerning value of running natural circulation test on B&W reactor TEDESCO.RL Assistant Director for Plant Systems 79/04/05 4pp
- 7905230032 Forwards JQ Herbein 790405 memo & agenda for 790406 daily planning meeting VGLEMER,R H Assistant Director for Site Analysis 79/04/05 Boo
- 7905230039 Forwards organizational chart for Deneral Public Utils' recovery operations Provides guidelines for communicating w/organization
  DENTON, H R Office of Nuclear Reactor Regulation 79/04/05 4pp
- 7909230099 Summary of 790404 meeting of Technical Working Group to discuss desirability of reducing RCS temp from 280 F to 230 F \* GPU Service Corp 79/04/05 1p
- 7905300295 Discusses infine & xenon concentrations in containment sumps
  BARRETT.L Environmental Evaluation Branch 79/04/05 3pm
- 7904270178 Notification of plans to conduct systematic review of stds to determine their adequacy, accuracy & completeness MINOGUE, R B Uffice of Standards Development 79/04/06 1p
- 7905090212 Forwards estimated core inventory of important fission & actinids products for TMI reactor.

  KENNEKE: A Office of Policy Evaluations 79/04/06 4pp
- 7905110245 Minutes of 790405 meeting of techincal working group \* Commission 79/04/06 18pp
- 7905110417 Discusses events within primary sys re core assessment KAUFMAN:N Commission 79/04/06 7pp
- 7705140037 Notifies of 1A primary coolant pump tripped offline & 2A pump started 3 minutes later Some change in thermocouple temp distribution noted but not serious FRALEY.RF ACRS Advisory Committee on Reactor Safeguards 79/04/06 ip
- 7909140129 Handwritten notes of 790406 meeting w/Natl Cancer Inst GCLDSMITH.R. Office of Standards Development 79/04/06. 2pp
- 7905160202 Submits summary of population dose for accident 790328-0405 BATTIST.L Environ Protect Standards Branch. 79/04/06 2pp
- 7905190002 TMI-2 control room manning assignments

  \* Office of Nuclear Reactor Regulation. 79/04/06. ip
- 7905190098 Nutification of reduction in IE personnel at TMI Organizational chart encl ORIER, B.H Region i, Philadelphia, Office of the Director 79/04/04 Spp.
- 7905190158 Notification of completion of RELAP-4 TMI simulations FISCHER, S R EQ & Q, Inc. 79/04/06 2pp.
- 7905190196 Forwards draft of chronology of events & 790406 memo from 8 Conver HOMARD.M Office of Inspection & Enforcement 79/04/06 ip,
- --7905190199 Forwards chronology of events from 790328 at 7 00 am to 790402 at midnight CONVER.8 Office of Management and Program Analysis 79/04/06 18pp

- 7705210030 Forwards 770405 meno to B Graber which lists NRC personnel who have been trained in radiation safety per 10CFR19
  SEYFRIT, K V Region 4. Dallas. Office of the Director 79/04/05
- --7905210035 Submits list of ARC personnel who have been trained in radiation safety per 10CFR19 & should be allowed unascorted access to areas requiring radiation work permits SEYFRIT, K V Region 4. Dallas, Office of the Director 79/04/06 2pp
- 7905210324 Responds to 790403 memo & suggests another possible cause of TME pressure decillation MARRIOTT.P W General Electric Co 79/04/06 ip
- 7905230037 Notifies that Trailer 27 will be used as working area for technical review team & safety assessment team Lists principal staff at work area ROSS.D F Assistant Director for Reactor Safety 77/04/06 ip
- 7905230040 Forwards JG Herbein 790405 memo & agenda for 790407 daily planning meeting VOLLMER:R H Assistant Director for Site Analysis 79/04/06
- 7905230107 Bummary of 790405 technical working group meeting re venting wasts gas in containment & long-term cooling + GPU Bervice Corp 79/04/06 3pp
- 7905230279 Forwards description of staff organization & personnel assignments for NRC operations at TMI-2 DENTON, H R Office of Nuclear Reactor Regulation 79/04/06 7pp
- 7903230496 Notes on hydrogen in RCS & procedure for measuring reactor coolant hydrogen concentration
  HASKIN,F E , THIESING, J H Industry Advisory Group 79/04/06 3pp
- 7905300259 Provides calculations of heat load in containment due to decay of airborns fission products & activity in sump water TAYLGR.M Office of Nuclear Reactor Regulation 79/04/06 11pp
- 7905110292 Forwards concept for benign control of THI-2 primary cooling sys HATTBON.R J Division of Systems Safety 79/04/07 App
- 7905190153 Summary of 790407 meeting w/Metropolitan Edison to discuss awaitiary control bidg exhaust progress rept of waste mgt group & radiation exposura tracting PETERBON T Sefeguards Standards Branch, 79/04/07 3pp
- 7905190203 Discusses plans for post-event liquid raduate No apparent mgt program for immediate future exists Suggests using zeolite/charcoal/sand filters to eliminate iodine BENAROYA, V Auxiliary Systems Branch 79/04/07 4pp
- 7708190250 Forwards concept for benign control of TMI primary coolant sys proposed by Levinson's study group Believes long-term water level in reactor vessel can conceivably be controlled by using accumulator line fill MATTSBN.R J Division of Systems Safety 77/04/07. Spp
- 7905210086 Minutes of 790407 technical working group meeting w/Metropolitan Edison Co re spent fuel pool, makeup tank leakage rates, mass balance & noise analysis # Office of Nuclear Reactor Regulation 79/04/07 2pp
- 7905230056 Forwards JQ Herbein 790407 memo & agenda for 790408 daily glanning meeting.
  COLLINS, J T Effluent Treatment Systems Branch 79/04/07 11pp
- 7905230110 Summary of 790407 planning meeting re establishment of task actions for TMI-2 study groups.

  ARNOLD, R C. GPU Service Corp 79/04/07 14pp
- 790523046B Observations & estimates re containment bldg & estimates of lower bound for total metal-water reaction THIESING, J W Industry Advisory Group. 79/04/07 2pp
- 7905110212 Forwards Commissioner Gilinsky's mark-up of Chairman Hendrie's testimony before Seneta Bubcommittee on Nuclear Regulation on 790410, HOGGDON: A. Commission. 79/04/08, 14pp.
- 7905110217 Discusers 790407 briefing by Westinghouse re preliminary

- 7905110282 Details procedures to be followed to assure coordination if natl Lab support for NRC activities at TMI per 790407 discussion Summary of natl lab effort encl MATTSON.R Division of Systems Safety 79/04/08 ip
- --7905110287 Summary of natl lab support work for THI BIXBY.W W , YBARRONDO.L J E0 & 0, Inc 79/04/07 1399
- 7905190116 Requests authorization to ship four charcoal filters from MPPES plant in Richland.WA to Harrisburg.PA MILEON.R C OPU Service Corp 79/04/08 ip
- 7905190252 Recommends deferral of permission to use addition partial next water sample ROSS, D.F. Division of Project Management 79/04/08 1p
- 7905210036 Bubmits revised list of IE personnel who should be authorized access to Unit 2 control room ALLAN, J N Region I. Philadelphia, Office of the Director 79/04/08 2pp
- 7908210091 Provides agenda for 790408 planning meeting includes the lists & 72-h lists DAVIS, J Q Gffice of Inspection & Enforcement 79/04/00 20pp
- 790521023B Suggests realignment in senior personnel at THI (erg stifts are unacceptable & fatigue is omen of ill-considered declation process
  ROSS-D F Division of Project Hanagement 79/04/08 ap
- 7905210253 Summary of 790407 maeting w/IE personnel at site to helfer understand overall response to event & onsite capabilities & activities BNIEZEK. J H Office of Inspection & Enforcement 79/04/00 %;
- 7905230048 Discusses BtW recommendation that add1 boron he sided to primary coolant sys
  ROBS.D F Assistant Director for Reactor Safety 79/04/08 is
- --7905230053 Discusses Westinghouse proposal to build decay had res. a sys to serve as backup to existing sys. Suggests mode to proposed sys design a Office of Nuclear Reactor Regulation 79/04/00 Spp
- 7703230058 Preliminary thoughts on lessons learned from FHt inclds:1 PALLADING, N. J. Pennsylvania State Univ 77/04/08 6pp
- 7905230070 Discusses Westinghouse 790407 briefing on preliminary conceptual design of mods of TMI-2 decay heat removel sys Mods intended to increase long-term reliability of sys. MATTSON-R J Division of Gystems Bafety 7970470U Jap
- 7905230074 Forwards JO Herbein 790409 memo & agenda for 790409 let 1 recovery deally planning meeting.

  COLLING. J Effluent Treatment Systems Branch. 79/04/08 [Cp.]
- 7905300075 Submits procedures to be followed to assume coordinators: natt lab support for NRC activities.

  MATTSON,R Division of Systems Safety 79/04/08. 259
- 7905100335 Forwards questions & answers for hearing backup book fr [\*] incident, to be provided to chairman MIRAOLIA.F Technical Section, 79/04/09, 24pp
- 790511012B Bummarizes 790405 offer by London Nuclear Decontainstitt
  Ltd to assist in TMI cleanup Recommends meetings w/London
  Nuclear.PNL & BNL consultants re decontamination
  O'GONNOR.P W Operating Reactors Branch 2 79/04/09 3;;
- 7905110358 Preliminary chronology of 790328 TMI incident. \* Division of Project Managament 79/04/09 70pp
- 7905110369 Requests continuing repts re analysis of TMI intident JENNEKENS, J. H. Atomic Energy Control Board, Canada 77/04/01 414
- 7905160102 Outlines scope of fact finding board investigation falls a technical & procedural viewpoints

  ENYDER.B. J. Office of Policy Evaluations, 79/04/09 29p
- 7905160158 Lists options for authorizing new mode of operation for TMI-2 discussion w/8 Traky & L Chandler. GRAY. J. Branch 1. 79/04/09. Spp.

- 7905160223 Ack receipt of info re decontamination & recovery procedures following nuclear incident RUSS,G D Atomic Industrial Forum 79/04/09 12pp
- 7903190121 Discusses establishment of data reduction & mgt group Copies of all THI-2 related documents must be provided to group Collection baskets will be placed in each trailer. LONG,R L. Hetropolitan Edison Co. 79/04/09 2pp
- 7905210039 Submite revised list of IE personnel who should be authorized access to Unit 2 control room ALLAN, J M Region 1, Philadelphia, Office of the Director 79/04/09 Spp
- 7905210095 Requests NRC staff members at TMI site provide summary rept of activities GRIER,B H Region 1, Philadelphia, Office of the Director 79/04/09 1p
- ~-7905210097 Describes new organizational arrangements for shift activities to improve IE coordination ORIER.B H Region 1, Philadelphia, Office of the Director 79/04/09 App
- 7905230081 Forwards 790409 planning meeting agenda & action items discusses in 790408 technical mgt meeting STELLO, V Division of Operating Reactors 79/04/09 25pp
- 7905230082 Announces establishment of data reduction & mgt group responsible for collecting math re incident LONG:R L Metropolitan Edison Co ARNOLD:R C GPU Service Corp 79/04/09 4pp
- 7905300155 Forwards flow chart delineating procedure path to be followed, key control group members & 790404 technical working group minutes PORTER: I. Metropolitan Edison Co 79/04/09 4pp
- 7705300268 Advises that NRC has deceided to defer any determination of extraordinary nuclear occurrence & should not consider Price-Anderson Act implications CHILK.8 J Office of the Secretary of the Commission 79/04/09
- 7703070400 Part 21 rept ABCO sclenoid HT-8331A45 disc holder is Delrin plastic which can become inoperable if subjected to max environ conditions 35° butterfly valve may fail BAAR.R P Affiliation Unknown 77/04/10 3pp
- 7905110123 Discusses need for containing radioactive tank spills at site since island is permeable Recommends tankage on term footing & processing waste through demineralizers KNIGHTON, & Environmental Evaluation Branch 79/04/10 ip
- 7905i10i40 Forwards rept on penetration availability for info Summarizes ability to monitor TMI reactor pressure & level using instruments outside containment. MIRAGLIA, F. J Program Support Branch 79/04/10 6pp
- 7903110193 Testimony of DO Eisenhut before Subcommittee on Nuclear Regulation of Senate Committee on Environ & Public Works, re TML-2 incident EISENHUT, DO Assistant Director for Systems & Projects 79/04/10. 9pp
- 7905110197 Testimony of Chairman Hendrie on 790410 before Bubcommittee on Nuclear Regulation of Senate Committee on Environ & Public Horks, re TMI incident IE Bulletins 79-05 & OSA enci HENDRIELJ M Commission 79/04/10 42pp
- 7905110230 Forwards summary statement for vice president's trip.790410 testimony before Benator Hart's subcommittee & add1 background matt.
  MENDRIE, J. M. Commission 79/04/10, App
- 7905110286 Directs preparation of vented containment conceptual design at TMI within five days per H Denton request
  BUDNITZ,R,J Office of Nuclear Regulatory Research 79/04/10 ip
- 7905110289 Describes telcon from JB Read re chemical behavior of boric acid in primary coolent sys during incident Suggests research into behavior of boric acid under pressure.
  BUDN172:R.J. Office of Nuclear Regulatory Research 79/04/10 ip
- 7903:10296 Submits advisory rept on cooldown from 280 F to 150 F at 1.000 psia.

  DAVIELD. Office of Nuclear Reactor Regulation. 79/04/10 29pp

- 790816006B Forwards questions & ensures re containment liner & decontamination, stainless steel covering over insulation & reactor coolants prepared 790408 for use by R Minague HENRY, J Transportation & Product Standards Branch 79/04/10 288
- 7905160092 Forwards questions & answers as backup for 790410 Congressional hearing re TMI incident \* Office of Policy Evaluations 79/04/10 18pp
- 7905190176 "Behavior of RCS w/Steam Generators in Condensing Hods "
  \* Industry Advisory Group 79/04/10 Epp
- 7905190226 Issues temporary Tach Spec mod re operability of reactor bldg emergency cooling booster pumps
  VOLLMER, R H Assistant Director for Site Analysis 79/04/10 1p
- 7905190247 Submits temporary changes to Tech Specs ra operability of reactor bldg emergency cooling booster pumps
  VOLLMER:R H Assistant Director for Site Analysis 79/04/10 ip
- 7905210082 Forwards Westinghouse responses to NRC 790408 questions re resolution of TMI incident MATTEUN.R Division of Systems Safety 79/04/10. Spp
- 7905210102 Provides ground rules for conducting interviews w/licensee employees during TMI investigation ORIER.B H Region 1, Philadelphia, Office of the Director 77/04/10 2pp
- 7905230065 Assesses RCS behavior in percolating mode before buildup of large amounts of honcondensibles THIESING.J W Industry Advisory Group 79/04/09 ip
- ---7905230049 Suppl 779409 memo re RCS behavior, stating percolation fraquency estimated at 0 5 to 0 5-s
  THIESING, J H Industry Advisory Group 79/04/09 ip
- 7905230080 Forwards mod criteria for USB of steam generators for short & lang-tesm cooldown
  CAPDDANNO.0 R GPU Service Corp 79/04/10 16pp
- 7705230085 Forwards 770410 planning meeting agenda, lists of action items discussed in 770409 technical review meeting & status of plant mods
  STELLOV Division of Operating Reactors, 79/04/10, 22pp
- 7905230094 Agenda for 790410 technical review meeting \* Office of Nuclear Reactor Regulation. 79/04/10 1p
- 7905230094 Submits evaluation of General Public Utils/Burns & Roe design for short— & long-term water solid steam generator operation

  \* Office of Nuclear Reactor Regulation. 79/04/10 7pp
- 7905230097 Notes of 6 PM 790410 technical mgt mmeting # Office of Nuclear Reactor Regulation 79/04/10 2pp.
- 7905230178 Forwards list of action items being carried out by Metropolitan Edison or consultants. Requests prompt notification of progress VOLLMER, R H Assistant Director for Site Analysis
- 7905230278 Forwards NRC lists of licensee's priority ac TELFORD, J T Office of Nuclear Reactor Regulation
- 7905300054 Submits status of "requests for work" to nat have been made since 790408. Forwards documentation of Labs work
  BIXBY, N. N. Commission 79/04/10 2pp
- ---7905300061 Bubmits brief synopses of info furnished b personnel to NRC re TMI accident, SNYDER: A W Bandia Laboratories 79/04/09 3pp
- 7904300123 Assessment of pressurizer level instrumentat TMI-2. BATTERFIELD,R M Electric, Instrumentation & Contr Branch 79/04/11 Spp
- 7703090245 Recommends that Commission host lunch for re Japanese Nuclear Bafety Commission investigating stat activities of TMI-2 events LAFLEUR.J.D Office of International Programs 79/0

- 7905110121 Forwards preliminary primary coolent analysis results for 790411 sample Final results available 790412 MIRAGLIA.F J Program Support Branch 79/04/11 2pp
- 7905110136 Forwards update on 790410 advisory rept re condenser integrity & containment isolation DAVIS.D & Systematic Evaluation Programs Branch 79/04/11
- 7905110328 Assesses impact of TMI incident on existing emergency control ctr bypass programs Analysis & reporting expected to slip due to diversion of key staff BECKNER.W D Division of Reactor Safety Research 79/04/11 1p
- 790514003B Forwards LER.IE insp rept & IE circular re Zion experience w/pressurizer level instruments W/o and AYCOCK.K Office of Nuclear Reactor Regulation 79/04/11 1p
- 7705160140 Forwards alternative drafts of policy statement for TMI accident review AHEARNE, J.F. Commission 79/04/11 25pp
- 7905190094 Discusses inquiry re decrease in reactor bldg negative pressure
  REPPLER.J.O. Region 3. Chicago, Office of the Director 79/04/11
- 7905190169 Submits criteria for use of steam generator for short- & long-term cooldown HERBEIN, J G Metropolitan Edison Co 79/04/11 ip
- 7905190172 Discusses acceptability of sys criteria for use of stem generators for short- & long-term cooldown Acceptable but for one exception re design flow rate for A&B mods MATTSON.R J Division of Bystems Bafety 79/04/11 2pp
- 7905190229 Responds to NRC 790411 itm & discusses criteria for use of steam generator for short- & long-term cooldown HERBEIN.J G Metropolitam Edison Co 79/04/11 ip
- 7905210076 Discusses reduction of reactor pressure for gas removal Pressure gauge w/most conservative reading should be used \* Babcock & Milcox Co 79/04/11 lp
- 7905210108 Evaluate TMI personnel desimetry Ability to assess deses to personnel is adequate SLOBODIEN, M J Region 1, Philadelphia, Office of the Director 79/04/11 4pp
- 7905210110 Requests daily written summary statement re public whole body counting SMITH.O H Office of Inspection & Enforcement 79/04/11 tp
- 7905210112 Requires revised schedule to include visit to NRC trailer at TMI observation ctr after each daily briefing SMITH.0 H Office of Inspection & Enforcement 79/04/11 ip
- 79052:01:17 Items presented at 7904:1 health physics planning meeting Correction factors not used for results of indine air samples collected on charcoal cartridges

  # Office of Inspection & Enforcement 79/04/11 ip
- 7905220442 Submits marked-up draft SER on HASH-1400 relevancy to THI CUNNINGHAM, M Office of Nuclear Regulatory Research 79/04/11
- 7905230026 Discusses installation of backup deep-bed filter for containment purge RODDERS, & Industry Advisory Group, 79/04/11 App
- 7905230109 Lists current or planned plant mods & status of Oft of Nuclear Reactor Regulation technical review group review NOVAK.T M Division of Bystems Safety. 79/04/11 3pp
- 7905230114 Submits power conversion sys results from Savannah River. VOLLHER.R H Assistant Director for Site Analysis 79/04/11. ip
- 7905230220 Agenda for TMI tour on 790411-12, OILINEKY, V., KENNEDY, R. T. Commission 79/04/11 ip
- 7905230476 Status re lesk from vent header & potential problem w/access hole to make up tank LAMPOSKI.8 ACRS - Advisory Committee on Reactor Befeguards 79/04/11. ip.

- --7905230480 Tentative qualification of makeup tank sys up to My vij notes LAHROSKI,S ACRS - Advisory Committee on Reactor Safaguards 79/04/12 1g
- 7903230486 List of RELAP-4 TMI natural convection simulations which have been performed Plot & add1 info available FISCHERS . BEHLINGS B 60 & 0, Inc 79/04/11 2pp
- 7903300232 Notification of 790423-25 meeting w/ANS in Chicago H. to discuss TMI-2 effort Requests NRC participation BUDENHOLRER.R Illinois Institute of Technology 79/04/11 Lp
- 7905090228 Forwards kists of NRC regulations & Reg Guides classified Category "A" & "B"
  ARLOTTO, G A Division of Engineering Standards 79/04/12 1099
- 7905090241 Forwards notice of extension of public comment period for NURGE-0396
  RYAN.R 0 Office of State Programs 79/04/12 1b
- --7905090244 Notice of extension of comment period re "Planning Basis Development of State & Local Govt Radiological Emergency Response Plans in Support of LWR Power Plants." NUREG-0398 RYAN,R G Office of State Programs 79/04/11 2pp
- 7905090253 Agenda of conference to be held 790412 in PA concerning health impact of TMI incident + Commission 79/04/12 2pp
- 7905100384 Summary of 790411 meeting w/Westinghouse in Bathasds: ND 11 corrective actions for its PWR plants: as result of TMI-2 incident ROSE, D.F. Division of Project Management 79/04/12 6pp
- 7905t10119 Forwards primary coolant sample analysis info developed by S Bland & F Kantor MIRAOLIA:F J Program Support Branch 79/04/12 App
- 7905110135 Forwards add1 detail on 790411 headquarters advisory repl re-specific valve designation for containment isolation penetrations DAVES, D.K. Systematic Evaluation Programs Branch 79/04/12
- 7905ti013B Forwards preliminary data re-primary coolant sample at Thi taken on 790410
  MIRAGLIA:F J Office of Nuclear Reactor Regulation 79/04/12 2;
- 7905110233 Questions & answers to questions posed by 8 Werbe,08 feat # Commission, 79/04/12 16pp
- 7905110295 Submits advisory rept on boration & criticality aspects of cooldown from points A to C.
  DAVIS.D Office of Nuclear Reactor Regulation 79/04/12 35pp
- 7903110322 Forwards info received from Ofc of Nuclear Reactor Regulation team at facility re cooldown MIRAGLIA:F J Office of Nuclear Reactor Regulation 79/04/12
- 7905140134 Handwritten notes of 790412 meeting w/PA State Health Dijt GOLDSMITH, R Office of Standards Development 79/04/12 7pp
- 7905160001 Requests notification of possible meeting date between D Eisenhut of NRC & H Uchida of Japanese Nuclear Safety Commission LAFLEUR: J D Office of International Programs 79/04/12 lp
- --7905160004 Submits preliminary info re 770328 incident Bult coll4\*\* inlet & outlet temps remain at 280 F. LAFLEUR, J D Office of International Programs 79/04/10 2Js
- 7909160003 Forwards FBI communication re TMI incident W/o eatl BRADY.R J Division of Security 79/04/12 1p
- 7905160155 Offers services in maint procedures re parts & manpower to help NRC establish procedures for nuclear power plants.

  MCGULLOUGH: H. Affiliation Unknown 79/04/12 2pp
- 7705170111 Authorizes NRC to ship skid-mounted hoist from Hernischtel Co for use at facility.NRC will be reimbursed reasonable costs ARNOLD.R C GPU Service Corp 77/04/12 ip

- 7905190173 Lists info requirements for in-plant data for inclusion in daily PNO SMITH.0 H Office of Inspection & Enforcement 79/04/12 1p
- 7905190175 Lists requested replacements for IE Region 1 personnel at
- THI-2 site KEIHIG,R R Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 79/04/12 ip
- 7905190177 Guidelines to facilitate NRC info exchange w/DGE & other agencies STOHR, J P Region 1, Philadelphia, Office of the Director 79/04/12 2pp
- 7905190236 Forwards safety analysis rept re proposed transition to natural circulation as requested at NRC 790409 meeting Long-term natural circulation is viable for stability HERBEIN, J O Metropolitan Edison Co 79/04/12 ip
- 7905190243 Agenda of meeting re recovery from incident \* Hetropolitan Edison Co 79/04/12 15pp
- 7905210034 Catalytic, Inc. can provide technical & field support CAPHTON.D L. Region 1, Philadelphia, Office of the Director 79/04/12 ip
- --7705210042 Forwards Insp Plan IP-1 for operating reactors in PA, effective immediately BRUNNER,E J Region 1. Philadelphia, Office of the Director 79704/11. 7pp
- --7905210044 Final version of testimony before Senate Subcommittee on Nuclear Regulation re six main factors causing accident Supporting documentation encl HENDRIE, J M Commission 79/04/10 16pp
- 7905210056 Recommends duty officer program for immediate notification of incidents, effective 790413

  DAVIS.J G Office of Inspection & Enforcement 79/04/12 2pp
- 7905210133 Forwards DDE illustrative matt re releases near plant site STOHR.J P Region 1, Philadelphia, Office of the Director 79/04/12 7pp
- 7905210140 Requests environ info to be gathered & picked up regularly at IE command post re facilitating info exchange w/DOE & other agencies
  8YOHR.JP Region 1, Philadelphia, Office of the Director
  79/04/12 2pp
- 7905210144 Lists Metropolitan Edison Co & contractor exposures by group to 790411 BLOBODIEM Region 1. Philadelphia, Office of the Director 79/04/12 ip
- 7904270088 Summarizes meeting w/Ctr for Disease Control & PA Dept of Health re possible epidemiologic studies
  OOLDSMITH. R. Radiological Health Standards Branch 79/04/19
- 7904270152 Forwards advisory on effect of loss of recombiner operation on hydrogen concentration in containment due to 790413 failure of Atomics Intl recombiner heater assembly MIRAOLIA,F.J Office of Nuclear Reactor Regulation 79/04/13 7pp
- 7904270379 Forwards preliminary evaluations & bases of meltdown analysis for TMI covering core melt penetration, hydrogen generation & potential for explosion MARCHESE, A , LONG, J , CARTER, T Advanced Reactors Branch 79/04/13 ip
- 7904270876 Forwards list of THI related followup actions currently underway or planned in response to LV Cossick 790412 memo MINGOUE, R B Office of Standards Development 79/04/13 2pp
- 7905090250 Discusses how transcript of NRC meetings helo /90506,09,10 & 13 re TMI-2 incident will be made available BICKWIT,L Office of the Ceneral Coursel 79/04/13, App.
- 7905090254 Summary of 790412 meeting w/Busquehanna River Basin Commission to discuss TMI-2. Stated . 5 Ci of I-131 discharged to river described water monitoring program & NRC role rewater quality during TMI-2 cleanup ELSASSER.T C Office of State Programs. 79/04/13, 2pp
- 7905110130 Forwards list of useful electrical, instrumentation & control schematics
  LAINAB, 0 Plant Systems Branch 79/04/13. 5pp.

- 7905110133 Forwards NRC advisory by RO Meyer recommending all incore thermocouples be read in continuous manner w/provisions for rapid retrieval & permanent storage LAINAS.0 Plant Systems Branch 79/04/13 2pp
- 7905110381 Lists Division actions re TMI w/contact person descriptive title of action & estimate completion dates

  \* Office of Nuclear Regulatory Research 79/04/13 4pp
- 7905210040 Lists IE personnel who are on duty at TMI MCGBCAR.J Region i. Philadelphia. Office of the Director 79/04/13 20pt
- 7905210120 Forwards interoffice memos routed to NRC re radioactive sample analysis, alternate method to measure steam generator lavel & modified criteria for use of steam generators for cooldown, DANIEL, J A · GPU Service Corp. 79/04/13 24pp
- 7903210124 Recommends procedures re util effluent monitoring STOHR, J P Region i, Philadelphia, Office of the Director 79/04/13 2pp
- 7905210240 Discusses nondestructive examinations of weld joints Requests resolution of inconsistencies on data sheets & rationale for util tating credit for imap TRIPP,1. Metropolitan Edison Co 79/04/13 2pp
- 7905220439 Summary of 790412 meeting w/Susquehanna River Basin Commission re TMI incident ELBABBER,T C Region 1, Philadelphia, Office of the Director 79/04/13 20p
- 7905230002 Summary of 790413 meating to plan THI-2 strategy \* Office of Nuclear Reactor Regulation 79/04/13 App
- 7905230041 Forwards list of electrical, instrumentation & control schematics W/o enclosure
  LAINAS, C. C. Office of Inspection & Enforcement 79/04/13 1p
- 7908210247 Exposure summary of Metropolitan Edison Co & contractor personnel on 790414
  SLOBODIENM J Region 1. Philadelphia. Office of the Director 79/04/14 10
- 7908230471 Comments on Task 1 qualifications of vent header sys (qualifications of make up tank sys). LAWROSKIN ACRS - Advisory Committee on Reactor Safeguards 79/04/14 1p
- 7905160129 "Preliminary Estimates of Population on Dose & Health Effects"
  BATTIST.L., BUCHANAN, J. CONGEL.F Division of Site Safety & Prelimental Analysis 79/04/15
- 7905190107 Ad hot interagency dose assessment group preliminary estimates of population dose & health effects re THI-2 events
  BATTIST, L. BUCHANAN, J. Environ Protect Standards Branch GUNGEL, F. Division of Site Safety & Environmental Analysis
  79/04/15 60pp
- 7905210018 Forwards TMI/General Public Utils Data Reduction & Mgt Group Status Rept 1. Includes info re temp & environ readings WEISER. J L. GPU Service Corp 79/04/15 9pp
- 7905210189 Agenda of 790415 technical group meeting w/Matropolitan Edison \* Commission 79/04/15 4pp.
- 7905230036 Conceptual design for TMI-2 venting Supercedes previous versions
  DIBALVO,R Office of Nuclear Regulatory Research. 79/04/15 3pp.
- 7905230118 Requests clearance for JT Collins to drive to processing bldg UBLIMER, R H Assistant Director for Bits Analysis 79/04/15 ip
- 7905020468 Forwards preliminary sequence of events for first 20-h following accident on 790228 HERBEIN, J G. Metropolitan Edison Co. 79/04/16, 16pp
- 7905090248 Forwards requested telephone log & states no significant contacts made on 790401.

  ELBASSER.T. Office of State Programs. 79/04/16 5pp

- 7905090255 Forwards request for info re involvement in NRC activities relating to THI during period from 790328-0401 ENGELHARDT, T F Office of the Executive Legal Director 79/04/16
- --7705070260 Request that all personnel engaged in MRC response to TMI accident record their actions on paper OOBSICK.L. V. Office of the Executive Director for Operations 79/04/13 ip
- 7905:1015: Forwards compilation of analysis of 790329 & 0410 primary coolant samples MIRADIA-F J Office of Nuclear Reactor Regulation 79/04/16 5pp
- 7905110330 Summarizes Branch recommendations for add1 operational safety research based on preliminary review of TMI incident BENNETT.O L Research Support Branch 79/04/16 12pp
- 7905160119 Suggests actions in response to ACRS TMI reptimethods should be provided to get direct water level reading in reactor core AMEARNE, J. F. Commission 79/04/19 2pp
- --7905160132 Requests comments on enci J Vellin 790402 ltr re TME incident KENNEDY.R T Commission 79/04/19 1p
- --7905160138 Buggests that ground dose measurements, isotopic composition & time pattern of activity released from plant & number of exposed workers be recorded for later analysis YELLIN, J. Harvard Univ. 79/04/02 19
- --7905160142 Requests chronology of arrival times of federal & state representatives at site.copy of Interagency Radiological Asistance Plan & NRC regulations ra smergency planning KENNEDV.R T Commission 79/04/19 Ip
- 7905160124 Confirms 790405 telcon re willingness to attend TMI related meeting TLUBE, H E London Nuclear Decombamination, Ltd., 79/04/16 ip.
- 7905210228 Yank car lease agreement between Union Tank Car Co & General Public Utils \* OPU Bervice Corp 79/04/16 19pp
- 7905230125 Summarizes NRC comments on acceptability of design criteria for mods to facility electrical power sys Design criteria for two new diesel generators & use of 13 B kV const power source is acceptable STELLD. V. Division of Operating Reactors 79/04/16 2pp
- 7905230128 Requests retention of IM Peters & DL Ebersole as drivers until 790421 STELLO, V Division of Operating Reactors 79/04/16 ip
- 7905230281 Forwards updated status of various proposals for achieving cold shutdown NOVAK.T H Office of Nuclear Reactor Regulation 79/04/16 44pp
- ---7905230287 Provides summary of GA practices associated w/facflity mods reviewed to date.
  OTLRAY.J Guality Assurance Branch. 79/04/14 Spp.
- 7703300100 Forwards inventory of current YMi-2 related actions OC881CK.L U. Office of the Executive Director for Operations 79/04/16 1p.
- --7905300105 Forwards inventory of current THI-2 related actions. GOBSICK.L.V. Office of the Executive Director for Operations 79704714 3pp
- ---7903:300:111 Responds to LV Gossick 7904:2 meno listing current THI related actions SKEArJ.R. Office of International Programs 79/04/13 5pp
- ---7705300118 Details personnel actions re TMI incident BIRD,P.E. Office of Administration, 79/04/13, 2pp
- --7905300186 Forwards info requested in 790412 memo re personnel in Div of Contracts who will review & list all procurement actions resulting from TMI incident.

  HALMAN-E L Division of Contracts 79/04/13 2pp
- --7905300162 Responds to 790413 memo listing gereonnel from Ofc of Administration involved in communications at TMI~2 site HALLACE.J.R Division of Facilities & Operations, 79/04/13

- --7905300169 Responds to 790412 memo listing current div projects se Taj incident BEBAH.W J. Technical Information & Document Control. 79/04/16 499
- 7903100016 Ack receipt of 790413 memo & accompanying proposal ra NRC commend & control center to improve communications sys for dealing wavents similar to THI Improved communication sys will be considered HENDRIE, J M Commission 79/04/17 ip
- ---7905100017 Forwards proposal for NRC command & control center for nuclear reactors & transport of SNM PODOLAK.E M Radiological Health Standards Brench 79/04/13 400
- ---7905100018 Proposes study of feasibility of NRC command & control of for nuclear reactors & transportation of SNM PODOLAK.E M Radiological Health Standards Branch. 76/02/17 Spp.
- --7905100022 Forwards 790329 & 790405 suggestions by E Podolst re computer controlled communications link & legislative authority to prosecute for felonies Requests 60-day review period COBB.t. I Office of I&E. Executive Officer for Management & Amalysis 79/04/16 ip
- --7905100034 Suggests that NRC bolster enforcement sys by sseling legislative authority to prosecute individuals who are personally responsible for serious NRC violations PODOLAK,E M Radiological Health Standards Branch 79/04/03
- 7905110265 Discusses Sandia Lab study of coolability of rubbliss core dabris High safety margin exists for cooling TMI core at atmospheric pressure by boiling callular natural convection HRIGHT, R H Experimental Fast Reactor Safety Research Branch 79/04/17 3pp.
- 7905140114 Requests further info re Ofc of Nuclear Reactor Regulation action on THI
  AHEARNE, J. F. Commission. 79/04/17, 1p
- 7705160220 Forwards 770407 ltr from C Russ of AIF re background articles used in attempt to put TMI in perspective BERNERG.R Assistant Director for Materials Safety Branch 77/04/17 1p
- 7905190093 Authorizes NRC to ship breathing air manifolds & 350 (whit ft per minute compressor w/hoses.manifolds & air suit tops NRC will be reimbursed all reasonable expenses ARNOLD.R.C. GPU Bervice Corp. 79/04/17 ip.
- 7905190187 Authorizes shipment of three charcoal filters from THI to Columbus, OH
  ARNOLD, R. C QPU Service Corp 79/04/17 1p.
- 7905210021 Forwards TMI/Oeneral Public Utils Data Reduction Myt Greep BEatus Rept 3 Info includes reactor & reactor bldg temp & pressure 79040E-0416. MEISER, J L. GPU Service Corp 79/04/17 6pp
- 7905210070 Forwards summary rept on gas analyses performed on TMI primary water sample received 790416.
  EMAL, N. A. Allied Chemical Corp. 79/04/17 14pp.
- 7905220453 Describes Task 11 ex-core manitoring of core canditions fave groups of detectors provide info re core conditions
  Discusses neutron sources & location
  BALL, R Special Instrument Group 79/04/17 2pp.
- 7903300420 Requests that Missions pass TMI-related info to MRC official contacts
  LAFLEUR, J D Office of International Programs. 79/04/17. is.
- 7905190089 Discusses sequence of events to be followed if reactor coolant pump 2A fails.Forwards operations support plans.
  ARNOLD, R. C., KEATEN, R. W. OPU Bervice Corp. 79/04/18, 6pp
- 7903210246 Summary of 790418 visit to Susquehanna River Islands,PA-10 take soil & grass samples, No evidence of recent const or activity.

  MCCLINTOCK, R. G. , SLOBODIEN, H Region i, Philadelphia, Office of the Director. 79/04/18 ip.

- 7905300319 Forwards recommendations re handling FOIA requests for documents on TMI-2 Requests comments & concurrences by 790419
  - BICKHIT.L Office of the General Counsel 79/04/18 3pp
- 7903020041 Responds to 790417 memo re need to apply special measures for transportation of radioactive wastes from TMI-2 site for disposal Requests to be kept informed of shipments BURNETT,R F Division of Safeguards 79704/19 ip
- 7905110231 Summary of 790419 meeting w/H Turpolak of HEH re response hat is preparing for Escretary Califano re recent todine releases at TMI & nature of final cleanup efforts ORIMES, B.K. Assistant Director for Engineers & Projects 7904/19 1p
- 7905210027 Forward requested questions re loss of main coolant pump.RHR heat removal sys.loss of air conditioning power & loss of pressuriter vent capability MDRPHY, J. A. Office of Nuclear Regulatory Research 79/04/19 Spp
- 7905210068 Forwards KA Power & Light answers to effectiveness of adding hydrazine to primary sys to scavange oxygen since there is indication of dissolved oxygen in primary coclant MATHEMS, P R Division of Systems Bafety 79/04/19 2pp
- 7903210073 Forwards analysis results of boron measurements from 790411 primary sys sample (non-pressurized)
  TELFORD, T Division of Operating Reactors 79/04/19 5pp
- 7905210293 Review & evaluation of personnel desimetry data from 790328-0405.
  BLOBODIEN: M J Region 1, Philadelphia, Office of the Director 79/04/19 3pp
- 7903210275 Forwards list of people to be interviewed list of procedures to be cartified, list of requested documents & list of addiprocedures in effect on 790328 MARTIN.R Division of Systems Safety, 79/04/19 lipp
- 790323D014 Changes designation of new dissel generator to "grey" to avoid confusion w/Class 1E blye div GRONEBERGER, D. K. QPU Service Corp. 79/04/19. 1p
- 7905230015 Technical support procedures group has developed variation on method to predict pressurizer level from indicated temp Recommends procedure be initiated HALLACE, E. Q OPU Service Corp 79/04/19 1p.
- 7905230265 Discusses analyses of boron measurements from 790411 non-pressurized primary sys sample TELFORD, J T Office of Nuclear Reactor Regulation 79/04/19 5pp
- 7905230445 Concerns re cleanup of auxiliary bldg & containment LAKROBKI.H ACR8 - Advisory Committee on Reactor Safeguards 79/04/19. 1p.
- 7905300437 Discusses current status of safety-related operator action study MILHOAN, J.L. Reactor Bystems Standards Branch 79/04/19 2pp
- ---7905300438 Draft rept, "Bafaty-Related Operator Action."
  BOTT, T. F., HAAB, P. H. Oak Ridge National Laboratory FIN 8-0421
  ORNL/TM-6853 79/04/13, 113pp.
- 7905090210 Responds to LV Obssick 790419 request for record of actions on TMI accident, Bummarizes 790402-0404 discussions rereactor coolant pumps & containment integrity MARINOS.E.C. Reactor Bystems Standards Branch 79/04/20. 1p
- 7903090219 Forwards scopes on Categories A & B reg guides being considered for revision as result of TMI-2 event data E186. A L Division of Engineering Standards 79/04/20. 125pp.
- 7905090231 Summary of 790412 meeting w/PA State Health Dept in Harrisburg, PA re strategy for evaluating health impact of TMI incident GOLDEMITH: Radiological Health Standards Branch 79/04/20
- 7405090237 Responds to 790420 request for names of candidates for TMI internal team to investigate accident Buggests H Collins. R Jaska.W Kerr.B Schwarts RYAN,R.J. Office of Nuclear Regulatory Research 79/04/20. 1#
- 7905110126 Forwards requested info prepared by R Emch & F Akstulewicz showing dose rate from 12-inch RHR pipe containing primary coolant, KIRAQLIA, F J Office of Nuclear Reactor Regulation 79/04/20 3pp.

- 7905:10266 Forwards Bandia Lab rept on calculations of coolability of rubblized TMI core debris WRIGHT.R W Experimental Fast Reactor Safety Research Branch 79/04/20 2pp
- --7905110267 Forwards rept "Cooling of TMI Core Debris " RIVARD.J B Sandia Laboratories 79/04/19 ip
- ---7905110269 "Cooling of TMI Core Debris" \* Sandia Laboratories 79/04/12 6pp
- 7905160079 Suggests improvements in sys of communications for emergency response situations & need for mobile radiation monitoring units available to each ofc Requests rept KENNEDY,R T Commission 79/04/20 ip
- 7905160088 Requests info re TMI including license conditions re flood levels, status of spent fuel pools & whether any addl plants are planned for area
  AHEARNE, J F Commission 79/04/20 ip
- 7905160147 Forwards itr from Logistics Management Institute offering to discuss maint procedures to help NRC establish procedures for nuclear power plants
  AHEARNE, J F Chmmission 79/04/20 Ip
- 7905210055 Updates R Bail's 790417 memo detailing rationals for high counting rate of B-F-3 neutron detacting startup channel BTELLO, V. Division of Operating Reactors 79/04/20 10pp
- 7905210261 Datails synopsis of environ analyses performed since 790418 All results are for 1-131 SMITH.O Office of Inspection & Enforcement 79/04/20 2pp
- 7905210319 Requests addition of JS Creswell, Dr Hunter, DC Kirkpatrick, T Shaub, R Summers, P Bissett to list for IE per Amend 3 to NRC access list dtd 790413 MCDBCAR, J J Region 1, Philadelphia, Office of the Director 79/04/20 2pp
- 7903220428 Notifies that Ofc of Executive Legal Director TMI decuments w/released info must be transmitted to FOIA afficer.per encl Announcement 39
  MONDICS.D Administrative Branch 79/04/20 1p
- --7905220429 Announcement 39 re preservation of records re TMI incident Forwards list of FUIA coordinators FELTON, J M Division of Rules and Records 79/04/12 3pp
- 7903230088 Forwards list of Region I personnel dispatched to site from 790328-0401.

  MARTIN, R Division of Bystems Safety 79/04/20 3pp
- 7905230011 Forwards "Criteria for Loss of Offsite Balance of Plant Electrical Power" CRONENBERGER:D GPU Service Corp 79/04/21 1p
- --7905230012 "Criteria for Loss of Offsite Balance of Plant Electrical Power" # OPU Service Corp 79/04/22 App
- 7905230138 Lists IE personnel to be added to NRC Access List dtd 790413 MCOSCAR, J J. Region i, Philadelphia, Office of the Director 79704/21 ip

- 7905230293 Discusses L Kovach's recommendations re carbon adsorbers in auxiliary bldg Trays should be removed from sys and cleaned of carbon COLLINS.J T Effluent Treatment Systems Branch 79/04/22 ip
- 7905070035 Synopsis of info obtained re operating history of TMI-2
  Info ra inventories of significant fission products expected
  in cora will be collected Plots of decaying inventories
  made where feasible
  NELLIS.D O
  Transportation & Product Standards Branch
  79/04/23
- 7905070216 Comments on Commissioner Ahearne's 790403 "set of thoughts on how we could possibly go about TMI accident review "
  Review must distinguish why & what happened MODRE.R H Office of Management and Program Analysis 79/04/23
- --7905090220 "Testimony of R Moore & L Abramson "
  MUDRE.R , ABRAMSON.L Office of Management and Program Analysis
  78/1/130 16pp
- ---7905090224 Supplemental Testimony of R Hoore & L Abramson in response to ALAB-525 MODRE:R Office of Management and Program Analysis 79/09/16
- 7905110220 Ack receipt of 790413 offer to serve on safety review panel Offer will be considered HENDRIE.J H Commission. 79/04/23 ip
- ---7905110223 Offers to serve an review committees of TM1 HOCEVAR, C J Affiliation Unknown 79/04/13 ip
- 7905110234 Testimony before Subcommittee on Nuclear Regulation of Senate Committee on Environ & Public Horks to TMI-2 Incident DIECKAMP, H. General Public Utilities 79/04/23 21pp
- 7905:10248 Suggests Nuclear Regulatory Research staff members to serve on TME incident investigation LEVINE,S Office of Nuclear Regulatory Research, 79/04/23 Ip
- 7905110312 Handwritten notes re TMI incident for period 790404-0423 CUNNINGHAM,M Probabilistic Analysis Branch 79/04/23 24pp
- 7905110331 Responds to 790406 memo requesting comments re environ qualification & instrumentation to follow course of an accident MILLER, C F Electric, Instrumentation & Control Systems Branch 79/04/23 2pp
- 7903140034 Observations made at meeting of Senate Bubcommittee on Nuclear Regulation Committee on Environ & Public North Concerning TMI Accident
  JOHNSON D. H. Office of the Secretary of the Commission 79/04/23
- ---7905140098 Forwards prepared testimony given at hearing before 790423 Senate Subcommittee on Nuclear Regulation W/o testimony KAMMERER.C Office of Congressional Affairs 79/04/23 29p
- 7905160018 Details actions taten in response to RJ Budmitz 790410 memo to file re vented containment conceptual design at TMI DIBALVO,R Office of Nuclear Regulatory Research 79/04/29 7pp
- 7905160144 Requests info re min requirements for control room manning by licensed reactor operators & advantages & disadvantages of presence of third operator KENNEDY.R.T. Commission 79/04/23 ip
- 7905230009 Forwards Revision 3 of "Reactor Coplent Pressure Control Sys Design Criteria-Makeup Portion." 6td 790420 CRUNEBERGER.D GPU Service Corp 79/04/23 ip
- ---7903230010 Task 68: "Reactor Coolant Pressure Control Bys Design Ctriteria-Makeup Portion:" Revision 3 ZANIS.L., LU.T GPU Service Corp. 77/04/23, 11pp.
- 7903230013 Lists members of newly formed Natural Circulation Initiation Task Force ARNOLD,R C OPU Service Corp 79/04/23 ip.
- 7905230171 Forwards draft of work statement for contract to review federal agency interaction.
  OREHER, E Office of Inspection & Enforcement 79/04/23 4pp
- 7905300424 Requests that THI bullstins & NRC plans for future Info dissemination be forwarded to NRC official contacts. LAFLEUR, J D Office of International Programs 79/04/23. 2pp.

- 7905070005 Forwards H Mazatis' comments on review of Emergency Procedure S MIRAGLIA.F J Office of Nuclear Reactor Regulation 79/04/24 2);
- 7905110218 Telcon summary Describes valve misalignment at THI furiry change of feedwater flow from main to auxiliary sys
  BRYAN,8 Office of Inspection & Enforcement 79704/24 1p
- 7905160131 Forwards rough estimate of initial source term that was potentially available in auxiliary bidg for release to atmosphere
- atmosphere
  BLOND:R Office of Nuclear Regulatory Research 79/04/24 3pp
- 7705190060 Submits evaluation re sys analysis of filling & operation once—through steam generator B water solid

  + Office of Inspection & Enforcement 79/04/24 3pp
- 7703190061 Requests info re site related activities from 770328 to 790331 at 12 01 AM OIBBON.A Region i. Philadelphia. Office of the Director 79704/24 3pp
- 7905230001 Savannah River life support air sys will be used by site personnel ROBISON.J D OPY Service Corp 79/04/24 ip
- 7905230005 Outlines priorities & procedures for waste disposal sqt Organizational chart & list of responsibilities encl RUSCHE.B., ARNOLD.R.C. OPU Service Corp. HERBEIN.J.G. Hetropellist Edison Co. 79704/24
- 7905230006 Forwards revised criteria for use in designing plant admits to use A & B steam generators as high pressure water to water heat exchangers for decay heat removal CAPODANNO, O GPU Service Corp. 79/04/24 2pp
- --7903230007 "TMI-2 Sys Criteria for Use of Steam Generator A for still & Long-Term Gooldown: "Revision 3

  \* QPU Service Corp 79/04/24 11pp
- ---7903230008 "TMT-2 Sys Criteria for Use of Steam Denerator E for Cooldown at High Pressure," Revision 3 \* OPU Service Corp 79/04/24 7pp
- 7905230024 Details reorganization of waste mgt activities RUBCHE.B , HERBEIN.J O , ARNOLD.R C, QPU Bervice Corp. 79/04/24 9pp
- 7905230152 Discusses effluent & process gas monitoring sys & Victorial air monitor STOUDART.P Division of Site Bafety & Environmental Abelysis 79/04/24 2pp
- 7905230172 Informs that main turbine was manually tripped when where was heard in steam line around turbine control valves
  OLSHINSKI, J Division of Systems Safety 79/04/24 1p
- 7905230175 Unexecuted memo of understanding to exchange environ lift! data between NRC, EPA. & HEW. Forwards morning repts for 790423-25 BTELLO, V Division of Operating Reactors COX, C Health, Education & Welfare, Dept of BRETTHAUER, E Environmental Protection Agency 79/04/24 App
- 7905230298 Forwards comments on sys analyses of filling and spenting once-through steam generator 8 water solid Secondary side should be filled slowly to avoid water hammer NOVAK-T.M Office of Nuclear Reactor Regulation 79/04/24 Jpp
- 7905300347 Discusses security assistance for NRC press ctr in Middletoum Borrow Hall Middletown PA BURCH.C.L Division of Security 79/04/24 2pp
- 7905;10215 Questions for Commission 790425 meeting on B&N plants \* Commission 79/04/25 2pp
- 7905110255 Forwards correspondence summarizing evaluation of hydrigits gas in primary coolant sys & containment blidg atmosphere. RIB.L.N. Assistant Director for Advanced Reactor Safety Research 79/04/25 2pp
- --7905:10257 Forwards table summarizing calculation of hydrogen (16 lt several pressure & temp conditions corresponding to systocoldown.pressure reduction & rapid depressurization REBL N Assistant Director for Advanced Reactor Gafety Research. 79/04/23 2pp.
- --7903110238 Presents results of parametric appraisal of hydrojen solubility data base & estimated hydrogen releases at TMI PERSON, L. S Fuel Reprocess. & Recycle Branch 79/04/11 493

- --7905110259 Discusses upper limit estimates of hydrogen formation via tirconium-water reaction b from radiolysis LARKINS, J T Experimental Gas-Cooled Reactor Safety Research Branch 79/04/11 3pp
- --7905110261 Discusses need for thorough review of radiation & physical chemistry of LWR primary coolout Suggest formation of task force & review of SARs & SERs
  WITT,F J Fuel Process Systems Standards Branch 79/04/25 App
- --7905110263 Summarizes info on hydrogen reduction methods RIB.L N Assistant Director for Advanced Reactor Bafety Research 79/04/25 3pp
- 7905110343 Provides preliminary assesment of core damage at TMI Forwards & discusses calculations by NRC & others to determine extent of damage MARING, G P Fuel Behavior Branch 79/04/25 22pp
- --7905110348 Discusses GRASS-SST calculations for TMI to explain release of 20-40% total core inventory of fission gas REST. J Argonne National Laboratory 79/04/16 2pp
- --7905110351 Discusses max steady-state clad temp reached in TMI after voiding Any means of assuring moderate flow of steam should have prevented serious rod damage MARINO.0 P Fuel Behavior Branch 79/04/04 3pp
- ---7905110363 Discusses prelininary calculations for outside limits of possible core damage Believes 25-35% core damage near ctr is upper limit at 1 8 hours transient
  BECKNER Division of Reactor Bafety Research 79/04/06 2pp
- 7905210057 Notifies NRC investigative team is onsite & available for private meetings by appointment MARSCH.R Region 3, Chicago, Office of the Director 79/04/25
- 7905230189 Recommends actions to be taken in case of work delays due to conflict of std operating procedures MULLEARY,T Metropolitan Edison Co 79/04/25 2pp
- 7903230194 Summary of 790425 meeting w/DOE re future support of NRC operations at site GRIER, B H Region 1, Philadelphia, Office of the Director 79/04/25 ip
- 7705300098 Forwards list of communications equipment sent to TMI that cannot be properly accounted for Requests identification of custodian of property during tour of duty at Trailer City JONES, J Q Telecommunications Branch 79/04/25 3pp
- 7908090240 In response to 790419 memo.forwards assessment of impact of TMI-2 on ofc resources RYAN.R G Office of State Programs 79/04/26 9pp
- 7905110275 Documents supply of emergency instrumentation at TMI site to collect air samples & measure radioactivity
  SWANDERO,F. Environmental Effects Research Branch 79/04/26
- 7905110304 Forwards proposed mods on suppls to LV Oossick 790420 memore actions re TMI DAVIDSON,E Office of Nuclear Regulatory Research 79/04/26 8pp
- 7905140035 Discusses 790330-0408 actions while part of NRC team at TMI Duties involved review of handling of accident & radwaste & gathering of info re plant sys status from logs & personnel BELL.M J Assistant Director for Waste Management (Pre 790501) 79/04/26 2pp
- 7905160028 Forwards record of actions involving NMSS staff which are not logged in Incident Response Ctr BROWN,R 8 Office of Nuclear Material Safety & Bafeguards 79/04/26, ip
- ---7905160029 Comments on rept on hydrogen solubility database & estimated hydrogen releases at TMI PERSON.L 8, Fuel Reprocess & Recycle Branch 79/04/11, 3pp
- --7905160036 Discusses actions of group working on radwaste sys at TMI Licensee procedures for handling radioactive wastes generated by accident are under review. BELL,M.J Low Level Waste Branch (Pre 790501) 79/05/10 ip
- 7905230202 Rept of activities on 790329 at site, initial assignment CDLLING, D. M. Region 2. Atlanta, Office of the Director 79/04/26

- 7905300108 Responds to questions of C Kepford re radiation releases at TMI No info substantiating claim of 0.5 millirems/hour 30 miles upuind from TMI TLDs have been limited, but calibr sensitivity to beta radiation SMITH.0 M Region 1, Philadelphia, Office of the Director 79/04/26 20m
- 7905110273 Summariies Branch actions associated w/TMI accident SOLBERG, D E Systems Performance Branch 79/04/27 ip
- 7905220412 Discusses health physics coverage for transition to natural circulation both offsite & onsite SNIEZEK, J H Office of Inspection & Enforcement 79/04/27 1p
- 7905210308 Recommends procedure for badging NRC employees SMITH.0 Office of Inspection & Enforcement 79/04/28 3pp
- 7905220450 Provides data re sys/component & instrument aperability status
  MILBER: M Office of Inspection & Enforcement 79/04/28 3pp
- 7905210273 Forwards Revision 1 of procedure for badging NRC employees SMITH 0 H Region i. Philadelphia. Office of the Director 79/04/29 4pp
- 7905230516 Forwards liquid discharge data for 790410-28 KINNEY.W Office of Inspection & Enforcement 79/04/29 Spp
- 7903230523 Forwards info re sys/component operability status GRIMES,B Assistant Director for Engineers & Projects 79/04/27 10pp
- 7905110279 "Generic Considerations of TMI-2 Incident "

  \* Office of Nuclear Reactor Regulation 79/04/30 Spg
- 7905110319 Input for items needed for requalification of TMI Discusses decontamination.insp of primary coolant sys & type of water chemistry
  MUSCARA.J Office of Nuclear Regulatory Research 79/04/30 2pp
- 7905140031 Suggests proposed Westinghouse decay heat removal sys design be modified to better prevent sys leakage Flanged connections should be welded & sealed pumps should be used \* Office of Nuclear Reactor Regulation, 79/04/30 Spp
- 7909160008 Summary of reactor decommissioning study \* Commission 79/04/30 App
- 7905210299 Transition of IE in-house health effort to normal regulatory position BMITH.0 H Office of Inspection & Enforcement 79/04/30 2pp
- 7909230103 Chart of review committee responsibilities \* GPU Service Corp 79/04/30 ip
- 7905230527 Forwards results of analysis of addi liquid discharge data PERROTYI, D Science Applications, Inc 79/04/30 15pp
- 7705070243 Informs that Joint Chiefs of Staff assigned nickname "Ivory Purpose" to operations in support of TMI incident OBSICK, V Office of the Executive Director for Operations. 77/05/01 in
- 7905090337 Forwards "Preliminary Licensing Rept for Westinghouse Decay Heat Removal Bys "Final rept will follow HERBEIN, J G Metropolitan Edison Co. 79/05/01 ip
- --7905090339 "Preliminary Licensing Rept for Westinghouse Decay Heat Removal Bys " \* Westinghouse Electric Corp. WP-TMI-003, 79/05/01 29pp
- 7905190118 Agenda for 790420-0301 planning meetings \* Office of Nuclear Reactor Regulation. 79/05/01 131pp.
- 7705300352 Discusses telcons for 3-day period following TMI-2 incident. RDBART.A.W Region 5. Ban Francisco: Office of the Director
- 7703210013 Discusses plans for epidemiology followup studies on populations exposed during TMI-2 event Contractor will be selected soon.

  KINGQUE,R B. Office of Standards Development. 79/05/02 2pp

- 7905090320 Notifies that submission of final rapt re impingament/ entrainment monitoring program at THI will be delayed to 790715 MELBIERLUF, TROFFER.O J Metropolitan Edjson Co 79/09/03 ip
- 7905140052 Summarizes 790328 telcon from C Heath of Ctr for Disease Control re ctr's role in responding to TMI incident Forwards summary of subsequent telcon w/K Goller RDSERTS: I C Assistant Director for Siting Standards 79/05/03 to
- 7905300053 Details agenda of Natl Conference of State Legislatures. Energy & Resources Committees' 790517 presentation to Congress re THI BCHMARTZ, S A Office of State Progress 79/05/04 Ip
- 7905140267 Forwards analysis results for tample of primary coolent water from THL.

  OVERNAN R F E I du Pont de Nemours & Co , Inc. 79/05/07 3pp
- 7905250479 FR notice of ACRS 790510-12 meeting in Hashington DC to discuss repts on TMI accident CHILK B J Office of the Secretary of the Commission 79/05/07 Ron
- 7908090236 Proposes temporary freeze on any new CP or DL & assessment of ongoing const projects Forwards (raft instructions from BJ Chilk to HR Denton HENDRIE.J.H Commission 79/05/08 3pp
- 7905:10277 "Pictorial Representation of Second Samiscale Relisf Valve Venting Test from TMI Conditions" # Office of Nuclear Regulatory Research 79/05/10 App
- 7905160002 Plant computer print-out for 790328 \* Probabilistic Analysis Branch 79/09/60 16pp
- 7905160003 Miscellaneous notes on various Commission meetings Q1BBON-T, Commission 79/05/10 15pp
- 7705160007 Hiscellaneous notes ra THI CAMPBELL, H. Commission. 79/05/10 34pp
- 7905160042 Various sheets for updating Mar 1978 Yellow Book \* Commission 79/05/10 Spp
- 7905160049 Commission meeting notes for 790328-31 GIRDON, T R Commission 79705/10 71pp
- 7905160059 Various sheets for updating Feb 1978 Oray Book to Feb 1979 • Commission 79/05/10 33pp
- 7905300300 "Population Dose & Health Impact of Accident at TMI Nuclear Station" BATTIST.L., BUCHANAN, J., CONGEL.F Commission NURE9-0558 79/05/10 104pp
- 7905160064 Lists info required re Battelle Columbus Lab analysis CUNNINGHAM, M Probabilistic Analysis Branch 79/05/11 ip
- 7905160139 Discusses definition of TMI-2 event in nomenclature of WASH-1400 CUNNINGHAM Probabilistic Analysis Branch 79/05/11 ip
- 7905160143 Questions natural circulation if main coolant pumps are lost \* Probabilistic Analysis Branch, 79/05/11 ip
- ---7905160149 Draft chronology of 790328 accident until core cooling restored \* Probabilistic Analysis Branch, 79/05/11 3pp.
- 7905300433 Forwards rept "Recriticality Potential of YMI-2 Core " MAROTTA, C. R Transportation Branch 79/05/14. ip
- ---7905300434 "Recriticality Potential of TMI-2 Core."
  MARGTTA.C.R Transportation Branch. 79/05/14 22pp
- 79051900B1 Comments on Special Operation Procedure Z-57.

  \* Office of Nuclear Reactor Regulation 79/05/17 ip.
- 790521Q012 Amends Tech Epecs to permit channel calibr currently required to be performed by 790429 to be extended up to 14 days following cold shutdown.

  VOLLMER: R. H. Assistant Director for Site Analysis. 79/05/17. 19

- 7905210049 Charts organizational responsibility in control rocally, health physics & effluent sys Office of Nuclear Reactor Regulation 79/05/17 to
- 7905210052 Requests assistance in locating documents on THI-2 inclient for onsite reproduction Related menual page & sample documents which may be disclosed encl for guidance ORIER, B H Region I: Philadelphia, Office of the Director 79/05/17 app.
- 7905230157 Discusses radiological consequences of operation of once-through steam generator B in solid mode COLLINS.J T Effluent Treatment Systems Branch 79705/17 4;;
- 790519016B Procedures for environ shift leaders re preparation of daily PNO STORR, J P Office of Inspection & Enforcement 79/05/18 18
- 7905190170 Procedures for environ shift leaders re daily TLD data BYOHR, J P Office of Inspection & Enforcement 79/05/18 (p
- 7905210230 Discusses radiological assessment of operation of once-through steam generator B in solid mode Comments on radioactive mati inventory leakage paths & effluents COLLINS, J T Effluent Treatment Bystems Branch 79/04/22 (4)
- 7908210276 Discusses restrictions on use of masks w/certridges have decontamination of auxiliary/fuel bldg # Office of Inspection & Enforcement 79/05/18 Ip
- 7905210284 Requests info re incident investigation ORIER, B H Region 1, Philadelphia, Office of the Director 79/05/18 5pp
- 7905230130 Notifies of amend to Tech Spec 4 3 3 4,adding 14 days to 790429 deadline for performance of channel calibr VOLLMER, R K Assistant Director for Site Analysis 79/05/10 L)
- 7905210305 Results of analysis of Ag reolite cartridges from three mobile labs
  MONTGOMERY, D M Region 1, Philadelphia, Office of the Director 79/19/21 1 m
- 7905210314 Recommends establishment of GA staff & delineation of rasponsibilities to ensure supervision re V Stello 790421 memo KELLOGO, P J Office of Inspection & Enforcement. 79/05/21 l)
- 7905210323 Forwards info from Bettis lab & OE re potential for radialysis contributing oxygen to bubble over reactor core Office of Nuclear Reactor Regulation 79/05/21. 7pp
- 7903230018 Forwards procedura production flow chart PORTER, I Metropolitan Edison Co 79/05/21 2pp
- 7905230206 Reading file index for TMI-2 incident
  \* Office of Nuclear Reactor Regulation 79/05/21 3pp
- 7905230212 Requests core coolability review in natural circulation by decay heat removal & review of Natl Lab work summary ROSS:D F. Assistant Director for Reactor Safety. 79/05/21 | |
- 7905220445 Forwards background matl on NRC actions re B&W reacters since TMI incident & DK Davis to EQ Case memo re establishment of Task Group on Generic Review of Feedwater Transient in B&W-Designed Reactors.
  EYEYMONTT. O Commission 79/03/22 24pp
- Q Inspection reports, IE Bulletins & correspondence
- 7903230385 IE Bulletin 78-07, "Protection Afforded by Air-Line Respirators & Supplied-Air Hoods." \* Region 1, Philadelphia, Office of the Director 78/04/12 3/1
- 7905300122 Forwards proposed IE circular re interconnections of contaminated sys w/syc air sys used as source of breathing air.Circular describes 781004 leak from raduasts sys to breathing air source at Peach Bottom Unit 2.
  ORIES, B. H. Region 1. Philadelphia, Office of the Director 79/01/25. 3pp
- 790501011B Forwards IE Info Notice 79-06, "Stress Analysis of Bafety-Related Piping " GRIER, P. H. Region 1, Philadelphia, Office of the Director 79/03/23, 1p.

- 7705010047 Forwards IE Info Notice 79-08. "Interconnection of Contaminated Sys w/Syc Air Sys Used as Source of Breathing
- ALT " GRIER/B H Region 1, Philadelphia, Office of the Director
- 7905010300 Forwards IE Info Notice 79-09, "Spill of Radioactively Contamination ORIER/B H R Contaminated Resin Region 1, Philadelphia, Office of the Director
- 7905090259 Ack request to close plant in light of TMI events. Actions are being taken to reassess individual situations IE Bulletin 79-03 encl HENDRIE, J H Commission 79/04/02 12pp
- 7905090234 Requested investigation into scope, procedures. & current status of NRR & IE analysis of TMI is complete Task force organized to examine B&W reactors KENNEKE.A Office of Policy Evaluations 79/04/04 2pp
- 7904170040 IE Bulletin 79-09A, "Nuclear Incident at TMI-Buppl " W/ 790405 telegram from JM Hendrie to all B&W licensees \* Office of Inspection & Enforcement 79/04/05 13pp
- 7905230016 Forwards temporary instruction 2595/02, "Insp Requirements to Review B&W Licenses Actions Taken in Response to IE Bulletin 79-05 & 79-034  $\,$ Office of Inspection & Enforcement 79/04/06 Bpg
- 7905190209 Discusses steps to be taken prior to returning TMI-2 to power operation IE bulletins.circulars,& info notices will be properly addressed
- will be properly addressed HERBEIN, J O Metropolitan Edison Co 79/04/10 ip
- 7903:10:87 Forwards IE Bulletin, "Review of Operational Errors & Bys Hisalignments Identified During THI Incident," & draft cover letters
- Office of Inspection & Enforcement 79/04/11 3pp
- 7905110413 Forwards IE Bulletin 79-068, "Review of Operation Errors & Bys Misalignments Identified During TMI Incident " MOSELEY,N C Division of Reactor Operations Inspections 79/04/13
- 7905190215 Discusses schedule for templeting actions required by IE Bulletin 79-03 Bearch of procurement documents to determine use of specified welded pips will be complete by 790831 HERBEIN.J O Metropolitan Edison Co 79/04/13. ip
- 7903210245 Forwards requested revision to development of policies & implementation programs for insp.
  810642 P Region 1: Philadelphia, Office of the Director 8TOHR, J P F 79/04/16 4pp,
- 7905300192 Lists IE reactor operations shift organization, 790416-0423, KEIMIG.R.R. Office of Inspection & Enforcement 79/04/16, 1p.
- 7705210232 Amend 1 to NRC 770413 access list for IE personnel HCDSGRR, J Region 1. Philadelphia, Office of the Director 77704/18. 2pp
- 7908230334 Forwards IE Bulletin 79-06A Revision 1, "Review of Operational Errors & Bys Misalignments Identified During TME Incident," list of licensees & CP holders receiving bulletin & sample information & action-required ltrs ORIER.8 H Region 1, Philadelphia, Office of the Director 79/04/18 1p.
- 7905300063 Forwards proposed outline & draft scope paragraph for TMI investigation rept Requests review.
  ALLENJ Region 1. Philadelphia. Office of the Director. ALLEN:J Re 79/04/20 3pp
- 7905110184 Forwards IE Bulletin 79-058, "Nuclear Incident at TMI." & draft cover ltrs. MGSELEY, N. C. Office of Inspection & Enforcement 79/04/21 Spp.
- ---7905110186 IE Bulletin 79-058, "Nuclear Incident at TMI " W/extract of B&W 790420 communication encl \* Office of Inspection & Enforcement. 79/04/21 Spp
- 7905140047 Suggests IE Bulletin 79-058 be dispatched for action by 790421 to all B&W rectors w/OL & by 790423 to facilities w/CP, Draft ltr to facilities encl.

  MCSELEY,N C. Division of Reactor Operations Inspections 79/04/21,

- --7905149053 Responds to 790418 itr requesting advice on action needed on 790417 oral recommendations Recommendations involve all PWRs & careful study should precede any action GARBON.HW \_ ACRS Advisory Committee on Reactor Safeguards CARBON, M W A
- 7905090214 Forwards PNOs & IE builetins to TMI incident COLLINS:HE Assistant Director for Emergency Preparedness 79/04/23 ip
- --7905090217 Forwards NUREG-0553 6td 790330 & requests comments by 790509 W/o enc1 RYAN:R 0 Office of State Programs 79/04/10
- 7705300070 Submits draft response to 770411 ltr requesting permission to accompany inspectors during insp of nuclear reactor operated by Saxton Nuclear Experimental Corp in Saxton.PA Invitation must be extended by licensee SNYDER.O L. Region 1. Philadelphia. Office of the Director 79/04/26. 3pp
- 7905230326 Summary of 790504 site visit to TMI re plans for monitoring worker radiation exposure
  KNIGHTON: 0 Environmental Evaluation Branch 79/05/15 4pp
- 7905300151 File index 1E 28. \* Office of Inspection & Enforcement 79/05/23 3ap
- R Pariodic operating reports & related correspondence
- 7905190223 Summary paper re B&W results for site & composition of bubble in reactor vessel, in response to NRC 790402 request ROY, D H Babcock & Wilcox Co 79/04/02 5pp
- 7905190194 Recommends lag books for control room personnel as opposed to procedures outlined in L Gassick 790404 memo STELLO,V. Division of Operating Reactors MATTBON,R J Division of Systems Safety ORIER, B. H. Region 1, Philadelphia, Office of the Director 79/04/05 2pp Division
- 7905220461 Plant status info BRUNNER,E J Region i, Philadelphia, Office of the Director 79/04/07 3pp
- 7904260272 Forwards summary of preliminary estimates of radioactivity releases as of 790407 As of midday 790409, population dose due to noble gases is estimated to be 2400 man-rems w/max individual exposure at less than 100 man-rems BARRETT.L H Environmental Evaluation Branch 79/04/12 20pp
- 7905210032 Rept update of environ monitoring data for 790409 to 790412 \* Energy, Dept of 79/04/12 4pp
- 7903160135 Forwards monthly operating report for Mar 1979 HERBEIN, J 0 Metropolitan Editor Co. 79/04/18 11
- ---7905160380 Monthly operating rept for Mar 1979. LEGEL, R. A Metropolitan Edison Co 79/04/18
- 7903020135 Forwards "Decay Heat Removal During Very Small Break LOCA for 88M 205 Fuel Assembly PWR:" prepared for TVA MCKINLEY: J C. ACRS Advisory Committee on Reactor Safeguards 79/04/20 1p.
- --7905020159 "Decay Heat Removal During Very Small Break LOGA for B&H 205 Fuel Assembly PHR:" preliminary copy Missisted Communication of Technology Communication (Communication)

- 7905210060 Requests assistance in responding to questions proposed at meeting w/Commission for Advancement for Public Interest Organizations
  HIGGENBOTHAM, L. Division of Fuel Facility & Materials Safety
  - 79/04/25
- ---7905210062 Describes testing conditions used by NBS for thermaluminescence dosimeters to radiation per NRC request Blant TMI waste shipment log sncl EISENHOWER, E. H. Commerce, Dept of 79/04/20 ip
- 7905030338 Forwards monthly operating rept for Mar 1979 W/o enc) TROFFER.Q J Metropolitan Edison Co 79/04/27 1p
- 7705080521 Forwards "Environ Operating Rept 1978," "Hydraulic Survey, June 1978," & "Monitoring of Cooling Tower Operation Effacts on Vegetation in Vicinity of THI, 1978 "
  MERBEIN.J O Metropolitan Edison Co 79705/01 2pp
- -7905080526 "Environ Operating Rept 1978 "

  \* Metropolitan Edison Co 79704/30 18ap
- --7905080528 "Hydraulic Survey. June 1978 "
  \* Metropolitan Edison Co 78/08/31
- --7905080531 "Monitoring of Cooling Tower Operational Effects on Vegetation in Vicinity of TMI-2, 1978 " \* Metropolitan Edison Co 78/12/31 4ipp
- S Reportable occurrences, LERs & related correspondence
- 7905090251 LER 78-029/03L-D on 780415 ventilation damper 8-4098 did not close as required upon receipt of high chlorine signal Caused by improperly adjusted damper linkage Metropolitan Edison Co 78/08/10 ip
- 7705160150 Info re emergency situation & investigation LAFLEUR.J D Office of International Programs 7970 79/03/28 3pp
- 7905110203 Board notification Seabrook refueling water storage tank design deficiency SCINTO, J Hearings Division 79/03/29 30pp
- 7905160093 Provides preliminary unclassified info re incident LAFLEUR. J D Office of International Programs 79/03/29
- 7905160156 Suppl info re TMI emergency situation for dispatch abroad LAFLEUR, J D Office of International Programs 79/03/29 4pp
- 7905160196 Provides details of plant & environ status as of 790330 Unit 2 continuing to remove decay heat through A-loop steam generator using one reactor
  LAFLEUR, J D Office of International Programs 79/03/30 6pp.
- 7905160153 Provides preliminary info re plant & environ status as of 790330 Gaseous radioactivity from primary coolant sys letdown has been contained in waste gas decay tanks LAFLEUR. J D Office of International Programs 79/03/31 4pp
- 7905160165 Provides details of plant & environ status as of 790331 for dispatch abroad LAFLEUR.J D Office of International Programs 79/03/31 5pp.
- 7903160012 Preliminary plant status as of 790331 No change in method of cooling since last rept
  LAFLEUR: J D Office of International Programs 79/04/01 4pp
- 79051602:1 Summary of info re nuclear incident as of 7 AM 79040: Describes plant & environ status LAFLEUR, J D. Office of International Programs 79/04/01 5pp
- 7905160011 Preliminary info re plant status as of 790402 Measurements indicate vol of gases within bubble significantly reduced LAFLEUR, J. D. Office of International Programs 79/04/02 App
- 7905160010 Preliminary info re plant status as of 790403 Reactor pressure remains at 1,000 pei w/bulk cord & coolant temp at 280 F. LAFLEUR, J. D. Office of International Programs 79/04/03 2pp.
- 7905160178 Summary of info re nuclear incident as of 790403 Reactor pressure remains near 1.000 psi w/hulk core codiant inlet & autlet temperatures at 280 F
  LAFLEUR, J. D. Office of International Programs 79/04/03 Gpp

hill less

- 7905300085 Discusses release of preliminary notices on TMI-2 & staffing of executive mgt team of NRC operations ctr ODSSICK.L V Office of the Executive Director for Operations 79/04/03 3pp
- 7905300089 Forwards results of preliminary radiological impact analysis of TMI incident GGSSICK, L V Office of the Executive Director for Operations 12pp
- 7905160055 Summary of preliminary into re nuclear incident as of 790404 Cooling path to remove core decay heat continues to be through A-loop steam generator

  LAFLEUR, J. D. Office of International Programs 79/04/04 2pp
- 7905160214 Summary of info re nuclear incident as of 7 AM 790404 Describes plant & environ status LAFLEUR, J D Office of International Programs 79/04/04 3pp
- 7905300096 Discusses possible determination of extraordinary nuclear occurrence at TMI-2
  KENNEDY.R T Commission 79/04/04 1p
- 7905160009 Preliminary info re plant status Containment atmosphere measurements indicate about 2% hydrogen LAFLEUR, J D Office of International Programs 79/04/05 4pp
- 7905160181 Provides details of plant & environ status LAFLEUR, J D Office of International Programs 79/04/05 4pp
- 7905140055 Forwards excerpts of LERs re feedwater related & other transients at DAW facilities other than TMI Related correspondence enci ORNSTEIN, H Office of the Executive Director for Operations 797/04/06 18pp
- -7905140067 PMD-79-91 vapor binding of shutdown cooling sys purp co 790314 Buction restoredino radioactive mati released to environ
  KILINGER, Q. NOLAN, F. BRYAN, S.E. Office of Inspection &
  Enforcement 79/04/23 ip
- 7905160066 Summary of info re incident as of 790406 Reactor continuit stable shutdown Will forward IE Bullatin 79-05A LAFLEUR. J D Office of International Programs 79/04/86 2pp
- 7905160188 Provides details of plant status as of 790406 Reactor continues stable shutdown heat removal conling at 1,075 ps., using one primary coolant pump & one steam generator LAFLEUR, J D Office of International Programs 79/04/06 3pp
- 7905140110 Provides preliminary chronology of NRC actions in confict.
  w/THI Forwards description of events, generic considerations,
  summary of surveys, health effects & insp.
  OOSSICKLL V Office of the Executive Director for Operations 79/04/09 52 p p
- 7905140121 Preliminary chronology of TMI incident on 790320 ( subsequent status through 790407 \* Commission 79/04/09 App
- 7905160195 Provides details of plant status as of 790410 including evacuation & environ status

  LAFLEUR. J D Office of International Programs 79/04/10 3pp
- 7905110200 PNO-79-78 facility shutdown on 790410 due to festivity regulating valve malfunction which caused reactor to trip 44 result of low steam generator water level, NOLAN,F, BRYAN,S E Office of Inspection & Enforcement 79/04/11
- 7905190231 Discusses schedule for repts re 790328 event b folicy up Because of incident & corrective actions involved, details will be delayed until 790515 HERBEIN.J Q Hetropolitan Edison Co. 79/04/11, 1p
- 7908300407 Reviews TMI-2 incident, Requests that TMI-related into be sent to NRC contracts in host goves
  LAFLEUR. J D Office of International Programs. 79/04/11 259
- 7905300187 Discusses IE responsibility for drafting daily stellalter; notice re TMI status Suggests procedures be established to ensure necessary info is available for input ORIER. H. Region i, Philadelphia, Office of the Director 79/04/14 ip

- 7905090227 "LER Output on events at TMI-1 % TMI-2 from 1969 to Present " \* Health, Education & Welfare, Dept of 79/04/18 83pp
- 7905100388 Forwards PNO-79-67X % Y related to TMI-2 incident W/o anci WASALLO.D B Assistant Director for Light Water Reactors 79/04/20 1p
- --7705100389 Forwards PNO-79-67U.V & W related to TMI-2 incident W/o enci VABSALO.D B Assistant Director for Light Water Reactors 77/04/17 ip
- ---7905100390 Forwards PNO-79-67G, R. 8 & T related to TMI-2 incident W/g encl VASEALLO, D B Assistant Director for Light Water Reactors 79/04/13
- ---7905100392 Suppl 790403 memo re submittal of info on TMI-2 Forwards PNO-671, J.K. L.M.N & P M/o enci VASSALLO, D B Assistant Director for Light Water Reactors 79/04/09 1p
- --7905100395 Recommends available info re TMI-2 incident be provided to Boards considering cases involving 86W reactors VARBALLO, D B Assistant Director for Light Water Reactors 79704403 2pp
- 7904300484 Forwards PNO-79-47AE ENGELKEN,R H Region 5, Ban Francisco, Office of the Director 79/04/24 1p
- 7905020260 PNO-79-67A0 summary of info re nuclear incident as of 790426 Describes plant status & environ status Highest incore temp reading is 311 F PAULUSIR C. TROMPSON.D Office of Inspection & Enforcement 79/04/26 & 2pp
- 7909040391 Forwards PND-79-67AC

  GEIDLE W C Region 4. Dellas, Reactor Construction & Engineering

  Support Branch 79/04/26 ip
- --7905040406 PNO-79-67AE summary of info re nuclear incident as of 790424 Describes plant & environ status \* Office of Inspection & Enforcement 79/04/24 Spp
- 7905040276 PND-77-67AH, summary of info re nuclear incident as of 770427 Describes plant & anviron status Highest incore temp 310 F Offsite radiation consistent w/background levels PAULUS, R C , THOMPSON, D Office of Inspection & Enforcement 79/04/27 2pp.
- 7903300410 Requests info re TMI followup be forwarded to official NRC contacts in host governments & visiting senior UB officials LAFLEUR, J D Office of International Programs 79/04/27 2pp
- 7903300413 Requests info re TMI natural circulation cooling be forwarded to official NRC contacts in host governments & visiting senior US officials

  LAFLEUR: J D Office of International Programs 79/04/28 2pp
- 7708040262 PNO-79-67AJ, summary of info re nuclear incident as of 790429, Describes plant & environ status Highest incore temp 320 f Offsite radiation consistent w/background levels CHAPELL, D Office of Inspection & Enforcement 79/04/29 2pp
- 7905040359 Forwards PNO-79-67AI.AJ & AK per NRC 790401 ltr transmitting IE Bulletin 79-05 ENGELKEN.R.H Region 5. Ban Francisco. Office of the Director 79/04/30 tp
- --7905040360 PNO-79-67AI summary of info re nuclear incident as of 790428 Describes plant % environ status 4 Office of Inspection & Enforcement 79/04/28 2pp
- --7905040365 PNO-79-67AK, summary of info re nuclear incident as of 790429 Describes plant & environ status \* Office of Inspection & Enforcement 79/04/30 2pp
- 7905040358 PNO-79-67AL: summary of info re nuclear incident as of 790501 Describes plant & environ status # Office of Inspection & Enforcement 79/05/01 3pp

- 7905140253 PND-79-67AM summary of info re nuclear incident as of 790507 Describes operational & environ status Environ radiation levels consistent w/natural background PAULUS, C , THOMPSON, D Office of Inspection & Enforcement 79/05/07 2pp
- 7905110251 Lists chronology of personnel-related events
  # Office of Nuclear Reactor Regulation 79/05/10 ip
- 7905230198 PNO-79-67AN summary of info re nuclear incident as of 790514 Describes operational & environ status highest incore temp 308 F, pressure maintained at 650 psi Environ radiation consistent w/background levels

   Office of Inspection & Enforcement 79/05/14 2pp
- 7903300250 "LER Output on Events of TMI-2 from 1969 to Present" output forted by facility & event date

  \* Office of Inspection & Enforcement 79/05/18 20pp
- T Hearing transcripts on non-antitrust matters
- 7905020024 Transcript of 790405 update briefing on TMI-2 Pp 1-217 HENDRIE, J M , GILINSKY, V , KENNEDY, R T Commission 79/04/05
- 7905190251 PA Governor D Thornburgh's press conference on 790409 re TMI incident THORNBURGH.D Pennsylvania, State of 79/04/09 13pp
- 7905020046 Transcript of 790417 joint meeting u/ACRS in Washington,DC Pg 1-22 HENDRIE,J M , OILINSKY,V , KENNEDY,R T Commission 79/04/17
- 7905020163 Transcripts of 790417 press conference on TMI in Middletawn. PA Pp 1-20 FOUCHARD, J Office of Public Affairs DENTON, H R Office of Nuclear Reactor Regulation 79/04/17 20pp
- 7905210069 Agenda for 790417 planning meeting re "Top Priorities" list action itmes from 790416 technical review meeting 790417 tasks lists % review schedules \* Office of Nuclear Reactor Regulation 79/04/17 14pp
- 7905140539 FOIA request for transcript of NRC deliberations occurring in aftermath of Harrisburg incident PERDUE, H D Eastern Washington Univ 79/04/18 1p
- 7903080125 Transcript of 790420 briefing in Washington.DC on procedures for qualifying reactor operators Pp 1-90 OILINSKY.V . KENNEDY.R T , BRADFORD.P A Commission 79/04/20 200pp
- 7905030055 Transcript of 790423 open meeting in Washington.DC for briefing on principal factors re current status of operating plants Pp 1-84
  HENDRIE, J M , GILINGKY, V , KENNEDY, R T Commission 79/04/23
- 7905140065 Statement of WO Kuhns, Chairman of Ogneral Public Utils Corp. before Subcommittee on Nuclear Regulation of Senate Committee on Environ & Public Works KUHNS, W O General Public Utilities 79/04/23 14pp
- --7905140072 Statement of M Bancroft.Public Citizen Litigation Group before Sanate Subcommittee on Nuclear Regulation dtd 790423 BANCROFT.M Public Citizen Litigation Group 79/04/23 14pp
- --7905140090 Statement by JT Conway, President, American Nuclear Energy Council before Subcommittee on Nuclear Regulation, Senate Committee on Environ & Public Works CONMAY, J T American Nuclear Energy Council 79/04/23 13pp
- --7903140094 Statement of AZ Roisman.NRDC Atty.before Subcommittee on Nuclear Regulation of Senate Public Works Committee RDISMAN.A Z Natural Resources Defense Council 79/04/23 12pp
- 7705140092 Statement of D Thornburgh, Governor of PA, before Senate Subcommittee on Nuclear Regulation THORNSUROH, D Pennsylvania, State of 79/04/23 9pp
- 7905020128 Transcript of 790424 press briefing on TMI in Hiddletown PA
  Pp 1-26
  WISHER, C Region 4, Dallae, Office of the Director STELLO, V
  Office of Nuclear Reactor Regulation. VOLLMER, R H
  Director for Site Analysis 79/04/24 26pp

- 7905030212 Transcript of 790427 press conference in Hiddlatown.PA Pp 1-25 STELLO.V Division of Operating Reactors 79/04/27 24pp
- 7905030210 Transcript of 790430 Ad Hot Subcommittee on TMI Incident in Washington, DC. Pp 1-360 CKRENT. D., CARBON, M. W., SIESB, C. ACRB - Advisory Committee on Reactor Sateguards 79704/30 361pg.
- 7905100052 Transcript of 790501 Ad Hoc Bubcommittee on THI Incident assting in Washington.DC Pp 361-544 GKRENT.D: CARBON.H W. SIESS.C ACRS - Advisoru Committee on Reactor Bafeguards 79/05/01 183pp
- 7905190233 Transcript of 790503 brisfing on offsite radiation levels at TMI & radiological assistance program Pp 1-67
  HENDRIE, J M . GILINSKY, V . KENNEDY, R. T. Commission 79/05/03
- 7905100054 Transcript of 790507 press brising in Hiddletown.PA STELLO.V Division of Operating Reactors VOLLMER.R H Assistant Director for Site Analysis 79/05/07 30pp
- 7908220459 Forwards transcripts of interviews w/TMI-2 operators at time of incident TROMBRIDGE, O. F. Shaw, Pittman, Potts, & Trowbridge, 79/05/07
- 7905;40537 Response to FDIA request for transcripts of NRC closed meetings re (farrisburg incident dives price list of transcripts available in PDR FELTON, J N Division of Rules and Records 79/05/09 ip
- 7905190235 Transcript of ACRS Ad Hoc Subcommittee 790509 on TMI-2 meeting Pp 1-309 OKRENT D. CARBON, M U. ETHERINGTON, H. ACRS Advisory Committee on Reactor Safeguards 79/05/09 310pp
- 7905190127 Transcript of 790510 public maeting re Pp 1-129 W/copies of presentation transparencies.
  HENDRIE, J M , GILINSKY, V , KENNEDY, R T. Commission 79/08/10
- 7905220451 Responds to 790514 memo Advises that transcripts of interviews w/TMI-2 operators have been submitted to PDR & Offc of Congressional Affairs.

  CORNELLE & Office of the Executive Director for Operations 79/05/17 ip.
- --7905220455 Forwards OF Trowbridge to E Case 790507 ltr submitting transcript of interviews w/TMI-2 operators Transcripts will be considered in IE investigation of accident MATTSON:R.J. Division of Bystems Barety. 79/05/14 ip
- DOCKET 50-321 EDWIN I. HATCH NUCLEAR PLANT, UNIT 1

  F Security, medical, emergency & fire protection plans
- 7903150089 Responds to 790302 ltr reporting reasons for delays on implementing 10CFR73 55 requirements & describing compensatory measures provided to meet these requirements Heasures are acceptable.

  1890LITO, T.A. Operating Reactors Branch 3, 79/04/18 2pp
- I Financial information
- 7905080497 Forward: "Annual Financial Rept 1978 "
  VARBUEZ.R D. Metropolitan Electric Authority of Georgia 79/05/02
  1p.
- --7905080508 "Annual Financial Rept 1978 "

  Betropolitan Electric Authority of Georgia 78/12/31. 24pp
- 7905070497 Confirms increased liability limit to \$124,000.000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,176,179,180,182,183,184,187,188,189,192,193,194,193,197,197,198,200,201,204,206,207,208,210,212,214,215,&others QUATTROCHHI, J. American Nuclear Insurers 77/05/01 1p
- 7905070582 Confirms increase in liability limit to \$36.000.000 for policies MF-22.26.29, 38.39.44.46.47.49.50.51.52.53.54.55.56.57.58.60.61.64.66.67.68.67.70.71.72.74.76.77.78.79.80.86.67.88.90.71.92.93.94.95 & 96.
- 7905080427 Forwards Amend 10 to Indemnity Agreement B-69 MHITMER, C F. Georgia Power Co 79705/01, 3pp.

- 7905140493 Forwards Amend 11 to Indemnity Agreement H-69 per iOCFRIchanges re increase in liability insurance from \$140 million to \$160 million.effective 790301. Supporting documentation encl SALTZMAN.J Antitrust & Indemnity Group 79/05/01 668
- 7903080430 Forwards Endorsement 49 to NELIA Policy NF-213 FIELDER, J. Harsh & HoLlenon, M & H Nuclear Consultants, Inc. Biv 79/03/03 2pp
- 7905080432 Forwards Endorsement 50 to NELIA Policy NF-215
  FIELDER: J. Harsh & McLenon: M & M Nuclear Consultants, Inc. Div. 79/05/03 2pp
- P Operating license stage documents & correspondence
- 7905070669 Responds to 790319 ltr questioning license amend fee requirement for 781221 application Fees paid are justified MILLER, W O License Fee Management Branch 79/04/05 ip.
- 7905190213 Amends 790322 submittal of Tech Spec changes in support (
  Reload 3 licensing application Class IV amend for encl
  WHITHER, C.F. Georgie Power Co. 79/05/11 32pp.
- 7903170234 Forwards schedule for implementation & resolution of Mark containment long-term program Only vent header deflectors are necessary as major mod for conformance to long-term program acceptance criteria HHITMER.C F Georgia Power Co 79/05/14 4pp
- 7905190059 Forwards proposed amend to Tech Specu re turbine (entre) valve fast closure trip setpoint
  WHITMER.C F Georgia Power Co 79/05/14 5pp
- 7905230047 Forwards Errata & Addenda Sheet 1 to NEDD-24175, "Bupplemental Reload Licensing Submittal for Edwin I Halch Unit 1.Reload 3" HHITMER:C F Georgia Power Co 79/05/16 4pp
- 7903230538 Responds to D Verrelli's request for add1 into releast feedwater notice & sparger GE licensing rept NEDE-21821.414 Mar 1778.provides discussion of causes & proposed solutions to cracking problems in BMRs WHITMER.C.F Georgia Power Co 79/05/16 1p
- 7703300006 Requests change to Tech Spec.App A to OL.modifying Surveillance Requirement 4 9 D due to incorporation of redundant breaker on output of reactor protection sys actor generator sets WHITMER.C F Georgia Power Co 79/05/22 Spp
- Q. Inspection reports, IE Bulletins & correspondence
- 7905010200 Forwards IE Info Notice 79-06, "Stress Analysis of Bafety-Related Piping" O'REILLY, J P Region 2, Atlanta, Office of the Director 79703/23 2pp
- 7905020489 Forwards IE Insp Repts 50-321/79-09 % 50-366/79-11 < 1 790210-0302 No noncompliance noted.

  LENIS.R. C. Region 2. Atlanta. Reactor Operations Nuclear B gas Branch. 79/03/23 2pp.
- ---7905020497 IE Insp Repts 80-321/79-09 & 80-366/79-11 on 790210 (3) noncompliance noted Major areas inspected. Unit 1 plant operations. Unit 2 startup testing. Tach Bagers compliance, reportable occurrences & Unit 2 transient test witnessing RODERG/R F Region 2. Atlanta, Office of the Director BANCE/H C Region 2. Atlanta, Reactor Operations Nuclear Bupport Branch 79/03/23 4pp.
- 7905030312 Forwards IE Info Notice 79-07, "Rupture of Redwell fail) O'REILLY, J. P. Region 2. Atlanta, Office of the Director 79/03/26. 2pp
- 7705010107 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air."

  D'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/28 2pp
- 7905010360 Forwards IE Info Notice 79-09, "Spill of Radioactivate Contaminated Resin" O'REILLY, P. Region 2. Atlanta, Office of the Director 79703/30. Zpp
- 790525009B Requests page 6 of IE Insp Repts 50-321/79-05 & 50-344/N be replaced w/encl corrected page.
  MILLER.J. H Georgia Power Co. 79/04/04 2pp.

- --7905250105 Forwards IE Insp Repts 50-321/79-06 & 50-366/79-07 on 790214-16 No noncompliance noted LEWIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/21 2pp
- --7905250110 IE Insp Repts 90-321/79-06 & 50-366/79-07 on 790214-16 No nancompliance noted Hajor areas inspected plant operations, followup of unresolved items. LERs & test witnessing DANCE, H C Region 2. Atlanta. Reactor Operations Nuclear Support Branch HINCKLEY.D G Region 2. Atlanta, Office of the Director 79/03/21 Spp
- 7905040216 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misslighments Identified During TMI Incident " O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 2pp
- 7905040304 Forwards IE Bulletin 79-07, "Beismic Stress Analysis of Bafety-Related Piping " Licenses action required D'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 ip
- 7905040413 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Mater Power Reactors Identified During TMI Incident "O'REILLY, J P Region 2. Atlanta. Office of the Director 79704/14 ip.
- 7905100244 Responds to IE Bulletin 79-03 No evidence of Youngstown Halding & Engineering seam welded ASME 6A-312 Type 304 stainless steel piping is being used in safety-related sys AGME 5A-398 Type 304 spool is used 6TAFFA.R W Georgia Power Co 79/04/16 ip
- 7903030165 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " Licensee action required O'REILLY, J P. Region 2, Atlanta, Office of the Director 79704/17, 200
- 7905020467 Forwards IE Bulletin 79-06A.Revision i, "Review of Operational Errors & Sys Misslignments Identified During TMI Incident."

  O'REILLY, J P Region 2, Atlanta, Office of the Director 7900418
- 7905290029 Responds to IE Builetin 79~09 Addresses events relevant to BMRs identified during TMI incident Response to Item 11 will be forwarded in 30 days

  MIDNER, M. A. Georgia Power Co. 79/04/25 15pp
- 7905000309 Responds to IE Bulletin 79-04. Review of design records indicates there are no 3.4 or 4-inch diameter Velan swing check valves used at facility BTAFFA.R W Georgia Power Co. 79/05/02 ip
- 7905270035 Forwards revised responses to IE Bulletin 79-08, "Events Relevant to BWRs Identified During TMI Incident " Replaces previous 790425 submittal (mentioned as 790415 in present ltr) Includes response to Item 11 HIDNER, W A Georgia Power Co 79/05/09 16pp.
- & Reportable occurrences, LERs & related correspondence
- 7905140316 Notifies that LERs 50-366/1979-27 & 50-321/1979-16 have been voided They were later determined to be not reportable HANRY. H Georgia Power Co 79/03/13 1p
- 7905010502 LER 50-321/1979-22 has been voided. Rept will be incorporated into LER 79-23 MANRY, M. Georgia Power Co. 79/04/19 ip
- 7905080546 Forwards LER 79-023/03L-0 HANRY.M. Gworgia Power Co 79/04/24 ip.
- --7905080550 LER 79-023/03L-0 on 790410 during steady state operation. "HCPI isolation trip logic A initiated" alarm received, closing inboard isolation valve E41-F002 Caused by high delta temp in HPCI room Sys reset ORECNE.T V Georgia Power Co 79/04/24 2pp
- 7905080473 Forwards LER 79-021/03L-2 MANRY, M. Gaorgia Power Co 79/04/30 ip.
- --7905080479 LER 79-021/O3L-2 on 790320 during steady state power operation, radioactive water observed bubbling from ground near diesel generator bldg. Caused by burned open line. Line closed immediately RDOERB, H. H. Georgia Power Cd. 79/04/30 Bpp.
- 7905080520 Forwards LER 79-025/03L-0. MANRY.M. Georgia Power Co 79/04/30 ip.

- --7905080524 LER 79-025/03L-0 on 790427 during steady state power operation.H202 analyzer pumps were inoperative Caused by incomplete HNP-1-3683 procedure Procedure will be revised by 790701

  BAXLEY.S X Georgia Power Co 79/04/27 ip
- 7703150519 Forwards LER 77-026/03L-0 MANRY-M Georgia Power Co 77/05/07 is
- --7905150525 LER 79-026/03L on 790422 while performing procedure HNP-1-3111; valves 821-F028A & 821-F028B closed too fast Caused by snubber adjustment drift Followup rept of corrective action will be sent NIX,R T Deorgia Power Co 79/05/07 ip
- 7905150543 Forwards LER 79-027/01T-0 MANRY:M Georgia Power Co 79/05/07 ip
- --7905150549 LER 79-027/01T-0 on 790427 initial tests of various Type C low level radiation test containment isolation valves proved unacceptable during local leak rate testing Caused by scratches on valve seat from valve closing on debris OREENE.T V Georgia Power Co 79/05/07 2pp
- 7905300591 Forwards LER 79-024/03L-0 MANRY,M Georgia Pawer Co 79/05/18 1p
- --7903300603 LER 79-024/03L-0 on 790420 both doors of airlock Ri06 were opened simultaneously Gaused by personnel error Glass installed to cover emergency overside pushbuttons of both airlock doors

  GREENE, T V Georgia Power Co 79/05/18 1p
- ---7905300627 Forwards LER 79-028/03L-0 MANRY.M Gagrgia Power Co 79/05/17 1p
- ---7905300638 LER 79-028/03L-0 on 770505 five containment isolation valves did not meet acceptance criteria during initial tests Cause under investigation Corrective maint will be performed to allow satisfactory leakage rate for valves QREENE,T V Georgia Power Co 79/05/17 2pp
- --7905300644 Forwards LER 79-029/03L-0 MANRY,M Georgia Power Co 79/05/17 ip
- --7903300660 LER 79-029/03L-0 on 790505 door interlock defeated & both bldg airlock doors were open at same time Caused by personnel error Personnel reinstructed & engineering design is being reevaluated BAXLEY.5 X Georgia Power Co 79/05/17 ip
- ---7905300664 Forwards LER 79-031/03L-0 MANRY, M Georgia Power Co 79/05/21 1p
- --7903300676 LER 79-031/03L-0 on 790508 main steam line tunnel temp wwitch B21-N0118 opened at 203F Caused by setpoint drift Bwitch recalibr & functionally tested. NIX,R T Georgia Power Co 79/05/21 ip
- --7905300683 Forwards LER 79-033/03L-0 MANRY.M Georgia Power Co 79/05/17 1p
- --7905300688 LER 79-033/03L-0 on 790808 air operware improperly installed Caused by insuffic installation info Maint procedures revised to installation GREENG.T V. Georgia Power Co 79/05/17 2;
- DOCKET 50-322 SHOREHAM NUCLEAR FOWER STATION

  A. Application/construction stage documents & co
- 7905300656 Responds to 790320 memo re policy on meetings to public DENTON:H R Office of Nuclear Reactor Regulat
- --7905300667 Requests NRC views on whether proce NRC & util representatives should be open to BRADFORD, P A Office of Nuclear Reactor Reg
- 7905040316 Summary of 790321 meeting of Mark II Jose,CA re intermediate plant program tasks ANDERSON,C J Containment Systems Branch

- 7905030212 Transcript of 790427 press conference in Middletown.PA Pp 1-25 STELLO.V Division of Operating Reactors 79/04/27 26pp
- 7905030210 Transcript of 790430 Ad Hoc Subcommittee on THI Incident in Hashington, DC Pp 1-360 CKRENT, D . CARBON, M H . BIEBB, C ACRB Advisory Committee on Reactor Bafaguards 79704/30 36ipp
- 7905100052 Transcript of 790301 Ad Hoc Bubcommittee on THI Incident moeting in Mashington. DC Pp 361-544
  CKRENT. D., CARBON. M. W., BIESB.C. ACRS Advisoru Committee on Reactor Safeguards 79703/01 183pp
- 7905190233 Transcript of 790503 briefing on offsite radiation levels at TMT & radiological assistance program Pp 1-67 HENDRIE, J M , QILINSKY, V , MENNEDY, R T Commission 79/05/03 ABoa
- 7905100054 Transcript of 790507 press briefing in Hiddletown PA STELLO, V Division of Operating Reactors VCLLMER, R H Assistant Director for Bits Analysis 79/05/07 30pp
- 7905220459 Forwards transcripts of interviews w/TMI-2 operators at time of incident
  TROMBRIDGE, G. F. Shaw, Pittman, Potts, & Trowbridge 79/05/07
- 7905140537 Response to FOIA request for transcripts of NRC closed mastings re Harrisburg incident Dives price list of transcripts evailable in PDR FELTON.J H Division of Rules and Records 79/05/09 ip.
- 7905190235 Transcript of ACRB Ad Hoc Subcommittee 790509 on THI-2 meeting Po 1-309
  DKRENT, D. CARBON, M W. ETHERINGTON, H. ACRB Advisory Committee on Reactor Safeguarus 79/05/09 310pp
- 7905190127 Transcript of 790510 public meeting rs Pp 1-129 W/copies of presentation transparencies HENDRIE/J M , QILINSKY, V. , KENNEDY, R T Commission 79/05/10 1570.
- 7905220451 Responds to 790514 memo Advises that transcripts of interviews w/TMI-2 operators have been submitted to PDR & Ofc of Congressional Affairs.

  CORNELL,E K. Office of the Executive Director for Operations 79/05/17
- ---7903220455 Forwards OF Trowbridge to E Case 790307 ltr submitting transcript of interviews w/THI-2 operators Transcripts will be considered in IE investigation of accident HATTBON.R J Division of Systems Safety 79/03/14
- DOCKET 30-321 EDWIN | HATCH NUCLEAR PLANT, UNIT 1 F Security, medical, emergency & fire protection plans
- 7903130089 Responds to 790302 itr reporting reasons for delays on implementing 100FR73 55 requirements & describing compensatory measures provided to meet these requirements Measures are acceptable.

  18POLITO, T.A. Operating Reactors Branch 3. 79/04/18. 2pp.
- I. Financial information
- 7705080497 Forwards "Annual Financial Rept 1978 "
  VASQUEZ.R O Metropolitan Electric Authority of Georgia 79/05/02,
  19
- --7905080508 "Annual Financial Rept 1978 "

  \* Metropolitan Electric Authority of Georgia 78/12/91 24pp.
- 7703070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,183,184,187,188,189,192,193,194,195,197,198,200,201,204,206,207,208,210,212,214,215,4 sthers GUATTROCHHI, J. American Nuclear Insurers 77/05/01, ip.
- 7905080427 Forwards Amend 10 to Indemnity Apraement B-69 MHITMER, C. F. Georgia Power Co. 79/05/01. 3pp.

- 7905140493 Forwards Amend 11 to Indemnity Agreement 8-69 per 10(FR14) changes re increase in liability insurance from \$140 million to \$160 million, effective 790501 Supporting documentation encl
  SALTZMAN, J Antitrust & Indemnity Group 79/05/01 6pp
- 7905080430 Forwards Endorsement 49 to NELIA Policy NF-215 FIELDER.J Marsh & McLenon: M & M Nuclear Consultants, Inc. Div 79/05/03 2pp
- 7905080432 Forwards Endorsement 50 to NELIA Policy NF-215 FIELDER.J Harsh & McLenon. M & M Nuclear Consultants. Inc Div 79/03/03 2pp
- P Operating license stage documents & correspondence
- 7905070669 Responds to 790319 ltm quastioning license amend fee requirement for 781221 application Fees paid are justified MILLER. H O License Fee Management Branch 79/04/05 lp
- 7905190213 Amends 790322 submittal of Tech Spec changes in suggest if Reland 3 licensing application Class IV amend fine encl
  WHITMER.C F Georgia Power Co 79/05/11 32pp
- 7905170234 Forwards schedule for implementation & resolution of Milip containment long-term program Only vent header deflectors are necessary as major mod for conformance to long-term program acceptance criteria
  HHITMER.C F Georgia Power Co 79/05/14. App
- 7905190059 Forwards proposed amend to Tech Specs on turbins contrep valve fast closure trip setpoint. WHITMER.C F Georgia Power Co 79/05/14 Spp
- 7905230047 Forwards Errata & Addenda Sheet 1 to NEDD-24175.
  "Supplemental Reload Licensing Submittal for Edwin | Hatch Unit 1:Reload 3 "
  WHITMER.C F Georgia Power Co 79/05/16 4pp.
- 7905230538 Responds to D Verrelli's request for add1 info re and all feedwater notate & sparger OE licensing rept NEDE-21821.die Mar 1978, provides discussion of causes & proposed solutions to cracking problems in BHRs WHITMER.C.F. Georgia Power Co. 79/05/16. ip
- 7705300006 Requests change to Tech Spac.App A to OL-modifying Surveillance Requirement 4 9 D due to incorporation of redundant breaker on output of reactor protection sys motor generator sets WHITMER.C.F. Georgia Power Co. 77/05/22 Spp.
- G. Inspection reports, IE Bulletins & correspondence
- 7903010200 Forwards IE Info Notice 79-06, "Etress Analysis of Bafety-Related Piping."
  O'REJILY, J. P. Region 2, Atlanta, Office of the Director 79/03/23, 2pp
- 7905020489 Forwards IE Insp Repts 50-321/79-09 & 50-366/79-[1 en 790210-0302 No noncompliance noted LEMIS.R.C. Region 2. Atlanta. Reactor Operations Nuclear Bappel Branch 79/03/23 2pp
- ---7905020497 IE Insp Repts 50-321/79-09 & 50-366/79-11 on 790210-0) a noncompliance noted Major areas inspected Unit 1 plant operations. Unit 2 startup testing. Tech Spacs compliance, reportable occurrences & Unit 2 transient test witnessing ROGERS, R F Region 2. Atlanta. Office of the Directer DANCE, H C. Region 2. Atlanta. Reactor Operations Myclass Support Branch 79/03/23 App
- 7905030312 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tante" O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/26 2pp.
- 7905010107 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Bource of Breathing Air."

  O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/03/28 2pp.
- 7905010360 Forwards IE Info Notice 79-09, "Spill of Redicactively Contaminated Resin" O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/03/30 2pp.
- 7905250098 Requests page 6 of IE Insp Repts 50-321/79-06 & 50-344/79 to replaced m/encl corrected page MILLER, J. H. Georgia Power Co. 79/04/04, 2pp.

- --7905250105 Forwards IE Insp Repts 50-321/79-06 & 50-366/79-07 on 790214-16 No noncompliance noted LEMIS.R C Region 2, Atlanta, Reactor Operations Nuclear— Bugport Branch 79/03/21 2pp
- --7905250110 IE Insp Repts 50-321/79-06 & 50-366/79-07 on 790214-16 No noncompliance noted Major areas inspected plant operations, followup of unresolved items. LERs & test witnessing DANCE,H C Region 2, Atlanta, Reactor Operations Nuclear Support Branch HINCKLEY,D Q Region 2, Atlanta, Office of the Director 79/03/21 Spp
- 7905040216 Forwards IE Bulletin 79-06B. "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "O'REILLY JP Region 2, Atlanta, Office of the Director 79/04/14 2pp
- 7905040304 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping " Licensee action required O'REILLY J P Region 2, Atlanta, Office of the Director 79704/14 ip
- 7905040413 Forwards IE Bulletin 79-08, "Evente Relevant to Boiling Mater Power Reactors Identified During TMI Incident " O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 ip
- 7905100244 Responds to IE Bulletin 79-03 No evidence of Youngstown Welding & Enginearing seam welded ASME SA-312 Type 304 stainless steel piping is being used in safety-related sys ASME SA-358 Type 304 spool is used GYAFFA-R W Georgia Power Co 79/04/16 ip
- 7905030165 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " Licensee action required D'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/17 2pp
- 7905020467 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."

  O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/18 200
- 7905290029 Responds to IE Bullstin 79-08 Addresses events relevant to BMRs identified during TMI incident Response to Item 11 will be forwarded in 30 days WIDNER,W A Gaorgia Power Co 79/04/25 15pp
- 7705300309 Responds to IE Bulletin 79-04 Review of design records indicates there are no 3.4 or 4-inch diameter Velan swing check valves used at facility BTAFFAR W Georgia Power Co 79/05/02 ip
- 7905270035 Forwards revised responses to IE Bulletin 79-08. "Events Relevant to BWRs Identified During TMI Incident " Replaces previous 790425 submittal (mentioned as 790415 in present ltr). Includes response to Item 11 MIDNER: H A Georgia Power Co. 79/05/09 16pp
- B. Reportable occurrences: LERs & related correspondence
- 7905140316 Notifies that LERs 50-366/1979-27 & 50-321/1979-16 have been voided They were later determined to be not reportable MANRY.M Georgia Power Go 79/03/13 lp
- 7905010502 LER 50-321/1979-22 has been voided Rept will be incorporated into LER 79-23 MANRY, M Georgia Power Co 79/04/19. ip
- 7905080546 Forwards LER 79-023/03L-0 MANRY: M Georgia Power Co 79/04/24 1p
- --79050B0550 LER 79-023/03L-0 on 790410 during steady state operation, "HCPI isolation trip logic A initiated" alarm received, closing inboard isolation valve E41-F002 Caused by high delta temp in HPCI room, Bys reset.

  OREENE,T V Georgia Power Co 79/04/24 3pp
- 7905080473 Forwards LER 79-021/03L-2 MANRY.H Georgia Power Co 79/04/30 1p.
- --7905080479 LER 79-021/03L-2 on 790320 during steady state power operation radioactive water observed bubbling from ground near diesel generator bldg. Caused by burned open line, Line closed immediately.

  RDGERB.H.H. Georgia Power Co. 79/04/30. Spp.
- 7903080320 Forwards LER 79-025/03L-0, HANRY:M. Georgie Fower Co 79/04/30. ip.

- --7905080524 LER 79-025/03L-O on 790427 during steady state power operation. H202 analyzer pumps were inoperative Caused by incomplete HNP-1-3653 procedure Procedure will be revised by 790701
  BAKLEY, S X Georgia Power Co. 79/04/27 1p
- 7909130519 Forwards LER 79-026/03L-0 MANRY.M Georgia Power Co 79/05/07 ip
- --7905150525 LER 79-026/03L on 790422 while performing procedure HNP-1-3111.valves B21-F02BA & B21-F02BB closed too fast Caused by snubber adjustment drift Followup rept of corrective action will be sent NIX,R T Georgia Power Co 79/05/07 ip
- 7905150543 Forwards LER 79-027/01T-0 MANRY,M Georgia Power Co. 79/05/07 1p
- --7905150549 LER 79-027/01T-0 on 790427 initial tests of various Type C low level radiation test containment isolation valves proved unacceptable during local leak rate testing Caused by scratches on valve seat from valve closing on debris GREENE, T V Georgia Power Co 79/05/07 2pp
- 7905300591 Forwards LER 79-024/03L-0 MANRY,M Georgia Power Co 79/05/18 1p
- --7905300603 LER 79-024/03L-0 on 790420 both doors of airlock R106 were opened simultaneously Caused by personnel error Glass installed to cover emergency overside pushbuttons of both airlock doors

  GREENE.T V Georgia Power Co. 79/05/18 ip
- ---7905300627 Ferwards LER 79-028/03L-0 MANRY,M Georgia Fower Co 79/05/17 1p
- ---7905300638 LER 79-028/03L-0 on 790505 five containment isolation valves did not meet acceptance criteria during initial tests Cause under investigation Corrective maint will be performed to allow satisfactory leakage rate for valves GREENE.T V Georgia Power Co 79/05/17 2pp
- --7903300444 Forwards LER 79-029/03L-0 MANRY, M Georgia Power Co 79/03/17 1
- --7905300660 LER 79-029/03L-0 on 790505 door interlock defeated & both bldg airlock doors were open at same time Caused by personnel error Personnel reinstructed & engineering design is being reevaluated BAXLEY, 8 X Georgia Power Co 79/05/17 is
- --7905300664 Forwards LER 79-031/03L-0 MANRY, M. Georgie Power Co 79/05/21 19
- --7905300676 LER 79-031/03L-0 on 790508 main steam line tunnel temp switch B21-NO118 opened at 203F Caused by setpoint drift Switch recelibr & functionally tested NIX,R.T Georgia Pawer Co. 79/05/21 ip
- --7905300683 Forwards LER 79-033/03L-0. MANRY, M Georgia Power Co 79/05/17. 1p
- --7905300688 LER 79-033/03L-O on 790508 air operators on 2821-F018A & C were improperly installed Caused by insufficient installation info Maint procedures revised to assure proper installation OREENE.TV. Georgia Power Co. 79/05/17. 2p;

DOCKET A. Appl

- 7905300656 Responds to 790320 memo re policy on opening procedural meetings to public DENTON, H R. Office of Nuclear Reactor Regulation, 79/04/04 2pp.
- --7905300667 Requests NRC views on whether procedural meetings between NRC & util representatives should be open to public.

  BRADFORD P A Office of Nuclear Reactor Regulation 79/03/20.
- 7905040316 Summary of 790321 meeting of Hark II owners group in San Jose,CA re intermediate plant program tasks. ANDERSON.C J. Containment Systems Branch, 79/04/13 150pp.

- 7909100298 Summary of 790410 meeting w/Cincinnati Pas & Electric Co. Long Island Lighting Co & Commonwealth Edison Co ra vibratory loads & equipment qualification Presentation math
  - Light Water Reactors Branch 1 79/04/19 15pp PELTIER I A
- 7905230558 Notification of 790515-17 meeting w/Cincinnati Gas & Electric Co.Long Island Lighting Co.Commonwealth Edison Co & GE in Ban Jose, CA to audit NSSS equipment for seismic & other dynamic qualification
  PELTIER: I A Light Water Reactors Branch 1 79/04/23 3pp
- 7905040310 Responds to 790223 ltr Resvaluation of balance of plants & NSSS Seismic Category 1 equipment has begun Outlines plans for resvaluation programs NOVARROLJ P Long Island Lighting Co 79/05/01 3pp
- 7905080500 Forwards list of GE Seismic Category I equipment for seismic qualification review List identifies equipment required for safe shutdown & includes brief list of plant sys noun designators. NOVARRO.JP Long Island Lighting Co 79/05/04 37pp
- 7903300208 Forwards summary of EDS Nuclear Inc resolution/documentation of albow fleribility error which existed in vertions of PISOL piping analysis computer program from Jan-Oct 1969 Review & reanalysis included all work through Bec 1970 PORTER F L EDS Nuclear Inc 79/09/21 9pp
- --7903300263 Forwards EDS Nuclear, Inc list of BURs & piping sys which could have been impacted by deficient computer program GE has no record of reanalysis for Cooper piping sys STEPHENS, P W. General Electric Co., Nuclear Energy Products Div 79/01/24 18pp
- F Security, medical, emergency & fire protection plans
- 7905240941 Requests copy of GAD rept to insufficient state & local emergency evacuation plans & NRC response to plan SHAPIRO.R Cammer & Shapiro 79/04/03 1p
- O Adjudicatory correspondence
- 7905240234 First set of interrogatories & notice to produce, submitted by County of Suffolk. NY to util Certificate of Svc encl LIKE, I Suffolk County, NY 79/03/28 10pp
- 7905080053 Responds to request for info re possible shutdown of facility due to possible design deficiencies caused by computer model design Computer model in question not used for facilities
  HDEFLING.R K. Branch 4 79/04/03 2pp
- 7705250156 Opposes licensing of plant
  OWEN.B Affiliation Unknown 79/04/03 2pp
- 7905250053 Directs recipient to QAD for rept.EMB-78-110 requested in 790403 ltr.ARC response is being prepared & will be provided when available HOEF-LING R.K Branch 4 79/04/13 ip
- 7903130207 Response to Suffolk County's 790328 discovery requests contained in Apps A & B of first set of interrogatories & natice to produce Affidavit of HJ Museler supporting documentation & Certificate of 8vc encl.

  WHITTEMORE.F C Long Island Lighting Co 79/04/17 57pp
- 7905240913 Requests details on allegation that ECCS failed on six different occasions SHAPIRO, R Cammer & Shapiro 79/04/17. ip
- 7905250311 Forwards response to questions from 790420 meeting re-util's first two ests of motions for summery disposition. Eubmits unexecuted third set of summery disposition motions Supporting documentation & affidavits encl WHITTEKORE.F C Hunton & Williams 79/04/27 51pp.
- K Utility Final Safety Analysis Report (FSAR) & amends
- 7905240369 Forwards Amend 32 to license application consisting of Revision 16 to FSAR Affidavit encl WOFFORD, A. H. Long Island Lighting Co 79/05/15 2pp
- --7905240376 Amend 32 to FBAR re containment design Oversized drawings encl. \* Long Island Lighting Co. 79/05/15 450pp
- 7905290210 Certificate of Bvc of Revision 16 to FSAR.
  MORIN, J.P. Long Island Lighting Co. 79/05/22. 1p.

- P Operating license stage documents & correspondence
- 7905040439 Util will invoke Code Case N-224 to ASME Section III which allows use of ASTM A500 Grade B & ASTM A501 structural tubing for welded attachments to ASME Section III Code Class 2 & S components This ltr supplements 790327 ltr NOVARRO, J P Long Island Lighting Co 79/04/25 1p
- O Inspection reports, IE Bulletins & correspondence
- 7903010114 Forwards IE Info Notice 79-06. "Stress Analysis of Bafety-Related Piping" ORIER.B H Region i. Philadelphia. Office of the Director 79/03/23 ip
- 7905240669 Forwards IE Insp Rept 50-322/79-03 on 790227-0302 No 0524066B Forwards it. http://www.noncompliance noted carlson.R T Region 1, Philadelphia, Reactor Construction & CARLSON.R T Region 1, Philadelphia, Region 1,
- --7905240673 EE Insp Rept 50-322/79-03 on 790227-0302 No hancompliants 705240673 IE Insp Rept 50-382/74-03 on 790227-0302 No indicomplished noted Major areas inspected quality verification records for reactor pressure vessel internals storage & installation & licensee action on NRC findings
  TOTH, A D . MCBREARTY, R A Region 1. Philadelphia, Office of the Director MCGAUGHY, R W Region 1. Philadelphia, fleactor Construction & Engineering Support Branch 79/03/22 9pp
- 7903240976 Responds to IE Bulletin 79-02, "Pipe Support Dass Plats Designs Using Concrete Expansion Anchor Bolts " Forwards addl info to clarify SER apen items & confirmatory issues NOVARRO.J P Long Island Lighting Co 79/03/28 lp
- 7905020051 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "ORIER, B H Region I, Philadelphia, Office of the Director 79/04/11 ip
- 7905020395 Forwards IE Bulletin 79-07, "Seismic Strase Analysis of Bafety-Related Piping" Licensee action required ORIER, B H Region 1, Philadelphia, Office of the Director 79/04/14 ip
- 7905040038 Forwards IE Bulletin 79-06B. "Review of Operational Errors b Sys Misalignments Identified During TMI Incident." GRIER, BH Region 1. Philadelphia, Office of the Director 79/04/14 ip
- 7905040208 Forwards IE Bulletin 79-08, "Events Relevant to Beilin Hater Power Reactors Identified During TMI Incident" GRIER.B H Region 1, Philadelphia, Office of the Director 79/04/14 1p
- 7905030070 Forwards IE Bulletin 79-09, "Failures of GE Type AX-2 Circuit Breaker in Safety-Related Bys " Licensee action ORIER, B H Region 1, Philadelphia, Office of the Director 79/04/17 ip
- 7905020263 Forwards IE Bulletin 79-06A Revision 1, "Review of Operational Errors & Bys Misalignments Identified During THI Incident " GRIER, B. H 79/04/18 1p Region 1, Philadelphia, Office of the Director
- 7905240639 Forwards revised procedures of preservice insp program NOVARRO, J.P. Long Island Lighting Co. 79/05/01 2pp
- ---7905240645 Automated ultrasonic examination procedures for resolvent vessel nozzla welds

  \* Long Island Lighting Go 78/11/03 33pp
- --7903240448 Remote ultrasonic examination procedures for reactor will notile safe-end walds \* Long Island Lighting Co 78/11/03. Sipp
- -- 7905240650 Automated ultrasonic examination procedures for results
- vessel welds # Long Esland Lighting Co 78/11/03 29pp
- ~-7905240654 Ultrasonic examination procedures for piping butt will b longitudinal welds \* Long Island Lighting Co. 78/09/01 Sipp

- DOCKET 50-329 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 2

  A Application/construction stage documents & correspondence
- 7905070674 Forwards replacement pages for Amends 1 & 4 to CPPR-39 & CPPR-49
  STOLZ.J F Light Water Reactors Branch 1 79/03/29 100c
- 7908230878 Extends const completion dates to 790630 for Unit 1 & 800229 for Unit 2 STQLZ.J F Light Water Reactors Branch 1 79/04/13 6pp
- --7905230582 FR notice ordering extension of const completion dates to 790630 for Unit 1 & 800227 for Unit 2 BOYD,R S Division of Project Management 79/04/13 2pp
- 7905020302 Forwards \$1,600 fee to extend CP,in response to NRC 770410 ltr Requests acknowledgment CRANE.P A Pacific Oas & Electric Co 77/04/27 2pp
- 7703210172 Forwards additinfo on containment electrical penetrations in response to NRC questions
  CRANE, P.A. Pacific Gas & Electric Co. 79/05/17 3pp
- 7908210169 Forwards info on boiled connections in linear supports in response to NRC 781208 ltr CRANE.P A Pacific Gas & Electric Co 79/05/18 9pp
- 7903300261 Forwards application to extend completion date for GPPR-39 to 791031 GRANG.P A Pacific Qas & Electric Co 79/08/24 1p
- --7903300364 Application to extend completion date for CPPR-39 to 791031 SHACKELFURD, B. CRANE, P. A. Pacific Qas & Electric Co. 79/05/23 in
- F Security, medical, emergency & fire protection plans
- 7905190054 Forwards modified physical security plan Plan withheld (ref 100FR2 790)
  CRANC.P A Pacific Gas & Electric Co 79/05/15 1p
- Q Adjudicatory correspondence
- 7905030166 Request by intervenors Scenic Shoreline Preservation Conference, San Luis Obispo Mothers for Psace, Ecology Action Club. SA Silver & JJ Foster for late filing of proposed findings of fact & conclusions of law W/Gertificate of Svc FLEISCHAKER. D 8 Fleischaker, D 8, 79/03/25 4pp
- --7905030174 Proposed findings of fact & conclusions of law by intervenors Scenic Shoreline Preservation Conference San Luis Dbispo Mothers for Peace Ecology Action Club SA Silver & JJ Foster FLEIBCHAKER D 8 Fleischaker D 8 PHILLIPS J R , KRISTOVICH B Center for Law in the Public Interest 79/03/25 69pp
- 7705250052 Informs of inability to submit proposed findings of fact on adequacy of plant security systdenied access to evidence & access to hearing on security plan Certificate of Svc encl BALDMIN, W A Ban Luis Obispo Mothers for Peace 77/03/27 3pp
- 7905230789 Oroup of 15 itre protesting opening of facility MARGOLIS, K. R. WYLER, B. Affiliation Unknown 79/03/30 19pp
- 7905010115 Forwards request for Board notification re nonsafety-grade equipment to mitigate transients.

  8CINTO, J.F. Hearings Division 79/04/02 31pp
- ---7905010156 Board notification staff assessment re nonsafety-grade aquipment to mitigate transients VABSALLO: D B Assistant Director for Light Water Reactors 79/03/29 2pp.
- --7903010198 Board notification recent issue on nonsafety-grade equipment to mitigate transients Hore info is required. TEDESCO, R L Assistant Director for Reactor Safety 79/03/16 Spe
- 7905240256 Raquests info on facility & earthquake Unhappy w/nuclear power OARCIA,O Affiliation Unknown 79/04/04 1p
- --- 7905240279 Requests that facility not be allowed to operate.

  MANZER, N : MANZER, R Affiliation Unknown 79/03/30. ip.

- 7705300044 Hotion of extension of time until 790410 to file proposed findings of fact & conclusions of law Certificate of Svc encl KETCHEN,E 0 Branch 3 79/04/04 4pp
- 7905290114 Grants NRC 790404 motion for extension until 790410 in which to file findings of fact BOMBERS, E.S. Atomic Safety and Licensing Board Fanel 79/04/05 ip
- 7905310104 Errata sheet tu joint intervenors' proposed findings of fact & conclusins of law Certificate of Svc encl FLEISCHAKER, D S Fleischater. D S PHILLIPS, JR, KRISTOVICH, S Center for Law in the Public Interest 79/04/05 7pp
- 7905250330 Responds to 790326 ltr re status of facility licensing Evidentiary record in proceeding closed 790312:last pleading scheduled to be filed by 790416 Precise date for initial decision cannot be made YORE, J R Atomic Bafety and Licensing Beard Panel 79/04/06 ip
- ---7905250335 Forwards 790315 ltr from Solar Use Now for Resources & Employment expressing concern about licensing of facility Requests info on status of licensing process ROUSBELOT.M C House of Rep 79/03/26 2pp
- 7903140554 Rebuttal to joint intervenors' 790325 proposed findings of fact & conclusions of law Certificate of Svc enci CRANE.P A Pacific Cas & Electric Ca 79/04/09 36pp
- --7905140556 Errata 2 suppl to proposed findings of fact 2 conclusions of law CRANE.P A Pacific Oas & Electric Co 79/04/09 2op
- 7905100157 Initial decision authorizing Director of Ofc of Nuclear Reactor Regulation to make such addl findings on uncontested matters as may be necessary to issue full-term OL Certificate of Svc encl
  TOUTELLOTTE.J , KETCHEN.E O Branch 4 STAENBERO,M R
  Regulations Division 79/04/10 114pp
- 7903280490 Requests that rebuttal to Joint Intervenors' proposed finding of fact be amended to ref ABLB 780803 order CRANE,P A Pacific Gas & Electric Co 79/04/11 ip
- 7903100370 Forwards corrected pages to NRC 790410 proposed findings. changing words "Initial Decision" to "Conclusions of Law "TOURTELLUTTE. J Branch 4 79/04/12 3pp
- 7905150726 Responds to 790216 & 790321 ltrs requesting denial of OLs ABLB will consider issue Views to be included in docket file of proceeding ENOELHARDT.T F Deputy Executive Legal Director 79/04/17 1p
- 7905150598 Forwards resolution adopted on 790416 Resolution requests deferrment of action on license application, pending determination that safety sys are adequate to assure public safety MENZEL.H C Santa Barbara County, CA 79/04/18 1p
- ---7905150603 Resolution of Board of Bupervisors of Banta Barbara County, CA urging NRC to defer final action on license application until facility safety systems are adequate to ensure public safety YAOER, D. M. Santa Barbara County, CA. 79/04/16 1p
- 7905150118 Responds to encl ltr opposing operation of facility because of proximity to active earthquake fault & concern for disposal of high level radioactive wastes Hatters being considered by ASLB BOYD, R. 8 Division of Project Management 79/04/30 3pp
- 7905240364 Requests denial w/o prejudice of joint intervenors' motion to withhold issuance of OL Certificate of Evc encl TOURTELLGITE. J Branch 4 79/05/02 Bp
- 7905300007 Response in opposition to joint intervenors' request to withhold issuance of OL Mation is untimely in wrong form & poorly taken MORRIESEY, J C Pacific Gas & Electric Co. GEHR, A C Snell & Wilmer NORTON, B Bruce Norton 79/05/09 &pp
- 7703300716 Ack receipt of 770423 & 770426 ltrs re opposition to operation of facility due to proximity to Hosgri Fault Facility designed to withstand seismic event of 7 5 ASLB is preparing decision re licensing based on 770215 hearing. DENTON, H. R. Office of Nuclear Reactor Regulation 79/05/14 2pp

- --7903390719 Expresses opposition to operation of facility due to provinity to Hosgri Fault NATERHOUSE.H Affiliation Unknown 79/04/26 ip
- ~-7903300720 Expresses oposition to operation of facility due to provinity to Hospri Fault
  WATERHOUSE, E. Affiliation Uninoun 79/04/25 ip
- N General correspondence
- 7905230452 Requests immediate halt to const of facility ANDREMS.H House of Rep. 79/04/02 ip
- 7903070551 Notifies of change of address for DG Brindenbaugh & RB Hubbard to 1723 Hamilton Ave.Suite K.Ban Jose, CA 95125 COOPER.K F MHB Technical Associates 79/04/25 ip
- 7905240713 Requests suspension of OL until necessary safety mods are implemented BROWN:E O California: State of 79/05/04 2pp
- 7905240265 Responds to 790320 itr re-constituent concerns re-granting of license to facility Seismic event of 7.5 magnitude can be withstood & quality of const is controlled by licensee GA program QOSSICK, L. V. Office of the Executive Director for Operations 79705708 Jpp.
- l Financial information
- 7903300168 Forwards "Annual Financial Rept 1978 " CRANE.P A Pacific Gas & Electric Co 79/05/23 ip
- 7905300510 Forwards "Estimated Internal Fund Cameration for CY79" & "Annual Financial Rept 1978" CRANES A Pacific Gas & Electric Co 79/05/24 3pp
- --7905300329 "Annual Finantial Rept 1978 "
  # Pacifit Gas & Electric Co 79/02/23 36pp
- √ Insurance & indemnity information
- 7905140512 Forwards Amend 4 to Indemnity Agreement B-75 per 10CFR140 changes, re increase in liability insurance from \$140 million to \$140 million effective 790501 Supporting documentation encl SALTZMAR. J Antitrust & Indemnity Group 79/05/01 6pm
- 7905140406 Forwards Amends executed Amends 21 & 4 to Indomnity Agreements 8-21 & 8-75, respectively CRANE, P. A Pacific Gas & Electric Co 79/05/08 3pp
- O, Advisory Committee on Reactor Safeguards reports % correspondence
- 7405100325 Responds to request for written rept after cancellation of ACRB 790331 assting re-possibility of problem strument guide tubes Staff rept and CROCKER, L.P. Division of Project Hanagement 79/03/30 Spp
- P. Operating license stage documents & correspondence
- 7905020244 Responds to NRC 790314 request for add1 info re containment purge valves Forwards results of CSBREV1 program to calculate containment purge valve closing data coincident w/LOCA CRANE.P.A Pacific Gas & Electric Co 79/04/13 45pp
- @ Inspection reports. IE Bulletins & correspondence
- 7905230656 Forwards IR Insp Rept 80-323/79-09 on 790220-23 No noncompliance noted SOCK-H E Region 5, San Francisco, Fuel Facility & Materials Safety Branch 79/03/19, 2pp.
- ~-7905230664 IE Insp Rept 30-323/79-09 on 790220-23 No noncompliance noted Major areas inspected training in emergency planning & radiation protection staffing, respiratory protection, radioactive waste sue & Offsite Dose Calculation Hanval NORTH, H S. Region 5, San Francisco, Office of the Director SOCK, H E Region 5, San Francisco, Fuel Facility & Materials Safety Brench. 79/03/19 4pp.

- 7908230617 Forwards IE Insp Repts 50-275/79-05 & 50-323/79-03 on 790806-09 & 15 No noncompliance noted CREWS.U L Region 5. San Francisco. Reactor Operations Nucleus Support Branch 79/03/21 2pp
- --7905230640 IE Insp Repts 50-275/79-05 & 80-323/79-09 on 790306-07 |
  No noncompliance noted Major areas inspected preoperational testing evaluation & verificastion of test results, IE bulleties & circulars following MORRILL,P 9 Region 5, San Francisco, Office of the Director STERNBERO,D M Region 5, San Francisco, Reactor Operations Nuclear Support Branch 79/03/20 App
- 7908010287 Forwards IE Info Notice 79-06, "Strees Analysis of Safety-Related Piping" ENDELKEN.R H Region 4, Dallas, Office of the Director 79,03.3 to
- 7905040081 Forwards IE Info Notice 79-07, "Rupture of Redwests Table ENGELKEN.R H Region 3, Ben Francisco, Office of the Director 79/03/26 ip.
- 7908010023 Forwards IE Bulletin 79-06A, "Review of Operational Fress Sys Misslighments Identified During TMI Incident " ENGELKEN R M Region 5, San Francisco, Office of the Director 79/04/14 ip
- 7705040509 Forwards IE Bulletin 79-06B, "Review of Operational Errain Bys Misslignments Identified During TMI Incident " ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/04/14 ip
- 7908070099 Forwards IE Bulletin 79-07, "Beismic Stress Analysis of Bafety-Related Piping "Licensee action required EMBELKEN:R ff Region 5, Ban Francisco, Office of the Direct 79704/14 ip
- 7903030291 Forwards IE Bulletin 79-09, "Failures of the Type AP 2 Circuit Breaker in Safety-Related Bys." Licenses action required ENGELKEN R M Region 5, San Francisco, Office of the Directs\* 79/04/17 ip
- 7905080366 Forwards IE Bullstin 79-058, "Nuclear Incident at TMI-Suppl" EMBELKEN, R H Region 5, San Francisco, Office of the Darestor 79/04/25 12
- S Reportable occurrences, LERs & related correspondence
- 7905110203 Board notification Seabrook refueling water storage sent design deficiency SCINTO, J Hearings Division, 79/03/29 30pp
- 7905130060 Forwards PNO-79-67L ENGELKENIR H Region 5. San Francisco, Office of the Director 79/04/06 Ip
- 7903150167 Forwards PND-79-67R ENGELKEN/R H. Region 3. Ban Francisco, Office of the Director 79704711 ip
- 7903040123 forwards PNO-79-678
  ENDELKEN,R H Region 5. Ban Francisco, Office of the Dissibile 79/04/12 ip
- 7903130141 Forwards PNO-79-677 ENGELKEN.R.H Region 5. Ban Francisco. Office of the Deretter 79/04/13 1p
- 7905030045 Forwards PND-79-67U
  ENGELKEN, R H Region 5. Ban Francisco, Office of the Direct.\*
  79/04/14 1P.
- 7905020327 Forwards PNO-79-67AA.
  ENGELKEN,R H. Region 5. San Francisco, Office of the Director 79/04/20 ip
- 7903010425 Forwards PND-79-67AB BNDELKEN.R H. Region 5, San Francisco, Office of the Difficit 79/04/21, 10.
- 7905010444 Forwards PNC-79-67AC & Ab ENGELKEN/R. H. Region 5, San Francisco, Office of the Dissiles 79/04/23. 1p

- 7905020227 Forwards PNO-79-67AF ENGELKEN.R H Region 5, Ban Francisco, Office of the Director 79/04/25 1m
- 7905020256 Forwards PNO-79-67AQ ENGELMEN.R H Region 5. San Francisco, Office of the Director 79704/26 ip
- 7905090000 Forwards PNO-79-67AH ENGLEKEN, R H Region 5. Ban Francisco, Office of the Director 79/04/27 1p
- 7903070007 Forwards PNO-79-47AL.psr NRC 790401 ltr transmitting IE Bulletin 79-03 ENGELMEN.R H. Region 5. San Francisco, Office of the Director, 79/05/04 in
- 7709090380 Submits followup rept to 770404 notification of RO. During progress of routine weld repairs on pipe rupture restraints, cracking discovered in immediate vicinity of repairs Full rept will be submitted CRANE, P.A. Pacific Oas & Electric Co. 77/05/03 3pp
- 7905170072 Forwards PND-79-47AM ENGELKEN,R H Region 5. San Francisco, Office of the Director 79/05/07 in
- 7703240651 Ack receipt of 770503 itr providing preliminary rept recracking found in pipe rupture restraints ENGELKEN, R. H. Region 5. San Francisco. Office of the Director 770705/16. ip.
- ---7905240701 Discusses situation reported to IE on 790404 re cracking in page rupture restraints Details program of investigation Suppl on crack severity will be forwarded CRANC.P.A Pacific Gas & Electric Co 79/05/03 3pp
- T. Hearing transcripts on non-antitrust matters
- 7903030244 Corrections to transcripts from Dec 1978 & Jan 1979 hearings Cortificats of Byc encl MORRISBEY, J C , FURBUSH, M. H , CRANE, P A Pacific Gas & Electric Co 79/04/04 23pp
- 7909240273 Requests info ms E Maschke 790315 itm of concerns about granting of license to util LAGOMARBINO.R House of Rep. 79/03/20 1p

# DOCKET 50-324 BRUNSHICK STEAM ELECTRIC PLANT, UNIT 2 J Insurance & Indemnity information

- 7908040599 Forwards Endorsement 30 to MALEU Policy MF-80 ORAHAM, N E Caroling Power & Light Co 79704728, 2pp
- 7903040607 Forwards Endorsement 33 to NELIA Policy NF-218
  GRAHAM.W E Carolina Power & Light Co 79/04/25 2pp
- 7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,179,179,180,182,188,187,188,189,192,193,194,195,197,198,200,201,204,206,207,208,210,212,214,215,8 others QUATTROCHHI,J American Nuclear Insurers 79/05/01 1p
- 7903070382 Confirms increase in liability limit to \$36,000,000 for policies MF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,54,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,91,92,93,94,95 & 96, ROBERTS, B. M. Mutual Atomic Energy Liability Underwriters 79/05/01 in
- 7905140508 Forwards Amend 9 to Indemnity Agreement 8-71 per 10CFR140 changes, re increase in liability insurance from \$140 million to \$160 million, effective 790501 Supporting documentation encl.
  SALTZMAN, J Antitrust & Indemnity Group 79/05/01. 6pp
- 7903170233 Forwards Amend 9 to Indomnity Agreements B-42 & B-71 reflecting increase in primary liability insurance provided by ANI/MAELU, BARHAM. C.D. Douglass & Barham 79/05/11. 3pp
- P. Operating license stage documents & correspondence
- 7705030353 Submits exceptions & corrections to operations GA program re ANSI codes for instrumentation & electrical equipment, & mechanical equipment & sys for const phase.
  UTLEY, E, E. Carolina Power & Light Co 79/04/23 3pp

- 7705150108 Responds to 770112 request for termination of leveling portion of 730610 Phase 1 "BEEP Program for Belamic Monitoring "Approves request to terminate program IPPOLITO,T A Operating Reactors Branch 3 77/04/25 2pp
- 7905040624 Requests Tech Specs change re trip feature, annunciator clarity to minimize operator confusion & stop valve UTLEY.E E Carolina Power & Light Co 79/04/27 13pp
- 7905080402 Submits schudule for implementing augmented offgas sys in response to 780912 ltr Earliest feasible date for completing mod.testing & demonstration of sys operability is 811231 UTLEY.E E Carolina Power & Light Co 79/05/01 1p
- 7905080417 Responds to 781127 ltr re containment purging during normal plant operation Should LOCA occur during operations, operation of ECCS sys would not be affected Supporting info encl
  UTLEY.E E Carolina Power & Light Co 79/05/01 App
- 7903080436 Provides results of GE analysis of prompt recirculation pump trip for Cycle 3 operation NRC should be able to license Cycle 3 operation until mid-cycle Recirculation pump trip will be tested during facility startup UTLEY.E E Carolina Power & Light Co 79/03/01 ip
- 7905310379 Responds to NRC 780912 ltr re schedule for implementing augmented offgas sys New hydrogen recombiners installed on front end Sys will be operable by 811231 UTLEV.E E Carolina Power & Light Co 79/05/01 lp
- 7905080453 Forwards oversized maps & photo attachments to util 781129 rept on main dam core trench features W/o drawings FLOYD.8 D Garolina Power & Light Co 79/05/08 Spp
- 7905300208 Forwards summary of EDS Nuclear, Inc resolution/documentation of elbow flexibility error which existed in versions of PISOL piping analysis computer program from Jan-Oct 1969 Review & reanalysis included all work through Dec 1970 PORTER, F L. EDS Nuclear, Inc 79/05/21 9pp
- --7905300263 Forwards EDS Nuclear, Inc list of BWRs & piping sys which could have been impacted by deficient computer program OE has no record of reanalysis for Cooper piping sys STEPHENS, P W. General Electric Co., Nuclear Energy Products Div 79/01/24 18pp
- 7905290370 Confirms & formalizes 790521 verbal commitment re seismic comparison & insp of safety-related piping Documents statements re reanalysis of circulation loops
  UTLEY,E E Carolina Power & Light Co 79/05/22 2pp
- @ Inspection reports: IE Bullatins & correspondence
- 7905010465 Forwards IE Insp Repts 50-324/79-05 & 50-325/79-05 on 790122-26 No noncompliance noted LENIS.R G Region 2. Atlanta. Reactor Operations Nuclear Support Branch 79/03/14 2pp
- --790010468 IE Insp Repts 50-325/79-05 & 50-324/79-05 on 790122-26. No noncompliance noted Major areas inspected radiological environ monitoring program-environ monitoring station & data-analytical sensitivity & control measures PERRY. W. W. Region 2. Atlanta-Reactor Operations Nuclear Support Branch 79/03/09 5pp
- 7905010168 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping" O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/03/23 2pp
- 7905030274 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks " O'RETLLY, J P Region 2, Atlanta, Office of the Director 79/03/24 2pp
- 7908010095 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Bys w/Svc Air Bys Used as Source of Breathing Air." O'REILLY, J.P. Region 2, Atlanta, Office of the Director
- 7905010345 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin" O'REILLY.J P Region 2, Atlanta, Office of the Director. 79/03/30, 2pp.
- 7905240661 Forwards IE Insp Repts 50-324/79-10 & 50-325/79-10 on 790304-07 No noncompliance noted.
  MURPHY, G E Region 2. Atlanta. Office of the Director. 79/04/06 200

- --7903246665 IE insp Repts 50-324/79-10 & 50-325/79-10 on 790304-07 No noncompliance noted Hajor areas inspected inservice insp program, procedures & insp data & evaluation & special program, procedures & insp data & evaluation & special program, procedures & insp data & evaluation & special program of recirculation loop injet sefe-ends QLAXE, J Region 2. Atlanta, Office of the Director 79/04/05 for
- 7905100241 Responds to IE Bulletin 79-03 No welded pipe from Youngstown Welding & Engineering is used or planned for use UTLEV.E E. Cardina Power & Light Co. 79/04/12 ip
- 7905230209 Ack receipt of 790402 ltr informing NRC of steps taken to covered violations noted in 16 Insp Rept 50-324/79-07 & 50-329/79-07 CENTS: R C Region 2. Atlanta, Reactor Operations Nuclear Support Research 79704/12 lp
- --7705230223 Responds to ARC 770309 itr re violations noted in IE Insp. Repts 90-324/79-07 & 50-325/79-07 Corrective actions individuals have been counseled an parforming data reviews & on corrective actions SUPR, 8 J. Carolina Power & Light Co. 79/04/02 2pp
- --7905230229 Forwards IE Insp Repts 50-324/79-07 & 50-325/79-07 on 790130-0202 & notice of violation LEMIS, P.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/09 2pp
- --7905230237 Notice of violation from insp on 790130-0202
  Region 2, Atlanta, Office of the Director 79/03/09 ip
- --7505230243 IE Insp Repts 50-324/79-07 % 50-325/79-07 on 790130-0202
  Noncompliance noted stroke time for valve 6046 was above
  may time required by Tech Specs Three independent reviews
  failed to note problem
  RILEY.B W. HESSITT.B R Region 2, Atlanta, Office of the
  Director DANCE.H C Region 2, Atlanta, Reactor Operations
  Nuclear Support Branch 79/03/09 App
- 7905040163 Forwards IE Bulletin 79-068, "Review of Operational Errors & Eys Misalignments Identified During THI Incident " O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/04/14 2pp
- 7905040281 Forwards IE Bulletin 79-07, "Beismic Strass Analysis of Safety-Related Piping " Licenses action required O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 in
- 7905150696 Forwards IE Bulletin 79~09, "Events Relevant to BWRs lientified During TMI Incident "Licensee action required O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 Zap
- 7905030141 Forwards IE Bulletin 79-07, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys " Licensee action required O'REILLY, J P. Region 2, Atlanta, Office of the Director 7900417 20-2
- 7905020373 Forwards IE Bulletin 79-06A.Revision 1, "Review of Operational Errors & Bys Hisalignments Identified During TMI Incident \* O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/04/18 2aa
- 7903010517 Forwards restated paragraph from 770330 18r, submitted as revision to OA program, in response to IE Insp Repts 50-324/79-02 & 50-323/79-02 Faragraph discusses radiation survey/measuring instruments
  UTLEY, E. Carolina Power & Light Co. 79/04/23 2pp
- 7905240192 Responds to IE Bulletin 79-07, "Baismic Stress Analysis of Safety-related Piping " Will reanalyze all remaining safety-related piping as soon as NRC ack that specified criteria is acceptable. Wisupporting documentation UNLEY.R E Caroline Pawer & Light Co 79/04/24 Spp
- 7903300283 Responds to IE Bulletin 79-01 Bearch of plant documentation indicates no Velan swing check valves w/djampter of 3-10 inches are used at facility UTLEY,R E Carolina Power & Light Co 79/04/30. iq.
- 7905210165 Supplements 790424 response to IE Bulletin 79-07 re reachaigsis of computer programs used for safety-related piping Addl program verification has been performed by running NRC-approved benchmark cases
  UTLEY.E E Carolina Power & Light Co. 79/05/15 7pp

- 7905230344 Forwards response to 790516 request for addl info to suffice analysis of safety-related piping Supplements util's 790424 to 790516 responses to IE Bulletin 79-07 FURR:B J Carolina Power & Light Co 79/05/21 34pp
- R Periodic operating reports & related correspondence
- 7905150631 Forwards monthly operating rept for Apr 1979 FURR:B J Carolina Power & Light Co 79/05/09 ip
- --7905150638 Monthly operating rept for Apr 1979
  WILLIS,E Carolina Power & Light Co 79/05/01 13pp
- 8 Reportable occurrences, LERs & related correspondence
- 7905030345 Forwards LER 79-017/03L-0 FURR.B J Carolina Power & Light Co 79/04/30 12
- --7905030347 LER 79-017/03L-O on 790404 RHR pumps 23 & 2D would not the on manual signal Caused by poor connection between fuses to fuse block Fuses soldered to fuse block TOLLISON, A C Carolina Fower & Light Co 79/04/30, 3pp
- 7905090282 Forward LER 79-018/03L-0 FURR.B J Carolina Power & Light Co 79/08/07 1p
- --7905090289 LER 79-018/03L-0 ON 790419 pressure switch 2-EHC-PQ-1733 failed to meet Teth Specs response time Caused by actuation time on installed switch being too slow Alternative switching methods under evaluation TOLLISON.A C Carolina Power & Light Co 79/05/07 &P
- 7905090302 Forwards LER 79-019/03L-0 FURR:B J Carolina Power & Light Co 79/05/07 1p.
- --7905090311 LER 79-019/03L-0 on 790420 electrical open circult terms 12 gover lead to ten motor Caused by junction box epilical between motor & contactor, TOLLISON, A C Carolina Power & Light Co 79/05/07 lp
- 7908230615 Submits 14-day radiological environ event rept radioactive waste was shipped on 790803 w/radiation levels exceeding EFS incident to be reviewed & health physics radwaste shipment procedures revised BANKS, H.R. Caroline Power & Light Co. 79/08/16 2pp
- 7905220406 Forwards LER 79-020/03L-0.
  BANKS, H R Carolina Power & Light Co 79/05/18 1p
- --- 7905-220411 LER 79-020/03L-O on 790421. while performing standby He-le control rolief valve test, relief valve lifted at 1,250 lb Caused by setpoint drift Setpoint reset, tested satisfactorily & returned to svc 10LL(SON, A C Caroline Power & Light Co 79/03/18 lp
- 7905300384 Forwards LER 79-030/03L-0
  BANKS, H R Caroline Power & Light Co 79/05/24 Ip
- ~-7903300390 LER 79-030/03L-0 on 790423:13 snubbers failed inspiser failed to lock up No apparent cause discerned Eight were rebuilt whew seals & poppets three replaced Remaining three snubbers failed to bleed Tao rebuilt:now replaced YOLLIBON. A C Carolina Power & Light Co 79/03/24 2ep
- 7905300371 Forwards LER 79-011/031-0 BANKS,H R Carolina Power & Light Co 79/05/25 ip
- --7905300377 LER 79-011/03L-0 on 790419 during inapyfive Berger Patting anubbers failed Caused by low fluid level & seal failure Snobbers rebuilt & returned to avo. TOLLISON,A C Garolina Power & Light Co 79/05/25 2ee
- 7905300375 Forwards LER 79-022/03L-0, BANNS, H. R. Garolina Power & Light Co. 79/05/25, tp
- --7705300380 LER 79-022/03L-0 on 770425. While in cold shutdown resecond stion of refueling outage, water chamistry Tech Speciamits exceeded Caused by exceetive condenser tube leatage causing rapid saltwater breakthrough TOLLISON, A.C. Caroling Power & Light Co. 77/05/25. 2pp
- 7905300387 Forwards LER 79-032/03L-0. BANKS,H R. Garolina Power & Light Co. 79/05/25. Ip.

- - TOLLISON, A C Carolina Power & Light Co 79/05/25 1p
- pocket 50-325 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 1

  J Insurance & Indomnity information
- 7908040399 Forwards Endorsement 30 to MALEU Policy MF-80 ORAHAM: W. E. Carolina Power & Light Co. 79704725 2pp
- 7905040407 Forwards Endorsement 33 to NELIA Policy NF-218 ORAHAM, W. E. Carolina Power & Light Co. 79/04/25 2pp
- 7905070497 Confirms increased liability limit to \$124,000,000 for policies NK-1, 25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,187,186,187,198,199,192,193,194,195,197,198,200,201,204,206,207,208,210,212,214,215,&others QUATEROCHILJ American Nuclear Insurers 79/05/01 in
- 7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22,26,29,38,39,44,46,47,49,30,51,52,53,54,55,56,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,91,92,93,94,95 \$ 96 ROBERTS, D M Mytual Atomic Energy Liability Underwriters 79/05/01
- 7905140508 Forwards Amend 9 to Indemnity Agreement B-71 per 10078140 changes is increase in tiability insurance from \$140 million to \$160 million, effective 790501 Supporting documentation entitions.

  8ALTZMAN, J Antitrust & Indemnity Group 79/05/01 App
- 7905170233 Forwards Amend 9 to Indemnity Agreements B-42 & B-71 reflecting increase in primary liability insurance provided by ANI/MATLU BARHAM, C D. Douglass & Barham 79/05/11 3pp
- P. Operating license stage documents & correspondence
- 7909010:193 Bubmits exceptions & corrections to operations GA program re ANGI codes for instrumentation & electrical equipment, & mechanical equipment & sys for const phase UTILY, L.K. Carolina Power & Light Co. 79/04/23 3pp
- /905230620 Notification of 790424 meeting w/util & QC in Bethesda, MD to resolve questions on proposed recirculation pump trip feature for end-of-cycle margin enhancement MARRON, J N Operating Reactors Branch 3 79/04/23 lp
- 7905150100 Responds to 790112 request for termination of leveling portion of 750610 Phase L "BBLP Program for Beismic Monitoring " Approves request to terminate program IPPOLITO, T A Operating Reactors Branch 3 79/04/25 2pp
- 7705040624 Requests Tech Specs change re trip feature annunciator clarity to minimize operator confusion & stop valve UTLEY: E. Carolina Power & Light Co. 77/04/27 13pp
- 7903150822 Motification of 770430 meeting w/util \$ 0E in Bethesda. MD to resolve questions on proposed recirculation pump trip feature for end-of-cycle margin enhancement HANNON, J M. Operating Reactors Branch 3 79/04/30.
- 79050BOAD2 Bubmits schedule for implementing augmented offgas sys in response to 700912 ltr Carliest feasible date for completing mod. testing & demonstration of sys operability is 911231 UTLEY.E & Carolina Power & Light Co 79/03/01 ip
- 7903080417 Responds to 781129 ltr re containment purging during normal plant operation Should LOGA occur during operations; operation of ECCS tys would not be affected Supporting info encl
  UTLEY.E E Garolina Power & Light Co 79/05/01. App.
- 7905310379 Responds to NRC 780912 ltr re schedule for implementing augmented offgas sys New hydrogen recombiners installed on front end Sys will be operable by 811231 UTLEY.E E Carolina Power & Light Co 79/03/01 lp
- 7905080433 Forwards oversized maps & photo attachments to util 781129 rept on main dam core tranch features W/o drawings FLOYD, B D Carolina Power & Light Co 79/05/08 5pp

- 7903300208 Forwards summary of EDS Nuclear, Inc resolution/documentation of albow flexibility error which existed in versions of PISOL piping analysis computer program from Jan-Oct 1949 Review & reanalysis included all work through Dec 1970 PORTER, F L EDS Nuclear, Inc 79/05/21 9pp
- 7905290370 Confirms & formalizes 790521 verbal commitment re seismic comparison & insp of safety-related piping Documents statements re reanalysis of circulation loops UTLEY.E E Carolina Power & Light Co 79/05/22 2pp
- Q Inspection reports: IE Bulletins & correspondence
- 7905010465 Forwards IE Insp Repts 50-324/79-05 & 50-325/79-05 on 790122-26 No noncompliance noted LEWIB.R C Region 2, Atlanta, Reactor Operations Nucleat Sugport Branch 79/03/14 2pp
- ---7903010466 IE Insp Repts 50-325/79-05 & 50-324/79-05 on 790122-24 No noncompliance noted Major areas inspected radiological environ monitoring program environ monitoring station & data\_analytical sensitivity & control measures , PERRY, W W Region 2. Atlanta, Reactor Operations Nuclear Support Brench 79/03/09. Spp
- 7905010168 Forwards IE Info Notice 79-06, "Stress Analysis of Bafety-Related Piping"
  O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/23 200
- 7905030294 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks "
  0'REILLY, J P Region 2, Atlanta, Office of the Director
  79/03/26 2pp
- 7905010095 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air "
  D'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/28 200
- 7905010346 Forwards IE Info Notice 79-09. "Bpill of Radioactively Contaminated Resin " O'REILLY.J P Region 2. Atlanta. Office of the Director 79/03/30 2pp
- 7908240661 Forwards IE Insp Repts 50-324/79-10 & 50-325/79-10 en 790304-07 No noncompliance noted MURPHY.C.E Region 2, Atlanta, Office of the Director 79/04/06 209
- --7903240665 IE Insp Repts 50-324/79-10 & 50-325/79-10 on 790304-07 No noncompliance noted Major areas inspected inservice insp programs procedures & insp data & evaluation & special ultrasonic insp of recirculation loop inlet safe-ands BLAKE, J J Region 2, Atlanta, Office of the Director 79/04/05 4pp
- 7905100241 Responds to IE Bullstin 79-03 Na welded pipe from Youngstown Halding & Engineering is used or planned for use UTLEY,E E Caralina Power & Light Co 79704/12 1p
- 7905230207 Ack receipt of 790402 Itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-324/79-07 & 50-325/79-07 LEWIS,R C Region 2, Atlanta: Reactor Operations Nuclear Support Branch, 79/04/12 ip
- --7903230223 Responds to NRC 790309 ltr re violations noted in IE Insp Repts 50-324/79-07 & 50-325/79-07, Corrective actions individuals have been counseled on performing data reviews & on corrective actions FURR, B, J Carolina Power & Light Co 79/04/02 2pp.
- --7905230229 Forwards IE Insp Repts 50-324/79-07 & 50-325/79-07 on 790130-0202 & notice of violation LEWIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 79/03/09. 2pp
- --7905230237 Notice of violation from insp on 790130-0202 \* Region 2, Atlanta, Office of the Director 79/03/09, ip

- --7903230243 IE Insp Repts 50-324/79-07 & 50-325/79-07 on 790130-0202
  Noncompliance noted stroke time for valve F046 was above
  max time-required by Tech Specs Three independent reviews
  failed to note problem
  RILEY.B N . MESSITT.B R
  Ritery.B N . MESSITT.B R
  Ritery.B N . MESSITT.B R
  Region 2. Atlanta, Office of the
  Nuclear Support Branch 79/03/09 6pp
- 7903040163 Forwards IE Bullstin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "
  O'REILLY, J.P. Region 2, Atlanta, Diffice of the Director 79/04/14 2pp
- 7905040281 Forwards IE Bulletin 79-07. "Seismic Stress Analysis of Safety-Related Piping " Licenses action required O'REILLY.J P Region 2. Atlanta, Office of the Director 79/04/14 1g
- 7905150696 Forwards IE Bulletin 79-08. "Events Relevant to BWRs Identifies During TMI Incident "Licensee action required O'REILLY, J P Region 2. Atlanta. Office of the Director 79/04/14 2pp
- 7905030141 Forwards IE Bulletin 79-09. "Failures of GE Type AK-2 Circuit Breater in Safety-Related Sys " Licensee action required O'REILLY, J.P. Region 2. Atlanta, Office of the Director
- 7905020373 Forwards IE Bulletin 79-06A.Revision i, "Raview of Operational Errors & Sys Hisalignments Identified During TMI Incident "
  O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/18 200
- 7905010517 Forwards restated paragraph from 770330 itr. submitted as revision to GA program in response to IE Insp Repts 50-324/79-02 & 50-325/79-02 Paragraph discusses radiation survey/measuring instruments
  UTLEY.E E Carolina Power & Light Co 79/04/23 2pp
- 7905240192 Responds to IE Bulletin 79-07. "Seismic Stress Analysis of Safety-related Piping " Mill reanalyte all remaining safety-related piping as soon as NRC ack that specified criteria is acceptable Mysupporting documentation UTLEY.E E Carolina Power & Light Co 79/04/24 Spp
- 7903300283 Responds to IE Bulletin 79-01 Search of plant documentation indicates no Velan suing check valves w/diameter of S-10 inches are used at facility UTLEY.E E Carolina Power & Light Co 79/04/30 1p
- 7905210165 Supplements 790424 response to IE Bulletin 79-07 re reanalysis of computer programs used for safety-related piping Addi program verification has been performed by running NRC-approved Senchmark cases UTLEY.E E Carolina Power & Light Co 79/05/15 7pp
- 7905230544 Forwards response to 790516 request for add1 info re smismic analysis of safety-related piping Supplements util's 790424 & 790514 responses to IE Bulletin 79-07 FURR.B J. Carolina Power & Light Co. 79/05/21 34pg.
- R. Periodic operating reports & related correspondence

's monthly operating rept for Apr 1979, 'na Power & Light Co 79/05/09 1p

> rept for Apr 1979 Fight Co 79/05/01 13pp

... . .. , elated correspondence

- 7905080504 Forwards LER 79-013/03L-0 W/o encl FURR:B J. Carolina Power & Light Co 79/03/04 ip
- ---7905080518 LER 79-013/03L-0 on 790406 several Tech Spec items not performed at proper intervals Caused by oversight in procedures.Periodic testing procedures revised.

  TDLLISCN:A C Carolina Power & Light Co. 79/05/04 3pp
- 7905090321 Forwards LER 79-020/03L-0 FURR: 8 d. Carolina Power & Light Co 79/05/07 1p.
- --7905090324 LER 79-020/03L-0 on 790408 during containment isolation valve local leak rate testrisolation valves did not seat & held pressure. Caused by valve bushing wear. Bushings replaced TOLLISON, A. C. Carolina Power & Light Co. 79/05/07. ip

- 7905090340 Forwards LER 79-016/03L-0 FURR, B J Carolina Power & Light Co 79/05/07 1a
- --7905090344 LER 79-016/03L-0 on 790417 during insp of fire protects:
  systisolation valves for makeup water treatment area
  sprintler systemes shut Caused by isolation valves being
  isolated due to extensive mod of fire protection sys
  TOLLISON.A C Carolina Power & Light Co 79/05/07 2pp
- 7905150427 Forwards LER 79-011/03L-0 FURR, B J Carolina Power & Light Co 79/05/09 1p.
- --7905150432 LER 79-011/03L-0 on 790419 while performing normal pure of drywell operator discovered 1-CAV-VIO isolation valve would not shut Caused by pneumatic flow restrictor in closing circuit being closed, preventing valve from closing TOLLIBON.A C Carolina Power & Light Co 79/03/09 ip
- 7905150506 Forwards LER 79-018/03L-0 FURR.B J Carolina Power & Light Co 79/05/09 1p
- --7905150518 LER 79-018/03L-0 on 790414 main steam relief valve opens 320 lb psig & immediately reseated.causing reactor scram due to high flux spike on intermediate range monitors TOLLISON.A C Carolina Power & Light Co 79/03/09 ip
- 7905230615 Submits 14-day radiological environ event rept sadicactive waste was shipped on 790503 w/radiation levels exceeding ETS Incident to be reviewed & health physics radwaste shipment procedures revised BANKS.H R Carolina Power & Light Co 79/05/16 2pp
- 7905220342 Forwards LER 79-008/03X-1 BANKS.H R Carolina Power & Light Co 79/05/19 1p
- --7903220345 LER 77-008/03X-1 on 770112 while performing two water secomponent test, high vibration levels discovered Caused by restrictor bushing seized to & rotating w/shaft. New impeller installed TOLLIBON.A C Carolina Power & Light Co 79/05/18 2pp
- 7905220361 Forwards LER 79-015/03X-1 BANKS,H R Carolina Power & Light Co 79/05/18 Lp
- --7905220349 LER 79-015/03X-1 on 790308 Hergen-Peterson snobker 1011-16881 failed to lock up Cause undetermined Shubber disassembled & new seals installed TOLLISON.A C Carolina Power & Light Co 79/05/18 lp
- 7905220367 Forwards LER 79-001/03X-1 BANKS, H R Carolina Power & Light Co 79/05/10 Lp
- --7905220373 LER 79-001/03X-1 on 790104 while performing FECT instit response test. HPCI turbine failed response time requirement Caused by misalignment of parameters on governor assembly Assembly realigned TOLLISON.A C Carolina Power & Light Co 79/05/18 2pp
- 7905240630 Forwards LER 79-021/03L-0 FURR: B J Carolina Power & Light Cg 79/05/21 ip
- --7905240637 LER 79-021/03L-0 on 790420:1-CAC-1263 drywell hydragen is oxygen monitor gave abnormally low reading Caused by rusted level switch for condensate pot preventing moisture buildup from draining.

  TOLLIGBON, A. C. Carolina Power & Light Co 79/05/21 2pp
- 7703250413 Forwards LER 77-017/03L-0, BANKB,H R Carolina Power & Light Co 79/05/22 is
- ---7905250419 LER 79-017/03L-0 on 790417 while auxiliary operator was hanging clearance on RHR pumps 2A & 2C, control operator noticed pumps were still energized Gaused by clearance listing Unit 1 instead of Unit 2. Clearance was corrected TOLLISON.A.C Carolina Power & Light Co. 79/05/22 2gp
- 7905300425 Forwards LER 79-012/03L-0.
  BANKB:H R Carolina Power & Light Co. 79/05/24 1p
- ---7903300432 LER 79-012/03L-O on 790425:no indication at notch 34 fer control rod 34-27 Caused by short in switch for notch 34 Mire insulated & switch returned to svc TOLLISON.A.C Garolina Power & Light Co. 79/05/24 | p
- 7903300512 Forwards LER 79-023/03L-0. BANKS:H R. Carolina Power & Light Co 79/05/25 ip.

- --7905300518 LER 79-023/03L-0 on 790429 control rod 10-07 did not have indication at notch Caused by electrical problem in prototypic inlet piping probe located in drywell Problem will be corrected at next outage when drywell is accessible FOLLIBON, A. C. Carolina Power & Light Co. 79/05/25 10
- DOCKET 50-326 UNIV OF CALIFORNIA AT IRVING RES REACTOR
- J. Insurance & indemnity information
- 7705160221 Forwards Amend 8 to Indemnity Agreement E-53, per 10CFR140 changes, re liability insurance increase from \$140 million to \$160 million effective 770501 Supporting documentation encl SALTZMAN, J Antitrust & Indemnity Group 79705/01 Spp
- DOCKET 50-327 SEGUDYAH NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 7905030080 Responds to 790412 itr requesting facility be responsible for monitoring discharges Monitoring is planned by TVA & required by NRC Ltr is being referred to NRC for more specific response MAPLANIC H Environmental Protection Agency 79/04/26 ip
- DOCKET 50-327 SEGUDYAH NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 7905040500 Forwards description of filters to remove air discharged from auxiliary bldg Changes implemented pursuant to 740730-31 OL hearings HILLS.L M Tennessee Valley Authority 79/04/30 6pp
- 7905070954 Requests mod of state certification of Natl Pollution Discharge Elimination Sys permit TN0026450 re conditions 4d & 4f. MDORE: NO Tennesses Valley Authority 79/05/01 2pp
- 7905010314 Submits Amend 41 to application consisting of revisions to certain chapters, responses & revised responses to NRC questions, further documentation to items already transmitted & FSAR tert changes Wo encl OILLELAND, J E Tennessee Valley Authority 79/05/24 1p
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 790311000B Forwards TVA's responses to five SER outstanding confirmatory items Responses will be incorporated into Amend 61 of FBAR OILLELAND, J E Tennessee Valley Authority 79/05/08 43pp
- 7905230319 Forwards comments from review of Mar 1979 SER apparent discrepancies between SER content & info provided to NRC supporting license application OILLELAND, J.F. Tennessee Valley Authority 79/05/17 Spp
- F Becurity, medical, emergency & fire protection plans
- 7905150649 Forwards comments which should be incorporated into modified amended security plan Comments withheld (ref 10CFR2 790) VARQA, 8 A Light Hater Reactors Branch 4 79/04/27 2pp
- 7905070420 Forwards revisions to physical security plan Ravisions withheld (ref 10CFR2.790)
  OILLELAND, J. E. Tennessee Valley Authority 79/05/01 ip
- 7905090341 Submits requested info on radiological emergency plan.
  Changes make plan consistent w/TVA responses to NRC
  questions on Watts Bar Nuclear Plant Will forward final
  revision by 790415.
  GILLELAND J E Tennessee Valley Authority 79/05/07 190pp
- J. Insurance & Indemnity information
- 7905010327 Forwards ANI Becondary Financial Protection Binder EB-66 DUCK.J.R Harsh & McLenon, M & M Nuclear Consultants, Inc. Div 79/04/25. 4pp
- 7908070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 23, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 179, 179, 180, 182, 183, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, % others GUATTROCHHI, J American Nuclear Insurers 79,03/01 Ip

- 7903160230 Forwards Amend 3 to Indemnity Agreement 8-82, per iOCFR140 changes, re liability insurance increase from \$140 million to \$160 million.effective 790501 Eupporting documentation encl SALTZHAN, J Antitrust & Indemnity Group 79/05/01 Spp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 7905300299 Amend 61 to FSAR
  \* Tennessee Valley Authority 79/05/25 250pp
- 7905300305 Forwards nonpreprietary version of FSAR Table 97 60-1, as revised by Amend 61
  OILLELAND, J E Tennessee Valley Authority 79/05/25 5pp
- P Operating license stage documents & correspondence
- 7905020490 Discusses 790315 telcon w/R Sero of Westinghouse re incorrect weights for Velan Hodel C650 6-inch check valves used in safety injection sys SCHMENGER: A Operating Reactors Branch 1 79/04/02 ip
- Q Inspection reports, IE Bulletins & correspondence
- 7905020435 Forwards IE Insp Repts 50-327/79-13 & 50-328/79-08 on 790206-09 No opposepliance noted MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/08 2pp
- --7905020442 IE Insp Repts 50-327/79-13 & 50-328/79-08 on 790206-09 No honcompliance noted Major areas inspected auxiliary bldg const status, storage & housekeeping of electrical panels & review of instrumentation records MALTERS,D K Region 2, Atlanta, Office of the Director-BRYANT.J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/07 3pp
- 7905070078 Forwards IE Insp Repts 50-327/79-14 & 50-328/79-09 on 790212-18 No noncompliance noted BUTHERLAND, J Region 2. Atlanta, Fuel Facility & Materials Bafaty Branch 79/03/14 2pp
- --7905070084 IE Insp Repts 50-327/79-14 & 50-328/79-09 on 790212-15 No noncompliance noted Hajor areas inspected mgt control, environ monitoring data, analytical sensitivity for radiological samples & GC measures.

  PERY, W M Region 2, Atlanta, Fuel Facility & Materials Bafety Branch MACARTHUR, TC, HUFHAM, J M Region 2, Atlanta, Office of the Director 79/03/13 3pp
- 7905240272 Forwards IE Insp Repts 50-327/79-11 & 50-328/79-06 on 790205-07 No noncompliance noted MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/20 2pp
- --7905240307 IE Insp Repts 50-327/79-11 & 50-328/79-06 on 790205-07 No noncompliance noted Major areas inspected licensee action on previous insp findings & environ qualification of safety-related electrical equipment OIBBONS, T D Region 2, Atlanta: Office of the Director BRYANT, J C Region 2, Atlanta: Reactor Construction & Engineering Support Branch. 79/03/14 Spp.
- 7903010211 Forwards IE Info Notice 79-06, "Etress Analysis of Eafsty-Related Piping " O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/23 2pp
- 7903010113 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air "
  O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/28 2pp
- 7905010363 Forwards IE Info Notice 79-07, "Spill of Radioactively Contaminated Resin " O'REILLV." Region 2, Atlanta, Office of the Director 79/03/30 2pp.

- 7905240483 Forwards IE Insp Rept 50-327/79-16 on 790213-0216 No noncompliance noted LENIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 79/04/04 2pp
- --7905240491 IE Insp Rept 50-327/79-16 on 790213-0216 No honcompliance noted Major areas inspected startup test procedures crana testing, fuel handling aquipment testing & review of boron analysis procedures BURNETT.P T , SAUER.R C Region 2, Atlanta, Office of the Director MARTIN.R D Region 2, Atlanta, Reactor Operations 79/04/03 Spp
- 7903030368 Forwards IE Bullstin 79-07, "Seismic Stress Analysis of Bafesty-Related Piping " Licensee action required O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 Jpp
- 7905040233 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident " O'REILLY.J P Region 2, Atlanta, Office of the Director 79/04/14 3pp
- 7905110365 Forwards IE Builetin 79-08, "Events Relevant to Boiling Mater Power Reactors Identified During TMI Incident " O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 ip
- 79030:0341 Forwards IE Info Notice 79-10. "Nonconforming Pipe Support Struts"

  O'REILLY, J P Region 2. Atlanta: Office of the Director, 79/04/16 16
- 7903030172 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breater in Bafety-Related Sys " Licensee action required O'REILLY, J P 79704/17 200
- 7905020495 Forwards IE Bulletin 79-06A.Revision 1, "Review of Operational Errors & Sus Misalignments Identified During TMI Incident " O'REILLY, J P Region 2, Atlanta, Office of the Director 79704718 2pp
- 7905300283 Submits supplemental response to IE Bulletin 77-07 Original response submitted 780120 Provides addl info received from manufacturer & describes plans in area of electrical penetrations
  OILLELAND, J E Tennessee Valley Authority 79/04/27 Bpp
- 7905140272 Responds to IE Bulletins 79-06A & 79-06A Revision 1, re review of operational errors during TMI, Pressurizer level bistables in coincident safety injection logic circuits will remain tripped except during testing OILLELAND, J F Tennessee Valley Authority 79/05/07 1p
- 7905290363 Forwards Revision 7 to "Preservice Baseline Insp & Inservice Insp Program for TVA" incorporating responses to Matl Engineering Branch 781208 questions OILLELAND.J E Tennessee Valley Authority 79/05/22 83pp

k related correspondence

deficiency rept re vibration in

wthority 79/03/09 is

during preoperational pipe occurred near stallation of RHR flow g studied. O7 2pp

- frequency of Tennessee Valley Authority 79/03/27 ip
- ---7905140497 Final deficiency rept forced vibration test showed RHR pump IA natural frequency does not meet design requirements RHR sys was reanalyzed, resulting in changed nozzle loads on pump & local pipe supports to meet new support loads Tennessee Valley Authority 79/03/27 1p
- 7905140446 Forwards final deficiency rept re safety injection sys accumulator level transmitter lines.
  OILLELAND, J. E Tennessee Valley Authority, 79/03/30, 1p
- --7905140451 Final deficiency rept use of Class O instead of Class G safety injection sys accumulator level transmitter lines from root valves to flanges. Nonsafety-grade, nonseismic Category I plping will be replaced a Tennessee Valley Authority 70/00/00

- 7905140352 Forwards final deficiency rept re overheating of bearings motor-friven auxiliary feedwater pumps.
  GILLELAND, J E Tennessee Valley Authority 79/04/09 Lp
- --7905140363 Final deficiency rept.during initial operation, bearings motor-driven auxiliary feedwater pumps were overheating Caused by design error Ingersoll-Rand presently modifying pumps Tennessee Valley Authority 79/04/09 ip
- 7905140468 Forwards first deficiency rept re incorrect analysis of essential raw cooling water sys piping over total temprange OILLELAND. J E Tennessee Valley Authority 79/04/18 2pp
- --7905140473 First interim deficiency rept essential raw cooling walk sys piping in auxiliary bldg Piping not analyzed for full thermal range defined in ASME code Reanalysis in progress a Tennessee Valley Authority 79/04/18. Ip
- 7905140458 Forwards deficiency rept re incorrect weight of swing cas: valves OILLELAND, J E Tennessee Valley Authority 79/04/19 ip
- --7905140464 Deficiency rept weight of swing check valves mfg by Vete
  Engineering Co was incorrect on Velan drawing 78704 Waight
  shown was 225 lbishould have been 450 lb Piping containing
  valves being analyzed
  \* Tennessee Valley Authority 79/04/19 ip
- 7905140495 Forwards first interim deficiency rept re overstresses penetrations in containment shell.
  GILLELAND.J E Tennesses Vallay Authority 79/04/19 ip
- --7905140300 First interim rept deficient design of four penetrations insert plate around containment spray & residual heat removal sys containment nozzles Computer models of piping supports revised & info sent to contractor for analysis \* Tennessee Valley Authority 79/04/19 ip
- 7905040552 Forwards final deficiency rept re diesel generator relief tachometer failures reported 790130 All overheated diodes replaced & tachometers closely monitored QILLELAND, J. E. Tennessee Valley Authority 79/04/30 Spp
- 7905090333 Forwards final rept re installation of improper colls in auxiliary feedwater & emergency gas treatment sys GILLELAND, J E Tennessee Valley Authority, 79/05/01, 2pp
- ---7903090336 Final deficiency rept during preoperational testing four instances were found where improper coils were installed in control circuits Design drawing altered & correct coils procurred OILLELAND, J & Tennassee Valley Authority 79/05/01 ip
- 7905110191 Forwards final rept of deficiency initially reported ##24: re fire hazard analysis.
  OILLELAND, J E Tennessee Valley Authority 79/05/04 lp
- ---7905110175 Deficiency rept.vapor barrier is combustible & constitut fire load not considered in fire hazard analysis Batt will be covered w/i-inch thick stainless steel plate in Units 1 & 2 \* Tennessae Valley Authority 79/05/04. ip
- 7905190197 Provides second interim rept of 790208 deficiency to vibration in RHR piping. Variable spring supports added to valve operators & one pipe support installed. Vibration problems resolved.

  OILLELAND, J. E. Tennessee Valley Authority 79/05/08 sp
- 7905160303 Provides final deficiency rept on control loop bistables failing to an undesirable position on loss of control power W/o ancl
  OILLELAND.J E Tennessee Valley Authority 79/05/10. 1p
- 7905230562 Forwards final deficiency rept on potential excessive wate hammer forces in main feedwater sys OILLELAND, J E Tennessee Valley Authority 79/05/16 1p
- ---7903230369 Final deficiency rept:potential excessive water hamar forces in main feedwater sys Procedures implemented at design stage to prevent recurrence.

  \* Tennessee Valley Authority. 79/03/16 2pp.
- 7905230645 Forwards final deficiency rapt on incorract thermal analysis of piping QILLELAND, J E Tennessee Valley Authority, 79/08/17 tp.

- --7905230654 Final deficiency rept incorrect thermal analysis of piping which was not analysed over total temp range as defined by ANSI std New analyses performed for some piping in auxiliary bldg & Unit 1 reactor bldg remnessee Valley Authority 79/05/17 2pp
- DOCKET SO-328 SEGUDYAH NUCLEAR PLANT, UNIT 2

  A Application/construction stage documents & correspondence
- 7905030030 Responds to 790412 itr requesting facility be responsible for monitoring discharges Monitoring is planned by TVA & required by NRC Ltr is being referred to NRC for more passible response (APLANCC, Is. Environmental Protection Agency 79/04/26 ip
- 7903040300 Forwards description of filters to remove air discharged from auxiliary bids Changes implemented pursuant to 740730-31 OL hearings MILLS, L. M Tennesses Valley Authority 79/04/30 App
- 7905070554 Requests mad of state certification of Natl Pollution Discharge Elimination Sys permit TN0026450 re conditions Ad & 42 HOURE, FI. Co. Tennessee Valley Authority 79/05/01 2pp
- 7909310014 Sebmits Amend 61 to application consisting of revisions to certain chapters, responses & revised responses to NRC questions, further documentation to items already transmitted k FSAR taxt changes Wo encl pillELAND. JE Tennesses Vailey Authority 79/05/24 ip
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 7905110000 Forwards TVA's responses to five BER outstanding confirmatory items Responses will be incorporated into Amend 61 of FSAR.
  OILLELAND, JE Tennessee Valley Authority 79/05/08 43pp
- 7905230519 Forwards comments from review of Mar 1979 SER apparent discrepancies between SER content & info provided to NRC supporting license application Oilleland JF Tennessee Valley Authority 79/05/17 Spp
- F Security. medical, emergency & fire protection plans
- 7905150649 Forwards comments which should be incorporated into modified amended security plan Comments withheld (ref 10CFR2 790) VAROA, S. A. Light Water Reactors Branch 4 79/04/27 2pp
- 7905070420 Forwards revisions to physical security plan Revisions withheld Cref 100FR2 790) OILLELAND. J.E Tennesses Valley Authority 79/05/01 ip
- 7905090341 Sebmits requested info on radiological emergency plan. Changes make plan consistent w/TVA responses to NRC questions on Watts Bar Nuclear Plant, Will forward final revision by 790615
  OLLELAND, J E Tennessee Valley Authority 79/05/07, 150pp.
- J Insurance & indemnity information
- 7905010527 Forwards ANI Secondary Financial Protection Binder E8-66 DUCK, J. R. Plarsh & McLenon, M & M Nuclear Consultants, Inc Div 79704/25. 6pp
- 7903070 497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,176,197,190,182,185,186,187,188,189,192,193,194,195,197,190,200,201,204,206,207,208,210,212,214,215,& others QUATTROCHHI, J American Nuclear Insurers 79/05/01 ip
- 7905070-582 Confirms increase in liability limit to \$36,000,000 for policies MF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,56,57,58,60,-21,64,66,67,68,69,70,71,72,74,76,77,78,79,79,60,86,87,88,90,91,92,93,94,95 & 96
  ROBERTS. D. M Mutual Atomic Energy Liability Underwriters. 79/05/01
- K Utility Final Safety Analysis Report (FBAR) & amends
- 79053000299 Amend 61 to FSAR \* Tennesses Valley Authority, 79/05/25 250pp
- 7903300의 Forwards nonproprietary version of FSAR Table 07 60~1.as revised by Amend 61 이니(ELAND: J. E. Tennesses Valley Authority 79/05/25 5pp

- P Operating license stage documents & correspondence
- 7905020490 Discusses 790315 telcon w/R Sero of Westinghouse re incorrect weights for Velan Model C658 6-inch check valves used in safety injection sys SCHMENCER.A Operating Reactors Branch 1 79/04/02 ip
- @ Inspection reports, IE Bullstins & correspondence
- 7905020436 Forwards IE Insp Repts 50-327/79-13 & 50-328/79-08 on 790206-09 No noncompliance noted MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Bupport Brench 79/03/08 2pp
- --7905020442 IE insp Repts 50-327/79-13 & 50-328/79-08 on 790206-07 No nuncompliance noted Major areas inspected auxiliary bldg const status, storage & housekeeping of electrical penels & review of instrumentation records WALTERS, D K. Region 2, Atlanta, Office of the Director BRYANT, J C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/03/07. 3pp
- 7905070078 Forward: IE Insp Repts 50-327/79-14 & 50-328/79-09 on 790212-15 No noncompliance noted.
  SUTHERLAND, J T Region 2. Atlanta: Fuel Facility & Materials Safety Branch 79/03/14 2pp
- ---7905070084 IE Insp Repts 50-327/79-14 & 50-328/79-09 on 790212-15 No noncompliance noted Major areas inspected mgt control. environ monitoring data analytical sensitivity for radiological samples & QC measures PERY.W W Region 2. Atlanta, Fuel Facility & Materials Safety Branch MAGARTHUR, T.C., HUFHAM, J.W. Region 2, Atlanta, Office of the Director 79/03/13 3pp
- 7703240292 Forwards IE Insp Repts 50-327/79-11 & 50-328/79-06 on 790203-07 No noncompliance moted MURPHY,C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/03/20 2pp
- ---7905240307 IE Insp Repts 30-327/79-11 & 50-328/79-06 on 790205-07 No noncompliance noted Major areas inspected licensee action on previous insp findings & environ qualification of safety-related electrical equipment OIBBONS,T D Region 2, Atlanta, Office of the Director BRYANT.J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/03/14 Spp
- 790301021: Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping" O'REILLY, P Region 2, Atlanta, Office of the Director 79703/23 2pp
- 7905030368 Forwards IE Bulletin 79-07, "Belemic Stress Analysis of Bafety-Related Piping." Licensee action required O'REILLY.J P Region 2. Atlanta, Office of the Director 79/04/14 3pp
- 7903040233 Forwards IE Bulletin 79-068, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident "O'REILLY.J.P. Region 2. Atlanta. Office of the Director 79/04/14 3pp

- 7905140272 Responds to IE Bulletins 79-06A & 79-06A, Revision 1, re review of operational errors during TMI Pressurizer level bistables in coincident safety injection logic circuits will remain tripped except during testing OllLELAND. J F Tennessee Valley Authority 79/05/07 1p
- 7905290363 Forwards Revision 7 to "Preservice Baseline Insp & Inservice Insp Program for TVA" incorporating responses to Hati Engineering Branch 781208 questions GILLELAND.J E Tennessee Valley Authority 79/05/22 83pp
- B Reportable occurrences, LERs & related correspondence
- 7905160455 Forwards first interim deficiency rept re vibration in RHR piping OILLELAND, J E Tennessee Valley Authority 79/03/09 1p
- --7903160460 First interim deficiency rept during preoperational pipe vibration testing excessive vibration occurred neer butterfly valves Caused by improper installation of RHR flow control valves Corrective actions being studied • Tennessee Valley Authority 79/03/09 2pp
- 7705140476 Forwards final deficiency rept re RHR pump 1A natural frequency OILCEAND.J E Tennessee Valley Authority 79/03/27 1p
- --7905140497 Final deficiency rept forced vibration test showed RHR pump IA natural frequency does not meet design requirements RHR sys was reanalyzed, resulting in changed norse loads on pump & local pipe supports to meet new support loads • Tennessee Valley Authority 79/03/27 Ip
- 7905140446 Forwards final deficiency rept re safety injection sys accumulator level transmitter lines OILLELAND.J E Tennessee Valley Authority 79/03/30 1p
- --7903140451 Final deficiency rept use of Class O instead of Class C safety injection sys accumulator level transmitter lines from root valves to flanges Nonsafety-grade nonselamic Category I piping will be replaced a Tennessee Valley Authority 79/03/30 ip
- 7905140352 Forwards final deficiency rept re overheating of bearings in motor-driven auxiliary feedwater pumps GILLELAND, J.E. Tennessee Valley Authority 79/04/09 1p
- ---7905140363 Final deficiency rept during initial operation, bearings in motor-driven auxiliary feedwater pumps were overheating Caused by design error Ingersoil-Rand presently modifying pumps \* Tennessee Valley Authority 79/04/09 1p
- 7905140468 Forwards first deficiency rept re incorrect analysis of assential raw cooling water sys piping over total temp range OILLELAND, J E Tennesse Valley Authority 79/04/18 2pp
- ---7905140473 First interim deficiency rept essential raw cooling water sys piging in auxiliary bldp Piping not analyzed for full thermal range defined in ASME code Reenalysis in progress Tennessee Valley Authority. 79/04/18 1p
- 7905140458 Forwards deficiency rept re incorrect weight of swing check valves
  OILLELAND, J E Tennessee Valley Authority 79/04/19. 1p
- --7905140464 Deficiency rept weight of swing check valves mfg by Velan Engineering Co was incorrect on Velan drawing 78704 Height shown was 225 birshould have been 450 ib Piping containing valves being analyzed \* Tennessee Valley Authority 79/04/19 ip
- 7905140495 Forwards first interim deficiency rept re overstressed penetrations in containment shell QILLELAND, J.E Tennessee Vailey Authority. 79/04/19 ip
- --7905140500 First interim rept deficient design of four penetrations in insert plate around containment spray & residual heat removal sys containment norlles Computer models of piping supports revised & info sent to contractor for analysis a Tennessee Valley Authority 79/04/19 ip
- 7703040562 Forwards final deficiency rept re diesel generator relay tachometer failures reported 770130 All overheated diodes replaced & tachometers closely monitored OILLELAND. J E Tennessee Valley Authority 79/04/30 3pp
- 7905110171 Forwards final rept of deficiency initially reported 790404 re fire hazard analysis GILLELAND, J E Tennessee Valley Authority 79/08/04 lp.

- --7905i10195 Deficiency meet vapor barrier is combustible & const fire load not considered in fire hazard analysis Belt will be covered w/i-inch thick stainless steel plate in Units 1 & 2 e Tennessee Valley Authority 79/05/04 1p
- 7905190197 Provides second interim rept of 790208 deficiency we vibration in RHR piping Variable spring supports added to valve operators & one pipe support installed Vibration problems resolved GILLELAND, J E Tennessee Valley Authority 79/08/08 1p
- 7903160303 Provides final deficiency rapt on control loop bistable failing to an undetirable position on loss of control power W/o encl.

  GILLELAND.J E Tennessae Valley Authority 79/09/10 ip
- 7905230362 Forwards final deficiency rept on potential excessive hammer forces in main feedwater sys. OILLELAND.J E Tennessee Valley Authority 79/09/16 ip
- --7905230567 Final deficiency reptrpotential excassive water haw forces in main feedwater sys Procedures implemented at design stage to prevent recurrence \* Tennessee Valley Authority 79/05/16 2pp
- 7905230645 Forwards final deficiency rept on incorrect thermal analysis of piping OILLELAND, J E Tennessee Valley Authority, 79/05/17 1p
- --7908230654 Final deficiency rept incorrect thermal analysis of which was not analysed over total temp range, as defined by AMBI sto New analyses performed for some piping in auxiliary blog & Unit i reactor blog # Tennessee Valley Authority 79/05/17 2pp
- DOCKET 50-329 MIDLAND PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 7908290415 Notification of 790809 meeting w/util in Betheeda,HD | discuss status of safety & environmental review schedule Date changed from 790403 HOODD B Light Water Reactors Branch 4 79/03/23 Opp
- 7905040462 Responds to NRG 790412 ltm. Discusses analysis of cooli lake impact on local traffic due to icing & fogging NRC requires fog/ice monitoring programs Describes rejevant studies CARBON-J E Argonne National Laboratory 79/04/20 Opp.
- 7905310360 Indicates state will withhold Section 401(4)(1) of certification of facilities until EIS is approved by MI Environ Review Board TANNER, H. A. Michigan, State of 79/05/17 2pp
- 7705250526 Responds to NRC 781011 ltr.Forwards "Investigation of Thermal Plume in Bhallow River, Hydrothermal Model Studies. Cooling Pond Blowdown Discharge" & "Midland Power Plant Cooling Pond Operation Study"
  HGWELL, 8 H Consumers Power Co 79/05/21 ip.
- --7905250528 "Investigation of Thermal Plume in Shallow River.

  Hydrothermal Model Studies, Cooling Pond Blowdown Dischargs."

  prepared by Alden Reswarch Lab for facility.

  ROBERGE\_J C. NYQUIST.R O Consumers Power Co. 45-79/H124&5

  79/04/30, 79pp
- ---7905230530 "Midland Plant Cooling Pond Operation Study." preps: Bechtel LIOU,C.P.: PAPADAKIS,C N Consumers Power Co. 45-79/H124AF 79/03/31 60pp.
- C Utility Environmental Report (ER), amends & correspondence
- 7905030358 Forwards Amend 64 to CP & OL. HONELLIS H Consumers Power Go. 79/04/30 1p
- --7905030362 Amend 64 to CP & DL.consisting of revised pages for Revision 8 to environ rept. HOWELL:8 H Consumers Power Co 79/04/30 41pp.
- 7905110207 Forwards affidavit of distribution of environ rept.DC. Amend 64.Revision 8 DAGUD,L. Consumers Power Co 79/05/07, 4pp.

#### Q Adjudicatory correspondence

- 7709250238 Forwards 100FR50 58(e) repts re spray piping supports Q1886,M E Isham, Lincoln & Beals 79/03/23 1p
- 7905160216 Forwards final evaluation of items discussed in 790228 memo re B&W-designed nuclear plants Requests addl info be forwarded to licensing boards
  MGBLEY, N.C. Division of Reactor Operations Inspections 79/03/28
- 7905160163 Forwards Board Notification 79-10 on reactor inspector concerns re BMW plants Certificate of Svc encl SCINTO, J.F. Hearings Division 79/03/29 14pp
- --7905160185 Board notification reactor inspactor concerns re B&W plants VASSALLO, D B. Assistant Director for Light Water Reactors 79/03/06 2pp
- --7905160201 Forwards two Moseley-to-Thompson memos for Board notification info THOMPSON.D Office of I & E Executive Officer for Operations Support 79/03/29 ip
- --7903160207 Informs that preliminary evoluation of Item 3 contained in 790320 memo will be reviewed in light of TMI transient Addl info may cause change in previous assessment MOSCLY.N C Division of Reactor Operations Inspections 79/03/27 ip.
- 7905240499 Notice of appearance on behalf of NRC DAMDLY.D C Operations & Administrative Division 79/03/30 1p
- 7903230438 Response to 790104 order by all intervenors except Dow Chemical Co Urges thorough examination of util's conduct.
  Certificate of Svc oncl
  FLYNN.P Cherry, H H /Cherry, Flynn & Kanter 79/03/30 20pp
- 7903310028 NRC response to ASLB 790104 order requesting add1 info from parties. Designates portions of prior record for consideration Provides names of persons having relevant info Certificate of Byc enc1
  OLMSTEAD.W J , NOEFLINO.R K Branch 4 DAMBLY.D Operations & Administrative Division 79/03/30 9pp
- 7905160112 Doard notification nuclear incident at TMI.Recommends boards on cases involving DAM reactors be provided w/IE Bulletin 79-05 & PNO-67 & 67A,B,G,D,E,F,G & H VABBALLO,D II Assistant Director for Light Water Reactors 79/04/03 Rpp
- 7908250163 Revises description of cooling sys for special prehearing conference order QIBBS.M.E. Isham, Lincoln & Beale, 79/04/03 2pp
- 7905290840 Forwards interim rept re discrepancies discovered in inboard terminal boxes of electrical penetration assemblies.
  OIBBB.M E. Ishem, Lincoln & Deale, 79/04/03 ip
- 7905290108 Notice of prehearing conference to begin on 790501 in Estherda. HD HILLER, M E Atomic Gafety and Licensing Doard Panel 79/04/09 ip.
- 7905130240 Opposes 790330 motion by util for summary disposition re Part 2 of ABLB 790104 order re remanded issues Motion is premature since no preheating conference has yet been held Cartificate of Svc entl. OLMSTEAD.W J Branch 4 79/04/19 5pp
- 7903130203 Hemo & order ALAB-541 denies 790424 motion by intervenors to postpone & relocate 790501 prehearing conference Allows ASLB to reconsider 790409 order DUFLO-M E Atomic Bafety and Licensing Appeal Panel. 79/04/27 5pp
- 7905240885 Denies intervenors 790424 motion to reschedule 790501 prehearing conference or change location of hearing HILLER, M.E. Atomic Safety and Licensing Board Panel 79/04/27
- --7905240891 Mation by intevenors to schedule 790301 prehearing conference & change location of hearing FLYNN.P. Cherry, M. M./Cherry, Flynn & Kanter 79/04/24 Gpp
- ---7905240899 Urges postponement of 790301 prehearing conference, due to inability of intervanor's counsel to attend FLYNN, P Cherry, H M./Cherry, Flynn & Kanter, 79/04/24 5pp

#### H General correspondence

- 7905090307 Forwards Certificate of Svc of Amend 63 (Revision 20 to FBAR) to application for CP & OL BACON, J L Consumers Power Co 79/05/02 2pp
- J Insurance & indemnity information
- 7905070497 Confirms increased liability limit to \$124,000.000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,185,186,187,188,187,192,193,194,195,197,198,200,201,204,206,207,208,210,212,214,215,&others QUATTROCHHI,J American Nuclear Insurers 79/05/01 ip
- K Utility Final Safety Analysis Report (FBAR) & amends
- 7905030308 Forwards Amend 63 to application for CP & OL which constitutes Revision 20 to FSAR Certificate of Syc & revised matl to supplemental ref drawings encl HOWELLS H Consumers Power Co 79/04/26 2pp
- --7905030311 Revision 20 to F8AR
  \* Consumers Power Co 79/04/26 240pp

#### M Antitrust correspondence

- 7905230832 Requests antitrust info for addl ownership participants to expedite processing of amend or transfer of license TOALBTON.A L Antitrust & Indemnity Group 79/04/23 Ppp
- Q Inspection reports. IE Bulletins & correspondence
- 7905020166 Forwards IE Insp Repts 50-329/78-20 & 50-330/78-20 on 781211-13, 18-20, 790104-05, 09-11, 22-25, 0223 & 0305
  KEPPLER, J G Region 3, Chicago, Office of the Director 79/03/22
- --7905020172 IE Insp Repts 50-329/78-20 & 50-330/78-20 on 781211-13, 18-20, 790104-05, 09-11, 22-25, 0223 & 0305 No noncompliance noted Major areas inspected diesel generator bidg foundations & unusual settlement of bidg FIORELLI. © Region 3, Chicago, Reactor Construction & Engineering Support Branch NORELUS. C E. HAYES, D W Region 3, Chicago, Office of the Director 79/03/17 29pp
- 7905010249 Forwards IE Info Notice 79-04, "Stress Analysis of Safety-Related Piping" KEPPLER, J Q Region 3, Chicago. Office of the Director 79/03/23
- 7905080529 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks" KEPPLER, J Q Region 3, Chicago, Office of the Director 79/03/26
- 7905290283 Forwards IE Insp Repts 50-329/79-04 % 50-330/79-04 on 790207 No noncompliance noted FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/03/29 2pp
- --7905250296 IE Insp Repts 50-329/79-04 & 50-330/79-04 on 790207 No noncompliance noted Major areas inspected project status; concerns re recent developments onsite & upcoming inspativity CODK.R.J., HANBEN.W.A. Region 3. Chicago, Office of the Director KNOP.R.C. Region 3. Chicago, Reactor Construction & Engineering Support Branch 79/03/27 App
- 7903240724 Forwards IE Insp Repts 50-329/79-06 & 50-330/79-66 on 790328-29 No noncompliance noted FICHELLI, Region 3. Chicago, Reactor Construction & Engineering Support Branch 79/04/09, 2pp
- --7903240734 IE Insp Repts 50-329/79-06 & 50-330/79-06 on 790328-29 No noncompliance noted Major areas inspected followup iOCFR50 55(e) rept re settlement of diesel generator bldg & plant area Pill GALLAGHER,E J , HAYES,D W Region 3, Chicago, Office of the Director 79/04/04 7pp
- 7905030022 Forwards IE Bulletin 79-06, "Review of Operational Errors & Bys Misslignments Identified During TMI Incident "
  KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/11

10

- 7905010583 Forwards IE Builstin 79-06A, "Review of Operational Errors % Sys Misslignments Identified During TMI Incident "
  KEPPLER, J Q Region 3. Chicago, Office of the Director 79/04/14
- 7905040331 Forwards IE Bulletin 79-068, "Review of Operational Errors & Sys Misalignments Identified During THI Incident "
  KEPPLER. J C Region 3, Chicago, Office of the Director 79/04/14
- 7905040465 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Bafety-Related Piping " Licensee action required KEPPLER.J G Region 3, Chicago, Diffice of the Director 79/04/14
- 7905040546 Forwards IE Builstin 79-08. "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident " KEPPLER, J Q Region 3. Chicago, Office of the Director 79/04/14
- 7905010387 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts " KEPPLER, J Q Region 3, Chicago, Office of the Director 79/04/16
- 7903030219 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " Licensee action required KEPPLER(J G Region 3, Chicago: Office of the Director 79/04/17
- 7905080404 Forwards IE Builetin 79-058, "Nuclear Incident at TMI-Suppl"
  KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/21
- R Periodic operating reports & related correspondence
- 7703300478 Forwards nonconformance repts for Apr 1979 HOWELL, S. H Consumers Power Co 79/05/25 1000pp
- 8 Reportable occurrences, LERs & related correspondence
- 7905290330 Ack receipt of 790307 final rept re air filtering units Review will be finished upon completion of corrective action FIORELLI, O Region 3. Chicago, Reactor Construction & Engineering Support Branch 79703/23 ip.
- 7905240549 Ack receipt of 790330 rept re electrical penetration assembly Final rept will be reviewed upon receipt FIGRELLI.O Region 3. Chicago. Reactor Construction & Engineering Support Branch 79704706 ip
- 7905140219 Forwards nonconformance rapts for Mar 1979, consisting of Bechtel nonconformance rapts, Bechtel nonconformance log, Bechtel quality audit findings, Bechtel quality action requests, B&U repts of nonconformity & util rapts.

  HGMELL, S. H Consumers Power Co 79/04/25 440pp
- 7905070501 Final deficiency rapt reactor bidy spray anchor discrepancy Local pipe stresses may potentially exceed ABME Code Section III allowables at points Existing procedural methods are adequate 

  \* Consumers Power Co 79/04/27, 4pp.
- 7905090082 Provides interim deficiency rept on actions to resolve settlement of diesal generator foundations & bldg HOMELL.S H Consumers Power Co 79/04/30 2pp
- --7903090084 Interim Deficiency Rept 5: settlement of diesel generator foundations & bldg Caused by insufficient compaction in area fill re seismic Category I structures. Lists status & corrective actions. W/62 oversized drawings.

  \* Consumers Power Co 79/04/14 10pp
- 7905030327 Final rept re reactor bidg spray piping supports. Analysis has verified adequacy of support design & ABME Section III Code allowable stresses Bechtel mgt corrective action rept McAR 22 encl.
  HOWELL:S.H Consumers Power Co 79/03/01 7pp
- 7905080532 Forwards interim rept on status of component qualification test documentation to review Forwards Becktel "Qualification Test Status Rept." Similar 85W rept will be reviewed Another rept will be sent by 790706, MOMELL.S.H. Consumers Power Co 79/05/04, 2pp.

- -7905080536 Interim rept on seismic & environ companent qualification. forwarding "Qualification Test Status Rept." Revision 7, dtd 790404.

  BALTAZR, R Z Bechtel Power Corp (subs of Bechtel Corp ) 79/04/20 39op
- 7905300252 Forwards final rept re discrepancies discovered in inhort terminal boxes HOMELLS Consumers Power Co 79/05/25 5pp
- --7905300256 Final deficiency rept on 790523 defects discovered in penetration assemblies in inboard terminal boxes, possibly caused by type of termination lug used Insp of terminations conducted

  \* Consumers Power Co 79/05/23 4pp
- T Hearing transcripts on non-antitrust matters
- 7905140364 Transcript of 790501 prehearing conference in Bethesda.MD Pp 50.001-50.171.
  MILLER.M E . LUEBKE, LEEDS Atomic Safety and Licensing Board Panel 79705/01 171pp
- 2 TINU THAIR DEALDEN OEE-08 TENDOD
- A Application/construction stage documents & correspondence
- 7905290415 Notification of 790509 meeting w/util in Bathasda. MD to discuss status of safety & environmental review schedule Date changed from 790403 HODD D B Light Water Reactors Branch 4 79/03/23 3pp
- 7905040462 Responds to NRC 790412 ltr Discusses analysis of cooling lake impact on local traffic due to icing & fogging NRC requires fog/ice monitoring programs Describes relevant studies

  CARSON, J E Argonne National Laboratory 79/04/23 3pp
- 7905310360 Indicates state will withhold Section 401(a)(i) of certification of facilities until EIS is approved by MI Environ Review Board TANNER.H A Michigan, State of 79/05/17 2pp
- 7905280526 Responds to NRC 781011 1tr Forwards "Investigation of Thermal Plume in Shallow River.Hydrothermal Model Studies, Cooling Pond Blowdown Discharge" & "Midland Power Plant Cooling Pond Operation Study" HOMELL.S H Consumers Power Co 79/05/21 1p
- --7905250528 "Investigation of Thermal Plume in Shallow River, flydrothermal Model Studies, Cooling Pond Blowdown Discharge," prepared by Alden Research Lab for facility ROBERGE, J. C., NYQUIST, R. G. Consumers Power Co.
- --7905250530 "Midland Plant Cooling Pond Operation Study," prepared by Bechtel. LIOU.C P , PAPADAKIB.C.N Consumers Power Co 45-79/NI24AF 79/03/31 60pp.
- C Utility Environmental Report (ER), amends & correspondence
- 7705030358 Forwards Amend 64 to CP & QL., HOWELL, 8 H Consumers Power Co 79/04/30 1p
- --7903030362 Amend 64 to CP & OL, consisting of ravised pages for Revision 8 to environ rept. HOMELL,8 H Consumers Power Co . 79/04/30, 41pp.
- 7905110207 Forwards affidevit of distribution of environ rept.CL stags.
  Amend 64.Revision 8
  DAGUD.L Consumers Power Co 79/05/07 4pp.
- Q Adjudicatory correspondence
- 7905250238 Forwards 10GFR50.55(e) repts re spray piping supports QIBHS.M E. Isham. Lincoln & Beale. 79/03/23 ip.
- 7905160216 Forwards final evaluation of items discussed in 790228 seas ra B&H-designed nuclear plants Requests add1 info be forwarded to licensing boards.

  MOBLEY, N C. Division of Reactor Operations Inspections. 79/03/28

- 7705160163 Forwards Board Notification 79-10 on reactor inspector concerns re B&W plants Certificate of Svc encl SCINTO, J F Hearings Division 79/03/29 14pp
- --7905160185 Board notification reactor inspector concerns re 86W plants VASSALLO, B Assistant Director for Light Water Reactors 797/03/06 2pp
- --7905160201 Forwards two Moseley-to-Thompson memos for Board notification info THOMPSON.D Office of I & E Executive Officer for Operations Bupport 79/03/29 ip
- --7903160209 Informs that preliminary evivation of Item 3 contained in 790328 memo will be reviewed in light of TM1 transient Addl info may cause change in previous assessment HGSLY-N C Division of Ruactor Operations Inspections 79/03/27 ip
- 7905240493 Notice of appearance on behalf of NRC DAMBLY, D C Operations & Administrative Division 79/03/30 ip
- 7705250438 Response to 790104 order by all intervenors except Dow Chemical Co Urges thorough examination of util's conduct Certificate of 8vc encl FLYNN.P Cherry, H M /Cherry, Flynn & Kanter 79/03/30 20pp
- 7903310028 NRC response to ASLB 790104 order requesting addl info from parties Designates portions of prior record for cansideration Provides names of persons having relevant info Certificate of Svc encl
  DLMSTEAD, W J , HOEFLING, R K Branch 4 DAMBLY, D Operations & Administrative Division 79/03/30 9pp
- 7905160112 Board notification nuclear incident at TMI Recommends boards on cases involving DAM reactors be provided w/IE Bulletin 79-05, & PND-67 & 67A, B, C, D, E, F, O & H VASSALLD, D B Assistant Director for Light Water Reactors 79704/03 2pp
- 7705250163 Revises description of cooling sys for special prehearing conference order of BBBGM E. Isham, Lincoln & Beals 79/04/03, 2pp
- 7903290540 Forwards interim rept re discrepancies discovered in inboard terminal boxes of electrical penetration assemblies GIBBS.M E Isham, Lincoln & Beale 79/04/03 1p
- 7905290108 Notice of preheating conference to begin on 790501 in Bethesda,MD MILLER,M E Atomic Safety and Licensing Board Panel 79/04/09 ip
- 7709190240 Opposes 770330 motion by util for summary disposition re Part 2 of ASLB 790104 order re remanded issues Motion is premature since no prehearing conference has yet been held Certificate of Byc enci OLMBTEAD:N J Branch 4 79/04/19 3pp
- 7905150233 Memo & order ALAB-541 denies 790424 motion by intervenors to postpone & relocate 790301 prehearing conference Allows ABLB to reconsider 790409 order DUFLOcM E. Atomic Bafety and Licensing Appeal Panel 79/04/27 Son.
- 7905240885 Denies intervenors 790424 motion to reschedule 790501 prehearing conference or change location of hearing.
  MILLER: M E Atomic Safety and Licensing Board Panel 79/04/27
  7pp
- ---7905240891 Motion by intevenors to schedule 790501 prehearing conference & change location of hearing.
  FLYNN:P Cherry, M M./Cherry, Flynn & Kanter 79/04/24 Gpp.
- ~~7905240899 Urgas postponement of 790501 prehearing conference due to inability of intervenor's counsel to attend FLYNN:F Cherry, M M /Cherry, Flynn & Kanter. 79/04/24 5pp
- H General correspondence
- 7905090307 Forwards Certificate of 8vc of Amend 60 (Revision 20 to FBAR) to application for CP & OL BACON, J.L. \* Consumers Power Co 79/05/02 2pp
- J Insurance & indomnity information
- 7705070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,185,186,187,188,189,192,193,194,195,197,199,200,201,204,204,207,208,210,212,214,215,tothers QUATTROCHHIJ American Nuclear Insurers 79/05/01 ip.

- K Utility Final Safety Analysis Report (FSAR) & amends
- 7905030309 Forwards Amend 63 to application for CP & OL which constitutes Revision 20 to FBAR Certificate of Svc & revised mat1 to supplemental ref drawings encl HDWELL, 8 H Consumers Power Co. 79/04/26 2pg
- --7905030311 Revision 20 to FBAR
  # Consumers Power Co 79/04/26 240pp
- M Antitrust correspondence
- 7905230832 Requests antitrust info for add1 ownership participants to expedite processing of amend or transfer of license TOALSTON. A L Antitrust & Indemnity Oroup 79/04/29 2pp
- Q Inspection reports. IE Bulletins & correspondence
- 7905020166 Forwards IE Insp Repts 50-329/78-20 & 50-330/78-20 on 781211-13,18-20,790104-05,09-11,22-25,0223 & 0305
  KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/22
- --7905020172 IE Insp Repts 50-329/78-20 & 50-330/78-20 on 781211-13, 18-20, 790104-05,09-11,22-25,0223 & 0305 No noncompliance noted Major areas inspected diesel generator bldg foundations & unusual sattlement of bldg FIORELLI,O Region 3. Chicago, Reactor Construction & Engineering Support Branch NORELIUS,C E. HAYES,D W. Region 3. Chicago, Office of the Director 79/03/19 29pp
- 7903010249 Forwards IE Info Notice 79-06. "Stress Analysis of Bafety-Related Piping" KEPPLER.J O Region 3. Chicago, Office of the Director 79/03/23
- 7705080529 Forwards IE Info Notics 77-07, "Rupture of Radwaste Tanks "
  KEPPLER, J G Region 3, Chicago, Office of the Director 79/03/24
- 7905280283 Forwards IE Insp Repts 30-329/79-04 & 30-330/79-04 on 790207 No noncompliance noted FIORELLI,0 Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/03/27 2pp
- ---7905250296 IE Insp Repts 50-329/79-04 & 30-330/79-04 on 790207 No noncompliance noted Major areas inspected project status, concerns re recent developments onsite & upcoming insp activity
  CODK.R. J : MANSEN.W A Region 3. Chicago. Office of the Director KNOP.R C Region 3. Chicago. Reactor Construction & Engineering Support Branch 79/03/27 App
- 7905240724 Forwards IE Insp Repts 30-329/79-06 & 50-330/79-06 on 790328-29 No noncompilance noted FIORELLI, G Region 3. Chicago, Reactor Construction & Engineering Support Branch 79/04/09 2pp.
- ---7905240734 IE Insp Repts 50-329/79-06 & 50-330/79-06 on 790328-29. No noncompliance noted Major areas inspected following 100FRBO. 55(a) rept re-settlement of diesel generator bidg & plant area fill GALLACHER, E. J., HAYEB, D. W. Region 3, Chicago, Office of the Director 79/04/04 7pp
- 7905030022 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."

  KEPPLER. J O Region 3, Chicago, Office of the Director 79/04/11
- 7905010583 Forwards IE Bulletin 79-06A. "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."

  KEPPLER, J O Region 3, Chicago, Office of the Director, 79/04/14
- 7905040331 Forwards IE Bulletin 79-04B, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident "
  KEPPLER, J. O Region 3: Chicago, Office of the Director 79/04/14.
- 7905040465 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping " Licensee action required. KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/14
- 7905040546 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."

  KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/14.

- 7903010387 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Strute" KEPPLER, J C Region 3, Chicago, Office of the Director 79/04/16
- 7905030219 Forwards IE Bullstin 79-09, "Failures of GE Type AK-2 Circuit Breater in Safety-Related Sys " Licensee action required KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/04/17
- 7905080404 Forwards IE Bulletin 79-059, "Nuclear incident at TMI-Suppl"

  KEPPLEN.J O Region 3, Chicago, Office of the Director 79/04/21
- R Pariodic operating reports & related correspondence
- 7905306478 Forwards nonconformance repts for Apr 1979
  HOWELL.S H Consumers Power Co 79/05/25 1000pp
- S Reportable occurrences, LERs & related correspondence
- 7905290330 Ack receipt of 790309 final rept re air filtering units
  Review will be finished upon completion of corrective
  action
  FIDRELLIG Region 3, Chicago, Reactor Construction & Engineering
  Support Branch 79703/23 ip
- 7905240549 Act receipt of 790330 rept re electrical penetration assembly Final rept will be reviewed upon receipt FIGRELLI.G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79704706 ip
- 7905140217 Forwards nonconformance repts for Har 1979, consisting of Bechtel nonconformance repts.Bechtel nonconformance log, Bechtel quality audit findings.Bechtel quality action requests.B&W repts of nonconformity & util repts HOHELL.S H Consumers Power Co 79/04/25 440pp
- 7705070301 Final deficiency rept reactor bidg spray enchor discrepancy Local pipe stresses may potentially exceed ASME Code Section III allowables at points Existing procedural methods are adequate Consumers Power Co 79/04/27 4pp
- 7905090002 Provides interim deficiency rept on actions to resolve settlement of diesel generator foundations & bldg MCHELL,S H Consumers Power Ca 79/04/30 2pp
- --7705090086 Interim Deficiency Rept 5 settlement of diesel generator foundations & bldg Caused by insufficient compaction in area full re-seismic Category I structures Lists status & corrective actions W/62 oversized drawings \* Consumers Power Co 79/04/16 10pp
- 7905030327 Final rept re reactor bldg spray piping supports Analysis has verified adequacy of support design & ASHE Section III Code allowable stresses Bechtel mgt corrective action rept NGAR 22 and 1 HONELL, B H Consumers Power Co 79/05/01 7pp
- 7905080332 Forwards interim rapt on status of component qualification test documentation re review Forwards Bachtel "Gualification Test Status Rept " Similar BEW rapt will be reviewed Another rapt will be sent by 790706
  HOHELL, S H Consumers Power Co 79/05/04 2pp
- --7905080536 Interim rept on seismic & environ component qualification, forwarding "Qualification Test Status Rept," Revision 7, dtd 790406
  BALTAZAR, R Z Bechtel Power Corp (subs of Bechtel Corp) 79/04/20 39pp
- 7705300252 Forwards final rapt re discrepancies discovered in inboard terminal boxes
  HOMELL.8 Consumers Power Co 79/05/25 5pp
- --7905300256 Final deficiency rept on 790523 defects discovered in panetration assemblies in inhosed terminal boxes, possibly caused by type of termination lug used. Insp of terminations conducted.

  \* Consumers Power Co 79/05/23 4pp
- T Hearing transcripts on non-antitrust matters
- 7903140564 Transcript of 790501 prehearing conference in Bethesda, MD Pp 50,001-50,171
  MILLER, H E , LUEBKE, LEEDS Atomic Safety and Licensing Board Panel 79/03/01, 171pp

- DOCKET 90-331 DUANE ARNOLD ENERGY CENTER
- F Security, medical, emergency & fire protection plans
- 7903040491 Forwards modified physical security plan Plan withheld (ref iOCFR2 790)
  LIU.L Jawa Electric Light & Power Go 79/04/30 ip
- 7905090368 Informs that fire hazard analysis rept will be submitted by 790610, due to addi analysis required by engineering staff & consultants
  LIU.L Iowa Electric Light & Power Co 79/09/02 ip
- 7905080465 Advises of delay in security mod project, due to labor disagreement & supplier's delay in mfg of critical computer components LTU.LEE Inua Electric Light & Power Co 79/05/04 ip
- 7905310447 Discusses schedule delays ne plant security program Local electrical union contract will expire on 790601 & work stoppage may ensue LIUL Iowa Electric Light & Power Co 79/05/18. (p
- Q Adjudicatory correspondence
- 7905150307 Forwards request to institute proceeding to suspend technical Amend 9 to License DPR-49, Also forwards pertinent FR notice DENTON-H R Office of Nuclear Reactor Regulation 79/04/12 200
- ---7905150312 Request for suspension of technical Amend 9 to License DPR-49
  MAGERS, J.E. Citizens United for Responsible Energy 79/03/20
- 7905250025 Ack receipt of request to institute proceeding to suspend Amend 9 to License DPR-49 Request is presently under consideration Relevant FR notice & petitioner's request for action encl DENTON, HR Office of Nuclear Reactor Regulation. 79/04/12 2pp
- --7905250027 Notice of request to suspend Amend 9 to License DPR-49 DENTON-H R Office of Nuclear Reactor Regulation 79/04/12 is
- 7905250437 Notification that Citizens for Responsible Energy filed pattion seeking proceedings to suspend Amend 9 to License DPR-49 BOYD, R S Office of Nuclear Reactor Regulation 79/04/12 ip
- 7905130315 FR notice of request to suspend technical Amend 7 to 1 Icense DPR-49 BOYD.R S Office of Nuclear Regulatory Research 79/04/12 ip
- 790525003i Request for action to institute proceeding to suspend Amend 9 to License DPR-49 re handling of 8NH MEYERS.J E Citizens United for Responsible Energy 79/03/20 3;
- J Insurance & indemnity information
- 7905070497 Confirms increased liability limit to \$124,000,000 for policis NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,175,177,180,182,183,186,187,188,187,172,173,194,175,177,189,200,201,204,206,207,208,210,212,214,215,& others, QUATTROCHHI, J American Nuclear Insurers, 79705701 1p
- 7905160275 Forwards Amend 6 to Indemnity Agreement 8-68, per IOCFR140 changes, re increase from \$140 million to \$160 million affective 790501. Supporting documentation encl SALTZMAN, J. Abstruct & Indemnity Group, 79/05/01 Spp
- P Operating license stage documents & correspondence
- 7905090196 Forwards Amend 50 to License DPR-49, security plan evaluation (withheld ref 100FR2 790) & notice of issuance & availability.

  IPPOLITO, T A Operating Reactors Branch 3, 79/04/19 Spp
- --7903070199 Amend 80 to License DPR-49, incorporating security plan which became effective on 790223.

  IPPOLITO, T.A. Operating Reactors Branch 3. 79/04/19 2pp

- --7905090201 Notice of issuance & availability of Amend 50 to License DPR-49 IPPOLITO,T A Operating Reactors Branch 3 79/04/19 Rep
- 7905080469 Informs of delay until 790630 of App I Tech Spec submittal originally scheduled for 790430 Consultant engaged on TMI
  - Iowa Electric Light & Power Co 79/05/02
- 7909230522 Forwards bar-chart schedule showing time periods for installation of specific plant mods as part of Mark I containment long-term program Installation currently scheduled for Feb 1981 rafueling outage LIU.L Iowa Electric Light & Power Co 79/05/17 2pp
- Inspection reports, IE Bulletins & correspondence
- 7905090165 Forwards IE Insp Rept 50-331/79-07 on 790227-0301 No OSOVOTOS FORMERO LE TIES REPO SU-331///-O/ DE //OSER/OSOT NO HEIEHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/03/22 2pp
- --7905090169 IE Insp Rept 50-331/79-07 on 790227-0301 No noncompliance noted Major areas inspected fire protection/prevention program & review of Tech Specs surveillance requirements for fire protection equipment WRIGHT.0 C Region 3. Chicago, Reactor Operations Nuclear Support Branch LITTLE.W S Region 3. Chicago, Office of the Region 3, Chicago, Office of the Director 79/03/16, 4pp,
- 7909010254 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping" KEPPLER.J G Region 3. Chicago, Office of the Director 79/03/23
- 7905230412 Forwards IC Insp Rept 50-331/79-04 on 790307-09 & notice of Violation DAVIS: A II Region 3. Chicago, Fuel Facility & Materials Bafety Branch 79/03/23
- --7905230420 Notice of violation from insp on 790307-07 \* Region 3. Chicago, Fuel Facility & Materials Safety Branch 79703/21 1p
- --7905230426 IE Insp Rept 50-331/79-06 on 790307-09 Noncompliance noted failure to submit QA program description for shipping packages as required.

  HILLER, DF, HIAYT, JH, Region D, Chicago, Office Director FISHUR, W L. Region D, Chicago, Fuel Fa Materials Safety Branch 79/03/21 6pp
- 7903040031 Forwards IC info Notice 79-07, "Rupture of Radwaste Tants "
  KEPPLER, J O Region 3, Chicago, Diffice of the Director 79/03/26 10
- 7905080204 Forwards IE Insp Rept 50-331/79-10 on 790204-07 & 0301-02 FIGRELLI, 0 Region 3. Chicago, Reactor Construction & Engineering Support Branch 79/03/27 2pp
- -7905080211 IE Insp Rept 50-331/79-10 on 790206-07 & 0301-02 Major areas inspected ultraspoint baseline test results for welds inspected ultraspoint baseline test results for welds involved in recirculation inlet piping repair & recirculation inlet norzle NZB lead plug KEY.H J. HILLIAMS.C C . DANIELBOND.H Region 3, Chicago, Office of the Director 79/03/23, Spp
- 7905150126 Forwards IE Insp Rept 50-331/79-05 on 790127-31,0205-06. 15-13 & 27 & notice of violation HCIBHMAN,R 8 Region 3. Chicago, Reactor Operations Nuclear Bupport Branch 79/03/27. 2pp.
- --7905150129 Notice of violation from insp on 790127-31.0205-06,11-13 & Region 3, Chicago, Office of the Director 79/03/23 ip
- ~-7905130134 IE Insp Rept 50-331/79-05 on 790127-31 & 0208-06,11-13 & 27
  Nuncompliance noted failure to adhere to welding procedures
  JACKIM, I N , WALKER, R. D Region 3, Chicago, Office of the
  Director. BPEBBARD, R. L. Region 3, Chicago, Reactor Operations
  Nuclear Support Branch 79/03/23 Spp
- 7905150424 Forwards IE Insp Rept 50-331/79-09 on 790108-12,17-19,24 & 29-31 & notice of violation KEPPLER, J G. Region G. Chicago, Office of the Director 79/03/27
- -7903180429 Notice of violation from insp on 790108-12,17-19,24 & 29-31 \* Ragion 3, Chicago, Office of the Director 79/03/27 ip

- -7905150436 IE Insp Rept 50-331/79-09 on 790108-12,17-19,24 & 29-31
  Noncompliance noted nonconformance repts improperly
  resolved & documented
  MILLIAMS,C C, KEY,M J Region 3, Chicago, Office of the
  Director DANIELSON,D H Region 3, Chicago, Reactor
  Construction & Engineering Support Branch 79/03/23 21pp
- 7905010167 Forwards 1E Info Notice 79-08. "Interconnection of Contaminated 8ys w/Svc Air Sys Used as Source of Breathing Air " KEPPLER, J Q Region 3, Chicago, Office of the Director Region 3, Chicago, Office of the Director 79/03/28 1 p
- 7905010398 Forwards IE Info Notice 79-09. "Bpill of Radioactively Contaminated Resin"
  KEPPLER, J 0 Region 3. Chicago, Diffice of the Director 79/03/30
- 7903230266 Forwards replacement pages for IE insp rept documents Revision reflects addition of insp dates 781212-15. 781218-21 & 781226-29, which were not previously included FIORELIC Region 3. Chicago, Reactor Operations Nuclear Support Branch 79/04/06 ip
- 7905030031 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "
  KEPPLER.J G Region 3, Chicago, Office of the Director 79/04/11
- 7905010388 Forwards IE Bulletin 79-06A. "Review of Operational Errors & Bys Misalignments Identified During TMI Incident " KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/14
- 7905040389 Forwards IE Bulletin 79-06B. "Review of Operational Errors & Bys Misalignments Identified During TMI Incident"
  KEPPLER, J G Region 3. Chicago, Office of the Director 79/04/14
- 7905040435 Forwards IE Bulletin 79-07, "Beismic Stress Analysis of Safety-Related Piping " Licensee action required KEPPLER.J G Region 3, Chicago, Office of the Director 79/04/14
- 7903040360 Forwards IE Bulletin 79-08. "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."

  KEPPLER.J G Region 3. Chicago, Office of the Director 79/04/14.
- 7905:50050 Responds to IE Bulletin 79-03 re pipe mfg by Youngstown Welding & Engineering Co Pipe is neither used nor planned for use in any safety-related sys at facility LIU.L lows Electric Light & Power Co 79/04/16 ip
- 7905030227 Forwards IE Builetin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " Licenses action required, KEPPLER.J G Region 3. Chicago, Office of the Director 79, Region 3, Chicago, Office of the Director 79/04/17
- 7905080496 Forwards IE Bulletin 79-058, "Nuclear Incident at TMI-Suppl " Region 3, Chicago, Office of the Director 79/04/21
- 7903300272 Responds to IE Bulletin 79-07 No methods specified in bulletin have been used Responses from NBSS supplier & A/E enci Towa Electric Light & Power Co 79/04/24 3pp LIULL
- 7905110159 Ack receipt of 790413 ltr informing NRC of steps taken to correct violations noted in IE insp conducted on 790307-09 DAVIS.A Region 3, Chicago, Fuel Facility & Materials Safety Branch. 79/04/25. Spp
- ---7905110163 Responds to NRC ltr re violation noted in IE insp tenducted on 790307-09 Corrective actions GA program will be implemented by 790601.

  LIV.L lows Electric Light & Power Co. 79/04/13 4pp
- 7905250213 Responds to IE Bullatin 79-08. Items 1-10, re TMI affect on BMRs. Response to Item 11 will be sent before 790518.

  MALLACE, J. A. Iowa Electric Light & Power Co. 79/04/27 18pp
- 7905240902 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Recirculation Motor Generator Set Resulted in Reactor Power Increase.", KEPPLER.J.O Region G. Chicago, Office of the Director 79/05/6 Region 3. Chicago: Office of the Director 79/05/02

- R Periodic operating reports & related correspondence
- 7905210220 Forwards monthly operating rept for Apr 1979
  HAMMOND.E L Towa Electric Light & Power Co RC 79/05/14 1p
- --7905210224 Monthly operating rept for Apr 1979
  VAN BICKEL, J Towa Electric Light & Power Co NRC 79/05/14
- B Reportable occurrences, LERs & related correspondence
- 7905020251 Forwards LER 79-008/03L-0
  HAMMOND.E L Iowa Electric Light & Power Co 79/04/25 ip
- --7909020253 LER 79-008/03L-0 on 790326 pin hole leat discovered in reactor water cleanup sys pipe Caused by linear indication in weld attributed to innergranular stress corrosion cracking Elbow & pipe on both snds replaced VAN SICKEL.P J Iowa Electric Light & Power Co 79/04/25, ip
- 7905160363 Forwards LER 79-010/03L-0
  HAMMOND, E L. Towa Electric Light & Power-Co 79/05/09 1p
- --7905160368 LER 79-010/03L-0 on 790410 containment purge inlet valve CV 4306 % torus purge outlet valve CV 4300 not sealing properly due to tee ring seals not being pressurized Caused by actuator valve linkage being out of adjustment VAN SICKEL. J lows Electric Light % Power Co 79/05/08 ip
- 7905160386 Forwards LER 79-009/03L-0 HAMMOND, E.L. | Iowa Electric Light & Power Co | 79/05/08 | 19
- --7905160387 LER 79-009/03L-0 on 790408 drain sump discharge valve CV 3704 stuck Caused by corrosion in valve operator Cylinder was lubricated & design review will be initiated to determine if oiling device can be installed VAN SICKEL, J. Iowa Electric Light & Power Co. 79/05/08. 2pp
- 7905290182 Forwards LER 79-011/03L-0
  HAMMOND,E L. lowe Electric Light & Fower Co. 79/05/18 ip
- --7905290191 LER 79-011/03L-0 on 790424 main exhaust radiation monitors RIM 7606A & 7606B tripped at out-of-spec setpoints Caused by Instrument drift Monitors recalibr VAN GICKEL J lowa Electric Light & Power Co 79/05/1B ip
- DOCKET 50-332 BARNHELL REPROCESSING PLANT
- G Inspection reports, IE Bulletins & correspondence
- 7905230782 Informs of deferral of corrective actions discussed in IE Insp Rept 50-332/77-02 re beliou seal angle valves Future facility operation uncertain due to NRC 771223 order terminating licensing proceedings BAXTER.R C Allied General Nuclear Services 79/03/14 ip.
- 7903010132 Forwards IE Info Notice 79-08. "Interconnection of Contaminated Bys w/Syc Air Sys Used as Source of Breathing Air."

  O'REILLY, J P Region 2. Atlanta, Office of the Director 79/03/28 io
- DOCKET 50-333 JAMES A FITZPATRICK NUCLEAR POHER PLANT F. Security, medical, emergency & fire protection plans
- 7905140307 Forwards add1 responses to draft safety evaluation of fire protection program Discusses diesel fire room sprinkler head spacing detector testing, piping penetration seal qualification & flame retardant coating EARLY:P J. Power Authority State of New York, 79/05/07 9pp.
- J. Insurance & indemnity information
- 7905070497 Confirms increased liability limit to e124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,183,186,187,188,189,172,193,194,193,197,198,200,201,204,204,205,208,210,212,214,215,to others, GUATTROCHHI, J American Nuclear Insurers, 79/03/01, 1p,
- 7905070582 Confirms increase in liability limit to \$36,000.000 for policies MF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,56,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,91,92,93,94,95,3,96,

- 7905160162 Forwards Amend 7 to Indemnity Agreement B-6G, per 10CFR140 changes, re liability insurance increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl BALTZMAN, J Antitrust & Indemnity Oroup 79/03/01 Spp
- 7905110175 Forwards Endorsement 34 to MAELU Policy MF-77 DEEQ:F H Power Authority State of New York 79/05/07 L
- 7905220387 Forwards Amend 7 to Indemnity Agreement 8-63, in response to 790501 request CLARK,F R Power Authority State of New York 79/05/16 3pp
- P Operating license stage documents & correspondence
- 7905080347 Assigns responsibility for prompt meeting notification re 790313 show cause orders STELLD.V Division of Operating Reactors 79/03/29 3pp
- 7705210046 Responds to 790316 ltr Apologizes for difficulty in obtaining info re space shutdown Clarifies role of Region I re state notification
  GRIER, BH Region 1, Philadelphia, Office of the Director 79704/12 200
- 7905040615 Forwards status rept on 790427 "Plan for Varification of Dynamic Analysis Godes "
  JACOBS.8 B Stone & Webster Engineering Corp. 79/04/27 2pp
- 7905040505 Responds to 790319 itr Info requested re skyshine radiation can be found in GE Nuclear Energy Sys Div rept. "Radiation Measurements at JA Fitzpatrick Nuclear Power Plant"

  EARLY, P J Power Authority State of New York 79/04/30 Ep
- 7905080945 Forwards list of piping analyzed during original design of plant using SHOCK II computer code EARLY,PJ Power Authority State of New York 79/04/30 7pp
- 7905090315 Proposes 790304 technical meeting w/NRC to discuse util piping stress reanalysis & to show startup is reasonable EARLY,P J Power Authority State of New York 79/05/01 ip
- 7905100175 Forwards application for amend to OL EARLY,P J Power Authority State of New York 79/05/02 2pp
- --7903100179 Application for amend to QL changing Tach Epacs to add limiting condition for operating & surveillance requirements & revising administrative controls for radiological effluents EARLY,P J Power Authority State of New York 77/05/07 ip
- --7905100183 Proposed Tech Baec changes re radiological efficients to monitoring \* Power Authority State of New York, 79/04/30 43pp
- 7705140239 Forwards proprietary documents requested during 770501-04 special insp.
  ERLENINE, J A Stone & Webster Engineering Corp. 77/05/08 (p.
- --7905140245 Requests withholding Technical Quideline EMTG-22-0 k Technical Rept EMTR-512 (ref 100FR2, 790) Affidavit encl. KENNEDY, W. J. Stone & Webster Engineering Corp 79/05/04 10);
- 7905140382 Confirms 790504 telcon w/WT Russell re computer dect associated w/SHOCK O program KENNEDY,W J Stone & Webster Engineering Corp 79/05/09 ip
- 7905210111 Forwards BHOCK 1 computer program listing. Bupersades submittal of 790406 Program listing withheld (ref 10CFR2 790)
  KENNEDY, W J Stone & Webster Engineering Corp 79/05/14 Ip
- 7905190073 Ack receipt of 790315 & 21 ltrs re spent fuel racks Requests extension of response time until 790525 Start of new spent fuel rack installation scheduled for 790702 Requests approval by 790611
  EARLY.P J. Power Authority State of New York, 79/05/15 is
- 7905290335 Summarizes procedures & calculational techniques used in reanalysis of piping sys designed w/8HDCK II computer program. Reanalysis will satisfy 790313 order to show cause KENNEDY, M. J. Stone & Webster Engineering Corp. 79/05/18. App.
- @ Inspection reports: IE Bullstins & correspondence
- 7905010127 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
  ORIER, N. Region 1, Philadelphia, Office of the Director. 79/03/23 1p.

- 7905010040 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Bys w/Svc Air Bys Used as Bource of Breathing Air "
  GRIER.B H Region 1. Philadelphia, Office of the Directo
- Region 1. Philadelphia, Office of the Director 79/03/28
- 7905010584 Responds to IE Dulletin 79-03 Welded pipe was not used at facility LECNARD.J D Power Authority State of New York 79/03/29 1p
- 7708010310 Forwards IE Info Notice 79-09, "Spill of Radioactively Gontaminated Resin "
  GRIER, H H Region 1, Philadelphia, Office of the Director 79/03/30. 2pp
- 7903230162 Responds to IE Bulletin 78-14. "Deterioration of Buna-N Components "Replacement of components during outage dependent upon plant stantup, in view of pipe stress problems Replacement within seven years of packaging date LEONARD, J.D. Power Authority State of New York 79/04/04 2pp
- 7903020072 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Missalignments Identified During TMI Incident " GRIER.D H Region 1, Philadelphia. Office of the Director 79/04/11 ip
- 7903080246 Requests add1 info to complete inservice testing program Info needed includes pumps, valves, core spray, reactor core isolation cooling sys, reactor water cleanup sys, control room area syc & chilled water IPPOLITO, T A Operating Reactors Branch 3 79/04/12 8pp
- 7905020321 Forwards IE Bulletin 79-07, "Beismic Stress Analysis of Safety-Related Piping " Licensee action required QRIEM.B H Region 1, Philadelphia, Office of the Director 79/04/14 1p
- 7903040074 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident" GRIEER, B H. Region 1, Philadelphia, Office of the Director 79/04/14. 1p
- 7905040249 Forwards IE Sulletin 79-08, "Events Relevant to Boiling Mater Power Reactors Identified During TMI Incident "Licensee action required ORIER.B.H Region i, Philadelphia. Office of the Director 79704/14 ip
- 7705240290 Responds to IE Bulletin 79-07. "Seismic Stress Analysis of Barety-Related Piping " A/E currently testing seismic stress on safety-related piping. Results will be reported per show cause order issued 770313
  LEUNARD. J D Power Authority State of New York 79/04/16 1p
- 7908030083 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Bafety-Related Bys " Licensee action GRIER, D. H. Region 1, Philadelphia, Office of the Director 79/04/17 Ip
- 7903020296 Forwards IE Bulletin 79-06A.Revision 1. "Review of Operational Errors & Bys Misalignments Identified During TMI Inclient " Region i. Philadelphia. Office of the Director GRIER, D. H
- 7905250174 Responds to IE Bulletin 79-08. Mgt personnel reviewed procedures in operations dept which dealt w/operations & ways under abnormal conditions. Containment isolation & institution design reviewed LEONARD. J. D. Power Authority State of New York. 79/04/25 34pp.
- 7905180492 Informs that response to 790412 inquiry re inservice testing program was provided at 790425-26 meeting w/NRC & BNL Revised program based on meeting resolutions will be aubmitted. EARLY, P J Power Authority State of New York 79/05/08 ip
- 7905230430 Supplements 790425 response to IE Bulletin 79-08 rs TMI incident implications for BWRs Amend being developed to correct instrumentation tables in Tech Specs identified in bulletin. Summarizes nonsefety-related discrepancies EARLY.P.J. Power Authority State of New York 79/05/18 2pp
- R. Periodic operating reports & related correspondence
- 7705070343 Submits weekly status rept of S&W piping reanalysis, as of 790430. FARLY, P. J. Power Authority State of New York. 79/05/01 2pp.
- 7905110254 Forwards monthly operating rept for Apr 1979. LECNARD, J D Power Authority State of New York 79/05/08. 1p.

- --7905i10256 Monthly operating rept for Apr 1979 ZUFELT.E Power Authority State of New York 79/05/31 Ron
- 7905240697 Forwards weekly status rept of S&W piping reanalysis, as of EARLY, P J Power Authority State of New York 79/05/18 200
- S Reportable occurrences. LERs & related correspondence
- 7905010499 Forwards LER 79-022/04L-0 LEONARD, J D Power Authority State of New York 79/04/24 1p
- --7905010503 LER 79-022/04L-0 on 790409 manitar 17-RM-50B did not activate local & remote high-high alarms as required by surveillance test F-BT-13 Caused by drift in trip setpoint Pulse height discriminator adjusted CHILDS.H.V Power Authority State of New York 79/04/24 2pp
- 7905010505 Forwards LER 79-021/03L-0 LEDNARD, J D Power Authority State of New York 79/04/24 is
- --7905010508 LER 79-021/03L-0 on 790327 offsite power lost while in cold shutdown Emergency svc water sys started automatically Caused by loose wire in controller of motor operated valves Connection repaired CHILDS.W V Power Authority State of New York 79/04/24 2pp
- 7905150475 Forwards LER 79-023/99L-0 LEONARD, J D Fower Authority State of New York 79/05/09 1p
- --7905150477 LER 79-023/099-0 on 790411 HPCI turbine disassembled for internal insp.requiring disassembly of piping for fixed fire suppression sys.contrary to Tech Specs Will remain disabled until 790615, when reassembly is complete CHILDS, W V Power Authority State of New York 79/05/09 2pp
- 7905300411 Forwards LER 79-024/03L-0 LEONARD, J D Power Authority State of New York 79/05/24 1p
- --7905300416 LER 79-024/03L-0 on 790428 emergency svc water pump B could not be demonstrated to produce min shutoff head of 120 psig Gaused by normal wear Tach Spec amend to reduce shutoff head requirement under consideration CHILDB.W V Power Authority State of New York 79/05/24 2pp
- 7903300506 Forwards LER 79-017/03L-1 LEDNARD, J D Power Authority State of New York 79/05/24 1p
- --7905300514 LER 79-017/03L-1 on 790320.while surveillance test F-ST-34D was being conducted standby gas treatment sys A in valve Oi 123-MGV-14A would not open Caused by failure of auxiliary contractor in valve motor controller Contractor replaced CHILDS.W V Power Authority State of New York 79/05/24 2pp
- 7905300522 Forward: LER 79-025/03L-0 LEGNARD J D Power Authority State of New York 79/05/24 1p
- --7905300527 LER 79-025/03L-0 on 790428 while conducting surveillance test F-8Y-76/16/master valve did not appear to be opening fully. Damaged gasket may have been causing sluggish operation of valve Gasket replaced CHILDS: W V Power Authority State of New York 79/05/24 2pp
- DOCKET 50-334 BEAVER VALLEY POWER STATION, UNIT 1
- O Adjudicatory correspondence
- 790521005B Requests plant shutdown because of threat of accident as severe as rupture to reactor vessel ROMANO:F.R Affiliation Unknown 79/04/12 Spp
- J Insurance & indemnity information
- 7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,185,186,187,188,189,192,193,194,195,197,198,200,201,204,206,207,208,210,212,214,215,& others. QUATTROCHHI, J American Nuclear Insurers. 79/05/01 1p
- 7905070582 Confirms increase in liability limit to \$36.000.000 for policies MF-22.26.29.38.39.44.46.47.49.50.51.52.53.54.55.56.57.58.60.61.64.66.67.68.69.70.71.72.74.76.77.78.79.80.86.87.88.90.91.92.93.94.95 \$ 96.
  ROBERTS.D H Mutual Atomic Energy Liability Underwriters 79/05/01

- 7905160199 Forwards Amend 5 to Indemnity Agreement 8-73, per 10CFR140 charges, re-liability insurance increase from \$140 million to \$160 million effective 790501. Supporting documentation encl. SALTEMAN. J. Antitrust & Indemnity Group. 79/05/01. Spp.
- P. Operating license stage documents & correspondence
- 7905080247 Assigns responsibility for prompt meeting notification re 790313 show cause orders. STELLOV Division of Operating Reactors. 79/03/29. 3pp.
- 7905020490 Discusses 790315 telcon w/R Sero of Westinghouse re incorrect weights for Velan Model C658 6-inch check valves used in safety injection sys SCHHENGER A Operating Reactors Branch 1, 79/04/02, 1p.
- 7905290723 Summary of 790329-30 meeting w/util & S&W in Boston,MA re progress to date & early analysis of pipe stresses in safety-related sys.
  WIGGINTON.D. Operating Reactors Branch 1. 79/04/10. 3pp.
- 7905090066 Submits engineering info re pipe stress reanalysis. Oversized diagrams available in Central Files only.

  DURN, C. N. Duquesne Light Co. 79/04/19. 2pp.
- 7905040615 Forwards status rept on 790427 "Plan for Verification of Dynamic Analysis Codes "

  JACOBS, S. B. Stone & Webster Engineering Corp. 79/04/27. 2pp.
- 7905080370 Forwards response to Questions 362.1,362.2 % 362.3 of NRC 790109 ltr. Also forwards soil analysis of turbine bldg % northern yard area.dtd 790430, in response to Question 362.4. HOGLEVER, E. J. Duquesne Light Co. 79/05/02. 600pp.
- 79C5110011 Responds to NRC 780913 ltr.Forwards reanalysis of effects of major LDCA. Requests permission to remove present administrative limit of 2.31 & to restore existing Tech Spec limit of 2.32.

  DUNN, C. N. Duquesne Light Co. 79/05/07. 75pp.
- 7905110070 Forwards add1 info re new steam line break protection sys.in response to informal questions during review.

  DUNN.C.N. Duquesne Light Co. 79/05/07. 10pp
- 7905140239 Forwards proprietary documents requested during 790501-04 special insp. ERLEWINE.J.A. Stone & Webster Engineering Corp. 79/05/08. 1p.
- --7905140245 Requests withholding Technical Guideline EMTG-22-0 & Technical Rept EMTR-612 (ref 10CFR2.790). Affidavit encI. KENNEDY, W. J. Stone & Webster Engineering Corp. 79/05/04. 10pp.
- 7905140382 Confirms 790504 telcon w/WT Russell re computer deck associated w/SHOCK 0 program.
  KENNEDY, W. J. Stone & Webster Engineering Corp. 79/05/09. 1p.
- 7905160335 Notifies of review completion of computer deck. SHDCK O program still unrecovered. Piping sys conservatively designed & will perform intended function.

  KENNEDY, M. J. Stone & Webster Engineering Corp. 79/05/11. 1p.
- 7905210111 Forwards SHOCK 1 computer program listing Supersedes submittal of 790406.Program listing withheld (ref 10CFR2.790).
  KENNEDY, M. J. Stone & Webster Engineering Corp. 79/05/14. 1p.
- 7905220081 Requests amend to DL.changing ETS to eliminate aquatic monitoring except for fish impingement. W/proposed ETS.App B to License DPR-66 & special study on aquatic monitoring reduction.

  DUNN.C.N. Duquesne Light Co. 79/05/15. 225pp.
- 7905220093 Forwards proposed amend to OL.consisting of revised versions of previously submitted Offsite Dose Calculation Manual & "Process Control Program."

  DUNN.C.N. Duquesne Light Co. 79/05/15. 2pp.
- ---7905220099 Offsite Dose Calculation Manual. \* Duquesne Light Co. 79/05/01. 131pp.
- 7905240583 Discusses monitoring capabilities of reactor incore thermocouples. Fifty operable thermocouples may be defective or have insecure head connectors.

  CAREY, J. J. Duquesne Light Co. 79/05/16. 2pp.

- 7905290335 Summarizes procedures & calculational techniques used in reanalysis of piping sys designed w/SHOCK II computer program. Reanalysis will satisfy 790313 order to show cause. KENNEDY, W. J. Stone & Webster Engineering Corp. 79/05/18. 6pp.
- G. Inspection reports, IE Bulletins & correspondence
- 7905010105 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping." GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/03/23. 1p.
- 7905010042 Forwards IE Info Notice 79-08. "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air."

  ORIER, B. H. Region 1, Philadelphia, Office of the Director. 79/03/28. 19.
- 7905010297 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin." GRIER.B.H. Region 1, Philadelphia, Office of the Director. 79/03/30. 1p.
- 7905290123 Forwards IE Insp Rept 50-334/79-06 on 790227-0302.No noncompliance noted.
  BRUNNER,E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/04/03. 2pp.
- --7905290126 IE Insp Rept 50-334/79-06 on 790227-0302 No noncompliance noted. Major areas inspected previously identified unresolved items & sequence of events re recent high river water level. MARKOWSKI.R. Region 1, Philadelphia. Office of the Director. KISTER.H.B. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/03/28. 6pp.
- 7905290154 Forwards IE Insp Rept 50-334/79-07 on 790315-16.No noncompliance noted. BRUNNER.E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/04/10. 2pp.
- --7905290157 IE Insp Rept 50-334/79-07 on 790315-16. No noncompliance noted. Major areas inspected:compliance w/790313 order to show cause.

  BECKMAN.D.A. Region 1, Philadelphia, Office of the Director.

  KEIMIG.R.R. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/04/14. 3pp.
- 7905020039 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." Licensee action required.

  ORIER, B.H. Region 1, Philadelphia, Office of the Director.
  79/04/11. 1p.
- 7905140322 Informs that pipe type described in IE Bulletin 79-03 has not been used in safety-related sys.
  DUNN, C. N. Duquesne Light Co. 79/04/11. 1p.
- 7905020346 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required. GRIER.B.H. Region 1, Philadelphia, Office of the Director. 79/04/14. 1p.
- 7905040018 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." ORIER.B.H. Region 1, Philadelphia, Office of the Director. 79/04/14. 1p.
- 7905040198 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Mater Power Reactors Identified During TMI Incident." GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/04/14. 1p.
- 7905030060 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.

  GRIER, B.H. Region 1, Philadelphia, Office of the Director.

  79/04/17. 1p.
- 7905010643 Forwards IE Bulletin 79-06A Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." Licensee action required. ORIER, I. H. Region 1, Philadelphia, Office of the Director. 79/04/18. 1p.
- 7905250461 Responds to IE Bulletin 79-07 re analysis of safety-related piping. Currently reanalyzing piping.per NRC 790313 order to show cause.

  DUNN.C.N. Duquesne Light Co. 79/04/23, 1p.

- 7905090373 Forwards proposed "Inservice Insp Program" for 20-month period starting 790301. Program prepared per NRC 780110 request. Encl available in Central Files.

  DUNN.C.N. Duquesne Light Co. 79/05/02. 1p.
- R. Periodic operating reports & related correspondence
- 7905010491 Forwards "1978 Annual Environ Rept, Radiological, " Vol 2. DUNN, C. N. Duquesne Light Co. 79/04/24. 1p.
- --7905010493 "1978 Annual Environ Rept,Radiological," Vol 2. \* Duquesne Light Co. 79/04/24. 120pp.
- 7905010532 Forwards national pollution discharge elimination sysmonthly discharge monitoring rept for Mar 1979, MODRE, G. W. Duquesne Light Co. 79/04/27. 3pp.
- --7903010537 National pollution discharge elimination sys monthly discharge monitoring rept for Mar 1979. MOORE, G. W. Duquesne Light Co. 79/04/27. 12pp.
- 7905030342 Forwards Nov 1978 "Reactor Containment Integrated Leak Rate Test Rept." NUNN, C. N. Duquesne Light Co. 79/04/30. 1p.
- --7905030344 "Reactor Containment Integrated Leak Rate Test Rept." \* Duquesne Light Co. 78/11/30. 83pp.
- 7905140300 Forwards monthly operating rept for Apr 1979. DUNN.C.N. Duquesne Light Co. 79/05/04. 1p.
- --7905140302 Monthly operating rept for Apr 1979. TIMKO,D.R. Duquesne Light Co. 79/05/02. 4pp
- S. Reportable occurrences, LERs & related correspondence
- 7905310384 RO 79-8/01P on 790329: notified by vendor of potential for single dropped control rod to lead to calculated DNB ratios lower than reported to NRC in safety analysis. Caused by inconsistency between control settings used & those assumed. WERLING, J. A. Duquesne Ligh't Co. 79/03/30. 2pp.
- 7905080460 Forwards LER 79-010/01T-0. WERLING, J. A. Duquesne Light Co. 79/04/30. 2pp.
- ---7905080468 LER 79-010/01T-0 on 790416:GE notified util of potential for failure of inside recirculation spray pump motor. Analysis indicates problem may occur when all bearing part tolerances & bearing housings are at extreme end of sprectrum.

  WERLING, J. A. Duquesne Light Co. 79/04/30. 2pp.
- 7905080545 Forwards LER 79-011/04T-0. WERLING, J. A. Duquesne Light Co. 79/05/02. 2pp
- --7905080551 LER 79-011/04T-0 on 790430: tritium activity in quarterly composite of grab samples collected in OH River exceeded ETS limits. Caused by tritium discharge during normal plant operation.

  WERLING, T. A. Duquesne Light Co. 79/05/02. 1p.
- 7905150531 Forwards LER 79-012/04T-0. WERLING, J. A. Duquesne Light Co. 79/05/10. 2pp.
- --7905130536 LER 79-012/04T-0 on 790430: gross beta in monthly composite grab samples from OH River exceeded ETS reporting level.
  Caused by naturally occurring radioactivity in sediments.
  WERLING, J. A. Duquesne Light Co. 79/05/10. 1p.
- 7903240568 Submits special rept on diesel driven fire pump removed from svc on 790416 when intake bay was drained for maint. Motor-driven pump remained operable. Diesel pump returned to svc on 790503.

  WERLING, J. A. Duquesne Light Co. 79/05/14. 2pp.
- DOCKET 50-335 ST. LUCIE PLANT, UNIT 1
- G. Adjudicatory correspondence
- 7905150125 Forwards NRC rept "Inquiry into Allegation of Employee Misconduct by Restricting Investigation to Determine Reliabililty of Power Grid Serving St Lucie."

  SOHINKI.S.M. Branch 3. 79/04/11. 1p.

- --7905150130 "Inquiry into Allegation of Employee Misconduct by Restricting Investigation to Determine Reliability of Power Grid Serving St Lucie." MCTIERNAN,T.J. Office of Inspector & Auditor. 78/06/30. 85pp.
- J. Insurance & indemnity information
- 7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,185,186,187,188,189,192,193,194,195,197,198,200,201,204,206,207,208,210,212,214,215,&others.

  GUATTROCHHI, J. American Nuclear Insurers. 79/05/01. 1p.
- 7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22.26,29,38,39,44,46,47,49,50,51,52,53,54,55,56,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,91,92,93,94,95 & 96.
  ROBERTS, D. M. Mutual Atomic Energy Liability Underwriters. 79/05/01.
- 7905160198 Forwards Amend 5 to Indemnity Agreement B-76.per 10CFR140 changes.re liability insurance increase from \$140 million to \$160 million.effective 790501.Supporting documentation encl. SALTZMAN.J. Antitrust & Indemnity Group. 79/05/01. 5pp.
- 7905100309 Forwards Endorsement 31 to NELIA Policy NF-227. FIELDER, J. Marsh & McLenon, M & M Nuclear Consultants, Inc. Div. 79/05/04. 2pp.
- 7905100311 Forwards Endorsement 32 to NELIA Policy NF-227. FIELDER, J. Marsh & McLenon, M & M Nuclear Consultants, Inc. Div. 79/05/04. 2pp.
- 7905250397 Forwards executed Amend 5 to Indemnity Agreement B-76, increasing coverage to \$160 million."

  UHRIG.R.E. Florida Power & Light Co. 79/05/21. 3pp.
- M. Antitrust correspondence
- 7905150234 Motion by FL Cities seeking antitrust hearing. Renews request to angue position re review & consolidation of antitrust issue. Certificate of Svc encl.

  JABLON.R.A. Spiegel & McDiarmid. 79/03/28. 2pp.
- 7905150729 Forwards motion for consolidated hearings on behalf of FL Cities.

  JABLON, R. A. Spiegel & McDiarmid. 79/04/02. 1p.
- --7905150733 Motion for consolidated hearings by FL Cities Certificate of Svc encl.

  JABLON, R. A. Spiegel & McDiarmid. 79/04/02. 4pp.
- 7905230622 Responds to 790328 & 790402 motions filed by FL Cities to initiate antitrust hearing in response to NRC 780727 order.

  Certificate of Svc encl.

  DEWEY, L., CHANANIA, F. D., EVANS, D. J. Anti-Trust Division. 79/04/17.
- P. Operating license stage documents & correspondence
- 7905070231 Forwards Amend 31 to License DPR-67, safety evaluation & notice of issuance & availability.
  REID.R.W. Operating Reactors Branch 4. 79/04/05. 2pp.
- --7905070236 Amend 31 to License DPR-67, modifying Tech Specs to allow replacement of selected safety-related hydraulic snubbers w/mechanical snubbers & to revise snubber surveillance requirements.

  REID.R.W. Operating Reactors Branch 4. 79/04/05. 15pp.
- ---7905070277 Safety evaluation supporting Amend 31 to License DPR-47.
  \* Office of Nuclear Reactor Regulation. 79/04/05. 3pp.
- --7905070299 Notice of issuance & availability of Amend 31 to License DPR-67.
  REID.R.W. Operating Reactors Branch 4. 79/04/05. 2pp.
- 7905150798 Notifies of adequacy of licensee's sys for insuring feedring is maintained full of water at all times. Suggests auxiliary feedwater flow be actuated automatically to obtain time lapse of less than one minute.

  LAINAS. G. Plant Systems Branch. 79/04/13. 2pp.

- 7905150278 Requests add1 info re review of proposed pump & valve test program submitted by 770916 & 780908 ltrs.Encl 1 identifies info needed on certain check valves.

  REID, R. W. Operating Reactors Branch 4. 79/04/20. Spp.
- 7905250263 Forwards safety evaluations re fuel handling accident inside containment. REID, R. W. Operating Reactors Branch 4. 79/04/27. 2pp.
- --7905250275 Safety evaluation re fuel handling accident inside containment. Reveals fuel handling accident w/one or two assemblies would provide doses within 10CFR100 guideline values.

  \* Office of Nuclear Reactor Regulation. 79/04/27. 4pp.
- 7905040585 Forwards addl info for Cycle 3 reload application re anticipated burnup for clad collapse for each fuel batch, combining of fuel pin powers & augmentation factors & investigation of control elements assembly sticking. UGRIG.R.E. Florida Power & Light Co. 79/04/30. 12pp.
- 7905070410 Provides status of verification program for technique of measuring resistance temp detectors time constants.

  UHRIG.R.E. Florida Power & Light Co. 79/05/01. 2pp.
- 7905140310 Reviews impact of using NRC fission gas release enhancement factors on results of Cycle 3 safety analyses. Application of factors does not adversely affect Cycle 3 results of 790222. UHRIORRE. Florida Power & Light Co. 79/05/08. 1p.
- 7905210121 Forwards startup testing info as suppl to Cycle 3 reload safety evaluation.
  UHRIG.R.E. Florida Power & Light Co. 79/05/10. 2pp.
- 7905220027 Forwards response to questions re reload safety evaluation. UHRIG.R.E. Florida Power & Light Co. 79/05/18. 13pp.
- 7905310214 Forwards responses to questions re reload safety evaluation. UHRIG.R.E. Florida Power & Light Co. 79/05/22. 10pp.
- 7905300014 Forwards responses to reload safety evaluation questions. UHRIG.R.E. Florida Power & Light Co. 79/05/23. 6pp.
- 7905310305 Submits info in response to NRC request Zero power physics tests after reload performed according to procedures. Review criteria will be established. Evaluation of difference in individual assemblies power to be sent in two weeks.

  UHRIG.R.E. Florida Power & Light Co. 79/05/25. 2pp.
- 7905310309 Confirms 790524 discussion during which util agreed to limit containment purging in operational Modes 1 & 2 to 90-h/year. UHRIG.R.E. Florida Power & Light Co. 79/05/25. 1p.
- Q. Inspection reports, IE Bulletins & correspondence
- 7905010195 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping." O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79/03/23. 2pp.
- 7905030310 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks." O'REILLY,J.P. Region 2, Atlanta, Office of the Director. 79/03/26. 2pp.
- 7905010104 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air."

  O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/03/28. 2pp.
- 7905010358 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin."
  O'REILLY,J.P. Region 2, Atlanta, Office of the Director.
  79/03/30. 2pp.
- 7905240045 Ack receipt of IE Insp Rept 50-335/79-04 on 790207-09.No proprietary info.

  UHRIG.R.E. Florida Power & Light Co. 79/04/10. 1p.
- --7905240054 Forwards IE Insp Rept 50-335/79-04 on 790207-09. No noncompliance noted. KENNA. W. B. Region 2, Atlanta, Safeguards Branch. 79/03/12.
- --7905240069 IE Insp Rept 50-335/79-04 on 790207-09 No noncompliance noted Major areas inspected facility organization & operation, measurement & controls, shipping & receiving, storage & internal control inventory & records.

  TODD, G. A., CLAY, E. L. Region 2, Atlanta, Office of the Director. WILLIAMS, G. H. Region 2, Atlanta, Safeguards Branch. 79/03/08.

- 7905020127 Forwards IE Bulletin 79-06, "Review of Operational E<sub>PT</sub>o<sup>r 6</sup>
  Sys Misalignments Identified During TMI Incident." Licensee
  action required.

  © REILLY, J. P. Region 2, Atlanta, Office of the Director.
- 7905040141 Forwards IE Bulletin 79-06B, "Review of Operational Error Sys Misalignments Identified During TMI Incident." Licensee action required.

  O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
  79/04/14. 2pp.
- 7905040308 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/14. ip.
- 7905040404 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident." O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/14. ip.
- 7905030164 Forwards IE Bulletin 79-09, "Failures of QE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.

  O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
- 7905020465 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Eppors & Sys Misalignments Identified During TMI Incident."

  O'REILLY, J. P. Region 2, Atlanta, Office of the Director, 79/04/18 200.
- 7905240169 Responds to IE Bulletin 79-07 re seismic analysis of safety-related piping. No such computer codes used.
  UHRIG.R.E. Florida Power & Light Co. 79/04/26. 3pp.
- 7905290150 Ack receipt of 790403 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-335/79-01.
  0/REILLY,J.P. Region 2, Atlanta, Office of the Director.
  79/05/01. 1p.
- --7905290159 Responds to NRC 790308 ltr re violations noted in IE Int Rept 50-335/79-01.Corrective actions:calibr info sheet 039 corrected & appropriate personnel instructed on correct method of making changes. UHRIG.R.E. Florida Power & Light Co. 79/04/03. 3pp.
- --7905290167 Forwards IE Insp Rept 50-335/79-01 on 790109-12 & notice violation.

  LEWIS.R.C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 79/03/08. 2pp.
- --7905290170 Notice of violation from insp on 790109-12.

  \* Region 2, Atlanta, Office of the Director. 79/03/07. 1p
- ---7905290174 IE Insp Rept 50-335/79-01 on 790109-12. Noncompliance not failure to review calibr procedures.

  MEBSTER, E. H., MOSSITT, B. R., CANTRELL, F. S. Region 2, Atlanta. Office of the Director. 79/03/07. 13pp.
- S. Reportable occurrences, LERs & related correspondence
- 7905150241 Forwards LER 79-009/03L-0. SCHLMIDT, A. D. Florida Power & Light Co. 79/04/04. 1p.
- 7905090062 Forwards LER 79-013/03L-0. SCHMIDT.A.D. Florida Power & Light Co. 79/04/30. 1p.
- --7905090064 LER 79-013/03L-0 on 790331: during surveillance testing q diesel generator, solenoid-operated fill valve for engine mounted fuel oil tank failed to open, causing tank level to drop below limit. Caused by burnt contacts in relay.

  SCHOPPMAN, M. A. Florida Power & Light Co. 79/04/30. 1p.
- 7905220091 Forwards LER 79-014/03L-0. SCHMIDT.A.D. Florida Power & Light Co. 79/05/09. ip.

- DOCKET 50-336 MILLSTONE NUCLEAR POWER STATION, UNIT 2
  F. Security, medical, emergency & fire protection plans
- 7905290073 Forwards response to NRC verbal questions re fire protection. Engineering & design of most mods in progress. COUNSIL. W. G. Northeast Utilities. 79/05/18. 16pp.
- J. Insurance & indemnity information
- 7905140422 Forwards Amend 14 to Indemnity Agreement B-39 per 10CFR140 changes, re increase in liability insurance from \$140 million to \$160 million, effective 790501. Supporting documentation encl.

  SALTZMAN, J. Antitrust & Indemnity Group. 79/05/01. 6pp.
- 7905190075 Forwards executed Amend 14 to Indemnity Agreement B-39. O'CONNOR, L. A. Northeast Utilities. 79/05/15. 4PP.
- P. Operating license stage documents & correspondence
- 7905070332 Forwards Amend 50 to License DPR-65, safety evaluation & notice of issuance & availability.
  REID,R.W. Operating Reactors Branch 4. 79/03/23. 2pp.
- --7905070337 Amend 50 to License DPR-65, incorporating low temp overpressure protection sys requirements. REID.R.W. Operating Reactors Branch 4, 79/03/23, 20pp.
- ---7905070347 Safety evaluation supporting Amend 50 to License DPR-65.

  \* Office of Nuclear Reactor Regulation, 79/03/23, 17pp.
- --7905070351 Notice of issuance & availability of Amend 50 to License DPR-65. REID,R.W. Operating Reactors Branch 4. 79/03/23. 200.
- 7905240253 Forwards draft safety evaluation re proposed neutron shield design to reduce radiation level outside containment.Load analysis to be completed 800101.

  LAINAS. G. Plant Systems Branch. 79/04/17. 7pp.
- 7905290007 Forwards Amends 60 & 51 to Licenses DPR-21 & DPR-65, respectively, EIA & notice of issuance & negative declaration.
  ZIEMANN, D. L. Operating Reactors Branch 2. 79/04/24. 3pp.
- --7905290012 Amends 60 % 51 to Licenses DPR-21 % DPR-65 respectively, revising ETS to provide more flexibility in sampling schedules % collection for aquatic monitoring % reflecting improved & modified program objectives.
  ZIEMANN, D. L. Operating Reactors Branch 2. 79/04/24. 13pp.
- ---7905290016 EIA supporting Amends 60 % 51 to Licenses DPR-21 % DPR-65, respectively.

  \* Office of Nuclear Reactor Regulation. 79/04/24. 11pp.
- --7905290019 Notice of issuance of Amends 60 & 51 to Licenses DPR-21 & DPR-65.respectively, & negative declaration.
  ZIEMANN,D.L. Operating Reactors Branch 2. 79/04/24. 2pp.
- 7905040135 Responds to NRC 780419 request for insulation resistance tests. Forwards electrical penetration testing evaluation. Modified conductor configuration is acceptable for Cycle 3 operation. COUNSIL.W.O. Northeast Utilities. 79/04/26. Bpp.
- 7905070359 Forwards proposed revision to Tech Specs to allow unlimited containment purges. Revisions deal w/containment isolation valves.
  COUNSIL, W. C. Northeast Utilities. 79/04/27. 16pp.
- 7905080406 Forwards responses to request for add1 info re Cycle 3 safety analysis. Nonproprietary rept encl. Proprietary version withheld (ref 10CFR2.790).

  COUNSIL, W. G. Northeast Utilities. 79/05/03. 17pp.
- 7905100320 Discusses addl info re control element assembly guide tube insp.Fuel assemblies suitable for continued use during Cycle 3 operation.

  COUNSIL.W. Q. Northeast Utilities. 79/05/07. 2ps.
- 7905160262 Notifies that stem-mounted limit switches on valves SI-614. SI-624. SI-634 & SI-644 will not be replaced; valves do not perform safety-related function. COUNSIL, W. G., SWITZER, D. C. Northeast Utilities. 79/05/08. 2pp.

- 7905160376 Discusses results of six tasks which utilized ADLPIPE computer program for reanalysis of piping sys. Mods involved minor changes to small portions of existing sys.

  COUNSIL, W. G., SWITZER, D. C. Northeast Utilities. 79/05/11. 3pp.
- 7905300645 Informs of forthcoming detailed reply to 790507 ltr re CT nuclear power plants. Plants will not start up until all post-TMI items & requirements are implemented & confirmed. HENDRIE, J. M. Commission. 79/05/11.
- --7905300647 Requests assurance that action required by IE info notices & bulletins have been implemented before CT plants return to operation. Also requests info on other anticipated NRC actions or anticipated problems.

  GRASSO.E. Connecticut, State of. 79/05/07. 2pp.
- 7905220116 Forwards add1 info re performance of control element assembly guide tubed sleeves in response to 790512 ltr. COUNSIL, W. G. Northeast Utilities. 79/05/17. 6pp.
- 7905300009 Comments on need for repairing or replacing aerated radwaste evaporator. Replacement not warranted, based on discharge criteria, actual plant releases & ALARA considerations. COUNSIL, W. G. Northeast Utilities. 79/05/21. 2pp.
- 7905310183 Forwards proprietary & nonproprietary versions of "Sleeved CEA Guide Tube Eddy Current Test Results." Proprietary version withheld (ref 10CFR2.790). W/affidavit re withholding.
  CDUNSIL.W. G. Northeast Utilities. 79/05/23. 6pp.
- --7905310189 "Sleeved CEA Guide Tube Eddy Current Test Results."

  \* Northeast Utilities. CEN-108(N)-NP. 79/05/02. 6pp.
- G. Inspection reports, IE Bulletins & correspondence
- 7905240692 Forwards IE Insp Repts 50-245/78-42 & 50-336/78-39 on 781208-790105. No noncompliance noted. BRUNNER,E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/03/21. 2pp.
- --7905240704 IE Insp Repts 50-245/78-42 & 50-336/78-39 on 781208-790105.

  No noncompliance noted Major areas inspected:Unit 1 reactor, turbine & radwaste bldgs. Unit 2 auxiliary & turbine bldgs, condensate polishing facility & radiation protection.

  SHEDLOSKY.J.T. Region 1, Philadelphia, Office of the Director.

  MCCABE.E.C. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/03/20. 13pp.
- 7905010121 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping." GRIER.B.H. Region 1, Philadelphia, Office of the Director. 79/03/23. 1p.
- 7905010053 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air."

  ORIER, B. H. Region 1, Philadelphia, Office of the Director. 79/03/28. 1p.
- 7905010304 Foreards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin." GRIER,B.H. Region 1, Philadelphia, Office of the Director. 79/03/30. 2pp.
- 7905290160 Forwards IE Insp Rept 50-336/79-04 on 790220-23.No noncompliance noted.
  BRUNNER.E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/04/10. 2pp.
- --7905290166 IE Insp Rept 50-336/79-04 on 790220-23. No noncompliance noted Major areas inspected:administrative controls of facility procedures & safety related calibr.
  ZIMMERMAN,R.P., BAUNACK,W.H. Region 1, Philadelphia, Office of the Director. KISTER,H.B. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/03/27. 16pp.
- 7905020061 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." Licensee action required.

  GRIER, B.M. Region 1, Philadelphia, Office of the Director.
  79/04/11. 1
- 7903020300 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required. GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/04/14. 1p.

- 7905040047 Forwards IE Bulletin 79-068, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." Licensee action required. Region 1, Philadelphia, Office of the Director. 79/04/14 1p
- 7905040214 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Hater Power Reactors Identified During TMI Incident." QRIER.B. H. Region 1, Philadelphia, Office of the Director. 79/04/14. 1p.
- 7905030077 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.

  ORIER.B H. Region 1, Philadelphia, Office of the Director.
  79/04/17. 19
- 7905020284 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."

  GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/04/18. 1
- 7905040053 Discusses guide tube insp program. Pull tests performed on 354 sleeves Evaluation of data indicates sleeves are functioning as expected.

  COUNSIL, M. G. Northeast Utilities. 79/04/26. 2pp.
- 7905300261 Provides info in response to NRC request re impact of mods & reanalyses on high energy pipe break. Topic discussed in util 790511 response to IE Bulletin 79-07.

  COUNSIL, H. G. Northeast Utilities. 79/05/23. 2pp.
- R. Periodic operating reports & related correspondence
- 7905150502 Forwards monthly operating rept for Apr 1979. OPEKA, J. F. Northeast Utilities. 79/05/09. 1p.
- --7905150505 Monthly operating mept for Apr 1979. HOWLETT, G.H. Northeast Utilities. 79/05/02. Spp.
- S. Reportable occurrences, LERs & related correspondence
- 7905140067 PND-79-91:vapor binding of shutdown cooling sys pump on 790314. Suction restored; no radioactive mat1 released to environ.

  KILINGER.G., NDLAN.F., BRYAN.S.E. Office of Inspection & Enforcement. 79/04/23. 1p.
- 7905080456 Forwards LER 78-022/03X-1.

  OPEKA, J. F. Northeast Utilities. 79/04/30. 1p.
- --7905080461 LER 78-022/03X-1 on 780906:loss of efficiency noted in methyl iodide removal sys for encl bldg A filtration sys train. Caused by normal degradation through use. MCCANN, W. J. Northeast Utilities. 79/04/30. 1p.
- 7905300452 Forwards LER 79-011/03L-0.

  OPEKA, J. F. Northeast Utilities. 79/05/18. 1p.
- --7905300457 LER 79-011/03L-0 on 790514: one electrical penetration & several boundary valves had leakage. Caused by inadevertent omission of pre-repair leak rate measurement for some valves. Test procedures to be revised.
  STRATMAN.R.A. Northeast Utilities. 79/05/18. 3pp.
- 7905290221 RO 79-12/IP: inoperable linear power range channels. Caused by open connections between channels A & D detector cables. Connections repaired.

  OPEKA, J. F. Northeast Utilities. 79/05/22. 1p.
- DOCKET 50-338 NORTH ANNA POWER STATION, UNIT 1
- G. Adjudicatory correspondence

- Marine

- 7905030262 Petition for formal intervenor status on turbine missile issue. If denied, requests permission to present evidence & cross-examine as amicus curiae. Certificate of Svc encl. WEISS, E. R. Sheldon, Harmon & Roisman. 79/03/14. 9pp.
- 7905030207 Agreement via stipulation of contentions, including withdrawal of previous contentions. Notice of appearance of RJ Goddard on behalf of NRC & Certificate of SVc encl. BOUGHERTY, J. B. Potomac Alliance. GOLDBERG

- --7905030209 Agreement via stipulation of contentions, including withdrawal of previous contentions.

  KROOT.I. Citizens Energy Forum. GOLDBERG.S.C. Branch 2.

  CHRISTMAN.J. Virginia Electric & Power Co. 79/03/23. 7pp.
- 7905030258 Answer by util in opposition to UCS 790314 petition to intervene. Claims untimeliness, intervention during appellate stage & lack of standing, Certificate of Svc encl. RINACA, J. M. Hunton & Williams. 79/03/29. 22pp.
- 7905010115 Forwards request for Board notification re nonsafety-grade equipment to mitigate transients.
  SCINTO.J.F. Hearings Division. 79/04/02. 31pp.
- --7905010156 Board notification:staff assessment re nonsafety-grade equipment to mitigate transients. VASSALLO.D.B. Assistant Director for Light Water Reactors. 79/03/29. 2pp.
- --7905010198 Board notification: recent issue on nonsafety-grade equipment to mitigate transients. More info is required. TEDESCO.R.L. Assistant Director for Reactor Safety. 79/03/16. 3pp.
- 7905230668 Notifies that recent info may affect licensing of high density spent fuel storage racks. Svc water temp & component cooling water temp will exceed values in FSAR. CHRISTMAN. J. N. Hunton & Williams. 79/04/04. 2pp.
- 7905240135 ALAB-536, denying UCS 790314 petition to intervene or participate in hearing as amicus curiae.

  DUFLG.M.E. Atomic Safety and Licensing Appeal Panel. 79/04/05.

  8pp.
- 7905240487 Directs parties to submit responsive prepared testimony re pumphouse settlement & turbine missile issues before 790331. Evidentiary hearing to be held during week of 790618. Lists procedures for informal discovery process. DUFLO.M.E. Atomic Safety and Licensing Appeal Panel. 79/04/09. 4pp.
- 7705100137 Forwards EIA re proposed increase of storage capacity of spent fuel pool.

  OULDBERG.S.C. Branch 2. 79/04/10. 1p.
- --7905100140 EIA supporting proposed increase in storage capacity of spent fuel pool.

  \* Office of Nuclear Reactor Regulation. 79/04/02. 32pp.
- 790511041B Response to ALAB-509 re radon emissions & de minimus theory from Perkins record.Certificate of Svc encl. SCINTO.J.F. Hearings Division. 79/04/11. 45pp.
- 7905140519 Response to 790404 brief of Philadelphia Electric Co.PSE&G & Atlantic City (NJ) Electric Co re de minimus theory.

  Certificate of Svc encl.

  KEPFORD, C. R. Citizens for Safe Environment. 79/04/11. Bpp.
- 7905241006 Corrects info submitted on 790334 re deficiency in Westinghouse ECCS evaluation model Model reanalysis indicates North Anna 1 & 2 still in compliance w/10CFR50.46. SWANSON,D.T. Branch 1. 79/04/13. 1p.
- 7905240255 Requests extension of time to 790504 in which to prepare testimony. Granted by ASLAB on 790420. Certificate of Svc encl.

  SWANSON, D. T. Branch 1. 79/04/20. 5pp.
- 7905230655 Grants interventions of Citizens Energy Forum & Potomac Alliance.Provides for hearing & designates contentions of intervenors.

  DEALE, V. B. Atomic Safety and Licensing Board Panel. 79/04/21. 4pp.
- 7905030330 Affidavit of Svc for applicant's Amend 66 in proceeding. NEIL,R.M. Virginia, State of. 79/04/25. 2pp.
- 7905140332 Notifies of consolidation of five intervenor groups re radon emissions issue. Parties have until 790525 in which to file for summary disposition.

  DUFLO, M.E. Atomic Safety and Licensing Appeal Panel. 79/04/25.
- 7905240814 Forwards second copy of util's testimony re probability of generating turbine missiles & turbine overspeed protection sys. W/o encl.
  CHRISTMAN, J. N. Hunton & Williams. 79/04/30. 2pp.

- 7905240455 Ack receipt of 790405 ltr requesting NRC to revoke OLs.Ltr is currently under consideration.Forwards FR notice re Allen 790405 1 tr
- 790403 Itr. DENTON, H. R. Office of Nuclear Reactor Regulation. 79/05/04. 1p
- --7905240461 FR notice re J Allen 790405 request for revocation of OLs. DENTON, H. R. Office of Nuclear Reactor Regulation. 79/05/04. 2pp.
- 7905240510 Extends time for NRC review of ALAB-536 until 790511. CHILK.S.J. Office of the Secretary of the Commission. 79/05/04.
- 7905240571 Following 790626 prehearing conference, hearing shall commence re application by util for OL amend to increase spent fuel pool storage capacity, per 790423 order granting intervention DEALE, V. B Atomic Safety and Licensing Board Panel. 79/05/04. Spp.
- 7905310033 Forwards J Allen 790405 ltr requesting NRC revoke facility OLs & FR notice of revocation request.W/790330 ltr to ASLAB re-Westinghouse ECCS deficiency.

  DENTON.H.R. Office of Nuclear Reactor Regulation. 79/05/04. 3pp.
- 7905250233 Request to amend petition to intervene by adding contention re svc water cooling sys. Notice of appearance of GM Gilman on behalf of intervenors, Certificate of Svc & supporting documentation encl.

  DOUGHERTY, J. B., GILMAN, G. Potomac Alliance. 79/05/09. 11pp.
- I. Financial information
- 7905020459 Discusses SEC 790321 ltr & registration statement.Util will file another statement which NRC will be able to review.

  DROMERICK.A.W. Light Water Reactors Branch 3. 79704/09. 1p.
- --7905020466 Forwards SEC 790316 registration statement filed by util. Requests comments by 790330/util wishes statement to become effective by 790402 MORIN/H F. Securities & Exchange Commission. 79/03/21. 60pp.
- J. Insurance & indemnity information
- 7905110107 Amend to Endorsement S1 to NELIA Policy NF-186. Constitutes
- Nuclear Energy Liability Insurance Association. 79/04/27. 1p.
- 7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,163,164,187,188,189,192,193,194,195,197,198,200,201,204,204,207,208,210,212,214,215,&others.

  QUATTROCHHI, J. American Nuclear Insurers. 79/05/01. 1p.
- 7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,56,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,91,92,93,94,95 % 96 ROBERTS,D.M. Mutual Atomic Energy Liability Underwriters. 79/05/01.
- 7905110090 Endorsements 16.30.36 & 47 to NELIA Policy NF-186. BARDES.C.R. Nuclear Energy Liability Insurance Association. 79/05/01. 1p.
- 7905140523 Forwards Amend 5 to Indemnity Agreement 8-80 per 10CFR140 changes, re increase in liability insurance from \$140 million to \$160 million, effective 790501. Supporting documentation SALTZMAN, J Antitrust & Indemnity Group. 79/05/01. 6pp.
- 7905240342 Forwards executed Amend 5 to Indemnity Agreement B-80. STALLINGS.C.M Virginia Electric & Power Co. 79/05/21. 2pp.
- 7903300334 Forwards Endorsements 17,20 & 21 to NELIA Policy NF-240. KELLEY,P J. Johnson & Higgins Insurance. 79/05/23. 4pp.
- O. Advisory Committee on Reactor Safeguards reports & correspondence
- 7905100325 Responds to request for written rept after cancellation of ACRS 790331 meeting re-possibility of problem w/instrument guide tubes Staff rept encl.
  CROCKER, L. P. Division of Project Management. 79/03/30. 5pp.
- P. Operating license stage documents & correspondence
- 7905020490 Discusses 790315 telcon w/R Sero of Westinghouse re incorrect weights for Velan Model C658 6-inch check valves used in cafety injection sys. SCHWENCER, A Operating Reactors Branch 1. 79/04/02. 1p.

- 7905070087 Forwards EIA re expansion of spent fuel storage pool REGAN, W. H. Environmental Projects Branch 2. 79704/06.
- -7905070090 EIA re proposed increase in storage capacity of spent fuel Environmental Projects Branch 2. 79/04/02. 32pp
- 7905090304 Informs of completion of review of 781226 revised plant staff organization. Revisions aceptable if add1 level is added & if appointment of alternates is clarified. PARR.O.D. Light Water Reactors Branch 4. 79/04/09. Spp.
- 7905020358 Ack receipt of 790409 ltr re reorganization. Modified requirements for personnel qualifications will be incorporated into FSAR in upcoming amend.

  STALLINGS.C.M. Virginia Electric & Power Co. 79/04/27. 1p.
- 7905040126 Responds to AW Dromerick request re elevation marker readings located on svc water piping at svc water pumphouse. BROWN, S. C. Virginia Electric & Power Co. 79/05/01. 1p.
- 7905240407 Submits 790903 elevations of three settlement markers at svc water pumphouse.

  BROWN, S. C. Virginia Electric & Power Co. 79/05/01. 1p.
- 7905100317 Forwards drawings of stainless steel pressure-balanced expansion joints for svc water piping at svc water pumphouse in response to AW Dromerick request. Oversized drawings encl.
  BROWN,S.C. Virginia Electric & Power Co. 79/05/03. 1P.
- 790508042B Notifies of plans to test Unit 2 auxiliary svc water pump 2-sw-p-4 on monthly bases, as outlined in inservice testing program submitted on 790131. Will test 1-sw-p-4 before OL is issued for Unit 2. Piping mod presently unnecessary.

  STALLINGS, C. M. Virginia Electric & Power Co. 79/05/04. 1p.
- 79050B0443 Supplements 79030B rept "Svc Water Reservoir & Spray Sys Performance Testing & Evaluation." Spent fuel pool temp will exceed 110 F FSAR limit.Lists methods to meet limits.Fuel rack license application & FSAR will be amended. BROWN,S.C. Virginia Electric & Power Co. 79/05/04. 1p.
- 7905080506 Lists completed Tech Specs testing requirements which should be deleted from list of tests requiring deferral for amend to OL. STALLINGS, C. M. Virginia Electric & Power Co. 79/05/04.
- 7905190062 Forwards fee for issuance of Amend 10 to License NPF-4. STALLINGS.C.M. Virginia Electric & Power Co. 79/05/07. 1p.
- 7905150270 Forwards replacement pages to 780501 application to amend License NPF-4 to expand spent fuel storage capacity. STALLINGS,C.M. Virginia Electric & Power Co. 79/05/11. 10pp.
- 7905210176 Forwards suppl to proposed Tech Spec Change 12 re increasing amount of allowable settlement for svc water pumphouse. STALLINGS, C. M. Virginia Electric & Power Co. 79/05/17. 23pp.
- 7905230536 Suppl to proposed Tech Spec Change 12, "Settlement of Class I Structures." increasing amount of allowable settlement for svc waterpump house. Forwards revised Tech Spec. marked-up original & discussion of change.

  STALLINGS, C. M. Virginia Electric & Power Co. 79/05/17. 23pp.
- 7905230022 Forwards response to NRC 790503 evaluation & request for add1 info re "Svc Water Reservoir & Spray Sys Performance Testing & Evaluation."

  BROWN,S.C. Virginia Electric & Power Co. 79/05/18. 8pp.
- 7905290375 Responds to AW Dromerick 790503 questions re containment depressurization, net positive suction head analyses & effects of increased calculated svc water temps on design of charging pump coolers. BROWN, S.C. Virginia Electric & Power Co. 79/05/23. 14pp.
- G. Inspection reports, IE Bulletins & correspondence
- 7905010255 Forwards IE Insp Repts 50-338-/79-01 & 50-339/79-01 on 790102-0202 & notice of violation. LEWIS,R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/03/16. 2pp.
- --7905010264 Notice of violation from insp on 790102-0202.

  \* Region 2, Atlanta, Reactor Operations Nuclear Support Branch.
  79/03/14. 1p.

- --7905010275 IE Insp Repts 50-338/79-01 & 50-339/79-01 on 790102-0202.

  Noncompliance noted:failure to document approval of change to test procedure.

  KIDDS:N S / CANTRELL.F.S. Region 2, Atlanta, Reactor Operations Nucleer Support Branch. 79/03/14. 19pp.
- 7905010224 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping" 0'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79/03/23. 2pp.
- 7905090129 Forwards IE Insp Repts 50-338/79-04 & 50-339/79-04 on 790122-25 & notice of violation.
  LEWIS.R.C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 79/03/23. 2pp.
- --7905090132 Notice of violation from insp on 790122-25.

  \* Region 2, Atlanta, Office of the Director. 79/03/13. 1p.
- --7905090135 IE Insp Repts 50-338/79-04 & 50-339/79-04 on 790122-25.
  Noncompliance noted:failure to identify Tech Spec-listed snubbers prior to removal for testing.

  DYER, J.A., JOHNSON, A.H. Region 2, Atlanta, Office of the Director, MARTIN, R.D. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/03/13, 8pp.
- 7905030319 Ferwards IE Info Notice 79-07, "Rupture of Radwaste Tanks." O'REILLY.J.F. Region 2, Atlanta, Office of the Director. 79/03/26. 2pp.
- 7905010123 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air."

  0 'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/03/28. 2pp.
- 7905010369 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin."

  O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
  79/03/30. 2pp.
- 7905080534 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." Licensee action required.

  O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
  790/04/11 1n
- 7905040254 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."

  O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
  79/04/14 200.
- 7905040271 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79704714. 1p.
- 7905040449 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident." O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/14. 1p.
  - onds to IE Bulletin 79-03, "Longitudinal Weld Defects in pe 304 Stainless Steel Pipe Spools Mfg by ding & Engineering Co." North Anna 1 uses no Surry 1 & 2 records are still under review. Virginia Electric & Power Co. 79/04/16. 2pp.
  - rds IE Bulletin 79-09, "Failures of GE Type AK-2 r in Safety-Related Sys." Licensee action
    - Region 2, Atlanta, Office of the Director.
  - rds IE Bulletin 79-06A.Revision 1, "Review of rors & Sys Misalignments Identified During TMI
    - Region 2, Atlanta, Office of the Director.
  - eceipt of 790411 ltr informing NRC of steps taken to ion noted in IE Insp Rept 50-338/79-03.
    Region 2. Atlanta, Fuel Facility & Materials 79/04/18. 1p.
  - ponds to NRC 790320 ltr re violation noted in IE Insp 79-03. Corrective actions: health physics rainee not meeting min qualification was removed n schedule. M. Virginia Electric & Power Co. 79/04/11. 2pp.

- --7905230672 Forwards IE Insp Rept 50-338/79-03 on 790205-09 & notice of violation.
  SUTHERLAND, J.T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/03/20. 2pp.
- --7905230674 Notice of violation from insp on 790205-09.

  \* Region 2. Atlanta, Office of the Director. 79/03/20. ip.
- --7905230679 IE Insp Rept 50-338/79-03 on 790205-09. Noncompliance noted:
  health physics technician trainee w/inadequate experience
  used in responsible position.
  JEMKINS. G.R. Region 2, Atlanta, Office of the Director.
  GIBSON.A.F. Region 2, Atlanta, Fuel Facility & Materials Safety
  Branch. 79/03/19. 5pp.
- 7905240162 Responds to IE Bulletin 79-07 re seismic analysis of safety-related piping. No computer codes identified using methods described.

  SPENCER.W.C. Virginia Electric & Power Co. 79/04/24. 10pp.
- 7905240181 Responds to IE Bulletin 79-06A. "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
  Review committee was established & detailed review of TMI incident has been completed.
  STALLINGS.C.M. Virginia Electric & Power Co. 79/04/26. 9pp.
- 7905290119 Ack receipt of 790410 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-338/79-11 & 50-339/79-16.
  SUTHERLAND.J.T. Region 2, Atlanta, Fuel Facility & Materials Bafety Branch. 79/05/01. 1p.
- --7905290125 Responds to NRC 790316 ltr re violations noted in IE Insp Repts 50-339/79-11 & 50-339/79-16. Corrective actions: applicable emergency plan implementing procedures put into action. STALLINOS.C.M. Virginia Electric & Power Co. 79/04/10. 3pp.
- --7905290130 Forwards IE Insp Repts 50-338/79-11 & 50-339/79-16 on 790228-0302 & notice of violation.
  SUTHERLAND.J.T. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 79/03/16. 2pp.
- --7905290138 Notice of violation from insp on 790228-0302. \* Region 2, Atlanta, Office of the Director. 79/03/16. 1p.
- --7905290142 IE Insp Repts 50-338/79-11 & 50-339/79-16 on 790228-0302.
  Noncompliance noted:release of radioactivity to unrestricted area.
  ZAVADOSKI.R.W. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/03/16. Spp.
- 7905300734 Ack receipt of IE Insp Rept 50-338/79-13 on 790305-15. No proprietary info.
  STALLINGS.C.M. Virginia Electric & Power Co. 79/05/01. 1p.
- 7905300023 Forwards IE Insp Repts 50-338/79-12 % 50-339/79-19 on 790416-20.No noncompliance noted.

  KENNA,W.B. Region 2, Atlanta, Safeguards Branch. 79/05/02. 2pp.
- --7905300026 IE Insp Repts 50-338/79-12 & 50-339/79-19 on 790416-20. No noncompliance noted Major areas inspected: security plan, protected area barriers: vital area barriers & access controls. Details withheld(ref 10CFR. 790).
  HENNESSEY, R. J. Region 2. Atlanta, Office of the Director. TOBIN, W. J. Region 2. Atlanta, Safeguards Branch. 79/05/02.
- 7905240481 Confirms 790426 response to IE Bulletin 79-06A re actions taken on Unit 1. All commitments for Unit 1 will apply to Unit 2.

  STALLINGS.C.M. Virginia Electric & Power Co. 79/05/03. 1p.
- 7905300706 Forwards response to IE Bulletin 79-04. Velan swing check valves of three & six inches installed in chemical vol & control & safety injection sys.

  STALLINGS.C.N. Virginia Electric & Power Co. 79/05/03. 4pp.
- 7905210275 Responds to IE Bulletin 79-06A, Revision 1. Provides requested info on design changes re containment sump pump trip valve actuation & safety injection logic.

  STALLINGS, C. M. Virginia Electric & Power Co. 79/05/17. 2pp.
- 7905290032 Responds to IE Bulletin 79-09. QE Type AK-2 circuit breakers not in use or planned for use.
  STALLINGS.C.M. Virginia Electric & Power Co. 79/05/23. 1p.
- 7905300018 Responds to IE Bulletin 79-10.Forwards requalification training program statistics.
  STALLINGS.C.M. Virginia Electric & Power Co. 79/05/24. 5pp.

- R. Periodic operating reports & related correspondence
- 7905190191 Forwards monthly operating rept for Apr 1979. STALLINGS, C. M. Virginia Electric & Power Co. 79/05/15. 1p.
- -7905190193 Monthly operating rept for Apr 1979. MADISON, W. R. Virginia Electric & Power Co. 79/05/08. 4pp.
- S. Reportable occurrences, LERs & related correspondence
- 7905110203 Board notification: Seabrook refueling water storage tank NOSINGUS BOARD HOUTTLEATION. SEABTHOOK PETUEIING & design deficiency. SCINTO, J. Hearings Division. 79/03/29. 30pp.
- 7905140401 Responds to 790411 notification of defect in computer program allowing vital area access by unauthorized personnel. Security personnel deployed to prevent recurrence. STALLINGS, C. M. Virginia Electric & Power Co. 79/04/12. 2pp.
- 7905230631 Forwards addl info re significant potential safety hazard reported on 790421. Software program failure caused degraded moderallowing unrestricted access to any cardholder. Vital entrances guarded while sys restored.

  STALLINGS.C.M. Virginia Electric & Power Co. 79/04/23. 2pp.
- 7905020245 Forwards LER 79-047/01T-0. STALLINGS,C.M. Virginia Electric & Power Co. 79/04/26. ip.
- --790502024B LER 79-047/01T-0 on 790412:during reanalysis of regenerative heat exchanger, nozzle loading by vendor discovered loads exceed vendor umbrella loading, caused by miscalculation of nozzle loading during initial analysis.

  CARTWRIGHT, W. R. Virginia Electric & Power Co. 79/04/26. 2pp.
- 7905020474 Forwards LER 79-043/01T-0. STALLINGS, C. M. Virginia Electric & Power Co. 79/04/26. 1p.
- --7905020484 LER 79-043/01T-0 on 790411:manufacturer determined generic problem exists w/lower radial bearings of recirculation spray sys motors. Bearing failure could result Installed Spray sys motors, bearing teather code to be bearings tested.

  CARTWRIGHT, W. R. Virginia Electric & Power Co. 79/04/24. 3pp.
- 7905020391 Forwards LERs 79-029/03L-0 & 79-042/03L-0. STALLINGS.C.M. Virginia Electric & Power Co. 79/04/27. 1p.
- --7905020396 LER 79-029/03L-0 on 790330:component cooling was lost to reactor coolant pump during steady state operation at 97% power. Caused by burned out, air solenoid coil. Coil replaced. CARTWRIGHT, W. R. Virginia Electric & Power Co. 79/04/24. 2pp.
- --7905020403 LER 79-042/03L-0 on 790330: auxilary feedwater pump 1-FW-P-2 turbine governor/trip valve tripped closed at 40% power. Caused by overspeed trip signal from auxiliary feedwater pump turbine. Further testing performed. CARTWRIGHT.W.R. Virginia Electric & Power Co. 79/04/24. 2pp.
- 7905040626 Significant deficiency rept on 790425. Computer program would not correctly operate sys, allowing unauthorized person access to vital area. Computer program currently being STALLINGS, C. M. Virginia Electric & Power Co. 79/05/01. 2pp.
- 7905070530 Forwards LER 79-052/01T-0. STALLINGS.C.M. Virginia Electric & Power Co. 79/05/03. 1p.
- --7905070533 LER 79-052/01T-0 on 790419:util informed by S&W of potential problem w/seismic pipe stress analysis on safety injection piping. Caused by error in computer program input for design of pipe supports. Program corrected & mods made. CARTWRIGHT, W.R. Virginia Electric & Power Co. 79/05/02. 2pp.
- 7905070656 Forwards LERs 79-045/03L-0 & 79-046/03L-0. STALLINGS.C.M. Virginia Electric & Power Co. 79/05/03. 1p.
- --7905070659 LER 79-045/03L-0 on 790404: level transmitter found out of calibr. Caused by instrument drift. Transmitter recalibr. CARTWRIGHT, W. R. Virginia Electric & Power Co. 79/05/02. 3pp.
- --7905070662 LER 79-046/031-0 on 790408: during cold shutdown, changing pumps 1A & 18 were tagged out w/o racking in alternate feeder breaker for pump 1C Caused by personnel error. Pump 1C alternate feeder breaker racked in.

  CARTWRIGHT, W. R. Virginia Electric & Power Co. 79/05/02. 2pp.
- 7905080444 Forwards LERs 79-056/01T-0 & 79-057/01T-0. 8TALLINGS,C.M. Virginia Electric & Power Co. 79/05/04. 1p.

- --7905080447 LER 79-056/01T-0 on 790421:12 expansion joints on svc water side of component cooling heat exchangers were deflected greater than alignment allowances. Caused by failure to install correct number of tie-rods on expansion joints. CARTWRIGHT, W. R. Virginia Electric & Power Co. 79/05/04. 2pp.
- --7905080449 LER 79-057/01T-0 on 790424: transfer bus & feeder cables not capable of continually carrying full load current for certain conditions. Caused by improper sizing of equipment. Final solution being analyzed.

  CARTWRIGHT, W. R. Virginia Electric & Power Co. 79/05/04. 3pp.
- 7905110142 Forwards LERs 79-034/03L-0 & 79-051/03L-0. STALLINGS, C. M. Virginia Electric & Power Co. 79/05/07. 1p.
- --7905110147 LER 79-034/03L-0 on 790410: snubber 1-RC-HSS-85 had empty reservoir & declared inoperable. Caused by improperly seated 0 ring resulting in leak. Snubber replaced.

  CARTWRIGHT, M. R. Virginia Electric & Power Co. 79/05/04. 1p.
- --7905110152 LER 79-051/03L-0 on 790416:RHR isolation valve MOV-1701 failed to close automatically in reponse to trip signal. Caused by misaligned limit switch contact in valve "close" circuitry. Contact realigned & valve retested satisfactorily. CARTWRIGHT, W. R. Virginia Electric & Power Co. 79/05/04. 2pp.
- 7905160432 Forwards LERs 79-048/03L-0,79-049/03L-0,79-050/03L-0 & 79-055/03L-0.
  STALLINGS,C.M. Virginia Electric & Power Co. 79/05/11. 1p.
- --7905160444 LER 79-049/03L-0 on 790412:recalibr of steam generator 1B revealed nonconservative drift. Caused by instrument drift. Recalibr for level channel corrected problem.

  CARTWRIGHT, W. R. Virginia Electric & Power Co. 79/05/11. 2pp.
- 4-7905160454 LER 79-050/03L-0 on 790412:recallibr on containment pressure channel P-LM-100A revealed nonconservative instrument drift. Caused by excessive drift of power supply in instrument. CARTWRIGHT, W. R. Virginia Electric & Power Co. 79/05/11. 2pCp./.
- --7905160458 LER 79-055/03L-0 on 790401: during Mode 3 operation, three rod position indicators read high while rods were actually at 0 steps. Caused by electrical drift in indicator circuitry. Recalibr solved problem.

  CARTWRIGHT. W. R. Virginia Electric & Power Co. 79/05/11. 2pp.
- 7905210258 Forwards LER 79-062/01T-0. STALLINGS.C.M. Virginia Electric & Power Co. 79/05/17. 1p.
- --7905210260 LER 79-062/01T-0 on 790503: temporary iron corner braces discovered on exhaust ducting of diesel generator cooling fans. Caused by braces left in place after ducting fabrication. Braces removed. CARTWRIGHT, W. R. Virginia Electric & Power Co. 79/05/17. 2pp.
- 7905220287 Forwards LER 79-053/03L-0. STALLINGS.C.M. Virginia Electric & Power Co. 79/05/18. 1p.
- --7905220296 LER 79-053/03L-0 on 790419: while performing penetration leak testing: 20 valves discovered to have leakage exceeding allowable limits. Caused by deterioration of valve seats. Valves reworked.

  CARTWRIGHT, W.R. Virginia Electric & Power Co. 79/05/19. 2pp.
- 7905230060 Forwards LER 79-065/01T-0. STALLINGS.C.M. Virginia Electric & Power Co. 79/05/21. 1p.
- --7905230071 LER 79-065/01T-O on 790507: informed by A/E that solenoid valves in sample sys did not meet proper environ qualifications. Caused by use of valves which were not environmentally qualified. CARTWRIGHT, W. R. Virginia Electric & Power Co. 79/05/21. 2pp.
- 7905300401 Forwards LERs 79-061/03L-0,79-072/03L-0 & 79-058/03L-0. STALLINGS, C.M. Virginia Electric & Power Co. 79/05/25. 1p.
- --7905300404 LER 79-061/03L-0 on 790430: temp indicator TI-RS-100A on casing cooling tank read out of specs at greater than 50 F.
  Caused by slipping belt on mechnical refrigerator unit.
  CARTWRIGHT. M.R. Virginia Electric & Power Co. 79/05/28. 2pp.

- --7905300408 LER 79-072/03L-0 on 790514:main steam trip valve TV-MS-111B would not fully shut.Caused by deteriorated internal gasket. Gasket replaced.
  CARTWRIGHT, W. R. Virginia Electric & Power Co. 79/05/28. 2pp.
- -7905300412 LER 79-058/03L-0 on 790430:safety injection valve MOV-1865B failed to open. Caused by dried packing around valve stem.
  Valve manually opened & broken free from closed position.
  CARTWRIGHT, W. R. Virginia Electric & Power Co. 79/05/28. 2pp.
- DOCKET 50-339 NORTH ANNA POWER STATION, UNIT 2 A. Application/construction stage documents & correspondence
- 7905290296 Requests NRC reconsider its 3-month moratorium on issuance of new OL because of large addl costs of replacement power. RAGONE, S. Virginia Electric & Power Co. 79/05/22. 2pp.
- 7905070087 Forwards EIA re expansion of spent fuel storage pool REGAN.W.H. Environmental Projects Branch 2. 79/04/06. 1
- --7905070090 EIA re proposed increase in storage capacity of spent fuel pool.

  Environmental Projects Branch 2. 79/04/02. 32pp.
- 7905040126 Responds to AW Dromerick request re elevation marker readings located on svc water piping at svc water pumphouse. BROWN.S.C. Virginia Electric & Power Co. 79/05/01. 1p.
- 7905240407 Submits 790903 elevations of three settlement markers at svc water pumphouse. BROWN, S. C. Virginia Electric & Power Co. 79/05/01. 1p.
- 7905100317 Forwards drawings of stainless steel pressure-balanced expansion joints for svc water piping at svc water pumphouse in response to AW Dromerick request Oversized drawings encl. BROWN, S. C. Virginia Electric & Power Co. 79/05/03. 1P.
- 7905080428 Notifies of plans to test Unit 2 auxiliary svc water pump 2-sw-p-4 on monthly bases, as outlined in inservice testing program submitted on 790131 Will test 1-sw-p-4 before OL is issued for Unit 2.Piping mod presently unnecessary.

  STALLINGS.C.M. Virginia Electric & Power Co. 79/05/04. 1p.
- 7905080443 Supplements 790308 rept "Svc Water Reservoir % Spray Sys Performance Testing % Evaluation." Spent fuel pool temp will exceed 110 F FSAR limit.Lists methods to meet limits.Fuel rack license application % FSAR will be amended.
  BROWN,S.C. Virginia Electric % Power Co. 79/05/04. 1p.
- 7905190062 Forwards fee for issuance of Amend 10 to License NPF-4. STALLINGS,C.M. Virginia Electric & Power Co. 79/05/07. 1p.
- 7905150270 Forwards replacement pages to 780501 application to amend License NPF-4 to expand spent fuel storage capacity.
  STALLINGS, C. M. Virginia Electric & Power Co. 79/05/11. 10pp.
- 7905210176 Forwards suppl to proposed Tech Spec Change 12 re increasing amount of allowable settlement for svc water increasing amount of allowable settlement for svc water pumphouse. STALLINGS.C.M. Virginia Electric & Power Co. 79/05/17. 23pp.
- 7905230536 Suppl to proposed Tech Spec Change 12, "Settlement of Class I Structures," increasing amount of allowable settlement for svc waterpump house. Forwards revised Tech Spec.marked-up original & discussion of change.

  STALLINGS.C.M. Virginia Electric & Power Co. 79/05/17. 23pp.
- 7905230022 Forwards response to NRC 790503 evaluation & request for add1 info re "Svc Water Reservoir & Spray Sys Performance Testing & Evaluation."

  BROWN, S. C. Virginia Electric & Power Co. 79/05/18. Spp.
- 7905290375 Responds to AW Dromerick 790503 questions re containment depressurization, net positive suction head analyses & effects of increased calculated svc water temps on design of charging pump coolers.

  BROWN, S. C. Virginia Electric & Power Co. 79/05/23. 14pp.
- 7905080441 Forwards corrections to Table A.5.1 % other matl in 790410 ltr from CM Stallings re startup physics testing program, description of input error in original computer code calculation & steps taken to preclude recurrence.

  STALLINGS,C.M. Virginia Electric & Power Co. 79/05/02. 20pp.

- Q. Adjudicatory correspondence
- 7905030262 Petition for formal intervenor status on turbine missile issue. If denied, requests permission to present evidence & cross-examine as amicus curiae. Certificate of Svc encl. WEISS, E. R. Sheldon, Harmon & Roisman. 79/03/14. 9pp.
- 7905030207 Agreement via stipulation of contentions, including withdrawal of previous contentions. Notice of appearance of RJ Goddard on behalf of NRC & Certificate of Svc encl.
  DOUGHERTY,J. B. Potomac Alliance. GOLDBERG,S. C. Regulations
  Division. CHRISTMAN,J. Virginia Electric & Power Co. 79/03/23. 1000.
- --7905030209 Agreement via stipulation of contentions, including withdrawal of previous contentions.

  KROOT.I. Citizens Energy Forum. GOLDBERG,S.C. Branch 2.

  CHRISTMAN, J. Virginia Electric & Power Co. 79/03/23. 7pp.
- 7905030258 Answer by util in opposition to UCS 790314 petition to intervene. Claims untimeliness, intervention during appellate stage & lack of standing. Certificate of Svc encl. RINACA, J. M. Hunton & Williams. 79/03/29. 22pp.
- 7905010115 Forwards request for Board notification re nonsafety-grade equipment to mitigate transients.
  SCINTO, J. F. Hearings Division. 79/04/02. 31pp.
- --7905010156 Board notification: staff assessment re nonsafety-grade equipment to mitigate transients.

  VASSALLO.D.B. Assistant Director for Light Water Reactors.

  79/03/29. 2pp.
- --7905010198 Board notification:recent issue on nonsafety-grade equipment to mitigate transients. More info is required. TEDESCO,R.L. Assistant Director for Reactor Safety. 79/03/16
- 7905230668 Notifies that recent info may affect licensing of high density spent fuel storage racks. Svc water temp & component cooling water temp will exceed values in FSAR. CHRISTMAN, J. N. Hunton & Williams. 79/04/04. 2pp.
- 7905240135 ALAB-536, denying UCS 790314 petition to intervene or participate in hearing as amicus curiae.

  DUFLO,M.E. Atomic Safety and Licensing Appeal Panel. 79/04/05.
- 7905240487 Directs parties to submit responsive prepared testimony re pumphouse settlement & turbine missile issues before 790531. Evidentiary hearing to be held during week of 790618. Lists procedures for informal discovery process. DUFLO.M.E. Atomic Safety and Licensing Appeal Panel. 79/04/07.
- 7905100137 Forwards EIA re proposed increase of storage capacity of spent fuel pool.
  GDLDBERG.S.C. Branch 2. 79/04/10. 1p.
- --7905100140 EIA supporting proposed increase in storage capacity of ent fuel pool. Office of Nuclear Reactor Regulation. 79/04/02. 32pp.
- 7905110418 Response to ALAB-509 re radon emissions & de minimus theory from Perkins record Certificate of Svc encl.
  SCINTO, J. F. Hearings Division. 79/04/11. 45pp.
- 7905140519 Response to 790404 brief of Philadelphia Electric Co.PSE&G Atlantic City (NJ) Electric Co re de minimus theory. Certificate of Svc encl. KEPFORD.C.R. Citizens for Safe Environment. 79/04/11. 8pp.
- 7905241006 Corrects info submitted on 790394 re deficiency in Westinghouse ECCS evaluation model Model reanalysis indicates North Anna 1 % 2 still in compliance w/10CFR50.46. SWANSON.D.T. Branch 1. 79/04/13. 1p.
- 7905240255 Requests extension of time to 790504 in which to prepare testimony Granted by ASLAB on 790420 Certificate of Svc Branch 1. 79/04/20. 5pp. SWANSON, D. T.
- 7905030330 Affidavit of Svc for applicant's Amend 66 in proceeding NEIL.R.M. Virginia, State of. 79/04/25. 2pp.

- 7905140332 Notifies of consolidation of five intervenor groups re rador emissions issue. Parties have until 790525 in which to file for summary disposition.

  BUFLO, M. E. Atomic Safety and Licensing Appeal Panel. 79/04/25.
- 7903240814 Forwards second copy of util's testimony re probability of generating turbine missiles & turbine overspeed protection sys. W/o encl.
  CHRISTMAN, J. N. Hunton & Williams. 79/04/30. 2pp.
- 7905240510 Extends time for NRC review of ALAB-536 until 790511. CMILK.S.J. Office of the Serretary of the Commission. 79/05/04
- 7905240571 Following 790626 prehearing conference, hearing shall commence re application by util for OL amend to increase spent fuel pool storage capacity, per 790423 order granting intervention.

  DEALE, V. B. Atomic Safety and Licensing Board Panel. 79/05/04. Spp.
- 7905250233 Request to amend petition to intervene by adding contention re svc water cooling sys. Notice of appearance of GM Gilman on behalf of intervenors, Certificate of Svc & supporting documentation encl.

  DOUGHERTY, J. B., GILMAN, G. Potomac Alliance. 79/05/09, 11pp.

#### I. Financial information

- 7905020459 Discusses SEC 790321 ltr & registration statement.Util will file another statement which NRC will be able to review.

  DROMERICK, A. W. Light Water Reactors Branch 3. 79/04/09. 1p.
- --7903020466 Forwards SEC 790316 registration statement filed by util. Requests comments by 790330:util wishes statement to become effective by 790402. MORIN.H.F. Securities & Exchange Commission. 79/03/21. 60pp.
- J. Insurance & indemnity information
- 7905110107 Amend to Endorsement 51 to NELIA Policy NF-186. Constitutes Endorsement 54.
   Nuclear Energy Liability Insurance Association. 79/04/27. 1p.
- 7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,176,179,180,182,185,186,187,188,189,192,193,194,195,197,198,200,201,204,206,207,208,210,212,214,215,&others.

  GUATTROCHHI, J. American Nuclear Insurers. 79/05/01. 1p.
- 7903070382 Confirms increase in liability limit to \$36,000,000 for policies MF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,56,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,91,92,93,94,95 & 96.
  ROBERTS,D.M. Mutual Atomic Energy Liability Underwriters. 79/05/01 ip.
- 7905110090 Endorsements 16,30,36 & 47 to NELIA Policy NF-186. BARDES.C.R. Nuclear Energy Liability Insurance Association. 79/05/01. 1p.
- 7905140523 Forwards Amend 5 to Indemnity Agreement 8-80 per 10CFR140 changes, re increase in liability insurance from \$140 million to \$160 million, effective 790501. Supporting documentation encl.

  8ALTZMAN, J. Antitrust & Indemnity Group. 79/05/01. 6pp.
- 7905240342 Forwards executed Amend 5 to Indemnity Agreement B-80. STALLINGS.C.M. Virginia Electric & Power Co. 79/05/21. 2pp.
- 7905300334 Forwards Endorsements 17.20 & 21 to NELIA Policy NF-240. KELLEY, P. J. Johnson & Higgins Insurance. 79/05/23. 4pp.

# Q. Inspection reports, IE Bulletins & correspondence

- 7905010255 Forwards IE Insp Repts 50-338-/79-01 & 50-339/79-01 on 790102-0202 & notice of violation.
  LEWIS:R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/03/16. 2pp.
- --- TYOSO10264 Notice of violation from insp on 790102-0202.

  \* Region 2. Atlanta. Reactor Operations Nuclear Support Branch.
  79/03/14. 1p.
- --7905010275 IE Insp Repts 50-338/79-01 & 50-339/79-01 on 790102-0202.

  Noncompliance noted:failure to document approval of change to test procedure.

  KIDDS,N.S.,-CANTRELL,F.S. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/03/14. 19pp.

- 7905230129 Forwards IE Insp Rept 50-339/79-12 on 790215-16. No noncompliance noted.

  MRPHY.G.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 79/03/20. 2pp.
- --7905230169 IE Insp Rept 50-339/79-12 on 790215-16. No noncompliance noted. Major areas inspected: 10CFR50. 55(e) & 10CFR21 items. MCFARLAND.C.R. Region 2. Atlanta. Office of the Director. HERDT.A.R. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 79/03/19. 4pp.
- 7905090051 Forwards IE Insp Rept 50-339/79-11 on 790129-0202.No noncompliance noted. LEMIS.R.C. Région 2. Atlanta, Reactor Operations Nuclear Support Branch. 79/03/21. 2pp.
- --7905090056 IE Insp Rept 50-339/79-11 on 790129-0202. No noncompliance noted Major area inspected procedures & activities necessary to implement operational GA program.

  JENKINS, H. D., MCDONALD, J. A. Region 2, Atlanta, Office of the Director. KELLOGO, P. J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/03/19. 30pp.
- 7905010224 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
  O'REILLY,J.P. Region 2, Atlanta, Office of the Director. 79/03/23. 200.
- 7905020458 Forwards IE Insp Rept 50-339/79-13 on 790212-15. No noncompliance noted. LEWIS.R.C. Region 2. Atlanta. Reactor Operations Nuclear Support. Branch. 79/03/23. 2pp.
- --7905020471 IE Insp Rept 50-339/79-13 on 790212-15. No noncompliance noted. Major areas inspected:comparison of as-built plant to FSAR description.

  SKOLDS, J.L. Region 2. Atlanta. Office of the Director.

  CANTRELL, F. S. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 79/03/12. 3pp.
- 7905090129 Forwards IE Insp Repts 50-338/79-04 & 50-339/79-04 on 790122-25 & notice of violation. LEWIS.R.C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 79/03/23. 2pp.
- --7905090132 Notice of violation from insp on 790122-25.

  \* Region 2, Atlanta, Office of the Director. 79/03/13. 1p.
- --7905090135 IE Insp Repts 50-338/79-04 & 50-339/79-04 on 790122-25.

  Noncompliance noted:failure to identify Tech Spec-listed snubbers prior to removal for testing.

  DYER, J. A. , JOHNSON; A. H. Region 2, Atlanta, Office of the Director. MARTIN, R. D. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/03/13. 8pp.
- 7905030319 Forwards IE Info Notice 79-07. "Rupture of Radwaste Tanks." O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/03/26. 2pp.
- 7905010123 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air."

  O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/03/28. 2pp.
- 7905010369 Forwards IE Info Notice 79-09, "Spill of Radioactively Centaminated Resin."

  D'REILLY, J. P. Region 2, Atlanta, Office of the Director.
  79/03/30. 2pp.
- 7905240530 Forwards IE Insp Rept 50-339/79-18 on 790314-0316.No noncompliance noted.
  LEWIS.R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/04/05. 2pp.
- --7905240534 IE Insp Rept 50-339/79-18 on 790314-16. No noncompliance noted Major areas inspected:startup procedures reviewed & pre-operational test witnessed.

  BURNETT, P. T., DYER, J. A. Region 2. Atlanta, Office of the Director. MARTIN.R. D. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 79/04/04. Spp.
- 7905020133 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/11. 1p.
- 7905040254 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."

  0'REILLY.J.P. Region 2, Atlanta, Office of the Director.

  79/04/14. 2pp.



- 7905040271 Forwards IE Bulletin 79-07. "Seismic Stress Analyusis of Safety-Related Piping." Licensee action required. C/REILUTUU Region 2. Atlanta, Office of the Director. 79/04/14 1p.
- 7905040448 Forwards IE Bulletin 79-08. "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident." CREILLY.J.P. Region 2. Atlanta, Office of the Director. 79/04/14. 1p
- 79050:0317 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts."

  O'REILLY, J.P. Region 2, Atlanta, Office of the Director.

  79/04/16. 2pp.
- 7905030191 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required. D'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/17 2pp.
- 7905020502 Forwards IE Bulletin 79-06A.Revision 1. "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."

  O'REILLY, J.P. Region 2. Atlanta. Office of the Director.
  79/04/18. 2pp.
- 7905240783 Responds to IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." No S&W computer codes were identified which used methods described in bulletin. SPENCER.W.C. Virginia Electric & Power Co. 79/04/25. 2pp.
- 7905290119 Ack receipt of 790410 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-338/79-11 & 50-339/79-16.
  SUTHERLAND, J. T. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 79/05/01. 1p.
- --7905290125 Responds to NRC 790316 ltr re violations noted in IE Insp Repts 50-338/79-11 & 50-339/79-16 Corrective actions: applicable emergency plan implementing procedures put into action. STALLINOS.C.M. Virginia Electric & Power Co. 79/04/10. 3pp.
- --7905290130 Forwards IE Insp Repts 50-338/79-11 & 50-339/79-16 on 790228-0302 & notice of violation.
  SUTHERLAND.J.T. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 79/03/16. 2pp.
- --7905290138 Notice of violation from insp on 790228-0302. \* Region 2, Atlanta, Office of the Director. 79/03/16. 1p.
- --7905290142 IE Insp Repts 50-338/79-11 & 50-339/79-16 on 790228-0302.
  Noncompliance noted release of radioactivity to unrestricted area.
  ZAVADOSKI.R.W. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/03/16. 5pp.
- 7905300023 Forwards IE Insp Repts 50-338/79-12 & 50-339/79-19 on 790416-20. No noncompliance noted.

  KENNA, H. B. Region 2, Atlanta, Safeguards Branch. 79/05/02. 2pp.
- 7905240481 Confirms 790426 response to IE Bulletin 79-06A re actions taken on Unit 1. All commitments for Unit 1 will apply to Unit 2.

  STALLINGS.C.M. Virginia Electric & Power Co. 79/05/03. 1p.
- 7905210275 Responds to IE Bulletin 79-06A. Revision i.Provides requested info on design changes containment sump pump trip valve actuation & safety injection logic.
  STALLINGS.C.M. Virginia Electric & Power Co. 79/05/17. 2pp.
- 7905290032 Responds to IE Bulletin 79-09. 9E Type AK-2 circuit breakers not in use or planned for use.
  STALLINGS.C.M. Virginia Electric & Power Co. 79/05/23. ip.
- 8. Reportable occurrences, LERs & related correspondence
- 7905100070 Provides info re overweight check valves used in safety injection sys. Error could result in pipes being overstressed during design basis test. Pipes being re-evaluated. BROWN, S. C. Virginia Electric & Power Co. 79/03/26. 2pp.

- 7905100076 Submits info re valve limit switch actuating arms flexing each time valve operates. Actuating arms being reworked. BROWN.S.C. Virginia Electric & Power Co. 79703/26. 2pp.
- 7905100055 Submits info re cracked splinter plate in reactor coolant sys. Weldment samples of splinter plate/weld metal/pipe boss transition being analyzed.

  BROWN, S. C. Virginia Electric & Power Co. 79/03/27. 3pp.
- 7905110203 Board notification:Seabrook refueling water storage tank design deficiency. SCINTO.J. Hearings Division. 79/03/29. 30pp.
- 7905230235 Submits addl info to 790329 rept re failure of reversing motor starter supplied by Klockner-Moeller Corp. Discusses corrective actions re checkout procedure for discovering failures prior to startup.

  \* Virginia Electric & Power Co. 79/04/03. 2pp.
- 7905290529 Submits final rept on valve malfunction. All actuating arms on valve limit switch replaced & tested satisfactorily. New arms will provide reliable valve position information. BROWN, S. C. Virginia Electric & Power Co. 79/04/19. 2pp.
- 7905070404 Rubber expansion joints in svc water piping found to be beyond misalignment tolerance acceptable to manufacturer. Svc water piping realigned & all expansion joints replaced. BROWN.S.C. Virginia Electric & Power Co. 79/05/02. 2pp.
- 7905080511 Submits final rept re deficiency in analysis of DNBR following simble rod drop. Proposes to assure that all dropped rods will result in reactor trip via negative rate trip function.

  BROWN.S.C. Virginia Electric & Power Co. 79/05/03. 1p.
- 7905080434 Follows up 790406 & 11 repts re failure of inside recirculation spray pump motor Mods & tests in progress. BROWN.S.C. Virginia Electric & Power Co. 79/05/04. 1p.
- 7905080452 Final rept re cracked flow splitter plate on reactor coolant loop piping. Cracks are characteristic of high cycle fatigue, which was probably caused by fluid flow-induced resonance in splitter plates.

  BROWN,S.C. Virginia Electric & Power Co. 79/05/04. 2pp.
- 7905090297 Notifies of completion of evaluation of cracks in loops C & A flow splitter plates. Cracks are characteristic of high cycle fatigue.

  BROWN, S. C. Virginia Electric & Power Co. 79/05/04. 2pp.
- 7905110214 Submits final 10CFR50.55(e) rept re overweight check valves in safety injection sys. New loads for nozzles, where pipes affected by overweight valves connect to reactor coolant loop piping, are acceptable.
  BROWN.S.C. Virginia Electric & Power Co. 79/05/08. 1p.
- 7905160418 Discusses pipe stress analysis deficiency for pipes passing through main steam valve house (MSVH). Analyses completed using appropriate MSVH seismic structural response. Revised nozzle loads on quench spray pumps sent to vendor. BROWN.S.C. Virginia Electric & Power Co. 79/05/10. 2pp.
- 7905220344 Provides final rept re potential deficiency in regenerative heat exchanger support Installation of bolt-on mod complete. BROWN,S.C. Virginia Electric & Power Co. 79/05/17. 1p.
- 7905290404 Forwards revised one-line diagram showing changes to alleviate potential overload situation of electrical sys which supply offsite power for startup & emergency loads. BROWN.S.C. Virginia Electric & Power Co. 79/05/23. 3pp.
- 7903300017 Reportable occurrence on 790321:weight of three 12-inch motor operated valves greater than that used by S&W in their original pipe stress analysis. Reanalysis of pipe stresses & support loads underway.

  BROWN.S.C. Virginia Electric & Power Co. 79/05/24. 2pp.
- DOCKET 50-341 ENRICO FERMI ATOMIC POWER PLANT, UNIT 2
- A. Application/construction stage documents & correspondence
- 7905150630 Notifies of cancellation of 790424 meeting w/util in Bethesda,MD to discuss OL review.

  KINTNER,L.L. Light Water Reactors Branch 1. 79/03/08. 2pp.
- 7905140251 Notifies of pending two-phase environ impact study at cooling water intake structure. Phase I will begin when plant begins drawing up water from Lake Eris. Phase II will commence when commercial operation begins.

  TURNEY, W. O. Michigan, State of. 79/05/03. 2pp.



- 7905310083 Requests add1 info to complete review of FSAR Requests FSAR be amended by 790615 to comply w/requirements BTDLZ.J.F. Light Water Reactors Branch 1 79/05/07. 4pp.
- F. Security, medical, emergency & Fire protection plans
- 7905290528 Forwards request for add1 info re security plan as result of review of OL application Request withheld (ref 10CFR 790) STOLZ, J.F. Light Water Reactors Branch 1 79/04/13 2pp.
- Q. Adjudicatory correspondence
- 7905300025 Applicants' interrogatories submitted to Citizens for Employment & Energy Certificate of Svc encl VOICHT/H.H. Lefloeuf, Lamb, Leiby & MacRae 79703727 9pp
- H. General correspondence
- 7905160443 Forwards Certificate of Evc indicating svc of Amend 22 to amended 5 substituted application for licenses to appropriate parties MATERS, B, R = Detroit I dison (for 79705704) (3pp)
- I. Financial information
- 7905040007 Forwards 1978 Annual Repts of each of three co-owners Enclavailable in Central Files only
  THOMAGRE B 79704724 tp
- G. Inspection reports. It Holletins & correspondence
- 7905010253 Forwards II Info Notice 79 Oc. "Stress Analysis of Safety-Related Piping"

  KEPPLER J G Region 'E Chicago. Office of the Director 79703/23.

  10.
- 7905230302 Forwards II Insp Rept 50 341 CP Oz. on 790000-09 No noncompliance noted FIGRELLI, C. Region 2. Chirago. Reactor Construction & Engineering Support Branch 79703723 2pp
- 7905040030 Forwards It Info Notice 29:02. "Hoptore of Radwaste Tanks " KEPPLER, J.G. Region 3. Chicago. Office of the Director 79703726 is
- 7905180410 Forwards It Insp Rept 50 341779 05 on 790306:09 & notice of violation FIORELLI, G Region 3. Chicago. Reactor Construction & Engineering Support Branch 7970327 2pp
- --7905150413 Notice of violation from insp on 790506-09 \* Region 3. Chicago. Office of the Director 79703/27 2pp
- ---7905150419 IE Insp Rept 50-341279-05 on 790306-09 Noncompliance noted density test was not performed & procedures re-noncomforming backfull were not followed HU0HES.J. BARRETT.P A Region 3. Chicago. Office of the Director HAYES.D & Region 3. Chicago. Reactor Construction & Engineering Support Branch 79703722 11pp.
- 7905030029 Forwards IE Bulletin 79-06. "Review of Operational Errors & Bys Misalignments Identified During TMI Incident."

  KEPPLER, J. Q. Region 3. Chicago. Office of the Director. 79/04/11.
- 7905010386 Forwards IE Bulletin 79-06A. "Review of Operational Errors & Bys Misalignmenta Identified During TMI Incident " KEPPLER, J.G. Region 3. Chicago, Office of the Director 79/04/14.
- 7905040387 Forwards If Sulletin 79-068. "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "
  KEPPLER, J C Region 3. Chicago, Office of the Director 79/04/14.
- 7905040460 Forwards IE Bulletin 79-07. "Seismic Stress Analysis of Bafety-Related Piping " Licansee action required KEPPLER, J Q Region 3, Chicago, Office of the Director 79/04/14.

- 7905040556 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."
  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/04/14.
- 7905010415 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts." KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/04/16. ip.
- 7905030224 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required. KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/04/17.
- 7905080492 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl." KEPPLER.J.G. Region 3, Chicago, Office of the Director. 79/04/21.
- 7905240898 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Recirculation Motor Generator Set Resulted in Reactor Power Increase." KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/05/02.
- S Reportable occurrences, LERs & related correspondence
- 7905080024 Ack receipt of 790322 interim report, per 10CFR50, 55(e), re handling damage to core spray pump motor. FIORELLI.G. Region 3, Chicago, Reactor Construction & Engineering Bupport Branch. 79/04/04. 1p.
- 7905090351 Forwards final status rept EF2-46.047 of 790419 deficiency rept on "Torus Ring Beam Weld Indications." FAHRNER, W. J. Detroit Edison Co. 79/05/01. 2pp.
- ---7905090355 Deficiency rept:defects in toe of ring beam attachment weld.

  Cracks caused hydrogen cracking characterized by intergranular fracture of course grained HAZ. Corrected by grinding & new welding procedures.

   Detroit Edison Co. 79/04/19. 3pp.
- DOCKET 50-344 TROJAN NUCLEAR PLANT, UNIT 1
- Q. Adjudicatory correspondence
- 7905250260 Submits contentions for Phase 2 of mod proceedings. Certificate of Svc & notice of change of address encl. BELLIN. Affiliation Unknown. 79/02/26. 7pp.
- 7905250279 Contentions of E Rosolie & Coalition for Safe Power reseismic capacity.cost/benefit analysis & insp procedures.

  Certificate of Svc encl.

  ROSOLIE.E Coalition for Safe Power. 79/02/26. 5pp.
- 7905030158 Response to 790130 contentions of N Bell, Consolidated Intervenors. E Rosolie & Coalition for Safe Power. Notice of appearance of AV Carr on behalf of Portland General Electric Co & Certificate of Svc encl.

  J
- 7905250273 Responds to 790305 interrogatories re adequacy of plant staff review.radioactive isotopes.core meltdown & QA programs.Certificate of Svc encl., ROSOLIE.E. Coalition for Safe Power. 79/03/19. 5pp.
- 7905:30722 Motion for order to compel E Rosolie & Coalition for Safe Power to respond fully to util's 790305 interrogatories. JOHNSON, R. W. Portland General Electric Co. AXELRAD, M., CARR, A. V. Lowenstein, Neuman, Reis, Axelrad & Toll. 79/03/23. 27pp.
- 7905100067 Affirms ASLB 781221 denial of appeal by Coalition for Safe Power & Consolidated Intervenors re interim operation issue. DUFLO.M.E. Atomic Safety and Licensing Appeal Panel. 79/03/27.
- 790510020B Position on contentions of Consolidated Intervenors & E Rosolie on behalf of Coalition for Safe Power, dtd 790226.

  Certificate of Svc encl., 79/03/27. 46pp.
- 7905070147 Informs of corrected address for Columbia Environ Council. GRAY, J. R. Branch 1. 79/04/02. 1p.

- 7905250030 Offers no objection to intervenor State of OR motion for extension of time in which to file petition for review of 790321 ASLAB decision.ALAB-531.

  ORAY, J. R. Branch 1. 79/04/05. 1p.
- 7905140033 Notifies parties that time for filing petitions for ALAB-531 review is extended until 790417. Time for NRC review is extended until 770430.

  CHILK, S. J. Office of the Secretary of the Commission. 79/04/06.
- 7905250148 Requests answers to Contentions 1 & 18 of NRC 790309 interrogatories by 790416 & identification of any add1 security concerns. GRAY, J. R. Branch 1. 79/04/09. 1p.
- 7905150811 Forwards info re PWRs. Discusses NUREG-0409, "Iodine Behavior in PWR Sys Following Postulated Steam Generator Tube Rupture Accident." GRAY, J. R. Branch 1, 79/04/10, 7pp.
- 7905250357 Petitions for review of 790321 ALAB-531 decision by ASLAB. Commission must ack strong possibility that each commercial reactor may become a de facto waste storage facility.

  GARRETT.S.M. Coalition for Safe Power. 79/04/10. 7pp.
- 7905230550 Supplemental response to 790305 interrogatories from util. Certificate of Svc encl. ROSOLIE,E. Coalition for Safe Power. 79/04/13. 7pp.
- 7905230546 Response to 790309 interrogatories from NRC.Certificate of Svc encl. ROSOLIE,E. Coalition for Safe Power. 79/04/17. 6pp.
- 7905300104 Licensees' response to 790402 request of PA Public Util Commission for hearing & petition to intervene re 790313 show cause order.Urges NRC to hold ruling in abeyance.
  CHURCHILL.B.W. Shaw. Pittman. Potts, & Trowbridge. 79/04/17. 4pp.
- 7905290042 Forwards revised pp 1 & 3 of util's answer opposing review of intervenor Garrett's 790410 petition.

  HASTINGS, W. Portland General Electric Co. 79/04/23. 3pp.
- 7905230661 Orders extension until 790503 to review ALAB-534.dtd 790324.
  CHILK.S.J. Office of the Secretary of the Commission. 79/04/24.
- 7905240948 Forwards list of requests for design charges re rept on design mods for control bldg.Certificate of Svc encl. JOHNSON, R. W. Portland General Electric Co. 79/04/24. 6pp.
- 7905240224 Opposes 790411 motion by SM Garrett & Coalition for Safe Power for NRC review of ASLAB 790321 order re storage pool mod.Certificate of Svc encl. GRAY,J.R. Branch 1. 79/04/26. 12pp.

. . . . . . . . .

mits info re work & workers involved in control bldg lised in 790420 response to intervenors in proceeding. Requests analysis.
Fortland General Electric Co. 79/05/02. 1p.

nual Financial Rept 1978" from Portland General ter & Electric Board & Pacific Power &

General Electric Co. 79/05/17. ip.

1978." -^/03/31. 36pp.

r Eugene Water & Electric

SEC.

503 extension of 1tr of

79/05/25. 3pp.

- --7905300429 Discusses financial obligations under agreement w/Eugene Water & Electric Board re retrospective premiums under Price-Anderson Act. HITTLE,L.G. Energy, Dept. of. 79/05/21. 2pp.
- J. Insurance & indemnity information
- 7905020388 Forwards Endorsement 30 to MAELU Policy MF-86.
  WILSON, F. R. Portland General Electric Co. 79/04/23. 2p
- 7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170, 173,174,178,179,180,182,185,186,187,188,189,192,193,174,195,197,198,200,201,204,206,207,208,210,212,214,215,&others.
- 7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22.26.29,38.39,44.46.47.49,50.51.52.53,54.55,56,57.58.60.61.64.66.67.68.69,70.71,72.74.76.77,78,79,80.86.87,88.70,91.92,93.94.95 & 96.
  ROBERTS, D. M. Mutual Atomic Energy Liability Underwriters. 79/05/0 ip.
- 7905160187 Forwards Amend 4 to Indemnity Agreement B-78,per 10CFR140 changes,re liability insurance increase from \$140 million to \$160 million.effective 790501. Supporting documentation encl. SALTZMAN.J. Antitrust & Indemnity Group. 79/05/01. 5pp.
- 7905220078 Forwards Endorsements 37 & 38 to ANI Policy NF-225, increasing limit of liability & establishing premium for increase, respectively.
  WILSON.R.F. Portland General Electric Co. 79/05/16. 3pp.
- P. Operating license stage documents & correspondence
- 7905020478 Forwards response to NRC 790126 comments on "Containment Structure Tendon Surveillance One Year Surveillance," prepared by Bechtel Corp. Comments have been applied to third-year program now underway.

  GOODWIN
- 7905030361 Responds to DDE 790411 ltr. Unable to provide supplemental info by 790430. Response dependent upon preparation & approval of Offsite Dose Calculation Manual. Response will be ready by 790531.

  GODDWIN.C. Portland General Electric Co. 79/04/27. 1p.
- 7905080431 Submits info re facility design in response to J Holman 790418 request. MITHERS.D.B. Portland General Electric Co. 79/04/30. 4pp.
- 7905040520 Forwards License Change Application 52.Certificate of Svc & \$4.000 Class III encl.
  BROEHL.D.J. Portland General Electric Co. 79/05/01. 2pp.
- ---7905040523 License Change Application 52 to License NPF-1.W/Tech Spec changes. \* Portiand General Electric Co. 79/05/01. 13pp.
- 7905150387 Forwards responses to 790508 & 790510 requests for info re pressurizer code safety valves,main feedwater sys & containment isolation valve functionability. Info needed for meeting on 790512. BROEHL,D.J. Portland General Electric Co. 79/05/11. 4pp.
- 7905230492 Notifies that Offsite Dose Calculation Manual & process control program require further review & will be submitted by 790630 instead of 790515.

  GOODWIN.C. Portland General Electric Co. 79/05/15. 1p.
- 7905230407 Forwards response to NRC 790509 request for infq re feedwater sys. GODDWIN.C. Portland General Electric Co. 79/05/18. 4pp.
- 7905300208 Forwards summary of EDS Nuclear, Inc resolution/documentation of elbow flexibility error which existed in versions of FISOL piping analysis computer program from Jan-Oct 1969. Review & reanalysis included all work through Dec 1970. PORTER, F. L. EDS Nuclear, Inc. 79/05/21. 9pp.
- --7905300263 Forwards EDS Nuclear. Inc list of BWRs & piping sys which could have been impacted by deficient computer program.

  GE has no record of reanalysis for Cooper piping sys.

  STEPHENS.P.W. General Electric Co., Nuclear Energy Products Div.

  79/01/24. 18pp.

- Q. Inspection reports, IE Bulletins & correspondence
- 7905010289 Forwards If Info Notice 79-06, "Stress Analysis of Safety Related Piping"
  ENGLISH.R P. Region 4, Dallaw. Office of the Director. 79/03/23.
- 7905290078 Requests extension until 790715 for response to IE Bulletins 78-12,78-12A & 78-12H 000DMIN.C. Portland General Flectric Co. 79703723 Ip
- 7905040086 Forwards IF Info Notice 79 O7. "Ropture of Radwaste Tanks " ENGELKEN.R H Region 5. San Francisco. Office of the Director, 79703/26 Ip
- 7905040362 Forwards II Insp Rept 50-344779 05 on 790226-0302 No noncompliance noted BOOK-HE Region 5. San Francisco, Fuel Facility & Materials Safety Branck 79703727 Ppp
- --7905040366 If Insp Rept 70 194727-05 on 290226 0302 No noncompliance noted Major areas inspected environ monitoring radiation protection spent fuel pool rack installation & followup on Part 21 rept

  BARD. J B. NORTH. H 5 Region 7. San Francisco, Office of the Director BHOR. H 1 Region 7. San Francisco, Fuel Facility & Materials Safety Branch 2920322 11pp
- 790501021B Forwards It Info Notice 22 OB. "Interconnection of Contaminated Gys w/tive Air Bys Used as Source of Breathing Air "
  ENGELKEN, R H Region 5. San Francisco. Office of the Director 79/03/20 10
- 7905010420 Forwards If Info Notice 79:09. "Spill of Radioactively Contaminated Resin" ENGLKEN.R H. Region 5. San Francisco. Office of the Director 79/03/30. 1p
- 7905010027 Forwards II Bulletin 79 (MA. "Review of Operational Errors & Sys Misalignments Identified During IMI Incident " Licensee action required ENGLHIN, R H. Region 5. Nan Francisco. Office of the Director 79/04/14 1p
- 7905040497 Forwards II Bolletin 79 OAB. "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." ENGLWIN.R H. Region 5. "an Francisco. Office of the Director 79704714 ip
- 7905040616 Forwards If Bulletin PV NB. "Events Relevant to Boiling Water Power Reactors Identified During IMI Incident " ENNELKEN R H Region 5, has francisco. Office of the Director 7970474 1p
- 7905070102 Forwards II Bulletin 79 07. Theismic Stress Analysis of Safety-Related Piping "Licensee action required ENGLKEN.R H. Region 5. San Francisco, Office of the Director 79704744 in
- 7905030293 Forwards II Bolletin 79 00, "Failures of QL Type AK-2 Circuit Breaker in Safety Related Sys " Licensee action required ENGERKO, R H. Region 5, San Francisco. Office of the Director 79/04/27 to
- 7905080369 Forwards II Bulletin 79 (258. "Norlear Incident at THY-Suppl" ENGLEEN.RH Region 7, San Francisco. Office of the Director 79704/21 1p
- 7905150812 Responds to 16 Swiletin 79-07 Details computer programs used in seismic stress analysis of safety-related piping OCCOMIN.C. Portland General Electric Co. 79704723 1p
- 7905240908 Responds to If Bulletin 79-06A re TMI-2 event Describes actions taken GOODWIN.C Portland General Electric Co 29/04/24 15pp.
- R. Periodic operating reports & related correspondence
- 7905110167 Forwards monthly operating rept for Apr 1979 MITHERS, B.D. Portland General Electric Co. 79/05/04 1
- --7905110169 Monthly operating rept for Apr 1979 BAIR.O G Portland General Electric Co 79/05/04 4pp

- 8. Reportable occurrences. LERs & related correspondence
- 7905150062 Forwards PNO-79-67L. ENGELKEN,R.H. Region 5, San Francisco, Office of the Director. 79/04/06. 1p.
- 7905150168 Forwards PNO-79-67R. ENGELKEN.R.H. Region 5. San Francisco. Office of the Director. 79/04/11. 1p.
- 7905040125 Forwards PNO-79-675. ENGELKEN.R.H. Region 5. San Francisco, Office of the Director. 79/04/12. 1p.
- 7905150142 Forwards PNO-79-67T.
  ENGELKEN.R. H. Region 5, San Francisco, Office of the Director.
  79/04/13. 1p.
- 7905030030 Forwards PNO-79-67U. ENGELKEN.R H. Region 5, San Francisco, Office of the Director. 79/04/14. 1P.
- 7905020529 Forwards PNO-79-67AA. ENGELKEN.R.H. Region 5. San Francisco. Office of the Director. 79/04/20. 1p.
- 7905040449 Forwards LER 79-002/03L-0. WITHERS, B. D. Portland General Electric Co. 79/04/20. 3pp.
- --7905040458 LER 79-002/03L-0 on 790322:automatic isolation feature of control room emergency ventilation sys on high chlorine & high radiation not verified during two 18-month periods. Caused by personnel error.

  PERRY, J C. Portland General Electric Co. 79/04/19. 1p.
- 7905010422 Forwards PNO-79-67AB.
  ENGELKEN,R H. Region 5, San Francisco, Office of the Director.
  79/04/21. 1p
- 7905010445 Forwards PNO-79-67AC & AD. ENGELKEN,R H. Region 5: San Francisco, Office of the Director. 79/04/23 ip.
- 7905010458 Forwards PND-79-67AE. ENGELMEN.R H. Region 5. San Francisco. Office of the Director. 79/04/24 1p
- 7905090039 Forwards PNO-79-67AF.
  ENGELKEN.R H. Region 5: San Francisco: Office of the Director.
  79/04/25: 1p.
- 7905090054 Forwards PNO-79-67AG. ENGELKEN, R. H. Region 5. San Francisco, Office of the Director. 79/04/26 ip
- 7905090116 Forwards PNO-79-67AH.

  ENGLEKEN,R H. Region 5. San Francisco, Office of the Director.
  79/04/27 1p.
- 7905100267 Forwards LER 79-003/01T-0. WITHERS.B.D. Portland General Electric Co. 79/04/27. 1p.
- --7905100270 LER 79-003/01T-O on 790414:CV-2256 & CV-2276 valves failed to respond to manually initiated closing signal during periodic surveillance testing. Caused by valve packing binding stem Packing adjusted.
  PERRY, J. C. Portland General Electric Co. 79/04/27. 3pp.
- 7905070028 Forwards PNO-79-67AI, AJ & AK per NRC 790401 ltr transmitting IE Bulletin 79-05.
  ENGELKEN.R. H. Region 5, San Francisco, Office of the Director. 79/04/30. ip.
- 7905070010 Forwards PNO-79-67AL per NRC 790401 ltr transmitting IE Bulletin 79-05. ENGELKEN.R.H. Region 5, San Francisco, Office of the Director. 79/05/01. 1p.
- 7905310053 Forwards PNO-79-67AM.
  EMOELKEN.R.H. Region 5, San Francisco, Office of the Director.
  79/05/07. 1p.

- 79C5:70238 Forwards LER 79-004/03L-0.
  MITHERS 3 D. Portland General Electric Co. 79/05/10. 1p.
- --7905170247 LER 79-004/03L-0 on 790411:1-h surveillance test of prantomy diesel generator not performed as required by Tech Elect Sulvey by personnel error Personnel reinstructed. PERRY, J C Portland General Electric Co. 79/05/10. 3pp.
- 7905220289 Forwards LER 79-005/03L-0.
  WITHERS.B D Portland General Electric Co. 79/05/14. 2pp.
- --7905220293 LER 79-005/03L-0 on 790414:feedwater isolation valve failed following reactor trip. Backup valve closed properly so feedwater line was isolated. Caused by failure of hydraulic fitting.

  PERRY, J C Portland General Electric Co. 79/05/14. 1p.
- 7905220311 Forwards LER 79-006/03L-0. WITHERS.B D. Portland General Electric Co. 79/05/15. 1p.
- --7905220316 LER 79-006/03L-0 on 790415:leak discovered in auxiliary feedwater pump fuel line fitting.Caused by vibration.Fitting replaced.Fuel line design will be modified. PERRY, J. C. Portland General Electric Co. 79/05/15. 2pp.
- 7905310350 RO: util cannot assure containment ventilation sys supply valves will remain leak tight following postulated LOCA while ventilating containment. Analysis shows damage to sys may result.

  HITHERS.B.D. Portland General Electric Co. 79/05/21. 1p.
- DOCKET 50-346 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 1
- 7905070239 Requests denial of J Doherty's 790404 motion for postponement of 790418 prehearing conference.Combustible gas control issue was not dropped from case.

  NEWMAN.J.R. Lowenstein.Newman.Reis.Azelrad & Toll. 79/04/06. 3pp.
- 7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170, 173,174,178,179,180,182,185,186,187,188,189,192,193,194,195,197,198,200,201,204,206,207,208,210,212,214,215,& others. QUATTROCHHI, J. American Nuclear Insurers. 79/05/01. 1p.
- 79C5070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22.26,29,38,39,44,46,47,49,50,51,52,53,54,55,56,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,91,72,73,94,95 & 96.
  ROBERTS,D.M. Mutual Atomic Energy Liability Underwriters. 79/05/01.
- 7905160231 Forwards Amend 4 to Indemnity Agreement B-79, per 10CFR140 changes, re liability insurance increase from \$140 million to \$160 million, effective 790501. Supporting documentation encl. SALTZMAN. J. Antitrust & Indemnity Group. 79/05/01. 5pp.
- 7905140361 Forwards Endorsements 28 & 29 to NELIA Policy NF-236. LLOVD.R.D. Harsh & McLenon, M & M Nuclear Consultants, Inc. Div. 79/05/07. 3pp.
- 7905300418 Forwards executed Amend 4 to Indemnity Agreement B-79. ROE, L. E. Toledo Edison Co. 79/05/25. 3pp.
- P. Operating license stage documents & correspondence
- 7905240933 Confirms 790401 discussions. Will notify NRC prior to resuming operations. Postpones meeting scheduled for 790404.

  KEPPLER, J. G. Region 3. Chicago. Office of the Director. 79/04/02.
- 7905240129 Ack receipt of 790116 ltr providing info re coolant sys flow data & total pressure drops. Review requires Class III fee.
  DIGOS.R.H. License Fee Management Branch. 79/04/24. 1p.
- 7903240662 Expresses appreciation for 790305 ltr providing util views on NRC activities. Describes development of STS & radiological effluent Tech Specs.
  BOYD, R. S. Division of Project Management. 79/05/01. 5PP.
- --- 7705240671 Requests evaluation of NRC Tech Spec requirements, which util believes are often counterproductive and unacessary.

  ROE.L.E. Toledo Edison Co. 79/03/05. 3PP.

- 7905080416 As result of commitments contained in 790427 ltr.details addl actions to be taken prior to startup. In order to meet requirements, will initiate mod to provide control room verification of auxiliary feedwater flow to steam generator. ROE, L. E. Toledo Edison Co. 79/05/04. 2pp.
- 7905090353 Forwards response to Q Vissing 790226 request for add1 info re spent fuel pool capacity mod, to finalize environ assessment. RDE.L.E. Toledo Edison Co. 79/05/04. 3pp.
- 7905150402 Forwards Chapters 1.2.8-10.12 & 13.revised by Suppl 4 of initial startup rept.W/instructions for insertion. GRANT.J.S. Toledo Edison Co. 79/05/09. 2pp.
- --7905150405 Initial startup rept.Suppl 4, revising Chapters 1, 2, 8-10, 12 & 13. Covers testing completed 790106-0405.

  \* Toledo Edison Co. 79/05/09. 80pp.
- 7905190031 Forwards interim anticipatory reactor trip sys design (Drawing SK-E-409, Revision 1). Oversized drawing available in Central Files.
  ROE.L.E. Toledo Edison Co. 79/05/11. 1p.
- 7905240586 In response to NRC 790424 ltr.forwards Class III amend fee. RDE, L. E. Toledo Edison Co. 79/05/15. 1p.
- 7905220095 Forwards Offsite Dose Calculation Manual, to aid review of radiological ETB, submitted 790316. ROE, L. E. Toledo Edison Co. 79/05/18. 67pp.
- 7905240403 Forwards addl info re auxiliary feedwater turbine dynamic brake installation, dual level setpoints for auxiliary feedwater controls & actuation signals, pressurizer level indication & water source & cross-connect requirements.

  ROE, L. E. Toledo Edison Co. 79/05/19. 7pp.
- 7905290419 Forwards "Evaluation of Transient Behavior & Small Reactor Coolant Sys Breaks in 177 Fuel Assembly Plant, 790516, "Vol 3, Revision 1. RDE: L.E. Toledo Edison Co. 79/05/22. 1p.
- --7905290422 "Evaluation of Transient Behavior & Small Reactor Coolant Sys Breaks in 177 Fuel Assembly Plant, 790516." Vol 3, Revision 1. \* Toledo Edison Co. 79/05/19. 66pp.
- 7905310450 Forwards info re auxiliary feedwater flow indicators, surveillance test/maint mode procedures & valve alignment requirements.
  ROE.L.E. Toledo Edison Co. 79/05/22. 3pp.
- 7905300483 Forwards info requested at NRC 790508 meeting. Info includes overall reliability of auxiliary feedwater sys w/regard to operating history & design improvements.

  ROE. L. E. Toledo Edison Co. 79/05/23. 16pp.
- 7905310375 Submits matrix to cross-reference station procedures w/operating procedure mods re NRC 790517 order & RN Reid 790518 ltr. ROE.L.E. Toledo Edison Co. 79/05/23. 4pp.
- Q. Inspection reports. IE Bulletins & correspondence
- 7905100357 Notice of deviation from insp on 771116-18 & 30 & 1201-02.

  \* Region 3, Chicago, Reactor Operations Nuclear Support Branch.
  77/12/16. 1p.
- --7905100362 IE Insp Rept 50-346/77-34 on 771116-18 & 30 & 1201-02. No noncompliance noted Major areas inspected: surveillance testing & investigation & followup associated w/loss of offsite power on 771129.

  TAMBLING,T.N., KNDY,R.C. Region 3, Chicago, Offsice of the Director. 77/12/16. 7pp.
- 7905:10097 Ack receipt of 77:214 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-346/77-32. FIGRELIT, G. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 78/01/13. 1p.
- ---7905110099 Responds to NRC 771122 ltr re violation noted in IE Insp Rept 50-346/77-32 Corrective actions: Administrative Procedure AD 1823.00 revised & supervisors reinstructed re importance of filling out log sheets. GRANT, J. S. Toledo Edison Co. 77/12/14, 2pp.

- --7905110100 Forwards 1E Insp Rept 50 346777-32 on 770926-30, 1005-07, 18-21 & 27. FIORELLI G Region 3, Chicago, Reactor Operations Nuclear Support Branch 77711722 Upp
- --7905110108 Notice of violation from insp on 770924-30.1005-07.18-21 & 27 Region D. Chicago. Office of the Director 77/11/18. 1p
- --7905110111 IE Insp Rept 50 J46/77 D2 on 770926-30,1005-07,18-21 % 27.
  Noncompliance noted failure to properly implement procedure
  for jumper-lifted wire
  TAMBLING.T N. HARPSHER.L L., KNOP.R C. Region 3. Chicago,
  Office of the Director 77/11/18 19pp
- 7905110089 Ack receipt of 280510 Itr informing NRC of steps taken to correct violations noted in It Insp Rept 50-346770-06 FIORELLIG Region & Chicago, Reactor Operations Nuclear Support Reactor 78707742 to
- --7905110091 Responds to NRC 7804.90 ltr re-violations noted in IE Insp. Rept 50-346770-06 Corrective actions test deficiency documented on 780417 & proper review & changes to dropped rod control test obtained on 780615 GRANT, J.S. Toledo Edison Co. 78705710 lp
- --7905110092 forwards II Insp Rept 50 (146770 06 on 771206-08 % 200006-08 % notice of Scolation FIORELLI, G Region J. Chicago, Reactor Operations Notlear Support Branch /0/04720 \_3pp
- --7905110093 Notice of violation from insp on 7/1206 00 & 700306-00 \* Region D. Chicago. Office of the Director 78/04/19 tp
- --7905110094 IE Insp Rept 50 (34A/78)-06 on 271206 OB & 200006-08
  Noncompliance insted failure to perform red drop testing at 40% power & failure to file test deficiency rept CRESHELL-J S Region D. Chicago. Office of the Director LITTLE W S Region J. Chicago. Reactor Operations Noclear Support Branch /11/04/19 12pp
- 7905010267 Forwards II Info Notice 79 Oc. "Titress Analysis of Safety-Related Piping "
  KEPPLER, J G Region D. Chirago. Office of the Director 79703723.
- 7905040055 forwards II Info Notice 79 07. "Reptore of Radwaste Tanks " KEPPLER, J.G. Region D. Chicago, Office of the Director 79705726 1p.
- 7905010176 Forwards II Info Notice 79 OB. "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air."

  KEPPLER, J.G. Region D. Chicago, Office of the Director 79703/28 is.
- 7905010413 Forwards IF Info Notice 79:09. "Spill of Radioactively Contaminated Resin"

  KEPPLER, J.G. Region 3, Chicago. Office of the Director 79/03/30
- 7905030053 Forwards If Bulletin 79-0A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident" KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/04/11
- 7903010604 Forwards IC Bulletin 79-06A. "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "
  KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14.
- 7905040427 Forwards II Bulletin 79:06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "
  KEPPLER, J. O. Region 3, Chicago, Office of the Director 79/04/14.
- 7905040591 Forwards IE Bulletin 79-08. "Events Relevant to Boiling Hater Power Reactors Identified During TM1 Incident."

  KEPPLER, J. G. Region D. Chicago. Office of the Director 79/04/14
- 7905070174 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping "Licensee action required KEPPLER, J G. Region 3, Chicago, Office of the Director 79/04/14 ip.
- 7905240097 Responds to IE Bulletin 79-03 re defects in pipes mfg by Youngstown Welding & Engineering Co Ultrasonic exam of containment spray sys piping revealed some defects, which are being evaluated GRANT, J. S. Toledo Edison Co. 79/04/16. 3pp

- 7905250198 Forwards revision to 790411 response to IE Bulletin 79-05/ re auxiliary feedwater trains. GRANT, J. S. Toledo Edison Co. 79/04/16. 2pp.
- 7905030245 Forwards IE Bulletin 79-09, "Failures of QE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required. KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/04/17.
- 7905080509 Forwards IE Bulletin 79-058, "Nuclear Incident at TMI-Suppl." Licensee action required.

  KEPPLER, J. C. Region 3, Chicago, Office of the Director. 79/04/21.
- 7905150113 Ack receipt of 790403 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-346/79-05. HEISHMAN.R.F. Region 3: Chicago, Reactor Operations Nuclear Support Branch. 79/04/25. 1p.
- ---7905150121 Responds to NRC 790314 ltr re violations noted in IE Insp Rept 50-346/79-05. Corrective actions: reemphasized importance of review of surveillance test data & personnel instructed on proper work method re safety-related equipment. GRANT, J. S. Toledo Edison Co. 79/04/03. 2pp.
- 7905100354 Forwards IE Insp Rept 50-346/77-34 on 771116-18 & 30 & 1201-02. No noncompliance noted. FIORELLI, Q. Region 3. Chicago. Reactor Operations Nuclear Suppert Branch. 77/12/16. 3pp.
- R. Periodic operating reports & related correspondence
- 7905140233 Forwards monthly operating rept for Apr 1979. MURRAY, T.D. Toledo Edison Co. 79/05/08. 1p.
- ---7905140235 Monthly operating rept for Apr 1979. CABA: E. C. Toledo, Edison Co. 79/05/08. 6pp.
- S. Reportable occurrences, LERs & related correspondence
- 7905100375 PNO-77-171:as of 770926 no radioctive releases occurred at Davis-Besse 1.as result of loss of coolant pressure due to failure of pressurizer power operated relief valve. KLINGER.O., NOLAN.F., SNIEZEK, J.H. Office of Inspection & Enforcement. 77/09/26. 1p.
- ---7905100378.Reviews available info re reactor coolant sys depressurization event at Davis-Besse 2.No current indication of fuel damage or other serious problems at plant.

  MCDERMOTT.R J Guality Assurance Branch. 77/10/06. 2pp.
- ---7905100380 LER NP-32-77-16(Suppl)on 770924:depressurization of primary sys from normal operating pressure occurred, resulting in steam formation.

  MURRAY, T. D. Toledo Edison Co. 77/11/14. 60pp.
- 7905100341 Forwards LER 77-096/03L-0.
  MURRAY, T. D. Toledo Edison Co. 77/12/16. 2pp.
- ---7905100345 LER 77-096/03L-0 on 771129: diesel generator 1-i started/but failed to supply power during temporary loss of power. Caused by diesel tripping on overspeed due to governor setting. Switches reset & diesel generator declared operable. BEYER, B. Toledo Edison Co. 77/12/16. 3pp.
- 7905020266 Notifies of reportable event on 790413: certain starters 'for essential motors had overload heaters installed which were smaller than capacity specified on relay data sheets causing possible overload heater burnout Heater being replaced. MURRAY.T.D. Toledo Edison Co. 79/04/16. 1p.
- 7905100286 RO on 790423:unplanned reactivity insertion of more than 0.5% occurred Caused by valve MU39 leaking demineralized water. Procedure mod rewritten to prevent valve leakage & increase sampling frequency. MURRAY, T. D. Toledo Edison Co. 79/04/23. 1p.
- 7905020303 Forwards LER 79-046/03L-0. MARRAY.T.D. Toledo Edison Co. 79/04/25. 1p.
- ---7905020330 LER 79-046/03L-0 on 790330: diesel generator declared inoperable after loud unusual noises & placed in action statement Caused by bearing failure in turbocharger. Turbocharger replaced. HARTIGAN.J.P. Toledo Edison Co. 79/04/25. 3pp.
- 7905020418 Forwards LER 79-047/03L-0. HURRAY.T.D. Toledo Edison Co. 79/04/25. 1p.

- --7905020438 LER 79-047/03L-0 on 790329: on 790331 makeup pump 1-1 taken out of svc for maint due to increased vibration & decreased pump performance. Caused by failure of first stage impeller which cut large groove in shaft.

  HARTIGAN, J. P. Toledo Edison Co. 79/04/25. 3pp.
- 7905020488 Forwards LER 79-045/03L-0. MURRAY.T.D. Toledo Edison Co. 79/04/25. 1p.
- --7905020500 LER 79-045/03L-0 ON 790330: borated water storage tank low level trip setpoint in Safety Features Actuation Sys Channel II discovered out of tolerance. Caused by instrument drift & analog amplifier. Analog amplifier recalibrated. NELSON, J. M. Toledo Edison Co. 79/04/25. 3PP.
- 7905020427 Forwards LER 79-048/01T-0. MURRAY.T.D. Toledo Edison Co. 79/04/26. 1P.
- --7905020443 LER 79-048/01T-0 on 790413: starters for essential motors had overload heaters installed which were smaller than capacity specified. Caused by error in initial installation due to procedural inadequacy. Check of overload heaters conducted. MURRAY.T.D. Toledo Edison Co. 79/04/26. 3pp.
- 7905040129 Forwards LER 79-049/03L-0.
  MURRAY, T. D. Toledo Edison Co. 79/04/26. 1p.
- --7905040132 LER 79-049/03L-0 on 790331:during surveillance testing half of steam safety valves discovered to be out of design setpoint range. Caused by changing ambient conditions. Valves adjusted & retested. BROWN.R.A. Toledo Edison Co. 79/04/27. 3pp.
- 7905090269 Forwards LER 79-050/01T-0. MURRAY, T. D. Toledo Edison Co. 79/05/04. 1p.
- --7905090273 LER 79-050/01T-0 on 790423:boron concentration dropped lower than anticipated final value, resulting in unplanned reactivity insertion. Caused by mechanical, personnel & procedural error. Valve being repaired.

  BROWN, D. H. Toledo Edison Co. 79/05/04. 3pp.
- 7905150455 Forwards LER 79-051/03L-0. MURRAY, T. D. Toledo Edison Co. 79/05/09. 1p.
- --7905150456 LER 79-051/03L-0 on 790410: fire alarm point F-056 sounded when no fire existed Caused by lack of proper control room annunciation & procedure control. Procedure mods being prepared & installation of annunciator investigated.

  LINGENFELTER, J. Toledo Edison Co. 79/05/09. 3pp.
- 7905160404 Forwards LER 79-052/03L-0. MURRAY, T. D. Toledo Edison Co. 79/05/11. 1p.
- --7905160409 LER 79-052/03L-0 on 790416: piece of duct tape found blocking inlet to containment pressure sampling line, rendering instruments inoperable. Tape removed.
  NELSON, J. M. Toledo Edison Co. 79/05/11. 2pp.
- 7905220124 Forwards LER 79-035/03L-1. MURRAY.T.D. Toledo Edison Co. 79/05/15. 1p.
- --7905220125 LER 79-035/03L-1 on 790228: reactor coolant pump 1-1-2 tripped, resulting in reactor runback to 74%. Caused by loosening of inservice filter cover during maint. Cover retightened & addl nameplates being made. ROHRER, E. Toledo Edison Co. 79/03/27. 3pp.
- 7905220096 Forwards LER 79-053/03L-0. MURRAY.T.D. Toledo Edison Co. 79/05/16. 1p.
- ---7905220101 LER 79-053/03L-0 on 790417: while in Mode 5, position indication for control rod 3 became erratic. Caused by defective connection in penetration butt splice. Butt splice reconnected. Tests will be made when in Mode 3. NAYLOR, R. W. Toledo Edison Co. 79/05/16. 2pp.
- 7905220117 Forwards LER 79-054/03L-0. MURRAY, T. D. Toledo Edison Co. 79/05/16. 1p.
- --7905220121 LER 79-054/03L-0 on 790409:control room isolation damper HV5311B stuck open during surveillance test. Caused by corrosion of bushing in damper shaft. Damper removed & returned to manufacturer for reconditioning. RUDOLPH. J. J. Toledo Edison Co. 79/05/16. 2pp.

- 7905230371 Forwards review of 770924 event re depressurization of primary sys.Similarities to 790328 incident at TMI-2 noted. ROE, L. E. Toledo Edison Co. 79/05/18. 3pp.
- 7905250134 Forwards LER 79-055/03L-0. MURRAY.T.D. Toledo Edison Co. 79/05/18. 1p.
- --7905250142 LER 79-055/03L-0 on 790423:low reactor coolant pressure block bistable BA103 did not reset automatically on increasing suveillance test signal. Caused by sticking of relay K-4. Relay replaced. NELSON.J.M. Toledo Edison Co. 79/05/18. 2pp.
- DOCKET 50-348 JOSEPH M. FARLEY NUCLEAR PLANT, UNIT 1
- A. Application/construction stage documents & correspondence
- 7905140357 Notifies of potential reportable inconsistency in calculated DNB rations as reported to util by Westinghouse. HAIRSTON, W. G. Alabama Power Co. 79/03/30. 2pp.
- F. Security, medical, emergency & fire protection plans
- 7905070631 Forwards check to replace check sent 790323 w/safeguards security contingency plan.
  CLAYTON.F.L. Alabama Power Co. 79/05/01. 2pp.
- I. Financial information
- 7905150391 Forwards "Annual Financial Rept 1978," unaudited financial statements for quarter ending 790331 & cash flow projections for 1979.
  BOWDEN, T. J. Alabama Power Co. 79/05/10. 7pp.
- --7905150395 "Annual Financial Rept 1978." \* Alabama Power Co. 78/12/31. 47pp.
- J. Insurance & indemnity information
- 7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,185,186,187,188,189,192,193,194,195,197,198,200,201,204,204,207,208,210,212,214,215,& others.

  GUATTROCHHI, J. American Nuclear Insurers. 79/05/01. 1p.
- 7905070592 Confirms increase in liability limit to \$36,000,000 for policies MF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,56,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,91,92,93,94,95 & 96.
  ROBERTS,D.M. Mutual Atomic Energy Liability Underwriters. 79/05/01.
- 7905160224 Forwards Amend 4 to Indemnity Agreement B-B1, per 10CFR140 changes, re liability insurance increase from \$140 million to \$160 million, effective 790501. Supporting documentation encl. SALTZMAN, J. Antitrust & Indemnity Group. 79/05/01. Spp.
- 7905100304 Forwards Endodrsement 23 to NELIA Policy NF-238.

  DUCK, J. R. Marsh & McLenon, M & M Nuclear Consultants, Inc. Div.
  79/05/04. 2pp.
- 7905150357 Forwards signed Amend 4 to Indemnity Agreement B-81. BARTON, A. R. Alabama Power Co. 79/05/11. 2pp.
- 7905160396 Forwards Endorsement 24 to ANI Policy NF-238.

  DUCK, J. R. Marsh & McLenon, M & M Nuclear Consultants, Inc. Div.
  79/05/11. 2pp.
- 7905300468 Forwards Endorsement 25 to ANI Policy NF-238.

  DUCK, J. R. Marsh & McLenon, M & M Nuclear Consultants, Inc. Div. 79/05/25. 2pp.
- M. Antitrust correspondence
- 7905100196 AL Electric Cooperative's Response to applicant's "Memo re Impact of Public Regulatory Policies Act of 1978." Certificate of Svc & supporting documentation encl. BOSKEY, B., MACGUINEA, D. B. Volpe, Boskey & Lyons. 79/03/28. 23pp.

- 7905100217 Response of Municipal Electric Util Association of AL to applicant's memo re impact of Public Util Regulatory Policies Act of 1978. Certificate of Svc encl. GOLDBERG.R. Goldberg, Fieldman & Letham, P.C. HJELMFIELT, D.C. Affiliation Unknown. 79/03/28. 10pp.
- 7905240978 Notice of appearance of DJ Evans on behalf of NRC. Certificate of Svc encl. EVANS.D.J. Anti-Trust Division. 79/03/28. 3pp.
- 7905100269 Reply memo re impact of "Public Util Regulatory Policies Act of 1978" on proceeding. Act neither changes legal status of case nor impacts on decisions of liability. Certificate of SVC encl.

  AXELRAD, J. A. Regulations Division, EVANS, D. J. Anti-Trust
  Division, 79/03/29, 12pp.
- 7905240985 Responds to applicant's memo re impact of Public Util Regulatory Policies Act of 1978. Certificate of Svc & supporting documentation encl. WHITLER, J. D. Justice, Dept. of. 79/03/29, 22pp.
- P. Operating license stage documents & correspondence
- 7905090079 Forwards Amend 11 to License NPF-2, safety evaluation & notice of issuance & availability.

  SCHWENCER, A. Operating Reactors Branch 1. 79/04/13. 3pp.
- ---7905090080 Amend 11 to License DPR-26, maintaining & implementing all provisions of approved fire protection plan.

  \* Operating Reactors Branch 1. 79/04/13. 2pp.
- --7905090083 Safety evaluation supporting Amend 11 to License DPR-26. \* Office of Nuclear Reactor Regulation. 79/02/12. 30pp.
- --7905090084 Notice of issuance & availability of Amend 11 to License DPR-26. SCHWENCER, A. Operating Reactors Branch 1. 79/04/13. 2pp.
- 7905020242 Forwards proposed amends to Tech Specs for Unit 1 incorporating radiological effluent Tech Specs into App A & proposed draft radiological effluent Tech Specs for Unit 2. Proposed draft App B Tech Specs encl. CLAYTON, F. L. Alabama Power Co. 79/04/16. 190pp.
- 7905040267 Ack receipt of 790104 application & 790321 supplementary filing Requests payment of Class III fee.
  MILLER.W.O. License Fee Management Branch. 79/04/16. 2pp.
- 7905170266 Forwards proposed Tech Specs revision modifying safety injection logic by deleting coincident low pressurizer pressure/level logic actuation. CLAYTON, F. L. Alabama Power Co. 79/05/11. 10pp.
- 7905230414 Requests informal facility info re TMI incident be withheld from public disclosure unless util conducts proprietary review. CLAYTON, F. L. Alabama Power Co. 79/05/16. 2pp.
- 7905310376 Submits add1 info re pressurizer pressure safety injection logic.in ref to 790523 telcon w/E Reeves & T Dunning. Pressurizer pressure transmitters 444.445.456 & 457 have control or protection functions. CLAYTON,F.L. Alabama Power Co. 79/05/23. 2pp.
- 7903010161 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
  0'REILLY, J.P. Region 2, Atlanta, Office of the Director.
  79/03/23. 2pp.
- 7905230777 Informs of delay in responding to IE Bulletin 78-12.78-12A & 78-12B re weld matls used for each reactor vessel primary boundary ferritic weldment Westinghouse is unable to provide needed data until 791031. Alabama Power Co. 79/03/23. 1p.
- 7903030290 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks." D'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/03/26, 2pp.
- 7905010093 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air." O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/03/28, 2pp.
- 7905010339 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin."
  0 TREILLY.U.P. Region 2, Atlanta, Office of the Director.
  79/03/30. 2pp.

- 7905240514 Forwards IE Insp Rept 50-348/79-10 on 790313-0316 & 21-23. No noncompliance noted. MURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 79/04/04. 2pp.
- --7903240518 IE Insp Rept 50-348/79-10 on 790313-0316 & 21-23. No noncompliance noted Major areas inspected inservice insp, welding & nondestructive examination.
  CROMLEY, B. R. Region 2, Atlanta, Office of the Director.
  COMLON.T.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/04/04. 7pp.
- 7905240523 Forwards IE Insp Rept 50-348/79-12 on 790306-0309. No noncompliance noted. LEWIS.R.C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 79/04/04. 2pp.
- --7905240527 IE Insp Rept 50-348/79-12 on 790306-09. No noncompliance noted Major areas inspected LERs, Part 21 repts, open items, operations review & independent insp.

  HARDIN.A.K. Region 2, Atlanta, Defice of the Director.

  CANTRELL, F. S. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/04/03. 6pp.
- 7905020124 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." Licensee action required.

  0'REILLY.J.P. Region 2, Atlanta, Office of the Director.
  79/04/11. 1p.
- 7905100279 Requests extension of time until 790512 to respond to IE Bulletin 79-03, "Longitudinal Weld Defects in Pipe Spools Mfg by Youngstown Welding & Engineering Co."
  CLAYTON, F. L. Alabama Power Co. 79/04/11. 1p.
- 7905150568 Confirms 790412 telcon to AK Hardin re IE Bulletin 79-02. Test program was initiated; enough failures found in anchor bolt installations to justify expansion of test scope Further details will come in 14-day followup. HAIRSTON, M. G. Alabama Power Co. 79/04/12. 1p.
- 7905040148 Forwards IE Bulletin 79-06B. "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."

  O'RETLLY.J.P. Region 2. Atlanta, Office of the Director.
  79/04/14. 2pp.
- 7905040298 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required. O'REILLY,J.P. Region 2, Atlanta, Office of the Director. 79/04/14. 2pp.
- 7905040322 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident." O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/14. ip.
- 7905030137 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required. D'REILLY, J. P. Region 2, Atlanta, Office of the Director. 2pp.
- 7905020370 Forwards IE Bulletin 79-06A.Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."

  O'REILLY J.P. Region 2, Atlanta, Office of the Director.
  79/04/18. 2pp.
- 7905240443 Responds to IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping," Methods specified by Item 1 have never been used. Therefore, specific concerns are not applicable to facility.

  CLAYTON, F. L. Alabama Power Co. 79/04/24. 3pp.
- 7905300710 Forwards response to IE Bulletins 79-06A & 79-06, Revision 1. Training program for personnel w/operational duties is being developed/actions required by operating procedures retransients & accidents have been reviewed. CLAYTON, F. L. Alabama Power Co. 79/04/24. 21pp.
- 7905300554 Responds to IE Bulletin 79-03.No SA-312 or other welded pipe mfg by Youngstown Welding & Engineering has been received on site or will be used in future.

  CLAYTON, F. L. Alabama Power Co. 79/04/26. 1p.
- 7903090075 Forwards "Inservice Testing Program for Class 1.2 & 3 Pumps & Valves." Encl available in Central Files.
  CLAYTON.F.L. Alabama Power Co. 79/03/01. 2pp.

- 7905250036 Responds to IE Bulletin 79-04 "Incorrect Weights for Swing Check Valves Mfg by Velan Engineering Corp." One discrepancy found between weights specified in bulletin & actual weight of valve.

  CLAYTON.F.L. Alabama Power Co. 79/05/01. 2pp.
- R. Periodic operating reports & related correspondence
- 7905230361 Forwards monthly operating rept for Apr 1979. CLAYTON,F.L. Alabama Power Co. 79/05/15. 2pp.
- --7905230362 Monthly operating rept for Apr 1979. HAIRSTON, W. G. Alabama Power Co. 79/05/01. 3pp.
- S. Reportable occurrences. LERs & related correspondence
- 7905140368 Confirms 790328 telcon re LER 79-015/01T-0. While performing inservice insp on 790327, five linear surface indications discovered on ECCS line. Currently evaluating nondestructive examination on similar components.

  HAIRSTON, W. G. Alabama Power Co. 79/03/28. 1p.
- 7905020247 Forwards LER 79-021/01T-0. CLAYTON, F. L. Alabama Power Co. 79/04/26. 1p.
- --7905020249 LER 79-021/01T-0 on 790412: in response to IE Bulletin 79-02, program initiated to randomly test anchor bolts installed in Seismic Category 1, safety-related, 2.5-inch grater piping sys. Statistical sample too small. Program expanded. HAIRSTON, N. G. Alabama Power Co. 79/04/26. 3pp.
- 7905110242 Forwards LER 79-018/03L-0. CLAYTON, F. L. Alabama Power Co. 79/05/07. 1p.
- ---7905110247 LER 79-018/03L-0 on 790409:discovered outer personnel air lock door not operating properly.Caused by inadequate procedural controls.Fuel handling procedures revised to verify that both air lock doors are closed.

  \* Alabama Power Co. 79/05/07. 3pp.
- 7905140306 Forwards LER 79-021/01T-1. CLAYTON, F. L. Alabama Power Co. 79/05/08. 1p.
- --7905140311 LER 79-021/01T-1 on 790412: statistical sampling of anchor bolt reliability not sufficient to provide high probability of greater than 95% reliability. Program expanded to include 100% testing. HAIRSTON, W. O. Alabama Power Co. 79/05/08. 4pp.
- 7905160403 Forwards LERs 79-020/03L-0 & 79-015/01T-0. CLAYTON, F. L. Alabama Power Co. 79/05/10. 1p.
- --7905160414 LER 79-020/03L-0 on 790411: alarm received on BIJ sequencer. Sequencer found in test, rendering IC dc inoperable & violating min requirement for one dc set. Caused by faulty key switch breaking internal parts. Switch replaced. \* Alabama Power Co. 79/05/11. 1p.
- --7905160407 LER 79-015/01T-1 on 790327: linear surface indications found on 2-inch ECCS line to Loop 1 cold leg.Loop 2 cold leg & Loop 3 hot leg.Probably caused during piping mfg. Affected part of Loop 1 replaced.Loop 2 % 3 indications ground out.

  \* Alabama Power Co. 79/05/10. 3pp.
- 7905300500 Forwards LER 79-019/03L-0. CLAYTON, F. L. Alabama Power Co. 79/05/22. 1p.
- ---7905300504 LER 79-019/03L-0 on 790420: chemical analysis of reactor coolant revealed overconcentrations of chloride & fluoride Cause undetermined. Engineering evaluation in progress.

  HAIRSTON, N. G. Alabama Power Co. 79/05/22. 1p.
- DOCKET 50-352 LIMERICK GENERATING STATION, UNIT 1
- A. Application/construction stage documents & correspondence
- 7905040316 Summary of 790321 meeting of Mark II owners group in San Jose, CA re intermediate plant program tasks.
  ANDERSON, C. J. Containment Systems Branch. 79/04/13. 150pp.
- G. Adjudicatory correspondence
- 7905210058 Requests plant shutdown because of threat of accident as severe as rupture to reactor vessel.

  ROMANO, F. R. Affiliation Unknown. 79/04/12. 5pp.

- H. General correspondence
- 7905230711 Requests const review of facility Expresses concern re insufficient supply of water near plant for cooling reactor. BUONANNO, N. A. Affiliation Unknown. 79/04/02. 1p.
- J. Insurance & indemnity information
- 7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,185,186,187,188,189,192,193,194,195,197,198,200,201,204,204,205,207,208,210,212,214,215,&others.QUATTROCHHI,J. American Nuclear Insurers. 79/05/01. 1p.
- Q. Inspection reports, IE Bulletins & correspondenc €
- 7905010134 Forwards IE Info Notice 79-06, "Stress Amalysis of Safety-Related Piping." GRIER.B.H. Region 1. Philadelphia, Office of the Director. 79/03/23. ip.
- 7905020077 Forwards IE Bulletin 79-06, "Review of Operational Errors; Sys Misalignments Identified During TMI Incident."

  GRIER.B.H. Region I, Philadelphia, Office of the Director.
  79/04/11. 1p.
- 7905020372 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping," Licensee action required.

  ORIER, B. H. Region 1, Philadelphia, Office of the Director.
  79/04/14. 1p.
- 7905040083 Forwards IE Bulletin 79-068, "Review of Operational Errors; Sys Misalignments Identified During TMI Incident."

  GRIER.B.H. Region 1, Philadelphia, Office of the Director.
  79704744. 1p.
- 7905040264 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Mater Power Reactors Identified During TMI Incident." GRIER, B.H. Region 1, Philadelphia, Office of the Director 79/04/14. 1p.
- 7905030086 Forwards IE Bulletin 79-09, "Failures of QE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.

  GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/04/17, 1p.
- 7905020305 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."

  ORIER, B. H. Region 1, Philadelphia, Office of the Director 79/04/18. 1p.
- DOCKET 50-353 LIMERICK GENERATING STATION, UNIT 2
- A. Application/construction stage documents & correspondence
- 7905210058 Requests plant shutdown because of threat of accident as severe as rupture to reactor vessel.
  ROMANO,F.R. Affiliation Unknown. 79/04/12. 5pp.
- 7905040316 Summary of 790321 meeting of Mark II owners group in Sen Jose CA re intermediate plant program tasks.
  ANDERSON.C.J. Containment Systems Branch. 79/04/13. 150pp
- H. General correspondence
- 7905230711 Requests const review of facility. Expresses concern re insufficient supply of water near plant for cooling reactor BUONANNO, N. A. Affiliation Unknown. 79/04/02. 1p.
- J. Insurance & indemnity information
- 7905070497 Confirms increased liability limit to \$124,000,000 for pelicies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,185,186,187,188,189,192,192,194,195,197,198,200,201,204,206,207,208,210,212,214,215,&others.

  @UATTROCHHI, J. American Nuclear Insurers. 79/05/01. 1p.

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22.26.29,38,39,44,46,47,49,50,51,52,53,54,55,56,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,91,92,93,94,95 & 96.
ROBERTS, D. M. Mutual Atomic Energy Liability Underwriters. 79/05/01.

# Q. Inspection reports, IE Bulletins & correspondence

7905010134 Forwards IE Info Notice 79-06, "Stress Analysis of Gold 134 Forwards 1E into Notice 79-06, "Stress Analysis of Safety-Related Piping."

GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/03/23. 1p.

7905020077 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."

QRIER, B. H. Region 1, Philadelphia, Office of the Director.
79/04/11. 1p.

7905020372 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required. ORIER, B. H. Region 1, Philadelphia, Office of the Director. 79/04/14. 1p.

7905040083 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."

ORIER, B. H. Region 1, Philadelphia, Office of the Director.
79/04/14. 1p.

7905040264 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident." ORIER, B. H. Region 1, Philadelphia, Office of the Director. 79/04/14. 1p.

7905030086 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.

ORIER, B.H. Region 1, Philadelphia, Office of the Director. 79/04/17. 1p.

7905020305 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." ORIER, B. H. Region 1. Philadelphia. Office of the Director.

## DOCKET 50-354 HOPE CREEK NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

7905070552 Submits revised schedule re response to NRC's position on NUREG-0313, "Technical Rept on Matl Selection & Processing Guidelines for BWR Coolant Pressure Boundary Piping," Response will be submitted no later than Sept 1979. MITTL.R.L. Public Service Electric & Gas Co. of New Jersey. 79/04/23. 1p.

# 9. Adjudicatory correspondence

7905230512 Util response to briefs opposing de minimus approach of Perkins proceeding. Licensees in Peach Bottom & Hope Creek proceedings conted approach is valid; no need to consider health effects further. M/Centificate of Svc.
CONNER, T. B. Conner, Moore & Corber. 79/04/04. 30pp.

7905110418 Response to ALAB-509 re radon emissions & de minimus theory from Perkins record.Certificate of Svc encl. SCINTO, J. F. Hearings Division. 79/04/11. 45pp.

7905140519 Response to 790404 brief of Philadelphia Electric Co.PSE&G & Atlantic City (NJ) Electric Co re de minimus theory.
Cartificate of Svc encl.
KEPFORD, C. R. Citizens for Safe Environment. 79/04/11. Spp.

7905140332 Notifies of consolidation of five intervenor groups re radon emissions issue.Parties have until 790525 in which to file for summary disposition.
DUFLO M.E. Atomic Safety and Licensing Appeal Panel. 79/04/25.

7905240585 Memo & order ALAB-546. Denies applicants' petition for reconsideration of ALAB-540, which consolidates applicants re radon issue.

DUFLO, M. E. Atomic Safety and Licensing Appeal Panel. 79/05/08.

#### H. General correspondence

7905070450 Ack receipt of 790216 resolution opposing storage of high level radioactive wastes in township. Objections should be made at ASLB hearing. Expansion of storage pools is unlikely. No independent facilities are planned.

DENTON, H. R. Office of Nuclear Reactor Regulation. 79/03/29. 5pp.

7905140291 Responds to 790312 ltr re resolution adopted on 790216 by Township of Lower Alloways Creek.NJ.Resolution opposes storage of high level wastes.Forwards NRC response. GDS5ICK.L.V. Office of the Executive Director for Operations. 79/04/11. 1p.

### I. Financial information

7905070647 Forwards "Annual Financial Rept,1978" for Public Svc Electric & Gas Co.Atlantic City Electric Co.Delmarva Power & Light Co & Philadelphia Electric Co. FRYLING.R. Public Service Electric & Gas Co. of New Jersey. 79/04/30. 162pp.

#### J. Insurance & indemnity information

7905070582 Confirms increase in liability limit to \$36.006,000 for policies MF-22.26.29,38.39,44.46.47.49.50.51.52.53.54.55.56.57.58.60.61.64.66.67.68.69.70.71.72.74.76.77.78.79.80.86.87.88.90.91.92.93.94.95 \$ 96.

#### Q. Inspection reports, IE Bulletins & correspondence

7905010140 Forwards IE Info Notice 79-06. "Stress Analysis of Safety-Related Piping."

ORIER.B.H. Region 1, Philadelphia, Office of the Director.
79/03/23. ip.

7905020100 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/04/11. 1p.

7905020369 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required. GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/04/14. 1p.

7905040093 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
GRIER.B.H. Region 1, Philadelphia, Office of the Director.
79/04/14. 1p.

7905040282 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident." ORIER.B.H. Region 1, Philadelphia, Office of the Director. 79/04/14. 1p.

7905030101 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.

ORIER, B. H. Region 1, Philadelphia, Office of the Director.
79/04/17. 1p.

7905020322 Forwards IE Bulletin 79-06A.Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."

ORIER, B. H. Region 1, Philadelphia, Office of the Director. 79/04/18. 1p.

### DOCKET 50-355 HOPE CREEK NUCLEAR STATION, UNIT 2

A. Application/construction stage documents & correspondence

7905070552 Submits revised schedule re response to NRC's position on NUREO-0313, "Technical Rept on Matl Selection & Processing Guidelines for BWR Coolant Pressure Boundary Piping."
Response will be submitted no later than Sept 1979.
MITTL.R.L. Public Service Electric & Gas Co. of New Jersey.
79/04/23. 1p.

# 9. Adjudicatory correspondence

7903230512 Util response to brief opposing de minimus approach of Perkins proceeding. Licensees in Peach Bottom & Hope Creek proceedings contend approach is validing need to consider health effects further. W/Certificate of Svc. health effects further. W/Certificate of Svc. CONNEZ, T. B. Conner, Moore & Corber. 79/04/04. 30pp.

7905110418 Response to ALAB-509 re radon emissions & de minimus theory from Perkins record Certificate of Svc encl. SCINTO.J.F. Hearings Division. 79/04/11. 45pp.

7905140519 Response to 790404 brief of Philadelphia Electric Co.PSE&G & Atlantic City (NJ) Electric Co re de minimus theory. Certificate of Svc encl.

KEPFORD, C. R. Citizens for Safe Environment. 79/04/11. Spp.

7905140332 Notifies of consolidation of five intervenor groups re radon emissions issue. Parties have until 790525 in which to file for summary disposition.

DUFLO: M.E. Atomic Safety and Licensing Appeal Panel. 79/04/25.
1390.

7905240585 Memo & order ALAB-546. Denies applicants' petition for reconsideration of ALAB-540, which consolidates applicants re radon issue.

DUFLO.M.E. Atomic Safety and Licensing Appeal Panel. 79/05/08.

3pp.

#### H. General correspondence

7905070450 Ack receipt of 790216 resolution opposing storage of high level radioactive wastes in township. Objections should be made at ASLB hearing Expansion of storage pools is unlikely. No independent facilities are planned.

DENTON.H.R. Office of Nuclear Reactor Regulation. 79/03/29. Spp.

7905140291 Resonds to 790312 ltr re resolution adopted on 790216 by Township of Lower Alloways Creek, NJ. Resolution opposes storage of high level wastes. Forwards NRC response. QOSSICK, L. V. Office of the Executive Director for Operations. 79/04/11. 1p.

#### I. Financial information

7905070647 Forwards "Annual Financial Rept.1978" for Public Svc Electric & Gas Co.Atlantic City Electric Co.Delmarva Power & Light Co & Philadelphia Electric Co. FRYLING.R. Public Service Electric & Gas Co. of New Jersey. 79/04/30. 162pp.

## J. Insurance & indemnity information

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,56,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,91,92,93,94,95 & 96.
ROBERTS,D.M. Mutual Atomic Energy Liability Underwriters. 79/05/01.

# Q. Inspection reports, IE Bulletins & correspondence

7905010140 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping." GRIER.B.H. Region 1. Philadelphia, Office of the Director. 79/03/23. 1p.

> orwards IE Bulletin 79-06, "Review of Operational Errors & inments Identified During TMI Incident." Region 1, Philadelphia, Office of the Director.

> > ismic Stress Analysis of required.

--'onal Errors &

tor.

7905030101 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.

ORIER B.H. Region 1, Philadelphia, Office of the Director.
79/04/17. 1p.

7905020322 Forwards IE Bulletin 79-04A.Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."

(RIER, B. H. Region 1, Philadelphia, Office of the Director. 79/04/18. 1p.

DOCKET 50-358 WILLIAM H. ZIMMER NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

7905040316 Summary of 790321 meeting of Mark II owners group in San Jose CA re intermediate plant program tasks. ANDERSON.C.J. Containment Systems Branch. 79/04/13. 150pp.

7905100258 Summary of 790410 meeting w/Cincinnati Qas & Electric Co.
Long Island Lighting Co & Commonwealth Edison Co re
vibratory loads & equipment qualification. Presentation matl
encl.
pELTIER, I. A. Light Water Reactors Branch 1. 79/04/19. 15pp.

7905230558 Notification of 790515-17 meeting w/Cincinnati Gas & Electric Co.Long Island Lighting Co.Commonwealth Edison Co & GE in San Jose.CA to audit NSSS equipment for seismic & other dynamic qualification.
PELTIER.I.A. Light Water Reactors Branch 1. 79/04/23. 3pp.

7905020451 Response to 790223 ltr requesting plans & schedule for re-qualification of equipment for seismic & hydrodynamic loads. All Category I equipment has been evaluated as qualified.

BDROMANN.E.A. Cincinnati Gas & Electric Co. 79/04/26. 3pp.

7905080439 Forwards requested info re seismic Category 1 equipment, scenario for accomplishing cold shutdown & Sargent & Lundy Balance of Plant equipment for Category 1.
BDROMANN,E.A. Cincinnati Gas & Electric Co. 79/05/04. 49pp.

E. NRC Safety Evaluation Report (SER), suppls & correspondence

7905010659 Summary of 790328 meeting w/util re status of implementation of SER issues.
PELTIER.I.A. Light Water Reactors Branch 1. 79/04/12. 7pp.

F. Security, medical, emergency & fire protection plans

7905240572 Summarizes progress in fire protection review Because redundant electrical divisions are in same fire area, they are subj to identical fire exposure. Fire ratings must be verified prior to CL issuance.

8TOLZ.J.F. Light Water Reactors Branch 1. 79/04/19. 3pp.

7905140156 Forwards intervenor Miami Valley Power Project's 790223 answers to util's second set of interrogatories. Guestions application of lead plant Mark II acceptance criteria. KOSIK.L.S. Kosik. L. S. 79/02/21. 1p.

--7905140157 Motion by intervenor Miami Valley Power Project to applicant's motion to dismiss Certificate of Svc encl. KOBIK.L.S. Kosik.L. S. 79/02/22. 2pp.

--7905140369 Answer by intervenor Miami Valley Power Project to applicant's second set of interrogatories. Supporting documentation & Certificate of Svc encl. KOSIK,L.S. Kosik, L. S. 79/02/22. Spp.

7905150131 Discusses answers to Cincinnati Qas & Electric Co's interrogatories. Propounds third set of interrogatories to obtain specific responses to second set of questions.

METTERHAHN, M. J. Conner, Moore & Corber. 79/03/05. 2pp.

--7905150133 Applicants' third set of interrogatories to Miami Valley
Power Project Certificate of Svc encl.
METTERHAHN.M.J. Conner, Moore & Corber. 79/03/05. 6pp.

7905010223 Requests to know if NRC has funds available for use by intervenors to obtain expert witnesses in licensing hearings.
KOSIK.S.L. Kosik. L. S. 79/03/07. ip.

- 7905150144 Interrogatories of intervenor D Fankhauser submitted to applicant. Certificate of Svc encl. MOLIVER, J. D. Woliver, J. D. 79/03/08. 5pp.
- 7905290171 Opposes D Fankhauser response to 790306 proposed timetable of events. Certificate of Svc encl.
  CONNER, T. B., WETTERHAHN, M. J. Conner, Moore & Corber. 79/03/08.
- --7905290176 Motion to order answering of fouth set of interrogatories directed to Miami Valley Power Project. Certificate of Svc encl.

  CONNER, T. B. , WETTERHAHN, M. J. Conner, Moore & Corber. 79/03/08.
- --7905290180 Serves fourth set of interrogatories on Miami Valley Power Project. Certificate of Svc encl. WETTERHAHN, M. J. Conner, Moore & Corber. 79/03/08. 4pp.
- 7905290464 Submits supplementary answers to applicant's second set of interrogatories. Affidavit encl. KOSIK.L.S. KOSIK.L.S. RIOBERG.S. Miami Valley Power Project. 79/03/13. 6pp.
- --7905290468 Memo in opposition to applicant's motion to require response to fourth set of interrogatories.
  RIGBERG, S. Miami Valley Power Project. 79/03/13. 4pp.
- --7905290520 Response to proposed prehearing conference schedule. Schedule reflects impatience rather than sound judgment. Certificate of Svc encl. RIGBERG.S. Miami Valley Power Project. 79/03/13. 5pp.
- 7905150151 Opposition by applicant to Miami Valley Power Project 790307 motion to admit addl contentions & to extend time for discovery. Project does not satisfy requirements of 10CFR2. 715. Certificate of Svc encl.
  CONNER, T. B., WETTERHAHN, M. J. Conner, Moore & Corber. 79/03/19. 9pp.
- 7905100210 Responds to intervenor Miami Valley Power Project's set of interrogatories. Affidavit & Certificate of Svc encl. BORGMANN, E. A. Gincinnati Gas & Electric Co. 79/03/21. 45pp.
- 7905300042 Forwards applicant's objections to Miami Valley Power 790302 Project first set of interrogatories & motion for protective order.
  WETTERHAHN, M. J. Conner, Moore & Corber. 79/03/21. 1p.
- --7905300067 Applicant's objections to certain of Miami Valley Power Project's first set of interrogatories & motion for protective order. Certificate of Svc encl. WETTERHAHN, M. J., CONNER, T. B. Conner, Moore & Corber. 79/03/21.
- 7905010215 NRC is not legally obligated to financially assist intervenors. SHAPAR, H. K. Office of the Executive Legal Director. 79/03/22. 2pp.
- 7905240412 Ack receipt of 790307 ltr. Informs that US Court of Appeals held that agencies cannot fund participants in proceedings w/o special grant of authority from Congress.NRC will not fund participants in rulemaking proceedings.
  SHAPAR, H. K. Office of the Executive Legal Director. 79/03/22. 1pp.
- 7905080379 Opposes applicant's 790308 motion to require response by intervenor Miami Valley Power Project to interrogatories submitted by applicant. Certificate of Svc encl. BARTH.C.A. Branch 3. 79/03/26. 7pp.
- 7905100222 Responds to interrogtories served by intervenor D Fankhauser upon applicant. Certificate of Svc encl.
  BOROMANN.E.A. Cincinnati Gas & Electric Co. 79/03/27. 23pp.
- 7905170301 Forwards applicant's objections to interveour Fankhauser's interrogatories & motion for protective order.
  WETTERHAHN.M.J. Conner, Moore & Corber. 79/03/27. 1p.
- --- 7905170303 Applicant's objections to intervenor D Fankhauser's interrogatories & motion for protective order. Three interrogatories exceed scope of proceeding. Certificate of Svc encl.
  WATTERHAHN M. J. Conner, Moore & Corber. 79/03/27. 6pp.
- 7905300091 NRC opposition to Miami Valley Power Project's motion to admit two addl contentions re adequacy of cable trays & control rods. Recommends denial of motion according to 10CFR2.714(a)&(b). Certificate of Svc encl. BARTH.C. A. Branch 3. 79/03/27. 5pp.

- 7905150757 Response in support of admission of addl contentions & extension of time for discovery. Certificate of Svc encl. RIGBERG, S., MCDONALD, T. Miami Valley Power Project. 79/04/02. 13pp.
- 7905020334 NRC expects to issue suppl to SER prior to end of May. BARTH, C. A. Branch 3. 79/04/04. 1p.
- 7905220075 Forwards summary of "Rept to Commission--Inquiry into an Allegation of Employee Misconduct by Restricting Investigation to Determine Reliability of Power Grid Serving St Lucie."
  BARTH.C.A. Branch 3. 79/04/04. 2pp.
- --7903220084 Discusses inquiries into charges of possible NRC employee misconduct by restricting investigations of power grid disturbances. Available evidence does not support such allegations.

  MCTIERNAN, T. J. Office of Inspector & Auditor. 78/06/26. 5pp.
- 7905080341 NRC has recently discovered document possibly relevant to issue of sabotage of spent fuel. Info is classified & may never be published in final form. NRC assessment of info will follow as soon as available.

  BARTH.C.A. Branch 3. 79/04/05. 2pp.
- 7905100169 Memo by Cincinnati Gas & Electric in support of 771031 motion for summary judgment re certain admitted contentions. Affidavits of KL Rooney, JR Schott & QC Ficke encl. WETTERHAHN, M. J. Conner, Moore & Corber. 79/04/06. 66pp.
- 7905140083 Response to second set of interrogatories submitted by intervenor Miami Valley Power Project Certificate of Svc encl.
  BDROMANN.E.A. Cincinnati Gas & Electric Co. 79/04/06. 24pp.
- 7905250117 Objections by util to portions of intervenor Miami Valley Power Project's 790319 second set of interrogatories. Also seeks protective order.
  WETTERHAHN,M.J. Conner, Moore & Corber. 79/04/06. 3pp.
- 7905250123 Request by util that Miami Valley Power Project be dismissed as party for violations of discovery rules, or in the alternative, that util be granted extension of time to file motion of summary judgment re project's contentions.

  WETTERHAHN, M. J. Conner, Moore & Corber. 79/04/06. 4pp.
- 7905300690 Notification of new schedule, including new dates for prehearing conference.

  BECHHOEFER, C. Atomic Safety and Licensing Board Panel. 79/04/06.
  4pp.
- 7905250208 Notice of prehearing conference on 790521-23, to be held per ASLB 790406 order. BECHHOEFER, C. Atomic Safety and Licensing Board Panel. 79/04/09.
- 7905150227 Motion to delay OL hearings & to extend time for discovery re Contention 13 Certificate of Svc encl. KOSIK, L. S. Miami Valley Power Project. 79/04/16. 6pp.
- 7905240506 Forwards request for ASLAB decisions from C Richards & summary of NRC 790327 meeting w/util to discuss fire protection.
  BARTH, C. A. Branch 3. 79/04/16. 5pp.
- --7905240515 Requests copies of ALAB-444 & ALAB-462 be sent to aid in research re use & availability of U fuel. RICHARDS.C. Affiliation Unknown. 79/04/10. 1p.
- 7905150218 Motion by intervenor D Fankhouser to reopen discovery & for continuance of hearing, pending NRC review of TMI-2 incident. Certificate of Svc encl.
  WOLIVER, J. D. Woliver, J. D. 79/04/17. 4PP.
- 7905130212 Opposes util's motion to dismiss intervenor Miami Valley Power Project as party Does not oppose util's alternative request for extension of time Certificate of Svc encl.

  KOSIK.L.S. Miami Valley Power Project. 79/04/18. 4pp.
- 7905150221 Third set of interrogatories to applicant Certificate of Svc encl. KDSIK.L.S. Miami Valley Power Project. 79/04/20. 11pp.
- 7905240092 Requests joint appearance for A Shapiro & EJ Torchia at ASLE hearings in Moscow.OH on 790522 & Cincinnati.OH on 790523. Requests notification of meeting schedule.

  TORCHIA.E.J. Affiliation Unknown. 79/04/20. 1p.

- 7905240104 Complains that date of 790423 is unrealistic; objections & protective order were filed after receipt of discovery motions.

  KOSIK.L.S. Kosik. L. S. 79/04/20. 1p.
- 7905310093 Fifth set of interrogatories submitted by util to Miami Valley Power Project Certificate of Svc encl. WETTERMAHN, M. J. Conner, Moore & Corber. 79/04/20. 7pp.
- 7905290036 Grants extension until 790502 for NRC to respond to util's 790406 motion for summary disposition.

  BECHHOEFER.C. Atomic Safety and Licensing Board Panel. 79/05/01.
- 7905150284 Orders one-day extension until 790502 for City of Cincinnati to respond to util's 790406 motion for summary disposition.

  BECHHOEFER.C. Atomic Safety and Licensing Board Panel. 79/05/02.
- 7905300749 Requests opportunity to present limited statement at 790523 prehearing conference in Moscow.OH.

  ZITT,K.L. Affiliation Unknown. 79/05/04. 1p.

#### H. General correspondence

- 7905300284 Requests deletion of PH Forster of Dayton Power & Light Co from svc list & replacement w/50 Smith. FLYNN, J. D. Cincinnati Gas & Electric Co. 79/05/25. 1p.
- J. Insurance & indemnity information
- 7905160272 Forwards Amend 2 to Indemnity Agreement B-B5, changes, re increase from \$140 million to \$160 million, effective 790501. Supporting documentation encl.
  SALTZMAN.J. Antitrust & Indemnity Group. 79/05/01. -85.per 10CFR140 79/05/01. 5op.
- 7905110148 Forwards Indemnity Agreement B-85 & Amend 1. BDRGMANN.E.A. Cincinnati Gas & Electric Co. 79/05/04. 15pp.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 7905290449 Forwards Amend 92 to application consisting of Revision 57 to FSAR. BORGMANN, E. A. Cincinnati Gas & Electric Co. 79/04/30. 2pp.
- --7905290456 Amend 92 to application, FSAR Revision 57. Submitted in response to second round questions.

  \* Cincinnati Gas & Electric Co. 79/04/30. 400pp.
- 7905160434 Forwards Certificate of Svc of Amend 92, in form of Revision BORGMANN, E. A. Cincinnati Gas & Electric Co. 79/05/10. 2pp.
- G. Inspection reports, IE Bulletins & correspondence
- 7905010242 Forwards IE Info Notice 79-06. "Stress Analysis of USDIVERS FORWARDS IN INTO NUTLE 17-00, Seres minings of Safety-Related Piping."

  KEPPLER, J. C. Region 3, Chicago, Office of the Director. 79/03/23. KEPPLER, J. G.
- 7905030372 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks."

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/03/26.
- 7905240719 Forwards IE Insp Rept 50-358/79-08 on 790305-06. No noncompliance noted. HEISHMAN, R. F. Re Region 3, Chicago, Reactor Operations Nuclear 79/03/27. 2pp. Support Branch. 79/03/27.
- -7905240729 IE Insp Rept 50-358/79-08 on 790305-06.No noncompliance noted Major areas inspected:operational GA program & station staffing. HARPSTER.T.L. HENNING.J.E., MARNICK,R.F. Region 3, C Reactor Operations Nuclear Support Branch. 79/03/13. 2p Region 3, Chicago, 9/03/15, 2pp.
- 7905150529 Forwards IE Insp Rept 50-358/79-10 on 790319-20. No noncompliance noted. noncompliance notes.
  FIORELLI.G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/03/29. 2pp.
- ---7905150535 IE Insp Rept 50-358/79-10 on 790319-20. No noncompliance noted Major areas inspected: review of procedures work activities & quality records for hangers, snubbers & restraints design.

  YIN, L. T., NATDUK, R. Region 3, Chicago, Office of the Director. DANIELSON, D. H. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/03/28, 5pp.

- 7905290699 Forwards IE Insp Rept 50-358/79-09 on 790321-23 No noncompliance noted. FIGRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/04/09. 2PP.
- --7905290720 IE Insp Rept 50-358/79-09 on 790321-23. No noncompliance noted Major areas inspected:followup of previously identified noncompliance & unresolved matters & review of electrical & instrumentation activities in progress. VANDEL.T.E., HUGHES.J., KNDP.R.C. Region 3, Chicago, Office of the Director. 79/04/06. Bpp. Region 3, Chicago, Office of
- 7905030017 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/04/11.
- 7905010574 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/04/14.
- 7905040351 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/04/14.
- 7905040452 Forwards IE Bulletin 79-07. "Seismic Stress Analysis of Safety-Related Piping." Licensee action required. KEPPLER.J.G. Region 3. Chicago. Office of the Director. 79/04/14.
- 7905040534 Forwards IE Bulletin 79-08. "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/04/14.
- 7905010400 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts. " KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/04/16. 10.
- 7905030215 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/04/17. 1p.
- 790504036B Responds to 781017 phone call re Sargent & Lundy control of stress rept documentation. NRC review discloses weakness in control of outdated procedures & will be pursued until open item is adequately resolved. W
- 7905080397 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl. " KEPPLER, J. G. Region 3. Chicago. Office of the Director. 79/04/21.
- 7905140107 Ack receipt of 790411 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-358/79-07.
  FIORELI, 6. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/04/25. ip.
- --7905140111 Responds to NRC 790305 ltr re violations noted in IE Insp Rapt 50-358/79-07. Corrective actions: approved calibr procedure implemented & uncontrolled rods & stubs removed. BORGMANN.E.A. Cincinnati Gas & Electric Co. 79/04/11. 3pp.
- 7905240887 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Recirculation Motor Generator Set Resulted in Reactor Power Increase."

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/05/02.
- S. Reportable occurrences, LERs & related correspondence
- 7905070009 Ack receipt of 790313 final rept re control rod interference.per 10CFR50.55(e).
  FIORELLI.G. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 79/04/04. 1p.

# DOCKET 50-360 BATTELLE MEMORIAL INST. CRITICAL FACILITY

#### J. Insurance & indemnity information

7905160233 Forwards Amend 7 to Indemnity Agreement B-58, per 10CFR140 changes.re liability insurance increase from \$140 million to \$160 million, effective 790501. Supporting documentation encl. SALTZMAN, J. Antitrust & Indemnity Group. 79/05/01. Spp.

7905300523 Forwards Amend 7 to Indemnity Agreement B-58.
FRANSEN.C.D. Battelle Memorial Institute, Pacific Northwest Laboratory. 79/05/24. 2pp.

## DOCKET 50-361 SAN ONOFRE NUCLEAR STATION, UNIT 2

#### A. Application/construction stage documents & correspondence

7905010553 Comments on "Cultural Resource Mgt Repts for San Onofre-to-Mission-to-Encino 230 kV Transmission Lines & Mapping & Data Recovery Program for Site W-1527." Repts are suitable as baseline studies. Identifies questions for clarification. MELLON, K. California, State of. 79/03/20. 2pp.

7905230589 Notification of 790426 meeting w/util in Bethesda.MD to discuss fuel design & analysis.
ROOD.H. Light Water Reactors Branch 2. 79/04/19. 3pp.

7905290411 Notification of 790504 meeting w/util in Bethesda.MD to discuss San Onofre geology. ROOD.H. Light Water Reactors Branch 2. 79/05/02. 3pp.

7905210160 Forwards equipment seismic qualification summary inforin response to NRC 790111 request in preparation for site visit Drawings available in Central Files only. BASKIN, K.P. Southern California Edison Co. 79/05/16. 700pp.

#### I. Financial information

7905150400 Forwards "Annual Financial Rept 1978" for Southern CA Edison Co & San Diego Gas & Electric Co. DRAKE, J. H. Southern California Edison Co. 79/05/08. 1p.

--7905150404 "Annual Financial Rept 1978."

\* Southern California Edison Co. 79/02/15. 31pp.

--7905150406 "Annual Financial Rept 1978." \* San Diego Gas & Electric Co. 79/02/20. 43pp.

## J. Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,185,186,187,188,189,192,193,194,195,197,198,200,201,204,206,207,208,210,212,214,215,&others.

QUATTROCHHI, J. American Nuclear Insurers. 79/05/01. 1p.

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22.26.29.38.39,44.46.47.49.50.51.52.53.54.55.56.57.58.60.61.64.66.67.68.69.70.71.72.74.76.77.78,79.80.86.87.88.90.91.92.93.94.95 & 96.

# M. Antitrust correspondence

7905310373 Submits request for addl info to complete antitrust review of OL application.
TOALSTON, A. L. Antitrust & Indemnity Group. 79/05/11. 3pp.

# G. Inspection reports, IE Bulletins & correspondence

7905010292 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping." ENGELKEN, R. H. Region 4, Dallas, Office of the Director. 79/03/23.

7905010025 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." Licensee action required. ENGELKEN.R.H. Region 5, San Francisco, Office of the Director. 79/04/14.

7905040512 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." ENOELKEN,R.H. Region 5, San Francisco, Office of the Director. 79/04/14, 1p.

7705040619 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident." ENGELKEN,R.H. Region 5, San Francisco, Office of the Director. 79/04/14. 1p.

7905070104 Forwards IE Bulletin 79-07. "Seismic Stress Analysis of Safety-Related Piping." Licensee action required. ENGELKEN, R. Region 5, San Francisco, Office of the Director. 79/04/14. 1p.

7905030296 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
ENGELKEN.R. H. Region 5, San Francisco, Office of the Director.

7905080371 Forwards IE Bulletin 79-058. "Nuclear Incident at TMI-Suppl."
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/21 1n

# S. Reportable occurrences, LERs & related correspondence

7905150064 Forwards PND-79-67L. ENGELKEN.R.H. Region 5, San Francisco, Office of the Director. 79/04/06. 1p.

7905150170 Forwards PNO-79-67R. ENGELKEN.R. H. Region 5, San Francisco, Office of the Director. 79/04/11. 1p.

7905040128 Forwards PNO-79-675. ENGELKEN.R. H. Region 5. San Francisco. Office of the Director. 79/04/12. 1p.

7905150145 Forwards PNO-79-67T.
ENGELKEN.R.H. Region 5, San Francisco, Office of the Director.
79/04/13. 1p.

7905030024 Forwards PND-79-67U. ENGELKEN.R.H. Region 5, San Francisco, Office of the Director. 79/04/14. 1P.

7905020532 Forwards PND-79-67AA. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/20. 1p.

7905010434 Forwards PNO-79-67AB. ENGELKEN.R.H. Region 5, San Francisco, Office of the Director. 79/04/21 10.

7905010449 Forwards PND-79-67AC & AD. ENGELKEN,R.H. Region 5, San Francisco, Office of the Director. 79/04/23. 1p.

7905010462 Forwards PNO-79-67AE. ENGELKEN.R.H. Region 5, San Francisco, Office of the Director. 79/04/24. 1p.

7905090041 Forwards PNO-79-67AF. ENGELKEN,R. H. Region 5, San Francisco, Office of the Director. 79/04/25. 1p.

7905090057 Forwards PNO-79-67AG. ENGELKEN.R.H. Region 5, San Francisco, Office of the Director. 79/04/26. 1p.

7905310012 Ack receipt of 790406 interim rept on Taylor Forge pipe defects pursuant to 10CFR50.55(e). ENOELKEN.R.H. Region 5, San Francisco, Office of the Director. 79/04/26. 1p.

7905090119 Forwards PND-79-67AH.

ENGLEKEN.R.H. Region 5, San Francisco, Office of the Director.

.79704/27. lp.

7905070031 Forwards PNO-79-67AI, AJ & AK, per NRC 790401 ltr transmitting IE Bulletin 79-05.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/30. 1p.

7905070012 Forwards PNO-79-67AL, per NRC 790401 ltr transmitting IE Bulletin 79-05. ENGELKEN.R.H. Region 5, San Francisco, Office of the Director. 79/05/01. 1p. 7905090277 Provides followup on 790108 final rept on reportable condition re fillet weld design. Revised drawings for remaining 78 pipe support assemblies will be issued for const use by 790904.

MODRE, J. B. Southern California Edison Co. 79/05/02. 1p.

7905310044 Forwards PNO-79-67AM. ENGELKEN.R.H. Region 5, San Francisco, Office of the Director. 79/05/07. 1p.

7905300265 Forwards interim rept of Marine Review Committee re ECCS. WONG, S California, State of. 79/05/15. 1p.

--7905300270 "Interim Rept of Marine Review Committee to CA Coastal Commission.Part I:General Summary of Findings,Predictions & Recommendations Concerning Cooling Sys."

CONNECL.J. H., MECHALAS, B. J., MIHURSKY, J. A. California, State of. 79/05/12. 22pp.

--7905300277 "Interim Rept of Marine Review Committee to CA Coastal Commission.Part II:App of Technical Evidence in Support of General Summary." (CONNELL, J. H., MECHALAS, B. J., MIHURSKY, J. A. California, State of, 79/05/12. 1970s.

7905310423 Forwards final deficiency rept, "Undersized Safety-Related Heating, Ventilating & Air Conditioning Damper Actuators," identified in 790419 ltr. MODREJ J.B. Southern California Edison Co. 79/05/18. 1p.

--7905310426 Final deficiency rept: "Undersized Safety-Related Heating, Ventilating & Air Conditioning Damper Actuators."
Appropriate drawing changes will be issued for design changes by 790715. Fifteen actuators will require rework.

\* Southern California Edison Co. 79/05/18. 3pp.

DOCKET 50-362 SAN ONOFRE NUCLEAR STATION, UNIT 3

A. Application/construction stage documents & correspondence

7905010553 Comments on "Cultural Resource Mgt Repts for San Onofre-to-Mission-to-Encino 230 kV Transmission Lines & Mapping & Data Recovery Program for Site W-1527." Repts are suitable as baseline studies. Identifies questions for clarification. MELLON, K. California, State of. 79/03/20. 2pp.

7905230589 Notification of 770426 meeting w/util in Bethesda.MD to discuss fuel design & analysis.

ROOD.H. Light Water Reactors Branch 2. 79/04/19. 3pp.

7905290411 Notification of 790504 meeting w/util in Bethesda.MD to discuss San Onofre geology. ROOD.M. Light Water Reactors Branch 2. 79/05/02. 3pp.

7905210160 Forwards equipment seismic qualification summary info, in response to NRC 790111 request in preparation for site visit. Drawings available in Central Files only.

BASKIN, K. P. Southern California Edison Co. 79/05/16. 700pp.

I. Financial information

7905150400 Forwards "Annual Financial Rept 1978" for Southern CA Edison Co & San Diego Gas & Electric Co. DRAKE, J. H. Southern California Edison Co. 79/05/08. 1p.

--7905150404 "Annual Financial Rept 1978." \* Southern California Edison Co. 79/02/15. 31pp.

--7905150406 "Annual Financial Rept 1978." .
\* San Diego Gas & Electric Co. 79/02/20. 43pp.

J. Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170, 173,174,178,179,180,182,185,186,187,188,189,192,193,194,195,197,198,200,201,204,206,207,208,210,212,214,215,% others.

GUATTROCHHI, J. American Nuclear Insurers. 79/05/01. 1p.

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,56,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,91,92,93,94,95 & 96.
ROBERTS,D.M. Mutual Atomic Energy Liability Underwriters. 79/05/01.

### M. Antitrust correspondence

7905310373 Submits request for add1 info to complete antitrust review of OL application.
TOALSTON,A.L. Antitrust & Indemnity Group. 79/05/11. 3pp.

Q. Inspection reports, IE Bulletins & correspondence

7905010292 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
ENGELKEN,R.H. Region 4, Dallas, Office of the Director. 79/03/23.

7905010020 Forwards IE Bulletin 79-06A. "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." ENGELKEN, R.H. Region 5. San Francisco. Office of the Director. 79/04/14. 1p.

7905040512 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." ENGELKEN.R.H. Region 5. San Francisco, Office of the Director. 79/04/14. 1p.

7905040619 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident." ENGELKEN.R.H. Region 5, San Francisco, Office of the Director. 79/04/14. 1p.

7905070104 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required. ENGELKEN,R.H. Region 5, San Francisco, Office of the Director, 79/04/14. 1p.

.7905030276 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/17, 10.

7905080371 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl."
ENGELKEN,R.H. Region 5, San Francisco, Office of the Director. 79/04/21. 10.

S. Reportable occurrences, LERs & related correspondence

7905150064 Forwards PNO-79-67L. ENGELKEN.R.H. Region 5, San Francisco, Office of the Director. 79/04/06. 1p.

7905150170 Forwards PNO-79-67R.
ENGELKEN,R.H. Region 5, San Francisco, Office of the Director.
79/04/11. 1p.

7905040128 Forwards PNO-79-678. ENGELKEN.R.H. Region 5. San Francisco. Office of the Director. 79/04/12. 1p.

7905150145 Forwards PNO-79-67T. ENGELKEN.R.H. Region 5. San Francisco. Office of the Director. 79/04/13. 10.

7905030024 Forwards PNO-79-67U.
ENGELKEN,R.H. Region 5, San Francisco, Office of the Director.
79/04/14. 1P.

7905020532 Forwards PND-79-67AA.
ENGELKEN,R.H. Region 5, San Francisco, Office of the Director.
79/04/20. 1p.

7905010434 Forwards PNO-79-67AB.
ENGELKEN,R.H. Region 5, San Francisco, Office of the Director.
79/04/21. 1p.

7905010449 Forwards PNO-79-67AC & AD.
ENGELKEN.R.H. Region 5, San Francisco, Office of the Director.
79/04/23. 1p.

7905010462 Forwards PND-79-67AE. ENGELKEN.R.H. Region 3, San Francisco, Office of the Director. 79/04/24. lp.

7905090041 Forwards PND-79-67AF. ENGELKEN.R.H. Region 5, San Francisco, Office of the Director. 79/04/25. 1p.

- 7905090057 Forwards PND-74-67AG.

  ENGLIKEN, R.H. Region 5, San Francisco, Office of the Director.
- 7905310012 Ack receipt of 790406 interim rept on Taylor Forge pipe defects pursuant to 10CFR30.55(e). ENGELKEN,R.H. Region 5. San Francisco. Office of the Director. 79/04/26. 1p.
- 7905090119 Forwards PND-79-67AH.
  ENOLEKEN.R.H. Region 5, San Francisco, Office of the Director.
  79/04/27 1p.
- 7905070031 Forwards PND-79-67AI.AJ & AK.per NRC 790401 ltr transmitting IE Bulletin 79-05.
  ENGLIKEN.R.H. Region 5. San Francisco. Office of the Director. 79/04/30. 1p.
- 7905070012 Forwards PND-79-67AL, per NRC 790401 itr transmitting IE Bulletin 79-05. ENGELKEN,R.H. Region 5, San Francisco, Office of the Director. 79/05/01. 1p.
- 7905090277 Provides followup on 790108 final rept on reportable condition re fillet weld design. Revised drawings for remaining 78 pipe support assemblies will be issued for const use by 790404.

  MOORE, J. B. Southern California Edison Co. 79/05/02. 1p.
- 7905310044 Forwards PND-79-67AM.
  ENGELMEN.R.H. Region 5, San Francisco, Office of the Director.
  79/05/07. 1p.
- 7905300265 Forwards interim rept of Marine Review Committee re ECCS. MONO, S. California, State of. 79/05/15. 1p.
- ---7905300270 "Interim Rept of Marine Review Committee to CA Coastal Commission.Part I:General Summary of Findings.Predictions & Recommendations Concerning Cooling Sys."
  CONNELL.J. H. MECHALAS.B. J., MIHURSKY, J. A. California, State of. 79/05/12. 22pp.
- ---7905300277 "Interim Rept of Marine Review Committee to CA Coastal Commission, Part II: App of Technical Evidence in Support of General Summary."

  CONNELL, J. H., MECHALAS, B. J., MIHURSKY, J. A. California, State of. 79/05/12. 197pp.
- 7905310423 Forwards final deficiency rept, "Undersized Safety-Related Heating, Ventilating & Air Conditioning Damper Actuators," identified in 790419 ltr.
  MOORE, J. B. Southern California Edison Co. 79/05/18. 1p.
- ---7905310426 Final deficiency rept: "Undersized Safety-Related Heating, Ventilating & Air Conditioning Damper Actuators."
  Appropriate drawing changes will be issued for design changes by 790715 Fifteen actuators will require rework.

  -- Southern California Edison Co. 79/05/18. 3pp.

## DOCKET 50-363 FORKED RIVER NUCLEAR STATION, UNIT 1

- A. Application/construction stage documents & correspondence
- 7905070466 Forwards "Design Info.Submittal 2.Structural Reorientation," w/current design features reflecting new licensing concerns of post-CP period.
  FINFRQCK, J. R. Jersey Central Power & Light Co. 79/03/05. 2pp.
- ---7905070470 "Design Info.Submittal 2.Structural Reorientation." FLNFROCK, J. R. Jersey Central Power & Light Co. 79/02/23. 54pp.
- 7905150287 Forwards 790307 ltr from 8 Rush, of Sea Alliance of Grean County, NJ, for placement in docket file.
  ABRAHAN, K. Region 1, Philadelphia, Office of the Director.
  79703/20. 1p.
- ---7905150293 Requests that planned salt water cooling tower not be built because of disasterous effects on natural beauty of area. RUSH.S. Sea Allience of Ocean County. 79/03/07. 1p.
- ---7903130298 Responds to 790307 ltr objecting to proposed cooling tower. Ltr forwarded to NRC headquarters. ABRAHAH.K. Region 1. Philadelphia, Office of the Director. 79/03/20. 1p.

#### H. General correspondence

- 7905090144 Ack receipt of 790206 ltr requesting list of publications re nuclear-powered electric generating facilities & related issues. List of repts re cooling towers, transmission lines & socioeconomic impacts encl.

  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/04/04. 3pp.
- 7905040343 Ack receipt of encl 790202 ltr to President Carter expressing concern over proposed facility. Describes environ review process. Const is about 5% complete.

  DENTON: H. R. Office of Nuclear Reactor Regulation. 79/04/13. 4pp.

## J. Insurance & indemnity information

- 7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,185,186,187,188,189,192,193,194,195,197,198,200,201,204,206,207,208,210,212,214,215,&others.

  GUATTROCHHI, J. American Nuclear Insurers. 79/05/01. ip.
- 7903070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,56,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,91,92,93,94,95 & 96.
  ROBERTS, D. M. Mutual Atomic Energy Liability Underwriters. 79/05/01.
- Q. Inspection reports, IE Bulletins & correspondence
- 7905010112 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."

  QRIER,B.H. Region 1, Philadelphia, Office of the Director. 79/03/23. 1p.
- 7905240679 Forwards IE Insp Rept 50-363/79-03 on 790306-07.No noncompliance noted. CARLSON,R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 79/03/23. 2pp.
- --7903240684 IE Insp Rept 50-363/79-03 on 790306-07. No noncompliance noted. Major areas inspected:containment concrete placement activities & associated quality records.
  CERNE, A. C. Region 1. Philadelphia, Office of the Director.
  MCGAUGHY, R. W. Region 1. Philadelphia, Reactor Construction & Engineering Support Branch. 79/03/22. 5pp.
- 7903020045 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."

  ORIER.B. H. Region 1, Philadelphia, Office of the Director.

  79704/11. 1p.
- 7905020393 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required. ORIER.B.H. Region 1, Philadelphia. Office of the Director. 79/04/14. 1p.
- 7905040020 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
  ORIER.B.H. Region i, Philadelphia, Office of the Director.
  79/04/14. 1p.
- 7905040204 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Hater Power Reactors Identified During TMI Incident." ORIER.B.H. Region 1, Philadelphia, Office of the Director. 79/04/14. ip.
- 7905030065 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
  ORIER.B.H. Region 1, Philadelphia, Office of the Director.
  79/04/17. 1p.
- 7905010650 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/04/18. 1p.

SCCKET 50-354 UDSEPH M FARLEY NUCLEAR PLANT, UNIT 2 A Application/construction stage documents & correspondence

7905140357 Notifies of potential reportable inconsistency in calculated INB mations as reported to util by Westinghouse. HAIRSTON # G. Alabama Power Co. 79/03/30. 2pp.

7905240109 Notifies of 790531 expiration of Centificate of Compliance 5364 for Model NPI-67-0442 Renewal must be requested. MACDONALD.C E Transportation Branch. 79/04/12. 1p.

7905020242 Forwards proposed amends to Tech Specs for Unit 1 intorporating radiological effluent Tech Specs into App A 8 proposed draft radiological effluent Tech Specs for Unit 2. Proposed draft App B Tech Specs encl. CLAYTON.F.L. Alabama Power Co. 79/04/16. 190pp.

7905230414 Requests informal facility info re TMI incident be withheld from public disclosure unless util conducts proprietary review CLAYTON:F L Alabama Power Co. 79/05/16. 2pp

F. Security, medical, emergency & fire protection plans

7905070631 Forwards check to replace check sent 790323 w/safeguards security contingency plan. CLAYTON,F.L. Alabama Power Co. 79/05/01. 2pp.

I. Financial information

7905150391 Forwards "Annual Financial Rept 1978," unaudited financial statements for quarter ending 790331 & cash flow projections for 1979.
BOWDEN, T. J. Alabama Power Co. 79/05/10. 7pp.

--7905150395 "Annual Financial Rept 1978." \* Alabama Power Co. 78/12/31. 47pp.

J. Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170, 173,174,178,179,180,182,185,186,187,188,189,192,193,194,195,197,198,200,201,204,206,207,208,210,212,214,215,&others. QUATTROCHHI,J. American Nuclear Insurers. 79/05/01. 1p.

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22.26.29,38,39,44,46,47,49,50.51,52,53,54,55,56,57,58,60.61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,91,92,93,94,95 & 96.

orwards Endodrsement 23 to NELIA Policy NF-238.

March & Melanon, M & M Nuclear Consultants, Inc. Div.

hent 24 to ANI Policy NF-238.
"Iclear Consultants, Inc. Div.

: y NF-238. Isultants, Inc. Div.

:o applicant's "Memo re 1 encl. |ons. 79/03/28, 23pp.

Association of AL to ulatory

. HUELMFIELT, D. C.

behalf of NRC.

300.

Regulatory Policies Act gal status of rtificate of

.J. Anti-Trust

7905240985 Responds to applicant's memo re impact of Public Util Regulatory Policies Act of 1978 Certificate of Svc & supporting documentation encl. WHITLER,J.D. Justice, Dept. of. 79/03/29. 22pp.

G. Inspection reports, IE Bulletins & correspondence

7905010161 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/03/23. 2pp.

7905030290 Forwards IE Info Notice 79-07. "Rupture of Radwaste Tanks." O'REILLY.J.P. Region 2. Atlanta, Office of the Director. 79/03/26. 2pp.

7905100279 Requests extension of time until 790512 to respond to IE Bulletin 79-03, "Longitudinal Weld Defects in Pipe Spools Mfg by Youngstown Welding & Engineering Co." CLAYTON,F.L. Alabama Power Co. 79/04/11. 1p.

7905150568 Confirms 790412 telcon to AK Hardin re IE Bulletin 79-02. Test program was initiated enough failures found in anchor bolt installations to justify expansion of test scope. Further details will come in 14-day followup. HAIRSTON.W. G. Alabama Power Co. 79/04/12. 1p.

7905040148 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/04/14. 2pp.

7905040298 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required.

9 ("REILLY,J.P. Region 2, Atlanta, Office of the Director.
79/04/14. 2pp.

7905040322 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident." O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/04/14. ip.

7905010331 Forwards IE Info Notice 79-10. "Nonconforming Pipe Support Struts. "
O'REILLY, J. P. ).P. Region 2. Atlanta. Office of the Director. 2pp. 79/04/18

7905030137 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.

O'REILLY,J.P. Region 2, Atlanta, Office of the Director.
79/04/17. 2pp.

7905020365 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."

O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
79/04/18. 2pp.

7905240443 Responds to IE Bulletin 79-07. "Seismic Stress Analysis of Safety-Related Piping." Methods specified by Item I have never been used Therefore, specific concerns are not applicable to facility.

CLAYTON,F.L. Alabama Power Co. 79/04/24. 3pp.

7905300710 Forwards response to IE Bulletins 79-06A & 79-06. Revision 1. Training program for personnel w/operational duties is being developed actions required by operating procedures retransients & accidents have been reviewed. CLAYTON.F. L. Alabama Power Co. 79/04/24. 21pp.

7905300554 Responds to IE Bulletin 79-03.No SA-312 or other welded pipe mfg by Youngstown Welding & Engineering has been received on site or will be used in future.

CLAYTON.F.L. Alabama Power Co. 79/04/26. 1p.

DOCKET 50-366 EDWIN I. HATCH NUCLEAR PLANT, UNIT 2

F. Security, medical, emergency & fire protection plans

7905150089 Responds to 790302 ltr reporting reasons for delays on implementing 10CFR73.55 requirements & describing compensatory measures provided to meet these requirements. Measures are acceptable.

IPPOLITO,T.A. Operating Reactors Branch 3. 79/04/18. 2pp.

I. Financial information

7905080497 Forwards "Annual Financial Rept 1978."
VASQUEZ,R.O. Metropolitan Electric Authority of Georgia. 79/05/02.

- ---7905080508 "Annual Financial Rept 1978." \* Metropolitan Electric Authority of Georgia. 78/12/31. 24pp.
- J. Insurance & indemnity information
- 7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1.25,43,76,83,100.111,140,146,151,161,164,170,173,174,178,179,180,182,185,186,187,188,189,192,193,194,195,197,199,200,201,204,206,207,208,210,212,214,215,&others.
- 7903070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,56,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,91,92,93,94,95 & 96.
  ROBERTS, D. M. Mutual Atomic Energy Liability Underwriters. 79/05/01.
- 7905080427 Forwards Amend 10 to Indemnity Agreement B-69. WHITMER, C. F. Georgia Power Co. 79/05/01. 3pp.
- 7905140493 Forwards Amend 11 to Indemnity Agreement B-69 per 10CFR140 changes, re increase in liability insurance from \$140 million to \$160 million, effective 790501. Supporting documentation encl.

  SALTZMAN, J. Antitrust & Indemnity Group. 79/05/01. 6pp.
- 7905080430 Forwards Endorsement 49 to NELIA Policy NF-215. FIELDER,J. Marsh & McLenon, M & M Nuclear Consultants, Inc. Div. 79/05/03. 2pp.
- P. Operating license stage documents & correspondence
- 7905090183 Forwards Amend 7 to License NPF-5 & notice of issuance & availability.

  IPPOLITO.T.A. Operating Reactors Branch 3, 79/04/03, 3pp.
- ---7905090186 Amend 7 to License NPF-5, changing Tech Spec deadline for initial startup rept. IPPOLITO, T. A. Operating Reactors Branch 3, 79/04/03, 5pp.
- ---7905090189 Notice of issuance & availability of Amend 7 to License NPF-5. IPPOLITO T. A. Operating Reactors Branch 3. 79/04/03. 200.
- 7905070669 Responds to 790319 ltr questioning license amend fee requirement for 781221 application. Fees paid are justified. MILLER.W. O. License Fee Management Branch. 79/04/05. 1p.
- 7905170234 Forwards schedule for implementation & resolution of Mark I containment long-term program. Only vent header deflectors are necessary as major mod for conformance to long-term program acceptance criteria.

  WHITMER.C.F. Georgia Power Co. 79/05/14. 4pp.
- 7905290184 Forwards changes to Unit 2 Tech Specs re reactor protection sys instrumentation.isolation actuation instrumentation & bases for applicability spec per 790201 request. WHITMER.C.F. Georgia Power Co. 79/05/22. 9pp.
- G. Inspection reports, IE Bulletins & correspondence
- 7905010200 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."

  O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/03/23. 2pp.
- 7905020489 Forwards IE Insp Repts 50-321/79-09 & 50-366/79-11 on 790210-0302.No noncompliance noted. LEWIS,R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/03/23. 2pp.
- ---7905020497 IE Insp Repts 50-321/79-09 & 50-366/79-11 on 790210-0302.No noncompliance noted Major areas inspected: Unit 1 plant operations, Unit 2 startup testing, Tech Specs compliance, reportable occurrences & Unit 2 transient test witnessing. ROGERS, R. F. Region 2. Atlanta, Office of the Director. DANCE.H.C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 79/03/23. 4pp.
- 7905030312 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks." 0'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/03/26. 2pp.
- 7905010107 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air."

  0'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/03/28 2na.

- 7905010360 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin."
  O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
  79/03/30. 2pp.
- 7905250098 Requests page 6 of IE Insp Repts 50-321/79-06 & 50-366/79-07 be replaced w/encl corrected page.
  MILLER, J. H. Georgia Power Co. 79/04/04. 2pp.
- --7905250105 Forwards IE Insp Repts 50-321/79-06 & 50-366/79-07 on 790214-16 No noncompliance noted.

  LEWIS.R.C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 79/03/21. 2pp.
- --7905250110 IE Insp Repts 50-321/79-06 & 50-366/79-07 on 790214-16. No noncompliance noted Major areas inspected: plant operations, followup of unresolved items. LERs & test witnessing.

  DANCE. H. C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. HINCKLEY. D. G. Region 2. Atlanta, Office of the Director. 79/03/21. 8pp.
- 7905040216 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/04/14. 2pp.
- 7905040304 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79/04/14. | 1p.
- 7905040413 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident." O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79/04/14. 1p.
- 7905100244 Responds to IE Bulletin 79-03.No evidence of Youngstown Welding & Engineering seam welded ASME SA-312 Type 304 stainless steel piping is being used in safety-related sys. ASME SA-358 Type 304 spool is used.
  STAFFA.R.W. Georgia Power Co. 79/04/16. 1p.
- 7905030165 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
  0'REILLY,J.P. Region 2. Atlanta, Office of the Director.
  79/04/17. 2pp.
- 7905020467 Forwards IE Bulletin 79-06A.Revision i, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."

  0'REILLY.J.P. Region 2, Atlanta, Office of the Director.
  79/04/18. 2pp.
- 7905290029 Responds to IE Bulletin 79-08. Addresses events relevant to BMRs identified during TMI incident. Response to Item 11 will be forwarded in 30 days.
  WIDNER, M. A. Georgia Power Co. 79/04/25. 15pp.
- 7905300309 Responds to IE Bulletin 79-04. Review of design records indicates there are no 3,4 or 6-inch diameter Velan swing check valves used at facility.

  STAFFA.R.W. Georgia Power Co. 79/05/02. 1p.
- 7905290035 Forwards revised responses to IE Bulletin 79-08, "Events Relevant to BWRs Identified During TMI Incident." Replaces previous 790425 submittal (mentioned as 790415 in present ltr). Includes response to Item 11.

  WIDNER, W. A. Georgia Power Co. 79/05/09. 16pp.
- R. Periodic operating reports & related correspondence
- 7905150344 Forwards monthly operating rept for Apr 1979. MANRY, M. Georgia Power Co. 79/05/09. 1p.
- ---7905150348 Monthly operating rept for Apr 1979. STANCIL,R. Georgia Power Co. 79/05/01. 11pp.
- S. Reportable occurrences, LERs & related correspondence
- 7905140316 Notifies that LERs 50-366/1979-27 & 50-321/1979-16 have been voided. They were later determined to be not reportable. MANRY.M. Georgia Power Co. 79/03/13. 1p.
- 7905010469 Forwards LERs 79-025/01X-1 & 79-025/01T-0. MANRY, M. Georgia Power Co. 79/04/19. 1p.

- --7905010470 LER 79-025/01X-1 on 790223: torus insp revealed several upper clevis pins of torus vent header support columns displaced Caused by vibration of vent header causing roll pins to be sheared. Design changes issued.

  GREENE, T. V. Georgia Power Co. 79/04/17. 2pp.
- 7905070639 Forwards LER 79-031/03L-0. MANRY.M. Georgia Power Co. 79/05/01. 2pp.
- --7905070646 LER 79-031/03L-0 on 781129: quick start test failed. Sys declared inoperable. Quick start surveillance procedure rewritten & personnel reinstructed. BAXLEY.S.X. Georgia Power Co. 79/05/01. 2pp.
- 7905150465 Forwards LER 79-030/03L-0. MANRY,M. Georgia Power Co. 79/05/04. 1p.
- --7905150467 LER 79-030/03L-0 on 790418: during surveillance on water level instrument 2B21-N024A, limit switch failed to actuate, tripping recirculation pump A on low level. Caused by fouled switch contacts. Contacts cleaned.

  NIX.R.T. Georgia Power Co. 79/05/04. 1p.
- 7905300683 Forwards LER 79-033/03L-0. MANRY.M. Georgia Power Co. 79/05/17. 1p.
- ---7905300688 LER 79-033/03L-0 on 790508:air operators on 2821-F018A & C were improperly installed. Caused by insufficient installation info. Maint procedures revised to assure proper installation. GREENE, T. V. Georgia Power Co. 79/05/17. 2pp.

# DOCKET 50-367 BAILLY GENERATING STATION

- A. Application/construction stage documents & correspondence
- 7905020400 Forwards NUREG-0531, "Investigation & Evaluation of Stress Corrosion Cracking in Piping of LWR Plants" & notice of issuance & availability. W/o encl. VASSALLO, D.B. Assistant Director for Light Water Reactors. 79/03/23. 2pp.
- 7905040316 Summary of 790321 meeting of Mark II owners group in San Jose, CA re intermediate plant program tasks.

  ANDERSON, C. J. Containment Systems Branch. 79/04/13. 150pp.
- G. Adjudicatory correspondence
- 7905240223 Requests that NRC grant hearing on Northern IN Public Svc 790207 petition for extension of CP. Certificate of Svc encl. ANDREWS.W., OLSZANSKI,S.M. Affiliation Unknown. 79/03/27. 3pp.
- G. Inspection reports, IE Bulletins & correspondence
- 7905010258 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/03/23.
- 7905040041 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks." KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/03/26.
- 7905030036 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/04/11.
- 7905010593 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." KEPPLER.J.O. Region 3, Chicago, Office of the Director. 79/04/14.
- 7905040398 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/04/14.
- 7905040568 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/04/14.
- 7905070164 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required.
  KEPPLER, J. C. Region 3, Chicago, Office of the Director. 79/04/14.

- 7905010429 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts." KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/04/16. 18.
- 7905030232 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.

  KEPPLER.J.G. Region 3, Chicago, Office of the Director. 79/04/17.

  1p.
- 7905080502 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl."

  \*KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/04/21.
- 7905240907 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Recirculation Motor Generator Set Resulted in Reactor Power Increase."

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/05/02.
- R. Periodic operating reports & related correspondence
- 7905010534 Forwards well charts for 790404-790411.well levels.Bailly wells w/o recorders.pond levels.pneumatic pressure transducers. & water meter readings for 790411.

  BOHN,R.J. Northern Indiana Public Service Co. 79/04/23. 33pp.
- 7905140308 Forwards well charts for 790411-18,well levels for 790412, 13,17 & 18,Bailly wells w/o recorders for 790418,pond levels for 790418,pendmatic pressure transducers for 790418 & water meter readings for 790418.

  B
- 7905110306 Forwards 790418-25 well charts, 790419-25 well levels, 790425 Bailly wells w/o recorders, 790425 pond levels, 790425 pneumatic pressure transducers, 790425 water meter readings & 790201-0316 rainfall at Flint Lake pump station.
  BOHN, R. J. Northern Indiana Public Service Co. 79/05/04. 19pp.
- 7905220207 Forwards well charts for 790425-790502. Bailly wells w/o recorders, pond levels pneumatic pressure transducers, water meter reading & USOS wells, all for 790502.

  BOHN, R. J. Northern Indiana Public Service Co. 79/05/11. 16pp.
- 7905210277 Forwards "Winter 1979 Guarterly Rept" on ecological monitoring program. SHORB,E.M. Northern Indiana Public Service Co. 79/05/15. 1p.
- --7905210280 "Winter 1979 Quarterly Rept" on ecological monitoring program for Jan-Mar 1979.

  \* Northern Indiana Public Service Co. 79/04/30. 126pp.
- 7905300329 Forwards well charts for 790502-09. Bailly wells w/o recorders pond levels pneumatic pressure transducers & water meter readings for 790509.
  BOHN,R.J. Northern Indiana Public Service Co. 79/05/18. 31pp.

# DOCKET 50-368 ARKANSAS NUCLEAR ONE, UNIT 2

## H. General correspondence

- 7905240955 Responds to 790412 ltr to JM Hendrie re nuclear power plant near Russellville. AR. Outlines steps for license review. Forwards "Transportation of Nuclear Fuel & Waste" & "Disposal of Radioactive Waste." W/o encl. DEYOUNO, R. C. Division of Site Safety & Environmental Analysis. 79/05/07. 2pp.
- --7905240965 Expresses concern re nuclear plants at Russellville.AR. Requests public investigation re safety of facility.Forwards policy statement of Arkansans for Safe Energy.

  BERKY, J. A. Affiliation Unknown. 79/04/12. 2pp.
- J. Insurance & indemnity information
- 7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,185,186,187,188,189,192,193,194,195,197,198,200,201,204,206,207,208,210,212,214,215,&others.
- 7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22.26,29,38,39,44,46.47,49,50,51,52,53,54,55,56,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,91,92,93,94,95 & 96.
  ROBERTS,D.M. Mutual Atomic Energy Liability Underwriters. 79/05/01.



- 7905140489 Forwards Amend 8 to Indemnity Agreement B-65 per 10CFR140 changes, re increase in liability insurance from \$140 million to \$160 million.effective 790501. Supporting documentation encl. SALTZMAN, J. Antitrust & Indemnity Group. 79/05/01. 6pp.
- 7905190167 Forwards executed Amend 8 to Indemnity Agreement B-65. TRIMBLE.D.C. Arkansas Power & Light Co. 79/05/10. 3pp.
- P. Operating license stage documents & correspondence
- 7905070491 Responds to 771205 request. Forwards addl info re fracture toughness & potential for lamellar tearing of steam generator & reactor coolant pump support matl. Oversized encl available in Central Files only.

  WILLIAMS.D.H. Arkansas Power & Light Co. 78/12/19. Spp.
- 7905230840 Requests verification to assure adequacy of onsite distribution of power from offsite circuits. Also requests review of electric power sys to determine if potential exists for violation of General Design Criteria 17. VASSALLO,D.B. Assistant Director for Light Water Reactors. 79/05/02. 8pp.
- 7905250210 Summary of 790425 meeting w/C-E re natural circulation capability for C-E plants.
  THADANI.A.C. Reactor Systems Branch. 79/05/02. 43pp.
- 7905250049 Forwards Amends 42 & 11 to Licenses DPR-51 & NPF-6, respectively, safety evaluation & notice of issuance & availability.

  STOL7. J.F. Light Water Reactors Branch 1. REID, R. W. Operating Reactors Branch 4. 79/05/03. 2pp.
- --7905250055 Amends 42 & 11 to Licenses DPR-51 & NPF-6, respectively, modifying App A & B Tech Specs re mgt organization. REID,R.W. Operating Reactors Branch 4. 79/05/03. 14pp.
- --7905250058 Safety evaluation supporting Amends 42 & 11 to Licenses DPR-51 & NPF-6, respectively.

  \* Operating Reactors Branch 4. 79/05/03. 2pp.
- --7905250065 Notice of issuance & availability of Amends 42 & 11 to Licenses DPR-51 & NPF-6.respectively. REID.R.W. Operating Reactors Branch 4. 79/05/03. 2pp.
- 7905230087 Forwards summary of 790501 meeting w/C-E re natural circulation conditions in C-E operating reactors.
  THADANI.A.C. Reactor Systems Branch. 79/05/09. 1p.
- 7905170265 Forwards proposed radiological Tech Specs changes & Class III amend fee. CAVANAUGH, W. Arkansas Power & Light Co. 79/05/10. 2pp.
- --7905170267 Proposed radiological Tech Spec changes covering engineered safety feature response time, physics tests liquid & gaseous radwaste treatment sys.

  \* Arkansas Power & Light Co. 79/05/10. 56pp.
- 7905300002 Forwards amend to 790417 ltr proposing change to Tech Spec 3.7.11. Seeks to include addl fire barriers in request for temporary relief. Plant can be operated w/o fire dampers in ventilation ducts.

  GAVANAUGH.W. Arkansas Power & Light Co. 79/05/18. 4pp.
- 7905300208 Forwards summary of EDS Nuclear, Inc resolution/documentation of albow flexibility error which existed in versions of PISGL piping analysis computer program from Jan-Oct 1969. Review & reanalysis included all work through Dec 1970. PORTER, F. L. EDS Nuclear, Inc. 79/05/21. 9pp.
- --7905300263 Forwards EDS Nuclear, Inc list of BMRs & piping sys which could have been impacted by deficient computer program. GE has no record of reanalysis for Cooper piping sys. STEPHENS.P.W. General Electric Co., Nuclear Energy Products Div. 79/01/24. 18pp.
- Q. Inspection reports, IE Bulletins & correspondence
- 7905010385 Forwards IE Insp Repts 50-313/79-02 % 50-368/79-02 on 790115-0211 % notice of violation.
  MADBEN.O.L. Region 4, Dallas, Reactor Operations Nuclear Support Branch. 79/03/01. 2pp.
- --7905010391 Notice of violation from insp on 790115-0211.

  \* Region 4, Dallas, Office of the Director. 79/03/01. 1p.

- 7905010395 IE Insp Repts 50-313/79-02 & 50-368/79-02 on 790115-0211. Noncompliance noted:failure to prepare weekly rept of overdue maint. WESTERMAN, T.F. Region 4, Dallas, Reactor Operations Nuclear Support Branch. BOYTER, N.C. Region 4, Dallas, Office of the Director. MADSEN, G.L. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/03/01. 15pp.
- 7905150079 Forwards IE Circular 79-04, "Loose Locking Nut on Limitorque Valve Operators."

  SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/03/16.
- 7905310387 Responds to IE Bulletin 78-12, "Atypical Weld Matl in Reactor Pressure Vessels." Records search initiated & final rept expected from GE by 790813.

  RUETER, D. A. Arkansas Power & Light Co. 79/03/16. 1p.
- 7905010448 Forwards IE Bulletin 78-12B, "Atypical Weld Matl in Reactor Pressure Vessel Welds."
  SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/03/19.
- 7905020441 Forwards IE Circular 79-05, "Moisture Leakage in Stranded Wire Conductors."
  SEYFRIT,K.V. Region 4, Dallas, Office of the Director. 79/03/20.
- 7905020277 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping." SEYFRIT,K.V. Region 4, Dallas, Office of the Director. 79/03/23.
- 7905020419 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks." SEYFRIT,K.V. Region 4, Dallas, Office of the Director. 79/03/26.
- 7905020436 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as the Source of Breathing Air." SEYFRIT,K.V. Region 4, Dallas, Office of the Director. Region 4. Dallas, Office of the Director. 79/03/28.
- 7905140152 Forwards IE Bulletin 79-04, "Incorrect Weights for Swing Check Valves Mfg by Velan Engineering Corp." Licensee action required.
  SEYFRIT.K.V. Region 4, Dallas, Office of the Director. 79/03/30.
- 7905150045 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin."
  SEYFRIT.K.V. Region 4, Dallas, Office of the Director. 79/03/30.
- 7905020325 Responds to 790228 ltr & forwards procedures re obtaining emergency relief from Tech Specs.
  MADSEN. Ø. L. Region 4, Dallas, Reactor Operations Nuclear Support Branch. 79/04/05. 2pp.
- -7905020343 Clarifies response to 781214 notice of violation. Quorum meetings will be held to review items in Safety Review Committee's purview. Voices concern re ability to obtain emergency Tech Spec mods in absence of quorum.
  RUETER, D. A. Arkansas Power & Light Co. 79/02/28. 2pp.
- 7905140088 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." Licensee action required.

  SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/04/11.
- 7905040606 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident." SEYFRIT.K.V. Region 4, Dallas, Office of the Director. 79/04/14.
- 7905070043 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required. SEYFRIT,K.V. Region 4, Dallas, Office of the Director. 79/04/14.
- 7905090096 Forwards suppl to IE Bulletin 79-05A, "Nuclear Incident at SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/04/16.

- 7905030265 Forwards IE Bulletin 79-09. "Failures of GE Type AX-2 Circuit Breaker in Safety-Related Sys " Licensee action required SEYFRIT, K V Region 4. Dallas, Office of the Director 79/04/17.
- 7905080348 Forwards IE Bulletin 79-058. "Nuclear Incident at TMI-Suppl " Applicable ACR8 recommendations & list of IE Bulletins issued in last 12 months encl SEYFRIT.K V Region 4. Dallas. Office of the Director 79/04/21 ip
- 7905290494 Responds to IE Bulletin 79-07 re seismic stress analysis Computer codes specified in Item 1 not used in analysis of safety-related piging TRIMBLE,D C Arkansas Power & Light Co 79/04/24 4pp
- 7903110007 Forwards page 12a, omitted from original responses to IE Bullatin 79-068 TRIMBLE, D C Artansas Power & Light Co 79/04/25 ip
- --7905110010 Forwards responses to IE Bulletin 79-06B re preliminary chronology of TM1-2 To further increase margin of safety, design change is being evaluated for items in Category III & IV
  TRIMBLE.D C Arkansas Power & Light Co 79/04/24 19pp
- R Persodic operating reports & related correspondence
- 7905070490 Forwards "Semiannual Environ Monitoring Rept" for Jul-Dec 1978 TRIMBLE.D C Arkansas Power & Light Co 79/04/30 1p
- --7903070494 "Semiannual Environ Monitoring Rept" for Jul-Dec 1978 \* Artansas Power & Light Co 79/04/30 550pp
- 7903170227 Forwards monthly operating rept for Apr 1979, corrected copy of monthly operating rept for Mar 1979 & LER 79-N/A/99X-O TRIMBLE, D C Arkansas Power & Light Co 79/05/10 2pp
- --7905170232 Monthly operating rept for Apr 1979
  6HIVELY, C N Arkansas Power & Light Co 79/05/09 5pp
- --7905170239 LER 79-N/A/99X-O on 790315 dissel generator i failed to achieve rated voltage & speed Caused by blown fuse in starting circuit for one of two air-starting sciencids LER submitted per Tech Spec 4 8 1 3 SHIVELY.C N Arkansas Power & Light Co 79/05/01 ip
- 8 Reportable occurrences, LERs & related correspondence
- 7905040106 Forwards PNO-79-678
  MADSEN: G L Region 4: Dallas, Reactor Operations Nuclear Support
  79/04/12 1p
  - 'ence Hemo 14 unusual sequence of events
    ad voltage resulting from onsite
    connected, causing second to
    tribution sys
    tors 79/04/12 6pp
- Branch 79/04/13 1p Region 4. Dallas, Reactor Operations Nuclear Support
- 7905010329 Forwards PNO-79-67U,V & W MADSEN.O L Region 4: Dallas, Office of the Director. 79/04/16
- 7905010538 Forwards PNG-79-67X & Y
  MADSEN, Q L Region 4, Dallas, Office of the Director 79/04/18,
- 7905010354 Forwards PNO-79-67Z
  MADSEN, 0 L Region 4. Dallas. Office of the Director 79/04/19

- 7905010367 Forwards PNO-79-67AA, AB, AC & AD.
  HADSEN, O L Region 4, Dallas, Office of the Director. 79/04/24
- 7905030008 Forwards PND-79-67AE
  MADBEN.Q L Region 4, Dallas, Reactor Operations Nuclear Support
  Branch 79/04/25 ip

- 7905150096 Forwards PND-79-67AF, AQ, AH, AI & AJ, re nuclear incident at THI MADSEN, Q L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/04/30 ip
- 7905140172 Forwards LERs 79-026/03L-0.79-027/03L-0 & 79-028/03L-0 TRIMBLE.D C Arkansas Power & Light Co 79/05/01 2pp
- --7903140176 LER 79-026/03L-O on 790323 during review of heatingventilation & air conditioning installation, 32 fire dampers discovered not installed as required Caused by installation GA Fire watch established Dampers to be installed SMIVELY.C N Arkansas Power & Light Co 79/05/01, 1p
- ---7905140182 LER 79-027/03L-O on 790330 high pressure safety injection header relief valve 2PSV-5112 body leaked Cause not reported Pressure setting verified.cap & gap screw gaskets repolaced & ECCS subsystem returned to svc SHIVELY.C N Arkansas Power & Light Co 79/05/01 ip
- ---7905140185 LER 79-028/03L-O on 790403 emergency feedwater pump 2P78 removed from svc Caused by packing leak Pump shaft repacked & returned to svc SHIVELY.C, N Arkansas Power & Light Co 79/05/01. Ip
- 7905240481 Forwards PNO-79-67AK & AL MADSEN.9 L Region 4, Dellas, Fuel Facility & Materials Safety Branch 79/05/02 1p
- 7905150572 Forwards LERs 79-029/03L-0, 79-030/03L-0 & 79-026/03L-1
  TRIMBLE,D C Arkansas Power & Light Co 79/05/09, 1p
- --7905150580 LER 79-029/03L-0 on 790415 during Mode 3 operation, condensate storage tank A dropped below Tech Spec min of 80%. Caused by inability of makeup plants to produce condensate to meet high demand during blowdown testing SHIVELY, C N Arkansas Power & Light Co. 79/05/09 ip
- ---7905150587 LER 79-030/03L-0 on 790421: while investigating ground problem in battery bank 2D02, inverter 2-1/22 switched to alternate source Caused by dc supply opening while attempting to locate 2D02 ground. Supply reestablished SHIVELY. C N Arkansas Power & Light Co 79/05/09. ip
- --- 7905150601 LER 79-026/03L-1 on 781216-2CV-1039-2 failed to operate from control room-rendering pump 2 P7A feed to steam generator 2E248 inoperable Caused by solid state relay actuating 2 CV-1039-2 & sealing in closed command SHIVELY.C N Arkansas Power & Light Co 79/01/19 1p
- 7905220398 Forwards LERs 79-031/03L-0 & 79-032/03L-0 TRIMBLE:D C. Arkansas Power & Light Co. 79/03/17 ip
- ---7905220400 LER 79-031/03L-O on 790418:leak found on charging pump A suction sips at 2-inch coupling to 2P8V4834. Caused by vibration Leak located in heat affected zone of 2-inch well-o-let Pipe section replaced SHIVELY.C.N Artenses Power & Light Co 79/08/17 ip.
- 7905300509 Forwards LER 79-033/01T-0. TRIMBLE, D. C. Arkansas Power & Light Co. 79/05/25 is.
- ---7905300517 LER 79-033/01T-0 on 790514:unisolatable leak discovered an reactor coolant pump 2P32A seal cavity pressure sensing line for 2PT-6006. Gause undetermined. Affected portion of schedule 80 pips replaced w/160 pipe.

  SHIVELY, C N Arkansas Power & Light Co 79/05/25 ip
- DOCKET 50-369 WILLIAM B. MCGUIRE NUCLEAR STATION, UNIT 1

  A Application/construction stage documents & correspondence
- 7905070481 Informs of delay in submitting add1 info ms status of outstanding review matters & evaluation of conformance of plant design w/NRC requirements PARKER, H O Duke Power Co. 79/04/30. ip.

#### Q. Adjudicatory correspondence

- 7705010115 Forwards request for Board notification re nonsafaty-grade aquipment to mitigate transients BCINTOL JF Hearings Division 77/04/02 3100.
- ---7905010156 Board notification staff assessment re nonsafety-grade equipment to mitigate transients VABBALLO, D.B. Assistant Director for Light Water Reactors 79/03/29, 2pp
- ---7903010198 Board notification recent issue on nonsafety-grade
  equipment to mitigate transients More info is required
  TEDEBCO,R L Assistant Director for Reactor Bafety 79/03/16
- 7903290976 Denies motion to reopen safety phases of licensing procedures as sought by Carolina Environ Study Oroup in 790128 patition & opposed by NRC & Duke Power Co 790323 answers.

  LAZO,R H Atomic Safety and Licensing Board Panel 79/04/10 14pp
- 7705100186 Orders issuance of OL to applicant, contingent upon procedural & factual conditions Orders stay of present initial decision until further order after issuance of suppl to BER re any unresolved generic safety issues LUEBKE, E. A. HAND, C. H., LAZO, R. M. Atomic Safety and Licensing Board Panel. 79/04/18 122pp.

## J. Insurance & indemnity information

- 7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,56,57,58,60,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,68,90,91,72,73,74,75 & 76
  ROBERTS.B.M Mutual Atomic Energy Liability Underwriters 79/05/01
- 7903140538 Forwards Amend 2 to Indemnity Agreement B-83 per 10CFR140 changes, re increase in liability insurance from 6140 million to 6160 million, effective 790301 Supporting documentation encl BALTZMAN, J Antitrust & Indemnity Group 79/05/01. 6pp

# O Inspection reports, IE Bulletins & correspondence

- 7905230770 Informs that response to IE Bulletins 78-12 % 78-12A is being prepared by Westinghouse Info being gathered from C-E & Rotterdam reactor vessel manufacturers Util's response will be provided by 791001.
  PARKER. W O Duke Power Co 79/03/16. 1p
- 7905010177 Forwards IC Info Notice 79-06, "Stress Analysis of BaPety-Related Piping"
  O'REILLY, J. P
  Region 2, Atlanta, Office of the Director.
  79/03/23, 2pp
- 7905030307 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks " O'REILLY.J P. Region 2. Atlanta, Office of the Director 79703/26 2pp
- 7903010078 Forwards IE Info Notice 79-08. "Interconnection of Contaminated Sys w/Syc Air Sys Used as Source of Breathing Air."

  O'REILLY, J. P. Region 2. Atlanta, Office of the Director 79/03/28. 2pp
- 7405010350 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin" O'REILLY, P. Region 2, Atlanta, Office of the Director 79/03/30, 2pp
- 7905020408 Ack receipt of IE Insp Rept 50-369/79-13 on 790205-08. No proprietary info PARKER, M. D. Duke Power Co. 79/04/09. ip.
- --7903020412 Forwards IE Insp Rept 50-369/79-13 on 790205-08 No noncompilance noted. LEWIS.R.C. Region 2. Atlanta, Reactor Operations Nuclear Support Brench. 79/03/14 2pp
- --7905020423 IE Insp Rept 50-369/79-13 on 790205-08. No noncompliance noted. Major areas inspected verification of preoperational test procedures & follow-up of previous enforcement matters CDITLE. M. T. DYER. J. A. Region 2. Atlanta. Diffice of the Director CANTRELL. F. B. Region 2. Atlanta, Reactor Operations Nuclear Support Branch 79/03/13 7pp

- 7905020285 Ack receipt of 790411 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 30-369/79-11 Does not consider info proprietary MURPHY, C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/04/11 2pp
- ---7905020301 Responds to NRC 790308 ltr re violation nuted in IE Insp Rept 50-369/79-11 Corrective actions burnt cable was result of molten metal falling on cable after welding PARKER, W O Duke Power Co 79704/11 ip
- ---7903020326 Forwards IE lnsp Rept 50-369/79-11 on 790206-09 & notice of violation MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/03/08 2pp
- --7905020339 Notice of violation from inep on 790206-09
  \* Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/07 ip.
- --7905020352 IE Insp Rept 50-369/79-11 on 790206-09 Noncompliance noted safety-related cable had 1-inch diameter burn hole HARDHICK.T J , BRYANT.J C Region 2, Atlanta, Reactor Construction 3 Engineering Support Branch 79/03/07 App
- 7905290700 Ack receipt of IE Inep Rept 50-369/79-17 on 790226-28 No proprietary info PARKER, U. Duke Power Co 79/04/13 ip
- --7905290707 Forwards IE Insp Rept 50-369/79-17 on 790226-28 No noncompliance noted LEWIS,R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 79/03/21 2pp
- --7905290717 IE Insp Rept 50-369/79-17 on 790226-28 No noncompliance noted Major areas inspected hot functional testing activities & followup on unresolved items CANTRELL,F B. COTTLE,W T Region 2, Atlanta, Office of the Director 79/03/20 4pp
- 7905040176 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/14 10
- 790504038: Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident" O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 1p
- 7905010335 Forwards IE Info Natice 79-10, "Nonconforming Pipe Support Struts."

  O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/16 2pp
- 7905030160 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Bafety-Related Sys " Licensee action required O'REILLY,J P Region 2, Atlanta, Office of the Director 79/04/17 2pp
- 7705020460 Forwards IE Bulletin 77-06A.Revision 1, "Review of Operational Errors & Sys Misalignments Identified During THI Incident " O'REILLY, J. P 77/04/18 2:
- 7905240426 Ad Agrees to b PARKER, W. O
- 7905250173 No 790420 1tr, 50-369/79-2 LEWIS, R C.
- 8 Reportable
- 7905110203 Be design def SCINTO, J.
- 7905150254 F

--7905150262 Deficiency rept SD-369/370-79-01 on 790412 during test of pressurizer power operated relief valves one valve stuck in partially open position Caused by valve plug binding in valve bonnet recess area Configuration will be revised # Dute Power Co 79/04/12 2pp

DOCKET 50-370 WILLIAM B MCGUIRE NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

7905070481 Informs of delay in submitting addl info re status of outstanding review matters & avaluation of conformance of plant dealign w/NRC requirements PARKER.W O Duke Power Co 79/04/30 ip

#### Q Adjudicatory correspondence

- 7905010115 Forwards request for Board notification re nonsafety-grade equipment to mitigate transients SCINTO, JF Hearings Division 79/04/02 31pp
- --7905010155 Board notification staff assessment re nonsafety-grade equipment to mitigate transients
  VASSALLO, D B Assistant Director for Light Water Reactors
  79/07/29 200
- --7905010198 Board notification recent issue on nonsafety-grade equipment to mitigate transients Hore info is required TEDESCO.R L Assistant Director for Reactor Safety 79/03/16
- 7905290574 Denies motion to reopen safety phases of licensing procedures as sought by Carolina Environ Study Group in 790128 petition & opposed by NRC & Duke Power Co 790323 answers LAZO.R M Atomic Safety and Licensing Board Panel 79/04/10 14pp
- 7903100186 Orders issuance of GL to applicant, contingent upon procedural & factual conditions Orders stay of present initial decision until further order after issuance of suppl to SER re any unresolved generic safety issues LUEBKE, E A . HAND. C H . LAZO, R M Atomic Bafety and Licensing Board Panel 79/04/18 122pp

### J Insurance & indemnity information

- 7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22.26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 71, 92, 93, 94, 95 & 96, 808ERTS, D.M. Mutual Atamic Energy Liability Underwriters 79/05/01
- 7905140538 Forwards Amend 2 to Indemnity Agreement B-83 per 10CFR140 changes re increase in liability insurance from \$140 million to \$160 million.effective 790501 Supporting documentation encl
  SALTZHAN.J Antitrust & Indemnity Group 79/05/01 épp.

# @ Inspection reports, IE Bulletins & correspondence

isponse to IE Bullstins 78-12 & 78-12A is ighouse Info being gathered from C-E ael manufacturers Util's response 1001, r Co 79/03/16 ip

- to Notice 79-06, "Stress Analysis of ', Atlanta, Office of the Director.
- Notice 79-07. "Rupture of Radwaste Tanks " '. Atlanta. Office of the Director
- etin 79-068. "Revise of Operational Errors & ied During TMI Incident " . Atlanta. Office of the Director
- etin 79-08, "Events Relevant to Boiling tified During TMI Incident " , Atlanta, Office of the Director.

- 7905010335 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts" O'REILLY,J P Region 2, Atlanta, Office of the Director 79/04/16 2pp
- 7905030160 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys " Licenses action required O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/17 2pp
- 7905020429 Forwards IE Bulletin 79-06A, Revision 1, "Revisw of Operational Errors & Bys Misalignments Identified During THI Incident"

  O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/18 20s
- S Reportable occurrences. LERs & related correspondence
- 7905110203 Board notification Seabrook refueling water storage tank design deficiency.

  8CINTOJ Hearings Division 79/03/29. Sopp.
- 7905150254 Forwards Bignificant Deficiency Rept SD-369-370/79-01 PARKER, W O Duke Power Co 79/04/13 ip.
- ---7905150262 Deficiency rept 8D-369/370-79-01 on 790412-during test of pressurizer power operated relief valves one valve stuck in partially open position Caused by valve plug binding in valve bornet recess area Configuration will be revised \* Duke Power Co 79/04/12 2pp

DOCKET 50-373 LABALLE COUNTY STATION, UNIT 1

- A Application/construction stage documents & correspondence
- 7905040316 Summary of 790321 meeting of Mark II owners group in Ban-Jose CA re intermediate plant program tasks ANDERSON C J Containment Bystoms Branch 79/04/13 150pp
- 7908040260 Requests addi info re soil-structure interaction effect based on elastic haif-space model & finite element model PARR.O D Light Water Reactors Branch S. 79/04/16 4pp
- 7905100258 Summary of 790410 meeting w/Cincinnati Qas & Electric Co.
  Long Island Lighting Co & Commonwealth Edison Co re
  vibratory loads & equipment qualification Presentation mati
  encl
  PELYIER, I A Light Water Reactors Branch 1 79/04/19 15pp
- 7903230538 Notification of 790515-17 meeting w/Cincinnati Oas & Electric Co.Long Island Lighting Go.Commonwealth Edison Co & OE in San Jose, CA to audit NSSB equipment for seismic & other dynamic qualification PELTICR, I A Light Water Reactors Branch 1. 79/04/23. Spp
- 7905070393 Bummarizes reevaluation of equipment qualification for seismic & hydrodynamic loads in response to R8 Boud to B Lee 790223 ltr Supporting info encl DELGEORGE, L. O Commonwealth Edison Co. 79/04/25. 64pp
- 79050404B2 Notifies of intention to develop safety analysis using existing computer codes. Requests addl info. BOLBRIQ.C. W. Commonwealth Edison Co. 79/04/26 ip
- 7903080396 Clarifies status of acquisition of transmission line rights-of-way Necessary property has been acquired for first of two sys. Final offers have been made to acquire remaining parcels.

  DELOEORGE, L. O. Commonwealth Edison Go 77/05/02 ip
- 7705270021 Notification of 770311 meeting w/util in Bethesda. HD to discuss open items on containment sys BOURNIA, A. Light Hater Reactors Branch 3. 77/05/03. 2pp
- 7905140312 Forwards IL EPA request to be removed from distribution list for FBAR & amends, effective as of Amend 46 DELQEORGE, L. C. Commonwealth Edison Go. 79/05/07 2pp.
- 7903300020 Application to use ABME Code Case N-240 to exempt certain piping from hydrostatic testing DELOEDROE, L.O. Commonwealth Edison Co. 79/05/21 3pp

- 790531034: Informs NRC of erosion on portions of makeup & blowdown dater pipeline corridor Plan submitted by Soil Conservation Svc will be implemented.

  REED.C. Commonwealth Edison Co. 79/05/23 2pp.
- F. Bacufity, Medical, emergency & fire protection plans
- 7905010323 Forwards Revision 4 to physical security plan Pian withheld (ref 10CFR2,790)
  REED.C Commonwealth Edison Co 79/04/17 ip
- J. Insurance & Indomnity information
- 7905100163 Endorsament 99 to MAELU Policy HF-22 OERASI T. Nuclear Energy Liability Insurance Association. 79/03/27 16.
- 7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,185,186,187,188,199,192,193,194,195,197,198,200,201,204,206,207,208,210,212,214,213,40,there,QUATTROCHMI.J American Nuclear Insurers 79/05/01.
- 7905070382 Confirms increase in liability limit to \$34,000,000 for golicles MT-22,26,29,38,39,44,46,47,49,80,51,52,53,54,55,56,87,68,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,91,92,93,94,95 & 96
  ROBERTS, D. M. Hutual Atomic Energy Liability Underwriters. 79/05/01.
- 7905340546 Forwards Amend 1 to Indemnity Agreement B-B4 par 10CFR140 changes; re increase in liability insurance from \$140 million to \$160 million; effective 790501 Supporting documentation encl.

  BALTZMAN, J Antitrust & Indemnity Group 79/05/01 App
- K. Utility Final Bafety Analysis Report (FBAR) & amends
- 7905020312 Forwards Amend 45 to FBAR which responds to 34 second round questions.
  REED, C. Commonwealth Edison Co. 79/04/20. 1p.
- --7905020320 Amend 45 to FBAR Oversized charts available in Central Files.

   Commonwealth Edison Co. 79/04/30. 260pp.
- 7905110155 Forwards affidevit for distribution of Amend 45 to FBAR. DELGEOROE: L. C. Commonwealth Edison Co. 79/05/04. 2pp.
- O Inspection reports, IE Bullwtine & correspondence
- 7403030054 Forwards IE Insp Repts 50-373/79-11 & 50-374/79-08 on 740221-23 & notice of violation.
  F10RELLI.O. Region G. Chicago, Reactor Construction & Engineering Support Branch 79/03/15. 2nn.
- ---7903030074 IE Insp Rspts 50-373/79-11 t 50-374/79-08 on 790221-23.

  Noncompliance noted: failure to maintain min bend radius for cables t failure to take measures to assure that max cable gull tensions were not exceeded.

  MARRETT, P. A., NEIBLER, J. H., KNOP, R. C. Region G, Chicago, Office of the Director. 79/03/14. Spp.
- 7903070020 Forwards IE Insp Rept 50-373/79-06 on 790130-31, 0201 to 07-08 to notice of violation. HEIBHMAN,R F. Region 3. Chicago: Reactor Operations Nuclear Bupport Branch. 79/03/19. 2pp
- ---7905070023 Natice of violation from insp on 790130, 0201 & 07-08 Region 3, Chicago, Office of the Director. 79/03/15, 3pp.
- 7903020421 Forwards response to IE Bulletins 78-12 & 78-12A. "Atupical Maid Matl in Reactor Pressure Vessel Welds." REED, C. Commonwealth Edison Co. 79/03/22. 10pp.
- 7903010236 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
  NEFPLER, J. Q. Region 3, Chicago, Office of the Director. 79/03/23.
  15.

- 7905030370 Forwards IE Info Notice 79-07, "Rupture of Radweste Tanks." KEPPLER.J Q. Region 3, Chicago, Office of the Director 79/03/26 is
- 7903030013 Forwards IE Bulletin 79-06, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident "
  KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/11
  18.
- 7903240711 Forwards IE Insp Rept 50-373/79-14 on 790402-03 No noncompliance noted FIORELLI,0 Region 3, Chicago, Reactor Construction & Engineering Support Branch, 79704/11 2pp
- --7903240716 IE Insp Rept 30-373/79-14 on 790402-03 No noncompliance noted. Major areas inspected preservice insp work activities & nondestructive examination data repts.

  HARD, K.D., DANIELBON, D.M. Region 3. Chicago, Office of the Director 79/04/10. 6pp.
- 7903010569 Forwards IE Bulletin 79-06A. "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "
  KEPPLER, J. O. Region 3, Chicago, Office of the Director 79/04/14
  is.
- 7905040334 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "
  KEPPLER, J O. Region 3, Chicago, Office of the Director 79/04/14
- 7905040529 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Mater Power Reactors Identified During TMI Incident " KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/04/14
- ₹905010380 Forwards IE Info Notice 79-10. "Nonconforming Pips Support Etruts." KEPPLER, J Q Region 3, Chicago, Office of the Director 79/04/16 is
- 7903030204 Forwards IE Bulletin 79-09, "Failures of 9E Typs AK-2 . Circuit Breaker in Safety-Related Bys " Licensee action required KEPPLER, J G Region 3. Chicago: Office of the Director 79/04/17 is
- 7905040142 Forwards IE Bulletin 79-058, "Nuclear Incident at TMI-Buppl"
  KEPPLER, J. G. Region G. Chicago, Office of the Director. 79/04/21
- ---7905040170 ACRS recommendations re 790328 incident at TMI. Suggests high priority be placed on development of safety research on behavior of LHRs during anomalous transients a ACRS Advisory Committee on Reactor Sefeguerds 79/04/17.
- ---7905040201 Forwards ACRS recommendations to TMI incident, presented on 790417, FRALEY, R.F. ACRS Advisory Committee on Reactor Safeguards, 79/04/18, 1p.
- --7905040221 In response to NRC 790418 itr, states all 790417 ACRS recommendations apply to all PHRs, but were not intended to require immediate changes. Plant mode should be made after study of effects on overall safety. THI excluded. CARBON, M.X. ACRS Advisory Committee on Reactor Safeguards, 79/04/20. 2ps.
- 7405240633 Forwards responses to IE Bulletin 79-07 requesting info re seismic analysis of safety-related piping Reanalysis indicates mythod of intramodal combination has little affect on pipe stresses & equipment support loads.
  REED, G. Commonwealth Edison Co. 79/04/24. App.
- 790514048B Forwards IE Gircular 79-07, "Unexpected Speed Increase of Reactor Recirculation Motor Generator Set Resulted in Reactor Power Increase." KEPPLER.J.O. Region 3, Chicago, Office of the Director 79/05/02, 16.
- S. Reportable occurrences, LERs & related correspondence

7903300435 Notifies that all super strut Tupe 1202 hangers which were galvanized prior to welding are subj to take defect reported in 790419 itr. Complete insp will be performed on Tupe 1202 hangers DELOEDROE, L. G. Commonwealth Edison Co. 79/05/21. Spp.

1

- DOCKET 50-374 LABALLE COUNTY STATION: UNIT 2
- A. Application/construction stage documents & correspondence
- 7905040316 Summary of 790321 meeting of Mark II owners group in San Jose, CA re intermediate plant program tasks ANDERSON, C J Containment Systems Branch 79/04/13 150pp.
- 7905040260 Requests add1 info re soil-structure interaction effect based on elastic helf-space model & finite element model PARR.O D Light Water Reactors Branch 3 79/04/16 4pp
- 7905100288 Summary of 790410 meeting w/Cincinnati Cas & Electric Co. Long Island Lighting Co & Commonwealth Edison Co re vibratory loads & equipment qualification Presentation matl encl PELTIER, I A Light Water Reactors Branch 1 79/04/19 1Spp
- 7905230558 Notification of 790513-17 meeting w/Cincinnati Qas & Electric Co.Long Island Lighting Co.Commonwealth Edison Co & QE in San Jose, CA to audit NSSB equipment for seismic & other dynamic qualification PELTIER, I A Light Water Reactors Branch 1 79/04/23 3pp.
- 7905070393 Summarizes recyaluation of equipment qualification for seismic & hydrodynamic loads, in response to RS Boud to B Lee 790223 lts Supporting info encil DELOEORGE, L O Commonwealth Edison Co 79/04/25 64pp
- 7905040482 Notifies of intention to develop safety analysis using existing computer codes Requests add1 info 80LBRIG.C W Commonwealth Edison Co 79/04/26 ip
- 7905080396 Clarifies status of atquisition of transmission line rights—of-way. Necessary property has been acquired for first of two sys Final offers have been made to acquire remaining parcels
  DELOEOROE, L. O. Commonwealth Edison Co. 79/03/02 ig.
- 7905290021 Natification of 790511 meeting w/util in Bethesds.MD to discuss open items on containment sys BOURNIA.A Light Water Reactors Branch 3 79/05/Q3 2pp
- 7905140312 Forwards IL EPA request to be removed from distribution list for FSAR & amends.effective as of Amend 46 DELGEORGE.L O Commonwealth Edison Co 79/05/07 2ep.
- 7905300020 Application to use ASME Code Case K-240 to exempt certain piping from hydrostatic testing DELQEORGE, L O Commonwealth Edison Co 79/05/21 3pp
- 7905310361 Informs NRC of erosion on portions of makeup & blowdown water pipeline corridor, Plan submitted by Boil Conservation Svc will be implemented REED.C Commonwealth Edison Co 79/05/23, 2pp
- P. Security, medical, emergency & fire protection plans
- 7905010523 Forwards Revision 4 to physical security plan, Plan withheld (ref 10CFR2 790), REED, C. Commonwealth Edison Co 79/04/17 ip
- J. Insurance & indomnity information

- 7905100163 Endorsement 99 to MAELU Policy MF-22 OERAS:T Nuclear Energy Liability Insurance Association 79/03/27
- 7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,23,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,185,186,187,188,189,192,193,194,195,197,198,200,201,204,204,207,208,210,212,214,215,4 others QUATTROCHHIJ. American Nuclear Insurers. 79,03501 1p.
- 7905140546 Forwards Amend 1 to Indemnity Agreement 8-84 per 10CFR140 changes, re increase in liability insurance from \$140 million to \$160 million, effective 790501 Supporting documentation enci SALTZMAN, J. Antitrust & Indemnity Group 79705/01, App.

- K. Utility Finel Safety Analysis Report (FSAR) & amends
- 7905020312 Forwards Amend 49 to FSAR which responds to 34 second round questions REED.C Gosmonwealth Edison Co 79/04/20 1p
- ---7905020320 Amend 45 to FSAR Oversized charts available in Central Files \* Commonwealth Edison Co 79/04/30 260pp
- 7905110155 Forwards affidavit for distribution of Amend 45 to FBAR DELOEORGE, L O Commonwealth Edison Ca 79/05/04 2pp
- @ Inspection reports, IE Bulletins & correspondence
- 7905030054 Forwards IE Inap Repts 50-373/79-11 & 50-374/79-08 on 790221-23 & notice of violation FIORELLI, Region G, Chicago, Reactor Construction & Engineering Support Branch 79/03/15 2pp
- --7903030061 Notice of violation from insp on 790221-23.
  \* Region G. Chicago, Office of the Director 79/03/14 2pp
- --7905030074 IE Insp Repts 50-373/79-11 & 50-374/79-08 on 790221-23
  Noncompliance noted failure to maintain min bend radius for cables & failure to take measures to essure that max cable pull tensions were not exceeded BARRETT, P A . NEISLER, J H . KNDP, R C Region 3. Chicago, Office of the Director 79/03/14 Spp
- 7905020421 Forwards response to IE Bulletins 78-12 & 78-12A, "Atypical Weld Matl in Reactor Pressure Vessel Welds"
  REED.C Commonwealth Edison Co 79/03/22 10pp
- 7905010236 Forwards IE Info Notice 79-06. "Stress Analysis of Bafety-Related Piping" KEPPLER.J O Region G. Chicago, Office of the Director 79/03/23
- 7905030370 Forwards IE Info Notice 79-07. "Rupture of Radwaste Tenks"
  KEPPLER.J & Region S. Chicago, Office of the Director 79/03/26
- 7905030013 Forwards IE Bulletin 79-06. "Review of Operational Errors & Bys Misalignments Identified During TMI Incident." KEPPLER.J O Region 3. Chicago. Office of the Director 79/04/11
- 7905010369 Forwards IE Bullatin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "
  KEPPLER, J Q Region 3, Chicago, Office of the Director. 79/04/14
- 7903040334 Forwards IE Bulletin 79-068, "Review of Operational Errors & Sys Kisalignments Identified During TMI Incident " KEPPLER.J G. Region 3, Chicago, Office of the Director 79/04/14
- 7905040529 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During THI Incident " KEPPLER, J G Region G, Chicago, Office of the Director. 79/04/14
- 7905010380 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts " KEPPLER, J. G. Ragion 3, Chicago, Office of the Director 79/04/16
- 7905030206 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " Licenses action required KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/04/17 ip.
- 7905040142 Forwards IE Bullstin 79-058, "Nuclear Incident at THI-Suppl"

  KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/21 ip
- ---7905040158 IE Bulletin 79-058, "Nuclear Incident at TMI-Suppl "
  Supporting documentation encl
  Region 3, Chicago, Office of the Director 79/04/21 1299

- -7905040170 ACRS recommendations re 790328 incident at TMI, Suggests high O Adjudicatory correspondence priority be placed on development of safety research on behavior of LWRs during anomalous transients.

  a AGRE Advisory Committee on Reactor Safeguards 79/04/17 7905240959 Forwards status representations.
- --7905040201 Forwards ACRS recommendations re TMI incident presented on 7970417.
  FRALEY,R F ACRB - Advisory Committee on Reactor Safeguards
- ---7905040221 In response to NRC 790418 ltr.states all 790417 ACRS recommendations apply to all PMRs, but were not intended to require immediate changes Plant mode should be made after study of effects on overall safety. TMI excluded CARBON, M X ACRS Advisory Committee on Reactor Safeguards 79/04/20 2pp
- 7905240633 Forwards responses to IE Bulletin 79-07 requesting info reseismic analysis of safety-related piping Reanalysis indicates method of intramodal combination has little effect on pipe stresses & aquipment support loads REED.C Commonwealth Edison Co 79/04/24 4pp.
- 7905140488 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Recirculation Motor Generator Set Resulted in Reactor Power Increase "REPPLERAJO Region 3. Chicago, Office of the Director 79/05/ Region 3. Chicago: Office of the Director 79/05/02 1p.
- 8 Reportable occurrences, LERs & related correspondence
- 7905300495 Notifies that all super strut Type 1202 hangers which were galvanized prior to welding are subj to same defect reported in 790419 itr Complete insp will be performed on Type 1202 hangers
  DELOGORGE, L. O Commonwealth Edison Co 79/05/21. Spp

#### DOCKET SO-375 NUCLEAR EXAMINATION REACTOR

- J. Insurance & indemnity information
- 7905160320 Forwards Amend 15 to Indomnity Agreement 8-13, per 10CFR140 changes:re increase from \$140 million to \$160 million, effective 790501 Bupperting documentation encl BALTZMAN, J. Antitrust & Indomnity Group 79/05/01 5pp
- A Periodic operating reports & related correspondence
- 7905080510 Forwards "L-85 Reactor, Annual Operations for 1978" & "Energy Sys Oroup Coviron Monitoring & Facility Effluent Annual Rept. 1978 " Rockwell International Corp 79/05/04 1p. BRINDLEY, J H
- --7905080513 "L-85 Reactor, Annual Operations for 1978 " SWANSON, V. A. Rockwell International Corp. 79/02/08. 3pp.
- ---7909080517 "Energy Bys Group Environ Monitoring & Facility Effluent Annual Rept. 1978 " HOCRE. J D. Rockwell International Corp. E89-79-7 79/04/30

#### DOCKET 50-374 NORTH COAST NUC PLANT

- A. Application/construction stage documents & correspondence
- 7705(10013) Forwards "Site Safety Evaluation Rept" for early site review of Islote site in Puerto Rico Site is suitable for plant-provided 0.45 g seismic design level is used & gutstanding items in rept are resolved.
  MOORE.V A. Assistant Director for Environmental Projects.
  79/04/27. ip.
- --7905110016 "Site Safety Evaluation Rept" re determination of suitability of Islots site for eventual const of plant by Puerto Rican Mater Resources Authority # Office of Nuclear Reactor Regulation. NUREO-0541 79/04/30.
- 7905150128 Forwards site safety evaluation rept ravism by ACRB. W/D @DC1. BALLARADIR.L Environmental Projects Branch 1 79/04/27 2pp.
- --/905150132 Notice of availability of site safety evaluation rept for facility MALLARD, R. L. Environmental Projects Stanch 1 79/04/27 2pp.

- 7905240939 Forwards status rept.as of 790430 on developments in Puerto Rico concerning facility application AXELRAD, H Lowenstein, Newman, Reis, Axelrad & Toll 79/04/30 ip
- --7905240970 Status rept by Puerto Rico Water Resources Authority refacility application as of 790430 Electric Power Sys will issue rept by late May Certificate of Syc encl.

  AXELRAD.M Lowenstein, Newman, Reis, Azelrad & Toil 79/04/30 3pp
- DOCKET 50-302 WATERFORD GENERATING STATION, UNIT 3
- A Application/construction stage documents & correspondence
- 7905020406 Forwards NUREO-0531, "Investigation & Evaluation of Stress Corrosion Cracking in Piping of LWR Plants" & notice of issuance & availability W/o encl VASSALLO, D B Assistant Director for Light Water Reactors 79/03/23, 2pp
- 7905140516 Forwards summary of major milestones re OL application safety review Review of schedule concludes 810923 is realistic date for issuance of OL BOYD, R S Division of Project Management 79/04/19 Spp
- 7905100112 Requests addl info to complete review of FBAR Complete responses should be provided by 790720 in order to maintain review schedule BAER,R L L Light Water Reactors Branch 4 79/04/26 70pp
- C Utility Environmental Report (ER), amends & correspondence
- 7905230855 Forwards request for addl info to complete environ review Answers should consist of sequentially numbered revisions to anviron rept BALLARD.R L Environmental Projects Branch 1 79/05/03 28pp
- O Adjudicatory correspondence
- 7905290300 Contentions of LA Consumers League Amends original petition Affidavit of L Samuel & Cartificate of Syc encl IRVING.8 M Louisiana Consumer's League, Inc 79/04/04 5pp
- 7705270151 Contentions of Save Our Wetlands, Inc & Oystershell Alliance, Inc Amends original petition Affidavits of N Haskell & B King & Certificate of Svc encl FONTANTA, L Fontana, L JUNES, L Cillespie & Jones 79/04/11
- 7905250340 Notices of appearance on behalf of LA Power & Light Co Certificate of Svc encl TROMBRIDGE OF , YUSPEH A.R Shaw, Pittman, Potts, & Troubridge 79/04/13 4pp
- 7905220037 Notice of appearance on behalf of LA Power & Light Co Certificate of Svc encl. STEVENSON:W M. Monroe & Lemann 79/04/17 Spp
- 7905290049 Suppl to patition to intervene Discusse NRC positions recontentions of Save Dur Hatlands, Inc & Gystershall Alliance, Inc Certificate of Svc enc!

  KCOURREN.H J. , Branch 1, 79/04/25 26pp.
- 7905250541 Discusses 790426 prehearing conference Intervenors' Contentions 2.3.4 & 6 were admitted NRC will file submission re Contentions 5 & 7 by 790801.

  WOLFE,8 J Atomic Bafety and Licensing Board Panel 79/05/09 3pp
- I. Financial information
- 7905070166 Forwards registration statement filed by LA Power & Light Co on 790321 W/o encl.
  BOROCHOFF, I D. Securities & Exchange Commission 79/03/23. 1p
- 7905110260 Forwards "Annual Financial Rept 1978 "
  ABWELL, D L Louisians Fower & Light Co 79/04/30. ip.
- ---7905110262 "Annual Financial Rept 1978 "
  \* Louisiana Power & Light Co 79/03/19 19pp
- K Utility Final Bafety Analysis Report (FBAR) & amends
- 7905170228 Forwards Amend 3 to FSAR
  ASWELL, D. L. Louisiana Power & Light Co. 79/05/10 2pp

- --7905170231 Amend 3 to FSAR ASHELL,D L Louisiana Power & Light Co 79/05/10 500pp
- 7905240590 Certificate of Svc for Amend 3 to FSAR \* Louisiana Power & Light Co 79/05/17. ip
- @ Inspection reports, IE Bulletine & correspondence
- 7905010276 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping" SEYPRIT, K V Region 4, Dalles, Office of the Director 79/03/23
- 7905150541 Forwards IE Insp Rept 50-382/79-03 on 790226-0309 & notice of violation SEIDLE-H C Region 4. Dallas. Reactor Construction & Engineering Support Branch 79/03/28 2pp
- --7905150544 Notice of violation from insp on 790226-0309 # Region 4, Dallas, Office of the Director 79/03/27 2pp
- --7905150550 IE insp Rept 50-382/77-03 on 790226-0309 Noncompliance noted improper mounting of Class IE 4160 volt switchgear & failure to follow approved drawings STEMART,R C. O'ILBERT, L D. MATIN'L E Region 4. Dallas. Office of the Director 79/03/27 9pp
- 7905010461 Forwards IE Bulletin 79-05A: "Nuclear Incident at TMI - Suppl " BEYFRIT.K V, Region 4: Dallas: Office of the Director, 79/04/05 19
- 7905040495 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "
  SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/14 is
- 7905040618 Forwards IE Bulletin 79-08, "Events Relevant to Builing Water Power Reactors Identified During TMI Incident "
  SEYPRIT, K V. Region 4, Dallas, Office of the Director 79/04/14
- 7905070066 Forwards IE Bulletin 79-07. "Seismic Stress Analysis of Safety-Related Piping " Licensee action required.
  BEYFRIT.K V Region 4. Dailas. Office of the Director 79/04/14 tp
- 7905010435 Forward: IE Info Notice 79-10, "Nonconforming Pipe Support Strute" SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/16
- 7905090101 Forwards supp) to IE Bulletin 79-05A. "Nuclear Incident at TMI."

  SEYFRIT.K V. Region 4. Dellas. Office of the Director 79/04/16 ip.
- 7905030274 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Bafety-Related Bys " Licenses action required.

  SEYPRIT.K V, Region 4. Dallas, Office of the Director. 79/04/17 is
- 8 Reportable occurrences, LERs & related correspondence
- 7905030134 Forwards PNO-79-67H, E, J & K.
  SEYFRIT, K V Region 4: Dallas, Office of the Director 79/04/06
  1P.
- 7905030113 Forwards PND-79-67L, M, N & P.
  SEIDLE, W. C Region 4, Dallas, Reactor Construction & Engineering
  Bupport Branch 79/04/09 ip
  - . Reactor Construction & Engineering
    - ractor Construction & Engineering
    - actor Construction & Engineering
    - actor Construction & Engineering

- 79030066 Forwards PND-79-67U & V &EIDLE, W C. Region 4, Dallas, Reactor Construction & Engineering #upport Branck 79/04/16 iP
- 7905030250 Forwards PNO-79-67W SEIDLE: W C Region 4. Dallas, Reactor Construction & Engineering Support Branch 79/04/17 1g
- 7905020524 Forwards PND-79-67AA SEIDLE W C. Region 4. Dallas, Reactor Construction & Engineering Support Branch 79/04/20 1p
- 7905020511 Forwards PNO-79-67AB.AC & AD SEIDLE.W C Region 4. Dallas, Reactor Construction & Engineering Support Branch 79/04/23 ip
- 7903040579 Forwards PNO-79-67AE. SEIDLE,W C Region 4. Dallas, Reactor Construction & Engineering Support Branch 79/04/26 ip
- 790507018B Forwards PNG-79-67AF & AO BEIDLE.H C Region 4. Dallas. Reactor Construction & Engineering Bupport Branch 79/04/27 1p
- 7905310222 Forwards PNO-79-67AH:AI & AJ % BEIDLE,H G Region 4: Dailas: Reactor Construction & Engineering Bupport Branch 79/04/30 ip
- 7905240374 Forwards PNO-79-67AK & AL BEIDLE,W C. Region 4: Dallas, Reactor Construction & Engineering Support Branch 79/05/04 ip
- 7905150264 Forwards Significant Deficiency Rept 11 re switchgear breaker position switch operator defect ASHELL,D L Louisiana Power & Light Co 79/05/10 ip
- --7905150273 Significant Deficiency Rept 11 switchgeer breaker position switch operator defect Switch may become bent due to interference w/circuit breaker New switch operator designed to be more rigid & protected by guide SARATHY.P.K., SANDIFORTH.D., COSTELLO.J Louisiana Power & Light Co 79/05/10 Spp
- 7903130408 Forwards Interim Rept 12 re significant const deficiency ASHELE,D L Louisiana Power & Light Co 79/05/10 1p
- --7905180417 Summarizes 790409 discussion w/RC Stewart Elbow cracking identified in lot W6719 Recall program initiated Six elbows from defective lot found at facility. After testing, defective fittings will be replaced OECRGE, H H Chemetron Corp , Tube Turns Div. 79/04/12 Rpp
- T Hearing transcripts on non-antitrust matters
- 7705140365 Transcript of 770426 hearing in New Orleans.LA Pp 1-111 MOLF:8, JORDAN,M., FOREMAN,H Atomic Safety and Licensing Board Panel. 79/04/26 112pp.
- DOCKET 50-387 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 1

  A. Application/construction stage documents & correspondence
- 7905040314 Summary of 790321 meeting of Mark II owners group in San Jose CA re intermediate plant program tasks. ANDERSON: C J Containment Systems Branch. 79/04/13 150pp
- 7705100224 Notification of 770315-16 meeting w/util at Susquehanna site in PA to discuss const schedule. Agenda encl MINER: S Light Water Reactors Branch 3. 79/04/19 4pp.
- 7903240806 Informs of possible six month delay in DL review schedule from Util MINER, 8. Light Water Reactors Branch 3. 79/05/03 2sp.
- 7905090346 Notifies of plans to replace reactor pressure vessel recirculation nozzle safe-end & thermal sleeves. Mod simed at increasing reliability & protection against interpanular stress corrosion cracking CURTIS.N.W Pennsylvania Power & Light Co. 79/05/04 2pp

- 7905090365 Forwards affidavit of svc for Amend 9 to OL application CURTIG:N N Pennsylvania Power & Light Co. 79/05/07 2pp
- 7905110300 Discusses 781103 deficiency rept re SBE sys standby diesel generator Safety impact to be evaluated & results transmitted by 790528, M/781103 rept CURTIG.N W. Pennsylvania Power & Light Co 79/05/11 2pp
- 7905240574 Lists EPA-approved herbicides used along transmission lines to replace suspended herbicide 2.4.8-T CURTIEN W Pennsylvania Power & Light Co. 79/05/21 1p.
- f. Security, medical, emergency & fire protection plans
- 7905:30794 Forwards request for additinfo re physical security plan to complete review of OL application Encl withheld (ref 10GFR2.790)
  PARR.O D. Light Water Reactors Branch 3 79/04/13 2pp
- O Adjudicatory correspondence
- 770529DIGA Investigation completed re allegations made at 770130 prehearing conference by MK Greasy, Investigation did not substantiate allegations.
  CURTIEN W Pennsylvania Power & Light Co 79/03/29 1p
- 7905240081 Daily transcript of hearings will be idened to intervenors whenever possible, as aid in preparation of case CUTCHIN, J. M Branch 3 79/04/10 2pp.
- 7905240625 Requests info re procedure to make limited appearance at hearing NEMETHY, E Affiliation Unknown 79/04/15 1p
- K Utility Final Safety Analysis Report (FSAR) & amends
- 7905020262 Forwards Amend 9 to application for OL, submitted as Revision 7 to FBAR CURTIS, N W Pennsulvania Power & Light Co 79/04/30 124pp
- 7905130224 Forwards Amend 10 to GL application containing Revision 8 to FBAR Amend withheld (ref 10GFR2.790)
  CURTIB.N.W Pannsylvania Power & Light Co 79/05/11 2pp
- O Inspection reports, IE Bulletins & correspondence
- 7905100428 Forwards IE Insp Rept 50-387/79-07 on 790222 No noncompliance noted CARLBON.R T Region i, Philadelphia, Reactor Construction & Engineering Bupport Branch 79/03/19 2pp.
- ---7905100433 IE Insp Rept 50-387/79-07 on 790222 No nencompliance noted Major areas inspected power generator control complex & areas containing electrical/instrumentation equipment installations KOLTAY/P,B Region 1, Philadelphia, Office of the Director EBNETER. B Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/03/16. 3pp.
- 7905010136 Forwards IE Info Notice 79-06, "Stress Analysis of Bafety-Related Piping." ORIER, B.H Region i, Philadelphia, Office of the Director 79/03/23, ip
- 7905040140 Ack receipt of 790319 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-387/79-03 CARLEON, R. T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/04/06.
- --7903040146 Responds to NRG 790220 ltr re violations noted in IE Insp Rept 50-387/79-03. Corrective actions, revised procedure for field touch-ups & reinspected structural steel members for Pennsylvania Power & Light Co. 79/03/19. 3pp
- --7905040149 Forwards IE Insp Rept 50-387/79-03 on 790130-0202 & natice violation. of violation. GARLBON:R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 79/02/20 2pp.
- ~~7705040133 Notice of violation from insp on 770130-0202 Region 1, Philadelphia, Office of the Director. 79/02/20 Īρ
- --7903040156 IE Insp Rept 80-387/79-03 on 790130-0202 Noncompliance noted failure to control structural steel arc strikes MCBREARTY.R.A., FASAND.A.N. Region 1. Philadelphia, Office of the Director TRIPP.L. Region 1. Philadelphia, Reactor Construction & Engineering Support Branch. 79/02/16, Spp.

- 7905020083 Forwards IE Bulletin 79-06. "Review of Operational Errors & Sys Misalignments Identified During TMI Incident " GRIER.B H Region I. Philadelphia, Office of the Director 79/04/ii ip
- 7905020402 Forwards IE Bulletin 79-07. "Seismic Stress Analysis of Bafety-Related Piping " Licensee action required GRIER. B H Region i. Philadelphia. Office of the Director 79/04/14 ip
- 7903040091 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Bys Misslignments Identified During TMI Incident "QRIER, B H Region 1, Philadelphia, Office of the Director 79/04/14 ip
- 7905040269 Forwards IE Bulletin 79-08. "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident " ORIER.B H Region 1. Philadelphia. Office of the Director 79/04/14 ip
- 7905030093 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " Licensee action required

  Region 1, Philadelphia, Office of the Director 79/04/17. ip
- 7905020314 Forwards IE Bulletin 79-06A:Revision 1, "Revisw of Operational Errors & Sys Misalignments Identified During TMI Incident." Operational Electric Action 1. Philadelphia, Office of the Director 79/04/18 1p
- R Periodic operating reports & related correspondence
- 7905040504 Forwards annual environ rept. "Bound Level Measurements Near Plant Site Const 1978" prepared by Bolt Beranek & Newman CURTIS,N W Pennsylvania Power & Light Co 79/05/01 1p
- --7905040506 "Sound Level Measurements Near Plant Site Const 1978." annual environ rept.const noise progress rept prepared by Bolt Berenek & Newman Inc BARNEB.J D . WOOD, E F Pennsylvania Power & Light Co 79/03/31
- 8 Reportable occurrences, LERs & related correspondence
- 7905030129 Ack receipt of 790323 interim deficiency rept re J-698 solenoid valves.

  CARLBON,R T Region 1: Philadelphia: Reactor Construction & Engineering Support Branch. 79/04/10 19
- --7905030149 Confirms info re potentially reportable deficiency in circle seal Model J-678 solenoid valves w/defective diodes Valves have been removed from installed locations & are in Jobsite warehouse awaiting return to vendor CURTIS,N W Pennsylvania Power & Light Co 79/03/23 2pp
- 7905160424 Forwards corrected page 1 of PLA-352 which includes missing date of 790507
  BARTO,M C Pennsylvania Power & Light Go 79/05/11 2pp
- 7905250421 Updates deficiency rept re Circle Seal Model J-698 solenoid valves Defective valves presently controlled per Bechtel procedure. Final rept to be submitted by 790701.
  CURTIS, N.W. Pennsylvania Power & Light Co. 79/05/22 2pp
- DOCKET 50-388 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 7905040316 Summary of 790321 meeting of Mark II owners group in San Jose, CA re intermediate plant program tasks ANDERSON, C J. Gontainment Systems Branch. 79/04/13 150pp
- 7905100224 Notification of 790515-16 mesting w/util at Busquehanna eite in PA to discuss const schedule. Agenda encl MINER. B. Light Water Reactors Branch 3, 79/04/19 4pp
- 7905240806 Informs of possible six month delay in OL review schedule from util. MINER,S Light Water Reactors Branch 3 79/05/03 2pp
- 7905090346 Notifies of plans to replace reactor pressure vessel recirculation notice safe-end & thermal sleaves Mod aimed at increasing reliability & protection against interganular stress corrosion cracking.
  CURTIS, N. W. Pennsylvania Power & Light Co. 79/05/04. 2pp.

- 7905090365 Forwards affidavit of svc for Amend 9 to OL application CURTIS.N N Pennsylvania Power & Light Co 79/05/07. 2pp
- 7905:10300 Discusses 78:103 deficiency rept to SSE sys standby diesel generator Safety impact to be avaluated & results transmitted by 790525 M/781:03 rept CURTIS,N W Pennsylvania Power & Light Co 79/05/11 29p
- 7905240574 Lists EPA-approved herbicides used along transmission lines to replace suspended herbicide 2.4.5-T CURTIS.N W Pennsylvania Power & Light Co 79/05/21 ip
- F Security, medical, emergency & fire protection plans
- 7905150794 Forwards request for add1 info re physical security plan to complete review of OL application Encl withheld (ref 10CFR2 790)
  PARR.O D Light Water Reactors Branch 3 79/04/13 2pp
- Q Adjudicatory correspondence
- 7905250186 Investigation completed re-allegations made at 790130 preheating conference by MK Creasy Investigation did not substantiate allegations CURTIS:N N Pennsylvania Power & Light Co 79/03/29 1p
- 7905240081 Daily transcript of hearings will be loaned to intervenors whenever possible as aid in preparation of case CUTCHIN, J M Branch 3 79/04/10 2pp
- 7905240625 Requests info re procedure to make limited appearance at hearing MEMETHY.E Affiliation Unknown 79/04/15 ip
- K Utility Final Safety Analysis Report (FSAR) & amends
- 7905020262 Forwards Amend 9 to application for OL, submitted as Revision 7 to FSAR CURTIE.N W Pennsylvania Power & Light Co 79/04/30 124pp
- 7905150224 Forwards Amend 10 to GL application containing Revision 8 to FBAR Amend withheld (ref 10CFR2 790)
  CURTIS-N W Pennsylvania Power & Light Co 79/05/11 2pp
- @ Inspection reports, IE Bulletins & correspondence
- 7905010136 Forwards IE Info Notice 79-06. "Stress Analysis of Bafesty-Related Piping" GRIER, BH Region 1. Philadelphia, Office of the Director 79/03/23 ip
- 7905020085 Forwards IE Bulletin 79-06. "Review of Operational Errors & Sys Misalignments Identified During TMI Incident " ORIER.8 H Region i, Philadelphia, Office of the Diractor 79/04/11 1p
- 7905020402 Forwards IE Bulletin 79-D7, "Seismic Stress Analysis of Safety-Related Piping " Licensee action required ORIER, B H Region I, Philadelphia, Office of the Director 79/04/14 ip
- 7905040091 Forwards IE Bulletin 79-068, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "
  GRIER:B H Region 1, Philadelphia, Office of the Director 79/04/14 1p.
- 7905040269 Forwards IE Bulletin 79-08. "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident "
  ORIER, B.H. Region i, Philadelphia, Office of the Director
  79/04/14 ip
- 7903030093 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Sefety-Related Sys " Licensee action required ORIER, H. Region 1, Philadelphia, Office of the Director. 79/04/17, 1p
- 7903020314 Forwards IE Bulletin 79-06A.Revision i, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident "ORIER, B H. Region 1, Philadelphia, Office of the Director 79/04/18 1p

- R. Periodic operating reports & related correspondence
- 7905040504 Forwards annual environ rept, "Sound Level Measurements Near Plant Bits Const 1978" prepared by Buit Berenek & Newman Inc CURTIS,N W Pennsylvania Power & Light Co 79/05/01 1p
- ---7905040506 "Sound Level Measurements Near Plant Site Const 1978," annual environ reptriconst noise progress rept prepared by Boit Seranek & Newman Inc BARNES, J D . HOUD, E.F. Pennsylvania Power & Light Co. 79/03/31
- 8 Reportable occurrences: LERs & related correspondence
- 7905160424 Forwards corrected page 1 of PLA-352 which includes missing date of 790507

  BARTOH C Pennsylvania Power & Light Co 79/05/11. 2pp.
- 7905250421 Updates deficiency rept re Gircle Seal Model J-698 soleneid valves. Defactive valves presently controlled per Bechtel procedure Final rept to be submitted by 790701 CURTIS.N W Pennsylvania Power & Light Co 79/05/22 2pp.
- DOCKET 50-389 BT LUCIE PLANT, UNIT 2

  Q Adjudicatory correspondence
- 7905240207 Response by util to 790301 ASLAB memo & order re redor release rates:concentrations & healths effects Certificate of Svc encl BAUSER, M.A. Lowenstein, Neuman, Reis, Axelrad & Toll 79/04/03 988
- 7905100402 Notifies new info re fuel blockage model for ECCS is presently being evaluated Review will be forwarded upon completion PATON.W D. Branch 4 79/04/11 1p
- 7905110418 Response to ALAB-309 re radon emissions & de minimus theory from Perkins record Certificate of Buc encl. SCINTO, J F Hearings Division 79/04/11. 45pp
- 7905140519 Response to 790404 brief of Philadelphia Electric Co.P8ELQ & Atlantic City (NJ) Electric Co re de minimus theory.

  Gertificate of SVc encl

  KEPFORD, C R Citizens for Safe Environment 79/04/11. Opp.
- 7905150125 Forwards NRC rept "Inquiry into Allegation of Employee Misconduct by Restricting Investigation to Determine Reliability of Power Grid Serving Bt Lucie " SOHINKI, S. M Branch 3 79/04/11. 1p.
- --7903150130 "Inquiry into Allagation of Employee Misconduct by Restricting Investigation to Determine Reliability of Power Orid Serving Bt Lucie." MCTIERNAN.T J Office of Inspector & Auditor. 78/06/30. 83pp
- 7905100130 Notifies continuance will be needed for preparation of info ra ALAB-537 Vital witness is currently assigned to THI-2, but may return 790301. Present estimate for submittal date is 790615 or later TOURTELLOTTE, J Branch 4. 79/04/12 2pp
- 7905100009 Forwards motion for reconsideration of 790405 ALAB-537 or scheduling of prehearing conference. Explains & exposes . Basis of ASLAB decision re manner of proceeding in captioned matter REIS.H F Lowenstein, Newman, Reis, Axelrad & Yoll 79/04/13 3pp
- --7905104011 Moves for reconsideration of 790405 ALAB-537 or scheduling prehearing conference Refers to accompanying memo containing justifications Certificate of Svc encl REIS.H F. Lowenstein, Newman, Reis. Axeirad & Toil. 79/04/19 339
- --- 7905100019 Supports 790413 motion for reconsideration of ALAB-537 or scheduling prahearing conference. Certificate of Svc encl REIS.HF Lowenstein, Newman. Reis. Axeirad & Toll. 79/04/13 9pp
- 7703240134 Forwards draft Reg Guide 1.XXX, "Lightning Protection for Nuclear Power Plants " W/o encl. PATON,W D. Branch 4, 77/04/17, 1p.

- 7703270289 Motion by intervenors for initiation of discovery procedures k submittal of interrogatories to util re util's electrical grid stability & emergency power sys Certificate of Syc HODDER, M. H. Hadder, M. H. 79/04/17 500
- 7909230035 Notifies that teleon to ABLAB from MH Hodder, counsel for intervenors, had little relationship to recently released ALAB-337 DUFLO.M E Atomic Bafety and Licensing Appeal Panel 79/04/19
- 7905240838 Requests denial of intervenors' 790417 motion to permit discovery Certificate of Svc encl COLL,N A Steel, Hector & Davis 79/04/19, 5pp
- 7905140332 Notifies of consolidation of five intervenor groups re radon existions issue Parties have until 790525 in which to file for summary disposition of the property of 13pp.
- 7909250205 Extends until 790517 time for Commission review of portion of ALAB-537 re steam generator tubes
  CMILK.8 J Office of the Becretary of the Commission 79/05/08
- J Insurance & indemnity information
- 7905970497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,176,179,180,182,183,186,187,188,189,192,193,194,195,197,178,200,201,204,205,207,208,210,212,214,215,8 others American Nuclear Insurers QUATTROCHSIL, J 79/05/01
- 7905070382 Confirms increase in liability limit to \$36,000,000 for policies MF-22,26,29,38,37,44,46,47,49,50,51,52,53,54,55,56,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,00,90,71,92,93,94,93 & 96,87,00,71,72,74,76,77,78,79,80,84,87,00,90,91,92,93,94,93 & 96,87,00,71,92,93,94,93 & 96,87,00,71,92,93,94,93 & 96,87,00,71,92,93,94,93 & 96,87,00,71,92,93,94,93 & 96,87,00,71,92,93,94,93 & 96,87,00,71,92,93,94,93 & 96,87,00,71,92,93,94,93 & 96,87,00,71,92,93,94,93 & 96,87,00,71,92,93,94,93 & 96,87,00,71,92,93,94,93 & 96,87,00,71,92,93,94,93 & 96,87,00,71,92,93,94,93 & 96,87,00,71,92,93,94,93 & 96,87,00,71,92,93,94,93 & 96,87,00,71,92,93,94,93 & 96,87,00,71,92,93,94,93 & 96,87,00,71,92,93,94,93 & 96,87,00,71,92,93,94,93 & 96,87,00,71,92,93,94,93 & 96,87,00,71,92,93,94,93 & 96,87,00,71,92,93,94,93 & 96,87,00,71,92,93,94,93 & 96,87,00,71,92,93,94,93 & 96,87,00,71,92,93,94,93 & 96,87,00,71,92,93,94,93 & 96,87,00,71,92,93,94,93 & 96,87,00,71,92,93,94,93 & 96,87,00,71,92,93,94,93 & 96,87,00,71,92,93,94,93 & 96,87,00,71,92,93,94,93 & 96,87,00,71,92,93,94,93 & 96,87,00,71,92,93,94,93 & 96,87,00,71,92,93,94,93 & 96,87,00,71,92,93,94,93 & 96,87,00,71,92,93,94,93 & 96,87,00,71,92,93,94,93 & 96,87,00,71,92,93,94,93 & 96,87,00,71,92,93,94,93 & 96,87,00,71,92,93,94,93 & 96,87,00,71,92,93,94,93 & 96,87,00,71,92,93,94,93 & 96,87,00,71,92,93,94,93 & 96,87,00,71,92,93,94,93 & 96,87,00,71,92,93,94,93 & 96,87,00,71,92,93 & 96,87,00,71,92,93 & 96,87,00,71,92,93 & 96,87,00,71,92,93 & 96,87,00,71,92,93 & 96,87,00,71,92,93 & 96,87,00,71,92,93 & 96,87,00,71,92,93 & 96,87,00,71,92,93 & 96,87,00,71,92,93 & 96,87,00,71,92,93 & 96,87,00,71,92,93 & 96,87,00,71,92,93 & 96,87,00,71,92,93 & 96,87,00,71,92,93 & 96,87,00,71,92,93 & 96,87,00,71,92,93 & 96,87,00,71,92,93 & 96,87,00,71,92,93 & 96,87,00,71,92,93 & 96,87,10,93 & 96,87,10,93 & 96,87,10,93 & 96,87,10,93 & 96,87,10,93 & 96,87,10,93 & 96,87,10,93 & 96,87,10,93 & 96,87,10,93 & 96,87,10,93 & 96,87,10,93 & 96,87,10,93 & 96,87,10,93 & 96,87,10,93 & 96,87,10,93 & 96,87,10,93 & 96,87,
- 7905100309 Forwards Endorsament 31 to NELIA Policy NF-227 FIELDER: J. Marsh & McLenon, M & M Nuclear Consultants, Inc. Div 79/09/04. 2pp
- 7905100311 Forwards Endorsement 32 to NELIA Policy NF-227 FIELDER.U. Marsh & McLenon, M & M Nuclear Consultants, Inc. Div 79/05/04 2pp
- H Antitrust correspondence
- 7905150232 Forwards add1 info re testimony preparation W/o encl EVANS.D J Anti-Trust Division 79/03/27 ip
- 7705240100 Supplements discovery rulings as result of parties' memos responding to 770209 memo & order Parties may negotiate mod of prehearing schedule First interim rept re progress of discovery will be due 770501
  SHITM
- 7903230622 Responds to 790328 & 790402 motions filed by FL Cities to initiate antitrust hearing, in response to NRC 780727 order Certificate of Byc encl.
  DEMEY.L. Anti-Trust Division. 79/04/17 5pp.
- 7905240853 Joint motion of util & FL Cities for suspension of discovery procedures to permit settlement discussions to be pursued Certificate of evc encl.
  JABLON.R.A., OUTHAN, D. Spiegel & McDiarmid SOUKNIGHT, J. A Lowenstein, Newman, Reis, Axelrad & Toll 79/04/20, 4pp.
- 7905150796 Grants 790420 joint motion by applicant & FL Cities seeking delay in discovery until 790801.
  SMITH, I.W. Atomic Bafety and Licensing Board Panel 79/04/23 ip
- 0. Inspection reports: IE Bulletins & correspondence
- 7903070352 Forwards IE Insp Rept 50-389/79-02 on 790131-0202. No nencompliance noted.
  MMRPHY.G E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch, 79/03/13 2pp.
- ---7903070358 IE Insp Rept 50-389/79-02 on 790131-0202 No noncompliance rugozogo IE Insp Rept 50-389/79-02 on 790131-0202 No no noted. Hajor areas inspected: concrets procedures, specs & records & concrets placement & backfill operations. HARRIS, J. R., BRYANT, J. C., Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/13.

- 7905010235 Forwards IE Insp Rept 50-389/79-03 on 790213-19 No noncompliance noted MAPHY: CE Region 2. Atlanta. Reactor Construction & Engineering Support Branch 79/03/16 2pp
- ---7905010243 IE Insp Rept 50-389/79-03 on 790213-15 No noncompliance noted. Major areas inspected reactor vessel internals procedures: work observation & quality records, equipment storage. & QA records storage ANG. M P , BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/15 3pp
- 7905230137 Forwards IE Insp Rept 50-389/79-04 on 790227-0302 No noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 79/03/21 2pp
- ---7905230153 IE Insp Rept 50-389/79-04 on 790227-0302 No noncompliance noted Hajor areas inspected concrete lab, intake structure, concrete placement, weld repair to containment vessel & site GA audit GA audit
  MRIGHT.R W. GDUGE.H J Region 2. Atlanta. Office of the
  Director HERDT.A R Region 2. Atlanta. Reactor Construction &
  Engineering Support Branch 79/03/20 Epp
- 7905010195 Forwards IE Info Notice 79-06. "Stress Analysis of Region 2, Atlanta, Office of the Director 79/03/23 2pp
- 7705030310 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tants " O'REILLY, J P Region 2. Atlanta, Office of the Director 79/03/26 200
- 7905040212 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Bys Misslignments Identified During TMI Incident "O'REILLY, J P Region 2: Atlanta: Office of the Director 79/04/14 2pp
- 7908040308 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping " Licensee action required O'REILLY, J P Region 2. Atlanta, Office of the Director 79/04/14 10
- 7905040404 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Hater Power Reactors Identified During TMI Incident " O'REILLY UP Region 2, Atlanta, Office of the Director 79/04/14, ip
- 7905010337 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts " O'REILLY, J. P Region 2. Atlanta, Office of the Director 79/04/18 2pp.
- 7905030164 Forwards IE Bulletin 79-09, "Fallures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " Licensee action required O'REILLY, J P 79/04/17 2pp Region 2, Atlanta, Office of the Director 200
- 7905020465 Forwards IE Bulletin 79-06A, Revision i, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"

  D'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/19 268 79/04/18 200
- B Reportable occurrences; LERs & related correspondence
- 7905110203 Board notification Seabrook refueling water storage tank design deficiency BCINTO, J Hearings Division. 79/03/29 30pp
- DOCKET 50-390 WATTS BAR NUCLEAR PLANT, UNIT 1 A. Application/construction stage documents & correspondence
- 7905100220 Notification of 790501-02 meeting w/util in Spring City.TN to review status of plant const in order to make independent estimate of fuel loading date BTAHLE.C R. Light Water Reactors Branch 4. 79/04/25 2pp
- 7905040348 Requests completion dates specified in CPs be extended to Jul 1980 for Unit 1 & Mar 1981 for Unit 2 Factors contributing to delay include ice condenser embedments & installation of large cable tray supports QILLELAND, J E Tennessee Valley Authority 79/04/27. 2pp
- 7905110225 Approval of Teftel 200 as snubber mat! requiring surveillance interval no more stringent than that required for ethylene propylene equipped snubbers.

  OILLELAND: J. E. Tennessee Valley Authority. 79/05/04. 21pp.

- 7905290390 Responds to NRC questions re plant containment sump. Forwards "NPSH Calculations for RHR & Containment Spray Pumps Operating in Recirculation Mode" & "Hodel Study of Plant RHR Sump "OILCELAND. J E Tennessee Valley Authority. 79/05/23 ip
- --7903290393 "NPSH Calculations for RMR & Containment Spray Pumps Operating in Recirculation Hode." Apr 1979 = Tennessee Valley Authority 79/04/30 10pp
- --7905290399 "Model Btudy of RHR Sump " FAIN.T & Tennessee Valley Authority HH28-1-85-101 79/03/31
- J Insurance & indemnity information
- 7905070497 Confirms increased liability limit to \$124,000,000 for golicies NF-1,23,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,185,186,187,188,187,192,193,194,195,197,198,200,201,204,206,207,208,210,212,214,215,&others GUATTROCHHI,J American Nuclear Insurers 79/05/01 ip
- 7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 84, 87, 88, 90, 91, 92, 93, 94, 95 & 96 ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/05/01
- 7905130802 Forwards IE Insp Rept 50-390/79-08 & 80-591/79-05 on 790129-0223.No noncompliance noted MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/03/22 2pp
- ---7905130803 IE Insp Rept 50-590/79-08 & 50-591/79-05 on 790129-0223 No noncompliance noted. Major areas inspected. welding of pressurizer agray pipe. RHR piping, containment spray piping & work on reactor internals COCHRAN. B J Region 3. Chicago. Office of the Director HERDTA R Region 3. Chicago. Reactor Construction & Engineering Support Branch 79/03/21 7pp
- 7905010211 Forwards IE Info Notice 79-06. "Stress Analysis of Safety-Related Piping"
  O'REILLY, J P Region 2. Atlanta. Office of the Director 79703/23 2pp
- 7905010113 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air"

  O'REILLY, J P. Region 2, Atlanta, Office of the Director 79/03/28 200
- 7905010363 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin" O'REILLY.J.P Region 2, Atlanta, Office of the Director 79/03/30 2pp
- 7905030368 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping " Licensee action required O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 3pp
- 7905040233 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "
  7'REILLY, J P Region 2, Atlanta, Office of the Director,
  - ) Forwards IE Bulletin 79-08, "Events Relevant to Boiling wer Reactors Identified During TMI Incident "
    .J P Region 2, Atlanta, Office of the Director
    19.

79-10, "Nonconforming Pipe Support

Office of the Director

lures of QE Type AK-2 icensee action

he Director

7903020479 Forwards IE Bulletin 79-06A, Revision i. "Review of Operational Errors & Bys Misalignments Identified During TMI Incident " O'RELLLY, J P Region 2. Atlanta, Office of the Director 79/04/18 2pp

ξģ

uri.i 数he n 7905010564 Forwards Revisions 2 & 3 to Preservice Baseline & Inservice Insp Program 81-4 4.LO 1.
OILLELAND, J. E. Tennessee Valley Authority. 79/04/24. 1p.

- --7905010567 'Surveillance Instruction.8I-4, 4, 10 1, Preservice Insp & Inservice Insp Program "
  BELEW, O L , ENNIS, E R Tennessee Valley Authority 78/10/25
  30pp
- 7905300253 Submits supplemental response to IE Bulletin 77-07. Original response submitted 750120 Provides add1 info received from manufacturer & describes plans in area of electrical penetrations of the CLLAND. J E Tennessee Valley Authority 79/04/27 5pp
- 8. Reportable occurrences: LERs & related correspondence
- 7905140490 Forwards first interim deficiency rept re defective Phillips self-drill concrete anchors OILLELAND.J E Tennessee Valley Authority 79/04/18 ip
- --790514049: First interim deficiency rept.defective Phillips self-fylll concrete anchors Deficiency reported by manufacturer ITT Phillips Drill Div.Search initiated to locate all anchors supplied in defective lot 
  > Tennessee Valley Authority 79/04/18 ip
- 7905140803 Forwards first interim rept re incorrect enalysis of piping sys over total temp range QILLELAND.J.E \_Tennesses Valley Authority 79/04/19 ip
- --7705140504 First interim rept.incorrect Analysis of piping sys over operating temp range. Util is reanalyzing stressing of all sys.subj to temp below ambient.

  + Tennessee Valley Authority 79/04/19 ip
- 7905010481 Fourth interim rept of status of review of possible unconservative pressurizer relief & safety line blowdown analysis Next rept to be submitted by 790531 Awaiting Hestinghouse review of nozzie loads OILLELAND, J E Tennessee Valley Authority. 79/04/23 1p.
- 7905010518 Forwards final rept on deficiency re omitted heating & ventilating ductwork hangers.
  GILLELAND, J E Tennessee Valley Authority 79/04/23, 1p
- ---7905010519 Final rept re omitted heating & ventilating ductwork hangers failing to provide seismic Category I integrity Design drawings being revised Required add1 hangers will be added \* Tennessee Valley Authority 79/04/23 1p.
- 7905040562 Forwards final deficiency rept re dissel generator relay tachometer failures reported 790130 All overheated diodes replaced & tachometers closely monitored.
  OILLELAND, J. E. Tennessee Valley Authority, 79/04/30 3pp
- 7905110228 Forwards first interim deficiency rept re GA program implementation breakdown GILLELAND, J E Tennessee Valley Authority, 79/05/04, îp.
- --7905110236 First interim deficiency rept on 790504 GA program breakdewn re structural integrity of high density spent fuel storage racks Objective documentary evidence will be obtained from supplier.
  79/05/04, 2pp
- 7905160317 Forwards first deficiency rept re failure of power operated relief valves to meet frequency requirements
  OILLELAND, J E Tennesses Valley Authority, 79/05/08. 1p.
- --7905160331 First interim deficiency rept/power operated relief valves (SIABBRO) do not meet frequency requirements Westinghouse is developing math model to consider valve frequency, which will be incorporated in piping analysis.

  \* Tennessee Valley Authority 79/05/08 1p
- 7905190217 Forwards final deficiency rept re failure of control loop bistables. OILLELAND, J E. Tennessee Valley Authority. 79/05/10. 1p
- --7905190220 Final deficiency reptrontrol loop bistables fail in undesirable position on loss of control power Caused by error in wiring of bistable. Bistable wiring corrected so that bistables will fail open on loss of power.

  Tennesses Valley Authority. 79/09/10, ip
- 7905230381 Provides second interim rept re deficiency in tensile anchor capacities lower than design allowables. Testing of stud anchors still in progress. Next rept to be submitted by 790806
  OILLELAND, J. E Tennessee Valley Authority. 79/05/17 1p

- DOCKET 50-391 WATTS BAR NUCLEAR PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 7905100220 Notification of 790501-02 mesting w/util in Spring City, TN to review status of plant const in order to make independent estimate of fuel loading date.
  BTAHLE, C. R Light Water Reactors Branch 4 79/04/29 2pp.
- 790504034B Requests completion dates specified in CPs be extended to Jul 1980 for Unit 1 & Mar 1981 for Unit 2.Factore contributing to delay include ice condenser embedments & installation of large cable tray supports.

  QILLELAND, J. E. Tennessee Valley Authority 79/04/27 2pp.
- 7905110225 Approval of Tefrel 200 as snubber matl requiring surveillance interval no more stringent than that required for estylene propulens equipped snubbers QII LELAND, J. E. Tennessee Valley Authority 79/05/04 21pp
- 7905290390 Responds to NRC questions re plant containment sump Forwards "NPSH Calculations for RHR & Containment Spray Pumps Operating in Recirculation Mode" & "Model Study of Plant RHR Bump."

  OILLELAND, J E Tennessee Valley Authority 79/05/23. 1p
- --7903290393 "NPSH Calculations for RHR & Containment Spray Pumps Operating in Recirculation Mode," Apr 1979 \* Tennessee Valley Authority 79/04/30 10pp
- --7705279379 "Model Study of RHR Sump " FAIN.T. 0 Tennessee Valley Authority WM28-1-85-101 79/03/31 27pp.
- J. Insurance & indomnity information
- 7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,177,180,182,183,184,181,181,182,172,173,174,175,877,198,200,201,204,206,207,208,210,212,214,215,6 others.

  QUATTRUCHHI, J. American Nuclear Insurers. 79/05/01. ip
- Q Inspection reports, IE Bulletins & correspondence
- 7903130802 Forwards IE Insp Rept 50-390/79-08 & 50-591/79-05 on 790129-0223. No noncompliance noted.

  MURPHY.C.E Region 2. Atlanta, Reactor Construction & Engineering Bupport Branch 79/03/22. 2pp.
- --7905150805 IE Insp Rept 50-590/79-08 & 50-591/79-05 on 790129-0223 No noncompilance noted. Major areas inspected welding of pressurizer spray pipe. RHR piping. containment spray piping & work on reactor internals.
  COCHRAN. B. J. Region G. Chicago, Office of the Director.
  HERDT. A.R. Region G. Chicago, Reactor Construction & Engineering Support Branch. 79/03/21 7pp.
- 7903010211 Forwards IE Info Notice 79-06, "Stress Analysis of Befsty-Related Piping" D'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/03/23, 2pp.
- 7905020D74 Ack receipt of 790402 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-391/79-04.
  MWRPHY.C.E. Region 2. Atlenta: Reactor Construction & Engineering Support Branch. 79/04/12 2pp.
- --7903020097 Forwards IE Insp Rept 50-391/79-04 on 790130-0202 & notice of violation MURPHY.C. E Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 79/03/09 2pp
- --7903020102 Notice of violation from insp on 790130-0202 \* Region 2, Atlanta, Office of the Director, 79/03/08, ip.
- --7905020117 IE Insp Rept 50-391/79-04 on 790130-0202 Noncompliance noted:failure to follow reactor vessel internals procedures. ANO.M.P. Region 2. Atlanta, Office of the Director BRYANT, U.C. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 79/03/08. 4pp.

- 7905040233 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident " O'REILLY, J P Region 2, Atlanta. Office of the Diractor 79/04/14 App
- 7905110365 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident " O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 ip
- 7905010341 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Strute "
  O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/18 10
- 7905030172 Forwards IE Bulletin 79-09. "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " Licensee action required O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/17 2pp
- 7905020479 Forwards IE Bulletin 79-06A, Revision 1. "Review of Operational Errors & Bys Misalignments Identified During THI Incident "O'REILLY, J P Region 2. Atlanta, Office of the Director 79/04/18 2pp
- 7905010364 Forwards Revisions 2 & 3 to Preservice Baseline & Inservice Insp Program SI-4 4 LD 1 OILLELAND, J. E Tennessee Valley Authority 79/04/24 ip
- --7905010367 "Surveillance Instruction, SI-4, 4, 10, 1, Preservice Insp & Inservice Insp Program "
  BELEW, 9 L., ENNIS, E. R. Tennessee Valley Authority 78/10/25
- 7905300253 Submits supplemental response to IE Bulletin 77-07 Original response submitted 780120 Provides add1 info received from manufacturer & describes plans in area of electrical penetrations OILLELAND, J E Tennesses Valley Authority, 79/04/27 5pp
- 8 Reportable occurrences, LERs & related correspondence
- 7905140490 Forwards first interim deficiency rept re defective Phillips self-drill concrete anchors
  OILLELAND, J. E Tennessee Valley Authority 79/04/18. 1p
- --7905140491 First interim deficiency rept defective Phillips self-drill concrete anchors Deficiency reported by manufacturer ITT Phillips Drill Div. Bearch initiated to locate all anchors supplied in defective lot # Tennessee Valley Authority 79/04/18 ip
- 7905140503 Forwards first interim rept re incorrect analysis of piping sys over total temp range OILLELAND, J E Tennessee Valley Authority, 79/04/19 1p
- --7905140504 First interim rept incorrect analysis of piping sys over operating temp range Util is reanalyzing stressing of all sys; sub, to temp below ambient a Tennessee Valley Authority 79/04/19 1p.
- 7905010481 Fourth interim rept unconservative pressurizer re analysis Next rept to be subm Hestinghouse review of norsh OILLELAND.J.E Tennesses Va
- 7905010518 Forwards final rept ventilating ductwork hangers GILLELAND, J E. Tennessee VJ
- ---7905010519 Final rept re omi hangers failing to provide Design drawings being revi added \* Tennettes Valley Author
- 7905040562 Forwards final defitachemeter failures reporter replaced & tachometers closs GILLELAND, U.E. Tennessee Vi

- 7905110228 Forwards first interim deficiency rept re GA program implementation breakdown OLLELAND.J E Tennessee Valley Authority 79/05/04 ip
- --7905110236 First interim deficiency rept on 790504 GA program breekdown re structural integrity of high density spent fuel storage racks Objective documentary evidence will be obtained from supplier

   Tennessee Valley Authority 79/05/04 2pp
- 7905160317 Forwards first deficiency rept re failure of power operated relief valves to meet frequency requirements
  OILLELAND.J & Tennessee Valley Authority 79/05/08 ip
- --7905160331 First interim deficiency rept power operated relief valves (31A88RQ) do not meet frequency requirements Mestinghouse is developing math model to consider valve frequency, which will be incorporated in piping analysis

  Tennessee Valley Authority 79/05/08 ip
- 7905190217 Forwards final deficiency rept re failure of control loop bistables GILLELAND, J E Tennessee Valley Authority 79/05/10 ip
- --7905190220 Final deficiency rept control loop bistables
  fail in undesirable position on loss of control power. Caused
  by error in wiring of bistable Bistable wiring corrected so
  that bistables will fail open on loss of power
  e Tennessee Valley Authority 79/05/10 1p
- 7905230381 Provides second interim rept re deficiency in tensile enchor capacities lower than design allowables Testing of stud anchors still in progress Next rept to be submitted by 790806 GILLELAND. J E Tennessee Valley Authority 79/05/17 1p.
- DOCKET 50-394 CALIFORNIA STATE POLYTECH COLLEGE RES REACTOR

  J Insurance & Indomnity information
- 7905160222 Forwards Amend 7 to Indemnity Agreement E-55.per 10CFR140 changes.re liability insurance increase from \$140 million to \$160 million.effective 790501 Supporting documentation encl SALTZMAN.J Antitrust & Indemnity Group 79/05/01. Spp
- 7903130438 Forwards Amend 7 to Indomnity Agreement E-55, PATTERSON, K.P. California Polytech State Univ 79/05/08 2pp
- DOCKET 50-395 VIROIL C SUMMER NUCLEAR STATION, UNIT 1

  A Application/construction stage documents & correspondence
- 7905020414 Forwards NUREG-0531: "Investigation & Evaluation of Stress Corrosion Cracking in Piping of LWR Plants" & notice of issuance & availability W/o encl VASSALLO, D B Assistant Director for Light Water Reactors. 79/03/23 3pp
- 7905240340 Bummary of 790327 meeting w/util.01lbert Associates.Inc & Westinghouse in Bethesda.MD re second round requests for info on Section 7 O of FSAR TIBBITTG:D L Light Mater Reactors Branch 2 79/04/27. 7pp.
- 7705300692 Forwards Technical Rept 79-8, "Oct-Dec 1978 Seismicity Near Plant." & Techical Rept 79-1. "Seismic Activity Near Plant for Jan-Mar 1979 "
  CREWS.E.H South Carolina Electric & Gas Co. 79/05/25 ip.
- ---7905300696 Technical rept 79-8, "Oct-Dec 1978 Beismicity Near Plant."

  \* South Cerolina Electric & Oas Co 79/03/01 66pp
- ---7908300700 Technical rept 79-1, "Seismic Activity Near Plant, Jan-Mar 1797."
  TALMANE, P. South Carolina, Univ. of 79/05/01 26pp.
- F Security, medical, emergency & fire protection plans

7905230686 Notification of 790430,0501-03 meeting w/util.
Oilbert/Commonwealth Companies & Gage-Babcock in Fairfield
County.SC to visit meterological munitoring installations &
review fire protection program
TIBBITTS: D L Light Water Reactors Branch 2. 79/04/11. 3pp.

- O Adjudicatory correspondence
- 7903290583 Dismisses intervenor B Bursey's Contentions A6 & A7:grants
  NRC 781003 motion for summary desposition
  LINENBERGER.O A. HODPER.F F. SMITH.I.W Atomic Bafety and Licensing
  Board Panel 79/04/09 14pp
- J Insurance & indomnity information
- 7905160193 Forwards Amend 1 to Indemnity Agreement 8-86, per 10CFR140 changes, re liability insurance increase from \$140 million to \$160 million.effective 790501 Supporting documentation encl SALTZMAN, J Antitrust & Indemnity Oroup. 79/05/01. 5pp
  - · ·
- M Antitrust correspondence
- 7905030214 Motion by SC Electric & Qas to strike Central Electric & Qas 790322 brief or in alternative for leave to file reply. Certificate of Svc entl. CONNERT I S., RADER R M Conner, Moore & Corber. 79/03/23 Spp
- 7905030268 Opposition to 790323 8C Electric & Qas motion to etrite Requests right to answer as due process of law or as matter of right from 8C move for summary disposition in two 790327 pleadings Certificate of Svc encl BRAND, W E , HALL, E E Central Electric Power Cooperative, Inc 79/03/27 Bpp
- 7905140137 Response of SC Electric & Oas Co in opposition to Central Electric Power Cooperative, Inc raply brief. Urgas denial of latter's request for further antitrust review Certificate of Svc & supporting documentation and CONNER.T.B , RADER,R M Conner, Moore & Corber 79/04/19 35pp
- 7905150216 Responds to reply brief of Central Electric Power Cooperative NRC should deny patition. Certificate of Svc encl
  CHAMANIA.F D Anti-Trust Division. 79/04/24 7pp
- 7905230743 Forwards corrected page to NRC 790319 response to amended petition of Central Electric Power Cooperative CHANANIA.F.D Anti-Trust Division 79/04/24, 2pp
- @ Inspection reports, IE Bulletine & correspondence
- 7905010466 Forwards IE Insp Rept 50-395/79-07 on 790227-0301 No noncompliance noted.

  LEHIS.R C Region 2. Atlanta: Reactor Operations Nuclear Support Branch 79/03/16. 2pp
- ---7905010467 IE Insp Rept 50-395/79-07 on 790227-0301 No noncompliance noted Major areas inspectedingt interview, preoperational test procedure review & plant bour.

  DONATIT.J , MARTIN.R D, Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/16, 2pp
- 7905010205 Forwards IE Info Notice 79-06. "Stress Analysis of Safety-Related Piping " 0/REILLY,J P. Region 2. Atlanta. Office of the Director 79/03/23 2pp
- 7905030317 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks."
  U'REILLY, J. P. Region 2, Atlanta, Office of the Director
  79703256 is.
- 7905240464 Forwards IE Insp Rept 50-095/79-08 on 790312-15 No noncompliance noted MURPHY.G.E Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 79/04/02. 2pp.
- ~~7903240468 IE Insp Rept 50~375/77~08 on 790312~15 No noncompliance noted. Hajor areas inspected licensee action on previous ineg findings: IE bulletins & circulars, const activities & implementation of 10GFR21 representation of 10GFR22 representation of 10GFR21 representation
- 7905090420 Ack receipt of IE Insp Rept 50-395/79-06 on 790212-14 Ne propriety into JOHNBON, M. C. South Caroline Electric & Oas Co. 79/04/11 13.
- --7905090424 Forwards IE Insp Rept 30-395/79-06 on 790212-14. No noncompliance noted. MURPHY.C.E Region 2: Atlanta: Reactor Construction & Engineering Support Branch 79/03/22 2pp.

- --7905090426 IE Insp Rept 50-395/79-06 on 790212-14 No noncompliance noted Major areas inspected Class A & B storage containment prastressing QA/QC controls quality records & const status LENAHANI J. Region 2. Atlanta. Office of the Director SRYAANI J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 79/03/22 App
- 7905230605 Responds to IE Bulletin 79-04 "Incorrect Weights for Bwing Check Valves Hfg by Velan Engineering Corp " No 3,4 or 6-inch valves are installed or scheduled to be installed GREWS,E H South Carolina Electric & Cas Co 79704/11 1p
- 790503019B Forwards IE Bullstin 79-07, "Beismic Stress Analysis of Bafety-Related Piping " Licensee action required O'REILLY, J P Region 2. Atlanta, Office of the Director 79/04/14 iP
- 7903040225 Forwards IE Bulletin 79-04B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident " O'RETLLY, UP Region 2, Atlanta, Office of the Director 79704/14 2pp.
- 7903040424 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Hater Power Reactors Identified During TMI Incident " O'REILLY, U P Region 2, Atlanta, Office of the Director 79/04/14 ip
- 7905010374 Forwards IE Info Notice 79-10, "Nonconforming Pipe Bupport Btruts " C+REILLY, J P Region 2, Atlanta, Office of the Director 79/04/16 Ip
- 7905030169 Forwards IE Bulletin 79-09, "Failures of QE Type AK-2 Circuit Breaker in Bafety-Related Bys " Licensee action required O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/17 2pp
- 7905020473 Forwards IE Bulletin 79-06A: Revision 1, "Review of Operational Errors & Sys Misslignments Identified During TMI Incident "O'REILLY, J.P. Region 2: Atlanta, Office of the Director 79/04/18, 2pp
- 7903020475 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Minalignments Identified During TMI Incident."
  O'REILLY, U.P. Region 2, Atlanta, Office of the Director, 79704/18, 200
- 7903290105 Ack receipt of IE Insp Rept 50-395/79-09 on 790320-23 No proprietary info.

  JOHNSON, M C Bouth Carolina, Electric & Gas Go 79/04/25 ip
- --7905290112 Forwards IE Insp Rept 50-395/79-09 on 790320-23 No noncompilance noted. MURPNY.C E. Region 2, Atlanta, Office of the Director 79/04/05. 2pp
- --7905290117 IE Insp Rept 50-395/79-09 on 790320-23 No noncompliance noted, Major areas inspected instrumentation of GA procedures, work activities, quality records, electrical cables & terminations work.
  OIHBONB:T D., BRYANT.J C. Region 2, Atlanta, Office of the Director 79/04/04 5pp
- 8. Reportable occurrences, LERs & related correspondence
- 7905100107 informs that injection pumps have been removed from engines, returned to factory inspected per namely established criteria returned to site & reinstabled engines. All injection pumps in good condition MORIARTY, J M. Colt Industries, Inc. 79/03/23. ip
- 7903010483 Interim rept updating status of previously identified items re full penstration butt weld splices in electrical support members.

  JCHNSDN.M C South Carolina Electric & Gas Co. 79/04/23 3pp
- DOGKET 50-396 UNIV. OF VIRGINIA CAVALIER REAGTOR

  O. Inspection reports, IE Bulletins & correspondence
- 790507014B Forwards IE Bulletins 79-05,79-05A & 79-06 re nuclear incident at TMI O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/04/13. 1p

- DOCKET 50-397 MPPSS NUCLEAR PROJECT, UNIT 2
- A Application/construction stage documents & correspondence
- 7905070319 "Air Products & Chemicals, Inc Post LOUA Recombiner Test Summary " \* Washington Public Power Supply System APCI-78-8 78/07/31 175pp
- 7905040316 Summary of 790321 meeting of Mark II owners group in San Jose CA re intermediate plant program tasks ANDERSON.C J Containment Systems Branch 79/04/13 150pp
- 7905150607 Notification of 790419 meeting w/util in Bethesda.MD to discuss Chapter 7 of FSAR LYNCH.M D Light Water Reactors Branch 4 79/04/13 2pp
- 7905010486 Repts on geological studies' status Generic rept expected in Fall 1979 Requests meeting to discuss plans for submitting repts of studies, as well as mechanism for identification & review of studies in Hanford area RENBERGER, D. L. Washington Public Power Bupply System 79/04/27
- 7905240411 Forwards NRC positions on HPPSS-QA-004, "Operational QA Program Description " Response to positions should be submitted by 790601 as amend to original rept HAASS.W P Quality Assurance Branch 79705/01 2pp
- 7705110232 Forwards util responses to round one set four questions from Accident Analysis Branch (Emergency Planning) re OL application RENBERGER, D L Washington Public Power Supply System 79/05/07
- --7905110237 Responses by util to round one set four questions from Accident Analysis Branch (Emergency Planning) re OL application \* Washington Public Power Supply System 79/05/04 53pp
- 7905190117 Proposes course of action to facilitate round two review Outlines most efficient utilization of manpower & resources at NRC, util & contractors Requests NRC to provide generic concerns for similarly-designed plants RENBERGER, D.L. Washington Public Power Supply System 79/05/11
- 7905250537 Forwards util responses to round one, set three questions from Auxiliary Sys Branch Responses will be incorporated into FBAR.
  RENBERGER, D. L. Washington Public Power Supply System 79/05/16
- F Security, medical, emergency & fire protection plans
- 7903230793 Forwards request for add1 info re physical security plan to complete review of application for OL Encl withheld (ref 10CFR2 790)
  VARGA:8 A Light Water Reactors Branch 4 79/04/05 2pp
- 7905080968 Forwards preliminary fire protection questions prior to site visit.

  BARNEB, R D Gage-Babcock Associates, Inc 79/05/02 20pp
- 7905040601 Forwards eafeguards contingency plan Plan withheld (ref 10CFR2 790) RENBERGER, D L. Washington Public Power Supply System 79/05/03
- H General correspondence
- 7905070499 Forwards affidavit & Certificate of Svc for Amend 3 to FSAR RENBERGER, D L Hashington Public Power Supply System 79/05/01 380.
- @ Inspection reports: IE Bulletins & correspondence
- 7905010294 Forwards IE Info Notice 79-06, "Btress Analysis of Bafety-Related Piping " ENGELKEN.R.H Region 4, Delias, Office of the Director. 79/03/23 ip.
- 7905070453 Forwards "Preservice Insp Program Plan, Vols 1 & 2."
  RENBERGER, D. L. Washington Public Power Supply System 79/03/28
- --7905070436 "Preservice Insp Program Plan, Vols 1 & 2 "
  \* Washington Public Power Bupply Bystem 79/01/08, 1200pp.

- 7905010015 Forwards IE Bulletin 79-06A. "Review of Operational Errors & Bys Misalignments Identified During THE Incident "
  ENGELKEN.R H Region 5, San Francisco, Office of the Director 79/04/14
- 7905040516 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Kisalignments Identified During TMI Incident "
  ENGELKEN.R H Region 5, San Francisco, Office of the Director 79/04/14
- 7905040625 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident "
  ENGELKEN.R.H Region 5, San Francisco, Office of the Director ENGELKEN, R. H 79/04/14 1p
- 7905070110 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Páping " Licensee action required ENGELKEN R H Region 5, San Francisco, Office of the Director 79/04/14 ip
- 7905030305 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breater in Safaty-Related Bys " Licensee action required ENGELKEN.R H Region 5, San Francisco. Office of the Directo Region 5, San Francisco, Office of the Director 79/04/17 to
- 7905080378 Forwards IE Bulletin 79-05B, "Muclear Incident at TMI-Bupp1 " ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/04/21. 10
- 7905190076 Responds to NRC 790417 ltr re violations noted in IE insp on 790227-28.0301-02 & 14-16 Corrective actions process instrument pipe & other parts of reactor vessel notice were taped RENBERGER, D. L. Washington Public Power Supply System 79/05/10.
- S Reportable occurrences, LERs & related correspondence
- 7905150069 Forwards PNO-79-67L EMBELKENIR H Region 5, San Francisco, Office of the Director ENGELKEN,R H
- 7905150173 Forwards PNO-79-67R Region 5. San Francisco, Office of the Director, ENGELKEN, R H 79/04/11 10
- 7905040134 Forwards PND-79-678 ENGELKEN:R H Region 5: San Francisco, Office of the Director. 79/04/12 ip

orwards PNO-79-67T. Region 5, San Francisco, Office of the Director.

> 1-79-67U. on 5. San Francisco, Office of the Director.

> > \* of the Director.

ie Director

rector.

· deficiency

704723.

rectar

rector

7905090121 Forwards PND-79-67AH ENGLEKEN.R H Region 5. San Francisco. Office of the Director 79/04/27. ip

7905070034 Forwards PNO-79-67AL.AJ & AK per NRC 790401 ltr transmitting IE Bulletin 79-05 ENGELKEN, R H Region 5, Ban Francisco, Office of the Director 79/04/30

- 7905090009 Forwards rept on deficient basic inflow valves used in standby gas treatment sys. RENBERGER.D.L. Washington Public Power Supply Bystem 79/04/30
- ---7905090073 Deficiency reptipossible failure of basic inflow butterfly valves w/limitorque motor & manual operators Valve may become inoperable due to vibration Ali 19 valves are being repaired per manufacturer's recommendation # Washington Public Power Supply System 79/04/30 1p
- 7905070018 Forwards PNO-79-67AL per NRC 790401 ltr transmitting JE Bulletin 79-05 ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/05/01
- 7905310037 Forwards PND-79-67AM Region 5, San Francisco, Office of the Director ENGELKEN R H 19/05/07. 1p.
- DOCKET 50-400 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 1 A Application/construction stage documents & correspondence
- 7905240459 Notification of 790508 meeting w/util in Bethesda, MD to discuss preparation of environ rept. BAJMA, 8 B. Environmental Projects Branch 2 79/04/27, 1p
- 7903080433 Forwards oversized maps & photo attackments to util 781139 rept on main dam core trench features W/o drawings FLDYD,8 D Carolina Power & Light Co 79/03/08 Spp
- 7905090348 Informs of design change notices re moisture content of backfill against Category I structures & of central core mati for main & auxiliary dam & separating dike Resolution of problem will be documented in FSAR MCDUFFIE.M A Carolina Power & Light Co 79/03/09 2pp
- 7905290380 Responds to Region II 790504 request for criteria used to approve previously placed backfill.

  MCDUFFIE.M A Carolina Power & Light Co 79/05/18 7pp.
- Q Adjudicatory correspondence
- 790525036B Response to intervenors Conservation Council of NC & Hete Environ, Inc 790226 motion to remand to ABLB for further hearings &/or patition to reopen record Certificate of Svc enc i Barthi C. A. Branch 3 79/03/16. 6pp.
- 7905300698 Responds to 790313 request of Kudzu Alliance & H Eddisman re 790213 ALAB-526 affirming 790110 order denying series of petitions filed by intervenors Bupporting documentation & Certificate of Bot encl. IRQUBRIDGE.O F. Shaw: Fittman, Potts, & Trombridgs. 79/03/28.
- 7705230827 NRC motion to accept exhibite into evidence re mat capability of applicant to comet & operate proposed facility Cartificate of Svc encl. BARTH C.A Branch 3 77/03/30. 4pp
- 7905010115 Forwards request for Board notification re noneafety-frace equipment to mitigate transients
  8CINTO.JF Hearings Division. 79/04/02 Sipp
- ---7903010156 Board notification staff assessment re nonsafety-grafs equipment to mitigate transients. VASSALLO, D. B. Assistant Director for Light Water Reactors 79/03/29. 2pp.
- --- 7903010198 Board notification recent issue on nonsafety-grade equipment to mitigate transients. More into is required. TEDEBCO, R L. Assistant Director for Reactor Safety. 79/03/14 Зрр.
- 7905080232 Applicant has no objection to NRC 790330 motion to accept into evidence Exhibits 12,13,14,15,19 & 20 from recent proceedings. Certificate of Syc encl., TROMBRIDGE, G.F. Shaw, Pittman, Potts, & Trowbridge. 79/04/04. 34;

rector.

- 7905250093 Forwards 790119 Press Release 79-19 re issuance of NRC policy statement on Reactor Bafety Study.its review by Lewis panel & HASH-1400 use survey BARTH.6 A. Branch 3 79/04/04 1p.
- 7905070216 Informs ABLB of review of natl security info re sabotage of spent nuclear fuel Forwards transmittal memo NRC assessment of eignificance of info to be forwarded when available BARTH C A Branch 3 79/04/05 2pp
- 7905220443 Forwards draft memo discussing aspects of accumulator delivery identified in NRC studies of ECCS performance characteristics NRC does not consider issue relevant to proceeding BARTH.C A Branch 3 79/04/05 5pp
- 7908240703 Forwards memo re behavior of iodine during postulated steam generator tube rupture accidents
  BARTH.C A Branch 3 79/04/05 ip
- 7905030132 Forwards NRC 781211 survey re use of WASH-1400 in licensing process
  BARTIN C A Brench 3. 79/04/10 90pp
- 7903110418 Response to ALAB-509 re radon emissions & de minimus theory from Perkins record Certificate of Svc encl BCINTO, J. F Hearings Division 79/04/11 45pp.
- 7905140519 Response to 790404 brief of Philadelphia Electric Co.PSE&G & Atlantic City (NJ) Electric Co re de minimus theory Certificate of Svc encl.

  KEPPORD, C. R. Citizens for Safa Environment 79/04/11 Spp.
- 7905150562 Forwards 790330 motion All requested exhibits mentioned in motion were submitted during Releigh, NC hearing, which respondent attended H/o encl RELB, E J Branch 3 79/04/13 ip
- 7908140221 Forwards applicant's transcript corrections & applicant's proposed findings of fact & conclusions of law in the form of supplemental initial decision Certificate of Svc encl TROWHRIDGE OF Shaw, Pittman, Potts & Trowbridge 79/04/17 Spp
- --7905140255 Lists corrections to be made in transcripts of evidentiary hearing conducted on 790227-0302 & 790306-08 in Releigh.NC D'NEILL, J.H. Shaw, Pittman, Potts, & Trowbridge 79/04/17. 3pp
- --7905140261 Proposed findings of fact % conclusion of law in form of supplemental initial decision (CP). List of exhibits encl TROUBRIDGE, G. F., G'NEILL, J. H. Shaw, Pittman, Potts. & Trowbridge 79/04/17. 54pp
- 7905270078 Cites evident error in proposed findings of fact of Carolina Power & Light Co counsel:no statement allowed by Kudzu Alliance or other parties Requests more participation be allowed EDDLEMAN.W. Kudzu Alliance 79/04/21. 1p
- 7905140332 Notifies of consolidation of five intervenor groups re radon emissions issue.Parties have until 790525 in which to file for summary disposition DUFLO.ME Atomic Bafety and Licensing Appeal Panel 79/04/25, 1300.
- 7903240821 Comments on ASLB findings re util operating record Suggests Board condition facility OLs in light of util operating problems.
  EDDLEMAN.W. Affiliation Unknown. 79/04/27. 2pp.
- 7905250165 Summary of 790502 Affirmation Session 79-10 in Weshington, DC re SECY-A-79-20 motion to reopen hearings in Shearon Harris proceeding & SECY-79-16A. Kranish FOIA Appeal 78-A-20. CHILK, B. J. Office of the Secretary of the Commission. 79/05/04 to.
- 7905250362 Informs parties of possibility of taking official notice retest for viscosity. Objections to ASLB procedure must be filed within ten days. Bupporting documentation & Certificate of Svc anci.
  SMITH I.W. Atomic Bafety and Licensing Board Panel 79/05/10. 3pp.
- 790501016B Forwards IE Info Notice 79-06, "Stress Analysis of Bafety-Related Piping."
  D'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/03/23 2PP.
- 7905030294 Forwards IE Info Notice 79-07, "Rupture of Redwaste Tanks." D'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/03/26. 2pp.

- 7905040163 Forwards IE Bulletin 79-068, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident "
  O'REILLY, J P Region 2, Atlants, Office of the Director 79/04/14 2pp
- 7705040281 Forwards IE Builstin 79-07. "Seismic Stress Analyusis of Safety-Related Piping " Licensee action required O'REILLY.J P Region 2. Atlanta. Office of the Director 79/04/14 io
- 7905040329 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident "
  O'REILLY, J P Region 2, Atlanta, Office of the Director
  79/04/14 1p
- 7905010324 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts"
  0'REILLY, J P. Region 2, Atlanta, Office of the Director 79/04/18 2pp
- 7905010324 Ferwards IE Info Notice 79-10. "Nonconforming Pipe Support Struts " O'REILLY.J P Region 2. Atlanta. Office of the Director 79/04/16 2pp
- 7905030141 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " Licensee action required O'REILLY.J P Region 2. Atlanta, Office of the Director 79/04/17 2pp
- 7905080325 Ack receipt of 790406 ltr informing NRC of steps taken to correct-violations noted in IE Insp Repts 50-400/79-02. 50-401/79-02 & 50-403/79-01 W 50-403/79-01 W Factor Construction & Engineering Support Branch 79/04/17 ip
- --79050B0330 Responds to NRC 790227 ltr re violations noted in IE Insp Rapts 50-400/79-02,50-401/79-02.50-402/79-01 & 50-403/79-01 Corrective actions appropriate personnel instructed in document close-out procedures HOWE.P W Carolina Power & Light Co 79/04/06 Spp
- 7905020373 Forwards IE Bulletin 79-06A.Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident" O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/04/18 2pp
- 7905250015 Ack receipt of IE Insp Repts 50-400/79-06.50-401/79-06. 50-402/79-05 & 50-403/79-05 on 790402-05 No proprietary info. HOWE.P.W Carolina Power & Light Co 79/04/26 2pp
- --7905250017 Forwards IE Insp Repts 50-400/79-06.50-401/79-06. 50-402/79-05 & 50-403/79-05 on 790402-05 No noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 79/04/19.
- --7905250020 IE Insp Repts 50-400/79-06:50-401/79-06:50-402/79-05 & 50-403/79-05 on 790402-05 No noncompliance noted M. areas inspected project status.const contract revilicenses action on previous insp findings BRADLEY,R D Region 2, Atlanta, Office: HERDTAR, Region 2, Atlanta, Reactor (Engineering Support Branch 79/04/19 Sp.
- R Periodic operating reports & related correspond
- 7905070475 Forwards "Seismic Monitoring Program,Fi 770930-790331. MCDUFFIE.H A Caroline Power & Light Co 79/04
- ---7905070480 "Seismic Monitoring Program:First Da' \* Carolina Power & Light Co. 79/04/30. Spp.
- B. Reportable occurrences, LERs & related correspo
- 7905140419 Informs that during 781027 site auditinspectors notified of potential reportable its containment water proofing membrane leakage Report yet determined. Final decision by 781201. CHIANGI.N J. Carolina Power & Light Co. 78/11
- 7705110203 Board notification Seabrook refueling design deficiency RCINTO, J. Hearings Division 79/03/29 30pp

- DOCKET 50-401 SHEARON HARRIS NUCLEAR POHER PLANT, UNIT 2

  A Application/construction stage documents & correspondence
- 7905240459 Notification of 790508 meeting w/util in Bethesda.MD to discuss preparation of environ rept BAJWA,8 8 Environmental Projects Branch 2 79/04/27 1p
- 7905080453 Forwards oversized maps & photo attachments to util 781129 rept on main dam core trench features. W/o drawings FLGYD,8 D Garolina Power & Light Go 79/05/08 5pp
- 790509034B Informs of design change notices re moisture content of bactfill against Category I structures & of central core mati for main & auxiliary dam & separating dite Resolution of problem will be documented in FSAR MCDUFFIE.M A Carolina Power & Light Co 79/05/09 2pp
- 7905290360 Responds to Region II 790504 request for criteria used to approve previously placed backfill MCDUFFIE:M A Carolina Power & Light Co 79/05/18 7pp

## O Adjudicatory correspondence

- 7905250369 Response to intervenors Conservation Council of NC & Wake Environ. Inc 790226 motion to remand to ASLB for further hearings &/or patition to reopen record Certificate of Svc and BARTH. C A Branch 3 79/03/14 6pp
- 7905300698 Responds to 790313 request of Kudzu Alliance & W Eddleman re 790213 ALAB-526 affirming 790110 order denying series of patitions filed by intervanors Supporting documentation & Certificate of Svc encl TROWERIDGE, O F Shaw, Pittman, Potts, & Trowbridge 79/08/21.
- 7905230827 NRC motion to accept exhibits into evidence re mgt capability of applicant to const & operate proposed facility Certificate of Svc encl BARTH.G A Branch 3 79/03/30 4pp
- 7905010115 Forwards request for Board notification re nonsafety-grade equipment to mitigate transients.

  8CINTO.J F Hearings Division 79/04/02 3ipp.
- ---7705010136 Board notification staff assessment re nonsafety-grade equipment to mitigate transients VASBALLO.b B Assistant Director for Light Water Reactors, 79/03/29 2pp
- ---7705010198 Board notification recent issue on nonsafety-grade
  equipment to mitigate transients More info is required
  TEDERCO,R L. Assistant Director for Reactor Safety 79/03/16
- 7905080232 Applicant has no objection to NRC 790330 motion to accept into evidence Ethibits 12:13:14:15:19 % 20 from recent proceedings. Certificate of Svc encl TROWERIDGE. O F. Shaw, Pittman, Potts, & Trowbridge 79/04/04. 3pp
- 7905250093 forwards 790119 Press Release 79-19 re issuance of NRC policy statement on Reactor Safety Study, its review by Lewis panel & MASH-1400 use survey.

  BARTH.C A Branch 3. 79704/04. 1p
- 7905070216 Informs ABLB of review of natl security info re sabotage of spent nuclear fuel Forwards transmitted memo. NRC assessment of significance of info to be forwarded when available BARTH.C.A Branch 2, 79/04/05 2pp
- 7705220443 Forwards draft memo discussing aspects of accumulator delivery identified in NRC studies of ECCS performance characteristics NRC does not consider issue relevant to proceeding.

  BARTH, C. A. Branch 3, 79/04/05 5pp.

The state of the s

- 7905240703 Forwards memo re behavior of indine during postulated steam generator tube rupture accidents
  BARTH.C.A. Branch 3. 79/04/03, 1p.
- 7905030152 Forwards NRC 781211 survey re use of MASH-1400 in licensing process
  BARTH/C A Branch 3. 79/04/10 90pp
- 770511Q418 Response to ALAB-507 re radon emissions & de minimus theory from Perkins record Certificate of Svc encl. SCINTO.U.F. Hearings Division 77/04/11 45pp.

- 7905140519 Response to 790404 brief of Philadelphia Electric Co.PSELG & Atlantic City (NJ) Electric Co re de minimus theory Certificate of Svc encl KEPFORD.C R Citizens for Safe Environment 79/04/11 Spp.
- 7905150562 Forwards 790930 motion All requested exhibits mentioned in motion were submitted during Raleigh.NC hearing.which respondent attended W/o encl.
  REIS.E J Branch 3 79/04/13 1p
- 7905140221 Forwards applicant's transcript corrections & applicant's proposed findings of fact & conclusions of law in the form of supplemental initial decision Certificate of Syc encl (ROMBRIDGE, OF Shaw, Pittman, Potts, & Troubridge 79/04/17 3pp
- --7905140255 Lists corrections to be made in transcripts of evidentlary hearing conducted on 790227-0302 & 790306-08 in Raleigh.NC O'NEILL.J H Shaw, Pittman, Potts, & Trowbridge 79/04/17 3pp
- --7905140261 Proposed findings of fact & conclusion of law in form of supplemental initial decision (CP) List of exhibits encl TROMBRIDGE.9 F, O'NEILL.JH Shaw, Pittman, Potts, & Trowbridge 79/04/17 54pp
- 7905140332 Notifies of consolidation of five intervenor groups to Fafon amissions issue Parties have until 790525 in which to file for summary disposition DUFLO, H E Atomic Safety and Licensing Appeal Panel 79/04/25 13pp
- 7905240821 Comments on ASLB findings re util operating record Suggests
  Board condition facility OLs in light of util operating
  problems
  EDDLEMAN. W Affiliation Unknown 79/04/27 2pp
- 7705250165 Summary of 770502 Affirmation Session 77-10 in Washington.DC rs SECY-A-79-20 motion to reopen hearings in Shearon Harris proceeding & SECY-79-16A, Kranish FOIA Appeal 78-A-20 CHILK:8 J. Office of the Secretary of the Commission 79/03/04
- 7905230362 informs parties of possibility of taking official notice retest for viscosity Objections to ASLB procedure must be filed within ten days Supporting documentation & Certificate of Swc encl
  SMITH, I W Atomic Safety and Licensing Board Panel 79/05/10 Opp
- Q Inspection reports. IE Bulletins & correspondence
- 790501016B Forwards IE Info Notice 79-06, "Btress Analysis of Bafety-Related Piping" O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/23, 2pp
- 7905030274 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks \* O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/26 2ps
- 7905040169 Forwards IE Bulletin 79-04B, "Review of Operational Errors & Sys Misslignments Identified During THI Incident " O'REILLV.J P Region 2, Atlanta, Office of the Director, 79/04/14. Zpp
- 7905040281 Forwards IE Bulletin 79-07, "Beismic Stress Analyusis of Safety-Related Piping " Licenses action required O'REILLY.J.P Region 2, Atlanta, Office of the Director. 79/04/14, 1p
- 7905040329 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident " O'REILLY, J. P Region 2, Atlanta, Office of the Director 79/04/14. Ip
- 7903010324 Forwards IE Info Notice 79-10, "Nonconforming Pige Support Struts."

  O'REILLY-J P Region 2, Atlanta: Office of the Director.

  79/04/16 2pp
- 7903030141 Forwards IE Bullatin 79-09, "Failures of GE Tggs AK-2 Circuit Breaker in Safety-Related Bys." Licensee action required O'REILLY.J P. Region 2, Atlanta, Office of the Director 79/04/17. 1p.
- 7905080325 Ack receipt of 79040A itr informing NRC of steps taken to correct violations moted in IE Insp Repts 50-400/79-02. 50-401/79-02. 50-402/79-01 & 50-403/79-01. MURPHY.C.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 79/04/17. 1p.

- 7903020373 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During THI Incident " U'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/18 2np
- 7705250015 Ack receipt of IE Insp Repts 50-400/79-06, 50-401/79-06, 50-402/79-05 & 50-403/79-05 on 790402-05. No proprietary info HOME, P W Carolina Power & Light Co 79/04/26 2pp
- --7905230017 Forwards IE Insp Repts 50-400/79-06, 50-401/79-06, 50-402/79-05 & 50-403/79-05 on 790402-09 No noncompliance noted MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/19 Zoo
- --7905250020 IE Insp Repts 50-400/79-06.50-401/79-06.50-402/79-05 & 50-403/79-05 on 790402-05 No noncompliance noted Major areas inspected project status, const contract review & licensee action on previous insp findings BRADLEY, RD Region 2. Atlanta, Office of the Director HERDTAR Region 2. Atlanta, Reactor Construction & Engindering Support Branch 79/04/19 5pp
- R Periodic operating reports & related correspondence
- 7905070475 Forwards "Seismic Monitoring Program,First Data Rept," 770930-790331 HCDUFFIE,M A Carolina Power & Light Co. 79/04/30 ip
- --7905070480 "Beismic Monitoring Program, First Data Rept." 770930-790331
  \* Carolina Power & Light Co. 79/04/30 8pp
- S Reportable, occurrences, LERs & related correspondence
- 7905140419 Informs that during 781027 site audit of const activities, implectors notified of potential reportable item recontainment water proofing membrane leakage Reportability not yet determined Final decision by 781201 CHTANGI,N J. Carolina Power & Light Co 78/11/22. ip
- 7905110203 Board notification Seabrook refueling water storage tank design deficiency SciNTO.J Hearings Division. 79/03/29. 30pp
- BOCKET 50-402 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 3

  A Application/construction stage documents & correspondence
- 7705240459 Notification of 770508 meeting w/util in Bethesda.MD to discuss preparation of environ rept BAJWA.B S. Environmental Projects Branch 2 77/04/27. ip
- 7903080433 Forwards oversized maps & photo attachments to util 781129 rept on main dam core trench features W/o drawings FCDYD.8 D. Garolina Power & Light Co. 79/05/08 Spp
- 7905070348 Informs of design change notices re moisture content of backfill against Category I structures & of central core mat1 for main & auxiliary dam & separating dike Resolution of problem will be documented in FBAR MCDUFFIE, M.A. Carolina Power & Light Co 79/05/09 2pp
- 7705270380 Responds to Region 1I 770504 request for criteria used to approve previously placed backfill MCDUFFIE/H A. Carolina Power & Light Co. 77/05/18. 7pp.
- 4. Adjudicatory correspondence
- 7905250368 Response to intervenors Conservation Council of NC & Wake Environ. Inc 790226 motion to remend to ASLB for further hearings &/or petition to reopen record. Certificate of Svc encl.

  BARTH.C A Branch 3. 79/03/16 App.
- 7903300698 Responds to 790313 request of Kudzu Alliance & W Eddleman re 790213 ALAB-526 affirming 790110 order denying series of patitions filed by intervenors. Supporting documentation & Cartificate of Syc encl.
  TROMBRIDGE, O. F. Bhaw, Pittman, Potts, & Trowbridge. 79/03/21, 11pp.
- 7903230829 NRC motion to accept exhibits into evidence re mgt capability of applicant to const & operate proposed facility. Certificate of Syc encl.
  BARTHY. G. A. Branch 3, 79/03/30 4pp.

- --79030B0330 Responds to NRC 790227 ltr re violations noted in IE Insp Repts 30-400/79-02, 50-401/79-02, 30-402/79-01 & 50-403/79-01 Corrective actions appropriate personnel instructed in document close-out procedures HOHE,P W Carolina Power & Light Co 79/04/06 3pp
- 79050i0115 Farwards request for Board notification re nonca<sup>2</sup>ety-grade equipment to mitigate transients
  SCINTO, J F Hearings Division 79/04/02 3ipp
- ---7903010156 Board notification staff assessment re nonsafety-grade Rquipment to mitigate transients VASSALLO.D B Assistant Director for Light Water Reactors 79703/29 2pp
- --7905010199 Board notification recent issue on nonsafety-grade equipment to mitigate transients More info is required TEDESCO, R. L. Assistant Director for Reactor Safety 79/03/16
- 7905080232 Applicant has no objection to NRC 790330 motion to accept into evidence Exhibits 12:13:14:15:19 & 20 from recent proceedings Certificate of Svc encl TROMBRIDGE, G F Shaw, Pittman, Potts. & Trowbridge 79/04/04 3pp
- 7903250093 Forwards 790117 Press Release 79-19 re issuance of NRC policy statement on Reactor Safety Study, its raview by Lewis panel & WASH-1400 use survey BARTH.C A. Branch 3 79/04/04 1p
- 7905070216 Informs ASLB of review of natl security info re sabotage of spent nuclear fuel Forwards transmittal memo NRC assessment of significance of info to be forwarded when available BARTH, C. A. Branch 3 79/04/05 2pp
- 7705220443 Forwards draft memo discussing aspects of accumulator delivery identified in NRC studies of ECCS performance characteristics NRC does not consider issue relevant to proceeding BARTH.C A Branch 3 77/04/05 5pp
- 7903240703 Forwards memo re behavior of iodine during postulated steam generator tube rupture accidents
  BARTH.C A Branch 3 79/04/05 ip.
- 7905030152 Forwards NRC 781211 survey re use of WASH-1400 in licensing process
  BARTH, C. A. Branch 3 79/04/10 90pp
- 7905110418 Response to ALAB-509 re radon emissions & de minimus theory from Perkins record Certificate of Svc encl BCINTO.J F Hearings Division 79/04/11 45pp
- 7903140319 Response to 790404 brief of Philadelphia Electric Co.PSE&O & Atlantic City (NJ) Electric Co re de minimus theory Gertificate of Evc encl KEPFORD.C.R Citizens for Safe Environment. 79/04/11 Spp
- 7903130562 Forwards 790330 motion All requested exhibits mentioned in motion were submitted during Raleigh, NC hearing, which respondent attended W/o encl.
  REIS.E J Branch 3 79/04/13 1p
- 7905140221 Forwards applicant's transcript corrections & applicant's proposed findings of fact & conclusions of law in the form of supplemental initial decision Certificate of Bvc enci.
  TROMBRIDGF.O.F. Shaw, Pittman. Patts, & Trowbridge 79/04/17. Spp
- --7905140255 hearing O'NEILL,
- --7903140261 suppleme TROWBRIE 79/04/17
- 7905140332 A emissions for summar DUFLO, M. E. 13pp.
- 7905240821 C Board cone problems. EDDLEMAN, F

- 7905280165 Summary of 790502 Affirmation Session 79-10 in Washington, DC re SECY-A-79-20 motion to reopen hearings in Bhearon Harris proceeding & SECY-79-16A, Kranish FOIA Appeal 78-A-20 CHILK, S J Office of the Secretary of the Commission 79/05/04
- 7905250362 Informs parties of possibility of taking official notice retest for viscosity Objections to ASLB procedure must be filed within ten days Supporting documentation & Certificate of Svc enc!
  SMITH, I W Atomic Safety and Licensing Board Panel, 79/05/10 3pp
- @ Inspection reports. IE Bulletins & correspondence
- 790501016B Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping " O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/23 2PP
- 7905030294 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks." O'REILLY J.P Region 2. Atlanta: Office of the Director 79/03/26 2aa
- 7905040163 Forwards IE Bulletin 79-06B. "Review of Operational Errors & Sys Misalignments Identified During TMI Incident " O'REILLY,J P Region 2. Atlanta: Office of the Director 7970474 2pp
- 7905040281 Forwards IE Bulletin 79-07, "Seismic Stress Analyusis of Safety-Related Piping " Licensee action required O'REILLY, J P Region 2. Atlanta. Office of the Director 79704/14 1p
- 7905040329 Forwards IE Bullatin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident " O'REILLY, J P Region 2. Atlanta, Office of the Directo, 79/04/14 1p
- 7905010324 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Strute" O'REILLY, J.P. Region 2. Atlanta, Office of the Director 79/04/16 2pp
- 7905030141 Forwards 1E Bulletim 79-09, "Failures of 0E Type AK-2 Circuit Breaker in Safety-Related Sys " Licensee action required O'REILLY, J P Region 2: Atlanta, Office of the Director 79/04/17 is
- 7905080328 Ack receipt of 790406 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/79-02, 50-401/79-02, 50-402/79-01 \$00-402/79-01 MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch 79/04/17 lp.
- ~~7905080330 Responds to NRC 790227 Itr re violations noted in IE Insp Repts 50~400/79~02.50~401/79~02.50~402/79~01 & 50~403/79~01 Corrective actions appropriate gersonnel instructed in document close-out procedures HOWE,P W Carolina Power & Light Co. 79/04/06 Spp
- 7905020373 Forwards IE Bullstin 79-06A. Revision 1. "Review of Operational Errors & Sys Misalignments Identified During TMI Incident " O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/18 2pp
- 7905250013 Ack receipt of 1E Insp Repts 30-400/79-06.30-401/79-06. 30-402/79-05 & 30-403/79-05 on 790402-05 No proprietary info. HOME: P.W. Carolina Power & Light Go. 79/04/26 2pp.
- --7905250017 Forwards IE Insp Repts 50-400/79-06, 30-401/79-06, 30-402/79-03 & 50-403/79-05 on 790402-05 No noncompliance noted MURPHY C.E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/19 2pp.
- ---7905250020 IE Insp Repts 50-400/79-06.50-401/79-06.50-402/79-05 & 50-403/79-05 on 790402-05. No noncompliance noted Major areas inspected, project status, const contract review & licensee action on previous insp findings.
  BRADLEY.R.D. Region 2: Atlants: Office of the Director. HERDT.A.R. Region 2: Atlants: Office of the Director. Engineering Support Branch 79/04/19 Spp.
- A. Periodic operating reports & related correspondence
- 7703070475 Forwards "Seismic Monitoring Program.First Data Rept," 770930-790301.
  MCDWFTE:H A. Carolina Power & Light Co 79/04/30, 1p

- --7903070480 "Beismic Monitoring Program, First Data Rept." 770930-793311

  \* Carolina Power & Light Co 79/04/30 Spp
- 8 Reportable occurrences, LERs & related correspondence
- 7905140419 Informs that during 781027 site audit of const activities, inspectors notified of potential reportable item recontainment water proofing membrane leakage Reportability not yet determined Final decision by 781201
  CHIANGIN J Garolina Power & Light Co 78/11/22 1p
- 7905110203 Board notification Seabrook refueling water storage tant design deficiency SCINTO, J Hearings Division 79/03/29 30pp
- DOCKET 50-403 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 4

  A Application/construction stage documents & correspondence
- 7905240459 Notification of 790508 meeting w/util in Bethesda. HD to discuss preparation of environ rept BAJHA.8 8 Environmental Projects Branch 2 79/04/27 1p
- 7905080453 Forwards oversized maps & photo attachments to util 78:129 rept on main dam core trench features. W/o drawings FLGYD, 8 D Carolina Power & Light Co 79/05/08 5pp
- 7905090348 Informs of design change notices re maisture content of backfill against Category I structures & of central corematl for main & auxiliary dam & separating dike Resolution of problem will be documented in FSAR.

  MCDUFFIE.M A Garolina Power & Light Co 79/05/09 2pp
- 79052703BO Responds to Region II 790504 request for criteria used to approve previously placed backfill MCDUFFIE.M A Carolina Power & Light Co 79/05/18 7pp
- Q Adjudicatory correspondence
- 7905230368 Response to intervenors Conservation Council of NC & Habe Environ. Inc 790226 motion to remand to ASLB for further hearings 8/or petition to reopen record Certificate of Svc encl BARTH.C A Branch 3 79/03/16 6pp
- 7905300698 Responds to 790313 request of Kudiu Alliance V W Eddlesen re 790213 ALAB-526 decision affirming 790110 order denying series of petitions filed by intervenors Supporting documentation & Certificate of Svc encl TROMBRIDGE, O F Shaw, Pittman, Potts, & Trombridge, 79/03/21
- 7905230629 NRC motion to accept exhibits into evidence re mgt capability of applicant to const & operate proposed facility Certificate of Svc encl BARTH-C A Branch 3. 79/03/30 4pp
- 7905010115 Forwards request for Board notification re nonsafety-grade equipment to mitigate transients
  SCINTO, J.F. Hearings Division. 79/04/02 Sipp.
- --7905010156 Board notification staff assessment re nonsafety-gradi equipment to mitigate transients VASGALLO,D.B Assistant Director for Light Water Reactors. 79/03/29, 2pp.
- ---7905010198 Board notification:recent issue on nonsafety-grade equipment to mitigate transients. More info is required. TERESCO,R L Assistant Director for Reactor Safety 79/03/16
- 7903080232 Applicant has no objection to NRC 790390 motion to accept into evidence Exhibits 12.13.14.15.19 & 20 from recent processings Certificate of Syc encl. TROUBERIDGE, 0 F Shaw. Pittman. Potts, & Troubridge. 79/04/04.
- 7905250093 Forwards 790119 Press Release 79-19 rd issuance of NRC policy statement on Reactor Safety Study.its review by Lawis panel & WASH-1400 use survey, BARTH.C.A Branch 3. 79/04/04. Ip.
- 7905070216 Informs ABLB of review of natl security info re sabotage of spent nuclear fuel Forwards transmittel memo NRC assessment of significance of info to be forwarded when available BARTH-C.A Branch 3. 79704705 2pp

- 7905220443 Forwards draft memo discussing aspects of accumulator delivery identified in NRC studies of ECCS performance characteristics NRC does not consider issue relevant to proceeding
- BARTH, C A Branch 3 79/04/05 5pp
- 7905240703 Forwards memo re behavior of iodine during postulated steam generator tube rupture accidents
  BARTH-C A Branch 3 79/04/05 ip
- 7905030152 Forwards 781211 NRC survey re use of WASH-1400 in licensing process.

  BARTH.C.A Branch 3 79/04/10, 90pp
- 7905t104t8 Response to ALAB-509 re redon emissions & de minimus theory from Parkins record Certificate of Svc encl SCINTO, J.F. Hearings Division 79/04/11 45pp
- 7905140519 Response to 790404 brief of Philadelphia Electric Co.P86&0 & Atlantic City (NJ) Electric Co re de minimus theory Certificate of Svc encl KEPFORD.C R Citizens for Safe Environment 79/04/11 8pp
- 7905:30562 Forwards 790330 motion All requested exhibits mentioned in motion were submitted during Raleigh.NC hearing.which respondent attended W/o encl
  REIS.E.J. Branch 3 79/04/13 ip
- 7905140221 Forwards applicant's transcript corrections & applicant's proposed findings of fact & conclusions of law in the form of supplemental initial decision Certificate of Syc encl TROWSRIDGE, O F Shaw, Pittman, Potts, & Trowbridge 79/04/17, 1p
- --7903140235 Lists corrections to be made in transcripts of evidentiary hearing conducted on 790227-0302 & 790306-08 in Raleigh, NC O'NEILL, J H Shaw, Fittman, Potts, & Troubridge 79/04/17 3pp
- ---7905140261 Proposed findings of fact & conclusion of law in form of supplemental initial decision (CP) List of exhibits encl TROWBRIDGE OF. Shaw, Pittman, Potts, & Trowbridge 79/04/17 54pp
- 7905290098 Cites evident error in proposed findings of fact of Carolina Power & Light Co counsel no statement allowed by Kudzu Alliance or other parties Requests more participation be allowed EDDLEMAN.W Kudzu Alliance 79/04/21 ip
- 7905140332 Notifies of consolidation of five intervenor groups re radon emissions issue Parties have until 790525 in which to file for summary disposition DUFLO.M.E Atomic Bafety and Licensing Appeal Panel. 79/04/25 13ab
- 7905240821 Comments on ASLB findings re util operating record Suggests Board condition facility OLs in light of util operating problems EDDLEMAN, W Affiliation Unknown 79/04/27, 2pp.
- 7905250165 Summary of 790502 Affirmation Session 79-10 in Washington, DC re SECY-A-79-20 motion to reopen hearings in Shearon Marris proceeding & SECY-79-16A: Kranish FOIA Appeal 78-A-20 CHILK, S J. Office of the Secretary of the Commission. 79/05/04 to
- 7905250362 Informs parties of possibility of taking official notice retest for viscosity Objections to ABLB procedure must be filed within 10 days. Supporting documentation & Cartificate Svc encl Svc encl SMITH, I W. Atomic Safety and Licensing Board Panel 79/05/10 Spp
- G Inspection reports, IE Bulletine & correspondence
- 7905010168 Forwards IE Info Notice 79-06. "Stress Analysis of Safety-Related Piping" O'REILLY, J.P. Region 2, Atlanta, Office of the Director, 79/03/23, 2PP
- 7905030294 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks." O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/03/26 2pp.
- 7903040163 Forwards IE Bulletin 79-068, "Revisw of Operational Errors & Sys Misalignments Identified During TMI Incident."
  D'REILLY, J.P. Region 2, Atlanta, Office of the Director.
  79/04/14, 2pp
- 7903040281 Forwards IE Bulletin 79-07. "Beismic Stress Analyssis of Bafety-Related Piping." Licensee action required D'REILLY, J.P. Region 2. Atlanta, Office of the Director. 79/04/14 ip.

- 7905040329 Forwards JE Bulletin 79-08. "Events Relevant to Boiling Mater Power Reactors Identified During THI Incident " O'REILLY, J P Region 2. Atlanta, Office of the Director. 79/04/14 1p.
- 7905010324 Forwards IE Info Notice 79-10, "Nanconforming Pipe Support Struts."
  0'REILLY, J P Region 2, Atlanta, Office of the Director.
  79/04/19 200
- 7905030141 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " Licenses action required O'RETLLY, J.P. Region 2, Atlanta, Office of the Director. 79/04/17 1p
- 7905080325 Ack receipt of 790406 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/79-02, 50-401/79-02, 50-402/79-01 & 50-403/79-01 MURPHY.C.E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/04/17 ip
- --7905080330 Responds to NRC 790227 ltr re violations noted in IE Insp Repts 50-400/79-02.50-401/79-02.50-402/79-01 & 50-403/79-01. Corrective actions appropriate personnel instructed in document close-out procedures HOWE.P H Carolina Power & Light Co. 79/04/06 3pp
- 7905020373 Forwards IE Bullstin 79-06A, Revision 1, "Review of Operational Errors & Gys Misalignments Identified During TMI Incident "
  O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/04/18, 2pp
- 7905250015 Ack receipt of IE Insp Repts 50~400/79-04.50-401/79-06. 50-402/79-03 & 50-403/79-05 on 790402-05. No proprietary info HOME.P.W Carolina Power & Light Co 79/04/26 2pp
- --7903250017 Forwards IE Insp Repts 50-400/79-06, 50-401/79-06, 50-402/79-05 & 50-403/79-05 on 790402-05 No noncompliance noted MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/04/19 2pp
- ---7905250020 IE Insp Repts 50-400/79-06, 50-401/79-06, 50-402/79-05 & 50-403/79-05 on 790402-05 No noncompliance noted Major areas inspected project status, const contract review & licensee action on previous insp findings.

  BRADLEY,R D Region 2, Atlanta, Office of the Director, 79/04/19 Spp
- R. Periodic operating reports & related correspondence
- 7905070475 Forwards "Seismic Monitoring Program, First Data Rept," 770930-790331 MCDUFFIE,M.A. Carolina Power & Light Co 79/04/30, 1p
- ---7905070480 "Seismic Monitoring Program First Data Rept," 770930-790331. \* Carolina Power & Light Co. 79/04/30. Epp
- 8. Reportable occurrences, LERs & related correspondence
- 7905140419 Informs that during 781027 sits audit of const activities, inspectors notified of potential reportable item recontainment water proofing membrane leakage. Reportability not yet determined Final decision by 781201.

  CHIANGI, N. J. Carolina Power & Light Co. 78/11/22. ip
- 7905110203 Board notification: Beabrook refueling water storage tank design deficiency BGINTO, J. Hearings Division 79/09/29. 30pp.
- DOCKET 50-404 NORTH ANNA POWER STATION, UNIT 3
- A. Application/construction stage documents & correspondence
- 7905090383 Forwards into re calculating flux at various locations in reactor vessel. Flux values provided at core edge at inside radius of reactor vessel & at outside radius of reactor vessel 8 at outside radius of reactor vessel 80YER, R. L. Babcock & Wilcox Co. 79/05/03. 2pp.
- 7905110297 Advises that util position is not in accordance w/Reg Guide 1.1. "Net Positive Suction Head for ECCS & Containment Heat Removal Sys Pumps " BROWN.S.C. Virginia Electric & Power Co. 79/05/08 ip.

- 7905220111 Defines util's nonconforming position on Reg Guide 1 55, "Concrete Placement in Category I Structures " BROWN.S C Virginia Electric & Power Co 79/05/17 2pp
- I Financial information
- 7908020459 Discusses SEC 790321 ltr & registration statement Util will file another statement which NRC will be able to review DROMERICK. A H Light Hater Reactors Branch 3 79/04/09 ip
- ---7905020466 Forwards SEC 790316 registration statement filed by util Requests comments by 790330,util wishes statement to become effective by 790402 MORIN.H F Securities & Exchange Commission 79/03/21 60pp
- J Insurance & indemnity information
- 7905110107 Amend to Endorsement 51 to NELIA Policy NF-186 Constitutes Endorsement 54 \* Nuclear Energy Liability Insurance Association 79/04/27 ip
- 7905070497 Confirms increased liability limit to \$124,000.000 for policies NF-1,25,49,76,83,100,111,140,144,151,161,164,170,173,174,178,179,180,182,185,186,187,188,187,192,193,194,195,197,198,200,201,204,204,207,208,210,212,214,215,&others QUATTROCHHIJ American Nuclear Insurers 79/05/01 1p
- 7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,56,57,58,60,61,64,66,67,68,69,70,71,72,74,74,77,78,79,80,86,87,88,90,91,92,93,94,93 & 98 ROBERTS,D M Kutusi Atamic Energy Liability Underwriters 79/05/01
- 7905110090 Endorsements 16,30,36 & 47 to NELIA Policy NF-186 BARDEG.C R Nuclear Energy Liability Insurance Association 79/05/01 ip
- 7905300334 Forwards Endorsements 17:20 & 21 to NELIA Policy NF-240 KELLEY.P J Johnson & Higgins Insurance 79/05/23 App
- Q Inspection reports, IE Bulletine & correspondence
- 7905010224 Forwards IE Info Notice 79-06, "Btress Analysis of Bafety-Related Piping " O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/23 2pp
- 7905030319 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks "
  O'REILLY, J P Region 2, Atlanta, Office of the Director
  79/03/26 2pp
- 7905020133 Forwards IE Bulletin 79-06, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident " O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/11 ip
- 7905040234 Forwards IE Bulletin 79-06B. "Review of Operational Errors & Bys Misalignments Identified During TMI Incident "O'REILLY, J P Region 2. Atlanta. Office of the Director 79/04/14 2pp
- 7905040271 Forwards IE Builetin 79-07, "Seismic Stress Analyusis of Bafety-Related Piping " Licensee action required O'REILLY, J P. Region 2, Atlanta, Office of the Director, 79/04/14 p.
- 7905040448 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident,"
  O'REJLLY, J P Region 2, Atlanta, Office of the Director,
  79/04/14 1p
- 7905010317 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts."

  O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/04/16 200
- 7905030191 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys " Licensee action required.
  0'REILLY, J P. Region 2, Atlanta, Office of the Director, 79/04/17, 2pp
- 7905020502 Forwards IE Bulletin 79-06A.Revision 1. "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."

  O'REILLY, J. P. Region 2, Atlanta. Office of the Director 79/04/19. 200

 $\beta_{I} = \mu$ 

ή L,

- DOCKET 50-405 NORTH ANNA POHER STATION, UNIT 4
- A Application/construction stage documents & correspondence
- 7905090383 Forwards info re calculating flux at various locations in reactor vessel flux values provided at core edge at inside radius of reactor vessel & at outside radius of reactor vessel BOYER.R L Babcock & Wilcox Co 79/05/03 2pp
- 7905110297 Advises that util position is not in accordance w/Req Quide 1 1, "Net Positive Suction Head for ECCS & Containment Heat Removal Sys Pumps" BROUNDS C Virginia Electric & Power Co 79/05/08 1p.
- 7905220111 Defines util's nonconforming position on Reg Guide 1 83, "Concrete Placement in Category I Structures " BRCHN.S C Virginia Electric & Power Co 79/05/17 2pp
- I Financial information
- 7905020459 Discusses SEC 790321 ltr & registration statement Util will file another statement which NRC will be able to review DROMERICK, A H Light Water Reactors Branch 3, 79/04/09 is
- --7905020466 Forwards 790316 SEC registration statement. Requests comments by 790330, as util wishes statement to become effective by 790402 MRRIN H F. Securities & Exchange Commission 79/03/21 60pp
- J Insurance & indemnity information
- 7905110107 Amend to Endorsement 51 to NELIA Policy NF-186 Constitutes Endorsement 54 • Nuclear Energy Liability Insurance Association 79/04/27 1p
- 7903070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,177,180,182,185,186,187,188,187,192,193,194,195,197,196,200,201,204,206,207,208,210,212,214,215,& others. guattrochHi.J American Nuclear Insurers 79/05/01 1ρ
- 7905070882 Confirms increase in liability limit to \$36.000,000 for galicies MF-22.26.29,38,39,44.46,47,49,50,51,52,53,54,55,56,57,58,60,61,64,66,67,60,69,70,71,72,74,76,77,78,79,80,86,87,88,90,91,92,93,94,95 & 96 ROSERTS,D M Mutual Atomic Energy Liability Underwriters 79/05/01
- 7705300334 Forwards Enforsements 17,20&21 to NELIA Policy NF-240 KELLEY,P J Johnson & Higgins Insurance 77/05/23 App
- 7905110090 Endorsements 16.30.36 & 47 to NELIA Policy NF-186 BARDEB.C.R Nuclear Energy Limbility Insurance Association 79/05/01. 1p.
- O Inspection reports. IE Bulletins & correspondence
- 7705010224 Forwards IE Info Notice 77-06, "Stress Analysis of Safety-Related Piping" O'REILLY, J P Region 2, Atlanta, Office of the Director. 77/03/23 2pp
- 7905030319 Forwards IE Info Notice 79-07, "Rupture of Radwasts Tents \* O'REILLY, J P Region 2, Atlanta, Office of the Director, 79/03/26. 2pp
- 7905020133 Forwards IE Bulletin 79-06, "Review of Operational Errers & Sys Misalignments Identified During TMI Incident."
  O'REILLY, P Region 2, Atlanta, Offics of the Director, 79/04/11. ip
- 7905040294 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 2pp
- 7905040271 Forwards IE Bulletin 79-07, "Beismic Stress Analyusis of Safety-Related Piping " Licensee action required O'REILLY, J. P. Region 2, Atlanta. Office of the Director 79/04/14. 1p.
- 7905040448 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Mater Power Reactors Identified During TMI Incident " D'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/06/14, ip

- 7905010317 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts " O'REILLY, J.P. Region 2, Atlanta, Office of the Director
- 7705030191 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " Licensee action required O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/17 200
- 7905020502 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Hisalignments Identified During TMI Incident"
  - CYREILLYJ P Region 2, Atlanta, Office of the Director 79/04/18 Zpp

## DOCKET 50-406 TUSKEGEE INST RESEARCH REACTOR

- 7905160284 Forwards Amend 5 to Indemnity Agreement E-57.per 10CFR140 changes.re increase from \$140 million to \$160 million, affective 790501 Supporting documentation encl SALTZMAN.J Antitrust & Indemnity Group 79/05/01. 5pp
- 7903240675 Amend 5 to Indemnity Agreement E-57 increasing amount of coverage to \$160.000.000 SALT/MAN.J Antitrust & Indemnity Group \* Tuskegee Inst 79/05/15 ip
- O Inspection reports, IE Bulletins & correspondence
- 7905070152 Forwards IE Bulletins 79-05.79-05A & 79-06.re nuclear incident at TMI D'REILLY, J.P. Region 2. Atlanta. Office of the Director 79/04/13 ip

#### DOCKET 50-407 UNIV OF UTAH RESEARCH REACTOR

- J Insurance & indemnity information
- 7905300034 Forwards Amend 10 to Indemnity Agreement E-91, reflecting change in 10CFR140, increasing primary layer of liability from \$140 million of hillion, effective 790501 Bupporting documentation encl BALTZMAN, J Antitrust & Indemnity Group 79/05/01 App.
- 7905(4028) Amend 10 to Indemnity Agreement E-31
  SALTIMAN, J Antitrust & Indemnity Group 79/05/07 1p

### DOCKET 50-409 LA CROBSE BOILING WATER REACTOR

- J. Insurance & indemnity information
- 7705160137 Forwards Amend 5 to Indemnity Agreement B-62.per 10CFR140 changes,re liability insurance increase from \$140 million to \$160 million; effective 770501 Supporting documentation encl SALTZMANIJ Antitrust & Indemnity Group, 79/05/01 5pp.
- 7905110303 Forwards Amend 5 to Indemnity Agraement 8-62. LINDER.F. Duke Power Co 79/05/07 2pp
- 7905310337 Forwards Endorsements 31 & 32 to ANI Policy NF-217 DEVINE:H F Dairyland Power Cooperative 79/05/22 3pp
- P. Experating license stage documents & correspondence
- 7905030332 Forwards draft rept "Review of Liquefaction Potential, LACBUR near Genca, Vernon County, WI"

  81GH. H., NATARAJA, M Dames & Moore 79/03/12 ip
- 7905100174 Notification of 790424 meeting w/util in Bethesda. MD to discuss LACBUR Cycle 5 fuel performance & reload Cycle A ZIEHANN.D L. Operating Reactors Branch 2 79/04/18. ip
- 7905100324 Notification of 790426 meeting w/util in Silver Spring.MD to discuss Cycle 5 fuel performance & reload Cycle 6. Meeting notes new date.

  HETMORE.J. S Operating Reactors Branch 2 79/04/18 ip
- 7703230399 Requests info on HPCS discharge line for systematic evaluation program review. Requests response within 15 days ZIEMANN.D L Operating Reactors Branch 2 79/04/18 Sp

- 7905100132 Forwards draft evaluation of systematic evaluation program Topic IV-1 A Requests review & response within 30 days ZIEMANN.D L Operating Reactors Branch 2 79/04/19 7pp
- 7903290074 Forwards list of topics deleted from systematic evaluation program review for facility
  ZIEMANN, D l Operating Reactors Branch 2 79/04/19 6pp
- 7905040373 Forwards "Structural Analysis Design Rept for LACEWR Replacement Peripheral Bhroud" LINDER, Dairyland Power Cooperative 79/04/30 2pp
- 7905090043 Responds to NRC 790108 ltr re ATMS requirements & recirculation pump trip designs ATMS procedures added to operating manual, operator training accomplished & recirculation pump trip design effort is in progress LINDER, F Dairyland Power Cooperative 79/04/30 2pp
- 7905160425 Forwards "Cycle 5 Fuel Performance & Finalized Refueling Plan for Cycle 6," Apr 1979 Includes responses to NRC 790424 request for addl info re rod withdrawal error & other transient analyses LINDER, F Dairyland Power Comperative 79/05/09 21pp
- ---7905160427 "Cycle 5 Fuel Performance & Finalized Refueling Plan for Cycle 6." Apr 1979 RAFFETY.8 J Dairyland Power Cooperative BUCK.P Nuclear Energy Service, Inc 79/04/30 25pp
- 7903220401 Requests amend to License DPR-45, changing Tech Specs re inservice insp program, which is in conflict w/1974 edition of ASME Section XI Supporting documentation encil LINDER, F Dairyland Power Cooperative 79/05/11 opp
- 7903290086 Ack receipt of NRC 790430 ltr re Cycle 5 fuel perforamance Applies for amend to provisional GL Submits proposed Tech Spec change LINDER: F Dairyland Power Cooperative 79/05/23 6pp
- 7908300012 Submits application to amend provisional License DPR-45 by proposing changes to Tech Specs re off gas activity W/reply to NRC 790822 query re varification of core configuration for Cycle 6 operation
  LINDER,F Dairyland Power Cooperative 79/09/23 6pp
- 7905300314 Requests amend to provisional DL Proposes changes re isolation of forced circulation loops % increase of operational condition for reactor vessel water level safety limits
  LINDER: F Dairyland Power Cooperative 79/09/25 App.
- 7903090173 Forwards IE Insp Rept 50~409/79-03 on 790221~23 No noncompliance noted HEISHMAN.R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79703/22 2pp
- ---7905090175 IE Insp Rept 90-409/79-03 on 790221-23 No noncompliance noted Major areas inspected core thermal power evaluation; control rod screm time test.comparison of calculated power shape wincore monitor & determination of shutdown margin CHOW.E.T. STREETER.JF Region 3. Chicago, Reactor Operations Nuclear Support Branch CRESMELL.JS Region 3. Chicago, Office of the Director 79/03/14 App
- 7905010231 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping" KEPPLER.J G Region 3, Chicago, Office of the Director 79/03/23. ip
- 7905090155 Requests immediate action re implementation of 10CFR79 55 as result of 790312-16 insp & 790321 meeting. Anticipated actions withheld (ref 10CFR2 79)

  KEPPLER, J G Region 3, Chicago, Office of the Director 79/03/23
- 7905040027 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks "
  KEPPLER. J G Region G. Chicago. Office of the Director 79/03/26
- 7905010165 Forwards IE Info Notice 79-08. "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air " KEPPLER, J G Region G, Chicago, Office of the Director 79/03/28.

- 7905010394 Forwards IE Info Notice 79-09, "Epill of Radioactively Contaminated Resin"
  KEPPLER, J. G Ragion G. Chicago. Office of the Director 79/03/30
- 7903290336 Responds to IE Bulletin 79-04 No check valves manufactured by Velan Engineering Corp are in use at facility LINDER, F Dairyland Power Cooperative 79/04/10 1p
- 7905030026 Forwards IE Bullstin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "
  KEPPLER.J. O Region 3, Chicago, Office of the Director 79/04/11,
- 7905010385 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Hisalignments Identified during TMI Incident "
  KEPPLER.J. O Region 3: Chicago: Office of the Director 79/04/14
- 7905040384 Forwards IE Bulletin 79-068, "Review of Operational Errors & Bys Misalignments Identified During TMI incident " KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/14
- 7905040440 Forwards IE Bulletin 79-07, "Saismic Stress Analysis of Safety-Related Piping " Licensee action required KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/14
- 7905040553 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident "
  KEPPLER, J O Region 3, Ghicago, Office of the Director 79/04/14
- 7905030222 Forwards IE Bulletin 79-09, "Failures of QE Type AK-2 Circuit Breaker in Bafety-Related Sys " Licensee action required KEPPLER, J O Region G. Chicago, Office of the Director 79/04/17.
- 7905080490 Forwards IE Bulletin 79-058, "Nuclear Incident at TMI-Supel"
  KEPFLER.J.G. Region 3. Chicaga: Office of the Director. 79/04/21
- 7905240516 Requests extension until 790502 to respond to IE Bulletin 79-08 re TMI effects on BNRs. LINDER:F Delryland Power Cooperative. 79/04/27 ip
- 7905240698 Responds to IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident "Personnel have participated in review of TMI incident LINDER.F. Dairyland Fower Gooperative. 79/05/02. 15pp
- 7905240896 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Recirculation Motor Generator Set Resulted in Reactor Power Increase "
  KEPPLER, J. G. Region 3: Chicago: Office of the Director 79/05/02.
  ip.
- 7905290417 Responds to IE Bulletin 79-07. Forwards info re seismic stress analysis of safety-related piping.
  LINDER:F. Dairyland Power Cooperative 79/05/23 16pp.
- R. Periodic operating reports & related correspondence
- 7905090352 Forwards "Radioactive Effluent Rept & Environ Monitoring Rept" for 1978
  LINDER, F Dairyland Power Cooperative. 79/04/30 1p.
- ---7933970336 "Radioactive Effluent Rept & Environ Monitoring Rept" for 1978. \* Dairyland Power Cooperative, 78/12/31 37pp
- 7905140231 Forwards monthly operating rept for Apr 1979, LINDER, F. Dairyland Power Cooperative, 79/05/08, ip,
- --7908140234 Monthly, operating rept for Apr 1979.
  PAPHORTH, L G. Dairyland Power Cooperative. 79/05/07. 10pp.
- B. Reportable occurrences, LERs & related correspondence
- 7905020238 Notifies of 790410 RO 79-06: fuel assembly 2-13 contains fuel rod w/degraded cladding.
  LINDER: F. Dairyland Power Cooperative 79/04/10, 1p
- 7903010304 Forwards LERs 79-005/01T-0 & 79-006/01T-0. LINDER,F. Dairyland Power Cooperative. 79/04/19. 791

- --7903010510 LER 79-005/01T-0 on 790405 during refueling inspectional degradation in stainless steel fuel cladding of fuel rod. Caused by pellet/clad interaction Assembly will not be reused PAPHORTH.L 0 Dairyland Power Cooperative. 79/04/19 ip
- --7905010520 LER 79-006/01T-0 on 790410 during refueling, insp of irradiated fuel assembly 2-13 revealed abnormal degradation in stainless steel fuel cladding of fuel rod Caused by pellet/clad interaction Assembly will not be reused. PAPMORTH.L. 9 Dairyland Power Cooperative 79/04/19. ip.
- 7905020243 RO 79-07 on 790425, abnormal degradation discovered in primary reactor containment during type B & C surveillance leakage rate testing Electrical penetration repairs started. LINDER, F Dairyland Power Cooperative 79/04/26 2pp
- 7905150517 Forwards LER 79-007/017-0. LINDER,F Dairyland Fower Cooperative. 79/05/09 4gp.
- ---7905150530 LER 79-007/01T-0 on 790425 electrical penetration unite 3 k 4 did not meet Type 8 test criteria during periodic leakage rate testing Caused by cracked individual penetration glands Penetrations replaced & sealing compound applied PAPMORTH, L 9 Dairyland Power Cooperative 79/05/09 isp
- 7905250404 Forwards LER 79-005/01T-1 LINDER: F Dairyland Power Cooperative 79/05/09. ip.
- --7905250407 LER 79-005/01T-1 on 790405 during refueling insp of irradiated fuel assembly 2-33 revealed abnormal degradation in fuel cladding of fuel rod Caused by pellet/clad interaction w/oxygen-assisting stress corrosion, SHIMSHAK,R E Dairyland Power Cooperative, 79/04/19 1p
- DOCKET 30-410 NINE HILE POINT NUCLEAR STATION, UNIT 2

  A. Application/construction stage documents & correspondence
- 7905040316 Summary of 790321 meeting of Hark II owners group in San Jose, CA re intermediate plant program tasks. ANDERSON, C. J Gontainment Systems Branch 79/04/13 130pp
- J Insurance & indemnity information
- 7905070497 Confirms increased liability limit to \$124,000,000 for galicies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,185,186,187,188,189,192,193,194,195,197,198,200,201,204,206,207,208,210,212,214,215,&others QUATTROCHHI,J American Nuclear Insurers, 79/05/01 ip
- G Inspection reports, IE Bulletins & correspondence
- 7903010125 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."

  ORIER.B H Region 1, Philadelphia, Office of the Director. 79/03/23 1p
- 7903020071 Forwards IE Bulletin 79-06, "Review of Operational Error: & Bys Misslignments Identified During TMI Incident "ORIER.B. H. Region 1, Philadelphia, Office of the Director 79/04/11. ip
- -7905020329 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping," Licensee action required, GRIER, B. M. Region i, Philadelphia, Office of the Director 79/04/14. 1p.
- 7905040068 Forwards IE Bulletin 79-048, "Review of Operational Errort & Bus Misslignments Identified During TMI Incident," ORIER.B.H. Region 1, Philadelphia, Office of the Director, 79/04/14, ip
- 7905040235 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Mater Power Reactors Identified During TMI Incident." ORIER.B.H Region 1, Philadelphia, Office of the Director. 79/04/14, ip.

- 7903030081 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Bafety-Related Bys." Licensee action required GRIER, B H 79/04/17 ip Region i, Philadelphia, Office of the Director
- 7905020292 Forwards IE Bulletin 79-06A.Revision 1. "Review of Operational Errors & Sys Misalignments Identified During TMI Incident " CRIER. 3 H 79/04/18 1p Region i, Philadelphia, Office of the Director.
- DOCKET 50-412 BEAVER VALLEY POWER STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 7905210058 Requests plant shutdown because of threat of accident as severe as rupture to reactor vessel ROMANO, F.R. Affiliation Unknown 79/04/12 5pp.
- @ Adjudicatory correspondence
- 7905150267 Forwards CP amend request for extension of expiration date to 841231 DUNN: C. N. Duquesne Light Co. 79/05/09 2pp
- --7705150269 Application for amend of CPPR-105 to extend const completion date to 841231 deta to 841231 DUNN.C.N Duquesne Light Co 79/05/09 4pp
- J Insurance & indemnity information
- 7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,185,184,187,188,189,192,193,174,195,197,198,200,201,204,206,207,208,210,212,214,215,& others QUATTROCKHI, J American Nuclear Insurers
- 7905070582 Confirms increase in liability limit to \$36.000,000 for policies HF-22.26.29.38.39.44.46.47.49.50.51.52.53.54.55.56.57.59.60.61.64.66.67.68.69.70.71.72.74.76.77.78.79.80.86.87.88.89.71.72.74.95.8 96. RBBERTS.D M Hutual Atomic Energy Liability Underwriters. 79/05/01
- Q. Inspection reports, IE Bullstins & correspondence
- 7905010106 Forwards IE Info Notice 79-06. "Stress Analysis of
- 7905020043 Forwards IE Bulletin 79-06, "Review of Operational Errors & Bus Misalignments Identified During TMI Incident,"
  ORIER, B H Region 1, Philadelphia, Office of the Director 79/04/11. 1p
- 7905020398 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping " Licensea action required. ORIER, S. H. Region i, Philadelphia, Office of the Director. 79/04/14 ip.
- 7905040014 Forwards IE Bulletin 79-068, "Review of Operational Errors & Bus Misalignments Identified During TMI Incident "ORIER, B. H. Region i, Philadelphia, Office of the Director, 79/04/14 ip.
- 7905040200 Forwards IE Builetin 79-08, "Events Relevant to Boiling Mater Power Reactors Identified During TMI Incident." ORIER.B.H Region 1, Philadelphia, Office of the Director 79/04/14 1p.
- 7905030063 Forwards IE Bullstin 79-09, "Failures of QE Type AK-2 Circuit Breaker in Bafety-Related Bys." Licenses action required. required.
  ORIER, B. H. Region 1, Philadelphia, Office of the Director
  79/04/17. ip
- 7905010645 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident " GRIER, B.H. Region i, Philadelphia, Office of the Director, 79/04/18. 1p.
- 8. Reportable occurrences, LERs & related correspondence
- 7705100103 Informs that injection pumps have been removed from engines, inspected per newly established criteria & reinstalled on angines. All injection pumps in good condition.

  HORIARTY, J. M. Colt Industries, Inc. 79/03/23 ip.

- 7905010541 Forwards 790329 initial interim rept on Bignificant Beficiency 79-01 we Birgham-Hillamette Co stop work directive Possibility of significant deficiency reported on 790330 Final rept to be issued by 790604.

  MOOLEVER.E J Duquesna Light Co 79/04/25 ip Duquesna Light Co
- --7905010551 Interim rept on Bignificant Deficiency 79-01 re Birgham-Willamette Co stop work directive for quench spray, recirculation spray & auxiliary feedwater pumps Describes QA problem & corrective action. e Duquesne Light Co 79/04/25 2pp
- DOCKET 50-413 GATANBA NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 7905100435 Ack receipt of 790321 ltr forwarding OL application Acceptance review to determine completeness has begun VAROA,8 A. Light Water Reactors Branch 4. 79/04/25 Spp.
- 7705190100 Forwards info in response to request for approval of flerible hoses in const of Class II & III piping DAIL:L C Duke Power Co 79/05/18 5pp.
- ---7905190101 "Documentation of Compliance of Metal Bellows Corp Part 76869 to Requirements of ASME Section III N D3649 for Use in Class II & Class III Piping." \* Duke Power Co. 79/02/26 Bpp
- ---7905190103 "Documentation of Compliance of Metal Bellows Corp Part 78864 to Requirements of ASME Section III N D3649 for Use in Class II & Class III Piping " \* Duke Power Co. 79/02/26 Hpp
- ---7905190104 "Documentation of Compliance of Metal Bellows Corp Part 76865 to Requirements of ABME Bection IFI N C3649 for Use in Class II & Class III Piping " # Duke Power Co 79/02/26 Spp.
- --7905190106 "Design Rept for House Assembly, Flexible Metal," prepared by
  Metal Bellows Corp.per ABME Boiler & Preseure Vessel Code
  Section III, Subsection NC/ND, Classes II & III
  \* Duke Power Co 79/02/23. 50pp.
- J. Insurance & indemnity information
- 7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,185,186,187,188,189,192,193,194,195,197,198,200,201,204,206,207,208,210,212,214,215,&others QUATTROCHHI, J American Nuclear Insurers. 79/05/01, 1p.
- @ Inspection reports. IE Bulletins & correspondence
- 7905010183 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."

  O'REILLY, J.P. Region 2. Atlanta, Office of the Director.
  79/03/23 2pp
- 7905030301 Forwards IE Info Notice 79-07, "Rupture of Radwa O'REILLY, J. P. Region 2, Atlanta, Office of the Directo 79/03/26, 2pp.
- 7905040185 Forwards IE Bulletin 79-06B, "Review of Operations Bus Micalignments Identified During TMI Incident " D'REILLY, J P Region 2, Atlanta, Office of the Director. 79/04/14 2pp.
- 7905040264 Forwards IE Bulletin 79-07, "Seismic Stress Analy Safety-Related Piping." Licenses action required. D'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/04/14. 2pp.
- 7905040346 Forwards IE Bulletin 79-08, "Events Relevant to B Hater Power Reactors Identified During TMI Incident." O'REILLY,J.P Region 2, Atlanta, Office of the Director 79/04/14. ip.
- 7905010354 Forwards IE Info Notice 79-10, "Nonconforming Pipe Strute, " O'REILLY, J. P 79/04/16, 1 Region 2, Atlanta, Office of the Director

- 7903030153 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " Licenses action required D'REILLY, J P Region 2, Atlanta, Office of the Director, 79/04/17, 2pp
- 7905020453 Forwards IE Bulletin 79-06A, Ravision i: "Review of Operational Errors & Bus Minalignments Identified During TMI
- Incident "
  O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/18 2pp
- 7905140162 Ack receipt of 790419 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/79-04 & 50-414/79-04 MURPHY.C E Region 2. Atlants, Reactor Construction & Engineering Bupport Branch. 79/04/30 ip
- --7905140167 Responds to NRC 790322 itr re violations noted in IE Insp Repts 50-413/79-04 & 50-414/79-04. Corrective actions weld identifications on both matls & tags were corrected Piping stored correctly DAILL C Duke Power Co 79/04/19 3pp
- DOCKEY 50-414 CATAMBA NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 7905190100 Forwards info in response to request for approval of flexible hoses in conet of Class II & III piping DAIL/L C Duke Power Co 79/05/18 5pp
- ---7905190101 "Documentation of Compliance of Metal Bellows Corp Part 78863 to Requirements of ASME Bection III N D3649 for Use in Class II & Class III Piping " \* Dute Power Co 79/02/26 Bpp
- ---7705190103 "Documentation of Compliance of Metal Bellows Corp Part 76864 to Requirements of ASME Section III N D3649 for Use in Class II & Class III Piping " \* Dute Power Co 79/02/26 Spp
- --7905190104 "Documentation of Compliance of Metal Bellows Corp Part 76865 to Requirements of ASME Section III N C3649 for Use in Class II & Class III Piping " \* Dute Power Co. 79702/26. 8pp.
- --7905190106 "Design Rept for House Assembly, Flexible Metal." prepared by Metal Bellows Corp. per ASME Boiler & Pressure Vessel Code Bection III. Subsection NC/ND. Classes II & III # Duke Power Co 79702/23 Sopp.
- 7905100435 Ack receipt of 790321 ltr forwarding OL application. Acceptance review to determine completeness has begun, VAROARB A. Light Water Reactors Branch 4 79/04/25 3pp
- J. Insurance & indemnity information

- 7905070497 Gonfirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,185,186,187,188,189,192,193,194,195,197,198,200,201,204,204,204,207,208,210,212,214,215,&others,GUATTROCHHI,J. American Nuclear Insurers 79/05/01. ip.
- O Inspection reports, IE Bulletins & correspondence
- 7905010183 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."

  O'REILLY, J. P Region 2, Atlanta, Office of the Director. 79/03/23 2pp.
- 7903030901 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks " O'REILLY, J P. Region 2, Atlanta, Office of the Director, 79/03/26, 2pp
- 7905040183 Forwards IE Bullstin 79-06B, "Review of Operational Errors & Bys Misslignments Identified During THI Incident,"
  0'RELLV,J.P. Region 2, Atlanta, Office of the Director,
  79/04/14, 2pg

- 7908040266 Forwards IE Bulletin 79-07, "Beismic Stress Analysis of Safety-Related Piping." Licenses action required D'REILLY. J P Region 2, Atlanta, Office of the Director 79704/14 2pp
- 7908040346 Forwards IE Bulletin 79-08, "Events Relevant to Bailing Water Power Reactors Identified During TMI Incident "O'REILLY. JP Region 2. Atlanta. Office of the Director 79704/14. Ip
- 7903010356 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts " O'REILLY, J P Region 2, Atlanta, Office of the Director
- 7905030183 Forwards 1E Bulletin 79-09, "Failures of QE Type AX-2 Circuit Breaker in Bafety-Related Bys " Licenses action required O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/17 2pp
- 7905020453 Forwards IE Bulletin 79-06A, Revision 1. "Review of Operational Errors & Sys Hisalignments Identified During THI Incident " O'REILLY, J P Region 2. Atlanta. Office of the Director 79/04/18 2pp
- 7905140162 Ack receipt of 790419 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/79-04 & 50-414/79-04 HURPHY,6 E Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/04/30 Ip
- --7905140167 Responds to NRC 790322 ltr re violations noted in IE Insp Repts 30-413/79-04 % 50-414/79-04 Corrective actions weld identifications on both matls & tags were corrected Piping stored correctly DAIL, L. G Duke Power Co 79/04/19 3pp.
- DOCKET 50-416 GRAND GULF NUCLEAR STATION, UNIT 1
- A. Application/construction stage documents & correspondence
- 7905100431 Forwards first round request for add1 info re sys analysis for FBAR review.
  8TOLZ.J F Light Water Reactors Branch 1. 79/04/25. 4pp
- H General correspondence
- 7905080450 Forwards affidavit of svc re distribution of Amend 29,ppr encl to NRC 780627 ltr pALE, L F. Mississippi Power & Light Co 79/04/30 22pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 7903300439 Forwards Amend 30 to FSAR & schedule for completing outstanding first round questions
  STAMPLEY. N. L. Mississippi Power & Light Co. 79/05/25. 4pp
- --7903300441 Amend 30 to FSAR Copies of plant area drainage drawing, equipment test plans & response spectra curves available in Central Files \* Hississippi Power & Light Co 79/05/25. 2000pp
- Q. Inspection reports, IE Bulletins & correspondence
- 7905010204 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping" O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79703-23 2pp.
- 7905030314 Forwards IE Info Notice 79-07, "Rupture of Radwasts Tanks." 0'REILLY.J.P. Region 2. Atlanta, Office of the Director. 79/03/26. 1p.
- 7905040223 Forwards IE Bulletin 79-048, "Review of Operational Errors b Sys Missignments Identified During TMI Incident." O'REILLY, J. P Region 2. Atlanta, Office of the Director. 79/04/14. 18.
- 7908040312 Forwards IE Bulletin 79→07, "Beismic Btress Analysis of Bafety-Related Piping " Licensee action required, O'REILLY, J. P. Region 2, Atlanta, Office of the Director, 79708714. 1p.

- 7703040420 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Mater Power Reactors Identified During TMI Incident " O'REILLY, J P Region 2, Atlanta, Office of the Director 17/04/14. 1p
- 7905010371 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts."

  0'REILLY, J P Region 2, Atlanta, Office of the Director
- 7905030167 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Bys " Licensee action required 0'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/17 200
- 7905020472 Forwards IE Bulletin 79-06A:Revision 1, "Review of Operational Errors & Sys Misslignments Identified During TMI Incident," O'REILLY.J.P Region 2, Atlanta, Office of the Director, 79/04/10 2pp
- 7905290061 Ack receipt of IE Insp Repts 50-416/79-01 & 50-417/79-01 on 790123-26 No proprietary info RCOANOHY, J.P. Mississippi Power & Light Co 79/04/18. 1p
- 7905040636 Responds to NRC 790322 ltr re violations noted in IE Insp Repts 50-416/79-02 & 50-417/79-02 Corrective actions Bechtel quality action request issued on welding slectrodes found in frywell area & supervisors instructed in rod control duties HCOAUGHY, J. P Mississippi Power & Light Co. 79/04/23 2pp
- 8 Reportable occurrences. LERs & related correspondence
- 7905140339 Forwards final deficiency rept for weld separation on strut type hanger maki ACGAUOHY-JP Mississippi Power & Light Co. 79/03/22 1p.
- --7905140340 Final rept on potentially Reportable Deficiency 78/03 investigation by Bechtel revealed factory weld separation on Unistrut Part PiOOi meti. All spot welds; except one lot; meet required sefecty factors Unacceptable lot isolated a Mississippi Power & Light Co 79/03/22. 1p.
- 7905020455 Interim rept on potentially reportable deficiency re-circuit separation discrepancies in power generation control complexes Final rept will be submitted by 790620 HCQAUGHY, J.P. Mississippi Power & Light Co. 79/03/23 ip
- 7905140354 Informs of potential Reportable Deficiency 79/05 improper drawings supplied by GE, Reportability is being determined; final rept will be issued by 790531 MCOAUGHY.J P Minaissippi Power & Light Co 79/03/27 1p.
- 7905230373 Informs of possible defective matl shipment purchased from Tube Turns & shipped to Bechtel Power Manufacturer's recell notice and.
  REILLYH K Liberty Equipment & Supply Go 79/04/04 5pp
- 7905040510 Informs that deficiency reported on 790323 re failure of solid state trip devices was caused by inadequate or incomplete older joints on printed circuit boards Boards returned to vendor for analysis MCGAUGHY, J.P. Mississippi Power & Light Co. 79/04/23. ip
- 7905040631 Interim Rept 1 for potentially reportable Deficiency 79-07 recircult separation descrepancies. Final rept will be submitted by 790620.

  MCGAUGHY.JP Mississippi Power & Light Co N 79/04/23 ip
- DOCKET 50-417 GRAND GULF NUCLEAR STATION, UNIT 2 A. Application/construction stage documents & correspondence
- 7903100431 Forwards first round request for add1 info re sys analysis for FBAR review. 8TOLZ, J.F. Light Water Reactors Branch 1 79/04/25. 4pp.
- H General correspondence
- 7905080430 Forwards affidavit of svc re distribution of Amend 29, per enci to NRC 780627 ltr.
  DALE.L.F. Mississippi Power & Light Co. 79/04/30 2pp.
- K Utility Final Bafety Analysis Report (FSAR) & amends
- 7905000439 Forwards Amend 30 to FBAR & schedule for completing outstanding first round questions.
  BTAMPLEY, N. L. Mississippi Power & Light Co. 79/05/25. 4pp

- ---790530044. Amend 30 to FSAR Copies of plant area drainage drawing, squipment test plans & response spectra curves available in Central Files

  \* Hississippi Power & Light Co 79/05/25 2000pp
- Q Inspection reports. IE Buildtins & correspondence
- 7905010204 Forwards IE Info Notice 79-06. "Stress Analysis of Bafety-Related Piping " O'REILLY, J P Region 2. Atlanta. Office of the Director 79/03/23 2pp
- 7905030314 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks "
  O'REILLY.J P Region 2, Atlanta, Office of the Director
  79/02/26 1p
- 7905040223 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "
  0'REILLY,J P Region 2, Atlanta, Office of the Director 79/04/14 ip
- 7905040312 Forwards IE Bulletin 79-07. "Beismic Stress Analysis of Bafety-Related Piping " Licensee action required O'REILLY, J P Region 2. Atlanta. Office of the Director 79/04/14 1p
- 7905040420 Forwards IE Bulletin 79-08. "Events Relevant to Boiling Hater Power Reactors Identified During THI Incident " C'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 ip
- 7905010371 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Btruts " D'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/16 1p
- 7905030167 Forwards IE Bulletin 79-09, "Failures of QE Type AK-2 Circuit Breater in Safety-Related Sys " Licensee action required O'REILLY, J P Region 2. Atlanta, Office of the Director 79/04/17 2pp
- 7905020472 Forwards IE Bulletin 79-06A.Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident " O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/18 2pp
- 7903290061 Ack receipt of IE Insp Repts 50-416/79-01 & 50-417/79-01 on 790123-26 No proprietary info MCGAUGHY.J P Histissippi Power & Light Co 79/04/18 Ip
- 7905040636 Responds to NRC 790322 ltr re violations noted in 1E Insp Repts 50-416/79-02 & 50-417/79-02 Corrective actions Becktel quality action request issued on welding electrodes found in drywell area & supervisors instructed in rod control duties MCGAUGHY, J P Mississippi Power & Light Co 79/04/23 2pp
- S. Reportable occurrences, LERs & related correspondence
- 7905140339 Forwards final deficiency rept for weld separation on strut type hanger matl MCGAUGHY.J P Mississippi Power & Light Co 79/03/22 ip
- --7905140340 Final rept on potentially Reportable Deficiency 78/03
  investigation by Bechtal revealed factory weld separation on
  Unistrut Part Pi001 matl. All spot welds.except one lot,meet
  required safety factory Unacceptable lot isolated
  \* Mississippi Power & Light Co 79/03/22 ip
- 7903020433 Interim rept on potentially reportable deficiency re-circuit separation discrepancies in power generation control complexes. Final rept will be submitted by 790620 MCOAUGHY, J. P. Mississippi Power & Light Co. 79/03/23 19
- 7905140354 Informs of potential Reportable Deficiency 79/05 improper drawings supplied by QE Reportability is being determined; final rept will be issued by 790531.

  HCGAUGHY, J P Hississippi Power & Light Co. 79/03/27. ip
- 7905250373 Informs of possible defective matt shipment purchased from Tube Turns & shipped to Bechtel Power, Manufacturer's recall notice encl REILLY, M K Liberty Equipment & Bupply Co 79/04/04. Spp
- 7905040510 Informs that deficiency reported on 790323 re failure of aclid state trip devices was caused by inadequate or incomplete clier joints on printed circuit boards. Boards returned to vendor for analysis.

  MCQAUGHY, J. P. Mississippi Power & Light Co 79/04/23 ip

- 7905040631 Interia Rept 1 for potentially reportable Deficiency 79-07 re-circuit separation descrapancies. Final rept will be submitted by 790620 MOAUGHY. J. P. Mississippi Power & Light Co N. 79/04/23. 1p.
- BOCKET 50-423 MILLSTONE MICLEAR POWER STATION, UNIT 3
- A Application/construction stage documents & correspondence
- 7705150439 Forwards draft application for extension of CPPR-113 to FOSTER, E. R. Northeast Utilities 79/05/09 5op
- J. Insurance & indemnity information
- 7905140422 Forwards Amend 14 to Indomnity Agreement B-39 per 10CFR140 changes, re increase in liability insurance from \$140 million to \$160 million, effective 790501. Supporting documentation Antitrust & Indemnity Group 79/05/01 App BALTZMAN, J
- 7903190075 Forwards executed Amend 14 to Indemnity Agreement P-39 O'CONNOR.L.A Northeast Utilities 79/05/15 4PP.
- G. Inspection reports: IE Bulletins & correspondence
- rosocoski rormands IE Info Notice 79-06. "Stress Analysis of Bafety-Related Piping." ORIER:BH Region 1. Philadelphia. Office of the Director 79/03/23 Ip 7905010121 Forwards IE Info Notice 79-06, "Stress Analysis of
- 7903010033 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Syc Air Sys Used as Source of Breathing. Region i, Philadelphia, Office of the Director
- 7905010304 Forwards IE Info Notice 79-09. "Spill of Radioactively Contaminated Resin ORIER.B.H Region 1, Philadelphia, Office of the Director. 79/03/30 2pp.
- 7903020066 Forwards IE Bulletin 79-06, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident "ORIER, S.H Region i, Philadelphia, Office of the Director. 79/04/11 ip
- 7905020300 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Bafety-Related Piping " Licensee action required ORIER, B. M. Region 1, Philadelphia, Office of the Director. 79/04/14 1p.
- 7905040059 Forwards IE Bulletin 79-068, "Review of Operational Errors & Sys Misalignments Identified During TM1 Incident." ORIER, 8. H Region 1. Philadelphia, Office of the Director 79/04/14, ig
- 7905040214 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident." ORIER, B.H. Region 1. Philadelphia, Office of the Director. 79704/14. 19
- 7905030077 Forwards IE Bullstin 79-09, "Pailures of GE Tyge AK-2 Circuit Breaker in Safety-Related Bys," Licenses action orients are the control of the Director. Topology of the Director. 19704/17. 1p.
- 7905020284 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident," ORIER, B.H. Region 1, Philadelphia: Office of the Director. 79/04/18 1s.
- 8. Reportable occurrences, LERs & related correspondence
- 7905100097 Informs of completion of analysis of injection pump failures. Failures were result of surface irregularities on barrel \$/or plunger, incorrect math, \$/or new pumps Pumps removed from facility.

  MORIARTY, J. M. Colt Industries, Inc. 79/03/22 ip.

- DOCKET 50-424 ALVIN W VOOTLE NUCLEAR PLANT, UNITT h. Application/construction stage documents & correspondence
- 7905020241 Informs that spare multiport discharge diffuser will neb be installed Evaluation at other operating plants indicates no mend for add1 diffuser. EHRENSPERGER.W Georgia Power Co. 79/04/25 2pp
- 7905230398 Submits clarification of use of 91-day compressive strangth concrete specified in const spec versus 28-day compressive strength concrete referenced in PSAR Section 3 S Requests prompt concurrence. EHRENSPERGER, W G Georgia Power Co 79/05/11 Bpp
- @ Adjudicatory correspondence
- 7905150080 Denies 781031 request by Georgians Against Nuclear Power la Office of Nuclear Reactor Regulation 79/04/13. 205
- 7905240201 Forwards denial of suspension of facility CP. Supporting documentation encl. DENTON.H R. Office of Nuclear Reactor Regulation. 79/04/13 lps
- --7905240211 Director's denial of 10CFR2.206 request BGYD.R B. Office of Nuclear Reactor Regulation. 79/04/13, 888
- -7905240219 Analysis of need for facility a Division of Sits Safety & Environmental Analysis. 79/04/13 Spp.
- --7905240227 Responds to RW Froelich 781207 request Forwards meti en Opongians Against Nuclear Energy request to suspend facility WHITMER, C.F. Georgia Power Co. 78/12/19. 13pp
- ---7905240232 TX PIRO's motion for admission of 781101 add1 Contention | 860TT.J M. Texas Public Interest Research Group. 79/03/22 3jj
- 7905300392 Denies 781031 request of Georgians Against Nuclear Power to suspend CP issued to GA Power Co & to hold hearings realleged new evidence BDYD.R.S. Division of Project Management 79/04/13, 2pp
- 7905180075 Forwards 790413 ltr denying Georgians Against Nuclear Energy request to suspend CP. Also forwards FR notice of denial, DENTON: H R. Office of Nuclear Reactor Regulation. 79/04/19 2js.
- 7905240918 Orders extension of time for NRC to review Ofc of Nuclear Reactor Regulation 790405 denial of request for exforcement action
  action
  GHILK, B. J. Office of the Secretary of the Commission 79/04/30
- I. Financial information
- 7905080497 Forwards "Annual Financial Rept 1978."
  VASOUEZ.R. O Metropolitan Electric Authority of Georgia. 79/05/62
- --7905080508 "Annual Financial Rept 1978,"

  \* Metropolitan Electric Authority of Georgia. 78/12/31. 24ss
- J. Insurance & indemnity information
- 7908070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,185,186,187,188,199,192,193,194,195,197,198,200,201,204,206,207,208,210,212,214,215,6 others.

  QUATTROCHMI, J. American Nuclear Insurers. 79/05/01, 19
- 7905070582 Confirms increase in liability limit to #36,000,000 for policies MF-22,26,29,38,39,44,46,47,49,50,51,52,53,34,55,56,37,58,60,61,64,66,67,68,69,70,71,72,74,74,77,78,79,80,86,87,86,90,91,92,93,74,95 4 96.
  ROBERTS, D. M. Mutuel Atomic Energy Liability Underwriters. 79/8 Mutual Atomic Energy Liability Underwriters. 79/05/01

## Q Inspection reports. IE Bulletins & correspondence

- 7905010200 Forwards IE Info Notice 79-06. "Strass Analysis of Safety-Related Piping " O'REILLY, J P. Region 2. Atlanta. Office of the Director 79/03/23 2pp
- 7903030312 Forwards IE info Notice 79-07. "Rupture of Radwaste Tanks "
  O'REILLY, J P Region 2. Atlanta, Office of the Director
  79/03/26. 2pp
- 7905040216 Forwards IR Bulletin 79-06B, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident " O'REILLY,JP Region 2, Atlanta, Office of the Director 79/04/14. 2pp
- 7905040304 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Bafety-Related Piping " Licensee action required O'REILLY.J.P Region 2, Atlanta, Office of the Director 79/04/14 ip
- 7903040413 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident "
  O'REILLY, J P Region 2, Atlanta, Office of the Director
  79/04/14 10.
- 7905010366 Forwards IE Info Notica 79-10, "Nonconforming Pipe Support Struts."

  O'REILLY,J P Region 2: Atlanta: Office of the Director
- 7905030165 Forwards IE Bulletin 79-09. "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Bys " Licensee action required 0'REILLY, J P Region 2. Atlanta, Office of the Director, 79/04/17 200
- 7903020467 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."

  D.REILLY, J.P. Region 2, Atlanta, Office of the Director.
- 7903240489 Ack receipt of IE Insp Repts 50-424/79-05 & 50-425/79-05 on 790326-29. No proprietary info. STAFFA-R W Georgia Power Co 79/05/03 ip.
- --7905240500 Forwards IE Insp Repts 50-424/79-05 & 80-425/79-05 on 790326-29 No noncompliance noted.

  MURPHY, C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/04/10 2pp
- ---7905240509 IE Insp Repts 50-424/79-05 & 50-425/79-05 on 79032A-29. No noncompliance noted Major areas inspected; const status, concrete procedures & specs concrete placement & records & action on previously identified items HARRIS. J R Region 2: Atlanta, Office of the Director. BRYANT. J C. Region 2: Atlanta, Reactor Construction & Engineering Support Branch. 79/04/10. 4pp.

### DOCKET 30-425 ALVIN W. VOOTLE NUCLEAR PLANT, UNIT 2

## A Application/construction stage documents & correspondence

- 7703020241 Informs that spare multiport discharge diffuser will not be installed. Evaluation at other operating plants indicates no need for addl diffuser.

  EMRENSPERGER, M. Georgia Power Co. 79/04/25. 2pp
- 7903230398 Submits clarification of use of 91-day compressive strength concrete specified in const spec versus 28-day compressive strength concrete referenced in PSAR Section 3.8. Requests prompt concurrence. EMRENSPERGER, M. Georgia Power Co. 79/05/11, Spp.

## • Adjudicatory correspondence

79/04/18

200

- 7905150080 Denies 781031 request by Georgians Against Nuclear Power to suspend CP.
  SCYD.R.S Office of Nuclear Reactor Regulation, 79/04/13, 2pp.
- 7703240201 Forwards denial of suspension of facility CP. Supporting documentation encl DENTON.H.R. Office of Nuclear Reactor Regulation, 79/04/13 ipp.
- --7905240211 Director's denial of 10CFR2, 206 request, BOYD, R. B. Office of Nuclear Reactor Regulation. 79/04/13. Sep.

- --7903240219 Analysis of masd for facility # Division of Bita Safety & Environmental Analysis 79/04/13
- ---7905240227 Responds to RW Froelich 781207 request.Forwards mat1 on Georgians Against Nuclear Energy request to suspend facility CP HHITMER, C F. Georgia Power Co. 78/12/19 13pp.
- ---7905240232 TX PIRG's motion for admission of 781101 add1 Contention 1 ECOTT, J M Texas Public Interest Research Group 79/03/22 3pp.
- 790330392 Denies 781031 request of Georgians Against Nuclear Power to suspend CP issued to GA Power Co & to hold hearings realleged new syldence BOYD.R.B Division of Project Management. 79/04/13. 2pp.
- 7905150075 Forwards 790413 ltr denying Georgians Against Nuclear Energy request to suspend CP Also forwards FR notice of denial, DENTON, H. R. Office of Nuclear Reactor Regulation 79/04/19 2pp.
- 7905240918 Orders extension of time for NRC to review Ofc of Nuclear Reactor Regulation 790405 denial of request for enforcement action CHILK:S U Office of the Secretary of the Commission 79/04/30.

## I. Financial information

- 7903080497 Forwards "Annual Financial Rept 1978."
  VASGUEZ, R.O. Metropolitan Electric Authority of Georgia. 79/05/02.
- ---7905080308 "Annual Financial Rept 1978,"

  \* Metropolitan Electric Authority of Georgia 78/12/31 24pp.

#### J. Insurance & indemnity information

- 7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,185,184,189,192,193,174,195,197,198,200,201,204,206,207,208,210,212,214,215,&others.
- 7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,56,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,71,92,92,94,95 & 96,80,80BERTS,D H. Mutual Atomic Energy Liability Underwriters. 79/05/01
- G Inspection reports. IE Bulletins & correspondence
- 7905010200 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
  0/REILLVJ P. Region 2, Atlanta, Office of the Director 79/03/23, 2pp.
- 7905030312 Forwards IE Info Notice 77-07, "Rupture of Radwaste Tanks," D'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/03/26 2pp
- 7908040216 Forwards IE Bulletin 79-068, "Review of Operational Errors & Bus Misalighments Identified During TMI Incident " D'REILLY, J.P. Region 2. Atlanta. Office of the Director 79/04/14. 200
- 7903040304 Forwards IE Bulletin 79-07, "Beismic Stress Analysis of Bafety-Related Piping." Licentee action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director, 79/04/14 ip.
- 7905040413 Forwards IE Bullatin 79-08, "Eventa Relevant to Reiling Mater Power Reactors Identified During THI Incident." O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/04/14, 1p.
- 7905010366 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts,"
  O'REILLY, J.P., Region 2, Atlanta, Office of the Director, 79/04/16. is.
- 7905030165 Farwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required. O'RETLLY, J.P. Region 2, Atlanta, Office of the Director, 79/04/17. 2pp.

- 7905020467 Forwards IE Bullstin 79-06A.Revision 1. "Review of Operational Errors & Sys Misalignments Identified During TMI Incident " O'REILLY, J P Region 2. Atlants, Office of the Director. 79/04/18. 2pp
- 7905240489 Ack receipt of IE Insp Repte 50-424/79-05 & 50-425/79-05 on 790326-29 No proprietary info STAFFA:R W Georgia Power Co 79/05/03 ip
- --7903240500 Forwards IE Insp Repts 50-424/79-03 & 50-425/79-03 on 790326-29 No noncompliance noted HURPHY, G E Region 2. Atlants. Reactor Construction & Engineering Support Branch. 79/04/10 2pp
- --7909240809 IE insp Repts 50-424/79-05 & 50-425/79-05 on 790326-29 No noncompliance noted Major areas inspected const status. Concrete procedures & specs, concrete placement & records & action on previously identified items

  HARRIS, J. R. Region 2, Atlanta, Office of the Director BRYANT, J C. Region 2, Atlanta, Pacetor Construction & Engineering Support Branch. 79/04/10 4pp

DOCKET 50-426 ALVIN W VOOTLE NUCLEAR PLANT, UNIT 3

- I Financial information
- 7905080497 Forwards "Annual Financial Rept 1978"
  VASQUEZ, R O Metropolitan Electric Authority of Georgia 79/05/02
- --7905080508 "Annual Financial Rept 1978 "
  \* Metropolitan Electric Authority of Georgia 78/12/31 24pp

DOCKET 50-427 ALVIN W VOGTLE NUCLEAR PLANT, UNIT 4

- I Financial information
- 7905080497 Forwards "Annual Financial Rept 1978 "
  VAROUEZ,R () Metropolitan Electric Authority of Georgia 79/05/02
  is.
- --7905080508 "Annual Financial Rept 1978 "

  \* Matropolitan Electric Authority of Georgia 78/12/31 24pp

DOCKET 50-430 ASCO, UNIT 1

- T. Hearing transcripts on non-antitrust matters
- 7905140086 Statement of C Walste, President, Atomic Industrial Forum, Inc before Subcommittee on Nuclear Regulation of Senate Committee on Environ & Public Works, WALSKE, C. Atomic Industrial Forum 79/04/23 5pp

DOCKET 50-433 UC-BANTA BARBARA RESEARCH REACTOR

- J insurance & indemnity information
- 7905160219 Forwards Amend 4 to Indemnity Agreement E-58.per 10CFR140 changes.re ilability insurance increase from #140 million to #160 million effective 790501 Bupporting documentation encl SALTZMAN, J Antitrust & Indemnity Oroup 79/05/01. Spp

10-497 FLOATING NUCLEAR PLANT

on/construction stage documents & correspondence

REO-053; "Investigation & Evaluation of Stress n Piping of LWR Plants" & notice of ity W/o encl. istant Director for Light Water Reactors.

chnical staff be informed that longer holdup re should be required to avoid to ocean & air. I Resources Defense Council 79/04/09. 1p

aview of OPS Rept 7270-RP-16451. Buckling ing Nuclear Plant," draft Revision B.& Application of Criteria to Design of all." of Nuclear Reactor Regulation, 79/04/17, ip

- --7705030034 Requests repts "Buckling Criteria & Application of Criteria to Design of Steel Containment Shell" & "Review of OPS Rept 7270-RP-16A51" BDISMAN.A Z Natural Resources Defense Council 79/03/27 1,
- --7905030042 "Review of DPS Rept 7270-RP-15A51, Buckling Criteria & Application of Criteria to Preliminary Design of Steel Containment Shell for Floating Nuclear Power Plant."

  Revision B.780501 \* International Structural Engineers, Inc NRC-03-77-131 79/03/31 32pp
- --7905030051 "Buckling Criteria & Application of Criteria to Design of Steel Containment Shell " MASRI, S F , BEIDE, P , WEINGARTEN, V I International Structurel Engineers, Inc. NRC-03-77-131 79/03/31 106pp
- 7905240108 Notification of 790507-08 meetings w/Harbison-Walker Refractories.OPS & NRC consultant to discuss Harbison-Walker's experience w/magnesium oxide refractories & DPS' floating nuclear plant core ladie BIRKEL.R A Light Water Reactors Branch 2 79/04/20 4pp
- 7905030339 Forwards list of items to be addressed by Harbison & Walker Refractories & OPS at 790507-08 meeting in Jacksonville.FL, SHANSON D & Aerospace Corp 79/04/24 5pp
- 7905040133 Forwards Amend 27 to plant design rept re cancellation of PSE& G contract, incorporation of refractory ladis & recommendations of NRC consultant re containment shall buckling analysis
  HAQA, P B Offshore Power Systems (subs of Westinghouse Electric Corp.) 79/04/30 121pp
- 7905190112 Discusses current activities of product assurance organization review & approval of drawings & specs Seeks to obtain mfg license & customers as soon as possible & approve drawings & specifications HAGA-P B Offshore Power Systems (subs of Westinghouse Electric Corp ), 79/05/11 2pp
- 7905220022 Forwards errata sheet to correct errors in Amend 27 to 790430 plant design rept HAGA,P P Offshore Power Systems (subs of Westinghouse Electric Corp.) 79705/14, 7pp
- 7905310455 Forwards "Buckling Criteria & Application of Criteria to Preliminary Design of Steel Containment Shell for Floating Nuclear Power Plant," Revision B. HAGALP 8 Offshore Power Systems (subs of Westinghouse Electric Corp.) 79/05/23. 19
- --7905310458 "Buckling Criteria & Application of Criteria to Preliminary Design of Steel Containment Shell for Floating Nuclear Plant: "Revision B \*\* Offshore Power Systems (subs of Wastinghouse Electric Corp.) 7270-RP-16451 79/05/31. 330pp
- G Adjudicatory correspondence
- 7905250313 Statement of matl facts which are not in dispute Applicant not able to build eight plants by 1985. Statement filed in opposition to NRDC statement of matl facts HAGA-P, B , NUTANT, J, A. Offshore Power Systems (subs of Westinghouse Electric Corp ), 79/03/08 7pp
- 7905250270 Identification of evidence for 790404 hearing, submitted in response to ASLB 790312 order. Professional qualifications of TM Philbin encl.
  CDNAN, B.Z.: DOUGHERTY, T.M., KENDRICK, J.R. Offshore Power Bystems (subs. of Westinghouse Electric Corp.), 79703723 6pp
- 7903250177 Responds to ABLB 790315 ltr re applicant's plans for conveyance of reactor pressure vessel to site Applicant will not channelize gither Brezos River or Ban Bernard River. Hilling to begin responding to discovery motions. COPELAND. J G. Baker & Botts. 79/03/27. 2pp
- 7903010113 Forwards request for Board notification re nonsafety-grafe equipment to mitigate transients.

  BCINTG.J.F. Hearings Division. 79/04/02. Sipp

- --7905010155 Board notification staff assessment re nonsafety-grade equipment to mitigate transients
  VASBALLO D B Assistant Director for Light Water Reactors
  774/03/27 20p
- --7909010198 Board notification recent issue on homsafety-grade equipment to mitigate transients More info is required TEDEBCO.R L Assistant Director for Reactor Safety 79/03/16 Spo
- 7903:60039 Discusses effects of TMI on hearing schedules: lists proceedings scheduled from Apr through June Forwards questions to be answered at 790404 hearing REIB.E. J. Branch 3 79/04/03 2pp
- --7905160045 Lists questions to be answered at 790404 hearing re liquid pathway generic study & FES NOLFE, B Atomic Safety and Licensing Board Panel 79/03/29 2pp
- 7903080884 Replies to applicant & NRC opposition to motion for summary disposition Opposes applicant motion for summary disposition Certificate of Svc encl ROIBMAN, A Z Natural Resources Defense Council 79/04/06 14pp
- --7905080202 Statement of matl facts in dispute to applicant motion for summary disposition. Supporting affidavit & resume of TB Cochran encl ROISMAN-A Z Natural Resources Defense Council 79/04/06 10pp
- 7905230292 No comment on proposed schedule submitted by applicant if all proposed findings of fact & conclusions of law re NRDC contention are filed after completion of Board action & hearings on contention, ROIGMAN, A Z Natural Resources Defense Council 1 79/04/09 3pp
- 7903180125 Forwards NRC rept "Inquiry into Allegation of Employee Misconduct by Restricting Investigation to Determine Reliability of Power Orld Serving Bt Lucie "SCHINKI, B.M Branch 3 79/04/11. 1p
- --7905150130 "Inquiry into Allegation of Employee Misconduct by Restricting Investigation to Determine Reliability of Power Orid Serving St Lucie"
  MCTIERNAN.T.J Office of Inspector & Auditor 78/06/30 85pp
- 7905150677 Ack receipt of 790411 ltr transmitting rept of investigation in connection w/8t Lucie proceeding Requests Board be advised of any relevance to proceeding.

  WDLFE.B.J Atomic Safety and Licensing Board Panel 79/04/12. ip
- 7705100122 Informs that written responses to ASLB 790327 its are being delayed; NRC staff originally assigned to work on response are presently involved at TMI-2 BUILINKI, B Branch 3 79/04/17 ip
- H General correspondence
- 7708230628 Expresses concern about safety of floating nuclear power plants, due to unpredictability of weather & oceanic conditions
  TOOHER, J. L. Affiliation Unknown. 79/04/08, 1p
- O. Inspection reports, IE Bulletins & correspondence
- 7908010138 Forwards IR Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
  O'HEILLY, J.P. Region 2, Atlanta, Office of the Director.
  79/09/23 ip
- 7905030323 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks." O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/03/26, 1p
- 7905030188 Forwards IE Bulletin 79-07, "Seitmic Stress Analysis of Bafety-Related Piping " Licensee action required. O'REILLY,J.P. Region 2. Atlanta, Office of the Director 79/04/14. 1P.
- 7905040145 Forwards IE Bulletin 79-068, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident."

  O'REILLY, J P Region 2, Atlanta, Office of the Director.

  79/04/14, ip
- 7905040457 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident." O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/04/14. ip

- 7905030133 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " Licenses action required O'REILLY, J P Region 2, Atlanta, Office of the Director
- 7905140095 Forwards IE Bullstin 79-06A. "Review of Operational Errors & Bys Missalignments Identified During TMI Incident "O'RETLLLY,J P Region 2. Atlanta. Office of the Director 79/04/18 1p
- 8 Reportable occurrences, LERs & related correspondence
- 7905110203 Board notification Seabrook refueling water storage tank design deficiency BCINTO. J Hearings Division 79/03/29 30pp
- DOCKET 50-498 BELLEFONTE NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 7708300376 Notifies that radiological safety review schedule has been reevaluated 5 revised New schedule encl
  PARR.O D Light Water Reactors Branch 3 79/04/30 3pp
- 7905310461 Forwards request for info re initial test program PARR.O D Light Water Reactors Branch 3 79/05/01 16pg
- 7905110225 Approval of Tefrel 200 as snubber matl requiring surveillance interval no more stringent than that required for ethylene propylene equipped snubbers OILLELAND.J E Tennessee Valley Authority 79/05/04 21pp
- J Insurance & indemnity information
- 7905070497 Confirms increased liability limit to \$124,000.000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,185,186,187,188,189,192,193,194,195,197,198,200,201,204,206,207,208,210,212,214,215,&others QUATTRUCHHI,J American Nuclear Insurers 79/05/01 1p
- 79050705B2 Confirms increase in liability limit to \$36,000,000 for policies MF-22,26,27,3B,39,44,46,47,49,50,51,52,53,54,55,56,57,5B,60,61,64,66,67,6B,69,70,71,72,74,76,77,7B,79,80,86,87,8B,90,71,92,93,94,95 % 96 ROBERTS,D M Hutual Atomic Energy Liability Underwriters 79/05/01
- @ Inspection reports, IE Bulletins & correspondence
- 7905010211 Forwards IE Info Notice 79-06, "Btress Analysis of Bafety-Related Piping" O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/23 2pp
- 7905030368 Forwards IE Bulletin 79-07, "Spismic Btrest Analysis of Bafety-Related Piping " Licenses action required O'REILLY, J.P Region 2, Atlanta, Office of the Director 79/04/14. 3pp
- 7905040233 Forwards IE Bulletin 79-D&B, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident."
  O'REILLY.J.P Region 2, Atlanta, Office of the Director 79/04/14, 3pp
- 7905110365 Water Po D'REILLY 79/04/14
- 7905010341 Strute " O'REILLY 79/04/18
- 790503017: Circuit require G'REILL 79/04/1
- 790502047 Operati Inciden O'REILL 79/04/1

- 7905300253 Submits supplemental response to IE Bulletin 77-07. Griginal response submitted 780120, Provides addl info received from samufacturer & describes plans in area of electrical penetrations
  OILLELAND, J.E. Tennessee Valley Authority 79/04/27 5pp
- 8. Reportable occurrences. LERs & related correspondence
- 7905230548 Forwards second interim rept of tensile anchor capacities lower than design allowables.
  OILLELAND, J E Tennessee Valley Authority 79/05/17 ip
- ---7705230557 Second interim rept tensile anchor capacities lower than assumed in design allowables Testing of stud anchors still in progress Final results espected 770801.

  \* Tennessee Valley Authority. 79/05/17 ip.
- DOCKET 50-439 BELLEFONTE NUCLEAR PLANT, UNIT 2
- A. Application/construction stage documents & correspondence
- 7903300376 Notifies that radiological safety review schedule has been reevaluated & revised New schedule encl
  PARR.O D Light Water Reactors Branch 3 79/04/30 3pp
- 7705310461 Forwards request for info re initial test program PARR.O D Light Water Reactors Branch 3 79/05/01 16pp.
- 7905110225 Approval of Tefrel 200 as anubbar mail requiring surveillance interval no more stringent than required for ethylene propulene equipped snubbers
  OILLELAND, J E Tennessee Valley Authority 79/05/04 2ipp.
- J. Insurance & indemnity information
- 7903070497 Canfirms increased liability limit to \$124,000,000 for policies NF-1,23,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,185,186,187,188,189,192,193,194,195,197,198,200,201,204,206,207,208,210,212,214,215,4 athers QUATTROCHHI,J American Nuclear Insurers. 79/05/01 ip
- 7905070582 Confirms increase in liability limit to 836,000,000 for policies MF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,56,57,58,50,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,91,92,93,94,95 & 96.
  ROBERTS,D M Mutual Atomic Energy Liability Underwriters 79/03/01
- A. Inspection reports, IE Bullstins & correspondence
- 7905010211 Forwards IE Info Notice 79-Q6, "Stress Analysis of Bafety-Related Piping." O'REILLY.J.P Region 2, Atlanta, Office of the Director 79/03/23 2pp.
- 7905030368 Forwards IE Bulletin 79-07, "Beismic Stress Analysis of Safety-Related Piping." Licenses action required. O'REILLY.J.P Region 2. Atlanta. Office of the Director. 79/04/14 Spp.
- 7705040233 Forwards IE Bulletin 77-058, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident." O'REILLY, J P. Region 2, Atlanta, Office of the Director, 79/04/14. 3pp
- 7905110365 Forwards IE Bulletin 79-08, "Eyents Relevant to Boiling Water Power Reactors Identified During THI Incident." D'REILLY.J P. Region 2: Atlanta, Office of the Director 79/04/14. 1p
- 7905010341 Forwards IE Info Notice 79-10. "Nonconforming Pipe Support Strute" O'REILLYJ, P. Region 2. Atlanta, Office of the Director. 79/04/18. ip.
- 7905030172 Forwards 1E Sulletin 79-09, "Pailures of GE Type AK-2 Circuit Breaker in Bafety-Related Sys." Licenses action required, O'REILLY, J. P. Region 2, Atlanta, Office of the Director, 79/04/17. 2pp.

7905020479 Forwards IE Sulletin 79-06A: Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident" GrREILLY.J.P. Region 2, Atlanta, Office of the Director, 79/04/18. 2pp.

- 7905300253 Bubmits supplemental response to IE Bulletin 77-07.Original response submitted 78120 Provides addl info received from manufacturer & describes plans in area of electrical penetrations
  GILLELAND.J E Tennesse Valley Authority 79/04/27. 5pp.
- S Reportable occurrences, LERs & related correspondence
- 7905230548 Forwards second interim rept of tensile anchor capacities lower than design allowables OILLELAND, J E Tennesses Valley Authority, 79/05/17. 1p.
- --7905230557 Second interim rept tensile anchor capacities lower than assumed in design allowables Testing of stud anchors still in progress Final results espected 790501

   Tennessee Valley Authority 79/05/17 ip
- DOCKET 50-440 PERRY NUCLEAR POWER PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 7905020424 Forwards NUREG-0531, "Investigation & Evaluation of Stress Corrosion Cracking in Piping of LWR Plants" & notice of issuance & availability W/o encl VASSALLO, D B Assistant Director for Light Water Reactors 79/03/23 2pp
- Q. Inspection reports. IE Bulletins & correspondence
- 7905010246 Forwards IE Info Notice 79-06, "Stress Analysis of Bafaty-Ralated Piping." KEPPLER, J Q. Ragion 3, Chicago, Office of the Director 79/03/23
- 7905040021 Forwards IE Info Notice 79-07. "Rupture of Radwaste Tents "
  KEPPLER J O Region 3. Chicago, Office of the Director. 79/03/26
- 7705030017 Forwards IE Bulletin 77-04, "Review of Operational Errors & Sys Misslignments Identified During TMI Incident." REPLER, J O. Region 3, Chicago, Office of the Director. 77/04/11 io.
- 7905010576 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During THI Incident."

  KEPPLER: J. G Region 3: Chicago: Office of the Director 79/04/14
- 7705040382 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident "KEPPLER. J. O. Region 3. Chicago. Office of the Director. 79/04/14, ip
- 7905040537 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident,"
  KEPPLER.J G Region 3, Chicago, Office of the Director 79/04/14
- 7905070170 Forwards IE Bulletin 79-07, "Beismic Stress Analysis of Safety-Related Piping " Licensee action required KEPPLER.J Q. Region 3, Chicago, Office of the Director. 78/04/14
- 7903010395 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts, " KEPPLER, J. O. Region 3, Chicago, Office of the Director 79/04/15 ip.
- 7905030217 Forwards IE Bulletin 79-07, "Failures of QE Type AK-2 Circuit Breaker in Bafety-Related Bys " Licenses action required.

  KEPPLER, J. Q. Region 3, Chicago, Office of the Director. 79/04/17 is.
- 7905080400 Forwards IE Bulletin 79-058, "Nuclear Incident at TMI-Suppl,"

  \*KEPPLER, J. G Region G. Chicago, Office of the Director. 79/04/21, ip.
- 7905240892 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Recirculation Mator Generator Bet Resulted in Reactor Power Increase," KEPPLER, J. G. Region 3, Chicago, Office of the Director, 79/05/02 Ip.

## DOCKET BO-441 PERRY NUCLEAR POWER PLANT, UNIT 2

- A Application/construction stage documents & correspondence
- 7905020424 Forwards NUREO-0531. "Invastigation & Evaluation of Stress Corrosion Cracking in Piping of LWR Plants" & notice of issuance & availability M/o encl.
  VASGALLO, D B Assistant Director for Light Water Reactors 79/03/23 2pp

## @ Inspection reports, IE Bullatins & correspondence

- 7905010246 Forwards IE Info Notice 79-06, "Btress Analysis of Safety-Related Piping" KEPPLER, J 9 Region 3, Chicago, Office of the Director 79/03/23,
- 7905040021 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks," KEPPLER, J 9 Region 3, Chicago, Office of the Director 79/03/26
- 7905030019 Forwards IE Bulletin 79-06, "Review of Operational Errors & Bys Misalignments Identified During THI Incident "
  KEPPLER, J. O. Region 3, Chicago, Office of the Director 79/04/11
- 7905010576 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Bys Misslignments Identified During TMI Incident,"

  KEPPLER.J.O. Region 3, Chicago, Office of the Director 79/04/14

  1p.
- 7905040382 Forwards IE Bullstin 79-068, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "
  KEPPLER, J O. Region 3, Chicago: Office of the Director. 79/04/14.
- 7905040537 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident "
  KEPPLER, J 0 Region 3, Chicago, Office of the Director. 79/04/14.
- 7905070170 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licenses action required KEPPLER.J.O Region 3, Chicago, Office of the Director. 79/04/14
- 7903010394 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts"
  KEPPLER.J O Region 3, Chicago, Office of the Director 79/04/16
- 7905030217 Forwards IE Builetin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Bafesy-Related Bys." Licensee action required. KEPPLER.J O. Region 3. Chicago. Office of the Director. 79/04/17. ip.
- 7905080400 Forwards lE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl."

  KEPPLER.J.Q. Region 3, Chicago, Office of the Director. 79/04/21.
  ip.
- 7905240892 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Recirculation Hotor Generator Set Resulted in Reactor Power Increase,"
  KEPPLER.U.G. Region 3, Chicago, Office of the Director. 79/05/02
  ip.

### DOCKET 50-443 SEABROOK NUCLEAR STATION, UNIT 1

- A. Application/construction stage documents & correspondence
- 7905080398 Raises questions by Seacoast Anti-Pollution League refinancing plan proposed in Public Svc Co 790321 4 790427 ltrs.

  BACKUS.R.A. O'Neil, Backus, Spislman. 79/05/04. 4pp.
- 7905170245 Forwards Amend 40 to license application. Certificate of Svc. amend fee & supporting documentation encl, RITSHER. J A. Ropes & Gray. 79/05/16. ip.
- ---7905170251 Appointment of agent & signature of applicant, CLEARY, J. V. Oreen Mountain Power Gorp. 79/04/30. 2pp.
- --- T905170253 Forwards Amend 40 to 790330 license application, request for partial transfer of ownership of CPPR-135 & CPPR-136 & supporting financial info of owners.

  MERRILL, D. N. Green Mountain Power Corp. 79/05/14. 315pp.

- F. Security, medical, smergency & fire protection plane
- 7905240343 Forwards Ofc of Nuclear Reactor Regulation 780929 memo to Commissioners re results of fire protection research test Will provide all generic board notifications in all proceedings involving facilities
  BRENNER, L Branch 3 79/04/05, 2pp

#### O Adjudicatory correspondence

- 7905010323 Forwards request for order to show cause why CP should not be suspended or revoked.NRC position on not reviewing consequences of Class 9 facility accident should be revealuated in light of SECY-78-137.

  BACKUB.R.A O'Neil. Backus. Spielmen 79/03/12 2pp
- --7905010329 Requests order to show cause why CP should not be suspended or revoked for lack of financial qualifications of lead applicant & other participating companies Certificate of Byc encl
  BACKUS, R A O'Neil, Backus, Spielman 79/03/12 7pp
- 7905070026 Responds to Seacoest Anti-Pollution League request for order to show cause why CP should not be suspended or revoked Calls for investigation into util's financial qualifications Certificate of BVc encl
  BURT, L Massachusetts, State of 79/03/26, 5pp
- 7905020410 Ferwards 790312 order to show cause & request for order to show cause DENTON.H R. Office of Nuclear Reactor Regulation 79/03/29. 3pp
- --7905020416 Forwards request for order to show cause why CP should not be suspended or revoked e O'Neil. Backus, Spielman 79/03/12 lp
- ---7903020422 Request for order to show cause why CP for proposed nuclear power plants should not be suspended or revoked.

  BACKUS,R A O'Neil, Backus, Spielman 79/03/12 Spp
- --7905020430 Request for order to show tause, filed by Seazonst Anti poliution League.

  DENTON, H R Office of Nuclear Reactor Regulation 79/03/12 1p.
- 7905300336 Requests NRC immediately stop const until design changes are made.
  HEINHOLD, E.H. Affiliation Unknown. 79/04/01. 3pp
- 7905110418 Response to ALAB-509 re radon emissions & de minimus theory from Perkins record. Certificate of Bvc and SCINTO. J. F. Hearings Division. 79/04/11. 45pp.
- 7905140519 Response to 790404 brief of Philadelphia Electric Go,PSE&O & Atlantic City (NJ) Electric Go re de minimus theory. Certificate of Svc encl. KEFFORD.C.R. Citizens for Safe Environment. 79/04/11. Spp.
- 7903240251 Urges swift conclusion to seismic issue for facilities in light of closing of five nuclear plants LENIG.R. Seacoast Anti-Pollution League. 79/04/18. 1p.
- 7905290353 Opposes EH Weinhold 790401 request for seismic design changes & for halt in const until implementation of such changes, EH Weinhold should be permitted to file brief amicus curies.

  BRENNER, L... Branch 3 79/04/23, 9pp.
- 7905140332 Notifies of consolidation of five intervenor groups re-rador emissions issue, Parties have until 790525 in which to file for summary disposition.

  DUFLO.M.E. Atomic Sefety and Licensing Appeal Panel. 79/04/25, 13pp.

## I Financial information

- 7905010477 Responds to NRC 790319 request for addl info re design, analysis, a fabrication for proposed mod of storing reactor cavity annular seal plate during operation info will be provided by 790731.

  HALBRIDGE, N. C. Sacremento Municipal Utility District, 79/04/26.
- 7905010447 Forwards util 790626 preliminary prospectus offering 1.000.000 shares of preferred stock at \$25 par value. RITEHER, J. A. Ropes & Gray 79/04/27, 51pp.
- 7905210129 Forwards 790515 final prospectus re sinking fund stock, 11.24% dividend series. RITSHER, J A. Ropes & Gray. 79/05/16, 53pp.

### @ Inspection reports, IE Bulletins & correspondence

- 7905010143 Forwards IE Info Notice 79-06. "Stress Analysis of Bafety-Related Piping" GRIERLB H. Region t. Philadelphia. Offics of the Director. 79/03/23 1p
- 7905020103 Forwards IE Bulletin 79-06, "Review of Operational Errors & Bys Hisalignments Identified During THI Incident " ORIER,B H Region 1. Philadelphia, Office of the Director, 79/04/11 19.
- 7905020364 Porwards IE Bulletin 79-07. "Beismic Stress Analysis of Safety-Related Piping " Licenses action required GRIER.B.H. Region 1. Philadelphia. Office of the Director. 79704/14 ip
- 7905040100 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident" GRIER:B H Region i, Philadelphia, Office of the Director 79704/14 ip
- 7905040284 Forwards IE Bulletin 79-08. "Evants Relevant to Boiling Water Power Reactors Identified During TMI Incident "
  ORIER.B H Region i. Philadelphia. Office of the Director.
  79704714 ip
- 7905030105 Forwards IE Bullstin 79-09, "Failures of CE Type AK-2 Circuit Breaker in Safety-Related Bys " Licenses action required ORIER B H Region I, Philadelphia, Office of the Director 79/04/17 ip
- 7905020324 Forwards IE Bulletin 79-05A.Revision 1, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident " QRIER.B H Region 1, Philadelphia, Office of the Director 79/04/18 1p
- 7905290083 Responds to IE Bullatin 79-09.QE type AK-2 circuit breakers not planned for use RHEPARDA M Public Service Co of New Hampshirs 79/04/23 ip

#### DOCKET 50-444 SEABROOK NUCLEAR STATION, UNIT 2

- 7905010447 Forwards util 790626 preliminary prospectus, offering 1,000,000 shares of preferred stock at \$25 par value RITSHER, J. A Ropes & Gray 79/04/27 51pp
- A Application/construction stage documents & correspondence
- 7905080398 Raises questions by Seaccast Anti-Pollution League re financing plan proposed in Public Svc Co 790321 & 790427 ltrs. BACKUS,R.A. O'Neil, Backus, Spielman 79/05/04 4pp
- 7905170245 Forwards Amend 40 to license application. Certificate of Byc. amend fee & supporting documentation encl RITSHER, J. A. Ropes & Gray. 79/05/16 1p
- ---7905170251 Appointment of agent & signature of applicant. CLEARY, J. V. Green Mountain Power Corp 79/04/30 2pp.
- --7905170283 Forwards Amend 40 to 790330 license application, request for partial transfer of ownership of CPPR-135 & CPPR-136 k supporting financial info of owners.

  MERRILL. D. N. Green Kountain Power Corp. 79/05/14. 315pp.
- F. Security, medical, emergency & fire protection plans
- 7905240343 Forwards Ofc of Nuclear Reactor Regulation 780929 memo to Commissioners re results of fire protection research test. Will provide all generic board notifications in all proceedings involving facilities.

  BRENNER, L. Branch 3. 79/04/05. 2pp.
- 9 Adjudicatory correspondence

7905010323 Forwards request for order to show cause why CP should not be suspended or revoked. NRC position on not reviewing consequences of Class 9 facility accident should be resvaluated in light of SECY-78-137.

BACKUB.R. A. O'Neil, Betkus, Spielman, 79/03/12, 2pp.

- ---7903010329 Requests order to show cause why CP should not be suspended or revoked for lack of financial qualifications of lead applicant & other participating companies Certificate of Syc encl
  BACKUS, R A O'Neil, Backus, Spielman 79/03/12 7gg.
- 7905070026 Responds to Smacoast Anti-Pollution League request for order to show cause why CP should not be suspended or revoked Calls for investigation into util's financial qualifications Certificate of Svc encl.

  BURT.L Massachusetts, State of 79/03/26 Spp
- 7905020410 Forwards 790312 order to show cause & request for order to show cause DENTON, H.R. Office of Nuclear Reactor Regulation 79/03/29 Jpp
- --7905020416 Forwards request for order to show cause why CP should not be suspended or revoked # 0'Net1, Backus, Bpielman 79/03/12 1p
- --7905020422 Request for order to show cause why CP for proposed nuclear power plants should not be suspended or revoked.

  BACKUS,R A O'Neil: Backus, Spielman 79/03/12 5pp
- --7905020430 Request for order to show causerfiled by Beaccast
  Anti-pollution League
  DENTON,H R Office of Nuclear Reactor Regulation 79/03/12 is.
- 7903300336 Requests NRC immediately stop const until design changes are made MEINOLD,E H Affiliation Unknown. 79/04/01 3pp
- 7905110418 Response to ALAB-509 re radon emissions & de minimus theory from Perkins record. Certificate of Byc encl BCINTO, J F Hearings Division 79/04/11 45pp
- 7905140519 Response to 790404 brief of Philadelphia Electric Co.FREEQ & Atlantic City (NJ) Electric Co re de minimus theory. Certificate of Svc encl KEPFORD, C. R. Citizans for Safe Environment 79/04/11. Opp
- 7903240251 Urges swift conclusion to seismic issue for facilities in light of closing of five nuclear plants LEWIS.R. Beacoast Anti-Pollution League. 79/04/18, ip
- 7905290353 Opposes EH Weinhold 790401 request for seismic design changes & for halt in constructil implementation of such changes. EH Weinhold should be permitted to file brief amicus curise.

  BRENNER.L. Branch 3 79/04/23, 900.
- 7905140332 Notifies of consolidation of five intervenor groups is ration emissions issue.Parties have until 790525 in which to file for summary dispusition DMFLO:M.E Atomic Safety and Licensing Appeal Panel. 79/04/25
- I. Financial information
- 7903010477 Responds to NRC 790317 request for addl info re design analyses. A fabrication for proposed mod of storing reactor cavity annular seal plate during operation Info will be provided by 790731.

  WMLBRIDGE, M. G. Bacramento Municipal Utility District. 79/04/26 ipp.
- 7903210129 Forwards 790313 final prospectus re sinking fund stock 11.24% dividend series
  RITBHER: J A Ropes & Gray, 79/05/16 53pp
- O Inspection reports, IE Bullatins & correspondence
- 7905010143 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
  ORIER.B.H. Region i. Philadelphia. Office of the Director. 79703/23 ip.
- 7903020103 Forwards IE Bulletin 79-06, "Review of Operational Errers & Sys Misalignments Identified During TMI Incident." ORIER. B. H. Region 1. Philadelphia, Office of the Director 79/04/11. 1p.

- 7905020364 Forwards IE Bulletin 79-07. "Seismic Stress Analysis of Bafety-Related Piping " Licenses action required GRIER:8 M. Region i. Philadelphia, Office of the Director 79/04/14 Ip
- 7703040100 Forwards IE Bulletin 77-06B, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident "ORIER, B H Region I, Philadelphia, Office of the Director 77/04/14 | Ip
- 7905040284 Forwards IE Bulletin 79-08, "Evente Relevant to Boiling Mater Power Reactors Identified During TMI Incident " GRIER.B H. Region i, Philadelphia, Office of the Director 79/04/14 lp
- 7905030105 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Gircuit Breaker in Safety-Related Sys " Licensee action required GRIER, B H Region 1, Philadelphia, Office of the Director 79/04/17 1p
- 7905020324 Forwards IE Bulletin 79-06A.Revision 1. "Review of Operational Errors & Sys Misalignments Identified During TMI Incident " GRIER.D H Region 1. Philadelphia. Office of the Director. 79/04/18 1
- 7905290083 Responds to IE Bulletin 79-09 GE type AK-2 circuit breakers not planned for use 8HEPARD,A M Public Service Co of New Hampshire 79/04/23 1p
- DOCKET 50-445 COMANCHE PEAK BTEAM ELECTRIC STA . UNIT 1

  A Application/construction stage documents & correspondence
- 7905140040 Summary of 790320-0321 meeting w/TX Utils Generating Co. Brown & Root Gibbs & Hill & TX Utils Svc. Inc in Glen Ross, TX re testing schedule, const progress & gathering of info to permit independent estimate of fuel loading date BURWELL, S B. Light Water Reactors Branch 2 79/04/06 Spp
- 7905030365 Forwards environ qualification plans Six oversized encls available in Central Files
  QARY,R J. Texas Utilities Generating Co 79/04/23 2pp
- 7905090313 Informs that response to 790406 request for addit second round info will be submitted by Jul 1979

  # Texas Utilities Generating Co 79/04/30 ip
- 7905140284 Forwards initial responses to GA Branch round one questions (0423, 7-0423 20) which will be retransmitted to NRC as FSAR Amend 6. BACKO, B.S. Texas Utilities Co. 79/04/30 125pp
- 7905140222 Forwards "Chlorine Minimization Plan" submitted by util Requests comment by 790601 ELLIGIT, R.B. Environmental Protection Agency. 79/05/08 ip
- ---7905140224 Forwards "Chlorine Minimization Plan." Requests comment within 60 days.
  FIKAR,L F Texas Utilities Generating Co. 79/04/12 ip
- --7905140226 "Chlorine Minimization Plan" RICELJ K Taxas Utilities Generating Co. 79/03/29 18pp.
- O Adjudicatory correspondence
- 7905100228 Answer to Citizens for Sound Energy 790228 petition to intervene re application for QL Seeks denial as matter of right & discretion. Notice of appearance of NS Reynolds on behalf of utils. Certificate of Syc encl. REYNOLDB, N S. . KNOTTS, J. B Debevoise & Lieberman 79/03/15 12pp
- 7905150821 Answer to Citizens for Fair Utility Regulation 790323 petition to intervene re application for OL Seeks denial as matter of right & discretion Certificate of Svc encl REYNOLDS,N B , KNOTTS,J,B. Debevoise & Lieberman 79/03/19 lipp
- 7908250271 Answer to Citizens for Sound Energy 790228 petition to intervene re application for DL Recommends granting intervention if petitioner refines request Certificate of Bwc encl.
  CHANDLER, L. J. Branch 1, 79/03/19. Bpp.
- 7905090154 Request for hearing & first amended patition to intervens by TX Association for Community Organizations Affidavits of T Thompson: Martin, M Bishop, C Bishop, WA Wood & O Wood & Certificate of Byc encl OARRETT.N., HAWTHORNE, S., GAY, O M West Texas Legal Services, 79/03/29, 17pp.

- 7905240115 Request by joint intervenors that time for filling of contentions & first prehearing conference be continued Notice of appearance of OH Oay on behalf of intervenors, raquest of suc of documents & Certificate of Suc encl OAY.O M Wast Taxes Legal Services 79/04/06 11pp
- 7905250143 Confirms scheduled 790417 meeting & requests draft of proposed contentions
  CHANDLER.L J Branch 1 79/04/06 1p
- 7905230853 Orders conference on 790522 to consider petitions to intervene BOMERS.E S Atomic Safety and Licensing Board Panel 79/04/09 2nn
- 7905100193 Answer by applicant in opposition to 790329 first amended petition to intervene & request for hearing filed by TX Association of Community Organizations for Reform Now & West TX Legal Sycs Certificate of Syc encl REYNOLDS N S Debevoise & Lieberman 79/04/13 24pp
- 7905220053 Corrects ASLB 790409 order re location of 790522 prehearing conference
  BOWERS, E.S. Atomic Safety and Licensing Board Panel 79/04/17 ip
- 7905300362 Recommends granting joint petition to intervene from TX Association of Community Organizations for Reform Now & West TX Legal Svcs.subj to clarification of interest & authorization Certificate of Svc encl CHANDLER.L J Branch 1 J 79/04/19 12pp
- 7905230639 Applicant's response to 790406 motion for continuance filed by Association of Community Organizations for Reform Now & West TX Legal Svcs Certificate of Svc enci REYMOLDS.N S Debevoise & Lieberman 79/04/25 4pp
- 7905240929 Motion to suppl contentions Certificate of Svc encl ELLIS, J Citizens Association for Sound Energy 79/05/07 3pp
- I Financial information
- 7905030154 Forwards financial analysis supporting Amend 1 to CPPR-126 & CPPR-127
  SALTZMAN, J Antitrust & Indemnity Group 79/04/13 6pp
- M Antitrust correspondence
- 7905150545 Forwards TX Utils Co & subsidiaries' answer to NRC initial interrogatories & requests for production of documents Reserves rights to file objections & protective order before 790305. Certificate of Svc encl SLICKEY, F K Horsham, Forsythe & Sampels 79/03/01. 1p
- 7905020232 Grants 790317 motion by Public Utils Board of Brownsville, TX sesking extensions, until 790330 & 790405, in which to compel fuller responses to Board's interrogatories MARBHALL, E.M. Atomic Safety and Licensing Board Panel 79/03/22
- 7905240127 Notifies that location of deposition of LC Peeler of Monsanto Co has been changed from Holiday Inn. Alvin. TX to Butler: Binion. Rice: Cook & Knapp law ofcs in Houston. TX. RYAN. T. O Isham. Lincoln & Beale. 79/03/22 5pp
- 7905020480 Order protecting confidentiality of info sought by Houston Lighting & Power from Central Power & Light, West TX Utils, Public Svc of GK & Southeastern Electric Power Co MILLER, M. E Atomic Safety and Licensing Board Panel, 79/03/23 3pp
- 7905310020 Response by util to second set of interrogatories & request for production of documents, submitted to Central Power & Light. Also moves for protective order Certificate of Byc encl BARRETY, E W Baker & Botts 79/03/28 25pp
- 7903070040 Advises that deposition of Edward Bherry, Air Products & Chemicals Co. Allentoum: PA. originally scheduled for 790406, has been changed to 790419 at ofc of Air Products & Chemicals Co.
  RYAN, T. O. Isham, Lincoln & Beals. 79/03/30 1p
- --7903070045 RL Hright, AD Cuphers & L Peeler were deposed during Mar Central Power & Light filed answers & objections to Houston Lighting & Power Co first set of written interrogetories. RYAN, T. G. Isham, Lincoln & Beale, 79/03/30, 2pp

i

-1

1 1

, 1

...

ď

- 7705300058 Rept on progress made in Mar 1979 in completing discovery, submitted per ASLB 780621 order Certificate of Svc enc!
  HARRISJ L , BERGER, M G , CLARK, R H Justice, Dept of 79/03/31 7ap.
- 7905030175 Describes discovery activities of Public Utils Board of Brownsville: TX for Mer 1979 Certificate of Bvc encl POIRER: H R Spiegel & McDiermid, 79/04/03 6pp
- 7905090036 Request by TX Utils Generating Co for NRC to dismiss Central Power & Light South West Corp as intervenors In alternative, seeks summary disposition or invoking of collateral estoppel. Certificate of Evc encl KNOTTS. J. B. Dabavoise & Liebsrman 79/04/03 5pp.
- ---7905090042 Request by TX Util Generating Co for order barring Central Power & Light from seeking relief inconsistent w/District Court decision for favorable decision re summary disposition KNOTTB, J B Debevoise & Lieberman 79/04/03 2pp
- ---7703090030 Memo by TX Utils Generating Co re points & authorities supporting motion to dismiss Central Power & Light South Mest Corp as intervenors or for summary disposition KNOTTS.J B Debeyoise & Lieberman. 79/04/03 42pp
- 7905100288 Response to second set of interrogatories & requests for production of documents directed to DOJ by Houston Lighting & Power Qualifications of export witnesses HE Scott & OTC Taylor & Certificate of Svc enci HARRIG, J L . BERGER, M G. , GLARK, R H Justice, Dept of 79/04/03 23pp
- 7705100288 Response to second set of interrogetories & requests for production of documents directed to Dept of Justice by Houseon Lighting & Power Qualifications of export witnesses WE Scott & OTC Taylor & Certificate of Svc enci HARRIS-J L., BERGER, H. Q., CLARK, R. H. Justice, Dept of 79/04/03, 23pp
- 7905140070 Response to first set of interrogatories & request for production of documents submitted by TX Util Generating Co Certificate of Syc encl.
  HARRIS,J L. Justice, Dept of 79/04/03 iipp
- 7903230361 Request by Central Power & Light that ASLB issue protective order re interrogatories & request for production of documents from Houston Lighting & Power. Certificate of Svc encl
  STAHL.D.H isham, Lincoln & Besle, 79/04/03 7pp.
- 7905100273 Response to TX Utils Generating Co's objections to & motion for protective orders & motion to compel further answers to interrogatories & request for production of documents Certificate of Svc encil BLUME, M B. Anti-Trust Division. 79/04/04 34pp
- 7905140115 Motion by Public Utils Board of Brownsville, TX to compel further production of documents from Bouth TX Electric Cooperative & Medina Electric Cooperative Supporting documentation & Gertificate of Syc enci.
  POIRIER, M R. Spiegel & McDiarmid. 79/04/05. 17pp.
- 790514013B Request by Central Power & Light for extension of time to respond to 79032B responses by Houston Lighting & Power & TX Utils Generating Co to former's interrogatories & document requests. Certificate of Byc encl.

  STAHL: D Isham, Lincoln & Beale, 79/04/05, 6pp
- 7705:00386 Moves that responses to motions for summary disposition filed by Houston Lighting & Power & TX Utils Generating Cobe governed by IOCFR2. 790(a). Certificate of Svc encl LESSY.R.P. Anti-Trust Division 79/04/06.
- 7905150190 Motion by Houston Lighting & Power for protective order republic disclosure of info requested by Public Utils Board of BrownsvillerTX. Certificate of Bvc encl. BARNETT.E.W Baker & Botts. BOUNNIGHT, J. A. Lowenstein, Newman, Reis, Axelrad & Toll. 79/04/06. 9pp.
- 7905230793 Status of discovery & production during Mar 1979. Certificate of Svc encl.
  BALOUGH.R.C Austin. TX 79/04/06. 3pp.
- 7905100412 Applies restrictions on confidential documents to be produced by Houston Lighting & Power Co in response to request for production of documents by Public Utils Board of Brownsville: TX.
  HILLER, M. E. Atomic Gafety and Licensing Board Panel. 79/04/09.

- 7905230488 Status rept on discovery for Mar 1979 Discovery requests were neither initiated nor received Certificate of Svc encl JOHN, D F Akin, Guep, Hauer & Feld 79/04/09 5pp.
- 7905230651 Answer by Houston Power & Lighting to NRC 790323 response to util motion for protective order, NRC motion to compel further answers to interrogatories & NRC request for production of documents Centificate of Svc encl BARNETT, E W Bater & Botts BOUKNIGHT, J A Lowenstein, Newman, Reis, Axelrad & Toll 79/04/11 12pp
- 7905030260 Forwards revised page 28-1 attached to Central Power & Light Co's answers & objections to Houston Lighting & Power Co's first set of written interrogatories to Central Power & Light Go Certificate of Buc enci
- 7905240332 Advises no discovery requests have been initiated or received by Tex-La Electric Cooperative, Inc Certificate of Byc encl
  BURCHETTE, H H Northcutt Ely. 79/04/12 4pp
- 7905150663 Orants motions for extention of time for parties to respond to discovery requests MILLER, M.E. Atomic Safety and Licensing Board Panel 79/04/13
- 790523044B Bouth TX Electric Cooperative. Inc & Medina Electric Cooperative, Inc's opposition to Public Utils Board of Brownsville. TX 790405 motion for fuller responses to interrogatories. Certificate of Svc encl. HUNIEZ. M. Kroinnis, Lochridge & Kilgore, JOHN, D.F. Akin, Quap, Hauer & Feld 79/04/13, lipp
- 7905240967 Advises that during Mer 1979 NRC filed motions to compel against Houston Lighting & Power & TX Utils Generating Co NRC is preparing responses to TX Util's first & Houston's second set of interrogationies.

  LE68Y, R.P. Anti-Trust Division 79/04/13 ip.
- 7905250129 Ack receipt of response to Mer 1979 motion to compet & evaluation in progress LEGSY, R.P. Anti-Trust Division 79/04/13, ip.
- 7905140126 Request by Public Utils Board of Brownsville, TX for extension of time to answer first set of interrogatories & requests for production of documents from Central Power & Light & Houston Lighting & Power, Certificate of Bvc encl HCDIARMID, R. G. Spiegel & HcDiarmid 79/04/16, 7pp
- 7905240241 Corrects ravised page 28-1 of Central Power & Light Co answers & objections in 790412 proceeding from "expenditure other than expenditure" to "expenditure other than advertising." Certificate of Svc enci STAHL
- 7905130780 Directs TX Utils Generating Co (TUOCO) to produce documents or make full responses to 79015 interrogatories Denies TUOCO's order for protective order.
  MILER.M.E. Atomic Safety and Licensing Board Panel. 79/04/18.
- 7905230624 Response by util to Central Power & Light's 790326 objections & 790403 motion for protective order re util's first set of interrogatories. Includes motion to compel answers, Winotice of appearance & Certificate of Svc BARNETT, E.W. Baker & Botts, BOUKKIGHT, J.A., FRANKLIN, W.J. Lowenstein, Newman, Reis, Axelrad & Toll. 79/04/19, 18pp.
- 7905230677 Grants extension of time to answer interrogatories by Public Utils Board of Brownsville, TX, in response to 790416 motion.
  MILLER, M.E. Atomic Sefety and Licensing Board Fanel 79/04/19. Ip
- 7905100118 Motion by Central Power & Light to compel Houston Lightin; & Power to answer second set of interrogetories submitted 790223.8 upporting documentation & Certificate of Svc encl. BTAML.D. Isham, Lincoln & Beale, 79/04/20 20pp.
- --7905100123 Motion by Central Power & Light to compel TX Utils Generating Co to answer first set of interrogatories submitted 790223. BTAME.D. Isham, Lincoln & Beale. 79/04/20. 12pp.
- 7905100271 Answer by Central Power & Light & Central & Bouth West Corp seeking continuence of NRC antitrust reviews, w/no party banned on grounds of res judicate of colleteral estoppel. Bupporting documentation & Certificate of Svc encl. POWELL-R.E., MILLER, M. I., SYAHL, D. M. Isham, Lincoln & Beals, 79/04/20, 113pp.

- 7905100106 Opposes City of Austin's 790329 brief & 790403 motions for full or partial summary judgment filed by Houston Lighting & Power & TX Utils Generating Co. Seeks denial of certification & interlocutory appeals W/Certificate of Svc LESSY.R.P., BLUME, M. B. Anti-Trust Division 79/04/23 24pp.
- 7905140151 Response of Public Utils Board of Brownsvills, TX opposing Houston Lighting & Power motion for summary decision & City of Austin brief in support of res Judicata Supporting documentation & Certificate of Syc enci
- 7903230466 NRC Answer to motions of Gulf States Util for protective order & order setting conditions for compliance w/790226 subpoens. Util should produce documents as requested Certificate of Svc encl.
  BLUME.M B. Anti-Trust Division 79/05/04 14pp
- 0. Inspection reports. IE Bulletine & correspondence
- 7905240196 Responds to IE Bulletin 79-01. No action to be taken at this time . GARY. R J Texas Utilities Generating Co 79/02/19 2pp
- 7903300761 Details actions taken in response to IE Bulletin 78-067 Burvay prepared by Westinghouse indicates none of Cutler-Hammer Type M relays w/coil are in use in safety-related equipment QARY.R J Texas Utilities Generating Co 79/02/19 2pp
- 7903070191 Forwards info meeting rept re 790213 meeting w/IE & local public officials in Oranbury,TX to discuss assignment of resident inspector assignment of resident inspector SEIOLE,W.C. Region 4, Délles, Reactor Construction & Engineering Support Branch 79/03/02. 2pp.
- --7905070209 Bummary of 790213 info meeting w/local officials of Oranbury.TX re assignment of resident inspector, lines of communication, facility status & community concerns TAYLOR.R.O., MIBNER.C.E., CROBBMAN.W A Region 4, Dallas, Office of the Director 79/03/02 3pp
- 7905010365 Forwards IE Insp Repts 50-445/79-03 & 50-446/79-03 on 790202-28 Notice of violation already forwarded w/NRC 790220 ltr. SEIDLE, W.C. Region 4, Dallas, Reactor Construction & Engine
- SEIDLE, W.C. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/03/14. 2pp
- --7905010370 IE Insp Repts 50-445/79-03 & 50-446/79-03 on 790202-28 Noncompliance noted failure to follow concrete placement procedures. TAYLOR.R.O. Region 4. Dallas: Office of the Director 79/03/13
- 7905010281 Forwards IE Info Notice 79-06, "Stress Analysis of Bafety-Related Piping." BEYFRIT, K. V. Region 4, Dalias, Office of the Director 79/03/23
- 7903180584 Forwards IE Insp Repts 50-445/79-07 & 50-446/79-07 on 7903081 12 & 13. No noncompliance noted. SEIDLE: N.C. Region 4. Dallas, Reactor Construction & Engineering Support Branch. 79/03/23. Zpp
- ---7905150561 IE Insp Repts 50-445/79-07 & 50-446/79-07 on 790308,12 & 13. No noncompliance noted. Hajor area inspected constactivities ROBENBERG, A. B. Region 4. Dallas, Reactor Construction & Engineering Support Branch. BARNES, I., ELLERBHAN, L. E. Region 4. Dallas, Office of the Director 79/03/23. Spp.
- 7905010464 Forwards IE Bulletin 79-05A, "Nuclear Incident at TNI Bugpl,"
  SEYFRIT, K.V. Region 4, Dallas, Office of the Director. 79/04/05.
- 7905040501 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Bya Misalignments Identified During TMI Incident."

  BEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/14
- 7905040629 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Hater Power Reactors Identified During TMI Incident "
  8EYFRIT, K V. Region 4, Dallas, Office of the Director 79/04/14, in
- 79050700B0 Forwards IE Bulletin 79-07, "Beismic Stress Analysis of Eafety-Related Figing," Licensee action required. BEYFRIT.K.V. Region 4, Dallas, Office of the Director. 79/04/14

- 7905010440 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts " SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/16
- 790509010B Forwards suppl to IE Bulletin 79-05A, "Nuclear incident at TMI "
  BEYFRIT.K V Region 4. Dailas, Office of the Director 79/04/16
  1p
- 7905030283 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys " Licensee action required SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/17
- 7905290631 Ack receipt of 790320 & 0412 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 30-445/79-04 & 30-446/79-04 & SCIDLE-W C Region 4. Dallas, Reactor Construction & Engineering Support Branch 79/04/26 1p
- ---7905290648 Responds to NRC 790320 ltr re violations noted in IE Insp Repts 50-445/79-04 & 50-446/79-04 Corrective actions equipment maint record for ventilation fan motor revised OARY,R J Texas Utilities Generating Co 79/04/12 3pp
- 8 Reportable occurrences, LERs & related correspondence
- 7905030140 Forwards PNO-79-67H, I.J & K SEYPRIT, K V Region 4. Dallas, Office of the Director 79/04/06 1P
- 7905030085 Forwards PNO-79-67L.M.N & P 8EIDLE:N C Region 4: Dallas, Reactor Construction & Engineering Support Branch 79/04/09. 1P
- 7905030107 Forwards PND-79-670
  BEIDLE:W C Region 4. Dallas, Reactor Construction & Engineering Support Branch 79704/10 ip
- 7905030151 Forwards PNO-79-67R & 79-77 SEIDLE:NC Region 4: Dailas: Reactor Construction & Engineering Support Branch 79/04/11 ip
- 7905030124 Forwards PND-79-678. BEIDLE,W C Region 4. Dallas. Reactor Construction & Engineering Bupport Branch 79/04/12 ip
- 7905030201 Forwards PND-79-67T BEIDLE:W C. Region 4. Dallas, Reactor Construction & Engineering Support Branch 79/04/13 1p
- 7905030076 Forwards PNQ-79-67U & V.

  8EIDLE: W C Region 4. Dallas, Reactor Construction & Engineering

  Support Branch 79/04/16 IP.
- 7905030254 Forwards PNO-79-67H BEIDLE,W C Region 4, Delles, Reactor Construction & Engineering Support Branch 79/04/17 ip
- 7905020314 Forwards PMO-79-67AA
  SEIDLE, M.C Region 4. Dallas, Reactor Construction & Engineering
  Support Branch 70/04/20 in
- 7905020508 Forwards PND-79-6748.AC & AD. 8EIDLE.W.C. Region 4. Dallas, Reactor Construction & Engineering Support Branch. 79/04/23. ip.
- 7905040580 Forwards PNO-79-67AE. SEIDLE, W. C. Region 4, Dallac, Reactor Construction & Engineering Support Branch. 79/04/26 ip
- 7905070193 Forwards PNO-79-67AF & AO BEIDLE, M. C. Region 4. Dallas, Reactor Construction & Engineering Support Branch. 79/04/27. 1p.
- 7905310230 Forwards PNU-79-67AH, AI & AJ BEIDLE, W C. Region 4: Dalles, Reactor Construction & Engineering Support Branch 79/04/30. ip
- 7905240399 Forwards PND-79-67AK & AL BEIDLE: N C. Region 4. Dalles, Reactor Construction & Engineering Support Branch. 79/05/04. 1p.

- 7905210192 Confirms potentially RO re reactor vessel nozzle weld metal defects originally reported in 790126 telcon. Investigation continuing QARY, R J Texas Utilities Generating Co 79/05/14. ip
- TOUGH TO AN AGMANGIN DEAN CITCAM CITCAMO CATOLO OTA LIBIT O
- DOCKET 50-446 COMANCHE PEAK STEAM ELECTRIC STA . UNIT 2

  A Application/construction stage documents & correspondence
- 7905140040 Bummary of 790320-0321 meeting w/TX Utils Generating Co. Brown & Root.Oibbs & Hill & TX Utils Svc.Inc in Glen Rose.TX re testing schedule.comst progress & gathering of info to permit independent estimate of fuel loading date BURNELL.B B Light Water Reactors Branch 2 79/04/06. Bpp
- 7905030365 Forwards environ qualification plans Six oversized encls available in Central Files OARY.R J Texas Utilities Generating Co 79/04/23 2pp.
- 7905090313 Informs that response to 790404 request for addl second round info will be submitted by Jul 1979

  \* Texas Utilities Generating Co 79/04/30 ip
- 7905140284 Forwards initial responses to QA Branch round one questions (Q423 7-0423 20) which will be retransmitted to NRC as FSAR Amend & DACKO, B B Texas Utilities Co 79/04/30 125pp
- 7905140222 Forwards "Chlorine Minimization Plan" submitted by util Requests comment by 790601. ELLIOTT.R 8 Environmental Protection Agency 79/05/08 ip
- ---7905140224 Forwards "Chlorine Minimization Plan " Requests comment within 60 days FIKAR.L.F Texas Utilities Generating Co 79/04/12 ip
- --7905140226 "Chlorine Minimization Plan" RICE,J K Texas Utilities Generating Co 79/03/29 18pp
- O Adjudicatory correspondence

10 h

411.

- 7905100228 Answer to Citizens for Bound Energy 790228 petition to intervene re application for OL Beeks denial as matter of right & discretion Notice of appearance of NS Reynolds on behalf of utils Certificate of Byc encl
  REYNOLDS, N. 8, KNOTTE, J B Debevoise & Lieberman 79/03/15 12pp
- 7905190821 Answer to Citizens for Fair Utility Regulation 790323 patition to intervene re application for DL Seeks denial as matter of right & discretion. Certificate of Bvc enci
  REYNOLDS: N. S., KNOTTS: J B Debevoise & Lieberman 79/03/19 1ipp.
- 7905250271 Answer to Citizens for Bound Energy 790228 petition to intervene re application for OL Recommends granting intervention if petitioner refines request Certificate of Svc encl.

  CHANDLER: L J Branch 1 79/03/19 Bpp
- 7903090154 Request for hearing & first amended patition to intervene by TX Association for Community Organizations, Affidavits of T Thompson, R Martin, M Bishop, C Bishop, WA Hood & O Wood & Certificate of Bvc encl.
  GARRETT, N., HANTHORNE, B., QAY, O.M. Hest Texas Legal Services.
  79/03/29. 17pp.
- 7905240113 Request by joint intervenors that time for filing of contentions & first probearing conference be continued. Notice of appearance of OH Gay on behalf of intervenors: request of svc of documents & Centificate of Svc encl. OAY. G. M. West Taxas Legal Services. 79/04/06 11pg.
- 7905250143 Confirms scheduled 790417 meeting & requests draft of proposed contentions.

  CHANDLER, L. J. Branch 1 79/04/06 1p
- 7905230853 Orders conference on 790522 to consider petitions to intervene BOHERS.E.B. Atomic Safety and Licensing Board Panel 79/04/09, 2pp
- 7905100193 Answer by applicant, in opposition to 790329 first amended petition to intervene & request for hearing filed by TX Association of Community Organizations for Reform Now & Hest TX Legal Sycs. Certificate of Syc encl. REYNOLDS.N.S. Debevoise & Lieberman. 79/04/13 24pp
- 7905220053 Corrects ASLS 790409 order re location of 790522 prehearing conference.

  BDMERS E 8 Atomic Safety and Licensing Board Panel. 79/04/17 ip

- 7905300362 Recommends granting joint petition to intervene from TX Association of Community Organizations for Reform Now & West TX Legal Svcs.subj to clarification of interest & authorization Certificate of Svc ancl CHANDLER.L J Branch i J 79/04/19 12pp
- 7903230637 Applicant's response to 770406 motion for continuance fills by Association of Community Organizations for Reform Now & Hest TX Legal Sycs Certificate of Syc encl.
  REYNOLDB.N 8. Dabayoise & Lieberman 79/04/23 4pp
- 7905240929 Motion to suppl contentions Certificate of Svc encl ELLIS,J Citizens Association for Bound Energy 79/05/07 Spp
- I Financial information
- 7905030154 Forwards financial analysis supporting Amend 1 to CPPR-126 & CPPR-127 BALTZHAN, J Antitrust & Indemnity Group 79/04/13 6pp
- M Antitrust correspondence
- 7903180845 Forwards TX Utils Co & subsidiaries' answer to NRC initial interrogatories & requests for production of documents Reserves rights to file objections & protective order before 790305 Certificate of Svc encl SLICKEY.F K Worsham, Forsyths & Sampels 79/03/01. ip
- 7708020232 Grants 770317 motion by Public Utils Board of Brownsville \$1 seeking extensions, until 770330 & 770405, in which to compel fuller responses to Board's interrogatories MARSHALL, E M Atomic Safety and Licensing Board Panel. 79/03/22 to
- 7905240127 Notifies that location of deposition of LC Peelsr of Monsanto Co has been changed from Holiday Inn. Alvin. TX to Butler, Binion, Rice, Cook & Knapp law ofcs in Houston, TX RYAN. T. O. Isham, Lincoln & Beele 79/03/22 Spp.
- 7905020480 Order protecting confidentiality of info sought by Houston of Lighting & Power from Central Power & Light, West TX Utils, Public Svc of DK & Southeastern Electric Power Co HILLER, M E. Atomic Safety and Licensing Board Panel. 79/03/23 558
- 7905310020 Response by util to second set of interrogatories & request for production of documents, submitted to Central Power & Light Also moves for protective order. Certificate of Svc encl.
  BARNETT, E W. Baker & Botts, 79/03/28, 25pp.
- 7905070040 Advises that deposition of Edward Bherry. Air Products & Chemicals Co. Allentown. PA. originally acheduled for 790405, has been changed to 790419 at ofc of Air Products & Chemicals Co. RYAN, T. Q. Isham, Lincoln & Beale. 79/03/30, ip
- ---7905070045 RL Wright, AD Cuphers & L Pesler were deposed during Har. Central Power & Light filed answers & objections to Houston Lighting & Power Co first set of written interrogetories. RYAN: T O Isham Lincoln & Beale. 79/03/30 2pp
- 7905300058 Rept on progress made in Mar 1979 in completing discovery, submitted per ASLB 780621 order. Certificate of Svc encl.
  HARRIS, J. L. / BERGER, M. G. / CLARK, R. H. Justice, Dept. of 79/03/31
- 7905030175 Describes discovery activities of Public Utils Board of Brownsville, TK for Mar 1979, Cartificate of Svc enci, POIRER, M R Spiegel & McDiarmid 79/04/03 6pp
- 7905090036 Request by TX Utils Generating Co for NRC to dismiss Central Power & Light South West Corp as intervenors. In alternative, seeks summary disposition or invoking of collateral estoppel Certificate of Bvc enci
- ---7905090042 Request by TX Util Generating Co for order barring Central Power & Light from seeking relief inconsistent w/District Court decision for favorable decision re summary disposition. KNOTTS.J B Debevoise & Lieberman 79/04/03. 2pp
- --7905090050 Memo by TX Utils Generating Co re points & authorities supporting motion to dismiss Central Power & Light South West Corp as intervenors or for summary disposition.
  KNOTTS.J.B. Debevoise & Lieberman 79/04/03 42pp

- 7905100288 Response to second set of interrogetories & requests for production of documents directed to DDJ by Houston Lighting & Pawer Qualifications of export witnesses HE Scott & GTC Taylor & Certificate of 8vc enc! HARRIS.J L , BERGER.M Q , CLARK.R.H. Justice. Dept of 79/04/03
- 790510028B Response to second set of interrogatories & requests for production of documents directed to Dept of Justice by Houston Lighting & Power Qualifications of export witnesses NE Scott & GTC Taylor & Certificate of Svc encl. MARRIEJ L , BERGER, M G , CLARK, R H Justice, Dept. of 79/04/03, 23pp
- 7905250361 Request by Central Power & Light that ABLB issue protective order re interrogatories & request for production of documents from Houston Lighting & Power Certificate of Sycenci.

  STAHL.D M Isham, Lincoln & Beals. 79/04/03 7pp.
- 7905100273 Response to TX Utils Generating Co's objections to & motion for protective orders & motion to compal further answers to interrogatories & request for production of documents Certificate of Svc encl.

  BLUME.M B Anti-Trust Division 79/04/04 34pp.
- 7905140115 Motion by Public Utile Board of Brownsville.TX to compal further production of documents from South TX Electric Cooperative & Medina Electric Cooperative. Supporting documentation & Certificate of Svc encl POIRIER.M R Spiegel & McDiarmid 79/04/05 17pg
- 7905140138 Request by Central Power & Light for extension of time to respond to 790328 responses by Houston Lighting & Power & TX Utils Generating Co to former's interrogatories & document requests Certificate of Syc ent., STAFIL:D Isham, Lincoln & Beale 79/04/05 6pp
- 7905100386 Moves that responses to motions for summary disposition filed by Houston Lighting & Power & TX Utils Generating Cobs governed by 10CFR2 790(a) Certificate of Svc encl. LESSY.R.P. Anti-Trust Division, 79/04/06, 5pp
- 7905150190 Motion by Houston Lighting & Power for protective order republic disclosure of info requested by Public Utils Board of Brownsville, TX Certificate of Byc encl.

  BARNETT, E. H. Baker & Botts BOUKNIGHT, J A Lowenstein, Newman, Reis, Axelrad & Toll 79/04/06. 7pp
- 7903230793 Status of discovery & production during Mar 1979 Certificate of Svc enci.

  BALDUGH.R C Austin, TX, 79/04/06 3pp.
- 7905100412 Applies restrictions on confidential documents to be produced by Houston Lighting & Power Co in response to request for production of documents by Public Utils Board of Brownsyills: TX MILLER, M E. Atomic Safety and Licensing Board Panel 79/04/09 Son.
- 7905250488 Status rept on discovery for Mar 1979. Discovery requests were neither initiated nor received Certificate of Svc encl.

  JOHN: D F Akin, Gump, Hauer & Feld 79/04/09. 5pp
- 790523065: Answer by Houston Power & Lighting to NRC 790323 response to util motion for protective order, NRC motion to compel further answers to interrogatories & NRC request for production of documents. Certificate of Syc encl.

  BARNETT, E. M. Baker & Botts. BOUKNIGHT, J A Lowenstein, Newman, Reis, Azelrad & Toll 79/04/11, 12pp.
- 7909030260 Forwards revised page 28-1 attached to Central Power & Light Co's enswers & objections to Houston Lighting & Power Co's first set of written interrogatorise to Central Power & Light Co. Certificats of 8vc encl.

  BTAHL.D.M Isham, Lincoln & Beale, 79/04/12 App
- 7903240332 Advises no discovery requests have been initiated or, received by Tex-La Electric Cooperative. Inc Certificate of Syc enci.
  BURCHETTE. H. H. Northcutt Ely. 79/04/12. 4pp
- 7905150663 Orants motions for extention of time for parties to respond to discovery requests. MILLERIM E. Atomic Safety and Licensing Board Panel. 79/04/13 300.
- 7905230448 South TX Electric Cooperative, Inc & Medine Electric Cooperative, Inc's apposition to Public Utils Board of Brownsville, TX 790405 motion for fuller responses to interrogatories. Cartificate of Bvc encl HUNTEZ.M. McGinnis, Lochridge & Kilgore, JOHN, D F. Akin, Gump, Hauer & Feld 79/04/13. 11pp

- 7905240967 Advises that during Mar 1979 NRC filed motions to compel against Houston Lighting & Power & TX Utils Generating Co. NRC is preparing responses to TX Util's first & Houston's second set of interrogatories LEGSY.R P Anti-Trust Division 79/04/13 ip.
- 7905250129 Act receipt of response to Mar 1979 motion to compel & avaluation in progress
  LESSY.R P. Anti-Trust Division 79/04/13, 1p
- 7905140126 Request by Public Utils Board of Brownsville, TX for sitension of time to answer first set of interrogetories & requests for production of documents from Central Power & Light & Houston Lighting & Power Certificate of Syc sncl MCDIARMID, R C Spiegel & McDiarmid 79/04/16 7pp.
- 7905240241 Corrects revised page 28-1 of Central Power & Light Co enswers & objections in 790412 proceeding from "expenditure other than expenditure" to "expenditure other than advertising "Certificate of Byc encl STAHL.D M Isham, Lincoln & Beale, 79/04/17. 4pp
- 7905180780 Directs TX Utils Generating Co (TUGCO) to produce documents or make full responses to 790115 interrogatories. Danies TUGCO's order for protective order HILLER, H & Atomic Safety and Licensing Board Panel 79/04/18.
- 7905230624 Response by util to Central Power & Light's 790326 objections & 770403 motion for protective order resulti's first set of interrogatories Includes motion to compel answers Winotice of appearance & Certificate of Svc BARNETT, E. W. Baker & Botts. BOUKNIGHT, J. A., FRANKLIN, W. J. Lowenstein, Neuman, Reis, Axelrad & Toll 79/04/19 18pp
- 7905230677 Grants extension of time to answer interrogatories by Public Utils Board of Brownsville.TX, in response to 790416 motion MILLER,M E Atomic Safety and Licensing Board Panel. 79/04/19 ip
- 7905100118 Motion by Central Power & Light to compel Houston Lighting & Power to answer second set of interrogatories submitted 790283. Supporting documentation & Centificate of Svc encl STAKL, D. Islam, Lincoln & Beale 79/04/20 20pp
- --7905100123 Motion by Central Power & Light to compel TX Utils Generating Co to answer first set of interrogatories submitted 790223. STAHL.D Isham. Lincoln & Beale 79/04/20. 12pp
- 7905100271 Answer by Central Power & Light & Central & South West Corp seeking continuance of NRC antitrust reviews, w/no party banned on grounds of res judicata of collateral estoppel Supporting documentation & Certificate of Svc encl. POWELL, R. E., MILLER, M. I., SYAML, D. M. Isham, Lincoln & Beale 79/04/20 115pp.
- 7905100106 Opposes City of Austin's 790327 brief & 790403 motions for full or partial summary judgment filed by Houston Lighting & Power & TX Utils Generating Go Seeks denial of certification & interlocutory appeals W/Cartificate of Bvc. LEBBY.R P., BLUME, M. B. Anti-Trust Division. 79/04/23 24pp.
- 7905140151 Response of Public Utils Board of Brownsville, TX opposing Houston Lighting & Power motion for summany decision & City of Austin brist in support of res judicata, Supporting documentation & Certificata of Syc encl MCDIARMID, R C , JABLON, R A , POIRIER, M. R Spiegel & McDiarmid 79/04/23. 84pp.
- 7905230466 NRC Answer to motions of Oulf States Util for protective order & order setting conditions for compilance w/790226 subposes Util should produce documents as requested. Certificate of Svc encl.
  BLUME, M B. Anti-Trust Division. 79/05/04. 14pp.
- G Inspection reports, IE Bulletins & correspondence
- 7905240196 Responds to IE Bulletin 79-01 No action to be taken at this time.

  QARY:R.J Texas Utilities Generating Co 79/02/19. 2pp
- 7905300761 Details actions taken in response to IE Bulletin 78-067. Survey prepared by Westinghouse indicates none of Cutler-Hammer Type M relays w/coil are in use in safety-related equipment. OARY,R J. Texas Utilities Generating Co. 79/02/19. 2pp.
- 7908070191 Forwards info meeting rept rs 790213 meeting w/IE & local public officials in Granbury. TX to discuss assignment of resident inspector.
  SEIDLE.W.C. Region 4. Dallas, Reactor Construction & Engineering Support Branch 79/03/02 2pp.

- 7905010365 Forwards IE Insp Repts 50-445/79-03 & 50-446/79-03 on 790202-28. Notice of violation already forwarded w/NRC 790220 ltr.

  SEIDLE N C Region 4. Dallas. Reactor Construction & Engineering Support Branch 79/03/14 2pp
- --7905010370 IE Insp Repts 50-445/79-03 & 50-446/79-03 on 790202-28 Noncompliance noted failure to follow concrete placement procedures TAYLOR,R 9 Region 4, Dallas, Office of the Director 79/03/13
- 7905010281 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping "
  BEYFRIT,K,V Region 4, Dailas, Office of the Director 79/03/23.
- 7905150556 Forwards IE Insp Repts 50-445/79-07 & 50-446/79-07 on 790308 12 & 13.No noncompliance noted SEIDLE-N.C Region 4, Dallas. Reactor Construction & Engineering Support Branch. 79/03/23 2pp
- --7905i5056i IE Insp Repts 50-445/79-07 & 50-446/79-07 on 790308.12 & 13.
  No noncompliance noted Major area inspected const
  activities
  ROBENBERG, A B Region 4. Dallas. Reactor Construction &
  Engineering Support Branch BARNES I , ELLERSHAW, L E Region 4.
  Dallas. Office of the Director 79/03/23 Spp
- 7905010464 Forwards IE Bulletin 79-05A: "Nuclear Incident at: THI - Suppl " SEYFRIT.K V Region 4, Dallas, Office of the Director 79/04/05 10.
- 7905040501 Forwards IE Bullatin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident " SEYFRIT.K V Region 4, Dallas, Offics of the Director 79/04/14 to.
- 7905040629 Forwards IE Bullstin 79-00, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident "
  BEYFRIT.K V Region 4. Dallas, Office of the Director 79/04/14 is
- 7905070080 Forwards IE Bulletin 79-07. "Seismic Stress Analysis of Safety-Related Piping." Licenses action required SEYFRIV.K V Region 4. Dallas, Office of the Director 79/04/14
- 7905010440 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts,"
  SEVFRIT,K.V Region 4, Dallas, Office of the Director 79/04/16
- 7905090108 Forwards suppl to IE Builetin 79-05A, "Nuclear Incident at TMI "
  BEYFRIT, K V Region 4, Dallas, Office of the Director, 79/04/16
  1p
- 7905030283 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys " Licenses action required SEYPRIT,K V Region 4, Dallas, Office of the Director, 79/04/17 ip
- 7905290631 Ack receipt of 790320 & 0412 ltre informing NRC of steps taken to correct violations noted in IE Insp Rept S0-445/79-04 & 50-446/79-04.
  SEIDLE-W C. Region 4 Dallas, Reactor Construction & Engineering Support Branch, 79/04/26, ip
- ---7905270648 Responds to NRC 770320 ltr re violations noted in IE Insp. Repts 50-445/77-04 & 50-446/77-04. Corrective actions: equipment maint record for ventilation fan motor revised.

  9ARY,R.J. Texes Utilities Generating Co. 77/04/12 3pp
- 8. Reportable occurrences. LERs & related correspondence

밥

1

} >1

- 7905030140 Forwards PNO-79-67H.I.J & K. SEYFRIT.K V Region 4. Dallas, Office of the Director. 79/04/06.
- 1 790503085 Forwards PNO-79-67L.M.N & P. SEIDLE.W G Region 4. Dallas, Reactor Construction & Engineering Support Branch. 79/04/09 1P.

- 7905030107 Forwards PNO-79-670
  SEIDLE,W C Region 4, Dellas, Reactor Construction & Engineering
  Bupport Branch 79/04/10 ip
- 7905030151 Forwards PND-79-67R & 79-77
  BEIDLE,W C Region 4. Dallas, Reactor Construction & Engineering
  Bupport Branch 79/04/11. ip
- 7903030124 Forwards PNO-79-678
  BEIDLE:N C Region 4, Dailas, Reactor Construction & Engineering Support Branch. 79/04/12. ip
- 7903030201 Forwards PNO-79-67T BEIDLE.W.C Region 4. Dallas, Reactor Construction & Engineering Support Branch 79/04/13 ip
- 7905030076 Forwards PNO-79-67U & V.
  SEIDLE: W G Region 4. Dallas. Reactor Construction & Engineering Bupport Branch 79704/16 1P.
- 7905030254 Forwards PNG-79-67H
  SETDLE-W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79704/17 ip
- 7905020514 Forwards PNO-79-67AA

  SEIDLE: H. C Region 4. Dallas, Reactor Construction & Engineering
  Support Branch 79/04/20 ip
- 7905020508 Forwards PNO-79-67AB.AC & AD.
  SETDLE.W.C. Replan 4, Dallas, Reactor Construction & Engineering Support Branch 79704/23 ip.
- 7905040590 Forwards PND-79-67AE
  BEIDLE: H C Region 4. Dallas, Reactor Construction & Engineering
  Bupport Branch 79/04/26 ip
- 7905070193 Forwards PNO-79-67AF & AG. BEIDLE-M.G Region 4. Delies: Reactor Construction & Engineering Bupport Branch 79/04/27 ip
- 7953310230 Forwards PND-79-67AH, AI & AJ.
  BEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/30, 1p
- 7905240397 Forwards PNO-79-674K & AL. BEIDLE,W C Region 4, Dallas, Reactor Construction & Engineering Bupport Branch. 79/05/04 1p
- 7905210192 Confirms potentially RD re reactor vessel noticle weld metal defects, originally reported in 790126 telcon. Investigation continuing.

  GARY, R. J., Texas Utilities Generating Co. 79/05/14 1p

### DOCKET STN-50-447 GESSAR-238

- A Application/construction stage documents & correspondence
- 7903220045 Responds to 79032; itr requesting June 1979 deadline for detailed review of GESSAR-238 NI preliminary design approval extension. Due to manpower shortages, extension review will not be conducted on schedule DENTON, H. R. Office of Nuclear Reactor Regulation 79/04/16. 7pp
- J. Insurance & indomnity information
- 7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,56,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,70,71,72,73,74,75 & 96,R08ERTS,D.M. Mutual Atomic Energy Liability Underwriters 79/05/01,19
- DOCKET 50-448 DOUGLAS POINT NUCLEAR STATION, LANIT 1

  A. Application/construction stags documents & correspondence
- 7905090374 Forwards "Site Selection Study for Two 1:100 Megawatt Nuclear Power Plants:" prepared by Dames & Moore COX.E.T. Potomac Electric Power Co. 79/05/07. 2pp
- ---7908090376 "Bite Belaction Study for Two 1,100 Megawatt Nuclear Power Plants."

  \* Potomac Electric Power Co. 79/05/01, 70pp.

### Aéjudicatory correspondence

7905020147 Btates NRC has recently discovered document possibly relevant to sabotage of spent fuel It is classified & may never be published in final form Forwards related 790122 TF Carter same, NRC assessment of into to follow BARTH, C A Branch 3 79/04/03 2pp

7905030079 Forwards NRC survey of its use of WABH-1400 unitted from 790404 ltr BARTH, C.A. Branch 3 79/04/10 40ph

#### M. Antitrust correspondence

7905180663 Grants motions for extention of time for parties to respond to discovery requests HILLER, M.E. Atomic Safety and Licensing Board Panel 79/04/13

## DOCKET 50-449 DOUGLAS POINT NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

7905090374 Forwards "Bits Selection Study for Two 1,100 Megawatt Nuclear Power Plants," prepared by Dames & Moore. COX.E.T Potomac Electric Power Co 79/05/07 2pp

---7905090376 "Site Selection Study for Two 1.100 Magawatt Nuclear Power Plants " • Potomac Electric Power Co 79/05/01 70pp

### O Adjudicatory correspondance

7905020147 States NRC has recently discovered document possibly relevant to sabotage of spent fuel It is classified & may never be sublished in final form Forwards related 790122 TF Garter memo NRC assessment of info to follow BARTH, C A Brench 3 79/04/05. 2pp

7905030079 Forwards NRC survey of its use of WASH-1400 omitted from 790404 itr BRATHLC A Branch 3. 79/04/10 40pp.

# M Antitrust correspondence

7905100118 Motion by Central Power & Light to compel Houston Lighting & Power to answer second set of interrogatories submitted 790223 Supporting documentation & Certificate of Syc encl. STARL.D Ishem, Lincoln & Seale, 79704/20 20pp

## DOCKET 50-450 SUMMIT NUCLEAR POWER STATION, UNIT 1

--7905240512 Requests to be informed when Delmarva Power & Light submits CP application for nuclear plant at Bummit, DE. BIDEN: J. R. Benate 79/04/10 ip

### DOCKET 50-451 BUMHIT NUCLEAR POWER STATION, UNIT 2

7903240508 Responds to 790410 ltr.Util has no immediate plans to submit CP application.
GD881CK.V. Office of the Executive Director for Operations.
79703708. 1p.

--7705240512 Requests to be informed when Delmarva Power & Light submits CP application for nuclear plant at Bummit, DE, BIDEN, J R Benate, 79/04/10, ip.

## DOCKET 50-452 GREENWOOD ENERGY CENTER: UNIT 2

A. Application/construction stage documents & correspondence

7905150265 States procedures followed in filing of Amend 14 to PSAR & Suppl 5 to environ rept. Same procedure will be followed in future if no objections are made within ten days MARGWARDT, P. A Detroit Edison Co 79/03/07.

7905240249 Finds PBAR sufficiently complete to begin technical review. Requests info re foundations for intake & discharge structures to complete review HELLERIL, W. Geosciences Branch 79/04/19, 7pp

7905230473 Requests waiver of 10CFRSO App 0-III B 4 & B 5 requirements re-fracture toughness tests as not applicable to reactor vessel:steam generators & pressurizers.

HARRIS.P. B Detroit Edison Co 79/05/01 2pp

## O Adjudicatory correspondence

7905150737 Forwards NRC rept "Inquiry into Allegation of Employee Misconduct by Restricting Investigation to Determine Reliability of Power Orid Serving Bt Lucie "BOHINKI.S M Branch 3 79/04/11, 19

DOCKET 50-453 GREENHOOD ENERGY CENTER, UNIT 3

A Application/construction stage documents & correspondence

7905150295 States procedures followed in filing of Amend 14 to PSAR & Suppl 5 to environ rept Same procedure will be followed in future if no objections are made within ten days MARGUARDT.P A Detroit Edison Co. 79/03/07 ip

7905240249 Finds PBAR sufficiently complete to begin technical review Requests into re foundations for intake k discharge structures to complete review HELLER/L. W. Geosciences Branch 79/04/19, 7pp

7905230473 Requests waiver of 100FR50 App Q-III B. 4 & B 5 requirements re fracture toughness tests as not applicable to reactor vessel steam generators & pressurfizers HARRIS.P B Detroit Edison Co 79/05/01 2pp

### O Adjudicatory correspondence

7905150737 Forwards NRC rept "Inquiry into Allegation of Employee Misconduct by Restricting Investigation to Determine Reliability of Power Orid Serving St Lucia."
80HINKI.S.K Branch 3. 79/04/11 ip.

## DOCKET 50-454 BYRON STATION: UNIT 1

A Application/construction stage documents & correspondence

7809050087 Forwards NUREG-0219, "Nuclear Security Personnel for Power Plants, Content & Review Procedures for Security Training & Qualification Program " M/o encl. VASSALLO, D. B. Assistant Director for Light Water Reactors. NUREG-0219, 78/08/23 App.

7903040482 Notifies of intention to develop safety analysis using existing computer codes, Requests addition of SDLBRIQ: C W. Commonwealth Edison Co. 79/04/26 tp.

### 9. Adjudicatory correspondence

7905090187 Grants petition to intervene by DeKalb Area Alliance for Responsible Energy, Sinnissippi Alliance for Environ & League of Momen Voters of Rockford, IL. Rejects M Westerman's petition; down not satisfy "interme

7905250284 Request by util that ASLB schedule special prehearing conference per 10GFR2.751(a).Certificate of Svc encl MURPHY.P M. Isham. Lincoln & Beale 79/04/18 5pp.

7905240334 Responds to 790411 ltr re constituent petition to intervene in facility OL proceeding. ASLB issued order on 790323 holding that B Neiner Farms had sufficiently demonstrated standing in proceeding observations. Office of the Executive Director for Operations. 79/03/08. 2ps.

## H. General correspondence

7905150635 Forwards 790327 ltr from constituent B Neiner re petition to intervene in OL proceedings Requests assistance in preparation for intervention 0'BRIEN.O.M. House of Rep. 79/04/11. 3pp.

- J. Insurance & indemnity information
- 7905100163 Endorsement 99 to MAELU Policy MF-22
  QERAS.T Nuclear Energy Liability Insurance Association 79/03/27
- 7905070497 Confirms intrassed liability limit to \$124,000,000 for galicies NF-1,25,43,76,83,100,111,140,145,151,161,164,170,173,174,178,179,180,182,185,184,187,189,192,193,194,193,197,197,198,200,201,204,205,207,208,210,212,214,213,& others **GUATTROCHHI**, J American Nuclear Insurers 79/05/01
- 7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,56,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,91,92,93,94,95 & 96 ROBERTS, D H Mutual Atomic Energy Liability Underwriters. 79/05/01
- 7905070567 Forwards amend to application for CP & OL. submitted as Amend 20 to FBAR REED.C Commonwealth Edison Co 79/05/02 2pp
- --7903070374 Amend 20 to FSAR \* Commonwealth Edison Co 79/05/02 430pp
- 7905130351 Forwards affidavit of distribution for FSAR Amend 20 NAUGHTON, W F Commonwealth Edison Co 79/05/11 2pp
- Q. Inspection reports, IE Bulletins & correspondence
- 7905020421 Forwards response to IE Bulletins 78-12 & 78-12A, "Atypical Weld Mati in Reactor Pressure Vessel Welds"
  REED, C Commonwealth Edison Co 79/03/22 10pp
- 7905010236 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Fiping." KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/03/23
- 7905030370 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks KEPPLER, J. G. Region 3. Chicago. Office of the Director
- 7905030013 Forwards IE Builetin 79-06, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident "
  KEPPLER, J G Region 3, Chicago, Office of the Director. 79/04/11
- 7905010369 Forwards IE Bulletin 79~06A, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident "
  KEPPLER, J Q. Region 3, Chicago, Office of the Director. 79/04/14. ío.
- 7903040334 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "
  KEPPLER, J O Region 3: Chicago, Office of the Director 79/04/14.
- 7905040529 Forwards IE Bulletin 79-08, "Events Relevant to Builling Water Power Reactors Identified During THI Incident "
  KEPPLER, J Q Region S. Chicago: Office of the Director 79/04/14
- 7905010380 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts " KEPPLER, J Q Region 3, Chicago, Office of the Director. 79/04/16.
- 7905030206 Forwards IE Bulletin 79-09, "Failures of QE Type AK-2 Circuit Breaker in Safety-Related Sys " Licenses action required. KEPPLER, J. D Region 3, Chicago, Office of the Director, 79/04/17
- 7905040142 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Buppl." KEPPLER, J. Q. Region 3, Chicago, Office of the Director. 79/04/21 1p.
- ---7905040158 IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl,"
  Supporting documentation encl.
  Region 3, Chicago, Office of the Director. 79/04/21. 12pp.
- --7905040170 ACRS recommendations to 790928 incident at TMI. Suggests high priority to placed on development of safety research on behavior of LWRs during anomalous transients. ACRS - Advisory Committee on Reactor Baseguards. 79/04/17

- -- 7705040201 Forwards ACRS recommendations re THI incident/presented to 7 YiRF A ACRS - Advisory Committee on Reactor Bafeguards
- --7905040221 In response to NRC 790418 ltr. states all 790417 ACRE recommendations apply to all PWRs, but were not intended to require immediate changes Plant mode should be made after study of effects on overall safety. THI excluded CARBUNAN X ACRS Advisory Committee on Reactor Safeguards. 79/04/20 200
- 7905240633 Forwards responses to IE Bulletin 79-07 requesting info re swismic analysis of safety-related piping Reanalysis indicates method of intramodal combination has little effect on pipe stresses & equipment support loads REED,C Commonwealth Edison Co 79/04/24 4pp
- DOCKET 50-455 BYRGN STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 7905040482 Notifies of intention to develop eafety analysis using existing computer codes Requests addl info, 80LBRIG,C W Commonwealth Edison Co, 79/04/26, 1p
- O. Adjudicatory correspondence
- 7905090187 Orants petition to intervene by DeKelb Area Alliance for Responsible Energy, Sinnissippi Alliance for Environ & League of Women Voters of Rockford: IL Rejects M Westerman's petitionidoes not satisfy "interest" requirements LUTON.E. Atomic Safety and Licensing Board Panel 79/03/23 3pp
- 7905250284 Request by util that ASLB schedule special prehearing conference per iOCFR2 751(a) Certificate of Svc encl MURPHY, P. M. Isham, Lincoln & Beale, 79/04/18 Spp
- 7905240334 Responds to 790411 ltr re constituent patition to intervent in facility OL proceeding ASLB issued order on 790323 holding that B Neiner Farms had sufficiently demonstrated standing in proceeding OSSICK.L V Office of the Executive Director for Operations 2pp
- J Insurance & indemnity information
- 7905100163 Endorsement 99 to MAELU Policy MF-22
  OERAS,T Nuclear Energy Liability Insurance Association 79/03/27
- 7705070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,141,144,170,173,174,178,179,180,182,185,186,187,188,189,192,193,194,195,197,198,200,201,204,204,207,208,210,212,214,215,& others.
  QUATTROCHHI, J American Nuclear Insurers 79/05/01 1p
- 7905070582 Confirms increase in liability limit to 436,000,000 for policies MF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,56,57,58,60,61,64,66,67,69,69,70,71,72,74,76,77,78,79,80,86,87,88,90,71,92,93,94,95 & 96
  ROBERTS, D. M. Hutual Atomic Energy Liability Underwriters 79/03/01
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 7905070367 Forwards amend to application for CP & DL, submitted as Amend 20 to FBAR REED, C. Commonwealth Edison Co 79/05/02 2pp.
- ---7905070574 Amend 20 to FBAR. \* Commonwealth Edison Co 79/05/02 430pp
- 7905150351 Forwards affidavit of distribution for FSAR Amend 20 NAUOHTON, W. F. Gommonwealth Edison Co. 79/05/11. 2pp.
- Q. Inspection reports, IE Bullatine & correspondence
- 7905020421 Forwards response to IE Bullatins 78-12 & 78-12A, "Atypical Wold Matt in Reactor Pressure Vessel Wolds."
  REED.C. Commonwealth Edison Co. 79/03/22, 10pp.
- 7905010236 Forwards IE Info Notice 79-06. "Btress Analysis of Bafety-Related Piping " KEPPLER, J. O. Region 3. Chicago Office of the Director 79/03/23

7705030970 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks KEPPLER, J. 0. Region 3, Chicago, Office of the Director 79/03/26 7905290294 Request by util that ASLB schedule special prehearing conference per 100FR2 751(a). Certificate of Svc encl MURPHY.P M. Isham. Lincoln & Beale 79/04/18 5pp 7903030013 Forwards IE Bullstin 79-06, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident "
KEPPLER.J.O Region 3, Chicago, Office of the Director. 79/04/11 7905240334 Responds to 790416 itr re constituent petition to intervene in facility OL proceeding ASLB issued order on 790323 holding that B Neiner Farms had sufficiently demonstrated standing in proceeding OOSBICK.L.V Office of the Executive Director for Operations 79/05/08 2pp 7905010369 Forwards IE Bulletin 79-0AA. "Review of Operational Errors & Sys Misalignments Identified During TMI Incident " KEPPLER, J O Region 3. Chicago, Office of the Director. 79/04/14 J Insurance & indemnity information 7905100163 Endersement 99 to MAELU Policy MF-22.

OERAB, T Nuclear Energy Liability Insurance Association 79/03/27 7905040334 Forwards IE Bulletin 79-068. "Review of Operational Errors & Bys Misalignments Identified During TMI Incident "
KEPPLER. J C Region 3. Chicago, Office of the Director 79/04/14 7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1.25,43,76.83,100,111,140,144,151,161,164,170,173,174,178,179,180,189,189,192,193,174,195,197,198,200,201,204,206,207,208,210,212,214,215,& others guartrachill J American Nuclear Insurers 79/05/01 1p 7903040529 Forwards IE Bulletin 79-08. "Eyents Relevant to Boiling Water Power Reactors Identified During TMI Incident" MEPPLER, J. O. Region 9, Chicago, Office of the Director 79/04/14 7905070582 Confirms increase in liability limit to \$36,000.000 for policies MF-22.26.29.38.39.44.46.47.49.50.51.52.53.54.55.56.57.58.60.61.64.66.67.68.69.70.71.72.74.76.77.78.79.80.86.87.88.90.91.92.73.94.95 & 96 7905010380 Forwards IE Info Notice 79-10. "Nonconforming Pipe Support KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/18 7905030204 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breater in Safety-Related Sys " Licensee action required K. Utility Final Bafety Analysis Report (FSAR) & amends KEPPLER, J C. Region 3. Chicago, Office of the Director 79/04/17 7908070867 Forwards amend to application for CP & OL. submitted as Amend 20 to FBAR REED.C Communwealth Edison Co. 79/05/02 2pp 7905040142 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Buppl " KEPPLER. J O Region 3, Chicago, Office of the Director, 79/04/21 --7905070574 Amend 20 to FSAR,
\* Commonwealth Edison Co 79/05/02, 430pp --7905040138 IE Bulletin 79-058, "Nuclear Incident at TMI-Suppl "
Supporting documentation encl.
Region 3, Chicago, Office of the Director 79/04/21 12pp 7903150331 Forwards affidavit of distribution for FBAR Amend 20 NAUGHTON, W F Commonwealth Edison Co 79/05/11. 2pp O Inspection reports. IE Bulletins & correspondence --7905040170 ACRS recommendations re 790328 incident at TMI Buggests high priority be placed on development of tafaty research on behavior of LWRs during anomalous transients \* ACRE - Advisory Committee on Reactor Safeguards. 79/04/17. 7905020421 Forwards response to IE Bulletins 78-12 & 78-12A. "Atypical Weld Hatl in Reactor Pressure Vessel Welds." REED.C. Communwealth Edison Co 79/03/22 10pp --7905040201 Forwards ACRS recommendations re TMI incident, presented on 7905010236 Forwards IE Info Notice 79-06. "Stress Analysis of Safety-Related Piping." KEPPLER.J.O Region 3. Chicago, Office of the Director 790417. FRALEY, R F ACRS - Advisory Committee on Reactor Safeguards. Region 3. Chicago: Office of the Director 79/03/23 --790504D22i In response to NRC 7904i8 ltr. states all 7904i7 ACRB recommendations apply to all PWRs. but were not intended to require immediate changes Plent mods should be made after study of effects on overall safety. TMI excluded, CARBON. M X ACRB - Advisory Committee on Reactor Safeguards. 79704/20. 2pp. 7905030370 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks.

KEPPLER, J O Region 3, Chicago, Office of the Director. 79/03/2 79/03/26. 10. 7905240740 Forwards IE Insp Repts 50-456/79-04 & 50-457/79-04 on 790320-21 & 23 No noncompliance. FIDRELLI, @ Region 9, Chicago, Reactor Construction & Engineering Support Branch 79/04/10. 2pp 7905240633 Forwards responses to IE Bulletin 79-07 requesting info re seismic analysis of safety-related piping Reanalysis 'indicates method of intramodal combination has little effect on pipe stresses & equipment support loads.

REED. C. Commonwealth Edison Co. 79/04/24 App -79051 No DOCKET 50-456 BRAIDWOOD STATION, UNIT 1 Dit A Application/construction stage documents & correspondence 790503 Sy : KEPP 7905040482 Notifies of intention to develop safety analysis using existing computer codes Requests additinfo BOLBRIO,C.W. Commonwealth Edison Co. 79/04/26. 1p. io. 790501 7908220337 Discusses fossil hunting program at facility. Number of passes will be reduced as const progresses to minimize possibility of injury & prevent interference w/const Special passes are available REED, G. Commonwealth Edison Go. 79/05/14. 2pp 10. 790504 Q. Adjudicatory correspondence 1p.

7905300032 Grants petitions to intervene filed by BL Rorem on behalf of Bailly Alliance & B Neiner Farms, Inc. Rejects K Hesterman's petition to intervene for failure to demonstrate standing.

LUTON: E. Atomic Safety and Licensing Board Panel 79/03/22. 4pp.

- 7905040529 Forwards IE Bulletin 79-08. "Events Relevant to Boiling Water Power Reactors Identified During TKI Incident "
  KEPPLER, J. G. Region 3. Chicago, Office of the Director. 79/04/14
- 7905010380 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts "
  KEPPLER, J G Region D. Chicago. Office of the Director 79/04/18
- 7905030206 Forwards IE Builetin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " Licensee action required. KEPPLER, J O Region 3, Chicago, Office of the Director. 79/04/17.
- 7905040142 Forwards IE Bulletin 79-058, "Nuclear Incident at TMF-Suppl"
  KEPPLER, J. G. Regian G. Chicago: Office of the Director 79/04/21
- ---790504015B IE Bullatin 79-05B. "Nuclear Incident at THI-Suppl "
  Supporting documentation encl
  \* Region G. Chicago, Office of the Director 79/04/21 12pp
- --7905040170 ACRB recommendations re 790328 incident at TMI Suggests high priority be placed on development of safety research on behavior of LMRs during anomalous transients # ACRB Advisory Committee on Reactor Safeguards. 79/04/17.
- --7903040201 Forwards ACRS recommendations to TMI incident, presented on 790417 FRALEY, R F ACRS - Advisory Committee on Reactor Bafeguards 79/04/18 1p
- ---7905040221 In response to NRC 79041B ltr.states all 790417 AGRS recommendations apply to all PMRs.but were not intended to require immediate changes. Plant mode should be made after study of affects on overall safety. TMI excluded. CARBON.M X ACRS Advisory Committee on Reactor Safeguards 79/04/20 2pg
- 7905240633 Forwards responses to IE Bulletin 79-07 requesting info re seismic analysis of safety-related piping Reanalysis indicates method of intramodal combination has little effect on pips stresses & equipment support loads.

  REED.C Commonwealth Edison Co 79/04/24 4pp

DOCKET 50-457 BRAIDWOOD STATION, UNIT 2

- A. Application/construction stage documents & correspondence
- 7809050087 Forwards NUREO-0219, "Nuclear Security Personnel for Power Plants, Content & Review Procedures for Security Training & Qualification Program." W/o encl. VASSALLO, D.S. Assistant Director for Light Water Reactors NUREO-0219 78/08/23 4pp
- 7905040482 Natifies of intention to develop safety analysis using axisting computer codes. Requests addl info.
  SOLBRIG.C W Commonwealth Edison Co 79/04/26 ip
- 7905220337 Discusses fossil hunting program at facility Number of passes will be reduced as const progresses to minimize possibility of injury & prevent interference w/const Special passes are evailable REED.C Commonwealth Edison Co 79/05/14 2pp.
- Q. Adjudicatory correspondence

, 1

44

1

The state of the s

- 7905300032 Grants patitions to intervene filed by BL Rorem on behalf of Bailly Alliance & B Neiner Farms. Inc. Rejects M Mesterman's patition to intervene for failure to demonstrate standing. LUTON.E. Atomic Safety and Licensing Board Panel. 79/03/22, 4pp.
- 7905250284 Request by util that ASLB schedule special prehearing conference per iOCFR2.751(a). Certificate of Svc encl. MURPHY:P.H Isham, Lincoln & Beale. 79/04/18. Spp.
- 7905240334 Responds to 790411 ltr re constituent petition to intervene in facility OL proceeding ASLB issued order on 790323 holding that B Neiner Fares had sufficiently demonstrated standing in proceeding.

  60881CK.L V. Office of the Erecutive Director for Operations.

  79705708. 2pp.

- H General correspondence
- 7905180655 Forwards 790327 itr from constituent 8 Meiner re petition to intervene in OL proceedings Requests assistance in preparation for intervention 0'BRIEN, G M House of Rep 79/04/11 3pp
- 7905100163 Endersement 99 to MAELU Policy MF-22 OERAS,T Nuclear Energy Liability Insurance Association 79/03/29 10.
- 7905070497 Confirms increased liability limit to \$124.000.000 for policies NF-1.25.43.76.83.100.111.140.146.151.141.164.164.170. 173.174.178.179.180.182.185.185.186.187.188.187.192.193.194.195.197.198.200.201.204.206.207.208.210.212.214.215.% others. QUATTROCHHI.J American Nuclear Insurers 79/05/01 tp
- 7905070582 Confirms increase in liability limit to \$36.000.000 for policies HF-22.26.29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96 ROBERTE, D H- Mutual Atomic-Energy Liability Underwriters, 79/05/01 19,
- K Utility Final Safety Analysis Report (FBAR) & amends
- 7905070557 Forwards amend to application for CP'& OL: submitted as Amend 20 to FBAR. REED,C. Commonwealth Edison Co. 79/05/02, 2pp
- --7903070574 Amend 20 to FBAR
  \* Commonwealth Edison Co 79/05/02 430pp.
- 7905150351 Forwards affidavit of distribution for FBAR AHend 20 NAUGHTON, W.F., Commonwealth Edison Co 79/05/11 2pg
- G. Inspection reports. IE Bulletins & correspondence
- 7905020421 Forwards response to IE Bulletine 78-12 & 78-12A, "Atypital Weld Mat1 in Reactor Pressure Vessel Welds"
  REED, C Commonwealth Edison Co 79/03/22 10pp
- 7905010236 Forwards IE Info Notice 79-06. "Btress Analysis of Safety-Related Piping" KEPPLER, J. O. Region 3, Chicago, Office of the Director 79/03/23
- 7903030370 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tants "
  KEPPLER, J. O. Region 3: Chicago, Office of the Director 79/03/26
- 7903240740 Forwards IE Insp Repts 50-456/79-04 & 50-457/79-04 on 790320-21 & 23.No noncompliance FIORELLI,0. Region 3. Chicago, Reactor Construction & Engineering Support Branch 79/04/10. 2pp
- --7905240748 IE Insp Repts 50-456/79-04 & 50-457/79-04 on 790320-21 & 21 No noncompliance noted Major areas inspected storage of N988 components & safety-related equipment, quality records for Class 2 & 3 equipment & automatic pipe welder operation, ERB.C.M., DANIELBON.D.H. Region 3, Chicago, Office of the Director 79/04/04 4pp.
- 7905030013 Forwards IE Bulletin 79-06, "Review of Operational Errors 5 8ys Misalignments Identified During TMI Incident." KEPPLER, J.O Region 3, Chicago, Office of the Director 79/04/11 19.
- 7903010369 Forwards IE Bulletin 79-06A, "Review of Operational Errors b Bys Misalignments Identified During TMI Incident " KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/04/L4
- 7905040334 Forwards IE Bulletin 79-068, "Review of Operational Errors L Sys Hisalignments Identified During THI Incident," KEPPLER, J. 9 Region 3, Chicago, Office of the Director, 79/04/14
- 7905040329 Forwards IE Bulletin 79-08, "Events Relevant to Bolling Water Power Reactors Identified During TMI Incident "
  KEPPLER, J. O. Region 3: Chicago, Office of the Director. 79/04/14

- 7905010380 Forwards IE Info Notice 79-10, "Nonconforming Pips Support Struts " KEPPLER, J Q
  - Region 3, Chicago, Office of the Director 79/04/18
- 7905030206 Forwards IE Bulletin 79-09, "Failures of QE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action
  - required. KEPPLER. J. O Region 3, Chicago, Office of the Director. 79/04/19
- 7905040142 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl. " Region 3, Chicago, Office of the Director 79/04/21
- --7905040158 IE Bulletin 79-05B. "Nuclear Incident at TMI-Buppl."

  Bupporting documentation encl

  Region 3. Chicago. Office of the Director 79/04/21. 12pp.
- --7905040170 ACRS recommendations re 790328 incident at TMI. Suggests high priority be placed on development of safety research on behavior of LMRs during anomalous transients. # ACRS Advisory Committee on Reactor Bateguards 79/04/17.
- -- 7905040201 Forwards ACRS recommendations re TMI incident, presented on 790417 FRALEY R F. ( ACRB - Advisory Committee on Reactor Safeguards.
- --7905040221 In response to NRC 790418 ltr.states all 790417 ACRB recommendations apply to all PMRs but were not intended to require immediate changes. Plant mode should be made after study of effects on overall safety. TMI excluded. CARBON. M.X. ACRS Advisory Committee on Reactor Safequards 79704720. 2pp.
- 7905240633 Forwards responses to IE Bulletin 79-07 requesting info re seismic analysis of safety-related piping Reanalysis indicates method of intramodal combination has little effect on pipe atreases & equipment support loads.

  REED, C. Commonwealth Edison Co 79/04/24 App.
- DOCKET 50-458 RIVER BEND STATION, UNIT 1
- A. Application/construction stage documents & correspondence
- 7903020437 Forwards NUREG-0531, "Investigation & Evaluation of Stress Corrosion Cracking in Piping of LWR Plants" & notice of issuance & availability
  VASSALLO, D B. Assistant Director for Light Water Reactors,
  79/03/23, 2pp.
- 7905150453 Notifies of reorganization of util's Engineering & Const Dept.JO Weigand has overall responsibility for River Bend Project. HUMPHREYB, L. L. Oulf States Utilities Co. 79/05/08 ip.
- 7905310429 Advises of delay from 790601 to 791231 in providing response to MRC Concerns re use of austenitic stainless steel in BMR facilities. Presently examining recommendations of pipe crack study in NUREO-0531.

  MEIGAND: J 0. Oulf States Utilities Co. 79/05/22. ip.
- 7905010277 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping" SEYFRIT.K.V. Region 4, Delias, Office of the Director. 79/03/23
- 7905010455 Forwards IE Bulletin 79-05A, "Nuclear Incident at TMI Buppl,"
  BEYFRIT, K. V. Region 4, Dallas, Office of the Director. Region 4, Dallas, Office of the Director. 79/04/05.
- 7903040489 Forwards IE Bullstin 79-068, "Review of Operational Errors & Bus Misalignments Identified During TMI Incident "
  BEYFRIT.K.V. Region 4, Dallas, Office of the Director. 79/04/14.
- 7903040610 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Idantified During THI Incident," BEYFRIT,K.V. Region 4, Dellas, Office of the Director. 79/04/14.

- 7905070050 Forwards IE Bulletin 79~07. "Seismic Stress Analysis of Safety-Related, Piping " Licensee action required, SEYFRIT, K. V Region 4. Dallas. Office of the Director 79/04/14.
- 7905010443 Forwards IE Info Notice 79-10. "Monconforming Pipe Bugport SEYFRIT.K V. Region 4. Dallas, Office of the Director 79/04/16
- 7905090098 Forwards suppl to IE Bulletin 79-05A, "Nuclear Incident at THI SEYFRIT K V Region 4. Dallas, Office of the Director 79/04/16
- 7905030267 Forwards IE Bulletin 79~09. "Pailures of GE Typs AK~2 Circuit Breaker in Safety~Related Bys." Licenses action SEYFRITAK V. Region 4, Dallas, Office of the Director 79/04/17
- B. Reportable occurrences, LERs & related correspondence
- 7905230808 Confirms 790327 telcon concerning potential deficiency resuspect caduald sleeve walds mfg by Graver Energy Sys.Will submit interim rept within 30 days.
  HUMPHREVS.L.L Quif States Utilities Co. 79/03/30 ip
- 7905030131 Forwards PNO-79-67H, I.J & K BEYFRIT, K V. Region 4, Dallas, Office of the Director 79/04/06 1P.
- 7905030089 Forwards PNO-79-67L, M.N & P. 8EIDLE, N.C. Region 4: Dallas, Reactor Construction & Engineering Support Branch 79/04/09, 1P.
- 7905030091 Forwards PNO-79-670.
  BEIDLE.W.C Region 4. Dallas. Reactor Construction & Engineering Support Branch. 79/04/10 ip.
- 7905030139 Forwards PNO-79-67R & 79-77.

  BEIDLE, N. C. Region 4. Dellas, Reactor Construction & Engineering Support Branch. 79/04/11. 1p
- 7903030117 Forwards PNO-79-678.

  BEIDLE.W.C. Region 4: Dallas: Reactor Construction & Engineering Support Branch 79/04/12 1p.
- 7905030186 Forwards PNO-79-67T.

  BEIDLE: H G. Region 4. Dallas: Reactor Construction & Engineering Support Brench. 79/04/13. 1p
- 7905030073 Forwards PNO-79-67U & V.
  ENGELKEN,R.H. Region 4: Dallas: Reactor Construction & Engineering Support Branch, 79/04/16, 1P.
- 7403030238 Forwards PNO-79-67W.
  SEIDLE, W. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/04/17. 1p
- 7905020328 Forwards PNO-79-67AA.
  8EIDLE: M.C Region 4. Dailes: Reactor Construction & Engineering Support Branch. 79/04/20. ip.
- 7905020498 Forwards PNO-79-67AB: AC & AD SEIDLE: W.C. Region 4: Dallas: Reactor Construction & Engineering Support Branch. 79/04/23. ip.
- 7905040594 Porwards PND-79-67AE

  8EIDLE, N. C. Region 4, Dallas, Reactor Construction & Engineering

  Bupport Branch. 79/04/26. ip.
- 7905070180 Forwards PNO-79-67AF & AG. BEIDLE.W.C. Region 4, Dallas. Reactor Construction & Engineering Support Branch. 79/04/27. 1p.
- 7905310226 Forwards PNO-79-67AH.AI & AJ.
  8EIDLE, M. C. Region 4. Dallas, Reactor Construction & Engineering Support Branch. 79/04/30. 1p.
- 7905240394 Forwards PNO-79-67AK & AL.
  SEIDLE, N.C. Region 4: Dallas, Reactor Construction & Engineering Support Branch. 79/05/04. 1p.

DOCKET 50-459 RIVER BEND STATION, UNIT 2

- A Application/construction stage documents & correspondence
- 7905020407 Forwards NUREO-0531, "Investigation & Evaluation of Stress Corroston Cracting in Piping of LMR Plants" & notice of issuance & availability VASSALLO, D B Assistant Director for Light Water Reactors 79/00/23 2pp

- 7905150453 Natifies of reorganization of util's Engineering & Const Dept JO Waigand has overall responsibility for River Bend project HUMPHREYS.L L Gulf States Utilities Co 79/05/08 ip
- 7905310429 Advises of delay from 790601 to 791231 in providing response to NRC concerns re use of austenitic stainless steel in BUR facilities Presently examining recommendations of pipe crack in MUREG-0531 Gulf States Utilities Co 79/05/22 1p
- G Inspection reports, IE Bulletins & correspondence
- 7905010277 Forwards IE Info Notice 79-06. "Stress Analysis of Safety-Related Piping \*
  SEYFRIT.K V Region 4. Dallas. Office of the Director 79/03/23
- 7905010455 Forwards IE Bulletin 79-05A: "Nuclear Incident at TMI Suppl"
  SEYFRIT, K V. Region 4. Dallas. Office of the Director Region 4: Dallas, Office of the Director 79/04/05
- 7903040489 Forwards IE Bulletin 79-068. "Review of Operational Errors & Bys Misalignments Identified During TMI Incident "
  SEYFRIT.K V Region 4. Dallas, Office of the Director 79/04/14
- 7905040610 Forwards IE Bulletin 79-08, "Evente Relevant to Boiling Water Power Reactors Identified During TMI Incident " SEYFRIT,K V Region 4. Dallas. Office of the Director 79/04/14
- 7905070050 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piging " Licensee action required, SEYFRIT:K V Region 4: Dallas: Office of the Director 79/04/14
- 7905010443 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support SEYFRIT.K V. Region 4: Dallas: Office of the Director 79/04/16
- 7905090098 Forwards suppl to [E Bulletin 79-05A, "Nuclear Incident at TMI " SEYFRIT: K V. Region 4. Dallas. Office of the Director 79/04/16
- 7705030267 Forwards IE Bulletin 77-09. "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " Licensee action BEYFRIT K V Region 4: Dallas, Office of the Director 79/04/17.
- 8 Reportable occurrences. LERs & related correspondence
- 7905030131 Forwards PNO-79-67H.I.J & K SEYPRIT.K V Region 4. Dallas. Office of the Director 79/04/06. IP
- 7903030089 Forwards PNO-79-67L, M.N & P
  SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering
  Support Branch 79/04/09 iP.
- 7905030091 Forwards PNO-79-67G SEIDLE,W C. Region 4. Dalles, Reactor Construction & Engineering Support Branch. 79/04/10 1p
- 7905030139 Forwards PNO-79-67R & 79-77, 8EIDLE,N.C Region 4, Delias, Reactor Construction & Engineering Support Branch. 79/04/11 ip.
- 7903030117 Forwards PND-79-678
  BEIDLE,W.C. Region 4. Dallas, Reactor Construction & Engineering Support Branch, 79/04/12 ip.
- 7905030186 Forwards PND-79-67T BEIDLE.W.C. Region 4, Delles, Reactor Construction & Engineering Support Branch 79/04/13, 1p.

- 7905030073 Forwards PNO-79-67U & V ENGELMEN.R H Ragion 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/16 1P
- 7905030238 Forwards PND-79-67W SEIDLE:W C Region 4. Dallas, Reactor Construction & Engineering Support Branch 79/04/17 ip
- 7705020328 Forwards PNO-79-67AA SEIDLE:W C Region 4. Dallas, Reactor Construction & Engineering Support Branch 79/04/20 ip
- 7705020498 Forwards PND-79-67AB, AC & AD
  SEIDLE, W G Region 4, Dallas, Reactor Construction & Engineering
  Support Branch 79/04/23 ip
- 7905040584 Forwards PNO-79-67AE BEIDLE,W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/26 ip
- 7905070180 Forwards PNO-79-67AF & AQ. BEIDLE.W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/27 ip
- 7903310226 Forwards PNO-79-67AH.AI & AJ
  BEIDLE, H C Region 4, Dallas, Reactor Construction & Engineering
  Support Branch 79/04/30 ip
- 7905240394 Forwards PND-79-67AK & AL SEIDLE,W C Region 4. Dallas, Reactor Construction & Engineering Support Branch 79/05/04 Ip
- DOCKET 50-460 MPPSS NUCLEAR PROJECT: UNIT 1
- A Application/construction stage documents & correspondence
- 7905010486 Repts on geological studies' status Generic regt expected in Fall 1979 Requests meeting to discuss plans for submitting repts of studies as well as mechanism for identification & neview of studies in Hanford area. RENBERGER, D L. Washington Public Power Supply System 79/04/27.
- 7905240411 Forwards NRC positions on MPP88-GA-004, "Operational GA Program Description." Response to positions should be submitted by 790601 as amend to original rept. HAASB-W P Guality Assurance Branch 79/05/01. 2pp
- 7703230834 Requests NRC itr stating acceptability of scale model to in lieu of implant tests, to satisfy commitment in WNP-1/4 PSAR Guestion 6 77 re recirculation sump testing.
  RENBERGER, D L Washington Public Power Supply System 77/03/13.
- 7905010274 Forwards IE Info Notice 79-06, "Stress Analysis of Safaty-Related Piping"
  ENGELKEN.R.H. Region 4, Dailas, Office of the Director 79/03/23
- 7905010015 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Bys Misalignments Identified During THI Incident "
  ENGELKEN.R H. Region 5, San Francisco, Office of the Director 79/04/14. ip
- 7905040516 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident." ENGELKEN.R H Region 5, Sen Francisco, Office of the Director 79/04/14. ip.
- 7903040625 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident "
  ENORLKEN,R H. Region 5, Ban Francisco, Office of the Director 79/04/14
- 7905070110 Forwards [E Bulletin 79-07, "Belemic Stress Analysis of Bafaty-Related Piping " Licensee action required. ENGELKEN.R.H Region 5, Ban Francisco, Office of the Director. 79/04/14. 1p.
- 7905030305 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Bys." Licenses action Circuit area, required, ENGELKEN, R. H, Region 5, San Francisco, Office of the Director. 79/04/17
- 7905080378 Forwards IE Bulletin 79-058, "Nuclear Incident at THI-Buggl," ENGELKEN, R H. Region 5, Ban Francisco, Office of the Division of the Region 5, San Francisco, Office of the Director. 79/04/21.

- 7905150069 Forwards PND-79-67L ENGELMEN.R H Region 5. San Francisco. Office of the Director 79/04/04 1p
- 7903130173 Forwards PNO-79-67R ENGELKEN.R. H Region 5. San Francisco, Office of the Director 79/04/11 ip
- 7905040134 Forwards PND-79-678 ENGELMEN,R H Region 5, San Francisco, Office of the Director 79/04/12 ip
- 7905130150 Forwards PNG-79-67T ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/04/13 ib
- 7905030018 Forwards PND-79-67U ENGELMEN.R.H Region 5. San Francisco. Office of the Director 79/04/14 ip
- 7905020536 Forwards PNO-79-67AA ENGELMEN.R H Region 5. San Francisco, Office of the Director 79/04/20 1p
- 7905010439 Forwards PNO-79-67AB ENGELKEN.R.H Region 5, San Francisco, Office of the Director 79/04/21 1p
- 7905010452 Forwards PNO-79-47AC & AD ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/04/23 1p.
- 7905010463 Forwards PNO-79-67AE ENGELMEN.R.H Region 5. Ban Francisco, Office of the Director, 79/04/24 1p.
- 7705090047 Forwards PNO-79-67AF.
  ENGELKEN,R H Region 5. San Francisco. Office of the Director
  79/04/25 ip
- 7905090059 Forwards PNO-79-67AG ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/04/26 1p
- 7905090121 Forwards PNU-79-67AH ENGLEMEN.R H Region 5. San Francisco, Office of the Director 79/04/27. ip
- 7905070034 Forwards PNO-79-67AI, AJ & AK per NRC 790401 ltr transmitting IE Bulletin 79-05 .
  ENGELMEN, R H Region 5, Ban Francisco, Office of the Director 79/04/30 io.
- 7905070018 Forwards PNO-79-67AL per NRC 790401 ltr transmitting IE Bulletin 79-05. ENGELKEN,R H Region 5. Ban Francisco. Office of the Director. 79/03/01 10.
- 7905190067 Forwards final deficiency rept re letdown cooler supports, per 790416 telcon RENBERGER, D.L. Washington Public Power Supply System. 79/05/07 to.
- ---T905190069 Final deficiency rept.letdown cooler supports imadequate to support specified loads.Caused by inadequate design by component manufacturer Wall mounted brackets redesigned.

  \* Washington Public Power Supply System. 79/05/07 2pp.
- 7905310037 Forwards PND-79-67AM. ENGELEEN,R H. Region 5, San Francisco, Office of the Director 79/05/07. ip.
- 7905240657 Ack receipt of 790507 final deficiency rept on letdown cooler support design inadequacy.

  ENGELKEN.R.H. Region 3, Ban Francisco, Office of the Director.
  79/05/16 ip
- DOCKET 50-461 CLINTON POHER STATION, UNIT 1

  A Application/construction stage documents & correspondence
- 7903290863 Notifies of proposed reactor pressure vessel mod GE authorized to act as agent for performance of work which will be subcontracted to Reactor Controls Inc. Work to begin 790319.

  KOCH-L J. Illinois Power Co. 79/03/15. 1p

- 7905040330 Requests addl info re 790426 teleon concerning emission stds for operating nuclear power plants Seeks info re gaseous release of U daughters & stds for emission of radioactsve products into cooling water PENNER, P Prairie Alliancs, 79/04/26 2pp
- G. Inspection reports. IE Bulletins & correspondence
- 7905040347 Forwards IE Insp Rept 50-461/79-02 on 790306-08 Na noncompliance noted FIORELLI.G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/03/22 2pp
- ---7905040349 IE Insp Rept 50-461/79-02 on 790306-08 No noncompliance noted Major areas inspected reactor coolant pressure boundary, sefety-related piping & welding, GA manuals & procedures & work activities

  LEE.E W Region G, Chicago, Office of the Director DANIELBON, DH Region G, Chicago, Reactor Construction & Engineering Support Branch 79/03/19 Spp
- 7905010257 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piging."

  KEPPLER, J G Region G, Chicago, Office of the Director 79/03/23 ip
- 7905040035 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks "
  KEPPLER, J G Region 3, Chicago, Office of the Director 79/03/26
- 7905030033 Forwards IE Bulletin 79~06, "Review of Operational Errors & Bus Misalignments Identified During TMI Incident "
  KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/11
- 7905010590 Forwards IE Bulletin 79-06A. "Review of Operational Errors & Bys Misalignments Identified during TMI Incident "
  KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14
- 7905040394 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "
  KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/14
  ip.
- 7905040459 Forwards IE Bulletin 79-07, "Beismic Stress Analysis of Safety-Related Piping " Licensee action required KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/04/14
- 7905040566 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."

  KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/14,
- 7905010426 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts " KEPPLER, J O Region 3, Chicago, Office of the Director. 79/04/16
- 7905030228 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " Licensee action required KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/04/17.
- 7905080498 Forwards IE Bulletin 79-058. "Nuclear Incident at THI-Suppl."
  KEPPLER.J.G. Region 3. Chicago, Office of the Director, 79/04/21
- 7905240906 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Recirculation Motor Generator Set Resulted in Reactor Power Increase "KEPFLER, J. O Region 3, Chicago, Office of the Director, 79/05/02
- S. Reportable occurrences, LERs & related correspondence
- 7905290048 Ack receipt of 790307 final rept re drywell wall platework defects Review will be completed during future insp. FIORELLI, 0 Region 3, Chicago, Reactor Construction & Engineering Support Branch 79703/23. ip.

- DOCKET 50-462 CLINTON POWER STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 7905040330 Requests additinfore 790426 teleon concerning emission stds for operating nuclear power plants Easts infore gaseous release of U daughters & stds for emission of radioactive products into cooling water PENNER, P Prairie Alliance 79/04/26 2pp
- G Inspection reports, IE Bullstins & correspondence
- 7905010257 Forwards IE Info Notice 79-06. "Stress Analysis of Safety-Related Piping." KEPPLER, J O Region 3. Chicago. Office of the Director 79/03/23
- 7905040035 Forwards IE Info Notice 79-07. "Rupture of Radwasts Tanks "
  KEPPLER, J Q. Region 3, Chicago, Office of the Director 79/03/26
- 7905030033 Forwards IE Bullstin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "
  KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/11.
- 7905010590 Forwards IE Bulletin 79-06A. "Review of Operational Errors & Sys Misalignments Identified during TMI Incident " KEPPLER, J O Region 3. Chicago, Office of the Director 79/04/14
- 7905040394 Porwards IE Bulletin 79~04B, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident " KEPPLER.J G Region 3. Chicago. Office of the Director 79/04/14
- 7905040459 Forwards IE Bulletin 79-07, "Beismic Stress Analysis of Bafety-Related Piping "Licensee action required KEPPLER, J. G Region 3, Chicago, Office of the Director 79/04/14 is.
- 7905040566 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Mater Power Reactors Identified During TMI Incident "
  KEPPLER. J. O. Region 3, Chicago, Office of the Director 79/04/14
  is.
- 7905010426 Forwards IE Info Notice 79-10, "Nonconforming Pipe Bupport Struts."

  KEPPLER, J. O Region 3, Chicago, Office of the Director 79/04/16
- 7905030228 Forwards IE Bulletin 79-09, "Failures of QE Type AK-2 Circuit Breaker in Bafety-Related Sys." Licenses action required. KEPPLER. J. C. Region G. Chicago. Office of the Director. 79/04/17
- 7905080498 Forwards IE Bulletin 79-058. "Nuclear Incident at THI-Bupp1" KEPPLER.J. C. Region G. Chicago, Office of the Director. 79/04/21. 19
- 7705240906 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Recirculation Motor Generator Set Resulted in Reactor Power Increase "
  KEPFLER, J G Region S, Chicago, Office of the Director. 79/05/02.
- DOCKET 50-469 FULTON GENERATING STATION: UNIT 1
- 9. Adjudicatory correspondence
- 7905250153 Updates 790302 ltr.advising 10CFR is available in Pottstown: PA Public Library GRAY, J. R. Branch 1 79/04/09. 1p.
- 7905150114 Discusses notifications not previously supplied in hearings re nuclear power reactors specifically Lewis Committee Rept & transportation of radionuclides in urban environs. GRAY, J. R. Branch 1 79/04/10. 3pp
- --7905150119 Ack receipt of GH Zimmer memo re neutron exposure at commercial power reactors Data does not imply lack of control by any licensee re neutron exposure) nor does it indicate personnel neutron dosimetry problem exists at LHRs. EISENHUT, D.O. Division of Operating Reactors. VOLLMER, R. H. Assistant Director for Site Analysis. 79/03/06, 2pp

- --7903150139 States that encl 780508 article by J Anderson, "Neutron Radiation at Nuclear Plants" contains factual errors No calculations have been made of neutron radiation inside nuclear plants Forwards EQ Case 780403 memo KREGER: N E Commission 78/05/08, 3pp
- 7903230246 Forwards into re behavior of iodine during postulated stream generator tube rupture accidents & aspects of accumulator delivery GRAY.J R Branch 1 79/04/10 700
- 7905230591 Ack receipt of 790402 itr & resolution opposing NRC early site suitability review NRC will consider issues raised DEYOUNG, R C. Division of Bite Safety & Environmental Analysis 79/04/19 ip
- --7905230595 Forwards resolution opposing early site suitability pryies OALBREATH.P Fulton Grange #66. 79704/02. 2pp
- H General correspondence
- 7905150124 Responds to comments re opposition to facility location NRC is required to conduct an early site review on site suitability issues selected by applicant & does not have initiative in this matter BALLARD, R L Environmental Projects Branch 1 79/04/30 is
- J Insurance & indemnity information
- 7905070382 Confirms increase in liability limit to 836,000,000 for policies MF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,56,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,68,90,91,92,93,94,95 & 96 ROBERTS,D M Mutual Atomic Energy Liability Underwriters 79/05/GI
- DOCKET 50-464 FULTON GENERATING STATION, UNIT 2
- O Adjudicatory correspondence
- 7905250153 Updates 790302 ltr.advising 10CFR is available in Pottstown PA Public Library. GRAY.J R. Branch 1. 79/04/09. ip,
- 7905150114 Discusses notifications not previously supplied in hearings re nuclear power reactors: specifically Lewis Committee Rept & transportation of radionuclides in urban environs GRAY.J. R Branch 1, 79/04/10 3pp
- --7905130119 Ack receipt of GW Zimmer memo re neutron exposure at commercial power reactors Data does not imply lack of control by any licenses re neutron exposure nor does it indicate personnel neutron dosimetry problem exists at LLMs. EISENHUT, D.Q. Division of Operating Reactors. VOLLMER, R.M. Assistant Director for Site Analysis 79/03/06 2pp
- --7905150139 States that encl 780508 article by J Anderson, "Neutron Radiation at Nuclear Plants" contains factual errors. No calculations have been made of neutron radiation inside nuclear plants. Forwards EQ Case 780403 memo. KREGER, W. E. Commission 78/05/08, Spp.
- 7905230246 Forwards info re behavior of lodine during postulated state generator tube rupture accidents & aspects of accumulator delivery ORAY.J R. Brench 1. 79/04/10, 7pp
- 7905230591 Atk receipt of 790402 ltr & resolution opposing NRC early site suitablity review NRC will consider issues raised. DEYOUNG, R C. Division of Site Sefety & Environmental Analysis 79/04/19 ip
- --7905230595 Forwards resolution opposing early site suitability revise GALBREATH.P. Fulton Grange #66 79/04/02. 2pp.
- H. General correspondence
- 7903130124 Responds to comments re opposition to facility location NRC is required to conduct an early site review on site suitability issues selected by applicant & does not have initiative in this matter.

  BALLARD.R.L Environmental Projects Branch 1, 79/04/30. Is

#### J Insurance & indemnity information

- 7905070497 Confirms increased liability limit to \$124,000,000 for policise NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,185,186,187,188,189,192,193,194,195,197,198,200,201,204,206,207,208,210,214,215,& others.

  OUATTRUCHHI, J American Nuclear Insurers, 79/05/01 ip.
- 7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,54,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,41,92,93,94,95 & 96,
- DOCKET 50-466 ALLENS CREEK NUCLEAR STATION, UNIT 1

  A. Application/construction stage documents & correspondence
- 7908250398 Forwards addi info re reactor pressure vessel off-loading facility, in response to 790328 request,
  MCGUIRE: H F Houston Lighting & Power Co. 79/05/17 8pp
- 7905310453 Responds to 790426 ltr & updates 771017 list of proposed & listed endangered species. Bald eagles now listed as endangered in TX. Requests biological assessment within 180 days of listed species in plant const
- E. NRC Bafety Evaluation Report (SER), suppls & correspondence
- 7905090299 Forwards Suppl 2 to BER re application for CP. N/o encl. VARQA, 8 A Light Mater Reactors Branch 4 79/04/09 3pp.
- 9 Adjudicatory correspondence
- 7903210381 Urges ABLB to modify 790212 order.grant JH Doherty's intervention petition & admit Contention 2 Certificate of Byc enci.
  BOHINKI,B M. Branch 3 79/03/06. 9pp.
- 7703080387 Request by Houston Lighting & Power that ABLB dany 770214 motion by JF Doherty & Armadiilo Coalition for admission of previously abandoned contentions Certificate of Svc encl CLULP.R.N., NEHMAN, J.R. Lowenstein, Newman, Reis, Akelrad & Toll. COPELAND, J. Q. Baker & Botts 79/03/06. 7pp
- 7908310013 Response in opposition to TX PIRO 790202 motion for admission of two contentions previously abandoned due to Class 9 accident prohibition based on Rasmussen Rept. Cartificate of Bvc encl. BOMINKI, S.M. Branch 2 79/03/08, 9pp
- 790B0B0331 Houston Lighting & Power's first set of interrogatories & request for production of documents for TX PIRO. Certificate of Byc encl.
  COPELAND, J. Q. Bater & Botts. NEWMAN, J. R., CULP, R. H.
  Lowenstein, Newman, Reis, Axelrad & Toll. 79/03/13. 28pp
- 7705060311 Request by Houston Lighting & Power that ASLAB deny appeals of eight positions for intervention; filed in response to ALSB 770209 order. Certificate of Svc encl. NEWHAN, J.R., REISH, F., CULP, R. H. Lowenstein, Newman, Reis, Azelrad & Toil. 79/03/15. 46pp.
- 7903080320 Request by Houston Lighting & Power that ASLAB deny 790223 patition for directed certification fixed by TX PIRO. Patition does not meet criteria of 100FR2. 718(i). Certificate of 80c encl.

  NEWMAN, J. R. . REIS, H. F. , CULP, R. H. Lowenstein, Newman, Reis, Axeirad & Yoll. 79/03/13. 35pp.
- 7903080392 Requests ASLAB deny 790223 petition of TX PIRO for directed certification. Interlocutory review of question is not needed or proper, Certificate of Bvc encl.

  WOODHEAD, C. P. Branch 3, 79/03/19, 14pp.
- 7903240178 Request to file brief amicus curiae. Certificate of 8vc snci. ROISMAN.A.Z. Natural Resources Defense Council. PARKER.D.L., IBCOE.D. Georgetown Univ. Law School. 79/03/19. 4pp.

- 7905150087 Answers first set of interrogations & request for production of documents from Houston Lighting & Power Certificate of Syc encl.
  HINDERSTEIN.C. Affiliation Unknown 79/03/26 2pp.
- 7905230130 Motion for admission of C Hinderstein's Contention 3 Certificate of 8vc enci HINDERSTEIN.C Affiliation Unknown 79/03/26 3pp
- 7905250230 Houston Lighting & Power's response to TX PIROs first set of interrogatories. Certificate of Svc and COFELAND, J. O., THRASH, C. O. Baker & Botts NEWMAN, J. R. Lowenstein, Newman, Reis, Akelrad & Toll 79/03/2
- 7905300172 Response to first set of interrogatories submitted by Houston Lighting & Power Certificate of Svc encl DCHERTY, J. F Texas Public Interest Research Group 79/03/27 App
- --7903300177 First request for production of documents from Houston Lighting & Power Certificate of Svc encl SCOTT.J.M. Texas Public Interest Research Group 79/03/27 2pp
- 7905250135 Answers to interrogatories submitted to B McCorkie by Houston Lighting & Power Co. Certificate of Byc encl MCCORKLE, B A Affiliation Unknown, 79/03/28, 2pp
- 7905250225 Request by Houston Lighting & Power Co for denial of 790324 motion by C Hinderstein & B McCorkle for 1-month extension of time for discovery Certificate of Bvc encl NEUMAN, J R., REIG, H F., CULP, R H Lowenstein, Newman, Reis, Azelrad & Toll 79/03/28 Spp.
- 7903240360 Second set of interrogatories & requests for production of documents submitted to Houston Lighting & Power Certificate of Svc encl
  HINDERSTEIN: C Affiliation Unknown 79/03/29 6pp.
- 7905240120 Requests to make statement at 790418 hearing.Requests proponents of Wallis Trade Territory be allowed to speak MAYER.B M Affiliation Unknown 79/03/30 ip.
- --7905240124 Requests to make statement at 790418 hearing MILLS, S Affiliation Unknown 79/04/10 2pp
- --7905240132 Requests to make statement at 790418 hearing. MUELLER,E E Affiliation Unknown 79/04/03 ip
- ---7905240141 Requests to make statement at 790418 hearing FUNDERBURKE,W H Affiliation Unknown 79/04/09 1p
- 7903310409 Consolidates TX PIRO & RC Hinderstein as intervenors.

  B McCorkle has until 790417 to complete discovery recontentions of TX PIRO & C Hinderstein; C Hinderstein must complete discovery by 790502

  WOLFE, B. J. Atomic Safety and Licensing Board Panel. 79/03/30 3pp
- 7903250242 First round of interrogatories submitted to State of TX. Certificate of Svc encl.
  SCOTT.J M Texas Public Interest Research Group. 79/03/31 3pp.
- 7905310042 First set of interrogatories & requests for production of documents submitted to State of TX Certificate of Svc encl. HINDERSTEIN.C. Affiliation Uninown, 79/03/31. 5pp.
- --7705310077 Third set of interrogatories & requests for production of documents submitted to util.
  HINDERSTEIN.C. Affiliation Unknown. 79/03/31, 4pp.
- --7905310080 First set of interrogatories & requests for production of documents submitted to NRC.
  HINDERSTEIN.C. Affiliation Unknown. 79/03/31. 3pp
- 7905310116 Request for production of documents & first set of interrogatories submitted to Houston Lighting & Power. Certificate of Svc encl. MCCORKER.B. Affiliation Unknown. 79/04/01 4pp.
- ---7905310123 Request for production of documents & first set of interrogatories submitted to State of TX MCCORKLE.B. Affiliation Unknown. 79/04/01. 2pp.
- 7908100276 Response to first set of interrogatories propounded by TX PIRO. Supporting documentation & Certificate of Svc encl. SCHINKI.S.M. Branch 3. 79/04/02. 22pp.

- 7903110339 Motion to assume Contentions 2 & 3 re const hearing license raised by intervenor JR Schreffler
  800TT.J M Texas Public Interest Research Group 79/04/02 2pp.
- 7905300066 Response of util to first interrogatories submitted by C Hinderstain Certificate of Svc encl COPELAND, J O . THRAGH.C O Baker & Botts NEWMAN.J R. Lowenstain.Newman.Reis.Azelrad & Toll. 79/04/02 Ppp
- 7905300072 Propounds interrogatories to TX PIRO Certificate of Svc encl. 80HINKI,8 M Branch 3 79/04/02 3pp
- 7905310111 First set of interrogatories & request for production of documents submitted to Houston Lighting & Power Certificate of Svc encl
  WHITE.M., FAINTER, J. W., LOWERRE, R. W. Texas, State of 79/04/02
  700
- 7905310407 Response by util to second set of interrogetories from TX PIRO Certificate of Svc encl COPELAND, J O , THRASH, C.O Baker & Botts NEWMAN, J R Lowenstein, Newman, Reis, Azelrad & Toll 79/04/02 lipp
- 7905310382 Motion to postpone 790419 prehearing conference until completion of inquiry re-accident at TMI DOMERTY.J.F Affiliation Unknown 79704/64 App
- 7905110336 Supplemental contention re lack of strength of steel containment shell DOMERTY, J. F' Affiliation Unknown 79/04/05 2pp
- 7705250161 Motion for admission of supplemental contention re strength of steel containment shell Intervenor asserts that petition is timely Certificate of Svc encl.
  DOMERTY, J. F. Affiliation Unknown 79/04/05. 2pp
- 7905290068 Applicant's response to TX PIRG's undated motion to gostpone further pretrial steps except for discovery Urges denial of motionTX PIRG does not offer justification for delay Certificate of Svc encl CDPELAND. J G. THRASH, C G Baker & Botts NEWMAN. J R Lowenstein Newman, Reis. Atelrad & Toll 79/04/05 6pp
- 7905310381 First request for production of documents to Houston Lighting & Power Co DOMERTY, J F. Affiliation Unknown 79/04/05 ip.
- 7905220057 Notifies of Intention to make oral statement before ASLS on 790418. BREMAECKER, D. E. Affiliation Unknown 79/04/06. ip
- 7905:50:85 First set of interrogatories & second set of requests for documents submitted to Houston Lighting & Power Certificate of Svc encl.

  DOHERTY, J. F Affiliation Unknown. 79/04/09 3pp
- 7905140060 Response to first set of interrogatories from TX PIRO. Certificate of Svc & supporting documentation encl MHITE.M., FAINTER, J W., LOHERRE, R W. Taxas, State of 79/04/10
- 7905230729 Requests appearance at 790418 prehearing conference in Houston, TX.
  BERGGREN, J Affiliation Unknown. 79/04/10 ip.
- ---7905230736 Requests appearance at 790418 prehearing conference in Houston, TX.
  LEWIG. E. A. Affiliation Unknown, 79/04/11, 2pp
- --7903230744 Profession const of facility.
  BILLINGTON.O , PICKINGTON.C. Affiliation Unknown
  - icility, Expresses concern for public lwn. 79/04/19, 2pp.
  - equiry into Allegation of Employee stigation to Determine ing St Lucie " W/o encl. 04/ii. ip.
  - tions as issues in controversy.es .Parties have 30 days to Rescinds due dates for
  - tomic Safety and Licensing Board Panel.

- 7905100:23 Informs of opposition to applicant's request for reconsideration of ASLB order canceling prehearing conference Order is reasonable, in light of issuance of ALAB-935
  80HINKI,8 M Branch J 79/04/12 2pp
- 7905140057 Motion by util for reconsideration of 790404 ALAB-835, as reversed & remanded to ASLB for further consideration Decision creates significant uncertainty re ASLB procedures Certificate of SVc encl NEWMAN, J.R., REIS, H.F., CULP, R.H., Lowenstein, Newman, Reis, Ayelred & Toll 79/04/12, 10pp
- /905100146 Forwards info re procedures involved in making limited appearance statements, in response to 790402 request SOHINKI,S H Branch 3, 79/04/13 2pp.
- 7905230477 Submits contentions re reactor safety. Believes FES is totally indequate FRANSON, R S . FRANSON, M B Affiliation Unknown 79/04/13 3pp.
- 7905240201 Forwards denial of suspension of facility CF Hupporting documentation encl
  DENTON,H R. Office of Nuclear Reactor Regulation 79/04/13 ipp
- --7905240211 Director's denial of 10GFR2 206 request. BOYD.R S Office of Nuclear Reactor Regulation 79/04/13 Bpp.
- --7905240219 Analysis of need for facility.

  \*\* Division of Site Safety & Environmental Analysis 79/04/13
- --7903240227 Responds to RH Froelich 781207 request Forwards matl on Georgians Against Nuclear Energy request to suspend facility CP. WHITMER, C F Georgia Power Co. 78/12/19 13pp
- --7905240232 TX PIRO's motion for admission of 781101 add1 Contention ( SCOTT, J M Texas Public Interest Research Group, 79/03/22. 3pp
- 7905230735 Expresses apposition to facility const Requests development of alternate sources of energy.
  ANDRUS, M. HICHAELS, N. , LOTZ, J. B., Affiliation Unknown. 79/04/16
- 7905240296 Response to TX PIRO brief supporting admission of renumbered Contention 12 re fire in wiring. Concurs that cable fires should be admitted as issue in controversy. Certificate of Svc encil SDHINKI.S.M Branch 3 79/04/17. 7pp
- 7905240149 Ack receipt of mailgram requesting copy of ALAB-335 which was submitted when ABLB issued ruling on 790404. BOHINKI, 8 M. Branch 3 79/04/18, 1p.
- 7905220071 Admits TX PIRO Contention 12 as issue in controversy.
  Discovery procedures shall begin immediately.
  WOLFE, B. J. Atomic Bafety and Licensing Board Panel. 79/04/19. 3pp
- 7905240310 Answers by Houston Power & Lighting to third set of interrogatories & requests for production of documents from intervenor C Hinderstein, Certificate of Svc encl COPELAND. J G THRASH. C. G. Baker & Botts NEHMAN, J. R Lowenstein, Newman, Reis, Assirad & Toll 79/04/19. 7pp.
- 7705100391 Requests by Houston Power & Lighting for denial of MRC 770418 motion for clarification of ALAB-535, Also requests that those matters be treated in ruling on util's motion for reconsideration. Certificate of Svc encl.
  NEWHAN, J. R., REISH, F., CULP, R. H. Lowenstein, Newman, Reis, Axelrad & Toil, 79/04/20, Spp.
- 7905240043 Answers by Houston Lighting & Power Co to first est of interrogatories & request for production of documents from intervenor B McCorkie. Affidavit & Certificate of Svc encl. CDPELAND. J O , THRASH. C. O., NEWMAN, J. R. Bater & Botte 79/04/20 1000.
- 7908240363 Notifies that ASLB orders of 790326.790412 & 790416 have not yet been received causing delay in response to ASLB order to perfect contentions to 30 days from date of receipt, Requests placement on syc list, DCHERTY, J. F. Affiliation Unknown 79/04/23. 1p
- 7903240328 Supports admission of UF Doherty 790405 supplemental contention re strength of steel containment shells. Certificate of Syc encl. SCHINKI/S.M. Branch 3. 79/04/23. 4pp

enci copeland, J G Baker & Botts, NEHMAN, J R , CULP, R H Lowenstein, Newman, Reis, Axelrad & Toll 79/04/27 10pp

7909230247 Moves for extension of time in which to submit contentions Supporting info encl POTTHOFF, F H Affiliation Unknown 79/05/07 4pp

DOCKET 50-467 ALLENS CREEK NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

7905250398 Forwards add1 info re reactor pressurs vassel off-loading facility. In response to 790388 request HCQUIRE,W F Houston Lighting & Power Co 79/05/17 Spp

7905310453 Responds to 790426 itr & updates 771017 list of proposed & listed endangered species Bald eagles now listed as endangered in TX Requests biological assessment within 180 days of listed species in plant const area MODLETERNHUMELJ Interior, Dept of, Fish & Wildlife Service 79705/22 2pg

# Adjudicatory correspondence

7903140060 Response to first set of interrogatories from TX PIRC Cartificate of Svc & supporting documentation encl WHITE: M . FAINTER, J W . LOWERRE, R W. Texas, State of 79/04/10 26pg

7905230729 Requests appearance at 790418 prehaaring conference in Nouston.TX BERGOREN.J. Affiliation Unknown. 79/04/10 ip

~~7905230736 Requests appearance at 790418 prehearing conference in Houston, TX. LENIS,E A. Affiliation Unknown 79/04/11 2pp.

~~7905230744 Protests const of facility TROCHEBBET.K P., BILLINGTON.G., PICKINGTON,G. Affiliation Unknown 79/04/13. ip

---7905230761 Opposes const of facility Expresses concern for public safety in event of mishap MARTIN A Affiliation Unknown 79/04/19, 2pp

DOCKET 80-471 PILORIM NUCLEAR POWER STATION, UNIT 2

A. Application/construction stage documents & correspondence

7908240794 Forwards info requested in 790420 discussion re evacuation of Cape Cod summer population
BURT-L. Massachusetts, Stats of 79/04/25 App

7909140435 Forwards response to NRC inquiries re need for power 2 cost of 3-year delay in operation Response based on NRC load forecast. Starting point not conceded to be appropriete by util Facility will be needed in 1985 BUTLER, R. M. Boston Edison Co. 79/05/08. 6pp

7905150397 Forwards responses to question re comparison of projected population densities in PBAR & 1978 update to 1974 site selection study.

BUTLER, R. M. Boston Edison Co. 79/05/10 14pp.

7905300011 Forwards into re NRC load growth cases pertaining to savings associated w/installing facility in 1985 vs 1988 & comparison of annual carrying charges.
BUTLER,R M. Boston Edison Co 79/05/23 App

D. NRC Draft/Final Environmental Statements, supple & correspondence

7905240151 Forwards comments received to date on draft suppl to FEB.
Requests review & response by 790418, W/o encl
REGAN, H. H. Environmental Projects Branch 2 79/04/10, 2pp.

7905090411 Comments by Commonwealth of MA on draft suppl to FES. BELLOTTI.F.X., BURT.L., WRIGHT.F.S. Massachusetts, State of 79/04/19 47pp.

7905040473 Comments on draft suppl to FES recognition should be given to cumulative impacts of siting two plants adjaceent to each other MEIEROTTU.L E Interior. Dapt of, Fish & Wildlife Service 79/04/26 200

7905220021 Forwards responses to comments submitted by Commenuealth of MA re draft suppl to FES Certificate of Svc encl BUTLER.R M Boston Edison Co 79/05/18 45pp

#### G Adjudicatory correspondence

7905290654 Forwards rept. "Parameters Bearing on Decision to Limit Biting Efforts to Given Geographical Area," & "Siting Study for Long-Term Power Generating Capacity Expansion," in response to NRC 780407 It re alternate sites BUTLER: R M Boston Edison Co 78/04/13 2pp

7905010115 Forwards request for Board notification re nonsafety-grade equipment to mitigate transients
SCINTO.JF Hearings Division 79/04/02 31pp

---7905010136 Board notification staff assessment re nonsafety-grade equipment to mitigate transients VABSALLO,D B Assistant Director for Light Water Reactors 79703/29 2pp

--790501019B Board notification recent issue on nonsafety-grade equipment to mitigate transients More into is required TEDESCO,R L Assistant Director for Reactor Safety 79/03/16 Jpp

7905070131 Forwards notification of NRC evaluation of new info re flow blockage model for ECCS to determine design conformance SMITH.8 H Branch 2 79/04/02 ip

7905240943 Opposes 790507 resumption of evidentiary hearings on alternative site Seeks postponement until 790321 BURT.L Massachusetts. State of 79/04/02 3pp

7905100326 Second motion to supplemental hearing record re need for power issue & to defer current hearing schedule w/notice of appearance of MB Meyer on behalf of Commonwealth of MA & Certificate of Svc BELLOTTI,F X . MEYER.M S. Massachusetts, State of 79/04/04 7pp

7705270055 Files memo on applicability & effect of 780714 Perkins partial initial decision re environ consequences of U cycle Certificate of Svc encl BMITH.B.M Branch 2 79/04/05 opp.

7905070127 Ack receipt of motion to resume evidentiary hearings Hearing should commence on 790507 BMITH.B H Branch 2 79/04/06 ip

7905100327 Evidentiary hearings shall resume 790524 in Plymouth.KA & continue on 790525 & 29-0601 LUTON.E. Atomic Safety and Licensing Board Panel 79/04/06 2pp

7905100336 Memo by util re applicability & effect of Pertins partial initial decision on proceedings. Requests adoption of Pertins findings.
LEMALD: OH Ropes & Oray STOODLEY, D. Q Boston Edison Co. 79/04/10 Spp

79052402 supple has no is of LEWALE 79/04/

79032902 ES Cht CLEET(

--79052°

7905020: Edisor Commit encl. MAZZOR

- 7905290626 Forwards most recent long-range energy & demand forecasts of util % New England Power Pool in response to Board's 790509 order. Certificats of Bvc encl
  STOODLEY.D.O Boston Edison Co 79/05/15, 4pp
- --7905290633 "Long-Range Forecast of Electric Power Needs & Requirements. Annual Suppl 1-C." 1979-1988, Vois 1 & 2. LYDON.J M , DESMOND.J. J Boston Edison Co 79/04/01 300pp
- --7905270637 "New England Load & Capacity Rept," 1978-1989 BMITH.J R Boston Edison Co 79/04/01. 55pp
- --7903290641 "New England Long-Range Forecast of Electric Power Needs & Requirements," 1979-1989
  SMITH,J R Boston Edison Co. 79/03/01. 3ipp
- --7905290645 "Rept of New England Power Pool Load Forecasting Task Force on Model-Based Forecast of New England Electric Energy & Peak Load." 1979-1989 \* Boston Edison Co 79/03/01 52pp
- ---7903290660 "Parameters Bearing on Decision to Limit Siting Efforts to Given Geographic Area " \* Boston Edison Co 78/04/13 Goopp. \_
- --7905290671 "Siting Study For Long-Term Power Generating Capacity Expansion:1975-2008." Vols A.B & C PRALL.T.F. Boston Edison Co 74/02/11 600pp.
- I Financial information

- 1

10

11

- 7905300013 Forwards response to NRC request for info to complete financial qualification review BUTLER:R M Boston Edison Co. 79/05/23. App.
- J. Insurance & indemnity information
- 7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,23,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,183,186,187,188,189,192,193,194,195,197,198,200,201,204,206,207,208,210,212,214,215,& others QUATTROCHHI,J. American Nuclear Insurers 79703001, 10
- 7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22.26.29.38.39.44.46.47.49.50.51.32.33.54.55.56.57.58.60.61.64.66.67.68.69.70.71.72.74.76.77.78.79.80.86.87.88.90.91.92.93.94.95 t. 96.69.70.71.72.74.76.77.78.79.79.80.86.87.
- 8 Reportable occurrences, LERs & related correspondence
- 7905ii0203 Board notification Seabrook refueling water storage tank design deficiency SCINTO.J. Hearings Division. 79/03/29. 30pp
- DOCKET 50-472 FILGRIM NUCLEAR POHER STATION, UNIT 3

  A. Application/construction stage documents & correspondence
- 7905150397 Forwards responses to question re comparison of projected population densities in PSAR & 1978 update to 1974 site selection study.

  BUTLER, R. M. Boston Edison Co. 79/05/10. 14pp.
- DOCKET STN-50-477 ATLANTIC GENERATING STATION, UNIT 1
- A Application/construction stage documents'& correspondence
- 7905150043 Forwards FR notice re withdrawal of application to construct & operate generating station.
  BALLARD,R.L. Environmental Projects Branch 1, 79/04/23 ip.
- DOCKET BTN-50-478 Atlantic Generating Station, Unit 2:
- A destratiun/sunesquettun state documents à torraspondence
- 7703150043 Forwards FR notice re withdrawal of application to construct & operate generating station BALLARD,R L. Environmental Projects Branch 1. 79/04/23, ip.
- DOCKET STN-50-482 WOLF CREEK GENERATING STATION
- A. Application/construction stage documents & correspondence
- 7905020432 Forwards NUREG-0331, "Investigation & Evaluation of Stress Corresson Cracking in Piping of LWR Plants" & motice of issuance & availability. W/o encl. VASSALLO, D.B. Assistant Director for Light Hater Reactors, 79/03/23, 2pp.

- 7905230731 Notification of 790515 meeting w/KB Qas & Electric Co & Bechtel in Burlington. KB to discuss concrete strength of facility base matl. LICITRA.E.A Light Water Reactors Branch 3 79/04/24, [s.
- 7705250089 Forwards summary of concrete problems, in response to 740212 request.
  OBSICK, L. V. Office of the Executive Director for Operations, 79/05/01. 4nd
- 7905080514 Forwards test rept of 28-day base mat cylinder Reactor bidg base mat concrete is uniform & of high quality w/strength srceeding specified design value of 5,000 psi.
  KOESTER. O. L. Kansas Gas & Electric Co. 79/05/03 ip.
- ---7905080516 "Reactor Base mat Concrete Testing of 28-Day Cylinder Remants " BHIDELER, J.J. Portland Cement Association. 79/04/27 20pp.
- 7905110311 Forwards "Reanalysis of Wolf Creek Reactor Bldg Base Mat," per NRC 790208 request KOESTER.O L. Kansas Gas & Electric Co 79/05/10 2pp
- --7905110314 "Reanalysis of Wolf Creek Reactor Bldg Base Mat "
   Kansas Gas & Electric Co. 79/05/09, 43pp,
- Q. Adjudicatory correspondence
- 7905080401 Forwards SAND77-1927, "Transport of Radionuclides in Urban Environs: Working Draft Assessment, " SECY-78-311, dtd 780614 & SECY-78-311A, dtd 781109 rs impact of working draft assessment on regulatory policy W/o encl LEHIS, 8 H. Branch 2. 79/03/30 2pp
- 7905040131 Discusses itr re sabotage of spent nuclear fuel, being separately forwarded to ASLAB.

  LEWIS, B. H. Branch 2. 79/04/02. 2pp
- 7905110418 Response to ALAB-509 re radon emissions & de minimus theory from Perkins record Certificate of Svc encl SCINTO, J F Hearings Division 79/04/11, 45pp.
- 7905140519 Response to 790404 brief of Philadelphia Electric Co.P8650 & Atlantic City (NJ) Electric Co re de minimus theory Cartificate of Svc encl., KEPFORD, C. R. Gitirens for Safe Environment. 79/04/11 Spp
- 7905150321 Responds to 790324 Itr requesting hearing for possible sale of 17% interest to certain rural electric cooperatives.
  ENGELHARDT, T. F. Deputy Executive Legal Director 79/04/16 Spp
- 7905140332 Notifies of consolidation of five intervenor groups regadenteristics issue. Parties have until 790525 in which to file for summary disposition.

  DUFLO, M.E. Atomic Safety and Licensing Appeal Panel. 79/04/25
- 7905150639 Responds to encl 781229 mailgram re problems encountered w/reactor base mat in const of facility.NRC staff action is being taken to resolve these problems Response by DDE is unnecessary.
  PREBBESKY.A.J. Energy, Dept. pf. 79/01/25. 1p.
- ---7905150645 Comments on shoddy work being done on reactor base set.
  OROTEWIEL, K. Affiliation Unknown, 79/01/25, 2pp.
- ---7905150656 Responds to 781229 mailgram re "shoddy work being done en reactor base mat" at facility. Although concrete apparently does not meet original design ultimate suitability yet to be detarmined. Wisummary of concrete problems.

  DAVIS. J. O. Office of Inspection & Enforcement. 79/04/27 5pp
- 7905240998 Responds to 790125 ltr to UM Hendris re faulty const. Revocation of license is being considered.Forwards summary of concrete problems, petition & FR notice DAVIS.J. G. Office of Inspection & Enforcement. 79704/27. Spp
- J. Insurance & indomnity information
- 7903070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,176,179,180,182,185,186,187,188,189,192,193,194,195,197,196,200,201,204,205,207,208,210,212,214,215,4 others.
  QUATTROCHHI, J. American Nuclear Insurers. 79/05/01, ip
- 7905070582 Confirms increase in liability limit to 436,000,000 for policies MF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,56,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,41,92,93,44,95 t 96
  ROBERTS,D.M. Mutual Atomic Energy Liability Underwriters. 79/05/01,

- û Inspection reports. IE Bulletins & correspondence
- 7705010302 Forwards IE Insp Rept 50-482/79-03 on 790220-23.notice of violation & notice of deviation BEIDLE-H C. Region 4. Dallas, Reactor Construction & Engineering Support Branch 79/03/14. 2pp.
- --7905010306 Notice of violation from insp on 790220-23
  + Region 4. Dailas. Office of the Director 79/03/12 ip
- --7903010308 Notice of deviation from insp on 790220-23.

  \* Region 4, Dallas, Office of the Director. 79/03/12 ip
- --7903010312 IE Insp Rept 50-482/79-03 on 790220-23. Noncompliance noted failurs to follow procedure to conform to Reg Ouide 1.55.
  OBERG.C.R. TAPIA.J I. Region 4. Dallas. Office of the Director HALL.R E. Region 4. Dallas. Reactor Construction & Engineering Support Branch 79/03/12 12pp
- 7905010280 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping" SEYFRITAR V. Region 4, Dallas, Office of the Director 79/03/23, ip.
- 7905010457 Forwards IE-Bulletin 79-08A, "Nuclear Incident at THI Suppl "
  BEYFRIT.K V Region 4, Dallas, Office of the Director 79/04/05, is.
- 790504049A Forwards IE Bullstin 79~06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident " SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/14
- 7908040617 Forwards IE Bulletin 79-0B, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident "BEYFRITIK V. Region 4, Dallas, Office of the Director, 79/04/14 is
- 79050700062 Forwards IE Builetin 79-07, "Geismic Stress Analysis of Bafety-Related Piping " Licenses action required BEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/04/14
- .7905010445 Forwards IE Info Notice 77~10, "Nonconforming Pipe Support Struts."

  BEYFRIT.K V. Region 4. Dallas, Office of the Director. 79/04/18.
- 7905090100 Forwards suppl to IE Bulletin 79-05A, "Nuclear Incident at THI."
  BEYFRIT, K. V. Region 4, Dailas, Office of the Director 79/04/16
- 7905030273 Forwards IE Bulletin 79-09, "Failures of QE Type AK-2 Circuit Breaker in Safety-Related Sys." Licenses action required. 8EYFRIT.K.V. Region 4. Dallas, Office of the Director 79/04/17
- 7905300621 Denies 790323 request for extension of time to respond to IE Bulletins 78-12,78-124 & 78-128. Generic repts from reactor vessel manufacturer are due by 790501; licensee responses by 790529.
  BEIDLE:N.C. Region 4. Dalles, Reactor Construction & Engineering Bupport Branch. 79/04/25 1p.
- --7905300626 Requests time extension to 791001 for responding to IE Bulletins 78-12,78-124 & 78-128. KOCSTER, O.L. Kansas Gas & Electric Co. 79/03/23 2pp.
- 7905230857 Clarifies current status of low concrete strength investigation at facility. Relevant documents are available at LPDR in Burlington KS.
  THORNBURG. H. D. Division of Reactor Construction Inspection 79/03/02. 6pp.
- --7905230858 Notification of 790515 public meeting w/util & Bechtel in Burlington KB to discuss concrete strength of base mat. LIGITRA E A. Light Water Reactors Branch 3, 79/04/24 2pp.
- 8. Reportable occurrences. LERs & related correspondence
- 7905030104 Forwards PNO-79-67H, I.J &K. SEYFRIT, K V. Region 4, Dallas, Office of the Director 79/04/06

- 7903030097 Forwards PNO-79-67L.M.N & P SEIDLE.W G Region 4. Dallas. Reactor Construction & Engineering Support Branch 79/04/09 IP
- 7903030099 Forwards PND-79-679
  SEIDLE:W C Region 4. Dailes, Reactor Construction & Engineering Support Branch 79704/10 ip
- 7905030146 Forwards PNO-79-67R & 79-77
  \* SEIDLE:W C Region 4. Dallas, Reactor Construction & Engineering Support Branch 79/04/11 | 19
- 7903030119 Forwards PND-79-678
  BEIDLE:N.C Region 4. Delias. Reactor Construction & Engineering
  Bupport Branch 79/04/12 ip
- 7903030193 Forwards PNO-79-67T SEIDLE,W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/13 ip
- 7905030037 Forwards PNO-79-67U & V BEIDLE: N C Region 4. Dallas, Reactor Construction & Engineering Busport Branch 79/04/16 1P
- 7905030248 Forwards PNO-79-67W
  SEIDLE W C Region 4: Dailes. Reactor Construction & Engineering Support Branch 79/04/17 ip
- 7905020534 Forwards PNO-79-67AA SEIDLE: N C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/20 ip
- 7905020503 Forwards PNO-79-67AB.AC & AD SEIDLE.W C Region 4. Dallas. Reactor Construction & Engineering Support Branch 79/04/23 ip
- 7905040575 Forwards PNO-79-67AE SEIDLE.W C Region 4. Dalles, Reactor Construction & Engineering Support Branch 79/04/26 ip.
- 7905310411 Withdraws initial notification of reportable deficiency in safety analysis methodology for certain single dropped control rod events Vendor 790410 itr of notification encl PETRICK, N A Bnupps-Standardized Nuclear Unit Power Plant System 79704/26 3pp
- --7903310418 Confirms 790328 telcon to H Thornburg re reportable deficiency in safety analysis methodology for certain single dropped control rod evants ANDERSON.T H Hestinghouse Electric Corp 79/03/30 2pp
- 7905070046 Forwards PND-79-67AF & AQ SEIDLE, W C Region 4. Dallas. Reactor Construction & Engineering Support Branch 79/04/27 ip
- 7905310206 Forwards PND-79-47AH, AI & AJ. SEIDLE, W. C. Region 4, Dalles, Reactor Construction & Engineering Support Branch. 79/04/30 ip
- 7905070649 Forwards deficiency rept "Final Rept on Pressurizer Support Anchor Bolts" for SNUPPS units PETRICK:N A. Snuppe-Standardized Nuclear Unit Power Plant System, 79/05/01. 2pp.
- ---7905070650 "Final Rept on Pressurizer Support Anchor Bolts" for SNUPPS units. Anchor bolts did not have adequate length to get full thread grip for two heavy hex nuts Design drawings revised MILLER, G. L. Snupps-Standardized Nuclear Unit Power Plant System. 79/04/30. 4pp.
- 7905240418 Forwards PNO-79-67AK & AL. BEIDLE,W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/05/04. 1p
- 7905290326 Provides interim significant deficiency rept re essential svc water pump anchor bolts. Preliminary indications show that anchor bolts as originally released for const may be adequate. Significant deficiency rept may be withdrawn. KDESTER. Q L. Kansas Qas & Electric Co. 79/05/18. 1p.

DOCKET STN-50-483 CALLOWAY PLANT, UNIT 1

## © Adjudicatory correspondence

7705160410 Requests consideration of forthcoming motion to show cause seeking order for review of portion of EIS which omitted ref to impact of transmission lines on migrating patterns OCHSTEIN.D S Missouri, State of 79/05/10 ip

#### H General correspondence

- 7905020210 Responds to 790307 request re ltr from R Lauf Forwards
  "Summary of Progress of Callaway Plant" & "Reactor Licensing
  Process." Latter not encl
  985516K.L V. Offfice of the Executive Director for Operations
  79/04/10 3pp
- ---7905020212 Requests response to R Lauf Etr if inquiry re NRC involvement w/plant EAGLETON.T F Senate 79/03/07 1p

#### O Inspection reports. IE Bulletine & correspondence

- 7905010268 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping " KEPPLER, J. O. Region G. Chicago, Office of the Director 79/03/23 to
- 7903040058 Forwards IE Info Notice 79-07, "Rupture of Radweste Tents." MEPPLER, J 0 Region 3, Chicago, Office of the Director 79/03/26
- 7905030058 Forwards IE Builetin 79-06. "Review of Operational Errors & Sys Mitalignments Identified During TMI Incident."

  KEPPLER. J. G. Region 3. Chicago. Office of the Director. 79/04/11
- 7903010610 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."

  KEPPLER, J. 9 Region G, Chicago, Office of the Director. 79/04/14
- 7905040428 Forwards IE Bulletin 79-068. "Review of Operational Errors & Bys Mitalignments Identified During TMI Incident "
  KEPPLER. J. O Region 3. Chicago. Office of the Director 79/04/14
- 7905040461 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Bafety-Related Piping " Licensee action required KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14
- 7905040575 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Hater Power Reactors Identified During TMI Incident" KEPPLER. J O Region 3, Chicago, Office of the Director 79/04/14 ip
- 7905010405 Forwards IE Info Natice 79-10, "Nonconforming Pipe Support Struts"

  KEPPLER, J 0 Region 3, Chicago, Office of the Director. 79/04/16 is
- 7905030249 Forwards IE Bulletin 79-09, "Failures of DE Type AK-2 Circuit Breaker in Safety-Related Sys " Licenses action required KEPPLER.J O Region 3, Chicago, Office of the Director 79/04/17. ip.
- 7905080512 Forwards IE Bulletin 79-058, "Nuclear Incident at TMI-Suppl."

  KEPPLER, J 0 Region 3, Chicago, Office of the Director. 79/04/21.

# 8. Reportable occurrences. LERS & related correspondence

| |

, ,]

- 7903310411 Withdraws initial notification of reportable deficiency in safety analysis methodology for certain single drapped control rad events. Vendor 790410 ltr of notification encl. PETRICK.N A Snupps-Standardized Nuclear Unit Power Plant System. 79/04/26. Spp.
- --7703310418 Confirms 790328 telcon to 4 Thornburg re reportable deficiency in safety analysis methodology for certain single dropped control rod events.

  ANDEREGNATH Westinghouse Electric Corp 79/03/30. 2pp

- 7905070649 Forwards deficiency rept "Final Rept on Pressurizer Eupport" Anchor Bolts" for SNUPPS units
  PETRICK, N A Snupps-Standardized Nuclear Unit Power Plant System
  79/03/01, 2pp
- --7905070650 "Final Rapt on Pressurizer Support Anchor Bolts" for SNUPF\$
  units Anchor bolts did not have adequate length to get full
  thread grip for two heavy hex nuts Design drawings revised
  MILLER, C. Enupps-Standardized Nuclear Unit Power Plant System.
  79/04/30 4pp

#### DOCKET STN-50-484 TYRONE ENERGY PARK, UNIT 1

#### esmebnoqeerros profesce

- 7905100133 Hemo by util submitting that radon release data & concentration levels contained in Perkins decision are complete & accurate Supports de minimus approach of Perkins board BLAKE, E. L., TRAVIESO-DIAZ, M. Shaw, Pittman, Potts, & Trowbridge 79/04/09 94pp
- 7905240799 Notice of appearance on behalf of Northern States Power Certificate of Svc encl
  TRAVIESO-DIAZ.M Shaw, Pittman, Potts, & Trowbridge 79/04/09 Opp
- 7905:104:B Response to ALAB-509 re radon emissions & de miniaus theory from Perkins record Certificate of Syc encl BCINTO-5 F Hearings Division 79/04/ii 45pp.
- 7905140519 Response to 790404 brief of Philadelphia Electric Co.PSE&Q & Atlantic City (NJ) Electric Co re de minimus theory Cartificate of Bvc encl
  KEPFCRD.C R Citizens for Bafe Environment 79/04/11 8sp
- 7905140332 Notifies of consolidation of five intervenor groups to radic emissions issue Parties have until 790525 in which to file for summary disposition DUFLO.KE Atomic Safety and Licensing Appeal Panel 79/04/25

#### J Insurance & indemnity information

- 7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,185,186,187,188,189,197,192,193,194,175,197,198,200,201,204,204,205,207,208,210,212,214,215,4 others QUATTROCHHI, J American Nuclear Insurers, 79/09/01 ip.

## Inspection reports: IE Bulletins & correspondence

- 7905010261 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping" REPPLER, J O Region 9, Chicago, Office of the Director, 79/03/23
- 7905040045 Forwards IE Info Notice 79-07, "Rupture of Radwaste Table." KEPPLER, J Q. Region 3, Chicago, Office of the Director. 79/03/26
- 7905030047 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "
  KEPPLER, J. O Region 3, Chicago, Office of the Director. 79/04/11
- 7908010897 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified during TMI Incident."

  KEPPLER, J. O. Region G. Chicago, Office of the Director 79/04/34
- 7905040418 Forwards IE Bullstin 79-068, "Review of Operational Errors & Sys Hisalignments Identified During THI Incident." KEPPLER, J. O. Region 3. Chicago, Office of the Director. 79/04/14.
- 7905040445 Forwards IE Bulletin 79-07: "Seismic Strees Analysis of Safety-Related Piping." Licenses action required. KEPPLER, J. G Region S. Chicago, Office of the Director. 79/04/14.

- 7905040587 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident,"
  KEPPLER.J Q Region 3, Chicago, Office of the Director 79/04/14
- 7903010419 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Btruts " KEPPLER, J Q Region 3, Chicago, Office of the Director 79/04/16
- 7905030239 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " Licensee action required
  - required
    KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/17
    io.
- 7905080503 Forwards IE Bulletin 79-058, "Nuclear Incident at THI-Buppl"

  KEPPLER, J. Q. Region 3, Chicago, Office of the Director, 79/04/21
- 8 Reportable occurrences, LERs & related correspondence
- 7905110203 Board notification Seabrook refueling water storage tank design deficiency BCINTD.J Hearings Division 79/03/29 30pp
- 7905310411 Hithdraws initial notification of reportable deficiency in safety analysis methodology for certain single dropped control rod events. Vendor 790410 ltr of notification encl PETRICK:N A Snupps-Standardized Nuclear Unit Power Plant Bystem 79704/26 Spp
- --7903310418 Confirms 790328 telcon to H Thornburg re reportable deficiency in safety analysis methodology for certain single dropped control rod events.

  ANDERSON, T M Westinghouse Electric Corp 79/03/30 2pp
- 7905070649 Forwards deficiency rept "Final Rept on Pressurizer Support Anchor Bolts" for SNUPPS units PETRICK N A Snupps-Standardized Nuclear Unit Power Plant System 79/05/01 2pp
- --7905070450 "Final Rept on Pressurizer Support Anchor Bolts" for SNUPPS units, Anchor bolts did not have adequate length to get full thread grip for two heavy hex nots Design drawings revised MILLER, C. L. Brupps-Standardized Nuclear Unit Power Plant System 79/04/30 4pp
- DOCKET BIN-90-485 STERLING POWER PROJECT NUCLEAR, UNIT 1
- A Application/construction stage documents & correspondence
- 7905150393 Bubmits revised Attachment A.B & C to 780728 submittal amending Tech Spacs for charcoel filter testing & iodine removal equipment operability HILKENS.P C Rochaster Gas & Electric Corp. 79/05/08 24pp
- O Adjudicatory correspondence
- 7905230497 Licenses's response to ALAB-509, Urges ASLAB to conclude that intervenors have not demonstrated any deficiencies of significance in Perkins record & that health effects responses to the second and the second and the second and seco
- 7905290473 Urges withdrawal of CP or remanding of alternative sites issue to ABLB. Contests ABLAB interpretation of "obviously superior" std. Certificate of Byc encl. REINERT. B. Ecology Action of Oswago. 79/04/09. 10pp.
- 7905230578 Orders extension, until 790411, for NRC to file memo, per 790308 order CHILK.S.J. Office of the Secretary of the Commission. 79/04/10.
- 7905110418 Response to ALAB-509 re radon emissions 5 de minimus theory from Perkins record Certificate of Svc encl. SCINTO, J.F. Hearings Division. 79/04/11 45pp.
- 7903140319 Response to 790404 brief of Philadelphia Electric Co.PSE&O & Atlantic City (NJ) Electric Co re de minimus theory.
  Cartificate of Syc encl.
  KEPFORD.C.R. Citizens for Bafe Environment. 79/04/11 Spp
- 7905150745 Forwards NRC rept "Inquiry into Allegation of Employee Misconduct by Restricting Investigation to Determine Reliability of Power Orid Serving St Lucie " W/o encl. SOHINKI, B. M. Branch 3, 79/04/11. 1p

- 7905270028 NRC memo in response to NRC 790308 order Supports approval of both 781017 ASLAB decision & formulation of obviously superior test as clear & substantial BRENNER, L Branch 3 79704/11 11pp
- 7905:50074 Licensee's reply brief to Ecology Action of Oswego's 790409 opening brief NRC should dismiss Action's petition for review as having been improvidently granted Certificate of Svc encl VOIGHT, H H MCBRIDE, H F , LARSON, L K LaBoauf, Lamb, Leiby & MacRae 79/04/24 14pp
- 7905310203 Reply to initial briefs re appeal of ALAB-502 Neither applicant nor NRC has made convincing argument for accepting ASLAB interpretation of "obviously superior " Cartificate of Svc encil REINERT.B Ecology Action of Oswego 79/04/24 App
- 7905140332 Notifies of consolidation of five intervenor groups re radon emissions issue Parties have until 790525 in which to file for summary disposition DUFLO.M E Atomic Safety and Licensing Appeal Panel 79/04/25
- I Financial information
- 7903040085 Forwards "Annual Financial Rept 1978" for Rochester Gas & Electric Co.Central Hudson Gas & Electric Co.Niagara Mohawk Power Corp. & Opange & Rockland Utils Repts available in Centrals Files only THOMAS, E B LeBoeuf, Lamb, Leiby & MacRae 79/09/02 ip
- J Insurance & indemnity information
- 7905070497 Confirms increased liability limit to \$124,000.000 for golicies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,185,186,187,188,189,192,193,194,195,197,194,200,201,204,204,207,208,210,212,214,215,& others QUATTROCHHI,J American Nuclear Insurers 79/03/01 ip
- 7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22,26,29,39,39,44,46,47,49,50,51,52,53,54,55,56,57,58,60,61,64,65,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,91,92,93,94,93 & 96 ROBERTS,D M Mutual Atomic Energy Liability Underwriters 79/05/01
- G. Inspection reports, IE Bulletins & correspondence
- 7905010145 Forwards IE Info Notice 79-06. "Stress Analysis of Bafety-Related Piping " GRIER,B H Region 1. Philadelphia. Office of the Director 79/03/23 ip
- 7905020111 Forwards IF Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "
  ORIER, BH Region i, Philadelphia, Office of the Director 79/04/11. 1p
- 7903020360 Forwards IE Bulletin 79-07, "Geismic Stress Analysis of Safety-Related Piping " Licensee action required REIER, B.H Region i, Philadelphia. Office of the Director 79/04/14. ip
- 7905040104 Forwards IE Bulletin 79-06B. "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "ORIER, B H. Region I, Philadelphia. Office of the Director 79/04/14. 1p
- 7905040295 Forwards IE Bulletin 79-08, "Eyents Relevant to Boiling Water Power Reactors Identified During TMI Incident " ORIER, B H Region i, Philadelphia, Office of the Director 79/04/14 ip
- 7905030110 Forwards IE Bulletin 79-09; "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " Licenses action required GRIER, B H Region 1, Philadelphia, Office of the Director. 79/04/17 ip
- 7905020331 Forwards IE Bulletin 79-06A.Revision 1, "Review of Operational Errors & Sys Misslignments Identified During TMI Incident."

  RIER, B H Region 1, Philadelphia, Office of the Director. 79/04/18 ip

# S Reportable occurrences, LERs & related correspondence

- 7905310411 Withdraws unitial notification of reportable deficiency in safety analysis methodology for certain single dropped control rod events Vendor ltr of notification on 790410 and PETRICK, N A Snupps-Standardsied Nuclear Unit Power Plant System 79/04/26 300
- --7905310418 Confirms 790328 telcon to H Thornburg re reportable deficiency in safety analysis methodology for certain single dropped control rod events
  ANDERSON.T M Westinghouse Electric Corp 79/09/30 2pp
- 7905070649 Forwards deficiency rept "Final Rept on Pressurizer Support Anchor Bolts" for SNUPPS units PETRICK.N A Snupps-Standardized Nuclear Unit Power Plant System 79705/01 2pp
- --7905070650 "Final Rept on Pressurizer Support Anchor Bolts" for SNUPPS units Anchor bolts did not have adequate length to get full thread grip for two heavy hex nuts Design drawings revised MILLER, C.L. Snupps-Standardized Nuclear Unit Power Plant System 79/04/30 4pp

## DOCKET STN-50-486 Calloway Plant, Unit 2

- A Application/construction stage
- **Q** Adjudicatory correspondence
- 7905160410 Requests consideration of forthcoming motion to show cause seeking order for review of portion of EIS which omitted ref to impact of transmission lines on migrating patterns DCHSTEIN.D S Missouri, State of 79/05/10 ip
- H General correspondence

. .

ļ. ; ; ;

- 7905020210 Responds to 790307 request re ltr from R Lauf Forwards
  "Summary of Progress of Callaway Plant" & "Reactor Licensing
  Process " Latter not encl
  GDSSIGN, L Y Office of the Executive Director for Operations
  79/04/10 3pp
- --7908020212 Requests response to R Lauf itr if inquiry re NRC involvement W/plant EAGLETON.T F Senate 79/03/07 ip
- Q Inspection reports, IE Bulletins & carrespondence
- 7905010268 Forwards IE Info Notice 79-06. "Stress Analysis of Safety-Related Piping"
  KEPPLER, J G Region 3. Chicago, Office of the Director 79/03/23
- 7905040058 Forwards It Info Notice 79-07, "Rupture of Radwaste Tanks "
  KEPPLER, J. O. Region G. Chicago, Office of the Director 79/03/26
- 7905030058 Forwards IE Bulletin 79-06, "Review of Operational Errors & Bys Misalignments Identified During TMJ Incident,"
  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/04/11, 19
- 7905010610 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "
  KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/14,
- 7905040428 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "
  KEPPLER, J G Region G, Chicago, Office of the Director. 79/04/14.
- 7905040461 Forwards IE Bulletin 79-07. "Beismic Stress Analysis of Safety-Related Piping " Licensee action required.

  KEPPLER, J G Region 3. Chicago, Office of the Director 79/04/14.
- 7905040395 Forwards IE Builatin 79~0B, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident "
  KEPPLER, J G Region 3, Chicago, Office of the Director, 79/04/14
- 7905010405 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Btruts " KEPPLER, J. G Region 3, Chicago, Office of the Director 79/04/16 10.

- 7905030249 Forwards IE Bulletin 79-09. "Failures of GE Tupe AX-2 Circuit Breaker in Safety-Related Bys " Licensee action required KEPPLER, J O Region 3. Chicago, Office of the Director 79/05/17
- 7903080312 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl"
  KEPPLER, J G Region 3. Chicago, Office of the Director 79/04/21-
- 7905310411 Withdraws initial notification of reportable deficiency in safety analysis methodology for certain single dropped control rod events Vendor Itr of notification on 790410 encl PETRICK, N A Snupps-Standardized Nuclear Unit Power Plant System 79004266 3no
- ---7908310418 Confirms 790328 telcan to H Thornburg re reportable deficiency in safety analysis methodology for certain single dropped control rod events
  ANDERSON,T H Westinghouse Electric Corp 79/03/30 2pp
- 7905070649 Forwards deficiency rept "Final Rept on Pressurizer Support Anchor Boils" for SNUPPS units PETRICK, N A Snupps-Standardized Nuclear Unit Power Plant System 79/03/01 2pp
- --7905070630 "Final Rept on Pressurizer Support Anchor Bults" for BRUPFS units Anchor bolts did not have adequate length to get full thread grip for two heavy hex nuts Design drawlings revised. HILLER.C. L. Bnupps-Standardized Nuclear Unit Power Plant System 79/04/30 App

#### DOCKET STN-50-488 PERKINS NUCLEAR STATION, UNIT 1

- G Adjudicatory correspondence
- 7905300099 Applicant's reply to intervenors' further supplemental proposed finding of fact & conclusions of law Certificate of Svc encl.
  MCCARRY.J M Duke Power Co 79/03/21, 22nd.
- 7905300056 NRC opposes intervenors' 790121 motion to reapen record to consider reactor safety study, geology, saismology, foundation & hydrology, Recommends motion be denied as lacking basis in law & fact. Certificate of Svc enci
  BARTH, C A Branch 3 79/03/26 9pp
- 7905010118 Forwards request for Board notification re nonsafety-grads equipment to mitigate transients
  SCINTO.J. F Heanings Division. 79/04/02 3ipp
- ---7905010156 Board notification staff assessment re nonsafety-grade equipment to mitigate transients VASBALLO, D. B. Assistant Director for Light Water Reactors 79/00/29 2pp
- ---7905010198 Board motification recent issue on nonsefety-grade equipment to mitigate transients, More info is required. TEDESCO, R L Assistant Director for Reactor Safety. 79/03/16 San
- 7905240635 Forwards Vollmer 780222 memo re behavior of iodine during postulated steam generator tube rupture accidents. BARTH-C, A Branch 3. 79/04/05 1p
- 7905250099 Forwards memo discussing info re behavior of iodine during postulated steam generator tube rupture accidents.

  BARTH/C A. Branch 3 79/04/10 ip.
- 7905020105 Responds to 790402 telegram re proposed facilities Results of NRC analysis of TMI incident will be forwarded when available.

  YORE T R Atomic Bafety and Licensing Board Panel. 79/04/17. 19
- ---7905020149 Requests proposed licensing of facility be held up.pending NRC assessment of TMI NEAL/S.L. House of Rep. 79/04/02. 1p
- 7905290475 Opposes intervenore' 790305 motion to reapen record & defer indefinitely issuance of initial decision on generic safety issue considerations Certificate of Svc anci.

  MCGARRY, J. M. Dute Power Co. 79/04/18. Spp
- 7905240667 Requests temporary moratorium on licensing of nuclear plants, in light of TMI incident PERKINS.L., HARRIS.P., BERECHER, J. Affiliation Unknown. 79/04/30 4pp.

#### J Insurance & indemnity information

- 7905070497 Confirms increased liability limit to \$124,000.000 for policies NF-1.25.43,76.83,100.111.140,146,151.161,164.170.173.174,178,179.180.182,185,186,187,188,189,192.193,194.195,197.198.200.201.204.205.207.208,210,212,214.215,4 others QUATTROCHMI.J. American Nuclear Insurers 79/05/01 1p
- 7905070582 Gonfirms increase in liability limit to \$36,000,000 for policies MF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,56,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,71,92,93,94,93 & 96,86,87,80
- Q. Inspection reports, IE Bulletins & correspondence
- 7905010183 Forwards IE Info Notice 79-06. "Stress Analysis of Safety-Related Piping"
  O'REILLY, J P Region 2. Atlanta, Office of the Director 79/03/23. 259.
- 7905030301 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks " O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/03/26 24p
- 7905040185 Forwards IE Bulletin 79-068, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident " O'REILLY, J. P Region 2. Atlanta, Office of the Director 79/04/14 2pp.
- 79050A0266 Forwards IE Dulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping " Licensee action required O'REILLYJ P Region 2, Atlanta, Office of the Director 79/04/14 2pp
- 7905040346 Forwards IE Bulletin 79-08, "Events Relevant to Beiling Water Power Reactors Identified During TMI Incident "O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14. Ip
- 7705010356 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts " O'REILLY.J.P Region 2, Atlanta, Office of the Director 79/04/16 ip
- 79030:00153 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaksr in Bafsty-Related Bys " Licensee action required O'REILLYJ P Region 2, Atlanta, Office of the Director 79/04/17 ip
- 7905020433 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident "
  G\*REILLY,J.P. Region 2, Atlanta, Office of the Director 79/04/16. 2pp
- 8 Reportable occurrences, LERs & related correspondence
- 7905110209 Board notification Seabrook refueling water storage tank design deficiency.
  SCINTO.J Hearings Division 79/03/29, 30pp
- DOCKET STN-50-489 PERKINS NUCLEAR STATION, UNIT 2 Q. Adjudicatory correspondence
- 7903300079 Applicant's reply to intervenors' further supplemental eropesed finding of fact & conclusions of law Certificate of Byc encl.

  MCGARRY, J. M. Duke Power Co. 79/03/21 22pp.
- 7905300056 NRC opposes intervenors' 790121 motion to reopen record to consider reactor safety study, geology, seismology, foundation & hydrology Recommends motion be denied as lacking basis in law & fact, Certificate of Byc encl.
  BARTH.C A. Branch 3. 79/03/26. 9pp.
- 7905010115 Forwards request for Board notification re nonsafety-grade equipment to mitigate transients.

  BGINTO, J.F. Hearings Division. 79/04/02 Sipp.
- --7905010106 Board notification staff assessment re nonsafety-grade equipment to mitigate transients.
  VASSALLO, D 8. Assistant Director for Light Water Reactors,
  79/03/29. 2pp.

- --7905010199 Board motification recent issue on nonsafety-grade equipment to mitigate transients More info is required TEDESCO,R L Assistant Director for Reactor Safety 79/03/16 Sao
- 7905240635 Forwards Vollmer 780222 memo re behavior of iodine during postulated steem generator tube rupture accidents BARTHL A Branch 3 79/04/05 1p
- 7905280099 Forwards memo discussing info re behavior of iodine during postulated steam generator tube rupture accidents BARTH.C A Branch 3 79/04/10 ip
- 7905020105 Responds to 790402 telegram re proposed facilities Results of NRC analysis of TMI incident will be forwarded when available.
  YORE, T R Atomic Safety and Licensing Board Panel 79/04/17 ip
- --7903020149 Requests proposed licensing of facility be held up, pending NRC assessment of THI NEAL S L. House of Rep. 79/04/02 ip
- 7905290475 Opposes intervenors' 790305 motion to reopen record & deferindefinitely issuance of initial decision on generic safety issue considerations Certificate of Evc encl MCGARRY, J M Duke Power Co 79/04/18 Spp
- J Insurance & indemnity information
- 7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,185,186,187,188,189,192,193,194,195,197,198,200,201,204,206,207,208,210,212,214,215,&others QUATTROCHHI,J American Nuclear Insurers 79/05/01 1p
- 7905070582 Confirms increase in liability limit to \$36,000.000 for policies MF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,56,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,60,66,67,79,68,90,91,92,93,94,95 & 96 ROBERTS,D.M Mutual Atomic Energy Liability Underwriters 79/05/01
- Q. Inspection reports, IE Bullstins & correspondence
- 7905010183 Forwards IE Info Notice 79-06. "Stress Analysis of Bafety-Related Piping" O'REILLY, J P Region 2. Atlanta, Office of the Director 79/03/23 2pp
- 7905030301 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks " O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/26 2pp
- 7905040185 Forwards IE Bullstin 79-068. "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "O'REILLY, JP Region 2. Atlanta. Office of the Director 79/04/14 2pp
- 7905040266 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping " Licensee action required D'REILLYJ P Region 2, Atlanta, Office of the Director 79/04/14, 2pp.
- 7905040346 Forwards IE Bulletin 79-08. "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident "G'REILLY,J P Region 2, Atlanta, Office of the Director 79/04/14. Ip.
- 7905010356 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts."

  G'REILLY, J P Region 2, Atlanta, Office of the Director.

  79/04/18. 1p
- 7905030183 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Bys "Licensee action required. U'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/04/17. 1p.
- 7905020453 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Hisalignments Identified During THI Incident" O'REILLY, J.P. Region 2. Atlanta, Office of the Director 79/04/18 2pp

i

- 8 Reportable occurrences, LERs & related correspondence
- 7905110203 Board notification Seabrook refueling water storage tank design deficiency
  SCINTO.J Hearings Division 79/03/27 30sp

DOCKET BIN-50-490 PERKINB NUCLEAR STATION, UNIT 3

- O Adjudicatory correspondence
- 7903300099 Applicant's reply to intervenors' further supplemental proposed finding of fact & conclusions of law Certificate of Svc encl
  MCGARRY, J M Duke Power Co. 79/03/21, 22pp.
- 7905300056 NRC opposes intervenors' 790121 motion to reapen record to consider reactor safety study, geology, seismology, foundation & hydrology Recommends motion be denied as lacting basis in law & fact Certificate of Buc encl
  BARTH, C A Branch 3. 79/03/26 9pp
- 7905010115 Forwards request for Board motification re nonsafety-grade .
  equipment to mitigate transients
  SCINTO.J F Hearings Division 79/04/02 Sipp
- ---7905010156 Board notification staff assessment re nonsafety-grade equipment to mitigate transients
  VASSALLO, D B Assistant Director for Light Mater Reactors
  79/03/27 2pp
- --7705010198 Board notification recent issue on nonsafety-grade equipment to mitigate transients More info is required TEDESCO.R.L Assistant Director for Reactor Sefety 79/03/16
- 7903240633 Forwards Voltaer 780222 memo re behavior of iodine during postulated steam generator tube rupture accidents.

  BARTH-C A Branch 3 79/04/05 1p
- 7905250099 Forwards memo discussing info re behavior of fodine during postulated steam generator tube rupture accidents BARTH/C A Branch 3 79/04/10 1p
- 7905020105 Responds to 790402 telegram re groposed facilities. Results of NRC analysis of TMI incident will be forwarded when available
- YORE, T.R. Atomic Safety and Licensing Board Panel 79/04/17, ip
- ---7905020149 Requests proposed licensing of facility be held up, pending NRC assessment of TMI.
  NEAL,8 L. House of Rep 79/04/02 ip
- 7905240667 Requests temporary moratorium on licensing of nuclear plants in light of TMI incident
  PERKING.L. HARRIE, P., BERECHER, J. Affiliation Unknown 79/04/30.
- J Insurance & indomnity information
- 7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,176,179,180,182,183,184,183,188,187,192,193,194,195,197,196,200,201,204,206,207,208,210,212,214,215,& others.

  QUATTROCHHI, J American Nuclear Insurers 79/05/01 1p.
- G. Inspection reports. IE Bulletins & correspondence
- 7905010183 Forwards IE Info Notice 79-06, "Btress Analysis of Safety-Related Piging"
  O'REILLY, J P. Region R. Atlanta. Office of the Director 79/03/23. 2pp.
- 7905030301 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks " O'RE[LLY.J P Region 2: Atlanta, Office of the Director 79/03/26 2pp.
- 7905040185 Forwards IE Bullstin 79-0AB, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident " O'REILLY, J. Region 2: Atlants, Office of the Director 79/04/14. 2pp.

- 7905040266 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping "Licensee action required O'REILLY, J P Region 2, Atlanta, Office of the Director. 79704/14 2pp
- 7905040346 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Hater Power Reactors Identified During TMI Incident."

  O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 16
- 7905010356 Forwards IE Info Notice 79~10, "Nonconforming Pipe Suggest Struts "
  O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/18 in
- 7905030153 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " Licensee action required O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/17 in
- 7905020453 Forwards IE Bulletin 79-06A:Revision i. "Review of Derational Errors & Sys Misalignments Identified During THI Incident " O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/18 20a.
- S Reportable occurrences, LERs & related correspondence
- 7905110203 Board notification Seabrook refueling water storage task design deficiency SCINTO. J. Hearings Division 79/03/29 30pp
- DOCKET STN-50-491 CHEROKEE NUGLEAR STATION, UNIT 1
- O Adjudicatory correspondence
- 79050B0359 Forwards DF Ross memo re accumulator characteristics identified during study of ECCS performance BARTH.C A Branch 3. 79/04/05 2pp
- ---7905080361 Discusses aspects of LOFT tests re accumulator delivery & effect on ECCS performance Participants having approved licensing models should provide addl relevant info ROSS DF Assistant Director for Reactor Safety 79/04/03 3pc.
- 7905090147 Forwards memos discussing problems experienced in connection w/pipe support base plate design.

  BARTH-C A Branch 3 79/04/03 2pp
- ---7903090130 Forwards 780928 Board notification pipe support base plate design. Requests notification of decision as to whether licensing boards will be notified.

  BCINTO, J F Office of the Executive Legal Director 78/10/11 ip.
- 7903240738 Forwards memo re behavior of iodine during postulated stein generator tube rupture accidents
  8ARTH-C.A Branch 3 79/04/05. ip
- 7905290198 Forwards memo re sabotage of spent fuel NRC assessment of significance of info will be forwarded to Board when available BARTH.C A Branch 3. 79/04/05 2pp
- 7905250061 Response filed per ALAB-509 Perkins Licensing Roard's use of de minimus theory was appropriate & in compliance w/applicable law Certificate of Svc encl.
  MCGARRY, J M. Duke Power Co. 79/04/09 11pp
- 7905110418 Response to ALAB-509 re radon emissions & de minimus theory from Perkins record Certificate of Syc encl SCINTG.J.F Hearings Division 79/04/11. 45pp
- 7905140519 Response to 790404 brief of Philadelphia Electric Co.PELO & Atlantic City (NJ) Electric Co re de minimus theory.
  Certificate of Svc encl
  KEPFORD.C R Citizens for Bafe Environment 79/04/11. Spp
- 7905140332 Notifies of consolidation of five intervenor groups to refer entsetons issue Parties have until 790825 in which to file for summary disposition.

  DUFLO: H E Atomic Safety and Licensing Appeal Panel 79/04/25

i

- 1 - [1

H

- Nee & indemnity information
- Confirms intrease in liability limit to \$36,000,000 for RF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,56,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,
- **tion reports, IE Bulletins & correspondence**
- Forwards IE Info Notice 79-06, "Stress Analysis of
- Related Piping "
  -Y.J.P. Region 2. Atlanta, Office of the Diractor
  2.3. 2pp
- ○1 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks." Y.JP Region 2, Atlanta, Office of the Director ZG\_ 2pp
- アラ Ack receipt of IE Insp Repts 50-491/79-05.50-492/79-05 & アフター05 on 790227-0302 No proprietary info C. Duke Power Co 79/04/06 ip
- 7726 Forwards IE Insp Repts 50-491/79-05, 50-492/79-05, & F3/79-05 on 790227-0502 No noncompliance noted 17.C E Region 2. Atlanta, Reactor Construction & Tworing Support Branch 79/03/20 2pp
- □ 752 IE Insp Repts 50-491/79-05,50-492/79-05 & 50-493/79-05 on □ 7-0302. No noncompliance noted Major areas inspected. □ plant rebar storage, concrete procedures, specs, records □ sting controls □ 10,J.R. BRYANT, J.C. Region 2, Atlanta, Reactor □ 10,J.R. BRYANT, J.C. Region 2, Atlanta, Reactor □ 10,J.R. BRYANT, J.C. Region 2, Atlanta, Reactor

- 53 Forwards IE Bulletin 79-07, "Smismic Stress Analyusis of -Related Piping " Licansee action required -Y.JP Ragion 2, Atlanta, Office of the Director 14 2pp
- 66 Forwards IE Bulletin 79-07, "Beismic Btress Analysis of -Related Piping " Licenses action required LY.JP Region 2, Atlanta, Office of the Director 14. 2pp
- 4소 Forwards IE Bulletin 79~0B, "Events Relevant to Boiling Power Reactors Identified During TMI Incident " LY, JP Region 2, Atlanta, Office of the Director 14 1p
- ರ್ಷ Forwards IE Info Notice 79-10,"Nonconforming Pipe Bupport
- LYIJP Region 2. Atlanta, Office of the Director.
- 509 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 t Breaker in Bafety-Related Sys " Licensee action ad. Y.JP Region 2, Atlanta, Office of the Director 17. 2pp.

- 20 Ack receipt of IE Insp Repts 50-491/79-07.50-492/79-07 & 79-07 on 790320 & 23 No proprietary info C. Duke Power Co. 79/04/25, ip.
- ○⇒25 Forwards IE Insp Repts 50-491/79-07,50-492/79-07 & ç2/79-07 on 790320 & 23.No noncompliance noted HY.C E. Region 2, Atlanta, Reactor Construction & newsring Support Branch 79/04/09, 2pp
- OS37 IE Insp Repts 50-491/79-07, 50-492/79-07 & 50-493/79-07 on 20 & 23. No noncompliance noted, Major areas inspected of ures for erection of containments, steel structures & rts, erection work & quality records . He Region 2. Atlanta, Office of the Director NT. J C Region 2. Atlanta, Reactor Construction & serving Support Branch. 79/04/06 6pp

- DOCKET STN-50-492 CHEROKEE NUCLEAR STATION, UNIT 2
- O. Adjudicatory correspondence
- 7905080359 Forwards BF Ross memo re accumulator characteristics identified during study of ECCS performance BARTH.C A Branch 3 79/04/05 2pp
- 7905090147 Forwards memos discussing problems experienced in connection w/pipe support base plate design. BARTH, C A Branch 3 79/04/05 2pp
- --7905090150 Forwards 780928 Board notification pipe support base plate design Requests notification of decision as to whether licensing boards will be notified RCINTO.JF Office of the Executive Legal Director 78/10/11
- 7905240738 Forwards memo re behavior of iodine during postulated steam generator tube rupture accidents
  BARTH.C A Branch 3 79/04/05 ip
- 7905290195 Forwards memo re sabutage of spent fuel NRC assessment of significance of info will be forwarded to Board whem available BARTH, C A Branch 3 79/04/05 20p
- 7905250061 Response filed per ALAB-509. Perkins Licensing Board's use of de minimus theory was appropriate & in compliance w/applicable law Certificate of Svc encl MCGARRYIJ M Duke Power Co 79/04/09 11pp
- 7905110418 Response to ALAB-509 re radon emissions & de minimus theory from Perkins record Certificate of Svc encl SCINTO, J F Hearings Division 79/04/11 45pp.
- 7905140517 Response to 790404 brisf of Philadelphia Electric Co.PSE&O & Atlantic City (NJ) Electric Co re de minimus theory. Certificate of Svc encl KEPFORD.C R. Citizens for Safe Environment 79/04/11 8pp
- 7905140332 Notifies of consolidation of five intervenor groups re radon emissions issue.Parties have until 790525 in which to file for summary disposition.

  DUFLO, H E. Atomic Safety and Licensing Appeal Panel. 79/04/25
- J Insurance & indemnity information
- 7905070582 Gonfirms increase in liability limit to \$36,000,000 for policies HF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,56,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,91,92,93,94,95 & 96. ROBERTS. D. M. Mutual Atomic Energy Liebility Underwriters 79/05/01
- G. Inspection reports: IE Bulletins & correspondence
- 7905010356 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Strute " O'REILLY, J. P. Region 2, Atlanta, Office of the Director
- 7905010183 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping" 0'REILLY,J.P. Region 2, Atlanta, Office of the Director 79/03/23 2pp
- 7905030301 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks."

  0'REILLY, J P Region 2. Atlanta, Office of the Director,

  79/03/26, 2pp.
- 7905230699 Ack receipt of IE Insp Repts 50-491/79-05,50-492/79-05 & 50-493/79-05 an 790227-0302.No proprietary info. DAIL.L.C. Duke Power Co 79/04/04 ip
- --7705230726 Forwards IE Insp Rapts 50-491/79-05, 50-492/79-05, & 50-493/79-05 on 790227-0302, No noncompliance noted MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 77/03/30. 2pp.
- --7905230752 IE Insp Repts 50-491/79-05,50-492/79-05 & 50-493/79-05 on 790227-0302 No noncompliance noted. Major areas inspected: batch plant:rebar storage.concrete procedures.specs.records & blasting controls.

  HARRIG.J.R., BRYANT.J.C Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 79/03/27 Spp.

- 7905040185 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misslignments Identified During TMI Incident " D'REILLY, J.P Region 2, Atlanta, Office of the Director 79/04/14 2pp.
- 7905040263 Forwards IE Bulletin 79-07, "Seismic Stress Analyssis of Safety-Related Piping " Licenses action required O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 2pp
- 7905040266 Forwards IE Bulletin 79-07, "Beismic Strees Analysis of Bafety-Related Piping " Licensee action required D'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 2pp
- 7905040346 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During IMI Incident " O'REILLY.J P Region 2, Atlanta, Office of the Director 79/04/14 ip
- 7905030193 Forwards IE Builetin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " Licensee action required O'REILLY, J P Region 2. Atlanta, Office of the Director 79/04/17 10
- 7705020453 Forwards IE Bulletin 77-06A.Revision i, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident " O'REILLY, J P. Region 2. Atlanta. Office of the Director 79/04/18 2p
- 7905240520 Ack receipt of IE Insp Repts 50-491/79-07.50-492/79-07 & 50-493/79-07 on 790320 & 23 No proprietary info DAIL.L C Duke Power Co 79/04/25 ip
- --7905240525 Forwards IE Insp Repts 50-491/79-07.50-492/79-07 & 50-493/79-07 on 790320 & 23 No noncompliance noted MURPHY.C E Region 2. Atlanta: Reactor Construction & Engineering Support Branck 79/04/09 2pp.
- --7903240537 IE insp Repts 50-491/79-07.50-492/79-07 & 50-493/79-07 on 790320 & 23 No noncompliance noted Major areas inspected procedures for exection of containments; steel structures & supports; exection work & quality records SHAN, M B. Region 2, Atlanta, Office of the Director BRYANT. J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/06 6pp.
- DOCKET 8TN-50-493 CHEROKEE NUCLEAR STATION, UNIT 3

  Q Adjudicatory correspondence
- 7905080337 Forwards DF Ross memo re accumulator characteristics identified during study of ECCB performance.

  BARTH.C A Branch S 79/04/05 2pp
- 7903090147 Forwards memos discussing problems experienced in connection w/pipe support base plate design.
  BARTHIC A. Branch 3 79/04/05, 2pp
- --7905090150 Forwards 780928 Board notification pipe support base plate design. Requests notification of decision as to whether licensing boards will be notified.

  SCINTO-J.F. Office of the Executive Legal Director 78/10/11
- 7903240738 Forwards memo re behavior of iodine during postulated steam generator tube rupture accidents
  BARTH.C A. Branch 3, 79/04/05 1p
- 7905290195 Forwards memo re sabotage of spent fuel NRC assessment of significance of info will be forwarded to Board when available.

  BARTH.C A Branch 3 79/04/05. 2pp.
- 790325006: Response filed per ALAB-509. Perkins Licensing Board's use of de minisus theory was appropriate & in compliance w/applicable law Gertificate of Byc and!. MCGARRY, J M Duke Power Co. 79/04/09 11pp.
- 7905110418 Response to ALAB-509 re radon smissions & de minimus theory from Parkins record, Cartificate of Svc encl.
  8CINTO, J. F Hearings Division. 79/04/11. 45pp.
- 7903140319 Response to 790404 brief of Philadelphia Electric Co.PSE&O & Atlantic City (NJ) Electric Co re de minimus theory.
  Certificate of Eyc encl.
  KEPPORD, C R Citizens for Bafe Environment. 79/04/11. Bpp.

- 7905140332 Notifies of consolidation of five intervenor groups to radon emissions issue Parties have until 790525 in which to file for summary disposition DUFLO.M E. Atomic Safety and Licensing Appeal Panel. 79/04/25
- J Insurance & indemnity information
- 7905070582 Confirms increase in liability limit to 436,000,000 for policies MF-22,26,27,38,39,44,46,47,49,50,51,52,53,54,55,56,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,91,92,93,94,95 & 96
- 7905010183 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping" O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/23 2pp
- 7905030301 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanis "
  O'REILLY, J P Region 2, Atlanta, Office of the Director
  79703/24 2pp
- 7903230699 Ack receipt of IE Insp Repts 50-491/79-05.50-492/79-05.5 50-493/79-05 on 790227-0302 No proprietary info DAIL.L.C Duke Power Co 79/04/06 ip
- --7905230726 Forwards IE Insp Repts 50-491/79-05, 50-492/79-05, 2 50-493/79-05 on 790227-0302 No noncompliance noted MURPHY.C E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/03/30 2pp
- --7905230752 IE Insp Repts 50-491/79-05,50-492/79-05 & 30-493/79-05 en 790227-0302 No noncompliance noted Major areas inspected batch plantresar storage, concrete procedures, specs, records & blasting controls HARRIS, J R. BRYANT, J C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/27 5pp
- 7905040185 Forwards IE Bulletin 79-068. "Review of Operational Errors & Eys Kisalignments Identified During THI Incident "OffEILLY.JP Region 2. Atlanta. Office of the Director 79/04/14 Zpp.
- 7905040263 Forwards IE Bulletin 79-07, "Seismic Stress Analyusis of Bafety-Related Piping." Licensee action required O'REILLY, J P Region 2, Atlanta, Office of the Director, 79/04/14, 2pp
- 7903040246 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping " Licensee action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/04/14, 2pp
- 7905040346 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Hater Power Reactors Identified During TMI Incident " O'REILLY, J. P Region 2, Atlanta, Office of the Director 79/04/14, ip
- 7905010356 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Btrute " O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/18 1s.
- 7703030153 Forwards IE Bulletin 77-07, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
  0/REILLY.U.P. Region 2, Atlanta, Office of the Director
- 7905020453 Forwards IE Bulletin 79-06A: Revision 1, "Review of Operational Errors & Sys Misalignments Identified During THI Incident,"

  0'REILLY, J. P. Region 2, Atlanta, Office of the Director, 79/04/18, 2pp.
- 7705240520 Ack receipt of IE Insp Repts 50-491/79-07,50-492/79-07 & 50-493/79-07 on 790320 & 23,No proprietary info. DAIL. L C. Duke Power Co 79/04/25. ip.
- --7905240525 Forwards IE Insp Repts 50-491/79-07, 30-492/79-07 & 50-493/79-07 on 790320 & 23 No nancompliance noted. MURPHY,C E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79704/09 2pp.

~~7905240537 IE Insp Repts 50~491/79~07, 50~492/79~07 & 50~493/79~07 on 790320 & 23 No noncompliance noted Major areas inspected procedures for erection of containments, steel structures & supports, erection work & quality records SHANN.H.B Region 2, Atlants, Defice of the Director BRYANT.J C. Region 2, Atlants, Reactor Construction & Engineering Support Branch 79/04/06 6pp

## DOCKET BIN-5Q-495 SWEBSAR-P1

- A Application/construction stage documents & correspondence
- 7905070446 Responds to NRC 790124 ltr requesting addl info re greliminary design approval Forwards list of cross-referenced categories as aid in review KENNEDY.W.J Stone & Webster Engineering Corp 79/05/03 2pp
- --7905070452 Discusses extension review re proliminary design approvals
  Requests assessment of SWESSAR/REBAR-41 design compared to
  Category I-IV items.
  BOYD.R.B. Division of Project Management 79/01/24 28pp
- 7905220202 Forwards set of SHESSAR-P1 through Amend 25 for preliminary design assessment per T Cox request & index committed to in util 790503 ltr to RS Boyd CULP, H. Q Stone & Hebeter Engineering Corp 79/05/14 4pp

# DOCKET STN-50-499 SOUTH TEXAS PROJECT, UNIT 1

- A Application/construction stage documents & correspondence
- 7905100069 Requests addl info in areas of mechanical engineering, structural engineering & sys analysis, for raview of FSAR. PARR. Q. D. Light Water Reactors Branch 3 79/04/13 16pp.
- 7905300372 Requests addl info re metallurgy to complete review of FBAR PARR. C. D Light Water Reactors Branch 3 79/04/30 700
- 7900240849 Notification of 790310 meeting w/util in Bethesda. MD to discuss first round questions dealing w/soil stucture interaction analysis LIGITRA.E Light Water Reactors Branch 3 79/05/04, 3pp
- F Sacurity, medical, emergancy & fire protection plans
- 7908030336 Forwards Amend 1 to physical security plan Plan withheld (ref 10CFR2 790)
  FURNCR.E.A. Houston Lighting & Power Co. 79/05/01 1p.
- 9. Adjudicatory correspondence
- 7705250386 Responds to Citizens for Equitable Utils 770223 petition to Intervene Petition should be granted because standing is shown Certificate of Syc encl, MCOURREN, H J Branch 1, 79/03/12, 17pp
- 7905250170 Request by applicant that ASLB issue add1 procedures prior to ruling on 780830 petition to intervene from Citizent Concerned About Nuclear Power, Certificate of Svc encl. NEWMAN, J. R., REIS, H.F., CULP, R.H., Lowenstein, Newman, Reis, Axelrad & Toll. 79/03/14. Spp.
- 7903330081 NRC response to Houston Lighting & Power 790314 motion for add1 procedures requested from Citizens Goncerned About Nuclear Power Request violates limitatins stated in NRC Rules of Practice Certificate of Buc enci. HCGURREN, H J. 9ranch 1. 79/03/29. 8pp.
- 7905000064 Response to applicant's motion to provide ABLB w/790319 decision in Health Research Group vs Kennedy Reproduced from "Legal Times of Washington." Certificate of Svc encl. PGOURREN.H.J. Branch i 79/04/02. 3pp.
- 7905250318 Assignment of RB Salzman, JH Buck & MC Farrar to ASLAB for proceeding.
  DUFLO, M.E. Atomic Safety and Licensing Appeal Panel. 79/04/17. 19
- 7905250328 Notice of appeal by Houston Lighting & Power of 790403 order granting intervention to different Concerned About Nuclear Power, Citizens for Equitable Utils & Austin Citizens for Economical Energy, Certificate of 8vc encl.
  NCUMAN, J.R., REIB, H.F., CULP, R.H. Lowenstein, Newman, Reis, Axelrad & Toll. 79/04/17. Spp.

- 7905290002 Reply by applicants to NRC 790420 motion for extension of time & to Citizens for Equitable Utils 790422 motion for continuance Both motions are unnecessary & unreasonable Certificate of Box enrl.

  8CHMARZ.M D Baker & Botts NEHMAN.J R . CULP.R H
  Lowenstein, Newman, Reis, Azelrad & Toll 79/04/27 5pp
- H General correspondence
- 7905090007 FOIA request for "Prehearing Conference Order Ruling Upon Intervention Petitions" & "Part 2 Rules of Practice for Domestic Licensing Proceedings "
  RYAN.C R Citizens Concerned About Nuclear Power, Inc 79/04/10 ip
- 7905010024 Response to FOIA request for "Prehearing Conference Order Ruling Upon Intervention Petitions," & "Part 2 Rules of Practice for Domestic Licensing Proceedings "Forwards requested into H7a enc!
  FELTON.J H Division of Rules and Records 79/04/24 1p
- 790508040B Forwards Amend 5 to FSAR TURNER.E A Houston Lighting & Power Co 79/05/04 3pp
- --7905080409 Amend 5 to FSAR
  # Houston Lighting & Power Co 79/05/04 500pp
- 7705150236 Forwards supplemental info to Amend 5 to FSAR covering Const Procedure AD40KPCCP-14 & GA vibroflotation insp rept dtd 760503 TURNER, E A Houston Lighting & Power Co 79/05/09 70pp
- M Antitrust correspondence
- 7905150045 Forwards TX Utils Co & subsidiaries' answer to NRC initial interrogatories & requests for production of documents Reserves rights to file objections & protective order before 790005 Certificate of Svc encl SLICKEY,F K Horsham, Forsythe & Bampels 79/03/01 1p
- 7905020232 Grants 790317 motion by Public Utils Board of Brownsville, TX seeking extensions: Until 790330 & 790405, in which to tomps! fuller responses to Board's interrogatories
  MARCHALL, E M Atomic Safety and Licensing Board Panel 79/03/22

  1p
- 7905240127 Notifies that location of deposition of LC Peeler of Monsanto Go has been changed from Holiday Inn. Alvin. TX to Butler, Binion, Rice, Gouk & Knapp law ofcs in Houston, TX RYAN, T O Isham, Lincoln & Beals, 79/03/22 Sp
- 7905020480 Order protecting confidentiality of info sought by Houston Lighting & Power from Central Power & Light, Nest TX Utils, Public Svc of OK & Boutheastern Electric Power Co MILLER, M. E Atomic Bafety and Licensing Board Panel 79/03/23
- 7905310020 Response by util to second set of interrogatories & request for production of documents, submitted to Central Power & Light Also moves for protective order Certificate of Sycencl BARNETT, E. H. Baker & Botts 79/03/28 25pp
- 7905070040 Advises that deposition of Edward Sherry, Air Products & Chemicals Co. Allentown. PA. originally scheduled for 790406. has been changed to 790419 at ofc of Air Products & Chemicals Co. RYAN. T. G. Isham, Lincoln & Beale 79/03/30 ip.
- ---7905070045 RL Wright, AD Cuphers & L Pesier were deposed during Mar Central Power & Light filed answers & objections to Houston Lighting & Power Co first set of written interrogatories. RYAN, T G Islam, Lincoln & Besie
- 7903300038 Rept on progress made in Har 1979 in completing discovery, submitted per ASLB 780621 order Certificate of Svc encl HARRIS, J. L., BERGER, H. G., CLARK, R. H., Justice, Dept. of. 79/03/31, 7pp.
- 7705030175 Describes discovery activities of Public Utils Board of Eromnsville:TX for Mar 1979 Certificate of Svc encl POIRER.M.R Spiegel & McDiarmid. 79/04/03 6pp.

- 7903090036 Request by TX Utils Generating Co for NRC to dismiss Central Power & Light South West Corp as intervenors in alternative, seeks summary disposition or invoking of collateral estoppel Certificate of Svc encl
  KNOTTS-J B Debevoise & Lieberman. 79/04/03 5pp
- ~~7905090042 Request by TX Util Generating Co for order barring Central Power & Light from seeking relief inconsistent w/District Court decision for favorable decision re summary disposition Debevoise & Lieberman 79/04/03 2pp
- --7905090050 Hemo by TX Utils Generating Co re points & authorities supporting motion to dismiss Central Power & Light South Hest Corp as intervenors or for summary disposition KNOTTS, J B Debevoise & Lieberman 79704703 42pp
- 790510028B Response to second set of interrogetories & requests for production of documents directed to DDJ by Houston Lighting & Power Qualifications of export witnesses HE Scott & OTC Taylor & Certificate of Sec encl.

  HARRIS.J L . BERGER.M O . CLARK.R H Justice, Dept of 79/04/03
- 7905100288 Response to second set of interrogatories & requests for production of documents directed to Dept of Justice by Houston Lighting & Power Qualifications of export witnesses ME Scott & DTC Taylor & Certificate of Svc encl HARRIS, J. L. BERGER, M. O., CLARK, R. H. Justice, Dept. of, 79/04/03
- 7905250361 Request by Central Power & Light that ASLB issue protective order re interrogatories & request for production of documents from Houston Lighting & Power Certificate of Svc STAHL.D M Isham, Lincoln & Beals 79/04/03 7pp
- 7705100273 Response to TX Utils Generating Go's objections to & motion for protective orders & motion to compel further answers to interrogatories & request for production of documents Cartificate of Bvc encil

  BLUME.M 8 Anti-Trust Division 79/04/04 34pp
- 7905070251 Mar 1979 discovery progress rept of City of San Antonio During week of 790323, documents made available by City were inspected by Public Utils Board of Brownville, TX Certificate of Svc encl WDOD, J C Hatthews, Nowlin, Macfarlans & Barrett 79/04/05 4pp
- 7903140115 Motion by Public Utils Board of Brownsville, TX to compel further production of documents from South TX Electric Cooperative & Medina Electric Cooperative. Supporting documentation & Certificate of Svc encil P
- 7905140138 Request by Central Power & Light for extension of time to respond to 790328 responses by Houston Lighting & Power & TX Utils Generating Co to former's interrogatories & document requests Certificate of Svc encl
- 7905100386 Hoves that responses to motions for summary disposition filed by Houston Lighting & Power & TX Utils Generating Cobe governed by IOCFR2 770(a) Certificate of Svc encl LESSYR P Anti-Trust Division 79/04/06 5pp
- 7905130190 Motion by Houston Lighting & Power for protective order republic disclosure of info requested by Public Utils Board of BrownsvillerIX Ceptificate of Bvc encl BARNETITE W Baker & Botts. BOUKNIGHT.J.A Lowenstein.Newman.Reis. Axeirad & Toll 79704/06 9pp
- 7905230793 Status of discovery & production during Mar 1979 Certificate of Syc enc! BALOUGH.R C Austin: TX, 79/04/04 3pp
- 7905100412 Applies restrictions on confidential documents to be produced by Houston Lighting & Power Co in response to request for production of documents by Public Utils Board of Brownsville-TX
  HILLER.H E Atomic Safety and Licensing Board Panel 79/04/0 Atomic Safety and Licensing Board Panel 79/04/09.

第二式

- 7905250488 Status rept on discovery for Mar 1979 Discovery requests were maither initiated nor received, Certificate of Svc encl JOHN, D F. Akin, Gump, Hauer & Feld 79/04/09, 5pp
- 7905290077 Motion by Gulf States Utils for further extension of time, volution of our others of the services of the

- 7905230651 Answer by Houston Power & Lighting to NRC 790323 response to util motion for protective order.NRC motion to compel further answers to interrugatories & NRC request for production of documents Certificate of Svc enci BARNETT.E H Bater & Botts BOUKNIGHT, J A Lowenstein, Newman, Res Lowenstein, Newman, Reig,
- 7903030260 Forwards revised page 28-i attached to Central Power & Light Co's answers & objections to Houston Lighting & Power Co's first set of written interrogatories to Central Power & Light Co Certificate of Svc enci
- 7905240332 Advises no discovery requests have been initiated or received by Ter-La Electric Cooperative Inc Certificate of BURCHETTE, H H Northcutt Ely 79/04/12 4pp
- 7905230448 South TX Electric Cooperative, inc & Medina Electric Cooperative, inc's opposition to Public Utils Board of Brownsville, TX 790405 motion for fuller responses to interrogatories Certificate of Svc encl HUNTEZ, M HcOinnis, Lochridge & Kilgore JOHN, D F Akin, Ou Hauer & Feld 79/04/13 11pp Akin, Quas.
- 7905240967 Advises that during Mar 1979 NRC filed motions to compe) against Houston Lighting & Power & TX Utils Generating Co NRC is preparing responses to TX Util's first & Houston's second set of interrogatories

  LEGSY
- 7705250127 Ack receipt of response to Mar 1979 motion to compel & evaluation in progress

  LESSY,R P Anti-Trust Division 79/04/13 ip
- 7905140126 Request by Public Utils Board of Brownsville,TX for extension of time to answer first set of interrugatories & requests for groduction of documents from Central Power & Light & Houston Lighting & Power Certificate of Svc encl MCDIARMID.R C Spiegel & McDiarmid 79/04/16 7pp
- 7905240241 Corrects revised page 28-1 of Central Power & Light Co answers & objections in 790412 proceeding from "expenditure other than expenditure" to "expenditure other than advertising "Certificate of Svc enc! STAHL.D M Isham, Lincoln & Beale 79/04/17 4pp
- 7905180780 Directs TX Utils Generating Co (TUGCO) to produce documents or make full responses to 790115 interrogatories Denies TUGCO's order for protective order MILLER, ME Atomic Safety and Licensing Board Panel 79/04/18
- 7705230624 Response by util to Central Power & Light's 770326 objections & 770403 motion for protective order re-util's first set of interrogatories Includes motion to compel answers Whotice of appearance & Certificate of Evc BARNETT, E. W. Baker & Botts BOUKNIOHT, J. A., FRANKLIN, W. J. Lowenstein, Newman, Reis, Axelrad & Toll 77/04/19. 18pp
- 7905230677 Grants extension of time to answer interrogatories by Public Utils Board of Brownsyills.TX.in response to 790416 motion MILLER.M E Atomic Safety and Licensing Board Panel 79/04/19 ip.
- 7905100118 Motion by Gentral Power & Light to compel Houston Lighting & Power to answer second set of interrogatories submitted 790223 Supporting documentation & Certificate of Svc encl. STAHL.D. Isham Lincoln & Beals. 79/04/20 20ps
- ~-7905100123 Motion by Central Power & Light to compel TX Utils Generating Co to answer first set of interrogatories submitted 790223 STAHL.D. Isham, Lincoln & Beale, 79/04/20 12pp.
- 7905100271 Answer by Central Power & Light & Central & South Mest Corp seeking continuance of NRC entitrust reviews.w/no party banned on grounds of res judicate of collatoral estoppel. Supporting documentation & Certificate of Svc encl POMELL.R.E., MILLER.M.I., STAHL.D.M. Isham. Lincoln & Beale 79/04/20. 115pp.
- 7905100106 Opposes City of Austin's 790329 brief & 790403 motions for full or partial summary judgment filed by Houston Lighting & Power & TX Utils Generating Co. Seeks denial of cartification & interlocutory appeals W/Certificate of Svc LESSY,R.P., BLUME,M B Anti-Trust Division. 79/04/23 24pp.
- 7905140151 Response of Public Utils Board of Brownsville, TX opposing Mouston Lighting & Power motion for summary decision & City of Austin brief in support of res judicata, Bupporting documentation & Certificate of Byc encl.
  MCDIARMID.R C. JABLON,R A., POIRIER,M.R. Spiegel & McDiarmid.
  79/04/23, 84pp.

- 7905240248 Conforms 790424 telcon that util plans to file response to 790419 Motion By NRC for reconsideration of board order of 790416 compelling further answer by util Certificate of Svc
  - FRANKLIN,W J Lowenstein, Newman, Reis, Axelrad & Toll 79/04/24
- 7905240824 Util's discovery progress rept for Apr,1979 Certificate of 8vc encl FRANKLIN.W J Lowenstein.Newman.Reis,Axelrad & Yoll 79/05/02 7ap
- 7705250191 Requests util suppl & update list of privileged documents LESSY, R F Anti-Trust Division 79/05/02 ip.
- 7903230466 NRC answer to motions of Oulf States Util for protective order % order setting conditions for compliance w/790226 subground Util should produce documents as requested Centificate of Svc encl.

  BLUME, H B Anti-Trust Division 79/05/04 14pp
- O Inspection reports, IE Bulletins & correspondence
- 7905010376 Forwards IE Insp Repts 50-499/79-03 & 50-499/79-03 on 790221-23 & notice of violation.
  SEIDLE,H.C Region 4, Dailas, Reactor Construction & Engineering Support Branch 79/03/14, 2pp
- --7905010379 Notice of violation from insp on 790221-23
  \* Region 4, Dallas, Office of the Director 79/03/13 ip
- --7905010383 IE Insp Repts 50-498/79-03 & 50-499/79-03 on 790221-23
  Noncompliance noted failure to follow procedures for storage of matl
  HUBACEK,W 0 , MARTINIL E Region 4, Dallas, Defice of the
  Director HALL,R E Region 4, Dallas, Reactor Construction &
  Engineering Support Branch 79/03/13 9pp
- 7905010279 Forwards IE Info Notice 79-06, "Btress Analysis of Bafety-Related Piping" SEYFRIT, K. V Region 4, Dallas, Office of the Director 79/03/23 1p.
- 7705010457 Forwards IE Bulletin 79~05A; "Nuclear Incident at TMI Buppl."
  SEYFRIT, K V Region 4, Dallas, Office of the Director. 79/04/05
- 7905040492 Forwards IE Bulletin 79~068, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "
  BEYFRIT, X V Region 4, Dallas, Office of the Director 79/04/14 in
- 7905040613 Forwards IE Bulletin 77-08, "Events Relevant to Boiling Hater Power Reactors Identified During TMI Incident "
  SEYFRIT.K V Region 4, Dailas, Office of the Director 79/04/14.
- 7905070055 Forwards IE Bulletin 79-07, "Beismic Stress Analysis of Safety-Related Piping." Licensee action required SEYPRIT.K V Region 4, Dallas, Office of the Director 79/04/14 by
- 7903010441 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts." SEYFRIT, K V. Region 4, Dallas, Office of the Director. 79/04/16 is.
- 7905090099 Forwards suppl to IE Bulletin 79-05A. "Nuclear Incident at TML."
  BEYFRIT, K V Region 4. Delies, Office of the Director. 79/04/16 ip.
- 7905030271 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Bafety-Related Sys." Licenses action required, SEYFRITIK V Region 4, Dallas, Office of the Director 79/04/17 Ip
- 7905240686 Ack receipt of 790403 ltr informing NRC of steps taken to corect violations noted in IE Insp Repts 50-498/79-03 & 50-499/79-03 SEIDLEN C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/26 ip.
- --7905240693 Responds to NRC 790314 ltr re violations noted in IE Insp. Repts 50-498/79-03 & 50-499/79-03 Corrective actions. storage areas on site surveyed for stainless steel math in contact w/carbon steel TURNER, E.A. Houston Lighting & Power Co. 79/04/03. 2pp.

- 8 Reportable occurrences. LERs & related correspondence
- 7905030138 Forwards PNO-79-67H, I.J & K 8EYFRIT.K V Region 4. Dallas, Office of the Director 79/04/06
- 7905030094 Forwards PNO-79-67L.M.N & P BEIDLE,M C Region 4, Dallas, Reactor Construction & Engineering Support Branch · 79/04/09 IP
- 7905030095 Forwards PNO-79-67G BEIDLE, H C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/10 1p
- 7905030143 Forwards PNO-79-67R & 79-77
  SEIDLE,W C Region 4. Dallas, Reactor Construction & Engineering Support Branch 79/04/11 ip
- 7903030118 Forwards PNO-79-678 SEIDLE, W. C Region 4, Dallas, Reactor Construction & Engineering Support Branch, 79/04/12 ip
- 7905030189 Forwards PNO-79-67T SEIDLE,W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/13, ip
- 7903030071 Forwards PNO-79-670 & V SEIDLE: W C Region 4, Dallas, Reactor Construction & Engineering Bupport Branch 79/04/16 iP.
- 7905030240 Forwards PNG-79-67W SEIDLE, W.C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/17 1p
- 7905020516 Forwards PNO-79-67AA BEIDLE.W C Region 4. Dellas, Reactor Construction & Engineering Bupport Branch 79/04/20 ip
- 7905020505 Forwards PND-79-67AB.AC & AD SEIDLE.W.C Region 4. Dallas. Reactor Construction & Engineering Support Branch 79/04/23 ip
- 7905040391 Forwards PNO-79-67AE BEIDLE,W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/26 1p
- --7908040406 PND-79-67AE summary of info re nuclear incident as of 790424 Describes plant & environ status

  \* Office of Inspection & Enforcement 79/04/24 3pp.
- 7905070185 Forwards PND-79-67AF & AG.

  8EIDLE: N G. Region 4. Dallas, Reactor Construction & Engineering Support Branch. 79/04/27 1p.
- 7905310216 Forwards PNO-79-67AH.AI & AJ SEIDLE.W C. Region 4. Dallas, Reactor Construction & Engineering Support Branch 79/04/30 ip.
- 7905240385 Forwards PNO-79-67AK & AL BEIDLE: N G Region 4. Dalles: Reactor Construction 4 Engineering Support Branch 79/05/04 ip.

DOCKET STN-50-499 SOUTH TEXAS PROJECT: UNIT "

A. Applicati

790510006

790530037£ PARR, D. I

790524086' discuss stucturi LICITRA

F, Securi

790503033 (ref 10

#### u. Adjudicatory correspondence

- 7905250306 Responds to Citizens for Equitable Utils 790223 petition to intervane Petition should be granted because standing is shown Certificate of Svc enc! MCOURREM.H J Branch 1 79703/12, 17pp.
- 7905230170 Request by applicant that ASLB issue addl procedures prior to ruling on 780830 petition to intervene from Citizens Concerned About Nuclear Power Certificate of Swc encl NEWHAN. J R. REIS, H F. CULP, R H. Lowenstein, Newman, Reis, Axelrad & Toli 79/03/14 Spp
- 79053000B1 NRC response to Hauston Lighting & Power 790314 motion for add1 procedures requested from Citizens Concerned About Nuclear Power. Request violates limitatins stated in NRC Rules af Practice Certificate of Suc encl HCGURREN.H J. Branch 1 79/03/29 Bpp
- 7905300064 Response to applicant's motion to provide ABLB w/790319 decision in Health Research Group vs Kennedy Reproduced from "Legal Times of Washington" Certificate of Bvc encl MCGURREN-H J. Branch 1 79/04/02 3pp.
- . 7705250318 Assignment of RS Salsman, JH Buck & HC Farrar to ASLAB for proceeding DUFLO, M E Atomic Safety and Licensing Appeal Panel 79/04/17, is
  - 7905230328 Notice of appeal by Houston Lighting & Power of 790403 order granting intervention to Citizens Concerned About Nuclear Power, Citizens for Economical Energy Certificate of Svc enci Neuman, Reis, Axelrad & Toll 79/04/17 5pp
  - 7905290002 Reply by applicants to NRC, 790420 motion for extension of time & to Citizens for Equitable Utils 790422 motion for continuance Both motions are unnecessary & unreasonable Certificate of Syc anci SCHWARJ, M D. Baker & Botts NEWMAN, J R , CULP, R H Lowenstein, Newman, Reis, Azelrad & Toll 79/04/27 5pp

## H General correspondence

- 7908090007 FOIA request for "Prehearing Conference Order Ruling Upon Intervention Petitions" & "Part 2 Rules of Practice for Domestic Licensing Proceedings,"

  RYAN.C R. Citizens Concerned About Nuclear Power, Inc. 79/04/10
- 7905010024 Response to FOIA request for "Prehearing Conference Order Ruling Upon Intervention Petitions," & "Part 2, Rules of Practice for Domestic Licensing Proceedings " Forwards requested info, W/o encl FELTON, J H Division of Rules and Records 79/04/24 ip.
- K. Utility Final Bafety Analysis Report (FBAR) & amends
- 7905080408 Forwards Amend 3 to FBAR. TURNER,E A Houston Lighting & Power Co. 79/05/04 3pp
- --7905080409 Amend 5 to FSAR
  \* Houston Lighting & Power Co 79/05/04 500pp.
- 7905150236 Forwards supplemental info to Amend 5 to FSAR covering Const Procedure A040KPCCP-14 & QA vibroflotation insp rept dtd 760503 TURNER, E. A Houston Lighting & Power Co 79/05/09, 70pp

# M Antitrust correspondence

1.

- 7903150343 Forwards TK Utils Co & subsidiertes' answer to NRC initial interrogatories & requests for production of documents. Reserves rights to file objections & protective order before 790303. Certificate of Svc encl SLICKEY, F. K. Worsham, Forsythe & Sampels, 79/03/01 1p
- 7905020232 Grants 790317 motion by Public Utils Board of Brownsville, TX sesting extensions until 790330 & 790405 in which to compel fuller responses to Board's interrogatories MARSHALL, E. M. Atomic Sefety and Licensing Board Panel 79/03/22 ip
- 7905240127 Natifies that location of deposition of LC Peeler of Monsanto Go has been changed from Holiday Inn. Alvin.TX to Butler, Binion,Rice, Cook & Knapp law offices in Houston,TX RYAN,T Q. Isham, Lincoln & Beale. 79703/22 565

- 7905020480 Order protecting confidentiality of info sought by Houston Lighting & Power from Central Power & Light, West TX Utils, Public Svc of OK & Southwestern Electric Power Co MILLER, M E Atomic Safety and Licensing Board Panel. 79/03/23
- 7905310020 Response by util to second set of interrogatories & request for production of documents, submitted to Central Power & Light Also moves for protective order Certificate of Svc encl BARKET, E. N. Bater & Botts 79/03/28 25pp
- 7903070040 Advises that deposition of Edward Sherry, Air Products & Chemicals Co. Allentown. PA. originally scheduled for 790406. has been changed to 790419 at ofc of Air Products & Chemicals Co RYAN.T.O Isham, Lincoln & Besie 79/03/30 ip
- --7905070049 RL Hright, AD Cyphers & L Paeler were deposed during Kar Central Power & Light filed answers & objections to Houston Lighting & Power Co first set of written interrogatories RYAN.T G Isham, Lincoln & Beale 79/03/30 2pp
- 7905300058 Rept on progress made in Mar 1979 in completing discovery submitted per ASLB 780621 order Certificate of Svc enci HARRIS, J L. Justice, Dept of 79/03/31 7pp
- 7905030173 Describes discovery activities of Public Util Board of Brownsville,TX for Mar 1979. Certificate of Svc enci PDIRER,M,R Spiegel & McDiarmid 79/04/03 6pp
- 7905090036 Request by TX Utils Generating Co for NRC to dismiss Central Power & Light South West Corp as intervenors In alternative, seeks summary disposition or invoking of collateral estopped Certificate of Buc encl.

  KNOTTB.J B Detevoise & Lieberman. 79/04/03 5pp
- ---7905090042 Request by TX Util Generating Co for order barring Central Power & Light from seeking relief inconsistent w/District Court decision for favorable decision re summary disposition KNOTTS, J B Debevoise & Lieberman 79/04/03 2pp.
- --7905070050 Memo by TX Utils Generating Co re points & authorities supporting motion to dismiss Central Power & Light South West Corp as intervenors or for summary disposition KMOTTS,J.R Debevoise & Lieberman 79/04/03 42pp
- 7705100288 Response to second set of interrogatories & requests for production of documents directed to Dept of Justice by Houston Lighting & Power Qualifications of export witnesses HE Scott & GTC Taylor & Certificate of Svc encl. HARRIS, J. L. Justice, Dept of 79/04/03. 23pp
- 7905140070 Response to first set of interrogatories & request for production of documents submitted by TX Util Generating Co Certificate of Svc encl HARRIS,J L Justice, Dept of. 79/04/03 lipp,
- 7905250361 Request by Central Power & Light that ASLB issue protective order re interrogatories & request for production of documents from Houston Lighting & Power, Certificate of Svcenci STAHL.D M. Isham, Lincoln & Beale 79/04/03 7pp
- 7905100273 Response to TX Utils Generating Co's objections to & motion for protective orders & motion to compel further answers to interrogatories & request for production of documents Certificate of Sice enci.

  BLUME.M B. Anti-Trust Division. 79/04/04 34pp
- 7905070251 Mar 1979 discovery progress mapt of City of Ban Antonic During week of 790323, documents made available by City were inspected by Public Utile Board of Brownville, TX Cartificate of Syc encl.

  WOOD, J. C Matthews, Nowlin, Macfarlans & Barrett. 79/04/05 489
- 7905140115 Motion by Public Utils Board of Brownsville, TX to compel further production of documents from South TX Electric Cooperative & Medina Electric Cooperative Bupporting documentation & Certificate of Sur encl. .
  POIRTER, M.R. Spiegel & McDiarmid 79/04/05 17pp.
- 7905140138 Request by Central Power & Light for extension of tipe to respond to 790328 responses by Houston Lighting & Power & TX Utils Generating Co to former's interrogatories. Document requests. Centricate of 8vc encl
  BTAHL: D Isham, Lincoln & Beale 79/04/05 opp.

- 7905100386 Moves that responses to motions for summary disposition filed by Houston Lighting & Power & TX Utils Generating Cobe governed by 100FR2 790(a) Certificate of 8vc encl LESSY.R P Anti-Trust Division 79/04/06 5pp
- 7905150190 Motion by Houston Lighting & Power for protective order re public disclosure of info requested by Public Utils Board of Brownsylle, TX Certificate of Svc encl BARNETT, E W Baker & Botts 79/04/06 9pp
- 7903230793 Status of discovery & production during Mar 1979 Certificate of Svc enci SALOUGH.R C Austin, TX 79/04/06 3pp
- 7905100412 Applies restrictions on confidential documents to be produced by Houston Lighting & Power Co in response to request for production of documents by Public Utils Board of Brownsville.TX HTLLER.M E Atomic Safety and Licensing Board Panel 79/04/09.
- 7705250408 Status rept on discovery for Mar 1979 Discovery requests were neither initiated nor received Cartificate of Svc encl JOHN, D.F. Akin, Gump, Hauer & Feld 79/04/09 5pp
- 7905290077 Motion by Gulf States Utils for further extansion of time, until 790425, in which to complete response to City of Brownsville's subposes for production of documents Cartificate of Sec enc!
  RADER,R M. Conner, Moore & Corber 79/04/09 App
- 7908230651 Answer by Houston Power & Lighting to NRC 790323 response to util motion for protective order.NRC motion to compal further answers to interrogatories & NRC request for production of documents Cartificate of Svc encl.

  BARNETT, E W Baker & Botts 79/04/11, 12pp
- 79050302&0 Forwards revised p 28-1 attached to "Central Power & Light Co's Answers & Objections to Houston Lighting & Power Co's First Bet of Mritten Interrogatories to Central Power & Light Co." W/Certificate of Svc.

  8TAHL:D M Isham, Lincoln & Beale 79/04/12 App.
- 7405240332 Advises no discovery requests have been initiated or received by Tex-La Electric Cooperative, Inc Certificate of Svc encl.
  BURCHETTE, W. H. Northcutt Ely 79/04/12. App.
- 7905:30669 Grants motions for extantion of time for parties to respond to discovery requests MILLER, M E Atomic Safety and Licensing Board Panel 79/04/13
- 7709230448 South TX Electric Cooperative, Inc & Medina Electric Cooperative, Inc's opposition to Public Utile Board Brownsville, TX 770405 motion for fuller responses to interrogatories Certificate of Syc encl HUNTEZ, M. McGinnis, Lochridge & Kilgors 77/04/13 lipp
- 7903240967 Advises that during Mar 1979 NRC filed motions to compel against Houston Lighting & Power & TX Utils Generating Co NRC is preparing responses to TX Util's first & Houston's accord set of interrogatories LEBSY.R.P. Anti-Trust Division 79/04/13 1p.
- 7905250127 Ack receipt of response to Mar 1979 motion to compel & evaluation in progress
  LESSY.R.P Anti-Trust Division 79/04/13 1p.
- 7903140126 Request by Public Utils Board of Brownsville,TX for extension of time to answer first set of interrogatories & requests for production of documents from Cantral Power & Light & Houston Lighting & Power, Certificate of Bvc encl. HCDIARMID,R C Spiegel & McDiarmid. 79/04/16 7pp
- 7905240241 Corrects revised page 28-1 of Central Power & Light Co Answers & Objections in 790412 proceeding from "expenditure other than expenditure" to "expenditure other than advertising " Certificate of Svc enci, STAHL,D M. Isham, Lincoln & Beale. 79/04/17 4pp
- 7905150780 Birects TX Utils Generating Co (TUGCQ) to produce documents or make full responses to 790115 interrogatories, Deniss TUGCQ's order for protective order.

  MILLER, M & Atomic Safety and Licensing Board Panel. 79/04/18, 2pp
- 7905230624 Response by util to Central Power & Light's 790326 objections & 790403 motion for protective order re util's first set of interrogatories. Includes motion to compel answers. M'notice of appearance & Certificate of Syc. BARNETT, E. M. Baker & Botts. 79/04/19. 18pp.

- 7905230677 Grants extension of time to answer interrogatories by Public Utils Board of Brownsville, TX, in response to 790416 motion MILLER, M.E. Atomic Bafety and Licensing Board Panel. 79/04/19 ip.
- 7905100123 Motion by Central Power & Light to compel TX Utils Generating Co to answer first set of interrogatories submitted 790223 BTAHL:D Isham, Lincoln & Beale 79/04/20 12pp
- 7905100271 Answer by Central Power & Light & Central & South West Corp seeking continuance of NRC untitrust reviews, w/no party banned on grounds of res judicate of colleteral estoppel Supporting documentation & Certificate of Svc encl POWELL, R. E. Isham, Lincoln & Beale. 79/04/20 115pp
- 7905:00106 Opposes City of Austin's 790327 brief & 790403 motions for full or partial summary judgment filed by Mouston Lighting & Power & TX Utils Generating Co Beeks denial of cartification & interlocutory appeals W/Certificate of Syc. LESSY, R. P. Anti-Trust Division. 79/04/23 24pp
- 7905140151 Response of Public Utils Board of Brownsville, TX opposing Houston Lighting & Power motion for summary decision & City of Austin brief in support of res judicate Supporting documentation & Certificate of Svc encl MCDIARMID, R C Spiegel & McDiarmid 79/04/23 84pp.
- 790524024B Conforms 790424 teleon that util plans to file response to 790419 Motion By NRC for reconsideration of board order of 790416 compelling further answer by util Certificate of Svc encl FRANKLIN, W J Lowenstein, Neuman, Rais, Axeirad & Toll, 79/04/24 600
- 7905240824 Util's discovery progress rept for Apr.1979. Certificate of 6vc enc! FRANKLIN, W. J. Lowenstein, Newman, Reis, Axelrad & Toll 79/05/02, 785.
- 7903250191 Requests util suppl & update list of privileged documents LESSY, R P. Anti-Trust Division 79/05/02 ip
- 7903230466 NRC answer to motions of Guif Status Util for protective order & order setting conditions for compliance w/790226 subposes Util should produce documents as requested Certificate of Svc encl BLUME, K B. Anti-Trust Division 79/05/04, 14pp
- G. Inspection reports, IE Bulletins & correspondence
- 7905010376 Porwards IE Insp Repts 30-498/79-03 & 50-499/79-03 on 790221-23 & notice of violation.
  SEIDLE.W.C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/03/14 2pp.
- --7905010379 Notice of violation from insp on 790221-23.
  \* Region 4, Dallas, Office of the Director 79/03/13 is.
- --7905010383 IE Insp Repts 50-498/79-03 & 50-499/79-03 on 790221-23.

  Noncompliance noted failure to follow procedures for storage of mati.

  HUBACEK, N 0 , MARTIN, L. E. Region 4, Dallas, Office of the Director MALL. R. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/03/13 9pp
- 7905010279 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
  SEYFRIT.K.V Region 4, Dallas, Office of the Director, 79/03/23, 15.
- 7905010457 Forwards IE Bullstin 79-05A, "Nuclear Incident at " TMI Suppl."

  SEYFRIT, K. V Region 4, Dallas, Office of the Director, 79/04/05, 1p.
- 7905040492 Forwards IE Bulletin 79-068. "Review of Operational Errors & Sys Mitalignments Identified During TMI Incident."
  SEYPRIT, K.V. Region 4, Dallas, Office of the Director. 79/04/14
- 7905040613 Forwards IE Builetin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."

  8EYFRIT, K.V. Region 4: Dalles, Office of the Director. 79/04/14.
- 7905070055 Forwards IE Sulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping " Licenses action required, SEYFRIT, K. V. Region 4. Dallas, Office of the Director, 79/04/14, in

- 7905010441 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts." SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/16
- 7905090099 Forwards suppl to lE Bulletin 79-05A. "Nuclear Incident at TMI." SEYFRIT.K V Region 4. Dallas, Office of the Director 79/04/16
- 7905030271 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " Licensee Action required. SEYPRIT, K V Region 4. Dallas, Office of the Director 79/04/17
- 7905240696 Ack receipt of 790403 ltr informing NRC of steps taken to corect violations noted in IE Insp Repts 50-498/79-03 & 50-499/79-03 SEIDLE:N C Region 4- Dallas, Reactor Construction & Engineering Support Branch 79/04/26 ip
- --7905240693 Responds to NRC 790314 ltr re violations noted in IE Insp Repts 50-498/79-03 & 30-499/79-03 Corrective actions storage areas on site surveyed for stainless stael matl in contact w/carbon steel TURNER.E A Houston Lighting & Power Co 79/04/03 2pp
- S Reportable occurrences, LERs & related correspondence
- 7905030138 Forwards PNO-79-67H.I.J & K SEYPRIT.K V Region 4. Dallas, Office of the Director 79/04/06. 1P
- 7905030094 Forwards PNO-79-67L.H.N & P SEIDLE:W C. Region 4. Dallas, Reactor Construction & Engineering Support Branch 79/04/09 IP
- 7905030095 Forwards PND-79-67Q SEIDLE:W C Region 4. Dallas, Reactor Construction & Engineering Support Branch 79/04/10 1p
- 7905030143 Forwards PNO-79-67R & 79-77
  BEIDLE:W C Region 4. Dallas, Reactor Construction & Engineering Eupport Branch 79/04/11. 1p
- 790303011B Forwards PNO-79-678
  BEIDLE,W C Region 4. Dallas. Reactor Construction & Engineering
  Support Branch 79/04/12 ip
- 7903030189 Forwards PNO-79-67T SEIDLE:N C Region 4. Dallas. Reactor Construction & Engineering Support Branch 79/04/13 ip.
- 7905030071 Forwards PNO-79-67U & V BEIDLE,W.C Region 4. Dellas, Reactor Construction & Engineering Support Branch 79/04/16 1P
- 7903030240 Forwards PNO-79-67W SEIDLE, W. C Region 4. Dallas, Reactor Construction & Engineering Support Branch 79/04/17 1p.
- 7905020516 Forwards PNG-79-67AA 8EIDLE,W.C Region 4. Dallas, Reactor Construction & Engineering 8upport Branch. 79/04/20 ip
- 7905020505 Forwards FNO-79-67AB.AC & AD. BEIDLE.W C. Region 4. Dallas, Reactor Construction & Engineering Support Branch. 79/04/23. 1p.
- 7905040391 Forwards PNO-79-67AE BEIDLE.W.C. Region 4, Delias. Reactor Construction & Engineering Support Branch 79/04/26 ip
- --7905040406 PNO-79-67AE, summary of info re nuclear incident as of 790524, Describes plant & environ status.

  \* Office of Inspection & Enforcement, 79/04/24, 3pp.
- 7905070183 Forwards PNG-79-67AF & AG.
  BEIDLE,W C. Region 4. Dallas. Reactor Construction & Engineering Support Branch 79/04/27 ip.
- 7905310216 Forwards PNO-79-67AH, AI & AJ. SEIDLE, H. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch, 79/04/30. 1p.
- 7905240385 Forwards PNC-79-67AK & AL. SEIDLE,# C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/05/04. Sp

- DOCKET 50-500 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 2

  Adjudicatory correspondence
- 7905[602]6 Forwards final evaluation of items discussed in 790228 member 8 B&N designed nuclear plants Requests add) info be forwarded to licensing boards
  MOSLEY-N C Division of Reactor Operations Inspections 79/03/28-10pp
- 7905160163 Forwards Board Notification 79-10 on reactor inspector concerns re B&H plants Certificate of Byc encl 8CINTO, J F Hearings Division 79/03/29 14pp
- --7905160185 Board notification reactor inspector concerns re 8kW plants VASSALLO B Assistant Director for Light Hater Reactors 77/03/06 2pp
- ---7905160201 Forwards two Moseley-to-Thompson memos for Board notification info THOMPSON: D Office of I & E Executive Officer for Operations Bupport 79/03/29 ip
- ---7905160207 Preliminary avaluation of Item 3 contained in 790328 geno will be reviewed in light of TMI transient Add1 info may cause change in previous assessment HOSELY.N C Division of Reactor Operations Inspections 79
- 7905160112 Board notification nuclear incident at TMI Recommends boards on cases involving B&W reactors be provided w/IE Bulletin 79-05 & PNO-67 & 67A.B.C.D.E.F.O & H VASSALLO.D B Assistant Director for Light Water Reactors 79/04/03. 2ap
- 7905110418 Response to ALAB-509 re radon emissions & de minimus theory from Perkins record Certificate of Svc encl. SCINTG, J.F. Rearings Division 79/04/11 45pp
- 7905140519 Response to 790404 brief of Philadelphia Electric Co,PSELQ & Atlantic City (NJ) Electric Co re de minimus theory Certificate of Svc ancl KEPFORD, C R Citizens for Bafe Environment 79/04/11 8pp.
- 7905140332 Notifies of consolidation of five intervenor groups to reference missions issue Parties have until 790525 in which to file for summary disposition DUFLO.M.E Atomic Safety and Licensing Appeal Panel 79/04/25 13pp
- J Insurance & indemnity information
- 7905070497 Confirms increased liability limit to #124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,185,186,187,188,189,192,193,194,195,197,198,200,201,204,206,207,206,210,212,214,215,&others.

  QUATTROCHHI, J American Nuclear Insurers, 79/05/01, 1p.
- 7905070382 Confirms increase in liability limit to \$36,000.000 for policies MF-22.26,29.38,39,44,46,47,49.50,51,52,53,54,55,54,55,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,91,92,93,94,75 & 96 ROBERTS, D M Mutual Atomic Energy Liability Underwriters. 79/09/01
- 7905140361 Forwards Endorsements 28 & 29 to NELIA Policy NF-236 LLOYD,R D. Marsh & McLenon, M & M Nuclear Consultants, Inc. Div 79/05/07. 3pp
- @ Inspection reports, IE Bulletins & correspondence
- 7903020461 Forwards IE Insp Rept 50-500/79-01 & 50-501/79-01 an 790222 No noncompliance noted. FIORELLI.G. Region 9, Chicago, Reactor Construction & Engineering Support Branch. 79/03/22 2pp
- --7905020470 IE Inep Rept 50-500/79-01 & 50-501/79-01 on 740222. No noncompliance noted Major areas inspected: GA/GC program in applicable areas, drilling & grouting in progress & manpower requirements.

  JONES, C. E., HAYES, D. W., KNDP, R. C., Region G, Chicago, Office of the Director. 79/03/19. App.
- S. Reportable occurrances, LERs & related correspondence
- 7905020266 Notifies of reportable event on 790413 certain starters for essential motors had overload heaters installed which were smaller than capacity specified on relay date sheets causing possible overload heater burnout Heater being replaced MURRAY, T D. Toledo Edison Co. 79/04/16, ip.

DOCKET 50-501 DAVIS-BESSE NUCLEAR FOWER STATION, UNIT 3

## 9 Adjudicatory correspondence

- 7905160216 Forwards final evaluation of items discussed in 790228 memo re B&W designed nuclear plants Requests add1 info be forwarded to licensing boards MOSLEY.N C Division of Reactor Operations Inspections 79/03/28
- 7905660163 Forwards Board Notification 79-10 on reactor inspector concerns re 884 plants Certificate of 8vc encl SCINTO, J.F. Hearings Division 79/03/29 14pp
- --7903160183 Board notification reactor inspector concerns re B&W plants VABSALLD, D B Assistant Director for Light Water Reactors 79/03/04 2pp
- --7905160201 Forwards two Mosaley-to-Thompson mamos for Board notification info
  TEICHPSCH.D. Office of I & E Executive Officer for Operations
  Support 79/03/29 ip
- ~~7905160209 Praliminary evaluation of Item 3 contained in 790328 memo will be reviewed in light of TMI transient Add1 info may cause change in previous assessment MOSELYAN C Division of Reactor Operations Inspections 1 p 79/03/29.
- 7905160112 Board notification nuclear incident at TMI Recommends boards on cases involving BMM reactors be provided w/IE Bulletin 79-05 & PNO-67 & 67A, B, C, D, E, F, O & H VASSALLO, D 8 Assistant Director for Light Water Reactors 79/04/03. 2pp
- 7905110418 Response to ALAR-509 re radon emissions & de minimus theory from Perkins record Certificate of Byc encl.
  5CENTO, J. F Hearings Division. 79/04/11. 45pp
- 7905140519 Response to 790404 brief of Philadelphia Electric Co.PBE&O & Atlantic City (NJ) Electric Co re de minimus theory, , Centificate of Svc encl KEPFORD.C R Citizens for Safe Environment 79/04/11 Spp
- 7905140332 Notifies of consolidation of five intervenor groups re radon emissions issue Parties have until 790525 in which to file for summary disposition DUFLO: M.E. Atomic Safety and Licensing Appeal Panel 79/04/25.

# J. Insurance > indemnity information

- 7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,176,179,180,182,185,186,187,188,189,192,193,194,195,197,198,200,201,204,204,207,208,210,212,214,215,& others.

  GUATTROCHHI,J. American Nuclear Insurers 79/05/01, 1p
- 7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,56,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,80,69,87,88,90,91,92,93,94,95 & 96
  RQBERTS, D M. Mutual Atomic Energy Liability Underwriters. 79/05/01.
- 7903140361 Forwards Endorsements 28 & 29 to NELIA Policy NF-236. LLCYD:R D. March & McLenon, M & M Nuclear Consultants: Inc. Div. 79/05/Q7. 3pp.

# G. Inspection reports, IE Bulletins & correspondence

- 7903020461 Forwards IE Insp Rept 50-500/79-01 & 50-501/79-01 on 790222 No noncompliance noted
  FIGRELLI, 0. Region 3. Chicago, Reactor Construction & Engineering
  Support Branch. 79/03/22. 2pp.
- ---7905020470 IE Insp Rept 50-500/79-01 & 50-501/79-01 on 790222. No noncompliance noted Major areas inspected; GA/GC program in applicable areas, drilling & grouting in progress & manpower requirements.

  JONES: C E., HAYES, D. W., KNOP, R. C. Region G, Chicago, Office the Director 79/03/19 App Region 3, Chicago, Office of
- B. Resortable occurrences, LERs & related correspondence
- 7903020266 Notifies of reportable event on 790413, certain starters for essential motors had overload heaters installed which were smaller than capacity specified on relay data sheets causing possible overload heater burnout Heater being replaced MURRAY.T.D. Toledo Edison Go 79/04/16. ip.

# DOCKET SIN-50-502 HAVEN NUCLEAR PLANT, UNIT I A Application/construction stage documents & correspondence

- 7905100322 Requests info re State of HI Public Svc Commission views on limiting const of facility & effect of HI Electric Power Co application for single nuclear unit hear Haven in Sheboygan County HI County, WI DENTON, H R Commission 79/04/05 2pp
- 7905090141 Forwards request for addl info re outstanding alternate Sites issues BALLARD, R L Environmental Projects Branch 1 79/04/19. 3pp
- 790303037 Forwards add1 copies of results of geological investigations re-possible faulting under Lake Michigan.presented by utility & SWH at 790307 meeting w/NRC No evidence of faulting indicated. 62 oversized drawings in Central Files BURSTEIN.8 Hisconsin Electric Power Co 79/04/20 86pp
- 7903150361 Bubmits addl info re PBAR & site addendum in response to 790320 request Identifies items requiring addl time for completion completion BURSTEIN,S. Hisconsin Electric Power Co 79/05/10 33pp
- B Utility Preliminary Bafety Analysis Report, amends
- 7905010513 Forwards Amend 22. to be inserted into PBAR site addendum Affidavit encl BURBTEIN, 8 Wisconsin Electric Power Co. 79/04/20 2pp
- --7903010515 Amend 22 to PBAR site addendum Invertion instructions enci \* Wisconsin Electric Power Co 79/04/20. 138pp
- C. Utility Environmental Report (ER), amends & correspondence
- 7905010489 Forwards "Amend 14 to Environ Rept," CP stage BURSTEIN,S Wisconsin Electric Power Co. 79/04/18
- ---7905010490 "Amend 14 to Environ Rept." CP stage w/oversized drawings \* Wisconsin Electric Power Co 79/04/18. 161pp

# O. Adjudicatory correspondence

- 7905070230 Requests explanation for dismissal of 701009 motion 9070230 Nequess spienness. spitificate of Svc enci. ANLEY, H.C. Bafe Energy for New Heven 79/03/30, Spp.
- 7905310267 Motion & brief in support of verification & analysis of data supplied by S&N Certificate of Svc enc1 HANLEY.W C. Bafe Energy for New Haven. 79/03/30. 2pp
- 7905250339 Beeks denial of 790330 motion by intervenor Bafe Haven for varification & analysis of computations & computer codes.

  Intervenor is making inappropriate requrest beyond scope of CHURCHILL, B W Shaw, Pittman, Potts, & Troubridge 79/04/13 App.
- 7905240286 Response in opposition to intervenor Safe Haven 790330 motion for verification & analysis of all S&W computer codes Intervenor does not cits sufficient facts or legal authority. Certificate of Svc encl. OCLOBERO. B.C. Branch 2 79/04/17. App.

# H. General correspondence

- 7905080470 Forwards affidavits of FP Libertowicz, attesting svc of environ rapt Amends 13 % 14 % PBAR Amend 22, BURBTEIN, 8 Wisconsin Electric Power Co. 77/05/02, 10pp.
- J. Insurance & indemnity information
- 7905070497 Confirms increased liability limit to \$124,000,000 fur policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170, 173,174,178,179,180,182,185,186,187,188,189,192,193,194,195, 197,198,200,201,204,206,207,208,210,212,214,215,& others, QUATTROCHHI,J. American Nuclear Insurers. 79/05/01, 1p.
- 7905070382 Confirms increase in liability limit to 836,000,000 for policies MF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,56,57,58,60,61,64,66,67,68,67,70,71,72,74,76,77,78,79,80,80,86,87,88,90,91,92,93,94,95 & 96

248

# DOCKETED ITEMS

- P. Operating license stage documents & correspondence
- 7905240395 Forwards chronology of FSAR amend re GA program in response to NRC 790320 request BASKIN., K.P. Southern California Edison Co. 79/04/27 3pp
- DOCKET STN-50-503 HAVEN NUCLEAR PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 7905100322 Requests info re State of WI Public Svc Commission visus on limiting const of facility & effect of WI Electric Power Co application for single nuclear unit hear Haven in Sheboygan County WI DENTON W R Commission 79/04/05 29p
- O Adjudicatory correspondence
- 7905070230 Requests explanation for dismissal of 781009 motion Certificate of Byc encl HANLEY/H C \_ Safe Energy for New Hayen. 79/03/30 3pp
- 7903310267 Motion & brief in support of verification & analysis of data supplied by 55W Certificate of Svc encl HANLEY,W.C Safe Energy for New Haven 79/03/30 2pp
- DOCKET STN-50-508 HPPBS NUCLEAR PROJECT, UNIT 3
- A Application/construction stage documents & correspondence
- 7905040379 Forwards Suppl 4 to "Groundwater Drainage Sys, Analysis of Sys Performance & Data to Date " RENBERGER, D L Washington Public Power Supply System 79704/26.
- --7905040388 Suppl 4 to "Oroundwater Drawings Sys.Analysis of Sys Performance & Data to Date " Oversized drawings encl \* Hashington Public Power Supply System 79/03/31. 10pp.
- 7905240411 Forwards NRC positions on HPPSS-GA-004, "Operational GA Program Description" Response to positions should be submitted by 790401 as amend to original rept HAASS, W P Guality Assurance Branch 79/05/01 2pp
- 7905160037 Notifies that environ evaluation has been performed on West Laydown Area; no adverse impacts associated w/development activity Development of area to begin in June 1979. Forwards internal memo & rept ne potential environ impacts RENBERGER, D. L. Hashington Public Power Supply System 79/05/07.
- I Financial information

Ð

Α.

 $x_{i,j}|_{L_{i}^{1,j}} \big\}$ 

2.296

The second of th

- 7905090284 Forwards "Annual Financial Rept 1976" for Puget Sound Power & Light Co.Portland GE.Pacific Power & WPP88 RENERGER.D L Washington Public Power Supply System 79/05/01
- --7905090285 "Annual Financial Rept 1978."

  \* Puget Sound Power & Light Co. 78/12/31, 44pp.
- ---7905090288 "Annual Financial Rept 1978 "
  \* Portland General Electric Co 79/03/31 40pp
- --7905090293 "Annual Financial Rept 1978," \* Pacific Power Co. 78/12/31 32pp
- ---7905090295 "Annual Financial Rept 1978,"

  \* Washington Public Power Supply System. 78/12/31 45pp.
- --7905090303 "Annual Financial Rept 1978."

  \* Washington Water Power Co. 78/12/31 32pp.
- 4 Inspection reports, IE Builetins & correspondence
- 7905010294 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping." ENGELKEN.R H. Region 4, Dallas, Office of the Director, 79/03/23 ig.
- 7905010015 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Bus Missignments Identified During TMI Incident." EMBELKEN.R H Region S, San Francisco, Office of the Director. 79704714 ip.

- 7905040516 Forwards IE Bullstin 79-06B, "Review of Operational Errors & Bys Misalignments Identified During TM1 Incident "ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/14 10
- 7905040625 Forwards IE Bulletin 79-08. "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident." ENGELKEN.R H. Region 5. Ban Francisco, Office of the Director 70/04/14. 10
- 7905070110 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Bafaty-Related Piping " Licensee action required ENGELKEN,R H Region 5, Ban Francisco, Office of the Director 79/04/14 io
- 7905030305 Forwards IE Bulletin 79-09, "Failures of GE Typs AK-2 Circuit Breaker in Safety-Related Sys " Licenses action required. ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/17 1p
- 7905080378 Forwards IE Bulletin 79-058, "Nuclear Incident at THI-Suppl" ENGELKEN.R H. Region 5, Sen Francisco. Office of the Director. 79/04/21 1p.
- 8 Reportable occurrences, LERs & related correspondence
- 7905150069 Forwards PNO-79-67L ENGLIKEN, R. H Region 5. San Francisco. Office of the Director 79/04/04 1p
- 7905130173 Forward\* PNO-79-67R ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/04/11 1p
- 7905040134 Forwards PNO-79-678.
  ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/04/12 1s
- 7905150150 Forwards PNO-79-67T.
  ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/04/13. 1p.
- 7903030018 Forwards PNO-79-67U.
  ENGELKEN,R H Region 5. Ban Francisco, Office of the Director, 79/04/14. 10.
- 7905020836 Forwards PNO-79-67AA ENGELMEN.R.H. Region 5, San Francisco, Office of the Director 79/04/20 1p
- 7905010439 Forwards PNO-79-67AB ENDELMEN.R.H. Region 5, San Francisco, Office of the Director 79/04/21 1s.
- 7903010452 Forwards PNO-79-67AC & AD. ENGELKEN, R. H Region 3, Ban Francisco, Office of the Director 79/04/23, 1p
- 7905010463 Forwards PNO-79-67AE ENGELKEN,R H Region 3, Ban Francisco, Office of the Director 79/04/24 1p.
- 7905090047 Forwards PNO-79-67AF. ENGELKEN.R H. Region 5, Ban Francisco, Office of the Director 79/04/23 ip
- 7905090059 Forwards PNO-79-67AC. ENGELKEN, R. H. Region 5. San Francisco, Office of the Director 79/04/26. 1p.
- 7905090121 Forwards PND-79-67AH. ENGLEKEN,R.H. Region 5. San Francisco, Office of the Director. 79/04/27. 1p
- 7905070034 Forwards PNO-79-67AI, AJ & AK per NRC 790401 ltr transmitting IE Bullstin 79-05. ENGLKEN.R.H. Region 5. San Francisco, Office of the Director. 79704730. lp.
- 7905070018 Forwards PND-79-67AL per NRC 790401 ltr transmitting IE Bulletin 79-03. ENGELKEN,R.H Region 5, San Francisco, Office of the Director 79/05/01. 1p.

7905310037 Forwards PNO-79-67AM.
ENGELKEN.R H Region S. San Francisco. Office of the Director 79/05/07 19

## DOCKET STN-50-509 WPPSS NUCLEAR PROJECT, UNIT 5

- A Application/construction stage documents & correspondence
- 7705040379 Forwards Suppl 4 to "Groundwater Drainage Sys, Analysis of Sys Performance & Data to Date " RENBERGER, D L. Washington Public Power Supply System 79/04/26 3aa
- ---7903040388 Suppl 4 to "Groundwater-Drawings Sys, Analysis of Sys Parformance & Data to Date " Oversized drawings and \* Washington Public Power Supply System 79703/31. 10pp
- 7705240411 Forwards NRC positions on WPP88-GA-004, "Operational GA Program Description " Response to positions should be submitted as amend to original rept by 790601. HAASS, W.P. Guality Assurance Branch 79/05/01 2pp
- 7905160337 Natifies that environ evaluation has been performed on West Laydown Arsaino adverse impacts associated w/development activity Development of area to begin in June 1979 Forwards Internal memo & rept re potential environ impacts RENBERGER.D L. Washington Public Power Supply System 79/05/07.

#### I Financial information

- 7905090284 Forwards "Annual Financial Rept 1978" for Puget Sound Power & Light Co.Portland OE.Pacific Power & WPPBS
  RENBERGER.D L Washington Public Power Supply System 79/05/01
- --7905090285 "Annual Financial Rept 1978 " # Puget Sound Power & Light Co 78/12/31 44pp
- --7905090288 "Annual Financial Rept 1978 "
  # Portland General Electric Co 79/03/31. 40pp
- ---7905090293 "Annual Financial Rept 1978."

  \* Pacific Power Co 78/12/31. 32pp
- ---7905090295 "Annual Financial Rept 1978."

  \* Weshington Public Power Supply System 79/12/31 45pp.
- --7905090303 "Annual Financial Rept 1978 "
  \* Washington Water Power Co 78/12/31 32pp
- 7909010274 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping" ENGEKENIR H Region 4, Dallas, Office of the Director 79/03/23
- 7905010015 Forwards IE Bulletin 79-06A. "Review of Operational Errors & Sys Misslignments Identified During TMI Incident "ENGELKEN.R H Region S, Ban Francisco, Office of the Director 79/04/14. 1p
- 7905040516 Forwards IE Bulletin 79-068, "Review of Operational Errors & Bus Misalignments Identified During TMI Incident." ENGELKEN, R H Region 5, Ban Francisco, Office of the Director 79/04/14 to.
- 7905040625 Forwards IE Bulletin 79-08. "Evants Relevant to Boiling Mater Power Reactors Identified During TMI Incident "ENGELKEN.R.H. Region 5. Ban Francisco: Office of the Director, 79704/14. 1p
- 7905070110 Forwards IE Bulletin 79-07, "Heismic Stress Analysis of Safety-Related Piping " Licenses action required. ENGELKEN.R.H. Region 5, Ban Francisco, Office of the Director 79/04/14 | 1p.
- 7705030305 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Bys " Licensee action required. Region 5, San Francisco, Office of the Director, 79/04/17, 1p.
- 41
- 7905080378 Forwards IE Bulletin 79-058, "Nuclear Incident at TML-Suppl." EMBELKEN.R.H. Region 5, San Francisco, Office of the Director, 79/04/21, 1p

- 8 Reportable accurrences, LERs & related correspondence
- 7903130069 Forwards PNO-79-67L ENGELKEN,R H Ragion 3, Ban Francisco, Office of the Director 79/04/06 ip
- 7905150173 Forwards PNO-79-67R ENGELKEN:R H Region 5. San Francisco. Office of the Director 79/04/11. 1p
- 7903040134 Forwards PNO-79~678
  ENGELKEN,R H Region 5, San Francisco, Office of the Director.
  79/04/12 ip
- 7905150150 Forwards PNO-79~67T ENGELKEN.R.H Region 5. San Francisco. Office of the Director 79/04/13 1p
- 7905030018 Forwards PNO-79-67U
  ENGELKEN,R H Region 3, San Francisco, Office of the Director.
  79/04/14 1p
- 7905020536 Forwards PNO-79-678A ENGELKEN,R H Region 5, San Francisco, Office of the Director. 79/04/20 ip
- 7903010439 Forwards PNO-79-67AB ENGELKEN.R H Region 5: Sam Francisco. Défice of the Director 79/04/21 1p.
- 7905010452 Forwards PNO-79-67AC & AD
  ENGELKEN.R H. Region 5. Sen Francisco. Office of the Director
  79/04/23 ip
- 7905010463 Forwards PND-79-67AE ENGELKEN/R H Region 5, San Francisco, Office of the Director 79/04/24, 1p.
- 7903090047 Forwards PNO-79-67AF ENGELKEN,R H Region 5. San Francisco, Office of the Director, 79/04/25 is
- 7903090039 Forwards PNO-79-67AQ ENGELKEN:R H. Region 5: San Francisco: Office of the Director 79/04/26. 1p
- 7905090121 Forwards PNO-79-67AH. ENGLEMEN,R H Region 5, San Francisco, Office of the Director, 79/04/27. 1p
- 7905070034 Forwards PNO-79-67AL, AJ & AK per NRC 790401 ltr transmitt. IE Bulletin 79-05. ENOELKEN.R.H Region 5. San Francisco. Office of the Director. 79/04/30. 1p
- 7905070018 Forwards PNO-79-67AL per NRC 790401 ltr transmitting IE Bulletin 79-05 ENOELKEN.R.H Region 5, San Francisco, Office of the Director. 79/09/01. ip.
- 7905310037 Forwards PNO-79-67AM.
  ENGELMEN.R.H. Region 5. San Francisco. Office of the Director.
  79/05/07 is

#### DOCKET 50-510 BLUE HILLS STATION, UNIT 1

- 9. Adjudicatory correspondence
- 7905130143 Forwards 780929 memo discussing results of recently conducted fire protection research test; performed by UL as part of NRC fire protection research program WOODHEAD, G.P Branch 3. 79/04/OS, 1p
- 7905240212 Evidentiary hearing re application / .to review will begin 790508.
  MILLER, M. E. Atomic Safety and Licensing Board Panel. 79/04/06.
- 7905300215 Requests permission to address site hearings. EVANS.R. Sierra Club. 79/04/26. 1p.

#### T Hearing transcripts on non-antitrust matters

- 7905230363 Transcript of 790508 hearing in Jasper,TX Pp 1-122 MILLER,M E . LITTLE,L W . KORNBLITH,L Atomic Bafety and Licensing Board Panel 79/03/08 123pp
- 7905250070 Transcript of 790509 hearing in Jasper TX Pp 123-289
  MILLER H E , LITTLE L W , KORNBLITH L Atomic Safety and Licensing
  Board Panel 79/05/09 167pp

DOCKET 50-511 BLUE HILLS STATION, UNIT 2

Q. Adjudicatory correspondence

- 7905:30143 Forwards 780929 memo discussing results of recently conducted fire protection research test performed by UL as part of NRC fire protection research program WODDHEAD, C P Branch 3 79/04/05 ip
- 7905240212 Evidentiary hearing re-application for early site review will begin 790508
  HILLER, M.E. Atomic Safety and Licensing Board Panel 79/04/06
- 7905300215 Requests permission to address site hearings EVANS.R Bierra Club 79/04/26 ip
- T. Hearing transcripts on non-antitrust matters
- 7905230563 Transcript of 790508 hearing in Jasper TX Pp 1-122 HillER M E , LITTLE L W , KORNBLITH L. Atomic Safety and Licensing Board Panel 79/05/08 123pp.
- 7903280070 Transcript of 790309 hearing in Jasper TX Pp 123-289
  MILLER M. E. LITTLE, L. W., KORNBLITH, L. Atomic Sefety and Licensing
  Board Panel 79/03/09, 167pp

DOCKET 50-513 WPPSS NUCLEAR PROJECT, UNIT 4

- A. Application/construction stage documents & correspondence
- 7905010486 Repts on geological studies' status Ceneric rept expected in Fall 1979, Requests meeting to discuss glans for submitting repts of studies, as well as mechanism for identification & review of studies in Hanford area RENBERGER, D.L. Washington Public Power Supply System 79/04/27
- 7905240411 Forwards NRC positions on WPP8S-GA-004, "Operational GA Program Description." Response to gositions should be submitted as amend to original rept by 790601.

  HARBS-W P Quality Assurance Branch 79705/01 2pp.
- 7905230534 Requests NRC ltr stating acceptability of scale model tests in lieu of implant tests, to satisfy commitment in MNP-1/4 PBAR Question 6, 77 re recirculation sump testing, RENBERGER, D.L. Washington Public Power Supply System. 79/03/15.

ion of review on ASLB ng record.

stem 79/04/09.

& de minimus theory

p.

a Electric Co.PSE&O & ory.

/04/11 8pp.

venor groups re radon th to file

anel. 79/04/25.

#### Q. Inspection reports, IE Bulletins & correspondence

- 7905010294 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping" ENCELKEN, R H Region 4, Dallas, Office of the Director 79/03/23
- 7905010015 Forwards IE Bullstin 79-04A. "Review of Operational Errors & Sys Misalignments Identified During TMI Incident " ENGELKEN,R H Region 5, Ban Francisco, Office of the Director 79/04/14 ip
- 7905040516 Forwards IE Bulletin 79-06B. "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "
  ENGELKEN,R H Region 5. San Francisco. Office of the Director 79/04/14 ip
- 7905040625 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Mater Pawer Reactors Identified During TMI Incident." ENGELKEN, R H Region 5. Ban Francisco. Office of the Director, 79/04/14 ip
- 7905070110 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping " Licenses action required ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/04/14 ip
- 7905030305 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Bys " Licenses action required ENGELKEN.R H Region 5, San Francisco, Office of the Director 79/04/17.
- 7905080378 Forwards IE Bullstin 79-058, "Nuclear Incident at THI-Suppl"
  ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/04/21 10
- 8 Reportable occurrences, LERs & related correspondence
- 7905150069 Forwards PNO-79-67L ENGELKEN.R H Region 5, Ban Francisco. Office of the Director 79/04/06 ip
- 7903130173 Forwards PNO-79-47R.
  ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/11 1p
- 7905040134 Forwards PNO-79-678
  ENGELKEN.R H Region 5. San Francisco. Office of the Director.
  79/04/12 ip
- 7905150150 Ferwards PNO-79-67T ENGELKEM, R. H Region S. Ban Francisco, Office of the Director 79/04/13 ip
- 7905030018 Forwards PND-79-67U, ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/04/14 10
- 7905020536 Forwards PNO-79-67AA. ENGELKEN, R. H Region 3, San Francisco, Office of the Director 79/04/20. 1p
- 7905010439 Forwards PNO-79-67AB ENGELKEN.R. H. Region 5. San Francisco, Office of the Director 79/04/21. 1p.
- 7905010452 Forwards PND-79-67AG & AD. ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/04/23 in
- 7903010463 Forwards PNO-79-67AE.
  ENGELKEN,R H Region 5, San Francisco, Office of the Director.
  79/04/24 1p.
- 7905090047 Forwards PNQ-79-67AF ENGELKEN.R H. Region 5, San Francisco, Office of the Director. 79/04/25. 1p.
- 7905090059 Forwards PNC-79-67AQ.
  ENGELKEN.R H. Region 5. San Francisco, Office of the Director 79/04/26. 1p.

- 7905090121 Forwards PND-779-67AH ENLEKEN.R.81 Region 5, San Francisco, Office of the Director 79/04/27 1p
- 7905070034 Forwards PND-79-67AI.AJ & AK per NRC 790401 ltr transmitting IE Bulletin 79-05
  ENGLKEN.R H Region 5. San Francisco. Office of the Director
- 7905070010 Forwards PNO-79-67AL per NRC 790401 itr transmitting IE Bulletin 79-05 ENOELKEN.R H Region 5, Ban Francisco, Office of the Director 79705/01 1p.
- 7905190067 Forwards final deficiency rept re letdown cooler supports, psr 790416 telcon.
  RENBERGER, D. L. Washington Public Power Supply System 79/05/07 to.
- --703190069 Final deficiency rept letdown cooler supports inadequate to support specified loads Caused by inadequate design by component manufacturer Wall mounted brackets redesigned washington Public Power Supply Bystem 79/05/07 2pp
- 7905310037 Forwards PNO-79-67AM ENDELKEN,R H Region 5, Ban Francisco, Office of the Director 79/05/07 ip.
- 7905240457 Ack receipt of 790507 final deficiency rept on letdown cooler support design inadequacy.
  ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/05716 ip

## DOCKET 50-514 PERBLE SPRINGS NUCLEAR PLANT, UNIT 1

#### @ Adjudicatory correspondence

- 7905140163 Forwards Board Notification 79-10 on reactor inspector concerns to HRW plants, Certificate of Svc encl SCINTD J F Hearings Division 79/03/29 14nn
- 7905010115 Forwards request for Board notification re nonsafety-grade equipment to mitigate transients 8CINTG.J.F Hearings Division 79/04/02, 31pp
- --790503031B6 Doard notification staff assessment re nonsafety-grade equipment to mitigate transfents. VABSALLEQ.D.B Assistant Director for Light Water Reactors 79703/27 2pp
- --7905010198 Board notification recent issue on nonsafety-grade equipment to mitigate transients More info is required TEDESCO.R L. Assistant Director for Reactor Safety 79/03/16
- 7003160112 Board notification.nuclear incident at TMI.Recommends boards on cases involving B&H reactors be provided w/IE Bulletin 79-05 & PND-67 & 676.B.C.D.E.F.O & H. VABSHLLO, D.B. Assistant Director for Light Water Reactors 79/04/03 2pp.
- 7905240762 Hemo & order re 790620 conference to discuss schedules, status of state of OR proceeding & status of open items YORE, J. R. Atomic Safety and Licensing Board Panel 79/05/11 2pp

#### I Financial Information

- 7905250475 "Annual Financial Rept 1978" from BEC s Portland Cameral Electric Co. 78/12/31 55pp
- J. Insurance & indemnity information
- 7905070497 Gunfirms increased liability limit to \$124,000,000 for palicies NF-1,23,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,183,186,187,188,189,192,193,194,195,197,198,200,201,204,206,207,208,210,212,214,215,& others. QUATTROCHHI, J. American Nuclear Insurers. 79/05/01 1p.

- O Advisory Committee on Reactor Safeguards reports & correspondence
- 7905110014 Forwards responses to 26 ACRS questions re plant application, in response to NRC 771121 ltr HILLIAMS, J L Portland General Electric Co 77/11/30 lipp
- P Operating license stage documents & correspondence
- 7905030361 Responds to DOE 790411 1tr Unable to provide supplemental info by 790430 Response dependent upon preparation & approval of Offsite Dose Calculation Manual Response will be ready by 790531 GDODWIN, C Portland General Electric Co 79/04/27 ip
- 8 Reportable occurrences, LERs & related correspondence
- 790510203 Board notification Seabrook refueling water storage tank design deficiency SCINTO. J Hearings Division 79/03/29 30pp
- DOCKET 50-515 PEBBLE SPRINGS NUCLEAR PLANT. UNIT 2
- 7905160163 Forwards Board Notification 79-10 on reactor inspector concerns re B&H plants Certificate of Svc encl BCINTO, JF Hearings Division 79/03/29 14pp
- 7905010115 Forwards request for Board notification re nonsafety-grade equipment to mitigate transients BCINTOL JF Hearings Division 79/04/02 Sipp
- --7903010156 Board notification staff assessment re nonsafety-grade equipment to mitigate transients VASBALLO.D B Assistant Director for Light Water Reactors 79/03/29 2pp
- ---7905010198 Board notification recent issue on nonsafety-grade equipment to mitigate transients More info is required TEDEECO.R L Assistant Director for Reactor Bafety 79/03/16
- 7905160112 Board notification nuclear incident at TMI Recommends boards on cases involving BAW reactors be provided w/IE Bulletin 79-05 & PNO-67 & 67A.B.C.D.E.F.O & H VASSALLO,D B Assistant Director for Light Water Reactors 79/04/03 2pp
- 7905240762 Memo & order re 790620 conference to discuss schedules, status of state of OR proceeding & status of open items
  YORE, J. R. Atomic Safety and Licensing Board Panel 79/05/11 2pp
- J Insurance & indemnity information
- 7905070497 Confirms increased liability limit to \$124.000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,179,179,180,182,185,186,187,188,189,192,192,193,194,175,197,198,200,201,204,206,207,208,210,212,214,215,4 others QUATTROCHHI, J American Nuclear Insurers 79/05/01 ip
- 7905070582 Confirms increase in liability limit to \$36,000,000 for policides MF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,56,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,91,92,93,94,95 & 96 ROBERTS,D M Mutual Atomic Energy Liability Underwriters 79/05/01
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 7905110014 Forwards responses to 26 ACRB questions re plant application, in response to NRC 771121 ltr.
  HILLIAMS, J. L. Portland General Electric Co 77/11/30. 11pp
- P. Operating license stage documents & correspondence
- 790803036i Responds to DOE 790411 ltr Unable to provide supplemental info by 790430 Response desendent upon preparation & approval of Offsite Dose Calculation Hanual Response will be ready by 790531

  OUGDWIN.C. Portland General Electric Co 79/04/27, 1p

- 8 Reportable occurrences, LERs & related correspondence
- 7905110203 Board notification Seabrook refueling water storage tank design deficiency
  SCINTO, J. Hearings Division 79/03/29 30pp.
- DOCKET STN-50-516 JAMESPORT NUCLEAR STATION, UNIT 1
- Q Adjudicatory correspondence
- 7905010115 Forwards request for Board notification re nonsafety-grade equipment to mitigate transients

  SCINTO.JF Hearings Division 79/04/02 31pp
- --7905010154 Board notification staff assessment re nonsafety-grade equipment to mitigate transients VABSALLO.D B Assistant Director for Light Water Reactors 79/03/29 2pp
- --7905010198 Board motification recent issue on nonsefety-grade equipment to mitigate transients More info is required TEDESCO.R i. Assistant Director for Reactor Bafety 79/03/16 Gpo
- 7905100192 Applicants' brief opposing Suffolk County 790118 exceptions & 790226 supporting brief. Supporting documentation & Certificate of Svc encl REVELEY, W T . WHITTEMORE Hunton & Williams 79/04/02 53pp
- 79050B0053 Responds to request for info re possible shutdown of facility due to possible design deficiencies caused by computer model design Computer model in question not used for facilities
  HOEFLING.R K Branch 4 79/04/03 2pp
- 7905240278 Opposes intervenor County of Suffolk brief in support of exceptions to ASLB 781226 initial decision Certificate of Svc encl
  BVR DENICK, B H Branch 4 79/04/12 29pp
- 7905290106 Requests inclusion of NV Dept of Public Svc on svc list for NY siting proceeding
  BLAU.J New York, State of 79/04/13 1p.
- Q Inspection reports, IE Bulletins & correspondence
- 7905010116 Forwards IE Info Notice 79-06. "Stress Analysis of Safety-Related Piping " GRIER.B.H Region i, Philadelphia, Office of the Director 79/03/23 ip
- 7905020051 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "GRIER.B H Region 1, Philadelphia, Office of the Director, 79/04/11 ip.
- 7905020395 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping " Licensee action required. QRIER.B. H Region 1. Philadelphia. Office of the Director 79704/14 1p
- 790504003B Forwards IE Bulletin 79~05B. "Review of Operational Errors & Sus Misalignments Identified During TMI Incident" GRIER.B H Region 1. Philadelphia. Office of the Director. 79/04/14 ip
- 7905040208 Forwards IE Bullatin 79-08, "Events Relevant to Boiling Hater Power Reactors Identified During THI Incident "ORIER.B.H. Region 1, Philadelphia, Office of the Director 79704/14 ig
- 7905030070 Forwards IE Bulletin 79-09. "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys." Licenses action required ORIER, B H Region i. Philadelphia. Office of the Director. 79/04/17 ip.

÷

- 7905020263 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident," ORIER, B. H. Region 1, Philadelphia, Office of the Director 79/04/18 is
- 8. Reportable occurrences, LERs & related correspondence
- 7905110203 Board notification Seabrook refueling water storage tank design deficiency. 8CINTO.J. Hearings Division, 79/03/29, 30pp

- DOCKET STN-50-517 JAMESPORT NUCLEAR STATION, UNIT 2

  O Adjudicatory correspondence
- 7905010115 Forwards request for Board notification re nonsafety-grads equipment to mitigate transients
  SGINTO.J F Hearings Division 79/04/02 3ipp
- --7903010136 Board notification staff assessment re nonsafety-grade equipment to mitigate transients. VASSALLOID B Assistant Director for Light Water Reactors 79/03/29 200
- --7905010198 Board notification recent issue on nonsafety-grade equipment to mitigate transferts More info is required TEDEBCO, R L Assistant Director for Reactor Bafety 79/03/16
- 7905100152 Applicants' brief opposing Suffolk County 790115
  exceptions & 790226 supporting brief. Supporting
  documentation & Cartificate of Syc encl
  REVELEY, W T , WHITTENORE Hunton & Williams 79/04/02 53pp
- 7905240278 Opposes intervenor County of Suffolk brisf in support of exceptions to ASLB 781226 initial decision Certificate of Svc encl
  BCRDENICK, B M Branch 4 79/04/12 29pp
- 7905270106 Requests inclusion of NY Dept of Public Svc on svc [ist for NY siting proceeding BLAU, J New York, State of 79/04/13 ip
- G Inspection reports. IE Bulletins & correspondence
- 7905010114 Forwards IE Info Notice 79-06. "Stress Analysis of Safety-Related Piping "
  ORIER, B H Region I. Philadelphia. Office of the Director 79/03/23. 1p.
- 7905020051 Forwards IE Bulletin 79-06. "Review of Operational Errors & Bys Misalignments Identified During TMI Incident "
  ORIER, B H Region 1, Philadelphia, Office of the Director 79/04/11. ip
- 7905020395 Forwards IE Bulletin 79-07. "Seismic Stress Analysis of Safety-Related Piping." Licenses action required ORIER. B H. Region i, Philadelphia, Office of the Director, 79/04/14 ip
- 7905040038 Forwards IE Builetin 79-04B, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident."
  ORIER, B.M. Region I, Philadelphia, Office of the Director.
  79/04/14 ip.
- 7905040208 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Fower Reactors Identified During TMI Incident "
  GRIER, B H Region i, Philadelphia, Office of the Director, 79/04/14, ip.
- 7905030070 Forwards IE Bulletin 79-09. "Failures of QE Type AK-2 Circuit Breaker in Safety-Related Sys " Licensee action required QRIER.B H Region 1. Philadelphia, Office of the Director 79/04/17. 1p.
- 7905020263 Forwards IE Bulletin 79-06A: Revision 1, "Review of Operational Errors & Bys Misalignments Identified During THI Incident "ORIER, B H Region 1, Philadelphia, Office of the Director 79/04/18, Ip.
- 8 Reportable occurrences: LERs & related correspondence
- 7905110203 Board notification Beabrook refueling water storage task design deficiency. BCINTO.J. Hearings Division. 79/03/29. SOpp.

- DOCKET STN-50-518 HARTSVILLE NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 7905080841 Discusses util position on leak testing pressure & temp requirements of ACI Stds 318 & 349 for piping to be embedded in concrete Revisions to PBAR re embedded piping will be implemented immediately.

  OILLELAND. J E Tennessee Valley Authority 79/05/03 3sr
- f. Sucurity, medical, amergency & fire protection plans
- 7905300462 Forwards add1 response to 780926 meeting minutes re STRIDE fire hazards; analysis Includes proposed design changes to fire protection sys Requests early meeting to discuss responses
  OILLELAND, J. E. Tennesses Valley Authority 79/05/20 9pp
- 0. Adjudicatory correspondence
- 7905240874 Requests adoption of de minimus theory of Perkins ASLS Cartificate of Svc encl. BANGER.NLS , WALLACE,LE , GUTTERMAN.A H. Tennessee Valley Authority 79704/06 lipp
- 790311041B Response to ALAB-307 re radon emissions & de minimus theory from Parkins record Certificate of Svc encl SCINTO, J. F. Hearings Division 79/04/11 45pp.
- 7905140519 Response to 790404 brief of Philadelphia Electric Co.PBE&Q & Atlantic City (NJ) Electric Co re de minimus theory Certificate of Svc encl.
  KEPFORD, C.R. Citizens for Safe Environment 79/04/11 Bps
- 7905140332 Notifies of consolidation of five intervenor groups ra radon emissions issue Parties have until 790525 in which to file for summary disposition.

  DUFLO: H E. Atomic Bafety and Licensing Appeal Panel. 79/04/25 1300
- J Insurance & indemnity information
- 7903070477 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,144,151,161,164,170,173,174,170,179,180,182,185,186,189,192,193,194,195,177,198,200,201,204,204,204,207,209,210,212,214,215,3 others QUATTRECHHI, J. American Nuclear Insurers. 79/05/01 18.
- 7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,85,56,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,91,92,93,94,95 & 96 ROBERTB,D M. Mutual Atomic Energy Liability Underwriters 79/05/01
- Q Inspection reports, IE Bulletins & correspondence
- 7905010211 Forwards IE Info Notice 79-06. "Stress Analysis of Bafety-Related Piping." U'REILLVJ P. Region 2. Atlanta, Office of the Director 79/03/23. 2pp
- 7905150072 Forwards IE Insp Repts 50-518/79-06.30-519/79-06. 30-520/79-06 & 50-521/79-06 on 790226-28 No noncompliance noted. MURPHY C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 79/03/23 2pp
- --7905150081 IE Insp Repts 50-518/79-04:50-519/79-04:50-520/79-06 & 50-521/79-06 on 790226-28. No noncompliance noted Hajor areas inspected: const activities: IE circulars & GA program as implemented by Const Engineering Hanual.

  BURDETTE: TE. Region 2. Atlanta, Office of the Director.

  HERDT. A R. Region 2. Atlanta, Reactor Construction & Engineering Support Stanct. 79/03/22 App.
- 7905230422 Forwards IE Insp Repts 50-518/79-07, 50-519/79-07, 50-520/79-07 & 50-521/79-07 on 790307-09 No noncompliance noted.

  HARPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/04/02 2pp.
- ---7905280431 IE Insp Repts 50-518/79-07.50-519/79-07.50-520/79-07.40
  50-521/79-07 on 790307-09 No noncompliance noted Major areas inspected concrete foundation of spray pond areas, safety-related steel structures. & GA audits & schedule.

  BHANN H B. Region 2. Atlanta. Office of the Director BHANN H B. Region 2. Atlanta. Reactor Construction & Engineering Support Brench. 79/04/02. 6pp

- 7905240498 Forwards IE Insp Repts 50-518/79-08, 50-519/79-08, 50-520/79-08 & 50-521/79-08 on 790326-0328 No noncompliants noted MURPHY, C E Region 2. Atlanta, Office of the Director 79/64/66 200
- ---7905240507 IE Insp Repts 50-518/79-08.50-519/79-08.50-520/79-08 at 50-521/79-08 at 790326-0328 No noncompliance noted Major areas inspected const activities, previously identified items, 10CFR20 55(e) items, 10CFR21 posting & QA BURDETTE, T E Region 2, Atlanta, Office of the Director HERDTAR Region 2, Atlanta, Pasactor Construction & Engineering Support Branch 79/04/06 5pp
- 7905030368 Forwards IE Bulletin 79-07. "Seisnic Stress Analysis of Bafety-Related Piping " Licensee action required D'REILLY.J P Region 2. Atlanta. Office of the Director 79/04/14 3pp
- 7905040233 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident "O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 3pp
- 7905110368 Forwards IE Bulletin 79-08, "Events Relevant to Bailing Water Power Reactors Identified During TMI Incident "O'REILLY, UP Region 2, Atlanta, Office of the Director 79/04/14 ip
- 7905010341 Forwards IE Info Notice 79-10. "Nonconforming Pipe Support Struts " O'REILLY.J P Region 2. Atlanta. Office of the Director 79/04/18 ip
- 7905030172 Forwards IE Bullstin 79-09, "Failures of GE Type AX-2 Circuit Breaker in Befety-Related Bys " Licensee action required O'REILLY, J P Region 2, Atlanta, Office of the Director 79704/17 2pp
- 7905020479 Forwards IE Bulletin 79-06A, Revision i, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident" O'REILLY, JP Region 2, Atlanta, Office of the Director 79704/18 2pp
- 7905300253 Submits supplemental response to IE Bulletin 77-07 Original response submitted 78120 Provides add1 info received from manufacturer & describes plans in area of electrical penetrations GILLELAND, J E Tennessee Valley Authority 79/04/27 5pe
- R Periodic operating reports & related correspondence
- 7903150286 Forwards "Socioeconomic Monitoring & Mitigation Rept"
  Apr 1979 Future repts will be prepared semiannually
  QILLELAND, J. E. Tennessee Valley Authority 79/03/09 ip
- ---7905150294 "Socioeconomic Monitoring & Mitigation Rept" Apr 1979
  \*\* Tennessee Valley Authority 79/04/30 46pp
- S. Reportable occurrences, LERs & related correspondence
- 7905140478 Forwards final rept of reportable condition re BMR/A MPCS ideal control panels.(NRC GE-79-01) GILLELAND, J E Tennessee Valley Authority 79/04/05 19
- DOCKET STN-50-519 HARTSVILLE NUCLEAR PLANT, UNIT 2

  A. Application/construction stage documents & correspondence
- 7905080541 Discusses util position on lask testing pressure & temp requirements of ACI Skds 318 & 347 for piping to be smbodded in concrete Revisions to PSAR re embedded piping will be implemented immediately GILLELAND, J. R. Tennessee Valley Authority 79/05/03 389

πŰ

- F Security, medical, emergency & fire protection plans
- 7905300462 Forwards add1 response to 780926 meeting minutes re STRIDE fire hazards analysis includes proposed design changes to fire protection sys Requests early meeting to discuss responses

  OILLELAND, J. E. Tennesses Valley Authority 79/05/20 9pp
- Q Adjudicatory correspondence
- 7905240874 Requests Adoption of de minimus theory of Perkins ABL9 Gertificate of Svc encl BANGER.H B . WALLACE.L E . GUTTERMAN.A H Tennessee Valley Authority. 79704/06 11pp
- 7905110418 Response to ALAB-509 re radon emissions & de minimus theory from Perkins record Certificate of Byc encl.
  8CINTG.J F. Hearings Division 79/04/11 45pp
- 7905140519 Response to 790404 brief of Philadelphia Electric Co, PSE&O & Aklantic City (NJ) Electric Co re de minimus theory Certificate of Svc encl KEPFORD.c R Citizens for Safe Environment 79/04/11 Spp
- 7905140332 Natifies of consolidation of five intervenor groups of radon emissions issue Parties have until 790525 in which to file for summary disposition
  DUFLO.H E. Atomic Safety and Licensing Appeal Panel. 79/04/25
- J Insurance & indemnity information
- 7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,185,187,189,197,192,173,194,175,197,197,198,200,201,204,206,207,208,210,212,214,215,5 others QUATTROCHHI, J American Nuclear Insurers 79/05/01 1p
- 7905070382 Confirms increase in liability limit to \$36,000,000 for policies MF-22,26,29,38,39,44,46,47,49,50,51,52,53,34,55,56,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,78,80,86,87,88,90,71,92,93,94,95 & 96
  ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79,05/01,10
- @ Inspection reports, IE Bulletins & correspondence
- 7905010211 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping" O'REILLY, JP Region 2, Atlanta, Office of the Director 79/03/23 2pp
- 7905150072 Forwards IE Insp Repts 50-518/79-04,50-519/79-06, 50-520/79-06 & 50-521/79-06 on 790224-28 No noncompliance noted. MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 79/03/23 2pp
- --7903130081 IE Inep Repts 50-518/79-06, 30-519/79-06, 50-520/79-06 & 50-521/79-06 on 790226-28, No nencompliance noted. Major areas implemented by Const Engineering Manual BURDETTE. T E Region 2, Atlanta, Deactor Construction & Engineering Support Branch 79/03/22. 4pp
- 7905230422 Forwards IE Insp Repts 50-518/79-07, 50-519/79-07, 50-520/79-07 & 50-521/79-07 on 790307-09 No noncompliance noted.

  MURPHY.C. E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/02 2pp
- --7905250431 IE lnsp Repts 50-518/79-07, 50-519/79-07, 50-520/79-07 & 50-521/79-07 on 790307-09 No noncompilance noted Major areas inspected: concrete foundation of spray pond areas, safety-related steel structures. & OA audits & schedule SMAN.W B. Region 2, Atlanta, Office of the Director, BRYANT.J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/04/02 App
- 7905240498 Forwards IE Insp Repts 50-518/79-08, 50-519/79-08, 50-520/79-08 & 50-521/79-08 on 790324-0328, No noncompliance noted.

  MURPHY, C. E. Region 2, Atlanta, Office of the Director. 79/04/06 20s

- --7905240507 IE Insp Repts 50-518/79-08,50-519/79-08,30-520/79-08 \$
  50-521/79-08 on 790326-0328 No noncompliance meted Hajor areas inspected const activities, praviously identified items, 10CFR30 55(e) items, 10CFR21 pasting & GA BURDETTE. T E Region 2, Atlanta, Diffice of the Director HERDIA R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch, 79/04/04 5pp
- 7905030368 Forwards IE Bulletin 79-07. "Seismic Stress Analysis of Bafety-Related Piping " Licenses action required O'REILLY, J P Region 2, Atlanta, Office of the Director 79704/14. 3pp
- 7905040233 Forwards IE Bulletin 79-06B. "Review of Operational Errs<sup>f1 &</sup>
  Bus Misslignments Identified During TMI Incident "
  O'REILLYJ P Region 2, Atlanta, Office of the Director
  79704/14 Spp
- 7905110365 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident " 6'REILLY.J P Region 2, Atlanta, Office of the Director, 79/04/14 ip
- 7903010341 Forwards IE Info Notice 79-10. "Nonconforming Pipe Support Strute"

  O'REILLY, J P Region 2, Atlanta, Office of the Director,
- 7905030172 Forwards. IE Bullstin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys " Licenses action required O'REILLY. J P Region 2, Atlanta, Office of the Director, 79/04/17 2sp
- 7905020479 Forwards IE Bulletin 79-06A, Revision 1. "Revisw of Operational Errors & Sys Misalignments Identified During THI Incident "O'REILLY, JP. Region 2, Atlanta, Office of the Director 79/04/18 200
- 7905300253 Bubmits supplemental response to IE Bulletin 77-07 Original response submitted 78120. Provides add1 info received from manufacturer & describes plans in area of electrical penetrations OILLELAND.JE Tennessee Valley Authority 79/04/27 Spp
- R. Periodic operating reports & related correspondence
- 7905150286 Forwards "Socioeconomic Monitoring & Mitigation Rest" Apr 1979 Future repts will be prepared semiannually OILLELAND, J E Tennessee Valley Authority 79/05/09 ip
- ---7905150294 "Sociaeconomic Monitoring & Mitigation Rept" Apr 1979. \* Tennessee Valley Authority 79/04/30, 46pp
- 8 Reportable occurrences, LERs & related correspondence
- 7905140478 Forwards final rept of reportable condition re BHR/6 IPC8 local control panels. (NRC GE-79-01)
  GILLELAND: J E Tennessee Valley Authority 79/04/05. 1p
- --7905140482 Reportable condition on 790306 GE determined that defect existed in HPCS panel H22-P028 Caused by installation of nonqualified type relay Procedures revised & GA program modified

  \* Tennessee Valley Authority. 79/04/05 2pp
- DOCKET STN-50-520 HARTSVILLE NUCLEAR PLANT, UNIT 3

  A. Application/construction stage documents & correspondence
- 7705080541 Discusses util position on leak testing pressure & teap requirements of ACI Stds 318 & 349 for piping to be embedded in concrete Revisions to PBAR re embedded piping will be implemented immediately, OILLELAND, J. E. Tennessee Valley Authority, 7705/03 3pp

# F Security, medical, emergency & fire protection plans

7705300462 Forwards add1 response to 780926 meeting minutes re STRIDE fire hetards analysis Includes proposed design changes to fire protection sys Requests early meeting to discuss responses
GillELAND. J E Tennessee Valley Authority 79/05/20 7pp

#### O Adjudicatory correspondence

7905240874 Requests adoption of de minimus theory of Perkins ABLB Certificate of Svc encl SANGER, H S., HALLACE, L E , OUTTERMAN, A H Tennessee Valley Authority 79/04/06 lipp

7905110418 Response to ALAB-509 re radon emissions & de minimus theory from Perkins record Certificate of Svc encl BCINTO.JF Hearings Division 79/04/11 45pp

7905140519 Response to 790404 brief of Philadelphia Electric Co.PSEtO & Atlantic City (NJ) Electric Co re de minimus theory Centificate of Svc encl KEPFORD.C R Citizens for Safe Environment 79/04/11 Bpp

7905140332 Notifies of consolidation of five intervenor groups re radon emissions issue Parties have until 790525 in which to file for summary disposition

DUFLO.H E. Atomic Bafety and Licensing Appeal Panel 79/04/25 (3

# J. Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1.25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,185,186,187,188,189,192,193,194,175,197,198,200,201,204,206,207,208,210,212,214,215,&others QUATTROCKHI, J American Nuclear Insurers 79/05/01 1p

7905070582 Confirms increase in liability limit to \$36.000,000 for policies MF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,56,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,91,92,93,94,95 & 96 RDBERTS,D M Mutual Atomic Energy Liability Underwriters. 79/05/01.

# G Inspection reports, IE Bulletins & correspondence

7705010211 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
O'REILLY, J P. Region 2, Atlanta, Office of the Director 79/03/23, 2pp

7905150072 Forwards IE Insp Repts 50-518/79-06, 50-519/79-06, 50-520/79-06 & 50-521/79-06 on 790226-28 No noncompliance noted MRPHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/23, 2pp

--7903130081 IE Insp Repts 50-518/79-06, 50-519/79-06, 50-520/79-06 & 50-521/79-06 on 790226-28 No noncompliance noted Major areas inspected tonet activities. IE circulars & GA program as implemented by Const Engineering Hanual BURDETTE. Region 2, Atlanta, Office of the Director. HERDTA.R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/22 App.

7905250422 Forwards IE Insp Repts 50-518/79-07.50-519/79-07, 50-520/79-07 & 50-521/79-07 on 790307-09. No noncompliance nated MURPHY, C. E. Region 2. Atlanta, Reactor Construction & Engineering Bupport Branch 77/04/02. 2pp

~-7905250431 IE Insp Repts 50-518/79-07,50-519/79-07,50-520/79-07 to 790307-09, No moncompliance noted, Major areas inspected, concrete foundation of spray pond areas, safety-related steel structures, & GA audits & schedule. BHAN, W B. Region 2, Atlanta. Office of the Director. BRYANT, J, C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/02 6pp

7903240498 Forwards IE Insp Repts 30-518/79-08, 50-519/79-08, 50-520/79-08 & 50-521/79-08 on 790326-0328 No noncompliance noted.

MMRPHY, C. E. Region 2, Atlanta, Office of the Director 79/04/06, 50-521

--7905240507 IE Imap Repts 50-518/79-08.50-519/79-08.50-520/79-08 & 50-521/79-08 on 790326-0328 No noncompliance noted Major areas inspected conet activities, previously identified items.10CFR30.55(s) items.10CFR31 posting & QA BURDETTE.T E Region 2. Atlanta. GP#fice of the Director HERDT.A R Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 79/04/06 5pp

7908030368 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping " Licensee action required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 79/04/14 | 3pp

7905040233 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Missing ments Identified During THI Incident " D'REILLY, J P Region 2, Atlanta, Office of the Director. 79/04/14 3pp

7705110365 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Mater Power Reactors Identified During TMI Incident " O'REILLY, J P Region 2, Atlanta, Office of the Director. 77/04/14 1p

7905010341 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Strute "
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/18 1p

7905030172 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required O'REILLY,J.P Region 2. Atlanta, Office of the Director 79/04/17 2pp

7905020479 Forwards IE Bulletin 79-06A.Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"

O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/18 2pp

7905300253 Bubmits supplemental response to IE Bulletin 77-07. Original response submitted 78120 Provides add1 info received from manufacturer & describes plans in area of electrical penetrations
OILLELAND, J E Tennesses Valley Authority 79/04/27 5pp.

#### R. Periodic operating reports & related correspondence

7905150286 Forwards "Reciseconomic Monitoring & Mitigation Rept" Apr 1979, Future repts will be prepared semiannually GILLELAND, J.E. Tennessee Valley Authority 79/05/09, ip.

---7905180294 "Recioeconomic Monitoring & Mitigation Rapt" Apr 1979 \* Tennesses Valley Authority, 79/04/30 46pp.

8. Reportable occurrences, LERs & related correspondence

7905140478 Forwards final rept of reportable condition re BWR/6 HPC8 local control panels (NRC GE-79-01) OILLELAND, J E Tennesses Valley Authority, 79/04/05, 1p.

--7905140482 Reportable condition on 790306. GE determined that defect existed in HPCS penel H22-P028. Caused by installation of nonqualified type relay Procedures revised & GA program madified \* Tennessee Valley Authority. 79/04/05. 2pp

QCCKET STN-50-521 HARTSVILLE NUCLEAR PLANT, UNIT 4

A. Application/construction stage documents & correspondence

79050B0341 Discusses util position on leak testing, pressure & temp requirements of ACI Stds 318 & 349 for piping to be embedded in concrete. Revisions to PBAR re embedded piping will be implemented immediately.

OILLELAND, JE Tennessee Valley Authority 79/05/03. 3pp.

i)

#### F Security, medical, emergency & fire protection plans

- 7905300462 Forwards add1 response to 780926 meeting minutes re STRIDE fire hazards analysis Includes proposed dusign changes to fire protection sys Requests early meeting to discuss responses
  OILLELAND, J E Tennessee Valley Authority 79/05/20 9pp
- O Adjudicatory correspondence
- 7905240874 Requests adoption of de minimus theory of Pertins ASLS. Certificate of Svc encl. SANGER.H.S Tennessee Vallay Authority. 79/04/06 11pp
- 7905:104:8 Response to ALAB-509 re radon emissions & de minimus theory from Perkins record Certificate of Syc encl BCINTG, J. F. Hearings Division 79/04/11 45pp
- 7905140519 Response to 790404 brief of Philadelphia Electric Co.PSE&O & Atlantic City (NJ) Electric Co re de minimus theory Certificate of Syc encl.

  KEPFORD.C R Citizene for Bafe Environment 79/04/11 Spp.
- 7905140332 Notifies of consolidation of five intervenor groups re radon emissions issue Parties have until 790525 in which to file for summary disposition DUFLO, M E Atomic Safety and Licensing Appeal Panel 79/04/25 13pp.
- J Insurance & indemnity information
- 7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,63,100,111,140,146,151,161,164,170,173,174,178,179,160,182,185,186,187,188,187,192,193,194,198,197,198,200,201,204,205,207,208,210,212,214,215,& athers QUATTROCHHI,J American Nuclear Insurers 79/05/01 lp
- 7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22,26,29,38,39,44,46,47,49,50,51,52,63,34,55,56,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,60,86,87,86,90,91,92,93,94,95 & 96.
  ROBERTS,D M Mutual Atomic Energy Liability Underwriters 79/05/01 ip.
- G. Inspection reports. IE Bulletins & correspondence
- 7905010211 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping" O'REILLY, JP Region 2, Atlanta, Office of the Director 79/03/23. 2pp.
- 7403130072 Forwards IE Insp Repts 50-519/79-04,50-519/79-04,
  50-520/79-06 & 50-521/79-06 on 790226-28 No honocompliance noted

  MRPHY, C. E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/23, 2pp.
- --- 7905150081 IE Insp Repts 50-318/77-04.50-519/79-04.50-520/79-04 & 50-521/79-05 on 790225-28 No noncompliance noted Major areas inspected, const ectivities, IE circulars & GA program as implemented by Const Engineering Manual.

  BURDETTE.T.E Region 2. Atlanta, Office of the Director. 79/03/22. App
- 7905250422 Forwards IE Insp Repts 50-518/79-07.50-519/79-07.
  50-520/79-07 & 50-251/79-07 on 790307-09 No noncompliance noted
  MURPHY: C E Region 2, Atlanta, Reactor Construction & Engineering Support Stanch. 79/04/02 2pp
- --7905250431 IE Insp Repts 50-518/79-07, 50-519/79-07, 50-520/79-07 & 50-521/79-07 on 790307-09. No noncompliance noted, Major areas inspected; concrete foundation of spray pond areas, safety-related steel structures, & GA audite & schedule. SMAN. W B Region 2, Atlanta, Office of the Director. 79/04/02, 6up
- 7905240498 Forwards IE Insp Repts 50-518/79-08.30-519/79-08.
  50-320/79-08 & 50-521/79-08 on 790326-0328.No noncompliance noted.

  MURPHY, C E Region 2: Atlanta, Office of the Director 79/04/06.
  2pp
- --7903240307 IE insp Repts 50-518/79-08,50-519/79-08,50-520/79-08 & 50-521/79-08 on 790322-0328. No noncompliance noted Major areas inspected constructions previously identified items. 10CFR50, 55(e) items. 10CFR21 posting & GA URDETTE.T E. Region 2. Atlanta. Office of the Director. 79/04/06. Spp

- 7905030368 rorwards IE Bulletin 79-07, "Seismic Stress Analysis of Bafety-Related Piping" Licensee action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director, 79/04/14. 3pp
- 7908040233 Forwards IE Bulletin 79-06B, "Raview of Operational Errors & Bys Misalignments Identified During TMI Incident " O'REILLY, JP Region 2, Atlanta, Office of the Director 79/04/14 3pp
- 7903110300 rorwards IE Builetin 79-08, "Events Relevant to Boiling Hater Power Reactors Identified During TMI Incident " O'REILLY.JP Region 2, Atlanta, Office of the Director 79704/14 1p.
- 7905010341 Forwards IE Info Notice 79-10. "Nonconforming Pipe Support Btruts = O'REILLY.J.P Region 2. Atlanta, Office of the Director 79/04/18 ip
- 7905030172 forwards IE Bulletin 79-09, "Failures of QE Type AX-2 Circuit Breaker in Safety-Related Sys " Licensee action required O'REILLY.J.P Region 2, Atlanta, Office of the Director 79/04/17 2pp
- 7905020479 Forwards IE Bulletin 79-06A.Revision 1, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident "
  O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/18. 2pp
- 7905300253 Submits supplemental response to IE Bulletin 77-07 Original response submitted 780120 Provides add1 info received from manufacturer & describes plans in area of electrical penetrations
  OILLELAND.J E Tennesses Valley Authority 79/04/27 Spp
- R Periodic operating reports & related correspondence
- 7905150284 Forwards "Socioeconomic Monitoring & Mitigation Rept" Åpr 1979, Future repts will be prepared semiannually OILLELAND, J E Tennessee Valley Authority 79/05/09 19
- ---7905150294 "Socioeconomic Monitoring & Mitigation Rept" Apr 1979 \* Tennesses Valley Authority 79/04/30 45pp.
- B. Reportable occurrences: LERs & related correspondence
- 7909140478 Forwards final rept of reportable condition re BHR/6 IPC9 local control panels (NRC GE-79-01) GILLELAND, J E Tennesses Valley Authority 79/04/05, 19
- ---7905140482 Reportable condition on 790306 OE determined that defect existed in HPCB panel H22-P028 Caused by installation of nonqualified type relay Procedures revised & GA program modified \* Tennessee Valley Authority. 79/04/05. 2pp
- POCKET STN-50-522 SKAOIT NUCLEAR POWER PROJECT: UNIT 1

  A Application/construction stage documents & correspondence
- 7905090211 Forwards summary of 790227 meeting of Skapit River Indian's representatives w/House Committee on Interior & Insular Affairs.

  LEECH.P H Environmental Projects Branch 2 79/04/10 1p
- ---7905090264 Summary of 790227 meeting w/representatives of Indian trits:
  in Washington,DC re study,funded by Bureau of Indian
  Affairs:of potential impact of facility on local hydrology,
  socioeconomic conditions & Indian fisheries.
  KAMMERER.G. Office of Congressional Affairs 79/03/05 2pp
- 7903230826 Discusses delays in issuance of CP in response to 790212 telegram to President Carter
  BTOLZ, J F Light Water Reactors Branch 1, 79/04/16, 3pp
- 7905240857 Approves request to withhold from public disclosure 790223 & 790416 ltrs re aeromagnetic data.
  STOLZ.J F. Light Water Reactors Branch 1, 79/04/30, 4pp
- 7905090090 Forwards "Environ Assessment, DDA Plant Assessment," in response to NRC 780605 request Recommends mods re mpt requirements in applicant's mitigation plan, Encl available in Central Files.

  BERGLAND, B Agriculture, Dept of, 79/05/02, 2pp.

- 7905160347 Forwards "Rept of Geological Investigations in 1978-1979,"
  Vols 2 & 3. Discusses deferred & supplemental sections,
  HECCA, J E Puget Bound Power & Light Co. 79/05/10 7pp
- --7905160356 "Rept of Gaological Investigations in 1978-1979" Vols 2 & 3 Four oversized drawings encl \* Puget Sound Power & Light Co 79/05/10. 28ipp
- 7905310393 Responds to 780630 request for add1 geological info Forwards add1 supportive matl to "Rept of Oeologic Investigations in 1978-1979" Extensive geologic investigations confirm site sultability, Rept encl
  MECCA, J E Puget Bound Power & Light Co 79/05/25 100pp

#### @ Adjudicatory correspondence

- 7905140159 Motion for leave to file interim statement of issues three days out of time.on 790312
  BUSCH.R W Evergreen Legal Bervices MEANS,D S. Heans, Donald S
  79/03/12.
- --7905140161 Intervenor Tribes interim statement of issues in response to 770208 order.
  BUBCH-R W Evergreen Legal Services, MEANS, D S. Means, Donald S 79/03/12 23pp.
- 77002230818 Forelaws on Board/Coalition for Safe Power's statement of issues, submitted per 770208 order Follows applicant 770222 ravised statement, Discusses environ issues. Certificate of Svc encl STACHOM, E.O. Coalition for Bafe Power 77/03/16 4pp.
- 7705010115 Forwards request for Board notification re nonsafety-grade equipment to mitigate transients
  8GINIO.JF Hearings Division 77/04/02 31pp
- --7703010106 Board notification staff assessment re nonsafety-grade equipment to mitigate transients VABHALLO, D B Assistant Director for Light Water Reactors 77/03/27 2pp.
- --7905010198 Board notification.recent issue on nonsafety-grade equipment to mitigate transients More info is required TEDEBCO.R.L. Assistant Director for Reactor Bafety 79/03/16 das.
- 7903230128 Forwards policy statement re NUREO/CR-0400, reactor safety study & survey of uses made of HABH-1400 H/o encl.
  BLACK: R L. Branch 1. 79/04/04 1p.
- 7905140030 Order for agenda of conference scheduled for 790424-26.
  DEALE.V.B Atomic Safety and Licensing Board Panel. 79/04/10 7pp
- 7905230180 Advises that recommanded order of OR Energy Facility Siting Council hearing examiner will be issued in Aug 1979 rather than Apr 1979.

  BANDVIK.R. M Oregon, State of 79/04/17. ip

#### 1. Financial information

- 7905250459 Forwards addl financial info.as requested by NRC 790405 ltr.
  Info includes matl re testimony & exhibits in most recent
  rate relief actions: BEC prospectus & annual financial repts.
  HECCA: J. E. Puget Bound Power & Light Co 79/05/17 350pp
- --7905290465 "Annual Financial Rept 1978." # Puget Sound Power & Light Co 78/12/91. 43pp.
- --7905280472 "Annual Financial Rept 1978" # Pacific Power Co. 78/12/31. 32pp
- 7905310372 Responds to 790405 ltr.Forwards financial info.form BEC 10-K, prospectus, testimony, exhibits & "Portland GE Pro Forma Bources of Funds for Sys Wide Const Expenditures & Capital Structure." Encl in Central Files, 19905/25, 400pp. HEGCA.J. E Puget Bound Power & Light Co. 79/05/25, 400pp.
- T. Hearing transcripts on non-antitrust matters
- 7905140016 Transcript of 790424 meeting in Seattle, WA.Pp 11,776-11,953.
  DEALE, V.B., LINENBERGER, O., HODPER, F.F. Atomic Safety and Licensing Board Panel. 79/04/24. 178pp.

- DOCKET STN-50-523 SKAOIT NUCLEAR POWER PROJECT. UNIT 2
  A. Application/construction stage documents & correspondence
- 79050902i1 Forwards summary of 790227 asseting of Stagit River Indian's representatives w/House Committee on Interior & Insular Affairs
  LEECH.P H Environmental Projects Branch 2 79/04/10 ip
- --7905090264 Summary of 790227 meeting w/representatives of Indian tribes in Washington,DC re study,funded by Bureau of Indian Affairs:of potential impact of facility on local hydrology, socioeconomic conditions & Indian fisheries KAMMERER.C Office of Congressional Affairs 79/03/05 2pp
- 7705230826 Discusses delays in issuance of CP in response to 770212 telegram to President Carter
  8TOLZ,J F Light Water Reactors Branch 1 79/04/16 3pp
- 7905240857 Approves request to withhold from public disclosure 790223 & 790416 ltrs re aeromagnetic data STDLZ.J F Light Water Reactors Branch 1 79/04/30 4pp
- 7903090090 Forwards "Environ Assessment, DOA Plant Assessment," in response to NRC 780605 request Recommends mods re mgt requirements in applicant's mitigation plan Encl available in Central Files
  BERGLAND, B Agriculture, Dept of 79/05/02 2pp
- 7905160347 Forwards "Rept of Geological Investigations in 1978-1979," Vols 2 & 3 Discusses deferred & supplemental sections MECCA, J E Puget Sound Power & Light Co 79/05/10 7pp
- --7905160356 "Rept of Qeological Investigations in 1978-1979" Vols 2 & 3 Four oversized drawings and \* Puget Sound Power & Light Co 79/05/10 281pp
- 7905310383 Responds to 780630 request for addit geological info Forwards addit supportive math to "Rept of Geologic Investigations in 1978-1979." Extensive geologic investigations confirm sits suitability Rept encl
  MECCA.J E Puget Bound Power & Light Co 79/05/25 100pp

# G Adjudicatory correspondence

- 7905140159 Motion for leave to file interim statement of issues three days out of time.on 790312 BUSCH.R W Evergreen Legal Services MEANS.D S Heans, Donald S 79/03/12 2pp
- ---7905140161 Intervenor Tribes interim statement of issues in response to 790208 order.
  BUSCH.R H Evergreen Legal Services MEANS.D B Means. Donald S 79703/12. 23pp
- 7903230B1B Forelaws on Board/Coalition for Safe Power's statement of issues, submitted per 79020B order Follows applicant 790202 revised statement Discusses environ issues Certificate of Syc enci.
  BTACHOM.E. & Coalition for Safe Power 79/03/16 4pp
- 7905010113 Forwards request for Board notification re nonsafety-grade equipment to mitigate transients.

  8CINTO.J.F Hearings Division 79/04/02 3ipp

--790501 equi VASI 79/0

--79050

7905250 gtudy BLACK

7905140 DEALE

#### I. Financial information

- 7903250439 Forwards addl financial info as requested by NRC 790405 ltr Info includes matl re testimony & exhibits in most recent rate relief actions. SEC prospectus & annual financial repts MECCA. J E Puget Bound Power & Light Co 79/05/17 350pp
- ---7905250465 "Annual Financial Rept 1978 "
  \* Pugat Bound Power & Light Co 78/12/31 43pp
- --7905250472 "Annual Financial Rept 1978" \* Pacific Power Co 78/12/31 32pp
- 7905310372 Responds to 790405 ltr Forwards financial info form SEC 10-K.prospectus, testimony, exhibits & "Portland GE Pro Forma Sources of Funds for Sys Mide Const Expenditures & Capital Structure " Encl in Central Files MECCA, J E Puget Sound Power & Light Co 79/05/25 400pp
- T. Hearing transcripts on non-antitrust matters
- 7905140016 Transcript of 790424 meeting in Seattle, WA Pp 11, 776-11, 953 DEALE: V B . LINENBERGER. C . HOOPER, F F Atomic Safety and Licensing Board Panel. 79/04/24 178pp.

# DOCKET 50-524 BARTON, UNIT 1 O Adjudicatory correspondence

- 7905140280 Describes NRC notification to ASLAB during past year renuclear power reactors for info of Board & parties in proceeding ORAY.J R Branch 1 79/04/12 3pp
- --7905i40287 Discusses issue of neutron exposure at commercial power reactors No problem exists Questions data on which concerns were based EISEMHUT,D O Division of Operating Reactors VOLLMER.R H. Assistant Director for Site Analysis 79/03/05 2pp
- --7905140292 Follows up 790306 memo & 790301 & 08 meetings re QE's BHR-NESS equipment adequacy evaluation. Describes action plan which parallels program & proposed decision process plan MATTSON.R J Division of Bystems Bafety 78/03/16 App
- ---7905140299 Summary of 780301 meeting w/QE re QE's BHR-N888 equipment adequacy evaluation for Mark II & III plants. W/supporting documentation MATTSON.R.J Division of Systems Safety. 78/03/06 21pp

# DOCKET 50-325 BARTON, UNIT 2 O. Adjudicatory correspondence

1.0

14.

- 7905140280 Describes NRC notification to ASLAB during past year renuclear power reactors, for info of Board & parties in proceeding ORAY, J R Branch i 79/04/12 3pp
- --7905140287 Discusses issue of heutron exposure at commercial power reactors No problem exists. Questions data on which concerns were based EISENHUT.D Q Division of Operating Reactors. VOLLMER, R, H Assistant Director for Site Analysis, 79/03/05. 2pp
- --7905140272 Follows up 790306 memo & 790301 & 08 meetings re GE's BMR-MSBS equipment adequacy evaluation Describes action plan which parallels program & proposed decision process plan. MATTBON:RJ Division of Systems Safety. 78/03/16. 4pp.
- ---7905140299 Summary of 780301 meeting w/GE re GE's BWR-N888 squipment adequacy evaluation for Hark II & III plants W/supporting documentation.

  MATTEON.R.J. Division of Systems Safety. 78/03/06 2ipp

# DOCKET STN-50-528 PALO VERDE NUCLEAR STATION, UNIT 1 A Application/construction stage documents & correspondence

7905220386 Requests authorization to use encl ASME code cases in plant const. VAN BRUNT, E. E. Arizona Public Service Co. 79/05/07. 2pp.

- --7905220392 Ack receipt of 741004 ltr requesting approval of ASME Code
  1481 for use in design of hydrogen recombiner for post-LOCA
  use. Approval is granted
  BCHRGEDER.F Atomic Energy Commission, Directorate of Licensing
  (Pre-1975) 74/10/22 lp.
- ---7905220397 Requests authorization to use ABME Code Case 1592 in dealqa of hydrogen recombiners for post-LOCA use N/list of LMR projects incorporating subj criteria GTONE: L R Rockwell International Corp 78/04/14 2pp.

# G Inspection reports, IE Bulletins & correspondence

- 7905150609 Forwards IE Insp Repts 50-528/78-09 & 50-529/78-07 on 761218-21 No noncompliance noted.

  VAN BRUNT, E Region 5, Ban Francisco, Reactor Construction & Engineering Support Branch 79/03/16 2pp.
- --7905150620 IE Insp Repts 50-528/78-09 & 50-529/78-07 on 781218-21 Mononcompliance noted Major areas inspected containment structural concrete containment post tensioning sys, reactor vessel final alignment & electrical cable & components.

  HAVNES,R C Region 5, San Francisco. Office of the Director ECKHARDT, J H , NARBUT,P P Region 5, San Francisco. Reacter Construction & Engineering Support Branch 79/03/16 11pp.
- 7905010283 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping " ENDELKEN.R H Region 4, Dallas, Office of the Director 79/03/23 ip
- 7905040076 Forwards IE Info Notice 79-07, "Rupture of Radwaste Ten): "
  ENGELKEN.R H Region S. Gan Francisco. Office of the Director
  79/03/26 ip
- 7903290056 Responds to IE Bullstin 79-03 Forwards 781117 ltr VANBRUNT, E E Arizona Public Service Co. 79/04/03. ip
- 7905010016 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident " ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/14. 1p
- 7905040307 Forwards IE Bulletin 79-04B. "Review of Operational Errors & Bus Hisalignments Identified During TMI Incident " ENOELKEN.R.H. Region 5. Ban Francisco. Office of the Director 79/04/14. ip
- 7905040614 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Hater Power Reactors Identified During TMI Incident." ENGELKEN, R H Region 3, San Francisco, Office of the Director. 79/04/14. 1p
- 7905070098 Forwards IE Builetin 79-07, "Beismic Stress Analysis of Safatu-Related Piping " Licensee action required. ENGELKEN, R.H. Region 5, San Francisco, Office of the Director, 79/04/14 1p
- 7905030286 Forwards IE Bulistin 79-09, "Failures of GE Type AX-2 Circuit Breaker in Bafety-Related Bys." Licenses action required ENOELKEN, R H. Region 5, San Francisco. Office of the Director 79/04/17. 1e
- 7905080365 Forwards IE Bulletin 79-058, "Nuclear Incident at THI-Suppl" ENGELKEN,R H Region S. Ban Francisco, Office of the Director. 79/04/21. 1p.
- 7903270072 Response to IE Bulletins 78-12 & 78-12A will be submitted by 790913. Awaiting generic rept from C-E. VANDRUNT, E. E. Arizona Public Bervice Co., 79/05/25. 1p.

## B Reportable occurrences, LERs & related correspondence

- 7905150057 Forwards PNO-79-67L. ENGELKEN. R. H Region 5, San Francisco, Office of the Director 79/04/06 10
- 7905150165 Forwards PNO-79-67R ENGELKEN:R H Region 5, San Francisco. Office of the Director. 79/04/31: 1p.
- 7903040121 Forwards PNO-79-678.
  ENGELMEN,R H Region 5, Ban Francisco, Office of the Director 79/04/12. ip

- 7905180136 Forwards PNO-79-67T ENGELMEN.R H. Region S. San Francisco. Office of the Director 79/04/13 1p
- 7905030030 Forwards PND-79-67U ENGELKEN R H Region 5, San Francisco, Office of the Director 79704/14 1P.
- 790303055 Forwards PNO-79-67AA ENGLIKENIR H Region 5, Ean Francisco, Office of the Director 79/04/20 1p
- 7905010420 Forwards PNO-79-67AB.
  ENGELKEN.R H Region 5, San Francisco, Office of the Director 79/04/21. 1p
- 7905010442 Forwards PNO-79-67AC & AD. ENGELKEN.R H Region 5, San Francisco, Office of the Director 79/04/23 1p
- 7905010456 Forwards PNO-79-67AE ENGELMEN.R H Region S. San Francisco. Office of the Director. 79/04/24 1p
- 7905090038 Forwards PNO-79-67AF ENGELMEN.R H Region 5, San Francisco, Office of the Director 79/04/25, 1p
- 7905090033 Forwards PNO-79-67A0 EMBELKEN,R N. Region 5. Ban Francisco, Office of the Director 79/04/26 10
- 7903090115 Forwards PNO-79-67AH ENGLEMEN.R H Region 5, San Francisco, Office of the Director. 79/04/27 ip
- 7905070028 Forwards PNO-79-67AI.AJ & AK per NRG 790401 ltr transmitting IR Bulletin 79-05 ENGELKEN.R H Region 5. San Francisco. Office of the Director. 79/04/30. is
- 7905040355 Forwards PNO-79-67AL per NRG 790401 ltr transmitting IE Bulietin 79-05 ENGELKEN.R H Region 5, San Francisco, Office of the Director, 79/05/01 1p.
- ~~7705040358 PNO~79~67AL.summary of info re nuclear incident as of 790501. Describes plant & environ status # Office of Inspection & Enforcement 79/05/01 3pp.
- 7705310059 Forwards PNQ-79-67AM
  ENGELKEN.R.H Region 5, San Francisco, Office of the Director.
  77/05/Q7. 1p
- DOCKET STN-50-529 PALG VERDE NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 7905220386 Requests authorization to use and ASME code cases in plant const. VAN BRUNT, E.E. Arizona Public Service Go. 79/05/07 2pp
- --7905220392 Ack receipt of 741004 ltr requesting approval of ABME Code
  1481 for use in design of hydrogen recombiner for post-LOCA
  use.Approval is granted
  SCHROEDER.F. Atomic Energy Commission: Directorate of Licensing
  (Pre-1975), 74/10/22, ip
- ---7905220397 Requests authorization to use ASME Code Case 1592 in design of hydrogen recombiners for post-LOCA use W/list of LWR projects incorporating subjectionia Corp 78/04/14, 2pp,
- O Inspection reports, IE Bulletins & correspondence
- 7905150609 Forwards IE Insp Repts 50-528/78-09 & 50-529/78-07 on 781219-21, No noncompliance noted.

  VAN SRUNT.E. E. Region 5. San Francisco. Reactor Construction & Engineering Support Branch. 79/03/16 2pp.
- --7905150620 IE Insp Repts 50-528/78-09 & 50-529/78-07 on 781218-21. No moncompilance noted Major areas inspected containment structural concrete, containment post tensioning systreactor yessel final alignment & electrical cable & components HAYNES, R. C. Region 5, San Francisco, Office of the Director, ECKNARDI, J.H., NARBUT.P.P. Region 5, San Francisco Reactor Construction & Engineering Support Branch 79/03/16, 11pp.

- 7905010283 Forwards IE Info Notice 79-06, "Btress Analysis of Bafety-Related Piping"
  ENGELKEN, R H Region A, Dallas, Office of the Director 79/03/23
- 7905040076 Forwards IE Info Notice 79-07. "Rupture of Radwaste Tanks." ENGELKEN.R H Rugion 5. San Francisco, Office of the Director 79/03/26 ip
- 7905290056 Responds to IE Bulletin 79-03 Forwards 781117 ltr VANBRUNT, E E Aritona Public Service Co 79/04/03 ip
- 7905010016 Forwards IE Bulletin 79-06A. "Review of Operational Errors & Bys Misalignments Identified During TMI Incident." ENGLKEN,R H Region 5, San Francisco, Office of the Director.
- 7905040507 Forwards IE Bullstin 79~06B, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident " ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/04/14 1p
- 7903040614 Forwards IE Builetin 79~08. "Events Relevant to Boiling Mater Power Reactors Identified During TMI Incident " ENGELKEN,R H Region 5. San Francisco, Office of the Director 79/04/14 10
- 7905070098 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping " Licensee action required ENGELKEN, R H Region 5: San Francisco, Office of the Director 78/04/54 in
- 7905030286 Forwards IR Bulletin 79-09, "Failures of QE Type AK-2 Circuit Breaker in Bafety-Related Bys " Licensee action required ENGLKEN, R. H. Region 5, Ban Francisco, Office of the Director 79/04/17 in
- 7905080365 Forwards IE Builetin 79-05B. "Nuclear Incident at TMI-Bupol" RNGELKEN.R H Region 5. San Francisco. Office of the Director 79/04/21 1p
- 7905290072 Response to IE Bulletins 78-12 & 78-12A will be submitted by 790913. Awaiting generic rept from C-E VANBRUNT. E E Arixona Public Service Co. 79/03/25 Ip
- 8 Reportable occurrences: LERs & related correspondence
- 7905150057 Forwards PNO-79-67L ENGELKEN: R H Region 5, San Francisco, Office of the Director 79/04/06 15
- 7905150165 Forwards PNO-79-67R ENGELMEN:R H Region S, San Francisco. Office of the Director 79/04/11 1p
- 7903040121 Forwards PNO-79-678.
  EMBELKEN.R H Region 5. Ban Francisco. Office of the Director 79/04/12. 1p.
- 7905150136 Forwards PNO-79-67T.
  ENGELKEN,R.H Region 5, Ban Francisco, Office of the Director.
  79/04/13. 1p.
- 7905030050 Forwards PNQ-79-67U ENGELKEN,R H Region 5. Ban Francisco, Office of the Director 79/04/14 1P
- 7905020525 Forwards PNO-79-67AA.
  ENGELKEN,R H Region 5: San Francisco: Office of the Director.
  79/04/20 1p.
- 7903010420 Forwards PNO-79-67AB.
  ENGELKEN,R H. Region 5, San Francisco, Office of the Director, 79/04/21 1p.
- 7905010442 Forwards PNO-79-67AC & AD. ENGELKEN.R.H Region 5, San Prancisco, Office of the Director 79/04/23. ip
- 7903010456 Forwards PNO-79-67AE ENGELKEN.R.H Region 5, Ban Francisco, Office of the Director. 79/04/24, 1p.
- 7905090038 Forwards PNO-79-67AF
  ENGELKEN.R H Region 5. Ban Francisco. Office of the Director.
  79/04/25 1p.

- 7905090053 Forwards PNO-79-67AD ENGELKEN, R H Region 5. San Francisco, Office of the Director. 79/04/24 10
- 7905090113 Forwards PNO-79-678H ENGLEKEN, R. H Region 5, San Francisco, Office of the Director 79/04/27 19
- 7905070028 Forwards PNO-79-67AI.AJ & AK per NRC 790401 itr transmitting IE Bulletin 79-05 ENGELKEN, R H Region 5, San Francisco, Office of the Director
- 7905040355 Forwards PNO-79-67AL per NRC 790401 Itr transmitting IE Bulletin 79-05 ENGELKEN,R H Region 5, San Francisco, Office of the Director
- 7905310059 Forwards PNO-79-67AM ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/05/07 ip
- DOCKET STN-50-130 PALO VERDE NUCLEAR STATION, UNIT 3

  A Application/construction stage documents & correspondence
- 7903100029 Suggests NRC command & control ctr w/communications link that automatically receives data from operating reactors & shippers of SNM PODOLAK, E. M Radiological Health Standards Branch 79/04/17
- 7905220386 Requeste authorization to use encl ASME code cases in plant const VAN BRUNT, E E Arizona Public Service Co 79/05/07. 2pp
- --7905220392 Ack receipt of 741004 ltr requesting approval of ABME Gode 1481 for use in design of hydrogen recombiner for post-LOGA use Approval is granted. GCHRGEDER.F Atomic Energy Commission, Directorate of Licensing (Pre-1975) 74/10/22 ip
- --7903220397 Requests authorization to use ABKE Code Case 1392 in design of hydrogen recombiners for post-LDCA use, W/list of LWR projects incorporating subj criteria STONE, L. R. Rockwell International Corp. 78/04/14 2pp.
- G Inspection reports, IE Bulletins & correspondence
- 7905010283 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping." ENGELKEN, R. H. Region 4. Dallas, Office of the Director, 79/03/23, ip
  - 'wards IE Info Notice 79-07. "Rupture of Radwaste Tanks " | Region 5. San Francisco. Office of the Director
    - TE Bulletin 79-03 Forwards 781117 ltr. na Public Service Co. 79/04/03, ip.
      - tin 79-06A, "Review of Operational Errors & ed During TMI Incident"

        Ban Francisco, Office of the Director.
      - tin 79-06B, "Review of Operational Errors & ed During TMI Incident."

        San Francisco, Office of the Director.
      - tin 79-08, "Events Relevant to Boiling ified During TMI Incident,"
        San Francisco, Office of the Director.
      - tin 79-07. "Belamic Stress Analysis of censee action required Ban Francisco, Office of the Director
      - tin 79-09, "Failures of GE Type AK-2 Related Sys." Licensee action
      - San Francisco, Office of the Director.

- 7905080365 Forwards IE Bulletin 79-058, "Nuclear Incident at TMI-Suppl."
  ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/04/21 io
- 7905290072 Response to IE Bulletins 78-12 & 78-12A will be submitted by 790913. Awaiting generic rept from C-E VANBRUNT, E. E Arizona Public Bervice Co 79/05/25 tp
- S. Reportable occurrences. LERs & related correspondence
- 7905150037 Forwards PNO-79-67L ENGELKEN.R H Region 5, Ban Francisco, Office of the Director 79704706 ip
- 7905150165 Forwards PNO-79-67R ENGELKEN.R H Region 5, San Francisco, Office of the Director
- 7905040121 Forwards PNO-79-675 ENGELKEN.R H Region 5. San Francisco. Office of the Director 79/04/12 1p
- 7905150136 Forwards PNO-79-67T ENGELKEN.R H Region 5. Ban Francisco. Office of the Director 79/04/13 1p
- 7905030050 Forwards PND-79-67U ENGELKEN, R. H Region S, San Francisco, Office of the Director 79/04/14 1P
- 7903020323 Forwards PNO-79-67AA ENGELMEN, RH Region 5, San Francisco, Office of the Director 79/04/20, ip
- 7903010420 Forwards PNO-79-67AB ENOELMEN.R.H Region 5. San Francisco. Office of the Director 79/04/21 1p
- 7905010442 Forwards PNO-79-67AC & AD ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/04/23. ip.
- 7905010456 Forwards PNO-79-67AE ENGELKEN, R H Region 5. Ban Francisco. Office of the Director 79/04/24. ip.
- 790509003B Forwards PNO-79-67AF ENGELMEN.R.H Region 5. San Francisco, Office of the Director 79/04/25 ip
- 7905090053 Forwards PND-79-67AG ENGELKEN,R. H 79/04/26 1p
- 7905090115 Forwards PNO-79-67AH ENGLEKEN,R. H. Region 5, San Francisco, Office of the Director 79/04/27. ip
- 7905070025 Forwards PNO-79-67AI, AJ & AK per NRC 790401 1tr translitting IE Bulletin 79-05 ENDELKEN, R. H Region 5, Ban Francisco, Office of the Director 79/04/30 10
- 7903040395 Forwards PNO-79-67AL per NRC 790401 ltr transmitting IE BULISTIN 79-05.
  ENGELKEN,R.H Region 5. San Francisco. Office of the Director. 79/05/01. 1p.
- 7905310059 Forwards PNO-79-67AM ENDELKEN, R H. Region 5, San Francisco, Office of the Director 79/05/07. in
- POCKET 8TN-50-531 GESBAR-251
- J. Insurance & indemnity information
- 7903070582 Confirms increase in liability limit to \$36.000,000 for policies MF-22.26.29.38.39.44.46.47.49.50.51.52.53.54.55.56.57.58.60.61.64.66.67.68.69.70.71.72.74.76.77.78.79.80.86.87.88.90.91.92.93.94.95 % % ROBERTS.D.M. Mutual Atomic Energy Liability Underwriters 79/05/03 ip.

DOCKET STN-50-532 BOP SAR

A. Application/construction stage documents & correspondence

7905240676 Notifies that expiration data for Preliminary Design Approval 5 is extended to 810507 based on review of Amend 9 to application 86VD.R 8 Division of Project Management 79/05/03 2PP

DOCKET 50-537 Clinch River Breeder Reactor

AApplication/construction stage

7905020293 Forwards effidavit confirming distribution of PSAR Amend 49 to designated local public officials & EPA representatives COPELAND, R L Energy, Dept of, Clinch River Breeder Reactor Plant 79704/25 2pp

DOCKET 50-538 MEMPHIS STATE UNIV RESEARCH REACTOR

J Insurance & indemnity information

7903160232 Forwards Amend 2 to Indemnity Agreement E-59.per 10CFR140 changes.re liability insurance increase from #140 million to #160 million.effective 790501. Supporting documentation enti SALTZMAN.J Antitrust & Indemnity Group 79/05/01 5pp

O Inspection reports, IE Bulletins & correspondence

7905070133 Forwards IE Bulletins 79-05,79-05A & 79-06 re nuclear incident at TMI D'REILLYIJ,P Region 2. Atlanta. Office of the Director 79/04/13 1p

DOCKET STN-50-546 MARBLE HILL NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

7903090292 Responds to comments re application for const of pumphouse intake & discharge structure W/781016 ltr from Attorney General of KY to Corps of Engineers. Louisville re dredge & fill application of Public Svc Co of IN WHITLOCK, W N Army, Dept of, Corps of Engineers 78/11/06 7pp

--7905090294 Notifies of licensee's mitigation plan to recover archeological resources disturbed by const of intake & discharge structures W/IN Dept of Natural Resources itr discussing plan

BALLARD.R L Environmental Projects Branch 2 78/09/22, 2pp.

7905020445 Forwards NUREO-0831. "Investigation & Evaluation of Stress Corresion Cracking in Piping of LWR Plants" & notice of issuance & availability W/o encl VABSALLO, B Assistant Director for Light Water Reactors 79703/23 Spp.

7705020521 Responds to 770403 ltr re cubicle coolers w/improperly installed gaskets.Matter will be reviewed in future insp. FIORELLI, 0 Region 3, Chicago, Office of the Director, 79/04/17 to

7905100171 Notification of 790503 meeting w/util in Bethesda.MD to discuss Gaseload Forecast Panel's estimate for fuel load date & submittal date for FBAR.
VARGA.8.A Light Hater Reactors Branch 4, 79/04/23, 4pp.

7905150296 Notification that lack of expected prehistoric resources justifies termination of mitigation effort BALLARD,R.L.. Environmental Projects Branch 1. 79/04/30 2pp

7905080415 Discusses NRC intention to delay FBAR review until end of year. Delay is unacceptable, as based on average const schedule Util is better than average & unit is commited for 1992 operation FBAR will be filed in June 1979.
GDUGHLIN, J. Public Service Go. of Indiana, Inc. 79/05/04. 4pp.

Adjudicatory correspondence

7905150220 Motion to reopen safety hearings to discuss WASH-1400 % herbicide "2.4,5-7" DATTILO,T.M. Dattilo, T.M. 79/03/22, 2pp.

7905020448 Forwards NRC memo discussing problems experienced w/pips support base plate design Piping design analysis on case-by-case besits being reviewed under SRP Section 3, 9, 2, BRENNER.L. Branch 3 79/04/05, 2pp

7909020456 Forwards 780929 memo from Director of Ofc of Nuclear Reactor Regulation to Commissioners, discussing fire protection research test results conducted by UL.
BRENNER.L. Branch 3 79704705. 2pp.

7903160208 Forwards latest motion to reopen safety hearings by T Dattilo on behalf of Bave the Valley — Save Marble Hill Forwards revisions to draft motions attached to 790402 memo MURRAY, J. P. Rutemating & Enforcement Division 79/04/05 2pp.

--7905160212 Motion to suspend & revoke CP for proposed facility because of TMI incident DATFILO, T. M. Metford & Dattilo 79/04/04 2pp

7905110418 Response to ALAB-509 re radon emissions & de minimus theory from Parkins record Certificate of Svc encl.

8CINTO.J F Hearings Division 79/04/11. 45pp

7905i405i9 Response to 790404 brief of Philadelphia Electric Co.PSE&O & Atlantic City (NJ) Risctric Co re de minimus theory Certificate of Svc ancl KEFFORD: C R Citizens for Safe Environment 79/04/11 8pp

7905240791 Ack receipt of 790404 petition to institute const suspension proceedings Decision under consideration Forwards 790412 FR notice DENTON, H R Office of Nuclear Reactor Regulation 79/04/12 ip.

---7905240813 FR notice of request to reopen safety hearing BOYD, R S Office of Nuclear Reactor Regulation 79/04/12 2pp.

---7905240850 Forwards motion of intervenor to reopen safety hearing, petition to revoke CP & FR notice.

DENTON, D R Office of Nuclear Reactor Regulation 79/04/12
Son

--7905240872 Motion for ASLAB to reopen safety hearings
DATTILO, T.M. Save the Valley - Save Marble Hill. 79/04/12 2pp

---7905240964 Mution to reopen safety hearings due to EPA ban on herbicide & invalidity of WASH-1400
DATTILO.T H Save the Valley - Save Marble Hill 79/04/12, Spp.

7905140332 Notifies of consolidation of five intervenor groups re radon emissions issue Parties have until 790525 in which to file for summary disposition DUFLO.M E. Atomic Gafaty and Licensing Appeal Panel 79/04/25

H General correspondence

7905240725 Discusses ability of Commissioners to reach objective decisions re-nuclear power, in light of svc in promotional capacity W/NRC Supposts addl govt funding for researching civilian energy needs
HATBON.S. Kentucky, State of 79/04/20 2pp.

Q, Inspection reports, IE Bullatine & correspondence

7905070386 Forwards IE Insp Repts 50-846/79-02 & 50-547/79-02 on 790227-0301 & notice of violation. FIDRELLI, 0 Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/03/14 2pp

--7705070370 Notice of violation from insp on 770227-0301.
Region 3: Chicago: Office of the Director. 77/03/13. ip.

--7905090393 IE Ins Noncompliance n instruction for BCHWEIBINZ, E. R. Office of th

79050102 Bafety KEPPLEI

79030400 KEPPLE 1p.

79050300 Sys Mi KEPPLE 1p

7905010/ Sus H KEPPLI ip.

- 7905040425 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident "
  KEPPLER: J 9 Region 3. Chicago, Office of the Director 79/04/14
- 7905040389 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During THI Incident."

  KEPPLER.J G Region 3. Chicago. Office of the Director 79/04/14
- 7905070167 Forwards IE Bulletin 79-07. "Seismic Stress Analysis of Safety-Related Piping " Licensee action required KEPPLER.J O Region 3. Chicago, Office of the Director 79/04/14 ip
- 7905010411 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Btruts " KEPPLER.J G Region 3. Chicago. Office of the Director 79/04/16 ip
- 7905030241 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Bafety-Related Sys " Licanses action required KEPPLER.J G Region 3. Chicago, Office of the Director 79/04/17 ip
- 7908080507 Forwards IE Bulletin 79-058, "Nuclear Incident at THI-Buppl" KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/21
- 7905140091 Ack receipt of 790410 ltr informing NRC of steps taken to correct violations noted in IE insp Repts 50-546/79-02 & 50-547/79-02 FIDRELLI, 0 Region 3. Chicago, Reactor Construction & Engineering Support Branch 79/04/25 ip
- --7903140097 Responds to NRC 790314 itr re-violations noted in IE Insp. Repts 50-946/79-02 & 50-947/79-02 Corrective actions epace heaters energized & shafts rotated. COUGHLIN, J. Public Bervice Co. of Indiana, Inc. 79/04/10 2pp
- 7905250433 Responds to IE Bulletin 79-03 rs piping mfg by Youngstown Welding & Engineering Co Piping not in use at facility COUGHLIN.J Public Bervice Co of Indiana. Inc 79/03/03 ip.
- 8 Reportable occurrences: LERs & related correspondence
- 7905230529 Forwards K Schelf 791121 1tr & ME Jamison 790315 1tr recubicle cooler defects & repairs
  HARRIS.R Trane Co 79/04/03 1p.
- 7908i60400 Potential RO on 790409 two const crames collided & fell, striking containment liner Vertical angle stiffener, horizontal reinforcing bars & circular CB ring stiffener were damaged Evaluation rept to follow COU
- 7703310420 Provides interim rept of RO on 770416.possible damage to two post-tensioning trumplates & surrounding concrete Caused by overheating from propage fired torches used to repair bendon duct Repair procedures studied COUOHLIN.J Public Service Co of Indiana. Inc. 79/05/16 ip.
- DOCKET STN-50-547 MARBLE HILL NUCLEAR STATION, UNIT 2

1

100

- A. Application/construction stage documents & correspondence
- 7905090292 Responds to comments re application for const of pumphouse intake & discharge structure. H/781016 ltr from Attorney General of KY to Corps of Englineers, Louisville re dredge & fill application of Public Byc Co of IN.

  WHITLOCK, H N Army, Dept. of: Corps of Engineers, 78/11/06 7pp.
- --7905090296 Notifies of licensee's mitigation plan to recover archeological resources disturbed by const of intake & discharge structures. W/IR Dept of Natural Resources litr discoussing plan.

  BALLARD: R L Environmental Projects Branch 2. 78/09/22. 2pp
- 7905020445 Forwards NUREG-0531, "Investigation & Evaluation of Stress Corrosion Cracking in Piping of LWR Plants" & notice of issuance & evaluability. W/o encl.
  VASSALLO, D B Assistant Director for Light Water Reactors 79/03/23, 3pp.
- 7905020321 Responds to 790403 itr re cubicle coolers w/improperly installed gaskets. Matter will be reviewed in future insp. FIGRELLI.O. Region 3. Chicago, Office of the Director. 79/04/17 ip.

- 7905100171 Notification of 790503 meeting w/util in Hethesda, MD to discuss Caseload Forecast Panel's estimate for fuel load date & submittal date for FBAR VAROA, S A Light Mater Reactors Branch 4 79/04/23 4pp
- 7905150296 Notification that lack of expected prehistoric resources justifies termination of mitigation effort BALLARD.R L Environmental Projects Branch 1 79/04/30 2pp.
- 7905080415 Discusses NRC intention to delay FBAR review until end of year Delay is unacceptable as based on average const schedule Util is better than average & unit is committed for 1982 operation FBAR will be filed in June 1979 COUCHLIN, J Public Service Co of Indiana, Inc. 79/05/04 4pp
- Q Adjudicatory correspondence
- 7903150220 Motion to reopen safety hearings to discuss WASH-1400 & herbicide "2.4,5-T "
  DATTILO.T M Dattilo. T M 79/03/22 2pp
- 790502044B forwards NRC memo discussing problems experienced w/pips support base plate design Piping design analysis on case-by-case basis being reviewed under SRP Section 3 9 2.
  BRENNER.L. Branch 3 79/04/05 2pp
- 7905020496 Forwards 780929 memo from Director of Ofc of Nuclear Reacter Regulation to Commissioners, discussing fire protection research test results conducted by UL BRENNER, L. Branch 3, 79704/03 2pp
- 7905140208 Forwards latest motion to reopen safety hearings by F Dattilo on behalf of Save the Valley Save Marble Hill Forwards revisions to draft motions attached to 790402 memo HURRAY, J P Rulemaking & Enforcement Division 79/04/05 2sp
- --7905160212 Motion to suspend & revoke CP for proposed facility because of TMI incident
  DATTILO,T M Metford & Dattilo 79/04/04 2pp
- 790311041B Response to ALAB-509 re radon emissions & de minimus theory from Perkins record Certificate of Syc encl.

  BCINTO, J. F. Hearings Division 79/04/11, 45pp
- 7905140519 Response to 790404 brief of Philadelphia Electric Co.f6E&O & Atlantic City (NJ) Electric Co re de minimus theory Certificate of Svc encl KEPFORD.C R Citizens for Safe Environment. 79/04/11 8pp
- 7905240791 Ack receipt of 790404 petition to institute const suspension proceedings Decision under consideration, Forwards 790412 FR notice.

  DENTON, H R Office of Nuclear Reactor Regulation 79/04/12, 1p
- --7905240813 FR notice of request to reopen safety hearing BOYD.R S Office of Nuclear Reactor Regulation. 79/04/12 2pp
- --7905240850 Forwards motion of intervenor to reopen safety hearing, petition to revoke GP & FR notice DENTON, D R Office of Nuclear Reactor Regulation, 79/04/12 556
- --7905240872 Motion for ASLAB to reopen safety hearings
  DATTILO,T H Save the Valley Save Marble Hill. 79/04/12 2pp
- --7905240944 Motion to reopen safety hearings due to EPA ban on herbicids t invalidity of WASH-1400 DATTILO:T M Save the Valley - Save Marble Hill 79/04/12 Opp
- 7905140332 Notifies of consolidation of five intervenor groups as radon emissions issue Parties have until 790525 in which to file for summary disposition DUFLO-M.E. Atomic Bafety and Licensing Appeal Panel 79/04/25 13pp.
- H. General correspondence
- 7905240725 Discusses ability of Commissioners to reach objective decisions re nuclear power, in light of svc in promotional capacity w/NRC Suggests addit govt funding for researching civilian energy needs.
  WATSON.S. Kentucky, State of. 79/04/20. 2pp.

- O Inspection reports: IE Bulletine & correspondence
- 7905090386 Forwards IE Insp Repts 50-546/79-02 & 50-547/79-02 on 790227-0301 & notice of violation FIDRELLI, G Region 3. Chicago. Reactor Construction & Engineering Support Branch 79/03/14. 2pp
- --7905090390 Notice of violation from insp on 790227-0301.
  \* Region 3. Chicago, Office of the Director 79/03/13 ip
- --7905070393 IE insp Repts 50-546/79-02 % 50-547/79-02 on 790227-0301
  Noncompliance noted failure to have special storage
  instruction for safety-related pump 5 motor
  SCHUEBINIX ER , MAXHELL, 0 F , KNOP, R C Region 3, Chicago,
  Office of the Director 79/03/13 10pp
- 7905010265 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping" REPPLER, J 0 Region 3, Chicago, Office of the Director 79/03/23
- 7905040051 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks "
  KEPPLER: J 0 Region 3, Chicago: Office of the Director 79/03/26
- 7905030049 Forwards IE Bulletin 79-06, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident"

  KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/11
- 7905010602 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Bys Misalignments Identified during TMI Incident."

  KEPPLER, J G Region G, Chicago, Office of the Director 79/04/14
- 7905040423 Forwards IE Bulletin 79~068, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident "
  KEPPLER, J. G Region 3, Chicago, Office of the Director 79/04/14
- 7705040587 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident "
  KEPPLER.JO Region G. Chicago, Office of the Director. 79/04/14
- 7905070167 Forwards IE Bullatin 79-07. "Seismic Stress Analysis of Safety-Related Piping " Licensee Action required KEPPLER.J O Region 3, Chicago, Office of the Director 79/04/14 is
- 79050(0411 Forwards IE Info Notice 79~10, "Nonconforming Pipe Support Struts " KEPPLER: J O Region 3, Chicago, Office of the Director 79/04/16.
- 7905030241 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " Licenses action required, KEPPLER, J.O. Region 3, Chicago: Office of the Director 79/04/17.
- 7905080307 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl."
  KEPPLER, J. O Region 3, Chicago, Office of the Director. 79/04/21
- 7903140091 Ack receipt of 790410 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-546/79-02 & 50-547/79-02. FigReLI.0. Region 3, Chicago, Reactor Construction & Engineering Bupport Branch 79/04/25 lp.
- --7905140097 Responds to NRC 790314 ltr re violations noted in IE Insp Repts 50-546/79-02 & 50-547/79-02. Corrective actions space heaters energized & shafts rotated. COUGHLIN.J Public Service Go of Indiana, Inc. 79/04/10. 2pp
- 7903250433 Responds to IE Bulletin 79-03 re piping mfg by Youngstown Helding & Engineering Co. Piping not in use at facility.
  COUGHLIN, J. Public Service Co. of Indiana. Inc. 79/03/03. ip.
- & Reportable occurrences, LERs & related correspondence
- 7905230529 Forwards K Scheid 791121 ltr & ME Jamison 790315 ltr re cubicle cooler defects & repairs. HARRIS,R. Trane Co. 79/04/03. 1p.

- 7905160400 Potential RO on 790409 two const cranes collided & fell, striking containment liner Vertical angle stiffener, horizontal reinforcing bars b circular CB ring stiffener were damaged Evaluation rept to follow COUGHLIN, J Public Service Co of Indiana, Inc. 79/05/09 ip
- 7905310420 Provides interim rept of RO on 790416 possible damage to two post-tensioning trumplates & surrounding concrete Caused by overheating from propane fired torches used to repair tendon duct Repair procedures studied COUGHLIN, J Public Service Co of Indiana, Inc. 79/05/16 1p

DOCKET 50-548 FORT CALHOUN STATION, UNIT 2

- G Adjudicatory correspondence
- 7905240989 Forwards info on indine behavor during postulated generator tube rupture accidents & ECCS performance characteristics GRAY, J. R. Branch 1 79/04/10 Spp
- --7905241001 Discusses accumulator delivery comparisons for LOFT tests
  L1-3a & L1-4, & effect on ECCS performance
  ROSS,D F Assistant Director for Reactor Safety 78/02/03
- 7903100110 Forwards notifications re UL fire protection test, Lewis Committee Rept, "Transportation of Radionulides in Urban Environ" & neutron dosimetry ORAY, J. R. Branch 1 79/04/12 4pp.
- 7905240801 Bubmits semiannual rept on behalf of util. Lawsuit brought by NE Public Power District against util has been settled Requests further licensing procedures be held in absyance due to parallel suit
  VOIOT. H. H. LeBoeuf, Lamb. Leiby & MacRae 79/04/30 ip
- DOCKET 50-549 GREENE COUNTY NUCLEAR POWER PLANT
- A. Application/construction stage documents & correspondence
- 790303030 Comments on "Federal-State Authorities & Cooperation in Nuclear Power Plant Licensing" outlines changes to NY siting law & attempts to eliminate duplication of regulatory processes between federal & state agencies SMOLINSKY, J New York, State of, 79/04/24 2pp
- G Adjudicatory correspondence
- 7905030239 Forwards interrogatories by NY Dept of Environ Conservation to NY Dept of Public Byc ENGEL, D, A New York, State of 79/03/09. 1p
- ---7905030247 Interrogatories of NY Dept of Environ Conservation to NY Dept of Public BVC.
  BISHOP.M Q. RMCLINSKY, J. H. New York, State of. 79/03/09 3pp
- 7905160163 Forwards Board Notification 79-10 on reactor inspector concerns re B&W plants, Certificate of Svc encl SCINTO, J F. Hearings Division, 79/03/29, 14pp
- 7905010115 equipmen SCINTO, J
- --79050101 equips VASBAL 79/03/
- --79050101 #quips TEDE8( 3pp
- 790507013 potenti fuel, W/ LEWIS. S

- 7905040425 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident "
  KEPPLER.J G Region 3. Chicago, Office of the Director 79/04/14
- 7903040389 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During THI Incident."

  KEPPLER.J.O. Region 3, Chicago, Office of the Director 79/04/14
- 7905070167 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping " Licensee action required KEPPLER.J O Region 3. Chicago. Office of the Director 79/04/14 lp
- 7903010411 Forwards IE Info Notice 79-10. "Nonconforming Pipe Support Struts"

  KEPPLER, J. G. Region 3. Chicago, Office of the Director 79/04/16
- 7905030241 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " Licensee action required KEPPLER, J.O. Region 3, Chicago, Office of the Director 79/04/17
- 7905080507 Forwards IE Bullstin 79-05B. "Nuclear Incident at THI-Bugpl"

  KEPPLER.J G Region 3. Chicago. Office of the Director 79/04/21
- 7905140091 Ack receipt of 790410 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-546/79-02 & 50-547/79-02 FIORELLIA Region G. Chicago, Reactor Construction & Engineering Support Branch 79/04/25 ip
- --7908140097 Responds to NRC 790314 ltr re violations noted in IE Insp Repts 50-546/79-02 & 50-547/79-02 Corrective actions space heaters energized & shefts rotated COUOHLIN.J Public Service Co of Indiana, Inc. 79/04/10 2pp
- 7905250433 Responds to IE Bulletin 79-03 re piging mfg by Youngstown Welding & Engineering Co Piping not in use at facility COUCHLIN.J Public Service Co of Indiana, Inc 79/05/03 1p.
- S Reportable occurrences, LERs & related correspondence
- 7905230529 Forwards K Scheid 791121 ltr & ME Jamison 790315 ltr re cubicle cooler defects & repairs HARRIS.R Trane Co 79/04/03, 1p
- 7905160400 Potential RU on 790409, two const crames collided & fell, striking containment liner Vertical angle stiffener, horizontal reinforcing bars & circular CB ring stiffener were damaged Evaluation rept to follow COU
- 7905310420 Provides interim rept of RO on 790416 possible damage to two post-tensioning trumplates & surrounding concrete Caused by overheating from propane fired torches used to repair tendon duct Repair procedures studied COUGHLIN,J Public Service Co of Indiana, Inc 79/05/16. Ep
- DOCKET STN-50-547 MARBLE HILL NUCLEAR STATION, UNIT 2

on/construction stage documents & correspondence

ts re application for const of pumphouse W/781016 ltr from Attorney gineers, Louisville re dredge b vc Co of IR. Coros of Engineers, 78/11/06 7pg.

of intake &

Branch 2 78/09/22 2pp

on & Evaluation of Stress \* & notice of

ght Water Reactors.

coolers w/improperly in future insp. f the Director 79/04/17

- 7905100171 Notification of 790503 meeting w/util in BethesdarMD to discuss Caseload Forecast Panel's estimate for fuel load date & submittal date for FBAR VAROA.B A Light Water Reactors Branch 4 79/04/23 4pp
- 7905150296 Notification that lack of expected prehistoric resources justifies termination of mitigation effort BALLARD,R L Environmental Projects Branch 1 79/04/3D 2pp
- 7905080415 Discusses NRC intention to delay FSAR review until end of year Delay is unacceptable, as based on average const schedule Util is better than average & unit is commited for 1982 operation FSAR will be filed in June 1979 COUCHLIN, J Public Service Co of Indiana, Inc 79/05/04. App
- O Adjudicatory correspondence
- 7905150220 Motion to reopen safety hearings to discuss WASH-1400 & herbicide "2,4,5-T"
  DATTILO,T M Dattilo, T M 79/03/22 2pp
- 7905020448 Forwards NRC memo discussing problems experienced w/pipe support base plate design Piping design analysis on case-by-case basis being reviewed under SRP Section 3.9.2 BRENNER.L. Branch 3 79/04/05 2pp.
- 7905020495 Forwards 780927 memo from Director of Ofc of Nuclear Reactor Regulation to Commissioners discussing fire protection research test results conducted by UL BRENNER.L Branch 3 79/04/05 2pp
- 7905160208 Forwards latest motion to reopen safety hearings by T Dattilo on behalf of Save the Valley Save Marble Hill Forwards revisions to draft motions attached to 790402 memo MURRAY, J P Rolemaking & Enforcement Division 79/04/05 2pp
- --7905160212 Motion to suspand & revoke CP for proposed facility because of TMI incident
  DATTILO,T M Metford & Dattilo 79/04/04 2pp
- 7905110418 Response to ALAB-509 re radon emissions & de minimus theory from Perkins record, Certificate of Byc encl 8CINTO, J F Hearings Division 79/04/11 45pp
- 7905140517 Response to 790404 brief of Philadelphia Electric Co.PBELO & Atlantic City (NJ) Electric Co re de minimus theory.
  Certificate of Bvc encl
  KEPFORD, C R Citizens for Bafe Environment 79/04/11 Bpp
- 7905240791 Ack receipt of 790404 petition to institute const suspension proceedings Decision under consideration Forwards 790412 FR notice.

  DENTON. H R Office of Nuclear Reactor Regulation 79/04/12 19
- ---7903240813 FR notice of request to reopen safety hearing. BGYD:R 8. Office of Nuclear Reactor Regulation. 79/04/12 2pp
- --7905240850 Forwards motion of intervenor to reopen safety hearing, petition to revoke GP & FR notice.

  DENTON, D.R Diffice of Nuclear Reactor Regulation 79/04/12
- ~-7905240872 Motion for ASLAB to reopen safety hearings DATT[LO:T M. Save the Valley - Bave Marble Hill 79/04/12 2pp
- --7908240964 Motion to reopen safety hearings due to EPA ban on herbicide & invalidity of WASH-1400 DATTILO,T.H Bave the Valley -- Save Marble Hill 79/04/12 3pg
- 7905140332 Notifies of consolidation of five intervenor groups re radon smissions issue Parties have until 790525 in which to file for summary disposition DUFLO.M.E. Atomic Bafety and Licensing Appeal Panel 79/04/25 iSpp.
- H. General correspondence
- 7905240723 Discusses ability of Commissioners to reach objective decisions re nuclear power. In light of svc in promotional capacity w/RRC. Suggests addl govt funding for researching civilian energy needs
  HATSON. 8 Kentucky, State of. 79/04/20, 2pp.

- Inspection reports, IE Bulletins & correspondence
- 7905090386 Forwards IE Insp Repts 50-546/79-02 & 50-547/79-02 on 790227-0301 & notice of violation FiORELLI, 0 Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/03/14 2pp
- ~~7905090390 Notice of violation from insp on 790227-0301
   Region 3, Chicago, Office of the Director 79/03/13 ip
- ~7705070393 IE Insp Repts 50-546/77-02 & 50-547/77-02 on 770227-0301 Noncompliance noted failure to have special storage instruction for safety-related pump & motor SCH-HEBINZ. E R. MAXWELL, 0 F. KNDP, R C Region G, Chicago, Office of the Director 79/03/13 10pp
- 7905010265 Forwards IE Info Notice 79-06. "Stress Analysis of Safety-Related Piping" KEPPLER, J Q Region 3. Chicago, Office of the Director 79/03/23
- 7905040051 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks "
  KEFPLER.J 0 Region G. Chicago, Office of the Director 79/03/26
- 7905030049 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misslignments Identified During YMI Incident "
  KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/11
- 7905010502 Forwards IE Bulletin 79-06A. "Review of Operational Errors & Bys Hisalignments Identified during TMI Incident "
  KEPPLER, J @ Region 3. Chicago. Office of the Director 79/04/14
- 7905040425 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."

  KEPPLER, J. O Region 3. Chicago, Office of the Director 79/04/14
  io
- 7905040589 Forwards IE Builetin 79-08, "Events Relevant to Boiling Water Fower Reactors Identified During TM1 Incident " MEPPLER, J. O Region 3, Chicago, Office of the Director, 79/04/14
- 7905070167 Forwards IE Bullatin 79-07, "Saismic Stress Analysis of Safaty-Related Piping " Licenses action required KEPPLER, J C. Region 3: Chicago: Office of the Director 79/04/14.
- 7905010411 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Biruts " KEPPLER, J Q Region 3, Chicago, Office of the Director 79/04/16
- 7903030241 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Bys." Licensee action regulated KEFPLER,J O Region 3: Chicago, Office of the Director 79/04/17
- 7905080507 Forwards IE Bulletin 79-058. "Nuclear Incident at THI-BURD!"

  MEPPLER.J.O Region 3, Chicago, Office of the Director 79/04/21 is
- 7905140091 Ack receipt of 790410 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-546/79-02 & 50-547/79-02 FIORELLIG. Region 3, Chicago, Reactor Construction & Engineering Bupport Branch. 79/04/25 ip
- ---7905140097 Responds to NRC 790314 ltr re violations noted in IE Insp Repts 50-546/79-02 & 50-547/79-02. Corrective actions. space heaters energized & shafts rotated COUGHLIN, J Public Service Co. of Indiana, Inc. 79/04/10. 2pp.
- 7905250433 Responds to IE Bulletin 79-03 re piping mfg by Youngstown Welding & Engineering Co.Piping not in use at facility COUGHLIN.J. Public Service Co. of Indiana. Inc. 79/05/03. ip.
- 8 Reportable occurrences. LERs & related torrespondence
- 7905230329 Forwards K Scheid 79112: Itr & ME Jamison 790315 ltr ra cubicle cooler defects & repairs. HARRIS.R Trans Co 79/04/03 1p.

- 7903i60400 Potential RO on 790409 two const cranes collided & fell: striking containment liner Vertical angle stiffener, horizontal reinforcing bars & circular GB ring stiffener were damaged Evaluation rept to fellow GOUGHLIN.J. Public Service Co of Indiana, Inc. 79/05/09. ip.
- 7903310420 Provides interim rept of RO on 790416 possible damage to two post-tensioning trumplates & surrounding concrete Caused by overheating from propane fired torches used to repair tendon duct Repair procedures studied CQUOHLIN.J Public Service Co of Indiana. Inc 79/05/16. 1p
- DOCKET 50-548 FORT CALHOUN STATION, UNIT 2

  O Adjudicatory correspondence
- 7903240989 Forwards info on iodine behavor during postulated generator tube rupture accidents & ECCS performance characteristics 9RAY,J R Branch 1 79/04/10 Spp
- --7705241001 Discusses accumulator delivery comparisons for LOFT tests L1-3a & L1-4, & effect on ECCS performance ROSS,D F Assistant Director for Reactor Safety 78/02/03.
- 7905100110 Forwards notifications re UL fire protection test, Lewis Committee Rept "Transportation of Radionalides in Urban Environ" & neutron desimetry ORAY, J R Branch 1 79704/12 4pp
- 7905240801 Submits semiannual rept on behalf of util Lawsuit brought by NE Public Power District against util has been settled Requests further licensing procedures be held in abeyance due to parallel suit VOIOT.H H LeBoeuf. Lamb. Leiby & MacRae 79/04/30 1p
- DOCKET 50-549 GREENE COUNTY NUCLEAR POWER PLANT
- A Application/construction stage documents & correspondence
- 7905030350 Comments on "Federal-State Authorities & Cooperation in Nuclear Power Plant Licensing".outlines changes to NY siting law & attempts to eliminate duplication of regulatory processes between federal & state agencies SMOLINEKY, J New York, State of 79/04/24 2pp.
- O Adjudicatory correspondence
- 7905030239 Forwards interrogatories by NY Dept of Environ Contervation to NY Dept of Public Svc ENGEL.D A. New York. State of 79/03/09 1p
- --7905030247 Interrogatories of NY Dept of Environ Conservation to NY Dept of Public Syc.
  BISHOP,M Q . SMQLINSKY,J H New York, State of 79/03/09 3pp
- 7905160163 Forwards Board Notification 79-10 on reactor inspector concerns re B&W plants Certificate of Svc encl. BCINTO.J.F Hearings Division. 79/03/29 14pp
- 7905230841 NRC motion for mod of 790923 Joint Board ruling extending scheduled dates in proceeding. Moves for stay of filing dates pending util's rept to be filed on 790320. Certificate of Bvc encl LEMIS, S. H. Branch 2 79/03/29. Ppp
- 7905010115 Forwards request for Board notification re nonsafety-grade squipment to mitigate transients.
  SCINTG-J F. Hearings Division. 79/04/02. 31pp.
- ---7905010136 Board hotification:staff assessment re nonsafety-grade aquipment to mitigate transients.
  VASBALLO.D.S. Assistant Director for Light Water Reactors 79/03/29. 2pp.
- --7905010198 Board notification recent issue on nonsefety-grade equipment to mitigate transients More into is required. TEDEBCO.R. L. Assistant Director for Reactor Sefety 79/03/16-300.
- 7905070134 Forwards transmittel memo for document which contains info potentially relevant to issue of mahotage of spent nuclear fuel. M/o encl.

  LEWIS. S. H. Branch 2, 79/04/02, 2pp

- --7905070141 Forwards draft rept on sabotage attacks on spent fuel transportation sys Rept is first one available re high level explosive attack on spent fuel shipping casks W/o encl CARTER.T F Division of Bafeguards 79/01/22 2pp.
- 7905160112 Board notification nuclear incident at TMI Recommends boards on cases involving B&W reactors be provided w/1E Bullatin 79-05 & PNO-67 & 67A, B, C, D, E, F, Q & H VASBALLO, D B Assistant Director for Light Water Reactors 79/04/03 2pp
- 7903250080 Suspends further hearings re util's application for certificate for authority to construct 2 operate plant Grants 790329 interlocutory appeal of State of NY Dept of Public Svc Certificate of Svc encl HADISON, B R New York, State of 79/04/05 11pp
- 7905100150 Forwards requested summary of 790410 telcon w/util re permission to construct nuclear facility MOORE, J E Branch 2 79/04/12 2pp
- 7905240983 Motion by Greene County & towns of Athens & Catstill in support of NRC & NY Dept of Public Svc 790405 motion to dismiss application & terminate proceeding & in apposition to applicant's 790416 alternative request BUTZEL.A K Butsel & Kass 79/04/22 2pp
- 7903300367 Forwards draft "Historical & Cutural Context of Proposed Oreene County Nuclear Power Plant." Requests certain matl not be reproduced due to copyrights LEMIS.S H Branch 2 79/04/23 1p
- J Insurance & Indemnity information
- 7905070497 Confirms increased liebility limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170, 173,174,178,179,180,182,185,186,187,188,189,192,193,194,195,197,198,200,201,204,206,207,208,210,212,214,215,&others QUATTROCHMI,J American Nuclear Insurers, 79/05/01 1p
- 79050705B2 Confirms increase in liability limit to \$36,000,000 for policies MF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,86,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,67,88,90,51,92,93,94,95 % 96.
  ROBERTS,D M Mutual Atomic Energy Liability Underwriters 79/05/01 ib.
- 8 Reportable occurrences, LERs & related correspondence
- 7905110203 Board notification Seabrook refueling water storage tank design deficiency SCINTO, J Hearings Division 79/03/27 30pp

DOCKET STN-50-550 GESSAR-238-80F INTERFACE

- J. Insurance & indemnity information
- 7903070382 Confirms increase in liability limit to \$36,000,000 for policies MF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,56,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,91,92,93,94,95 & 96. . . ROBERTS, D. H. Hutual Atomic Energy Liability Underwriters 79/03/01

DOCKET BIN-50-553 PHIPPS BEND NUCLEAR PLANT, UNIT 1

- A Application/construction stage documents & correspondence
- 7905100093 Discusses 790329 site visit reladd fault found in core cooling water trench Util to provide description of trench fault.discussion of fault's relationship to regional geology is fault area mapping
  HELLER.L.W Geosciances Branch 79/04/17. 2pp
- 7905040345 Forwards description of add1 fault discovered beneath component cooling water pumping station. Fault not considered to be capable One oversized drawing encl
  GILLELAND, J. E Tennesses Valley Authority, 79/04/30, 2pp.
- 7705080541 Discusses util position on leak testing pressure & temp requirements of ACI Stds 318 & 349 for piping to be embedded in concrete Revisions to PBAR re ambedded piping will be implemented inmediately, GILLELAND, J.E. Tennessee Valley Authority. 79/05/03. 3pp.
- 7905:40270 Describes adjusted route for transporting reactor pressure vessels. Util finds environ impact to be within scope of criginal analysis
  GILLELAND.J E. Tennesses Valley Authority. 79/05/07. 1p.

- F Security, medical, emergency & fire protection plans
- 790300462 Forwards addl response to 780926 meeting minutes re BTRIDE fire hazards analysis Includes proposed design changes to fire protection sys Requests early meeting to discuss responses GILLELAND, J E Tennesses Valley Authority 79/05/20 9pp
- O Adjudicatory correspondence
- 7903240874 Requests adoption of de minimus théory of Perkins ABLB Certificate of Svc encl SANGER.H 8 Tennessee Valley Authority 79/04/06 11pp
- 7905:104:8 Response to ALAB-509 re radon emissions & de minimus theory from Parkins record Certificate of Svc encl SCINTO.JF Hearings Division 79/04/11 45pp
- 7905140519 Response to 790404 brief of Philadelphia Electric Co.PBEt04 Atlantic City (NJ) Electric Co re de minimus theory Cartificate of Evc encl REPFORD C R Citizens for Bafe Environment. 79/04/11 Spp
- 7905140332 Notifies of consolidation of five intervenor groups re rates emissions issue Parties have until 790325 in which to file for summary disposition DUFIG.M E Atomic Safety and Licensing Appeal Panel, 79/04/25.
- G Inspection reports: IE Bulletins & correspondence
- 7905010211 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping " G'REILLY.J P. Region 2, Atlanta, Office of the Director 79/03/23 2pp
- 7908030368 Forwards IE Bulletin 79-07, "Seismic Strass Analysis of Safety-Related Piping " Licensee action required D'REILLY, J P Region 2, Atlanta, Office of the Director 7970474 3pp
- 7905040233 Forwards IE Bulletin 79-04B, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident "O'REILLY, J P Region 2: Atlanta, Office of the Director," 79/04/14 3pp
- 7905110345 Forwards IE Bulletin 79-08, "Events Relevant to Softing Mater Power Reactors Idantified During TMI Incident."
  0'REILLY,J P. Region 2, Atlanta, Office of the Director
  79/04/14 1p
- 790501034; Forwards IE Info Notice 79-10. "Nonconforming fipe Support Struts." O'REILLY, J P Region 2. Atlanta, Office of the Director 79/04/18. is
- 7905030172 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licenses action required.
  O'REILLY, J.P. Region R. Atlanta, Office of the Birector 79/04/17. 2ps
- 7905020479 Forwards IE Builetin 79-06A, Revision I. "Review of Operational Errors & Bys Misalignments Identified During THI Incident " O'REILLY, J P Region 2. Atlanta, Office of the Director. 79/04/16 2pp
- 7905300253 Bubmits supplemental response to IE Bulletin 77-07. Original response submitted 780120, Provides addl info received from manufacturer & describes plans in area of electrical penetrations.

  OILLELAND, J. E. Tennessee Valley Authority 74/04/27. Spp.
- 5. Reportable occurrences: LERs & related correspondence
- 7903140478 Forwards final rept of reportable condition re BHR/6 HFCS local control panels. (NRC QE-79-01)
  QILLELAND, J E Tennesses Valley Authority. 79/04/05. 1p.
- ---7905140482 Reportable condition on 790306.QE determined that defect existed in HPCB panel H22-P028.Caused by installation of nonqualified type relay Procedures revised & GA program modified

  \* Tennessee Valley Authority 79/04/05. 2pp.

DOCKET STN-50-554 PHIPPS BEND NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

7905100093 Discusses 790329 site visit re addl fault found in core cooling water tranch Util to provide description of tranch fault-discussion of fault's relationship to regional geology & fault area mapping HELLER.L W Geosciences Branch 79/04/17 2pp

7905040345 Forwards description of add1 fault discovered beneath component cooling water pumping station Fault not considered to be capable One oversized drawing encl 01LLELAND, J E Tennessee Valley Authority 79/04/30, 2pp

7905080541 Discusses util position on leak testing pressure & temp requirements of ACI Stds 318 & 349 for piping to be embedded in concrete Revision to PSAR re embedded piping will be implemented immediately OILLELAND, J E Tennessee Vailey Authority 79/05/03 3pp

7905140270 Describes adjusted route for transporting reactor pressure vessels Util finds environ impact to be within scope of original analytis
OLLLELAND, J E Tennessee Valley Authority 79/05/07 ip

F Security, medical, emergency & fire protection plans

7905300462 Forwards add1 response to 780926 meeting minutes re BTRIDE fire hazards analysis Includes proposed design changes to fire protection sys Requests early meeting to discuss responses

GILLELAND, J. E. Tennessee Valley Authority 79/05/20 9pp

### O Adjudicatory correspondence

7905110418 Response to ALAB-509 re radon emissions & de minimus theory from Perkins record Certificats of Svc encl SCINTO.J F Hearings Division 79/04/11 45pp.

7905140517 Response to 790404 brief of Philadelphia Electric Co.PSE&O & Atlantic City (NJ) Electric Co me de minimus theory Certificate of Svc encl KEPFORD.C R Citizens for Safe Environment. 79/04/11 Spp.

7905140332 Notifies of consolidation of five intervenor groups re radon emissions issue Parties have until 790525 in which to file for summary disposition.

DUFID.H E. Atomic Bafety and Licensing Appeal Panel 79/04/25

G Inspection reports, IE Bulletins & correspondence

7905010211 Forwards IE Info Notice 79-06. "Stress Analysis of Safety-Related Piping."
O'REILLY, J P Region 2. Atlanta, Office of the Director 79/03/23 2pp.

790303036B Forwards IE Bulletin 79-07, "Beigmic Stress Analysis of Bafety-Related Piping." Licensee action required O'REILLY, J P Region 2, Atlanta, Office of the Director, 79/04/14 | 3pp

7905040233 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Hisalignments Identified During TMI Incident."

0'REILLY,J P Region 2, Atlanta, Office of the Director 77/04/14, 3pp

7905110365 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident." O'REILLY, J P Region 2, Atlanta, Office of the Director. 79/04/14, 1p.

7903010341 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts "
O'REILLY, J.P. Region 2, Atlanta: Office of the Director.
79704/18. 1p

7905030172 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys." Licenses action requires. O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/17. 2pp

7705020479 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident."

O'REILLY, J. P. Region 2, Atlanta, Office of the Director, 79/04/18 2pp.

7903300253 Submits supplemental response to IE Bulletin 77-07. Original response submitted 780120, Provides add1 info received from manufacturer & describes plans in area of electrical penetrations.

OILLELAND, J E Tennessee Valley Authority 79/04/27 Spp

S Reportable occurrences, LERs & related correspondence

7905140478 Forwards final rept of reportable condition re BWR/6 HPC9 local control panels (NRC GE-79-01) GILLELAND, J E Tennessee Valley Authority 79/04/05. 1p

--7903140482 Reportable condition on 790303 GE determined that defect existed in HPCS panel H22-P028 Caused by installation of nonqualified type relay Procedures revised & QA program modified \* Tennessee Valley Authority 79/04/05 2pp

DOCKET STN-50-556 BLACK FOX STATION, UNIT 1

A. Application/construction stage documents & correspondence

7905020452 Forwards NUREO-0531, "Investigation & Evaluation of Stress Corrosion Cracking in Piging of LWR Plants" & notice of issuance & availability W/o encl VASSALLO, D B Assistant Director for Light Water Reactors 79/03/23 2bp

7905150641 Natification of 790503-04 geologic site visit w/util in Inola.QK to observe site excavation & geologic mapping activities
THOMAS,C D Light Water Reactors Branch 1 79/04/04 4pp.

E NRC Safety Evaluation Report (SER), supple & correspondence

7905070665 Forwards Suppl 2 to SER VAROA.S.A Light Water Reactors Branch 4 79/04/05 Spp.

Q Adjudicatory correspondence

7905160504 Response by util in opposition to intervenors' 790301 motion to suppl record w/"Tulsa Metropolitan Area. Tulsa Urban Study. Draft. Summany Rept. Stage 2 Study" prepared by Tulsa Army Corps of Engineers W/Certificate of Svc MURPHY.P.M., BIELAMSKI.A.P Isham, Lincoln & Beale 79/03/14, 6pp

7705090185 Applicant's response to intervenors' 770307 motion to file supplemental brief & to intervenors' supplemental brief itself Brief concerns failure to consider Glass 9 accidents in environ review Cartificate of Syc encl MURPHY, P. H. & BIELANSKI, A. P. Isham, Lincoln & Beats 79/03/16. 7pp.

7905070021 NRC response in opposition to intervenors 790301 motion to suppl record w/"Twiss Metropolitan Area Urban Study. Draft. Summary Rept.Stage 2 Study" prepared by Tulsa Army Corps of Engineers Certificate of Svc encl DAVIS.L D Branch 4 79/03/19. Spp

7905090182 NRC response to intervenors 790304 motion to file supplemental brief re letter's Exceptions 112 & 113 Certificate of Svc encl. DAVIS.0 L. Branch 4, 79/03/23 App

7703010113 Forwards request equipment to mitigate transcript F. Heer

--7905010 equip VASSA 79/03

--7905010 equip TEDES 3pg

790529027 facts & FARRIB,

790524027 law on THOMAS

79051500' DAVIS,

- 7905220062 Forwards errata sheet correcting errors in findings of fact & conclusions of law submitted 790326 & 28
  QALLO, J Isham, Lincoln & Beale 79/04/09 2pp
- 7905230259 Discusses regulations re interconnection of sys of both reactors, in event of accident at one reactor affecting safe operation at other reactor.

  DAVIS.L D Branch 4 79/04/11 2pp
- 7905140547 Notice of filing of intervenors Citizens for Bafe Energy.
  L Burrell & I Younghein proposed findings of fact,
  conclusions of law & proposed order in form of partial
  inital decision Certificate of Svc encl
  FARRIS.J.R Oreen, Feldman, Hall & Wooderd 79/04/12 4pp
- ---7905140850 Intervenore Citizens Action for Safe Energy, L Burrell & I Younghein proposed findings of fact conclusions of law & proposed order in form of partial initial decision reradiological health & safety matters FARTS, J R , HDDDARD, J R Green, Feldman, Hall & Hondard 79/04/12 77pp
- 7908100226 Proposed findings of fact & conclusions of law in form of initial decision re radiological health & safety matters W/supporting documentation DAVIS.D L . PATON W D Branch 4 WOODHEAD.C P Branch 3 79/04/13 161pp
- 7905220064 Requests Reed rept & subtask repts be returned to GE Repts will be made available for NRC review if needed Certificate of Svc encl
  EDGAR.O L Morgan, Lewis & Bockius 79/04/13 4pp
- 7905100215 Requests extension until 790426 to file ECCS portion of proposed findings of fact & conclusions of law Gertificate of Evc encl
  DAVIS.L D Branch 4 79/04/16. 3pp
- ---7905100219 Proposed findings of fact & conclusions of law in form of initial decision re radiological health & safety matters.

  W/o ECCB section Certificate of Evc enci
  DAVIS.L D Branch 4 79/04/16 2pp.
- 7905240879 Requests Reed Rept be maintained in confidence pending ASLB ruling on whether rept should be returned to QE EDGAR.O L Morgan, Lewis & Buckius 79/04/18 2pp
- 7905150069 Moves for indefinite stay of proceeding concerning issuance of initial decision pending investigation of TMI-2 & hearings refacility financing Certificate of Svc enci.
  THOMAS 0. ROGERS, C.S., CARTHRIGHT, J.E. Oklahoma, State of 79/04/19 11pp
- 7903130491 Ack receipt of 790418 ltr Request basis is hypothetical; no NRC personnel have requested ASLB for access to Reed Rept NRC technical & legal staff will not have access to report until 790430 MOLFE, B J. Atomic Safety and Licensing Board Panel 79/04/19. Ip
- 7905230759 Advises that motion has been filed to stay issuance of initial decision. ROCERS.C. Oklahoma, State of 79/04/19 ip
- 7905250179 Errata sheet & table of contents to applicants 790426 reply to proposed findings of fact & conclusions of law filed by NRC & intervenors 8 Isham. Lincoln & Beale 79/04/26, 2pp.
- 7903240924 Response by intervenors Gitizens Action for Safe Power, L. Burrell & I Younghein supporting adoption of motion by State of OK for indefinite stay in issuance of initial decision. Certificate of Sec encl. FARRIS.J.R. Oreen, Feldman, Hall & Hoodard 79/04/27, 10pp.
- 7905230174 Porwards into re schedule & cost analysis. Commercial operation for Unit 1 shall begin on 850701 & for Unit 2 on 880301 Applicants filed reply to NRC & intervenors proposed findings of fact & conclusions of law on 790426 OALLO, J Isham, Lincoln & Beals. 79/04/30 12pp.

ė<sub>ų</sub>

Ŋ,

- 7905230560 Orants extension until 790509 to file proposed findings of fact re ECCS; per NRC 790426 request HOLFE, S. J Atomic Safety and Licensing Board Panel 79/05/01. 1p
- 7905230570 Orants extension until 790511 for util 4 NRC to file answers to motion by State of OK for indefinite stay of issuance of initial decision.

  WOLPE,B.J. Atomic Safety and Licensing Board Panel. 79/05/01. 1p

- H Caneral correspondence
- 7903130279 Requests info re Juna 1979 hearing in Phoenix.AZ Oroup wants to send delegation to hearing

  \* Nuclear Free State 79/03/28 ip.
- 7905100353 Beliaves GE should publish Reed Rept re unresolvable safety issues Opposes nuclear plant const Supports solar & wind power research BELCHER.T Affiliation Unknown 79/04/16 ip
- 7905310397 Urges NRC to release all portions of transcripts of safety hearings, including portions dealing w/Reed Rept OARNETT, H . GARNETT, Q . Affiliation Unknown 79/04/17 ip
- I Financial information
- 7905250029 Requests add1 financial info on updated cost estimates, in order to complete review of revised financial info.
  EMING.T N Public Service Co of Oklahoma 79/05/07 3pp
- 7905090357 "Annual Financial Rept 1978 "
  \* Central % Southwest Services, Inc. 79/05/09 40pp
- 7905090359 "Annual Financial Rept 1978 "
  \* Public Service Co. of Oklahoma 79/05/09 39pp
- 7909230424 Submits add1 financial info in response to NRC 790507 request Previous info was solely to advise of cost & schedule study & not in response to motions to intervene Syc list encl
  EMING.T N Public Service Co of Oklahoma 79/05/14. 2pp
- 7905240393 Responds to NRC 790501 request for add1 info Util 790430 lift included all available financial info EMINO.T N Public Service Co of Oklahoma 79/05/14 2pp
- Q Inspection reports, IE Bulletins & correspondence
- 7905150364 Forwards IE Insp Repts 50-556/79-02 & 50-557/79-02 on 790306-09. No noncompitance noted SEIDLE.W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/03/23 2pp
- --7905130370 IE Insp Repts 50-356/79-02 & 50-557/79-02 on 790306-09 No noncompliance noted Major areas inspected, const status, development of concrete mix design.training & Indoctrination & QA HUBACEK, W O , CROSGMAN, W, A , HALL, R E Region 4, Dallas, Office of the Director 79/03/23 7pp
- DOCKET STN-50-557 BLACK FOX STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 7905020452 Forwards NUREO-053; "Investigation & Evaluation of Streets Corrosion Cracking in Piping of LWR Plants" & notice of Issuance & availability M/o encl.
  VASSALO, D B Assistant Director for Light Water Reactors 79/03/23 2pp
- 7905130641 Notification of 790503-04 geologic site visit w/util in Inola, CR to observe site excavation & geologic mapfing activities.
  THOMAS, C. O Light Water Reactors Branch 1 79/04/06. App
- E. NRC Safety Evaluation Report (SER), supple & correspondence
- 7905070665 Forwards Suppl 2 to SER.
  VARQA, S. A. Light Water Reactors Branch 4 79/04/05 Spp.
- Q. Adjudicatory correspondence
- 7905i60504 Response by util in opposition to intervenors' 790301 motion to suppl record w/"Tulsa Hetropolitan Area, Tulsa Urban Study, Draft, Swamary, Rept, Stage 2 Study" prepared by Tulsa Army Corps of Engineers, W/Cortilicate of Svc. HURPHY, P. M., 2 SIELAMSKI, A. P. Isham, Lincoln & Seele, 79/03/14, 688.
- 7905090185 Applicant's response to intervanors' 790307 motion to file supplemental brief & to intervenors' supplemental brief itself.Brief concerns failure to consider Class 9 accidents in snyion review. Certificate of Syc encl.
  MURPHY.P.M. . BIELAWSKI.A.F Isham, Lincoln & Beals, 79/03/16. 7pp.

- 7905070021 NRC response in opposition to intervenors 790301 motion to suppl record w/"Tulsa Metropolitan Area Urban Study, Draft, Swamary Rept. Stage 2 Study" prepared by Tulsa Army Corps of Engineers Certificate of Svc suc. DAVIS.L D Branch 4 79/03/19 Spp
- 7905090182 NRC response to intervenors 790304 motion to file supplemental brief re latter's Exceptions 112 & 113 Certificate of Svc encl DAVIS.D L. Branch 4 79/03/23 App
- 7905010115 Forwards request for Board notification re nonsafety-grade equipment to mitigate transients
  SCINTO, J. F Hearings Division 79/04/02 Sipp
- --7903010155 Board notification staff assessment re nonsafety-grade equipment to mitigate transients VASSALLO.D B Assistant Director for Light Water Reactors. 79/03/29 200
- --7905010198 Board notification recent issue on nonsafety-grade equipment to mitigate transients More info is required TEDESCO.R L. Assistant Director for Reactor Bafety 79/03/16
- 7905290273 Requests extension until 790412 to file proposed findings of facts & conclusions of law Certificate of Byc encl FARRIB, J R Citizens Action For Safe Energy 79/04/03 5pp
- 7705246275 Declines to file proposed findings of fact & conclusions of law on limited record Certificate of Syc encl
  THOMAS, 0 , ROGERS, C S. Oklahoma, State of 79/04/05. Spp.
- 7903130039 Forwards NUREG-0190, Mar 1979, Suppl 2 to SER DAVIS, L. D. Branch 4, 79/04/09 1p
- 7905220062 Forwards errata sheet correcting errors in findings of fact & conclusions of law submitted 790326 & 28
  QALLG,J Isham, Lincoln & Beale 79/04/09 2pp
- 7905230259 Discusses regulations re interconnection of mys of both veactors in event of accident at one reactor affecting mafe operation at other reactor DAVIB.L D Branch 4 79/04/11. 2pp
- 7905140547 Notice of filing of intervenors Gitizens for Safe Energy, L Burrell & I Younghein proposed findings of fact, conclusions of law & proposed order in form of partial inital decision Certificate of Svc encl FARRIS, J R. Green, Feldman, Hall & Woodard 79/04/12 4pp
- --7903:40550 Intervenors Citizens Action for Bafe Energy.L Burroil & I Younghein proposed findings of fact.conclusions of law & proposed order in form of partial initial decision rereadological health & safety matters FARRIB.J.R. HODDARD.J.R. Orsen, Feldman, Hall & Woodard. 79/04/12 77pp
- 7905100226 Proposed findings of fact & conclusions of law,in form of initial decision re radiological health & safety matters W/supporting documentation DAVIE,D L , PATON,M, D. Branch 4, WOODHEAD,C,P, Branch 3, 79/04/i3
- 7905220064 Requests Read rept & subtask repts be returned to GE.Repts will be made available for NRC review, if needed Certificate of Svc enci.
  EDOAR, O.L. Morgan, Lewis & Bockius 77/04/13. 4pp
- 7905100215 Requests extension until 770426 to file ECCS portion of proposed findings of fact & conclusions of law Certificate of Bvc encl
  DAVIS.L D. Branch 4. 79/04/16 Spp
- --7903100219 Proposed findings of fact & conclusions of law in form of initial decision re radiological health & safety matters H/o ECCB section Certificate of Svc encl DAVIS:L.D Branch 4. 79/04/16. 2pp.
- 7905240879 Requests Reed Rept be maintained in confidence pending ASLB ruling on whether rept should be returned to OE, EDGAR.Q L. Margan, Lewis & Bockius. 79/04/18, 2pp
- 7905150063 Moves for indefinite stay of proceeding concerning issyance of initial decision, pending investigation of TMI-2 & hearings re-facility finencing Certificate of Svc encl. THOMAS.C., ROGERS.C.S., CARTHRIOHT, J.E. Okiahoma, State of. 79/04/19, lipp

- 7903130491 Ack receipt of 790418 ltr Request basis is hypothetical no NRC personnel have requested ABLB for access to Reed Rept NRC technical & legal staff will not have access to report until 790430 WOLFE B J Atomic Bafety and Licensing Board Panel 79/04/19 ip
- 7905230759 Advises that motion has been filed to stay issuance of initial decision ROGERB.C Oblahoma, State of, 79/04/19 ip
- 7905250179 Errata sheet & table of contents to applicants 790426 reply to proposed findings of fact & conclusions of law filed by NRC & intervenors \* Isham. Lincoln & Beale. 79/04/26 2pp
- 7905240924 Response by intervenors Citizens Action for Safe Power, L Burrell & I Younghein supporting adoption of motion by State of OK for indefinite stay in issuance of initial decision Certificate of 8vc encl. FARRIS.J R Green, Feldman, Hall & Woodard 79/04/27 10pp
- 7905290174 Forwards info re schedule & cost analysis Commercial operation for Unit 1 shall begin on 850701 & for Unit 2 on 880501 Applicants filed reply to NRC & intervenors proposed findings of fact & conclusions of law on 790426 QALLO, J Isham, Lincoln & Beate 79/04/30 12pp
- 7905230560 Grants extension until 790509 to file proposed findings of fact re EGCS,per NRC 790426 request.

  WOLFE:8 J Atomic Safety and Licensing Board Panel 79/03/01, is
- 7908230870 Grants extension until 790811 for util & NRC to file answers to motion by State of OK for indefinite stay of issuance of initial decision HOLFE-B. J. Atomic Safety and Licensing Board Panel 79/08/01 ip
- H General correspondence
- 7905150279 Requests info re June 1979 hearing in Phoenix. AZ Group wants to send delegation to hearing.

  \* Nuclear Free State 79/03/28. 19
- 7905100353 Believes GE should publish Read Rept re unresolvable safety issues Opposes nuclear plant const Supports solar & wind power research BELCHER: T. Affiliation Unknown. 79/04/16 ip.
- 7905310397 Urges NRG to release all portions of transcripts of safety hearings, including portions dealing w/Reed Rept OARNETT, H., OARNETT, O. Affiliation Unknown 79/04/17 1p
- I. Financial information
- 7905250029 Requests add1 financial info on updated cost estimates, in order to complete review of revised financial info EMINO, Y N Public Bervice Co of Oklahoma 79/05/07. 3pp
- 790909037 "Annual Financial Rept 1978. # Central & Southwest Services. Inc 79/05/09. 40pp
- 7905090359 "Annual Financial Rept 1978 "
  \* Public Service Co. of Oklahoma 79/05/09, 39pp.
- 7905230424 Submits addi financial info in response to NRC 790507 request Previous info was solely to advise of cost & schedule study & not in response to motions to intervene. Syc list enci EWING, T.N. Public Service Co. of Oklahoma, 79/05/14. 2pp.
- 7905240393 Responds to NRC 790501 request for addl info.Util 790430 ltrincluded all available financial info
  EWING,T.N., Public Service Co. of Oklahoma 79/05/14. Rep.
- O Inspection reports: IE Bulletins & correspondence
- 7905180564 Forwards IE Insp Repts 50-356/79-02 & 50-557/79-02 on 790306-09. No noncompliance noted. SEIDLE-M.C. Region 47 Delies: Reactor Construction & Engineering Bupport Branch. 79703/23. 2pp.
- ---7905150570 IE Insp Repts 50-556/77-02 & 50-557/77-02 on 790306-09 No noncompliance noted Major areas inspected const status, development of concrete mix design training & indoctrination & GA, HUBACEK, N. O., CROBEMAN, N. A.: HALL, R. E. Region 4, Dailas, Office of the Director. 79/03/23. 7pp

- DOCKET 50-364 NUCLEAR FUELS RECOVERY & RECYCLE CENTER
- J Insurance & indemnity information
- 7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,177,160,182,185,186,187,188,187,172,179,174,179,177,176,200,201,204,204,204,207,208,210,212,214,215,to thers guattrochti,J American Nuclear Insurers 79/03/01 1p
- 7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22,26,29,38,39,44,46,47,49,50,51,32,53,54,55,56,57,56,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,41,92,93,94,95 & 96
  ROBERTS,D M Mutual Atomic Energy Liability Underwriters 79/05/01
- DOCKET STN-50-966 YELLOW CREEK NUCLEAR PLANT, UNIT 1

  A Application/construction stage documents & correspondence
- 790508054i Discusses util position on leak testing pressure & temp requirements of ACI Stds 318 & 349 for piping to be embedded in concrete Revision to PSAR re embedded piping will be implemented immediately OILLELAND.J E Tennessee Valley Authority 79/05/03 3pp
- Q. Inspection reports, IE Bulletins & correspondence
- 7905010211 Forwards IE Info Notice 79-06. "Stress Analysis of Safety-Related Piping " O'REILLLY,J.P Region 2. Atlanta, Office of the Director 79/03/23 2pp
- 7905030368 Forwards IE Bulletin 79-07. "Seismic Stress Analysis of Safety-Related Piping " Licensee action required O'REILLY.J P Region 2. Atlanta, Office of the Director 79/04/14 dpp
- 7905040233 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "
  O'REILLY, U P Region 2. Atlanta, Office of the Director 79/04/14 3pp.
- 7905110365 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident "O'REILLY.J P Region 2. Atlanta, Office of the Director 79/04/14 ip
- 7905010341 Forwards IE Info Notice 79-10. "Nonconforming Pipe Support Struts."

  O'REILLY,J P Region 2. Atlanta, Office of the Director 79/04/18 1p
- 7905030172 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " Licenses action required D'REILLY,J P Region 2, Atlanta, Office of the Director 79/04/17 20e
- /YOS020479 Forwards IE Bulletin 79-06A.Revision i, "Review of Operational Errors & Bus Misalignments Identified During TMI Incident"

  O'REILLY,J.P Region 2. Atlanta, Office of the Director 79/04/18. 200
- 7903230698 Ack receipt of 790409 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-366/79-04 & 30-367/79-04.

  MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/19 ip
- ---7905230733 Responds to NRC 790315 itr re violations noted in IE Insp. Repts 50-566/79-04 & 50-567/79-04 Corrective actions: concrete cylinder curing tank temp was reaudited & immersion heaters were installed OILLELAND.
- ---7905230740 Forwards IE Insp Repts 50-566/79-04 & 50-567/79-04 on 790220-22 & notice of violation.
  HURPHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/03/15. 2pp.
- ---7905230747 Notice of violation from insp on 790220-22,
  \* Region 2, Atlanta, Office of the Director. 79/03/14. 1p.

- --7905230753 IE Insp Repts 50-566/79-04 & 50-567/79-04 on 790220-22 Noncompliance noted GA audit deficiencies QUUGE.M J Region 2, Atlanta, Office of the Director HERDT.A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/14 opp
- DOCKET SIN-50-967 YELLOW CREEK NUCLEAR PLANT, UNIT 2

  A Application/construction stage documents & correspondence
- 7903080341 Discusses util position on leak testing, pressure & teap requirements of ACI Stds 318 & 349 for piping to be embedded in concrete Revisions to PBAR re embedded piping will be implemented immediately OllLELAND.
- Q Inspection reports, IE Bullatins & correspondence
- 7903010211 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
  O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/23 20a
- 7905030368 Forwards IR Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping " Licensee action required, O'REILLY, P Region 2, Atlanta, Office of the Director 79/04/14 3pp
- 7905040233 Forwards IE Bullstin 79-048, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident " O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14. 3pp
- 7905110365 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Hater Power Reactors Identified During TMI Incident " O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14, 1p
- 7905010341 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts"

  O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/18. 10
- 7905030172 Forwards IE Bulletin 79-09: "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " Licenses action required.

  O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/17. 2pp
- 7905020479 Forwards IE Bulletin 79-06A.Revision 1, "Review of Operational Errors & Bys Misalignments Identified During THI Incident"

  0:REILLY.J P Region 2, Atlanta, Office of the Director 79/04/18 2pp
- 7905230698 Ack receipt of 790409 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-566/79-04 & 50-567/79-04 MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 79/04/19. ip
- --7905230733 Responds to NRC 790315 ltr re violations noted in IE Ens; Repts 50-566/79-04 & 50-567/79-04. Corrective actions: concrete cylinder curing tank temp was reaudited & immersion heaters were installed OILLELAND. J E Tennesses Valley Authority, 79/04/09. 3pp
- --7905230740 Forwards IE Insp Repts 90-566/79-04 & 50-567/79-04 on 790220-22 % notice of violation MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/03/15. 2pp
- ---7905230747 Notice of violation from insp on 790220-22.
  \* Region 2. Atlanta. Office of the Director. 79/03/14 19.
- --7905230753 IE Insp Repts 50-566/79-04 & 50-567/79-04 on 790220-22 Noncompliance noted GA audit deficiencies GDUGE,M J. Region 2, Atlanta, Office of the Director HERDTA R Region 2, Atlanta, Reactor Construction & Engineering Support Brench 79/03/14. 6pp

- DOCKET STN-50-548 NEP NUCLEAR, UNIT 1
- esnebnogeerros profesibulbA ©
- 7905240641 Changes issuance date for DES to early May 1979 CUTCHIN, J M Branch 3 79/04/12 1p
- 7903240940 Hithdraws appearance on behalf of intervenor Concerned Citizens of RI.effective 790402 Certificate of Svc ancl COLLINS.C 0 Affiliation Unknown 79/04/13 App.
- I Financial information
- 7705250240 Notifies of denial of request to withhold from public disclosure.Revision 3 to general & financial info section of license application Forwards BEC ltr PARR.O D Light Water Reactors Branch 3 77/03/12 4pp
- ---7905250245 Responds to NRC 780807 ltr re public availability of financial info submitted for license application Bubmission of financial info for public disclosure does not contravene SEC requirements
  CODK, J R Becurities & Exchange Commission 78/12/14 3pp
- DOCKET STN-50-569 NEP Nuclear, Unit 2
  A Application/construction stage
- 7905240641 Changes issuance date for DEG to early May 1979 CUTCHIN:J M Branch 3 79/04/12 1p.
- 7905240940 Withdraws appearance on behalf of intervenor Concerned Citizens of RI. offective 790402. Certificate of Svc encl COLLINS. C. O Affiliation Unknown 79/04/13. App
- 7905280240 Notifies of denial of request to withhold from public disclosure. Revision 3 to general & financial info section of license application Forwards SEC ltr PARR.O b Light Water Reactors Branch 3 79/03/12 4pp
- --7905250243 Responds to NRC 780809 ltr re public evailability of financial info submitted for license application Submission of financial info for public disclosure does not contravene SEC requirements

  GOOKJ R Securities & Exchange Commission. 78/12/14 3pp
- DOCKET STN-50-574 BAGNAC NUCLEAR FOWER PROJECT
- Q Adjudicatory correspondence
- 7905240168 Opposes licensing of proposed Hestinghouse nuclear power plant in Philippines
  AIN,F P. Another Mother for Peace. 78/10/31 1p
- 7905150235 Requests denial of nuclear reactor export license to Philippines Reactor design is unsafe; sited on sarthquake fault-near four active volcances & in tidal wave zone, thus geografizing US soldier nearby HURLEY, J Nautilus Alliance 78/11/26. 1p
- DOCKET STN-50-580 ERIE NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 7703150783 Forwards request for add1 info to continue review of CP application REGANWH Environmental Projects Branch 2. 79/04/06. 17pp.
- 7903240936 Requests add1 info re new mgt organization to be incorporated into PBAR Amend 21, PAER.R.L Light Water Reactors Branch 2, 79/04/30, 3pp.
- O. Adjudicatory correspondence
- 7905160163 Forwards Board Notification 79-10 on reactor inspector Concerns re B&W plants, Certificate of Byc encl. SCINTO, J. P. Hearings Division, 79/03/29, 14pp.
- 7700010115 Forwards request for Board notification re nonsafety-grade equipment to mitigate transients.

  BCINTO, J. F. Hearings Division 79/04/02 3tpp.
- --7903010156 Board notification staff assessment re nonsafety-grade equipment to mitigate transients VASSALLO, D. B. Assistant Director for Light Water Reactors. 79/03/29. 2pp.

- ---7903010198 Board notification recent issue on nonsefety-grade equipment to mitigate transients More info is required TEDEBCO,R L Assistant Director for Reactor Safety 79/03/16.
- 7905160112 Board notification nuclear incident at TMI Recommends boards on cases involving BMH reactors be provided w/IE Bulletin 79-05 & PNO-67 & 67A.B.C.D.E.F.Q & H VASBALLO.D B Assistant Director for Light Hater Reactors, 79/04/03 2pp
- 7905070225 Forwards memos re problems of pipe support base plate design.
  BARTH, G A Branch 3 79/04/05 21pp
- 7905080377 Informs that NRC has recently discovered document possibly relevant to sebotage of spent fuel Info is classified & may never be published in final form Forwards TF Carter 790122 memo Info assessment will follow when available BARTH, C. A Brench 3 79/04/08 2pp
- 7905130AB3 Forwards aspects of PHR accumulator delivery to ECC8 performance characteristics BARTH, C A. Branch 3 79/04/05 5pp.
- S Reportable occurrences. LERs & related correspondence
- 7905110203 Board notification Seabrook refueling water storage tank design deficiency BCINTO. J Hearings Division 79/03/29 30pp
- DOCKET STN-50-591 ERIE NUCLEAR PLANT, UNIT 2
- A. Application/construction stage documents & correspondence
- 7905150783 Forwards request for add1 info to continue review of CP application REGAN, W H Environmental Projects Branch 2. 79/04/06 17pp
- 7905240936 Requests add1 info re new mgt organization to be incorporated into FBAR Amend 21.
   BAER.R.L Light Water Reactors Branch 2 79/04/30 3pp.
- 7905160163 Forwards Board Notification 79-10 on reactor inspector concerns re 854 plants Certificate of Eyc encl BCINTO.J.F Hearings Division 79/03/29, 14pp
- 7905010115 Forwards request for Board notification re nonsafety-grade equipment to mitigate transients
  SCINTO.J F. Hearings Division. 79/04/02. Sipp.
- ---7905010156 Board notification staff assessment re nonsafety-grade aquipment to mitigate transients VASSALLO,D B. Assistant Director for Light Water Reactors. 79/03/29 2pp.
- --7905010198 Board notification: recent issue on nonsefety-grade equipment to mitigate transients. More info is required TEDESCO.R.L. Assistant Director for Reactor Safety. 79/03/16 Spp.
- 7905;601;2 Board notification: nuclear incident at TMI. Recommends boards on cases involving BSW reactors be provided w/IE Bulletin 79-05 & PND-67 & 67A.B.C.D.E.F.G & H. VASSALLO.D B Assistant Director for Light Water Reactors. 79/04/03. 2pp
- 7905070225 Forwards memos re problems of pipe support base plate design.
  RARTH.G.A Branch G. 79/04/05 Zipp.
- 79030B0377 Informs that NRC has recently discovered document possibly relevant to sebotage of spent fuel Info is classified & may never be published in final form Forwards TF Carter 790122 memo. Info assessment will follow when available.

  BARTH, C A Branch 3, 79/04/05 2pp
- 7905130685 Forwards aspects of PWR accumulator delivery re ECCB performance characteristics.

  BARTH, C. A. Brench 3 79/04/05 Spp.
- 8 Reportable occurrences, LERs & related correspondence
- 7905110203 Board notification. Seabrook refusiing water storage tank design deficiency.
  BCINTQLJ. Hearings Division, 79/03/29 30pp.

- DOCKET STN-50-584 GIBBSAR, GIBBS & HILL
- A. Application/construction stage documents & correspondence
- 7903100117 Forwards first round requests for add1 info to complete review of OIBBSAR Also forwards G-1's & G-2's for purpose of completing formal record of review
  MELITEMES, C J Standardization Branch 79/04/27 53pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 7905090272 Forwards Amend 13 to GIBBSSAR BDPSSAR, referencing REBAR-414 Includes responses to NRC Questions 032 B-032 32, except 032 15 & 032 27 Affidavit encl PRIETO, R Gibbs & Hill, Inc. (subs. of Drave Corp.) 79/05/04
- --7905090274 Amend 13 to GIBBSSAR BDPSSAR referencing RESAR-414 \* Gibbs & Hill, Inc (subs of Dravo Corp.) 79/05/04 175pp.
- 7905230432 Forwards Amend 14 to BDPSSAR.including responses to NRC questions Table 6 219 reissued in amend, due to preproduction error in Amend 13 PRIETO, R 9(bbs & Hill, Inc. (subs. of Dravo Corp.) 79/05/18
- --7905230435 Amend 14 to BUPSGAR
  # Gibbs 5 Hill, Inc (subs of Dravo Corp.) 79/05/18 134pp
- DOCKET STN-50-892 PALO VERDE NUCLEAR STATION, UNIT 4
- A Application/construction stage documents & correspondence
- 79050203:6 Act 790405 telcon & canfirms 790426 meeting in Los Angeles. CA COLDBERG.J R Anti-Trust Division 79/04/05 is
- 7903240218 Details chronology for period from BAR docketing through issuance of SER STRIGHT, R L Light Water Reactors Branch 3 79/04/09, 4pp
- 7905090180 Summary of 790329 & 0406 meetings w/util.consuitants & ACRS in Phoenix.AZ & Hashington.DC.respectively.re replication of CP for addl units
  LICITRA.E A Light Water Reactors Brench 3 79/04/13 3pp
- 790310378 Forwards info re plant seepage analysis, consisting of listing of "Bimulation Conditins & Assumptions for Predictive Model Presented in PSAR Section 2 4, 13 i 2" & matrix table on sensitivity of seepage model VAN BRUNT,EE Arizona Public Service Co 79/05/17 5pp
- D. NRC Draft/Final Environmental Statements, supple & correspondence
- 7905220058 Forwards DES for review W/o encl.
  REGAN: W. H Environmental Projects Branch 2 79/04/12 2pp.
- 7905090345 Submits no comments on DES.

  BARROWS,H.L. Agriculture, Dept of, 79/05/03 ip Available at NRC
- 7905240598 Requests 30-day extension of comment period for DES URBAN.M California, State of. 79/05/14. 1p
- 7905310349 Comments on DES.discusses soil surveys drainage areas & pH organic matter content & texture of soils.
  ROCKENBAUOH.T. Agriculture.Dept. of. 79/05/23 ip
- 7705310422 No comments on DES DILLABOUGH, N. Transportation, Dapt of 79/05/24 lp.
- Q. Adjudicatory correspondence

 $\mathbf{t}_{i,1}^{t}$ 

''انانا

- 7905150127 NRC response to amended contention of L. Bard, Opposes admission of contentions re transportation of spent fuel, as issue in controversy, Certificate of Svc encl. BOHINKI,S H Branch G. 79/03/21 7pp.
- 7905090178 Palo Verde Nuclear Intervenors' petition to intervene is defective for untimeliness & lack of standing Denies patition but grants intervenors opportunity to cure defects by filing amended patition within ten days.

  LAZO, R. M. Atomic Bafety and Licensing Board Panel 79/03/22 7pp.

- 7905100332 Amended patition for co-intervention filed in response to NRC 790306 response to first petition for co-intervention if granted co-intervenor status. will consolidate \( \omega/L\) Bard RHODEG.L., DANIELSON.T., FULLINWIDER.S P Palo Verde Nuclear Intervenors 79/03/27 3pp
- 7905100002 Joint applicants' response to undated third amended contention of L Bard Submits that Bard failed to file an admissible contention on transportation of hazardous matis Suggests that contentions be limited to 790211 order. QEHR, A.C., BISCHOFF, C.A. Sneil & Wilmer 79/03/30 Spp.
- 7905220061 Requests development of nuclear power in US be stopped for take of safety
  JOSEPH.P Affiliation Unknown 79/04/05 1p
- 790515074B Forwards NRC rept, "Inquiry inquiry into Allegation of Employee Misconduct by Restricting Investigation to Determine Reliability of Power Orid Serving St Lucie " SOHINKI.S M Branch 3 79/04/11 ip
- 7905300537 Discusses evaluation of new info re C-E flow blockage model for ECCS in order to determine sys design conformance to requirements of App K.10CFR50 46
  SOHINKILS M Branch 3 79704/11 2pp
- 7905240133 Forwards DES for facility W/o encl SOHINKI.S M Branch 3 79/04/17 2pp
- # General correspondence
- 7905240502 Confirms agreement to meet w/recipient & E Ross in Anahale: GA on 790425 GDLDBERG.J.R. Anti-Trust Division 79/04/10 ip.
- I Financial information
- 7905300616 Requests add1 info re ownership, sources of funds & annual repts to complete financial review Previous responses. dtd 790111 & 790405, have not been adequate PARR. D D Light Water Reactors Branch 3 79/04/23. Spp
- 7905150282 Forwards addl financial info Info withheid(ref 100FR2 790) JOHNSON, W J El Paso Electric Co. 79/04/26 2pp
- 7908090085 Forwards "Sources of Funds for Bys Wide Const Expenditures During Period of Const of Bub; Nuclear Plant," w/application to withhold document & affidavit of R Korpan Proprietary info withhold (ref 100FR2 790) MASTER.V P San Diego Gas & Electric Co 79/03/03. 3pp
- 7905300287 Forwards "Addendum 2 to General Financial Info "
  VAN BRUNT,E E Arizona Public Service Co 79/05/23 3ee,
- ---7905300292 "Addendum 2 to General Financial Info."

  \* Arizona Public Service Co 79/05/23, 600pp
- DOCKET STN-50-593 PALG VERDE NUCLEAR STATION, UNIT 5

  A. Application/construction stage documents & correspondence
- 7905020316 Ack 790405 telcon & confirms 790426 meeting in Los Angeles. CA GDLDBERG, J. R. Anti-Trust Division 79/04/05 ip
- 7905240218 Details chronology for period from SAR docketing through issuance of SER.

  BTRIGHT, R. L. Light Water Reactors Branch 3. 79/04/09. 43p
- 7905090180 Summary of 790329 & 0406 meetings w/util.consultants & ACRS in Phoenix. AZ & Washington, DC, respectively, re-replication of CP for add1 units
  LICITRA.E.A Light Water Reactors Branch 3. 79/04/13. 3pp
- 7903310378 Forwards info re plant seepage analysis, consisting of listing of "Simulation Conditins & Assumptions for Predictive Model Presented in PBAR Section 2 4.13.1, 2" & matrix table on sensitivity of seepage model. VAN BRUNT.E.E. Arizona Public Service Go. 79/05/17. Spp

- D NRC Draft/Final Environmental Statements, supple & correspondence
- 7705220058 Forwards DES for review H/o encl REGAN, H. H Environmental Projects Branch 2, 79/04/12 2pp
- 7905090345 Submits no comments on DES
  BARROWS.H L Agriculture.Dept of 79/05/03 ip Available at NRC
- 7705240598 Requests 30-day extension of comment period for DES URBAN, M California, State of 79/05/14 1p
- 7903310349 Comments on DES discusses soil surveys drainage areas & pH organic matter content & texture of soils
  ROCKENBAUGH.T Agriculture, Dept of, 79/05/23, ip
- 7903310422 No comments on DES
  DILLABOUGH: N Transportation, Dept of 79/05/24 ip.
- O Adjudicatory correspondence
- 7905150127 NRC response to amended contention of L Bard Opposes Admission of contentions re transportation of spent fuel, as issue in controversy Certificate of Byc encl BOHINKIIS M Branch 3 79/03/21 7pp
- 7905070178 Palo Verde Nuclear Intervenors' petition to intervene is defective for untimeliness & lack of standing Denies petition but grants intervenors opportunity to cure defects by filling amended petition within ten days LAIO,R H Atomic Bafety and Licensing Board Panel. 79/03/22 7pp
- 7905100332 Amended petition for co-intervention filed in response to NRC 790306 response to first petition for co-intervention If granted co-intervenor status, will consolidate w/L Bard RHODEG.L., DANIELSON, T., FULLINHIDER.B P Palo Varde Nuclear Intervenors, 79/03/27. 3pp
- 7705100002 Joint applicants' response to undated third amended contention of L Bard Submits that Bard failed to file an addisable contention on transportation of hazardous matts Suggests that contentions be limited to 770211 order OEHR, A C , BISCHOFF, C A Snell & Wilmer 79/03/30 Spp.
- 7905220061 Requests development of nuclear power in U8 be stopped for sake of safety
  JOSEPH.P. Affiliation Unknown 79/04/05, 1p.
- 7903150748 Forwards NRC rept, "Inquiry inquiry into Allegation of Employee Misconduct by Restricting Investigation to Determine Reliability of Power Orid Serving St Lucie "SCHIRKIS M Branch 3 79/04/11 ip
- 7905300537 Discusses evaluation of new info re C-E flow blockage model for ECCS in order to determine sys design conformance to requirements of App K.10CFRO 46
  EONINKI.B M Branch 3. 79/04/11 2pp
- 7705240133 Forwards DES for facility W/o encl SOHINKI.S M. Branch 3, 79/04/17, 2pp
- H. General correspondence
- 790340502 Confirms agreement to meet w/recipient & E Ross in Anaheim. CA on 790425 GOLDBERG, J R. Anti-Trust Division. 79/04/10. ip.
- I. Financial information
- 7905300&16 Requests add1 info re ownership; sources of funds & annual rapts to complete financial review Frevious responses, dtd 790111 & 790405, have not been adequate, PARR: O. D. Light Water Reactors Branch 3, 79/04/23
- 7705150282 Forwards add1 financial info. Info withheld(ref 10CFR2.790). JOHNBON, W. J. El Paso Electric Co. 79/04/26. 2pp.
- 7705090085 Forwards "Bources of Funds for Bys Wide Const Expenditures During Period of Const of Bubj Nuclear Plant;" w/application to withhold document & affidavit of R Korpan. Proprietary info withhold (ref 10CFR2,790). MASTER, V.P. Ban Diego Qas & Electric Co. 79/05/03. 3pp.
- 7705300287 Forwards "Addendum 2 to General Financial Info." VAN BRUNT, E.E. Arizona Public Service Co. 77/05/23. 3pp.

- ---7905300272 "Addendum 2 to General Financial Info "
  # Arizona Public Service Co 79/05/23 600pp.
- DOCKET STN-50-596 NEW HAVEN, UNIT 1
- A. Application/construction stage documents & correspondence
- 7905290053 Forwards requested R8 Boyd 790119 ltr to A Kintigh re alternate site analysis W/o encl. BWANSON,D.T Branch 1 79/03/28 ip
- 7903010664 Forwards proposed schedule for radiological safety review 80YD.R S Division of Project Management 79/04/13 3pp
- 7905020390 In response to 790327 ltr.forwards signed agreements for technical support in review of facility
  DEYOUNG.R C Division of Site Bafety & Environmental Analysis
  79/04/13 2pp
- 7905070070 Requests addl info for completion of PSAR review Matl concerns discrepancy in participation of operator license candidates in similator training course COLLING:P F Operator Licensing Branch 79/04/13 2pp
- 790503030 Comments on "Federal-State Authorities & Cooperation in Nuclear Power Plant Licensing", outlines changes to NY siting law & attempts to eliminate duplication of regulatory processes between federal & state agencies
  BMGLINEKY, J New York State of 79/04/24. 2pp
- 7905230837 Informs of establishment of schedule for radiological safety review of application for CP Estimates prospective decision date to be 810708 BOYD.R S. Division of Project Management 79/04/24 4pp
- 7905250107 Notification of 790508 meeting w/util:NY state representatives & ANL in Mexico.NY to acquent local residents w/status on environ review SELLE,D E. Environmental Projects Branch 2. 79/04/24 2pp
- 7905010494 Ferwards "1978 Hudson River Shortnose Sturgeon Study, Scope of Work." RAY.M.J. New York State Electric & Gas Corp. 79/04/25 22pp.
- 7905290066 Requests additinfo in order to continue evaluation of PBAR Specific info requested concerns areas of containment sys, afficient treatment sys, radiological assessment geology & seignology & operator training.

  PARR.O.D. Light Water Reactors Branch 3. 79/04/27 15pp.
- 7905310464 Forwards previously omitted page from 790427 ltr re-Questions 361.24 & 361.25, PARR.O.D. Light Water Reactors Branch S. 79/05/03, 3pp.
- 7905220120 Responds to 790427 ltr requesting add1 info Info will be submitted as PBAR amend by mid-July, KINTIOH.A.E New York Etate Electric & Oap Corp 79/05/14 ip
- B. Utility Preliminary Safety Analysis Report, amends
- 7905310342 Forwards affidavit of svc for Amend 3 to PBAR & CP application Kintloh,A.E. New York State Electric & Oas Corp. 79/05/16. App.
- C. Utility Environmental Report (ER), amends & correspondence
- 7905070316 Requests add1 info re analysis of cooling tower & thermal discharge, Amend to environ rept containing responses to encl questions should be submitted by 790615 in order to continue environ review.

  REGAN, H. H. Environmental Projects Branch 2. 79/04/23 4pp.
- 7903070467 Requests extension to file preliminary draft of first chapters of environ statement.

  8HOLINSKY, J. New York, State of. 79/04/26 2pp.
- 7905300477 Amend 2 to environ rept.
  KINTIGH, A. E. New York State Electric & Que Corp. 79/05/24. 303pp.
- 0. Adjudicatory correspondence
- 7905250353 Petitions to intervene in proceeding Asserts health & safety will be adversely affected by plant.
  MEBER, 8., DALY, M. Ecology Action of Oswego. 79/03/08. Spp.

- 7905240098 Patition to intervene, submitted by Columbia County, NY, Town of Studyesant, NY & Concerned Citizens for Safe Energy. Inc. KAFIN:R J Kafin:R. J 79/03/12 2pp
- --7905240106 Supports petition to intervens submitted by Columbia County, NY. Town of Beugvestant, NY & Concerned Citizens for Safe Energy, Inc Notice of appearance & Certificate of Svc encl KAFIN, R J KAFIN, R J 79/03/12. 10pp
- 7905250350 Petitions to intervene in proceeding Asserts health & safety will be adversely affected by plant CLARK.L Safe Energy for New Haven 79/03/16 3pp
- 7905230409 Kid-Hudson Nuclear Opponents' patition to intervene as full party re alternate site considerations, need for facility, financial qualifications of applicants & cost of proposed plant BROWN,P D Mid-Hudson Nuclear Opponents, Inc. 79/03/19 3pp.
- 7905250365 Notice of appearance on behalf of util BCHUTT,R , ZEBRAK,I L Huber, Maglil, Lawrence & Farrell 79/03/20
- ---7905250370 Answer to intervention petitions of various groups, including NY State Energy Ofc. Oswego County Farm Bureau. Ecology Action & Safe Energy for New Haven. Certificate of Svc encl SCHUTT, R. ZEBRAK, I L. Ruber, Magill. Lawrence & Farrell 79/03/20 Spp
- 7905100178 Response to petitions to intervene filed in Columbia/Ulster County area during Mar 1977 Intervenors failed to establish standing petitions should be denied.
  Certificate of Svc encl SWANSON D T Branch 1 79/04/02
- 7905240160 Answer seeking denial of 790319 patition to intervene filed by Mid-Hudson Nuclear Opponents, Inc Certificate of Svc encl SCHUTT, R. ZEBRAK, I E New York State Electric & Qas 79/04/03 650
- 7905150266 Forwards first set of interrogatories to util from NY Bt Dept of Environ Conservation ENGEL.D A New York, State of 79/04/04 ip
- ---7905150271 First set of interrogatories for util from NY St Dept of Environ Conservation \* New York, State of 79/04/04 Spp
- 7905150164 Requests copy of 790402 "NRC Answer to Petitions to Intervene Filed in Columbia/Ulster County Area " ZEBRAK, I, L. Huber, Megili, Lawrence & Farrell 79/04/06 2pp.
- 7905240148 Requests leave to intervene in proceedings re selection of alternate sites. Protests previous denial of intervenor status.

  KEEPING. W. Gardiner, NV. 79/04/12 ip

# H. General correspondence

- 7905230347 Notice to all parties & interested persons to send documents for W Jordan to 881 West Outer Drive, Oak Ridge, TN WENNER, 8 Atomic Safety and Licensing Board Panel, 79/04/20. ip
- 7705i50ii5 Forwards info requested in 770i3i itr re nuclear reactor const for utils & schools REGAN.W.H. Environmental Projects Branch 2 77/04/30 5pp

### DOCKET BIN-50-597 NEW HAVEN, UNIT 2

- A. Application/construction stage documents & correspondence
- 7905290053 Forwards requested RB Boud 790119 itr to A Kintigh re alternate site analysis W/o encl, SHANSON: D T Brench 1 79/03/28. 1p
- 7705010664 Forwards proposed schedule for radiological safety review SOYD, R. S. Division of Project Hanagement. 79/04/13, Spp.
- 7905020390 In response to 790327 itr.forwards signed agreements for technical support in raylew of facility.

  DEYOUNG, R.C. Division of Site Safety & Environmental Analysis 79704/13. 2pp.
- 7905070070 Requests add1 info for completion of PSAR review. Mat1 concerns discrepancy in participation of operator license candidates in similator training course.

  COLLINS.P.F. Operator Licensing Branch, 79/04/13. 2pp.

- 7905030350 Comments on "Federal-State Authorities & Cooperation in Nuclear Power Plant Licensing" outlines changes to NY siting law & attempts to eliminate duplication of regulatory processes between federal & state agencies SMOLINSKY, J New York, State of. 79/04/24, 2pp
- 7705230837 Informs of establishment of schedule for radiological salety review of application for CP Estimates prospective decision date to be 810708

  BDYD.R 8 Division of Project Management 79/04/24 4pp
- 7903230107 Notification of 790308 meeting w/util,NY state representatives & ANL in Mexico.NY to acquant local residents w/status on environ review SELLE.D E Environmental Projects Branch 2 79/04/24. 2pp
- 7905010494 Forwards "1978 Hudson River Bhortnose Sturgeon Study, Boope of Work "
  RAY, M J New York State Electric & Qas Corp 79/04/25 22pp
- 7905290066 Requests add1 info in order to continue evaluation of PSAR Specific info requested concerns areas of containment sys. effluent treatment sys.radiological assessment, geology & seismology & operator treatming PARR.O.D Light Water Reactors Branch 3 79/04/27 15pp.
- 7905310464 Forwards previously emitted page from 790427 ltr re Questions 361 24 & 361 25 PARR:0 D Light Hater Reactors Branch 3 79/05/03 3pp
- 7903220120 Responds to 790427 itr requesting add1 in#a Infa will be submitted as PBAR amend by mid-July KINTIGH:A E New York State Electric & Gas Corp 79/05/14 1p
- B. Utility Preliminary Safety Analysis Report, amends
- 7905310342 Forwards affidavit of svc for Amend 3 to PSAR & CP application KINTIONIA E. New York State Electric & Oas Corp. 79/05/16, 4pp
- C 'Utility Environmental Report (ER), amends & correspondence
- 7903070316 Requests add1 info re analysis of cooling tower & thermal discharge Amend to environ rept containing responses to encl questions should be submitted by 790615 in order to continue environ review REGAN.W.H. Environmental Projects Branch 2 79/04/23. App
- 7905070467 Requests extension to file preliminary draft of first chapters of environ statement.

  8MGLINSKY, J New York, State of 79/04/26. 2pp.
- 7905300477 Amend 2 to environ rept.
  KINTIGH.A E New York State Electric & Gas Corp 79/05/24. 303pg
- Q Adjudicatory correspondence :
- 7905250353 Petitions to intervene in proceeding. Asserts health & safety will be adversely affected by plant.
  MEBER, 8., DALY.H. Ecology Action of Oswego. 79/03/08 3pp
- 7905240098 Petition to intervens submitted by Columbia County, NY, Fown of Stuyvasant, NY & Concernad Citizens for Safe Energy, Inc. KAFIN:R. J. Kafin:R J 79/03/12, 2pp.
- --7905240106 Supports petition to intervene submitted by Golumbia Counts, NY, Town of Stuyvesant, NY & Concerned Citizens for Safe Energy, Inc. Notice of appearance & Certificate of Svc encl. KAFIN.R. J. Kafin.R J. 79703/12 10pp.
- 7905250350 Petitions to intervene in proceeding Asserts health & safety will be adversely affected by plant.
  CLARK, L. Safe Energy for New Haven. 79/03/16 Spp.
- 7905230409 Mid-Hudson Nuclear Opponents' patition to intervens as full party re alternate site considerations, need for facility, financial qualifications of applicants & cost of proposed plant.

  BROWN, P. D. Mid-Hudson Nuclear Opponents, Inc. 79/03/19 Spp
- 7905250365 Notice of appearance on behalf of util.
  BCHUTT,R.: ZEBRAK,I.L. Huber, Magill, Lawrence & Farrell. 79/03/20

- --7905250370 Answer to intervention petitions of Various groups, including NY State Energy Ofc, Oswego County Farm Bureau, Ecology Action abservation data for 760801-770731, in response to RC Before the New Haven Certificate of Svc encl Schuff, R. ZeBRAK, I. L. Huber, Magili, Lawrence & Farrell MAUGHTON, W. F. Commonwealth Edison Co. 79/05/07, 7pp
- 7905100178 Response to petitions to intervene filed in Columbia/Ulster County area during Mar 1979 Intervenors falled to establish standing petitions should be denied Certificate of 8vc encl.

  SHANSON, D T Branch 1, 79/04/02 12PP
- 7905240160 Answer seeking denial of 790319 patition to intervane filed by Mid-Rudson Nuclear Opponents, Inc Certificate of Svc encl SCHUTT.R., ZEBRAK, I E. New York State Electric & Qas. 79/04/03
- 7905130266 Forwards first set of interrogatories to util from NY St Dept of Environ Conservation ENGEL.D A New York, State of 79/04/04 ip
- --7905150271 First set of interrogetories for util from NY St Dept of Environ Conservation.

  New York: State of 79/04/04 8sp
- 7905150164 Requests copy of 790402 "NRG Answer to Petitions to Intervene Filed in Columbia/Ulster County Area " IEBRAK, I.L. Huber, Magill, Lawrence & Farrell 79/04/06. 2pp.
- 7905240148 Requests leave to intervene in proceedings re selection of alternate sites Protests previous denial of intervenor KEEPING.W Gardiner, NY. 79/04/12 1p
- H General correspondence
- 7905250347 Notice to all parties & interested persons to send documents for W Jordan to 881 West Outer Drive. Oak Ridge, TN WERNER, S., Atomic Safety and Licensing Board Panel 79/04/20. 1p.
- 7905150115 Forwards info requested in 790131 ltr re nuclear reactor const for utils & schools
  REÇAN, H H Environmental Projects Branch 2 79/04/30 5pp
- DOCKET 50-0598 NORTHWESTERN UNIV
- A Application/construction stage documents & correspondence
- 7905170243 Requests that application for CP & OL for Model AGN-201. Serial 114, nuclear reactor be withdrawn STROTZ.R H Northwestern Univ 79/05/15 ip.
- DOCKET 50-599 CARROLL FACILITY I
- A Application/construction stage documents & correspondence
- 7705150759 Notification of 770509 meeting w/util in Bethesda, MD for pretendering discussions involving certain NRC branches Instrumentation & Control Reactor Sys Core Performance & Amaiysis & Containment Sys BIRKEL.R A Light Water Reactors Branch 2, 79/04/26 2pp
- 7903230091 Notification of 790502 meeting w/util.ANL.EPA.DQI & Corps of Engineers in Bavanna.IL to discuss environ issues related to NRC licensing review HAUPT.C.A Environmental Projects Branch 1. 79/04/26 ip
- 7905090360 Forwards "Site Investigations of Areas Along MS & Lower IL Rivers," Aug 1974, "Eric Sits Geotechnical Evaluation."
  'May 1975, "Preliminary Site Evaluation.La Salle & Putnam Counties, IL," 771201 W.O encl.
  NAUGHTON.H.F Commonwealth Edison Co 79/05/07. 2pp.
- 7903170246 Forwards repts in response to NRC 790404 ltr resite investigations & evaluations for areas along MB & lower IL. rivers.Erie Site. Oladations North & Rozetta Mest site. @uef-Cties. Lasslie & Putham Counties. IL sites M/o enci. NAUGHTON, H F Commonwealth Edison Co. 79/03/07. 2pp
- 7905240914 Forwards FR natice rs CP application for info.due to proximity of proposed site to WI state border.W/o encl.
  BALLARD.R L. Environmental Projects Branch 1. 79/05/07 1p.
- 7705240919 Forwards FR notice of CP application for info H/o enci BALLARD, R L. Environmental Projects Branch 1, 79/05/07 1
- 7905240926 Forwards FR notice re CP application for info. due to proximity of site to IA state border. W/o encl BALLARD.R.L. Environmental Projects Branch 1 79/05/07. 1p.
- 7905240966 Requests comments on site suitability environ rept by 790903, BALLARD, R. L. Environmental Projects Branch 1. 79/05/08. 4pp.

- 7905176264 Notification that USGS quadrangle maps have been forwarded under separate cover, in response to first part of Question 361.4 MAUGHTON, W.F. Commonwealth Edison Co. 79/03/11 4pp
- 7705220102 Forwards Amend 1 to application for CP & early site review. REED, C Commonwealth Edison Co 77/05/18 1p.
- ~-7905220107 Amend 1 to application for CP & early site review Amend comprises util responses to NRC questions re site suitability generated during early site review acceptance # Commonwealth Edison Co 79/05/18 630pp
- 7905310393 Forwards affidevit certifying 790523 distribution of site suitability/site safety rapt. Amend i NAUGHTON, H F Commonwealth Edison Co 79/05/25 2pp
- O Adjudicatory correspondence
- 7905180260 Notice of hearing re request for early site review & CP CHILK.S J Office of the Secretary of the Commission 77/05/01
- DOCKET 50-600 CARROLL FACILITY II
- A Application/construction stage documents & correspondence
- 7905150759 Notification of 790509 meeting w/util in Bethesda.MD for pretendering discussions involving certain NRC branches: Instrumentation & Control.Reactor Bys Core Performance & Analysis & Containment Bys BIRKEL,R A Light Water Reactors Branch 2. 79/04/26. 2pp
- 7905250071 Notification of 770502 meeting w/util.ANL.EPA.DOI & Corps of Engineers in Savanna.IL to discuss environ issues related to NRC licensing review HAUPT.C.A Environmental Projects Branch 1 79/04/26. 1p.
- 7905090340 Forwards "Site Investigations of Areas Along MS & Lower IL Rivers," Aug 1974, "Erie Site Geotechnical Evaluation," May 1975, "Praliminary Site Evaluation, La Saile & Putnam Counties, IL." 771201. W.C. anci. NAUGHTON, M.F. Commonwealth Edison Co. 79/05/07, 2pp.
- 7905170246 Forwards repts in response to NRC 790404 ltr re site investigations & evaluations for areas along MS & lower IL rivers.Eric Site Oladstone North & Rosetta West site. Quad-Cities.Lasalle & Putham Counties.IL sites.Wo ancl. NAUGHTON.W F Commonwealth Edison Co 79/05/07. 2pp.
- 7905240914 Forwards FR notice re CP application for info, due to proximity of proposed site to WI state border W/o encl.
  8ALLARD, R. L. Environmental Projects Branch 1. 79/05/07. ip.
- 7905240919 Forwards FR notice re CP application for info. W/o encl BALLARD, R. L Environmental Projects Branch 1 79/05/07. 1
- 7903240926 Forwards FR notice we CP application for info.due to proximity of site to IA state border. H/o encl BALLARD, R. L. Environmental Projects Branch 1 79/05/07. ip
- 7905240966 Requests comments on site suitability environ rept by Environmental Projects Branch 1. 79/05/08 4pp.
- 7905240664 Forwards magnetic tape containing hourly meteorological observation data for 760801-770731; in response to RC Beyoung, 790404 request NAUOHTON.W F Commonwealth Edison Co 79/05/09. 7pp.
- 7905:70264 Notification that USOS quadrangle maps have been forwarded under separate cover in response to first part of Question 361.4 NAUGHTON.W.F. Commonwealth Edison Co. 79/05/11. 4pp.
- 7905220102 Forwards Amend 1 to application for CP & early site review REED.C. Commonwealth Edison Co. 79/05/18 1p
- --7905220107 Amend 1 to application for GP & early site review. Amend comprises util responses to NRC questions re site suitability generated during early site review acceptance. # Communication Co. 79705/18. 650pp.

- 7905310373 Forwards affidavit certifying 790523 distribution of site suitability/site safety rept.Amend 1 NAUGHTON.W F Commonwealth Edison Co 79/05/25 25p
- G Adjudicatory correspondence
- 7905150260 Notice of hearing re request for early site review & CP CHILK'S J Office of the Secretary of the Commission 79/05/01

### **DOMESTIC LICENSING OF SPECIAL NUCLEAR MATERIAL**

DOCKET 70-0008 Battelle Columbus Laboratories

- 7905150814 Forwards "Site Security Personnel Training Plan for Facility " Encl withheld (seef 10CFR2 790) TOY.H L. Battelle Hemorial Institute. Columbus Laboratories 79/02/20 2pp
- 7905010191 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Syc Air Sys Used as Source of Breathing Air "

  KEPPLER. J Q Region 3, Chicano, Office of the Director 79/03/28
- 7709150790 Forwards 790908 itr requesting fee for review of security training & qualification plan Requests fee be forwarded within 15 days M/o encl HCISS.D License Fee Management Branch 79/04/24 ip

DOCKET 70-0025 ROCKWELL INTERNATIONAL CORP

7905010239 Forwards IE Info Notice 79-08. "Interconnection of Contaminated Sys w/Syc Air Sys Used as Source of Breathing Air "
ENGELKEN.R.H Region 5. San Francisco. Office of the Director 79/07/28 10

DOCKET 70-0027 BABCOCK & WILCOX CO

- 7905040105 Ack receipt of 790323 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0027/79-02 KENNA:W B. Region 2. Atlanta, Safeguards Branch 79/04/03 Ip
- --7905040114 Responds to NRC 790309 ltr re violations noted in IE Insp. Rept 70-0027/79-02 Corrective actions withheld (ref t005R2, 790).
  EWING. J. F. Babcock & Wilson Co. 29/03/23 in
- ---790504011B Forwards IE Insp Rept 70-0027/79-02 on 790213-16 Notice of violation withheld (ref 100FR2 790)

  KENNA.W. B Region 2: Atlanta. Bafeguards Branch 79/03/09

  2pp
  - IE Insp Rept 70-0027/79-02 on 790213-16. Noncompliance noted o include weight measurements of fabrication esidues in limit of error calculations. Details (ref 10CFR2, 790)
    Region 2. Atlanta, Office of the Director H. Region 2. Atlanta, Safeguards Branch 79/03/09

ntus of efforts to develop new LEMUF model 1701 including additime required to or validation Procedural mode will 0101 Wilcox Co 79/04/23 ip.

DUCKEY 70-0033 TEXAS INSTRUMENTS, INC.

- 7905230277 Forwards IE Insp Rept 70-0033/79-02 on 790220-22 No noncompliance noted HARTIN:W G. Region i: Philadelphia: Safeguards Branch 79/03/14 2pp.
- --7905230288 IE Insp Rept 70-0033/79-02 on 790220-22 No noncompliance noted Major areas inspected physical inventory verification, & measurement & statistical control of nuclear meth. Details withheld (ref 10CFR2 790).

  ZIBULSKY, H., COMEN, I. Region 1, Philadelphia, Office of the Director JOYNER, J. H. Region 1, Philadelphia, Safeguards Branch. 79/03/14 1p

7905240078 Forwards revision to HFIR project safeguards contingency plan for final acceptance review Plan withheld (ref Atomic Energy Act of 1954 & Energy Reorganization Act of 1974 & Energy Reorganization Act of 1974 B

DOCKET 70-0102 AMHERST COLLEGE

7905100422 Discusses IE insp of Licenses 20-03570-02, 20-03570-03, 20-03570-04 & RMM-94 on 790308 No noncompliance noted Hajor areas inspected examinations of procedures & representative records & interviews w/personnel. MCGLINTOCK, R O Region 1, Philadelphia, Office of the Director, 79/03/20 1p

DOCKET 70-0135 Babcock & Hilcox Co

- 7905090060 Forwards revised organization chart for PA operations & updated position description for nuclear matl control & accountability personnel excluding SNM custodian & technician positions which were not changed AUSTIN.H A Babcock & Wilcox Co., Nuclear Material Div 79/02/26
- 7905080027 Responds to 790130 ltr to LC Rouse Agrees to assignment of Ortr as compliance section manager & deletion of regulatory projects coordinator position Assignment of Congedo as licensing & nuclear safety specialist is conditional CROW, W. T. Division of Fuel Cycle & Material Safety 79/03/16
- 7905240594 Forwards Table 6 i, "Comprehensive Listing of Storage Area Codes" enumerating current matl balance areas & item control areas Table was omitted from B&W 781213 ltr AUSTIN.M A Babcock & Wilcox Co 79/04/06 2pp
- 7905220072 Ack receipt of 790220 itr informing NRC of steps taken to correct violations noted in IE Inep Repts 70-0135/78-30 & 70-0364/78-32 MARTIN. # Q Region i. Philadelphia. Safeguards Branch 79/04/10
- --7905220077 Responds to NRC 790130 ltr re violations noted in IE Inse Repts 70-0135/78-30 & 70-0364/78-32 Corrective action withheld (ref 10CFR2 790) AUSTIN:M A Babcock & Wilcox Co , Nuclear Material Div. 79/02/20
- --7905220087 Forwards IE Insp Repts 70-0135/78-30 & 70-0364/78-32 on 781106-1201 Notice of violation withheld (ref 10CFR2.790). MARTIN.H 9 Region 1, Philadelphia, Bafeguards Branch 79/01/30 2pp
- --7905220092 IE Insp Repts 70-0135/78-30 & 70-0364/78-32 on 781106-1203.
  Noncompliance noted failure to maintain stds program for crane scale & failure to assure gross weights and measurements of slement Details withheld (ref 10CFR2, 790)
  KUSHMER.W.L., JOYNER.J.H. Region 1, Philadelphia, Safeguarde Branch, 79/01/22 ip
- 7905230048 Responds to 790221 itr requesting assessment of potential magnitude of MUF bias due to degree of verification currently performed No addl measurements required for verification Forwards measurements control plan. H/o encl. AUSTIN.M A Babcock & Wilcox Co. 79/04/20 2pp
- 7905240756 Ack receipt of 790416 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 70-0135/79-01 & 70-0364/79-02.

  MARTIN.W O Region 1, Philadelphia, Bafeguards Branch 79/04/26
- ---7905240763 Responds to NRC 790320 ltr re violations noted in IE Inag-Repts 70-0135/79-01 & 70-0364/79-02. Corrective actions shop talk will be scheduled to review SNM custodian responsibilities. AUSTIN.M A Babcock & Wilcox Co. 79/04/16. 2pp.
- ---7905240775 Forwards IE Insp Rept 70-0135/79-01 & 70-0364/79-02 on 790103-0202 Notice of violation withheld(ref 100FR2 790).

  MARTIN.W.O. Region i, Philadelphia, Safeguards Branch 79/03/20 3pp
- --7903240784 IE Insp Rept 70-0135/79-01 & 70-0364/79-02 on 790103-0203 Noncompliance noted failure to advise NRC of changes to internal control sys & failure to adhere to control procedures for SNM, Details withheld (ref 10CFR2 790), KUSHNER,M.L. Region 1, Philadelphia, Diffice of the Director JONNER,J H Region 1, Philadelphia, Safeguards Branch. 79/03/19. 3pp

- 7905300513 Accepts enci proposed contingency plan to provide acceptable level of physical protection in event of strike, as discussed & agreed upon during MJ Defilippi 790423 visit Plan withheld (ref 10GFR2.790).
  MCGORKLE. Q U Physical Security Licensing Branch 79/04/26.
- DOCKET 70-0143 NUCLEAR FUEL BERVICES, INC
- 7905090265 Responds to NFS 781009 ltr transmitting decommissioning program for U-235 facilities & requesting that Part 2 be withheld traf iOCFR2 790) Request denied/considerations are not specific enough GROWHULT Fuel Process & Fab. Branch 79/03/09 3pp.
- 7903230684 Forwards IE Insp Rept 70-0143/79-08 on 790226-0302 No ndncompilance noted.
  KENNA,M.B. Region 2. Atlanta, Bafeguards Branch, 79/03/19 2pp
- --7905230609 IE Insp Rept 70-0143/79-08 on 790226-0302 No noncompliance noted Major areas inspected records & repts. HODGER, J. W. Region 2, Atlanta, Office of the Director OILLEGPIE.F.P. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/19 3pp
- 7905180664 Informs that info requested re amend to Certificate of Compliance 6400 will be submitted by 790430.
  MICHELL C. J. Nuclear Fuel Services, Inc. (subs. of Oetty Gil Co.) 79/03/23. ip.
- 7905100423 Requests Amend MMP-1 to License SNM-124 Details withheld (ref 10CFR2 790).
  HENSLEY, R. Nuclear Fuel Bervices, Inc. (subs. of Getty Gil Co.).
  79/03/29. 200
- 7905250535 Forwards project rept on sys analysis study Btudy withheld (ref 100fR2.790).
  HANSER.W.G Nuclear Fuel Services, Inc. (subs. of Gatty Oil Co.)
  79704703. 1s.
- 7905150024 Submits proposed new Section 7 7 of fundamental nuclear math control plan for approval in response to 790112 ltr Details withheld (ref 10CFR2 790) MANBER.W.C. Nuclear Fuel Services: Inc. (subs. of Getty Dil Co.) 79/04/06. 200
- 7905020417 Ack receipt of 790403 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0143/79-07 XENNA: H D. Region R, Atlanta: Bafeguards Branch 79/04/12 ip.
- --7905020425 Responds to NRC 790312 ltr re violations noted in IE Insp. Rept 70-0149/79-07. Corrective actions re safeguard measures withheld (ref 10CFR2 790) HANBER, H. C. Nuclear Fuel Bervices, Inc. (subs. of Qetty Oil Co.) 79/04/03 19
- --7905020403 Forwards IE Inep Rept 70-0143/79-07 Notice of violation withheld (ref 100fR2 790) KENNA, H. D. Region 2, Atlanta, Bafeguards Branch, 79/03/12 228.
- \*\*\*7905020439 IE Insp Rept 70-0149/79-07 on 79010-0209 Noncompliance noted failure to calculate bias associated w/massurement of process holdup & stack & laundry discharges LEG.T D. Region 2. Atlanta: Office of the Director WILLIAMS: OH Region 2. Atlanta: Bafeguards Branch. 79/03/07.
- 7905240344 Ack receipt of IE Insp Rept 70-0143/79-15 on 790414-15.No proprietary info MANBER.H.G Nuclear Fuel Services, Inc. (subs. of Gatty Oil Co.) 79/04/20. ip
- --7905240382 Forwards IE Insp Rept 70+0143/79-15 on 790414-15.No honcompliance noted.

  KENNA, N. B. Region 2. Atlanta. Office of the Director. 79/04/20.
- --7905240361 IE Insp Rept 70-0143/79-15 on 790414-15.No noncompliance moted Major areas inspected shutdown preparations & plant operations KENNA, H B Region 2. Atlanta, Office of the Director, 79/04/19.
- 7905140141 Notifies that Section 7.7 of fundamental nuclear maticontrol plan submitted in 790406 ltm is satisfactory.License condition 2.1 of Amend MPP-1 to License SNN-125 is revised accordingly.

  PARTLOH, J. O Material Control Licensing Branch. 79/04/24. 2pp

- 7905130135 Responds to 790423 ltr requesting time extension for conducting low enriched U inventory Request is granted PARTLOH. J C Material Control Licensing Branch 79/04/26 lp
- 7905230844 Determines that revised & corrected safeguards contingency plan is acceptable License Conditions 9 1 & 9 2 are being amended Physical protection requirements encl MCCORKLE, O W Physical Security Licensing Branch 79/05/02 2pp
- 7905010137 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air "
  O'REILLLY JP Region 2, Atlanta, Office of the Director 79/03/28 in
- DOCKET 70-0150 PURDUE UNIV
- 7905110041 Forwards IE Insp Repts 50-182/79-01 & 70-0150/79-02 on 790213-19 Notice of violation withheld (ref 10CFR2 790) \* Region 3, Chicago, Safeguards Branch 79/03/26 2pp
- --7705110047 IE Insp Repts 50-182/77-01 & 70-0150/77-02 on 790213-15 Noncompliance noted keys locks & hardware deficiencies for fast breader blanket facility Details withheld (ref 10CFR2,790) CHRISTOFFER: Q M. MADEDA, T J Region 3, Chicago, Office of the Director HIND, A Region 3, Chicago, Safeguards Branch 79/03/21 1p
- DOCKET 70-0364 PARKS TOWNSHIP SITE, BABCOCK & WILCOX CO
- 7905090060 Forwards revised organization chart for PA operations & updated position description for nuclear math control & accountability personnel.excluding SMM custodian & technician positions.which were not changed AUSTIN.M A Babcock & Wilcox Co., Nuclear Material Div 79/02/26
- 7903130137 Requests administrative change to License SNM-414, changing layels of U enrichment in matl limitations portion of Tech Specs AUSTIN:M A Babcock & Wilcox Co 79/03/01 3pp
- 7905080027 Responds to 790130 ltr to LC Rouse Agrees to assignment of Ortr as compliance section manager & deletion of regulatory projects coordinator position Assignment of Congedo at licensing & nuclear safety specialist is conditional. CROW.W T Division of Fuel Cycle & Material Safety 79/03/16
- 7905220072 Ack receipt of 790220 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 70-0135/78-30 & 70-0364/78-32 MARTIN:W G Region 1, Philadelphia, Safeguards Branch 79/04/10
- --7905220077 Responds to NRC 790130 ltr re violations nated in IE Insp Repts 70-0135/78-30 & 70-0364/78-32 Corrective action withheld (ref 100FR2.790) AUSTIN:M A Babcock & Wilcox Co., Nuclear Material Div 79/02/20
- ---7905220087 Forwards IE Insp Repts 70-0135/78-30 & 70-0364/78-32 on 781106-1201 Notice of violation withheld (ref 10CFR2 790) MARTIN, W 0 Region 1, Philadelphia, Safeguards Branch 79/01/30 2pp
- --7905220092 IE Insp Repts 70-0135/78-30 & 70-0364/78-32 on 781106-1201
  Noncompliance noted failure to maintain stds program for
  crane scale & failure to assure gross weights and
  measurements of element Dateils withheld (ref 100FRZ. 790).
  KUSHNER; W.L., JOYNER, J. H. Region 1, Philadelphia, Safesuards
  Branch. 79/01/22 1p.
- /905240089 Forwards revisions to proposed Parks Township site safeguards contingency plans in response to 790228 itr.Plan withheld (ref Atomic Energy Act of 1954 & Energy Reorganization Act of 1974 )
  AUBTIN.M.A. Babcock & Nilcox Co., Nuclear Material Div 79/04/18
  789.
- 7905230048 Responds to 790221 itr requesting assessment of potential magnitude of MUF bias due to degree of verification currently performed No addi measurements required for varification. Forwards measurements control plan M/o encl AUSTIN.M.A. Babcock & Milcor Co. 79/04/20. 2pp

- 7905020530 Responds to 780623 htr Data generated in Pu glovehox line must be treated individually PARTLOW.J 0 Haterial Control Licensing Branch 79/04/24 19
- 7908110052 Forwards 790323 itr requesting \$150 fee for amend to delay Pu physical inventory Requests payment, within 15 days of receipt of itr
  HEISS.D License Fee Management Branch 79/04/24 ip
- 7909230706 Summary of 790420 meeting w/B&W re revisions to Section II of License SNM-414 re improvement of Pu facility fire protection & ventilation sys BURWHARDT, W Fuel Reprocess & Recycle Branch 79/04/26 ip
- 7905240756 Ack receipt of 790416 itr informing NRC of steps taken to correct violations noted in IE Insp Regts 70-0135/79-01 & 70-0364/79-02 HARTIN.N.G Region 1. Philadelphia, Safeguards Branch 79/04/26
- ---7905240763 Responds to NRC 790320 ltr re violations noted in IE Insp Repts 70-0135/79-01 & 70-0364/79-02 Corrective actions shop talk will be scheduled to review SNM custodien responsibilities AUSTIN.M A Babcock & Wilcox Co 79/04/16 2pp
- --7905240775 Forwards IE Insp Rept 70-0135/79-01 & 70-03&4/79-02 on 790103-0202 Notice of violation withheld(ref 10CFR2 790) MARTIN.H O Region i, Philadelphia, Sefeguards Branch 79/03/20 Gpp
- --79D5240784 TE Insp Rept 70-0135/79-01 & 70-0364/79-02 on 790103-0202 Noncompliance noted failure to advise NRC of changes to internal control sys & failure to adhere to control procedures for SMM Details withheld (ref 100FR2 790) KUSHNER, H ... Region i, Philadelphia, Office of the Director. JONNER, J H Region i, Philadelphia, Safeguards Branch 79/03/19 3pp
- 7905300583 Accepts encl proposed contingency plan to provide acceptable level of physical protection in event of strike as discussed & agreed upon during MJ Defillippi 790423 visit Plan withheld (ref 100FR2 790)
  MCCORKLE, O W Physical Security Licensing Branch 79/04/26.
  20p
- 7905160116 Forwards Amend 1 to Indemnity Agreement 0-1.per 10CFR140 changes, re liability insurance increase from \$140 million to \$160 million. effective 790501 Supporting documentation encl.

  BALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp.
- 7908110205 Confirms 790501 teleon increasing liability limit to \$36 million for MAELU Policies MF-5,MF-84 & MF-85 ROBERTS, D. Mutual Atomic Energy Liability Underwriters 79/05/02 to.
- 7905290410 Forwards executed Amend 1 to Indemnity Agreement G-1. LEWIS, J. R. Babcock & Wilcox Co., Nuclear Material Div. 79/05/21 2pp
- 7905010080 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys co/Svc Air Sys Used as Source of Breathing Air "ORIER, B. H. Region 1. Philadelphia, Office of the Director 79/03/28 fp.

### DOCKET 70-0371 UNITED NUCLEAR CORP

i i

44

- 7905290059 Forwards Naval Products Div training & qualification plan. Plan withheld (ref 10CFR2.790) KIRK, M.F. United Nuclear Corp 79/02/13 2pp.
- 7903230798 Responds to 790303 request to use bolt type seal on drums for burial Request referred to Ofc of Btds Development PARTLOW, J 9 Material Control Licensing Branch. 79/04/09. ip
- 7905240984 Responds to 790410 ltr requesting exemption from License Condition 3, 1 & 10CFR70.58E.Administrative amond fee is required MEISS.D. License Fee Hanagement Branch. 79/04/17. ip.
- 7905230850 Responds to 790330 ltr re fee for guard training & qualification plan, Purpose of review & approvel of plan is to determine whether licensee meets requirements of regulations, Amend fee of \$8,300 is required.

  MILLER, H 0 License Fee Management Branch, 79/05/08, 2pp.

- DOCKET 70-D734 GENERAL ATOMIC CD
- 7905010234 Forwards IE info Notice 79-08, "Interconnection of Contaminated Bys w/Svc Air Sys Used as Source of Breathing Air" ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/03/28.
- 7905100048 Ack receipt of 790330 ltr in response to 790308 natice of violation Corrective actions will be reviewed during next physical protection insp.
  NORDERHAUGL R Region 5. San Francisco. Bafeguards Branch 79/04/03 to
- DOCKET 70-0754 VALLECITOS NUCLEAR CENTER, GENERAL ELECTRIC CO
- 7905230730 Forwards details of proposal to eliminate need for granting of exemptions re excess SNM holdings at facility Proposal withheld (ref 10CFR2.770)
  MDSCHNER,R A General Electric Co., Nuclear Energy Products Div. 79/01/11. 2pp.
- 7905290062 Forwards security training & qualification plan. Plan withheld (ref 100FR2 790)
  CUNNINGHAM, O.E. General Electric Co , Nuclear Energy Products Div 79/02/16 200
- 7905010230 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air "
  ENGELKEN, R H Region S, San Francisco, Office of the Director 78/03/28 10
- 7905250218 Forwards safeguerds contingency plan.w/comments on revisions suggested in NRC 790207 ltr Plan & comments withheld (ref 100FR2 790) CUNNINOHAM, Q E General Electric Co .Nuclear Energy Products Div 79/04/05. Zoo
- 7905300680 Responds to 790111 ltr Agrees w/concept of tailored fundamental nuclear matl control & accounting program for Advanced Fuel Lab Any request for mod to plants plan should include description of process equipment & flows PARTLON, J. Q. Material Control Licensing Branch 79/04/23 is
- 7905160161 Forwards Amend 1 to Indemnity Agreement 0-4, per 10CFf1140 changes.re liability insurance increase from \$140 million to \$160 million.effective 790801. Supporting documentation encl SALTZMAN, J. Antitrust & Indemnity Group 79/05/01. Spp
- 7905240230 Determines request for amend to License SNM-960 contains administrative changes requiring \$150 administrative fee. WEISS.D License Fee Management Branch. 79/05/02. 1p.
- 7905150382 Amend 1 to Indemnity Agreement G-4.

  SALTZMAN,J Antitrust & Indemnity Group, DARMITZEL,R W General Electric Co 79/05/08 1p.
- DOCKET 70-0820 United Nuclear Corp
- 7903130628 Forwards fuel recovery operation training & qualifitations plan. Plan withheld (ref 10CFR2, 790), 910LIGITI.R United Nuclear Corp. 79/01/13 2pp.
- 7905110029 Forwards IE Insp Repts 70-0820/79-05 & 70-2760/79-01 on 790205 No noncompliance noted.

  HARTIN.W.O. Region i, Philadelphia, Safeguards Branch 79/03/Q7 200
- --7905110036 IE Insp Repte 70-0820/79-05 & 70-2760/79-01 on 790205 Mg noncompliance noted, Major areas inspected export shipment of BNM.

  BMITH, G.C., MCKEOWN, L.. Region i, Philadelphia, Office of the Director JOYNER, J. H. Region i, Philadelphia, Safeguards
  - Director JOYNER J H. Region 1. Philadelphia. Safegueres Branch. 79/03/02. 1p.
- 7905220032 Notifies that response to 790308 ltr re proposed vault adds is not expected until further advice from licenses.

  MGCORKLE, G H Physical Security Licensing Branch. 79/03/19 Ep.
- 7905250236 Forwards add1 info in form of revised pages re const of recovery bay authorized by Amend 4 to License 8NM-777. Info does not involve changes in processible location or safety & environ controls W/encl drawings.

  BOWERS.C E United Nuclear Corp. 79/03/26. 7pp.
- 7905220067 Forwards fee for safeguards inep conducted on 780522-24 Paywant is submitted under protest, Requests refund if decision is reversed.

  SCHUTZ/D M. United Nuclear Corp. 79/04/06, 2pp.

- 7905250532 Requests exception to License Condition 9 3,20 for contractor vehicles to be used to transport excavated metiguate outside area Each vehicle to be excorted by armed 010LIGITI.R J United Nuclear Corp. 79/04/09 10
- 790324000% Forwards revised pages of "United Nuclear Corp Recovery Bys. Fundamental Nuclear Matl Control Flan," in response to 790322 ltr Plan withheld (ref Atomic Energy Act of 1954 & Energy Reorganization Act of 1974 BOMERG, C.E. United Nuclear Corp 79/04/20 2pp
- 7908241000 Notifies that rept on safeguard contingency plan changes is withheld (ref Atomic Energy Act of 1984), s United Nuclear Corp 79/04/24 ip.

# DOCKET 70-0824 BABCOCK & WILCOX CO.

- 790516014B Forwards Amend 1 to Indemnity Agreement G-2, per 10CFR140 changes are liability insurance increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl SALTZMAN, J Antitrust & Indemnity Group 79/05/01 Spp
- /90510203 Confirms 790501 teleon increasing liability limit to 436 million for MAELU Policies MF-5, MF-84 & MF-85, ROBERTO, D. Mutual Atomic Energy Liability Underwriters 79/05/02 jp
- 7905240745 Notifies B&W of overpayment of license amend fee Refund will be sent HEIBG:D License Fee Management Branch. 79/05/03 ip

### DOCKET 70-0984 PACIFIC NORTHWEST LAS

7905010325 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Bys w/Byc Air Bys Used as Source of Breathing Air."
ENGLIKEN. R II Region 5, San Francisco, Office of the Director 79/03/29 In

### DOCKET 70-1007 GENERAL ELECTRIC CO

- /90501023D Forwards IC Info Notice 79-08, "Interconnection of Contaminated Bys w/Syc Air Sys Used as Source of Breathing Air "
  ENGLISHING II Region 5, San Francisco, Office of the Director
- 7905240568 Forwards "Annual Financial Rept 1978" CUNINGHAM, Q. E. General Electric Co., Nuclear Energy Products Div 79703/300 ip.

# DOCKET 70-1006 WESTINGHOUSE ELECTRIC CORP

- 7905250307 Forwards "Bemiannual Effluent Monitoring Rept."
  Jul-Dec 1978,
  NARDI.A J Heatinghouse Electric Corp. 79/03/02 1pp.
- --7905250014 "Semiannual Effluent Monitoring Rept," Jul-Dec 1978 NARDI,A.J Hestinghouse Electric Corp. 79/03/02. 1p

# DOCKET 70-1100 COMBUSTION ENGINEERING, INC

- 7905240267 Forwards emergency plan for low enriched U oxide fuel fabrication plant in Hindsor, CT, in response to 790215 ltr. LICHTENBERGER Combustion Engineering, Inc. 79/04/10. 1p
- --7905240276 Emergency plan for low enriched U oxide fuel fabrication plant in Hindson, CT W/780612 & 780614 ltrs. # Combustion Engineering, Inc. 79/04/01. 35pp.

### BOCKET 70-1113 GENERAL ELECTRIC CO.

- 7905140307 Forwards requested revisions to Wilmington Mfg Dept's emergency plan Changes reflect use of protective equipment & supplies, notification of offsite agencies & restoration of plant to safe status KOPLANA L. Oeneral Electric Co., Nuclear Energy Products Div. 79/04/04. 9pp
- 7905240600 Extende appreciation for guidance re reporting of proposed changes to fundamental nuclear mati control plans. Agraes W/NRC position re prompt submittal of plan changes KAPLAN, A. L. General Electric Co.: Nuclear Energy Products Div. 79/04/04 19

- 7905150791 Ack receipt of itr reporting results of 790312-15 insp conducted by DH Jones at fuel fabrication plant KAPLAN/A L General Electric Co 79/Q4/09 1p
- 7905070091 Ack receipt of IE Insp Rept 70-1113/79-10 on 790320 No proprietary info. KAPLAN:A L General Electric Co /Nuclear Energy Products Div 79/04/18 ip
- --7905070095 Forwards IE Insp Rept 70-1113/79-10 on 790320 No noncompliance noted SUTHERLAND, J T Region 2. Atlanta. Fuel Facility & Materials Safety Branch 79/04/06 2pp
- ~~7905070101 IE Insp Rept 70-1113/79-10 on 790320 No noncompliants noted Major areas inspected determination of site boundary concentration due to unplanned release on 781203 TROUP, 0 L. Region 2, Atlanta, Office of the Director 91880N, A F. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/04/06 3pp
- 7905240811 Ack receipt of results of 790326-30 insp conducted at fuel fabrication plant.

  KAPLAN, A L General Electric Co , Nuclear Energy Products Div 79704/18 ip
- 7905220025 Forwards revised version of App G to soergency plan re dose distance plots KAPLAN.A L General Electric Co .Nuclear Energy Products Div 79/04/19 10pp
- 7905290082 Act receipt of 790406 ltr informing NRC of steps taken to currect violations noted in IE Insp Rept 70-1113/79-07 BUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/04/30 ip
- ---7905290087 Responds to NRC 790329 ltr re violations noted in IE Insp Rept 70--113/79-07 Corrective actions new procedure implemented re posting of documents required by NRC KAPLAN.A L. General Electric Co 79/04/06 2pp
- J-7905290092 Forwards IE Insp Rept 70-1113/79-07 on 790226-0302 & notice of violation SUTHERLAND, J T Region 2. Atlanta. Fuel Facility & Materials Safety Branch 79/03/29 2pp
- --7905290094 Notice of violation from insp on 790226-0302

  \* Region 2, Atlanta, Office of the Director 79/03/29 ip
- ---7903290099 IE Insp Rept 79-1113/79-07 on 790226-0302 Noncompliance noted: failure to post responses to notice of violations KAHLE, J. B Region 2. Atlanta, Office of the Director POTYER, J.P. Region 2. Atlanta, Fuel Facility & Materials Bafety Branch 79/03/29 Gpp
- 7905240222 Reviews 790321 itr to GAO re record-teeping requirements found in 10CFR40. 61. Records retained for five years unless part of investigation PARTLOW. J O Material Control Licensing Branch 79/05/02 ip

# DOCKET 70-1143 WESTINGHOUSE ELECTRIC CORP

- 7905240826 Forwards amend fee re safeguards contingency plan review Bubmits fee under protest DIPIAZZA,R P Hestinghouse Electric Corp 79/01/30. 2pp
- 7905250286 Forwards Revision 6 to "Plan for Providing Physical Security at Cheswick Sits " Revision withheld (ref 10CFR2 790).
  DIPIAZZA,R P Westinghouse Electric Corp 79/02/19 1p
- 7905010086 Forwards IE Info Notice 79-08. "Interconnection of Contaminated Sys w/Svc Air Sys Usad, as Source of Breathing Air."

  ORIER.B.H Region 1. Philadelphia. Office of the Director. 79/03/28 ip.
- 7903110072 Ack receipt of 790316 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 70-1143/79-01 & 30-6134/79-01.
  SHITH G H. Region 1. Philadelphia, Fuel Facility & Materials Bafety Branch. 79/04/04 ip
- --7905110077 Responds to NRC 790226 ltr ra violations noted in IE Insp Rapts 70-1143/79-02 & 30-6134/79-01 Corrective actions:more detailed sys of control has been instituted MODRE, J. S. Westinghouse Electric Corp. 79/03/16 2pp.

- --7905110102 Forwards IE Insp Repts 70-1143/79-02 & 30-6134/79-01 on 790123,24.31 & 0201 & notice of violation SHITH.G H Region i. Philadelphia. Fuel Facility & Materials Safety Branch 79/02/26 2pp
- --7905110105 Notice of violation from insp on 790123.24.31 & 0201 SMITH, G L Region 1, Philadelphia, Fuel Facility & Materials Bafety Branch 79/02/26 19
- --7905110113 IE Insp Repts 70-1143/79-02 & 30-6134/79-01 on 790123-24.31 & 0201 Noncompliance noted failure to perform bloassay analysis
  - CLERIONS, P. NIMITZ, R. L. Region 1. Philadelphia, Office of the Director CROCKER H W. Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 79/02/21 11pp
- 7905160108 Forwards Amend 1 to Indomnity Agreement 0-3.per 10CFR140 changes.re liability insurance increase from \$140 million to \$160 million.effective 790501 Supporting documentation encl SALTZMAN, J Antitrust & Indomnity Group. 79/05/01 5pp
- 7905110205 Confirms 790501 telcon increasing liability limit to #36 million for MAELU Policies MF-5.MF-84 & MF-85.
  ROBERTS.D Mutual Atomic Energy Liability Underwriters 79/05/02

#### DOCKET 70-1151 WESTINGHOUSE ELECTRIC CORP

- 7903230621 Requests license amend to accumulate contaminated low enriched scrap w/uncertainty of greater than 10% for period not to exceed Jul 1980, Contaminated scrap will be purified through solvent extraction, Details withheld (ref 100FR2 790) DIPIAZZA,R.P Westinghouse Electric Corp 79/02/13 2pp
- 7905300712 Requests forwarded mat1 MRD-LS&S-668 be withheld from public disclosure (ref 10CFR2 790)
  DIPIAZAR P Hestinghouse Electric Corp 79/03/22 ip
- 7905140321 Clarifies issues discussed in recent telcon re request for License SNN-fi07 exemption from regulations, including accumulation of scrap containers FORTER. H. Westinghouse Electric Corp. 79/03/23 ip
- 7905250474 Forwards revised Page 3 of 790322 submittal of proposed solid waste fixation transportation & burial infe, in response to 790323 telcon.
  REITER: K Westinghouse Electric Corp 79/03/23 2pp
- --7905250477 Forwards proposed solid waste fixation, transportation & burial info describing operations at Columbia site REITER.E K Hestinghouse Electric Corp. 79/03/22. 5pp
- 7905100419 Confirms 790327 telcon request for extension of next BNM physical inventory from 790428 to 790519 Deteils reasons for request FOSTER, H. Nestinghouse Electric Corp. 79/03/27 1p
- 7905240323 Forwards IE Insp Rept 70-1151/79-04 on 790226-28 No noncompliance noted.
  KENNA, W B Region 2, Atlanta, Bafeguards Branch. 79/03/27. 2pp.
- ---7905240336 IE Insp Rept 70-ii31/79-04 on 790226-28 No nuncompliance nated Major areas inspected export license, container identification & documentation & radiation & contamination monitoring CLAY.E.L., GILLESPIE,F.P. Region 2, Atlanta, Office of the Director. 79/03/27 4pp.
- 7905140315 Clarifies issues discussed in recent telcon re request for License SNM-1107 exemption from regulations, including amount of incluerated ash & contaminated scrap w/U content. FOSTER.H. Hestinghouse Electric Corp. 79703/29, 1p.
- 7905240295 Forwards IE Insp Rept 70-1151/79-05 on 790319-21 No noncompliance noted. KENNA, N.B. Region 2. Atlanta, Safeguards Branch, 79/03/30, 2pp.
- --7905240312 IE Insp Rept 70-1151/79-05 on 790319-21 No noncompliance noted, Major areas inspected export license, shipping procedures & techniques & radiation & contamination monitoring, CLAY, E.L., QILLEBPIE, F.P. Region 2, Atlante, Office of the Director 79/03/30 4pp.
- 7905090190 Requests amend to License SNM-i107 authorizing operations w/BNM in expansion of Columbia facility.per encl application.Proprietary portion to be transmitted under separate cover.Forwards fee.W/supporting documentation DIPIAZZA,R P. Mestinghouse Electric Corp. 79/04/03. 53pp.

- 7905020187 Forwards application for amend to License SNM-1107 to authorize operations w/SNM in expanded Columbia Facility Replaces earlier submittal of 790305 Application withheld (ref 10CFR2 790) DIPIAZZA, R.P. Westinghouse Electric Corp. 79/04/04. 200
- 7905020146 Ack receipt of 790405 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-1151/79-03
  KENNA,W B Region 2, Atlanta, Safeguards Branch. 79/04/12 lp
- ---7905020150 Responds to NRC 790313 ltr re violations noted in IE [msp Rept 70--1151/79-03 Corrective actions withheld (ref 10CFR2 790) GODDMIN.H L Westinghouse Electric Corp. 79/04/05 ip
- --7905020156 Forwards IE Insp Rept 70-1151/79-03 on 790206-09 Notice of violation withheld(ref 10CFR2 790)
  KENNA, W B Region 2. Atlanta, Bafeguards Branch 79/03/13
- 7905020161 IE Insp Rept 70-1171/79-03 on 7902066-09. Noncompliance noted failure to follow approved plan for sampling U oxide pellets Details withheld (ref 10GFR2, 790) BATES, J W. ROBERTSON, J S., WILLIAMS, O H Region 2, Atlanta, Office of the Director 79/03/13 ip
- 7905070249 Forwards IE Insp Rept 70-1151/79-07 on 790409-12 No noncompliance noted. KENNA W B Region 2. Atlanta, Bafeguards Branch. 79/04/23 19
- --7903070283 IE Insp Rept 70-1151/79-07 on 790409-12 No moncompliance noted Major areas inspected onsite records & repts. Details withheld (ref 10CFR2, 790) GILLESPIE, F Region 2, Atlanta, Bafaguards Branch HODGES.J W Region 2, Atlanta, Office of the Director 79/04/18 is
- 7905230852 Formalizes 790417 discussion re current LEID model
  Hestinghouse-Columbia model needs to be modified to ensure
  proper treatment of systematic errors
  PARTLOW, J. 0 Hateriel Control Licensing Branch. 79/05/08 ip

### DOCKET 70-1173 MERCYHURBT COLLEGE

- 7905300051 Ack receipt of 790427 ltr identifying inaccurate amend numbers in NRC 790409 ltr Forwards corrected pages, Enci withheld(ref 10GFR2 790).

  MCCORKLE, O W. Physical Security Licensing Branch. 79/05/07.
- DOCKET 70-1193 CIMARRON FACILITY, KERR-MCGEE CORP.
- 7905010197 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air "
  KEPPLER.J 9 Region 3, Chicago, Office of the Director. 79/03/26.
- 7905230735 Cancels Amend MPP-2 & issues encl safeguards Amend MPP-3 for License SNH-1174 BURNETT.R.F. Division of Bafeguards. 79/04/09. 2pp.
- --7905230771 Amend MPP-3 to License BNM-1174 re requirements for controlaccounting & physical security of BNM. \* Division of Safeguards. 79/03/21, lipp
- 7905240139 Responds to 781129 ltr re dismantling & removal of solvent extraction sys. Forwards license Amend 3. Comments on deletions & revisions to license which were rendered obsolete by change in operation.

  BURNETT/R F Division of Safeguards. 79/04/09 2pp.
- --7905240146 Amend 3 to License BNM-1174, requiring measurement of U,Pu & U-235 content of BNM receipt shipments & metl inventoried, except where specified in Condition 2.1.

  \* Division of Bafeguards. 79/03/31. 11pp.
- DOCKET 70-1201 UF & CONVERSION FACILITY, BABCOCK & WILCOX CO
- 7905150112 Forwards IE Insp Rept 70-1201/79-09 on 790327-30 Ne noncompliance noted.
  KENNA, M. B. Region 2, Atlanta, Bafeguards Branch. 79/04/13. 2gp

- --7905150116 IE Insp Rept 70-1201/79-07 on 790327-30 No noncompliance noted Major areas inspected licensee action on previously identified items & measurements & statistical control Details withheld (ref 10CFR2 790)
  JUNES.D W . WILKINS.T.D. Region 2. Atlanta, Office of the Director GILLEBPIE,F P Region 2. Atlanta, Safeguards Branch 79/04/09 1p
- 7705070240 Ack receipt of 770412 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-1201/79-06.
  KENNA, W B Region 2, Atlanta, Safeguards Branch. 79/04/20 ip
- ---7905070245 Responds to NRC 790326 ltr re violations noted in IE Insp Rept 70-1201/79-06 Corrective actions withheld (ref 19CFR2 790), SILK.E J Babcock & Wilcox Co 79/04/12 ip
- --790\$070252 Forwards IE Insp Rept 70~1201/79-06 on 790226-0301.Notice of violation withheld (ref 10CFR2 790)
  KENNA: W B Region 2: Atlanta: 8afeguards Branch. 79/03/26
- --7905070259 IE Insp Rept 70-1201/79-06 on 790226-0301 Noncompliance noted failure to determine measurement bias from stds program Details withheld (ref 10CFR2 790) NILLIAMS, 0 H. ROBERTSON, J S C Region 2, Atlanta, Bafeguards franco 79/03/22 1p
- 7905300016 Forwards IE Insp Rept 70-1201/79-11 on 790419-20 No noncompliance noted KENNA.W 8 Region 2, Atlanta, Safeguards Branch 79/05/02 2pp
- ---7908300021 IE Insp Rept 70-1201/79-11 on 790419-20 No nencompliance noted Major areas inspected storage & internal control & followup on pravious enforcement matters Details withheld (ref 10CFR2 790)
  YODD.Q.A Region 2. Atlanta, Office of the Director QILLESPIE,F P Region 2. Atlanta, Bafeguards Branch 79/05/01.
- 7905250184 Proposes adding new license conditions to Amend MPP-2 to allow for procedures in fundamental nuclear mat1 control plan contrary to 1tr of regulation, Requests response as to acceptability of amend PARTLOW-JO Material Control Licensing Branch 79/05/08 3pp.
- DOCKET 70-1257 MIXED OXIDE FABRICATION PLANT, EXXON NUCLEAR CO , INC.
- 7905150686 Forwards IE Insp Rept 70~1257/79-01 on 790212-16 No noncompliance noted BOOK.H E. Region 5. Ban Francisco, Fuel Facility & Materials Safety Branch 79/03/16 2pp
- --7905150701 IE Insp Rept 70-1257/79-01 on 790212-16. No noncompliance noted Major areas inspected safety committee activities, training, calibr, criticality safety, emergency planning & fire & radiation protection COCLEY,W J , ZURAKAWEKI,P R. Region 5, San Francisco, Office of the Director BOOK, H E Region 5, Ban Francisco, Fuel Facility & Materiale Safety Branch 79/03/16 lipp.
- 7905010228 Forwards, IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Syc Air Sys Used as Source of Breathing Air."
  ENGELKEN,R.H Region 5, San Francisco, Office of the Director 79/03/28, ip.
- 7905150289 Forwards IE Insp Rept 70-1257/79-02 on 790326-31 Rept withheld (ref 1005R2 790).

  NORDERHAUGL R. Region 5. San Francisco. Safeguards Branch.
  79/04/24 2pp
- 7905160123 Forwards Amend 1 to Indemnity Agreement 0-3, per 10CFR140 changes:re liability insurance from increase from \$140 million to \$160 million:effective 790301. Supporting documentation enci.

  SALTZMAN, J. Antitrust & Indemnity Group 79/05/01, 5pp
- DOCKET 70-1308 MORRIS OPERATIONS, GENERAL ELECTRIC CO.
- 7905140305 Forwards table indicating no status change for fuel stored in Jan & Feb 1979
  DAMSON,D M General Electric Co , Nuclear Energy Products Div. 79/03/08, 2pp.
- 7905230437 Forwards IE Insp Rept 70-1308/79-02 on 790228,0301-02 & 07. No nuncompliance noted. DAVIS.A.B. Region G. Chicago, Fuel Facility & Materials Bafety Branch 79/03/26. 2pp.

- --7905230442 IE Insp Rept 70~1308/79~02 on 790228,0301-02 & 07,No noncompliance noted Major areas inspected emergency planning & fire protection

  AXELBON,W L., ESSIG/T,H Region 3, Chicago, Office of the Director 79/03/21. 9pp
- 7903100426 Forwards responses to NRC 790301 ltr re decommissioning plan for Morris Operation
  DAHSON.D M General Electric Co , Muclear Energy Products Div.
  79/04/04 4pp
- 7905240370 Forwards Amend 7 to License BNK-1265 SNM-1281 is terminated ROUSE.L C Fuel Reprocess & Recycle Branch 79/04/10, 2pp
- ---7905240383 Amend 7 to License BNM-1265, terminating License BNM-1281 & incorporating operation spece of consolidated BAR Chapter 10 ROUSE, L. C. Fuel Reprocess & Recycle Branch. 79/04/10 2pp.
- 7905150297 Ack receipt of 790404 1tr informing NRC of steps taken to correct violation noted in LE Insp Rept 79-1308/79-01 Details withheld (ref 10CFR2 790) HIND, J. A. Region 3. Chicago, Safeguards Branch 79/04/20 2pp
- --7905150301 Responds to NRC 790316 ltr re violations noted in IE Insp. Rept 70-1308/79-01 Corrective actions withheld (ref. 10CFRZ 790)

  IAHN-L.L. General Electric Go «Nuclear Energy Products Div. 79/04/04 ip
- 7905150744 Forwards IE Insp Repts 70-1308/79-04 & 70-1309/79-01 on 790410-12 No noncompliance noted HIND, J A Region 3, Chicago, Safeguards Branch 79/04/26 2pp
- ~-7905150754 IE Insp Repts 70-1308/79-04 & 70-1309/79-01 on 790410-12 No noncompliance noted Major areas inspected review of BNM records.Pu-241 decay calculations & nuclear metitensaction betails withheld (ref 100FR 790)
  FINLEY.A 0 , PATTERSON.J P. Region 3. Chicago, Office of the Director HIND.J.A Region 3. Chicago, Befeguards Branch 79/04/26 1p
- DOCKET 70-1309 MORRIS OPERATIONS, BOURCES & STANDARDS, GENERAL
- 7905240370 Forwards Amend 7 to License SNM-1265. SNM-1281 is terminated RQUBE/L C Fuel Reprocess & Recycle Branch. 79/04/10. 2pp
- ---7705240383 Amend 7 to License SNM-1265, terminating License SNM-1281 & incorporating operation spect of consolidated BAR Chapter 10 ROUSE, L. C. Fuel Reprocess & Recycle Branch 77/04/10. 2pp
- 7905150744 Forwards IE Insp Repts 70-1308/79-04 & 70-1309/79-01 on 790410-12 No noncompliance noted, HIND.J.A. Region 3. Chicago. Bafeguards Branch 79/04/26, 2pp
- --7905150754 IE Insp Repts 70-1308/79-04 & 70-1309/79-01 on 790410-12. No noncompliance noted Major areas inspected: review of BNM records: FU-231 decay calculations & nuclear mati transaction Details withheld (ref 100FR2 790) FINLEY, A.O., PATTERSON, J.P. Region 3, Chicago, Office of the Director. HIND, J.A. Region 3, Chicago, Safeguards Branch. 79/04/26

DOCKET 70 \*\*\*

790511002

790522002 ML Nucl radinat licenst CUNNING 79/04/

DOCKET 7

79052400 suryeş decont

#### DOCKET 70-1355 ARMY, DEPT OF

- 7905100374 IE Insp Findings & Licenses Ack, dtd 790304, of Licenses 29-01022-08,29-01022-11,29-01022-12,8UB-1150,6MB-1327 k SNM-1327 Insp findings no noncompilance noted FRIEDMAN, L F Region 1, Philadelphia, Office of the Director 79/03/06 19
- DOCKET 70-1379 PARKWELL LABORATORIES, INC
- 7905290183 Forwards guidelines & info re decontamination of facilities & radiation surveys, per 790312 telcon Requests implementation schedule within two weeks KEPPLER, J G Region 3. Chicago, Office of the Director 79/03/14
- 7905150635 Forwards IE Insp Rept 70-1379/79-01 on 790301 & notice of violation DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/03/27 2pp
- ---7905150640 Notice of violation from insp on 790301 \* Region 3. Chicago, Fuel Facility & Materials Safety Branch 79/03/19 ip.
- ---7905180646 IE Imap Rept 79-1979/79-01 on 790301 Noncompliance noted possession of licensed matl w/o license FINN.J A. JANUSKA, A.O. PAGLIARD, J.A. Region 3. Chicago, Office of the Director. 79/03/19. 7pp.
- DOCKET 70-1921 PLUT. PROD FACIL . ALLIED GENERAL NUCLEAR SERVICES CORP
- 7905150660 Responds to 790206 ltr requesting refund of application fee paid by Allied-General Nuclear Svcs in Jan 1975 for proposed Pu product facility Hill notify re refund request upon collection of complete cost data
  DONGOHUE, D. J. Office of Administration, 79/04/11 lp
- --7905150665 Requests refund to Allied-Owneral Nuclear Svcs for application fee paid to NRC on 750124 for Pu product facility Application withdrawn due to suspension of design work BOSKEY, B. Volpe, Boskey & Lyons 79/04/11, 4pp.
- --7905150669 Forwards questions re initial review of 740703 application to construct Pu product facility
  ROUSE,L. C. Atomic Energy Commission (Pre 1975) 74/12/10. 2pp.
- ---7905150674 Forwards Category & B fee for Pu processing & fabrication plants
  NEWMAN.R I Allied General Nuclear Bervices 75/01/24 3pp
- ---7905130679 Ack receipt of 750115 itr re status of const at Pu processing & fabrication plant Discusses problems of license review, design & const resulting from GESHO & safeguards studies. Requests meeting GOBSICK.L.V. Office of the Executive Director for Operations. 75/02/03 2pp.
- ---79051506B3 Notifies of suspension of design work for Pu product facility. PRICE,N J. Allied Coneral Nuclear Services. 75/01/15 4pp.
- DOCKET 70-2428 ST FRANCIS GENERAL HOSP, PI, PENNSYLVANIA
- 7905150727 Discusses IE Imsp of License SNM-1689 on 790205 No nuncompliance noted License is inactive & licensed mat1 has naver been used under authorization of license MCCLINTOCK-R O Region 1, Philadelphia, Dffice of the Director. 79/02/26. 1p.
- DOCKET 70-2623 MCGUIRE BPENT FUEL POOL, DUKE POWER CO.
- 7905110040 Applicant serves interrogatories & requests to produce documents on Carolina Action.per 790223 order.Certificate of Svc encl.
  HCOARRY, J. M Duke Power Co. 79/03/16, 33pp
- 790509043B NRC second set of interrogatories served on Safe Energy Alliance Certificate of Svc enct HOEFLING, R. K. Branch 4 79/03/23. 9pp.
- 7905090440 Requests that Bafe Energy Alliance permit insp & copying of documents identified in responses to NRC second set of interrogatories Cartificate of Svc encl. HOEFLING, R.K. Branch 4. 79/03/23. 3pp.

- 7905230766 First set of interrogatories submitted to NRDC Certificate of 8vc encl HOCFLINO.R K Branch 4 79/03/23 13pp.
- --7905230775 Requests production of all documents identified by NRDC in response to NRC first of interrogatories HOEFLING.R K Branch 4 79/03/23 ip
- 7905110037 Applicant's response to NRDC interrogatories to applicant Supporting documentation & Certificate of Svc ancl MCGARRY, J M Duke Power Co 79/03/27 22pp
- 7903090164 Requests 1tr either withdrawing 790213 original security plan submittal or ack it for record as original plan ROUSE, L.C. Fuel Reprocess. & Recycle Branch. 79/03/29 2pp
- 7905240317 Forwards statements of qualifications of DH Sterrett, SB Hager HT Shead & RN Bostian as experts intending to testify for applicant in answer to NRDC interrogatories MCGARRY, J M Debevoise & Lieberman 79/03/30 7pp
- 7905150440 Motion to dismiss Gafe Energy Alliance as active particleant in proceeding due to Alliance's failure to comply W/ASLB 790223 order Certificate of 8vc ancl. MCOARRY, J M Duke Power Co. 79/04/02 Spp.
- 7903240482 Serves NRC request for admission of matters & facts upon applicant. Certificate of Svc enci. RDISHAN A Z Natural Resources Defense Council. 79/04/02 7pp.
- 7905030103 NRC motion to compel Carolina Environ Study Oroup to respond to 790306 interrogatories Supporting brief, proposed form, original interrogatories & Cartificate of Svc encl KETCHEN.E 0 Branch 3 79704/05 14pp
- --7905030116 NRC motion to compel Carolina Action to respond to 790306 interrogatories. Bupporting brise, proposed form of order, original interrogatories & Certificate of Svc encl. XETCHEN.E O Branch 3 79/04/05 14pp.
- --7905030120 NRC motion to compel Davidson College chapter of RC Public Interest Group to respond to 790306 interrogatories Supporting brief, proposed form of order, original interrogatories & Certificate of Svc ancl.

  KETCHEN, E O Branch 3 79/04/05 16pp
- 7905310132 Describes event re-packaging to be used by util for shipment of spent fuel. Defect may substantially decrease effectiveness of packaging Certificate of Evc encl. CUNNINGHAM.R.E. Division of Fuel Cycle & Material Bafety 79/04/11. 4pp
- ---7905310152 Forwards NMSS 790406 order to use of Model NFS-4 packaging BIRCKS.N J. Office of Nuclear Material Safety & Bafeguards. 79/04/06 296
- 790509013B Forwards request for add1 info re proposed amend of License 8NM-1773 to ship spent fuel from Ocones to McQuire, Requests resonse by 790423 ROUSE, L C. Fuel Reprocess. & Recycle Branch. 79/04/12 Opp.
- 7903220048 Dismisses Safe Energy Alliance as party intervenor.
  MILLER, M. E. Atomic Safety and Licensing Board Panel 79/04/12
- 7905230666 Orders intervenors Carolina Environ Study Group, NC PIRC chapter & Carolina Action to interrogatories within five days, Adopts schedule to govern summary disposition, discovery direct testimony & evidentiary hearing HILLER M E Atomic Safety and Licensing Board Panel. 79/04/12 3pp.
- 7905220463 Forwards modified interim security plan for fuel storage bldg & interim safeguards contingency plan, Plans withheld (ref 10GFR2, 790), PARKER, M.O. Duke Power Co. 79/04/13. 3pp.
- 7905140077 Responds to util's interrogatories Affidavits of TB Cechtan HR Tamplin & AZ Roisman & Centificate of Svc encl. COCHRAN, T. B., TAMPLIN, A. R., ROISMAN, A. Z. Natural Resources Defense Council 79/04/16, 32pp.
- 7905240921 Requests notification of any addl witnesses to be included in proceedings.
  PORTER, M L. Duke Power Co. 79/04/19. ip.
- 790524093B Confirms 790312 telcon re vital areas during storage of spent fuel Irradiated fuel must be protected as vital squipment.

  MCGORKLE, 9, W. Physical Security Licensing Brench. 79/04/20.

7905290679 Decond set of interrogatories submitted to applicant goldMAN.A.Z. Natural Resources Defense Council 79704/23 9p/

7905240470 Motion for order to dismiss Caroline Action as active participant in proceeding due to failure to provide answers to applicant's interrogatories of 790316 Certificate of Svc sacl
KCOARRY, J M Duke Power Co 79/05/03 5pp.

# DOCKET 70-2753 HOLYOKE HORP HO, MASSACHUSETTS

7905290106 Ack receipt of 790323 ltr informing NRC of steps taken to correct deviation noted in IE Insp Repts 30-1873/79-01 & 70-2753/79-01 MCCLINTOCK, R O Region 1, Philadelphia, Office of the Director 79/04/05 ip

--7903290161 Responds to NRC 790308 itr re deviation noted in IE Insp. Rept 30-1073/79-01 & 70-2753/79-01 Corrective actions no food or wrinks allowed in areas where radioactive matts are used or stored.

HAYHARD. J. Holyoke Hosp. HO. Massachusetts 79/03/23 ip

--7905270165 Discusses IE Insp Rept 30-1873/79-01 & 70-2753/79-01 on 790216 Noncompliance noted drink permitted to be stored in same area where radioactive matl stored.

MCCLINTOCK, R. O Region 1, Philadelphia, Office of the Director 79/03/05. 2pp.

### DOCKET 70-2760 UNITED NUCLEAR CORP.

7905110029 Forwards IE Insp Repts 70-0820/77-05 & 70-2760/79-01 on 790205.No noncompliance noted KARTIN.H O Region 1, Philadelphia, Safeguards Branch 79/03/07 Zpp.

\*\*\*7903110036 IE Inep Repts 70-0820/79-05 & 70-2760/79-01 on 790205 No nuncompliance noted Major areas inspected export shipment of 6NH BHITH, 0 C., MCKECHN, L Region 1, Philadelphia, Office of the Director JOYNER, J H Region 1, Philadelphia, Bafeguards Branch, 79/03/02 1p

# DOCKET 70-2038 CINCINNATI GAS & ELECTRIC CO.

7905240180 Amends License SNK-1823 Itams 4 % 9 re expiration date & aids Items Ac. Sc & 14. CROW, H. T. Division of Safeguards 79/03/06 2pp.

--79052401BB Recommands approval of 790202 amend request relicense expiration date change to allow use of nominal 5 Ci Pu-beryllium neutron source.

DELANGY. J. C. Division of Bafeguards 79/03/06. 2pp

# PACKAGING OF RADIOACTIVE MATERIAL FOR TRANSPORT, AND TRANSPORTATION OF RADIOACTIVE MATERIAL UNDER CERTAIN CONDITIONS

### DOCKET 71-0001 ANEFCG, INC

7905170278 Forwards request for add1 info to complete review of GA #198788 HACDONALD: C. E. Transportation Branch. 79/03/29. 1p.

7905290146 Forwards revised QA program for shipping packages for radioactive mat! HURPHY, J. D. Anefco.Inc. 79/05/Q3 ip

--7905290148 GA program for Thipping packages for radioactive math. HURPHY, J. D. Anefeo. Inc. 79/05/01. 29pp.

# MICKET 71-0002 CHEM-NUCLEAR BYSTEMS, INC.

7905240041 Forwards request for addl info to complete review of QA progress.

Transportation Branch. 79/04/27. 13pp

# DOCKET 71-0006 UNITED NUCLEAR CORP.

7905020185 Forwards request for add1 info to complete review of GA Program. MACDONALD, C.E. Transportation Branch. 79/04/11, 12pp.

# DOCKET 71~0008 CONHONIEALTH EDISON CO

7905150076 Responds to NRC 790319 required by revising epalication for approval of program to meet requirements of 10CFR71 51 "GA Program for Nuclear Generating Stations." CE-1-A Revision 6, fulfills GA requirements REED, C Commonwealth Edison Co 79/04/16 229

7905240847 Forwards OA program approved for radicacti-e matt perhaps MACDONALD,C E Transportation Branch 79/05/01 1p

--7905240854 GA program approval for radioactive eatl package 000008 Revision 0 MACOUNALD.C E Transportation Branch 79/05/01 19

DOCKET 71-0024 HITTHAN HUGLEAR & DEVELOPMENT CORP

7905240045 Forwards request for add1 info to complete review of SA program
MACDONALD, C E Transportation Branch 79/04/27 12se

DOCKET 71-0031 MARYLAND BHIPBUILDING & DRY DOCK CO

7905150149 Proposed GA program does not meet requirements of App E to 10CFR71 Forwards tample GA program for industrial radiography licensess, dtd 790402, to assist in application revision Requests revision by 790527 MACDONALD, C E Transportation Branch 79/04/27 3pp

DOCKET 71-0033 IND TEST LAB SERVICES CORP

7905150268 Forwards "GA Program for Use Heint & Repair of Shipping Packages for Special Form Radioactive Matl." Revision 1 HANDRAHAN.E Industrial Testing Laboratory Services Corp 79/04/16

--7905150274 "QA Program for Use Maint & Repair of Shipping Packages for Special Form Radioactive Matl." Revision 1 HANDRAHAN,E Industrial Testing Laboratory Bervices Corp 79/04/16 Spp

### DOCKET 71-0034 BABCOCK & WILCOX CO

7905020198 Forwards request for add1 info to complete review of QA program MACDDNALD.C E Transportation Branch 79/04/13 299

DOCKET 71-0034 ITT GRINNELL CORP

7905080128 Forwards GA progrem, in response to 790321 request for addition of the transfer of

---7905080134 "GA Program Radioactive Math Shipping Pactages "
4 International Talephone & Telegraph Corp 79/04/02 APpa

DOCKET 71-0038 CRANE CO

7905150329 Forwards QA program approval for radioactive mati partage MACDONALD, C E Transportation Branch 79/03/22 ip

--7905150303 OA program approval for radioactive matt package 0008, Raviation 0 MACDONALD: 0 E. Transportation Branch 79/03/22 ip

# DOCKET 71-0039 WALMORTH CO.

7905240140 Proposed GA program does not mest requirements of App E to 10CFR71 Forwards sample GA program for industrial radiography licensees det 790402; to assist in application revision. Requests revision by 790502 MACDONALD, C E Transportation Branch 79/04/27 Jpp

### DOCKET 71-0047 CAPITOL INTERNATIONAL AWYS . INC

- 7905130737 Forwards request for add1 info to complete review of GA program
  MACDDNALD.C E Transportation Branch 79/04/13 2pp
- 7905180692 Forwards GA requirements for transportation packaging in response to 790426 telcon
  EPARKS,E Capital International Airways, Inc. 79/04/27 1p
- --7905150699 "OA Requirements for Transportation Packaging (10CFR71) As Applicable to Industrial Radiography Licensess " + Capitol International Airways, Inc. 79/04/27. App

### DOCKET 71-0048 INTERMOUNTAIN PIPE & HELDING

7905150174 Proposed QA program does not meet requirements of App E to 10CFR71. Forwards sample QA program for industrial radiography licensees, dtd 790402, to assist in application revision Requests revision by 790527 MACDUNALD, C & Transportation Branch 79/04/27. 3pp

#### DOCKET 71-0050 MEDLAND-ROSE CORP

- 7905150318 Forwards QA program approval for radioactive math package MACDONALD.C E Transportation Branch 79/03/22 1p
- ~~7909150323 GA program approval for radioactive mat1 package 0050. Revision 0 MACDUNALD.C E Transportation Branch 79/03/22 to.

### DOCKET 71-0055 H R INSPECTION SERVICE

7905240904 Forwards addl info for approval of QA program ROCERS, H W H R Inspection Service 79/05/02. 2pp

### DOCKET 71-0054 PHILADELPHIA ELECTRIC CO

7905240184 Informs that Amend 35 to FBAR contains existing GA program in response to NRC 790321 request.
DALTROFF:8 L. Philadelphia Electric Co 79404/10 ip

### DOCKET 71-0057 EXXON CO USA, EXXON CORP.

7905300658 Forwards Radiation Safety Committee organizational chart, in response to NRC 790413 ltr.
HEILAND, R W Exxon Corp 79/04/20 2pp

### DOCKET 71-0063 DZARK AIRLINES, INC.

7905190682 Forwards request for additinfo to complete review of GA program. Requests statement that scope of audit program will include annual audit repersonnel training, personnel qualifications & record keeping.

MAGDONALD.C.E Transportation Branch 79/04/19 2pp

7905150004 Forwards GA Program for License 24-13591-01. YQUNO,R E Ozark Airlines 79/04/23 ip

--7905150094 GA Program for License 24-13591-01, # Grark Airlines. 79/04/23. 4pp.

### DOCKET 71-0045 H.P & ASSOCIATES, INC

1

Me i

7905240582 Proposed GA program does not meet requirements of App E to iOCFR71. Forwards temple GA program for industrial radiography licensees, dtd 770402, to assist in application revision. Requests revision by 790502.

MACDONALD, C. E. Transportation Branch. 79/04/27. 3pp.

### DOCKET 71-0066 CERTIFIED TESTING LABS . INC.

7905150160 Proposed GA program does not meet requirements of App E to 10CFR71 Forwards sample GA program for industrial radiography licensees, 4td 790402. to assist in application revision, Requests revision by 790427 MACDONALD, C E. Transportation Branch. 79/04/27. 3pp.

#### DOCKET 71-0068 YANKEE ATOMIC ELECTRIC CO

- 7905240311 Forwards GA program approval for radioactive matl package MACDONALD,C E Transportation Branch 79/05/Q4 1p
- --7905240318 GA program approval for radioactive mat1 package 0068, Revision 0 MACDONALD.C E Transportation Branch 79/05/04 ip

### DOCKET 71-0070 GENERAL MOTORS CORP

- 7905240565 Informs that proposed GA program does not meet requirements of App E to 10CFR71 Forwards sample GA program for industrial radiography licensees, dtd 770402, to assist in application revision Requests revision by 790520

  MACDONALD, C E Transportation Branch 79/04/20 ip.
- --7905240569 "GA Program for Industrial Radiography Licensess" \* Transportation Branch 79/04/02 2pp

### DOCKET 71-0072 BABCOCK & WILCOX CO

7905110069 Proposed GA program does not meet requirements of App E to 1005R71 Forwards sample GA program for industrial radiography licensees dtd 790402, to assist in application revision. Requests revision by 790502

MACDDNALD, C E. Transportation Branch. 79/04/27 3pp

### DOCKET 71-0074 NUCLEAR WELDING, INC

7908110071 Proposed QA program does not meet requirements of App E to 10CFR71 Forwards sample QA program for industrial radiography licensess and 790402, to assist in application revision Requests revision by 790502 MACDONALD. C. E Transportation Branch 79/04/27. 3pp

#### DOCKET 71-0077 MIDSTATE TESTING LAD

- 7905020255 Forwards GA Program for License 13-11822-01 KEILMAN.T.J Midstate Testing Laboratory, Inc. 79/04/05 ip.
- --7905020259 QA Program for License 13-11822-01 KEILMAN,T J Midstate Testing Laboratory, Inc. 79/04/05 App.
- 7903240165 Forwards request for add1 info to complete review of GA program
  HACDONALD, C.E. Transportation Branch 79/04/27 2pp

# DOCKET 71~0087 NAVY, DEPT, OF

790Bil0204 Proposed QA program does not meet requirements of App E to IOCFR71. Forwards sample QA program for industrial radiography licensees. dtd 790402. to assist in application revision. Requests revision by 790320.

HACDONALD.C E Transportation Branch. 79/04/20 3pp.

### DOCKET 71-0088 BABCOCK & HILCOX CO

7905020407 Forwards request for add1 info to complete review of GA program.

MACDONALD, C. E. Transportation Branch, 79/04/11 12pp

### DOCKET 71-0089 NAVY, DEPT. OF

7708070267 Forwards request for add1 info to complete review of GA program MACDONALD, C. E. Transportation Branch 79/04/13 2pp.

# DOCKET 71-0090 COMBUSTION ENGINEERING CO. : ING

7905250013 Responds to request for add1 info re GA program. Hill continue to use existing GA program until approval of GA Program CENFN-WH is obtained. Supporting documentation encil LICHTENSERGER. H Combustion Engineering. Inc. 79/04/11. App.

### DOCKET 71-0099 FOSTER WHEELER ENERGY CORP

7905070272 Forwards request for add1 info to complete review of GA program MACOONALD.C E Transportation Branch 79/04/13 2pp

### DOCKET 71-0103 THIN CITY TESTING & ENGR LAB

7905070279 Forwards request for add1 info to complete review of GA program.

MACDONALD.C E Transportation Branch 79/04/13 2pp

#### DOCKET 71-0104 CHICAGO BRIDGE & IRON CO

7905070292 Forwards request for add1 info to complete review of QA program MACDONALD, C. E. Transportation Branch 79/04/13 2pp

7905270511 Forwards QA program for License 12-05637-01 WEMRLE,8 R Chicago Bridge & Iron Co 79/04/18 2pp

--7905290514 GA program for License 12-05639-01.

\* Chicago Bridge & Iron Co 79/04/18 4pp

#### DOCKET 71-0109 UNION CARBIDE CORP

7905241000 Forwards request for add1 info to complete review of GA gragaten MACCONALD,C E Transportation Branch 79/04/20 12pp.

### DOCKET 71-0110 BUCKEYE STEEL CASTINGS

7904200311 Forwards request for add1 info to complete review of GA grogram MACDONALD,C E Transportation Branch 79/04/06 2ep.

7905240616 Forwards QA program for industrial radiography re handling & shipping of isotopes
KRANER.J F Buckeye International, Inc., Steel Castings Div.
79/04/27 3pp

--7905240715 GA program for industrial radiography = Buckeya International, Inc , Stael Camtings Div. 79/04/27. 4pp

# DOCKET 71-0111 MATERIAL TESTING LAS. OF VIRGINIA, INC.

7905110075 Proposed GA program does not meet requirements of App E to 10CFR71 Forwards sample GA program for industrial radiography licenses, dtd 790402, to assist in application revision Requests revision by 790502 MACDGNALD, C E Transportation Branch. 79/04/27. App

### DOCKET 71-0114 NAVY, DEPT, OF

790510210 Proposed GA program does not meet requirements of App E to 10CFR71 Forwards sample GA program for industrial radiography licensees, dtd 790402. to assist in application revision. Requests revision by 79020 MACDONALD Transportation Branch 79/04/20 3pp

### DOCKET 71-0119 INGERSOLL-RAND CO.

7903070237 Forwards request for add1 info to complete review of GA program. \*\*KACDONALD.C E Transportation Branch. 79/04/13. 2pp

### DOCKET 71-0120 DANIEL INTERNATIONAL CORP.

790511007B Proposed GA program dose not meet requirements of App E to 10CFR71.Forwards sample GA program for industrial radiography licensees, dtd 790402, to assist in application revision.Request revision by 790502, MACDONALD.C.E. Transportation Branch. 79/04/27 3pp.

### DOCKET 71-0121 NEVTRON PRODUCTS, INC

7905240156 Forwards request for add1 info to complete review of QA program
MACDDNALD,C E Transportation Branch 79/04/27 12pp

### DOCKET 71-0126 STANWICK CORP

7705150742 Forwards request for add1 info to complete review of GA program MACDONALD.C E Transportation Branch 79/04/13 2pp

### BOCKET 71-0127 NATIONAL ANNEALING BOX CO

7905070282 Forwards request for add1 info to complete review of GA program MACDONALD, C E Transportation Branch 79/04/13 2pp.

7905100104 Forwards organizational chart requested by NRC 790413 ltr. FRANTZ, J. R. National Annealing Box Co. 79/04/16 2pp

#### DOCKET 71-0128 AMGCO OIL CO

79051100B1 Proposed GA program does not meet requirements of App E to 10CFR71. Forwards sample GA program for industrial radiography licensees, dtd 790402, to assist in application revision Requests revision by 790502 MACDUNALD. C Transportation Branch 79/04/27 3pp

# DOCKET 71-0130 CHICAGO BRIDGE & IRON CO

7905070287 Forwards request for add1 info to complete review of @A program MACBDNALD.C.E Transportation Branch 79/04/13 2pp

### DOCKET 71-0131 WELDING INSTITUTE OF ALASKA

7905140119 Proposed GA program does not ment requirements of App E to fOCFR71 Forwards sample GA program for industrial radiography licensees, dtd 790402, to assist in application revision Requests revision by 790527 MACDONALD.C.E Transportation Stanch 79/04/27 3pp.

### DOCKET 71-0197 METALB TESTING CO . INC.

7909150078 Forwards "Shipping Container GA Requirements."
DELIGLE, R. Metals Testing Co., Inc. 79/04/16. ip.

---7905150088 "Shipping Container GA Requirements"

\* Metals Testing Co. Inc. 79/04/16 Opp.

# DOCKET 71-0141 ROCKWELL INTERNATIONAL

7905110084 Proposed GA program does not meet requirements of App E to 10CFR71 Forwards sample GA program for industrial radiography licensees, dtd 790402. to assist in application revision Requests revision By 790502.

MACDQNALD.C E Transportation Branch 79/04/27 3pp.

### DOCKET 71-0143 RANCHERS EXPLORATION & DEV. CO

7905240161 Forwards request for add1 info to complete review of GA program MACDONALD.C.E. Transportation Branch. 79/04/27. Spp.

#### DOCKET 71-0151 HESS OIL VIRGIN ISLANDS CORP

7905150265 Responds to request for addl info re QA program Discusses organization, decument control, handling, storage & shipping, insp. records & audits
PHELAN, N K Hess Dil Virgin Islands Corp 79/04/16 6pp

### DOCKET 71-0154 GENERAL DYNAMICS

7905270816 Informs that term "radiation safety officer" has been replaced w/"radiation protection officer" for License 20-11915-01
ROBERTS,V M General Dynamics Corp , Quincy Shipbuilding Div 79/04/16

### DOCKET 71-0156 INDUSTRIAL FABRICATING CO

7905110063 Proposed GA program does not meet requirements of App E to 10CFR71 Forwards sample GA program for industrial radiography licensees.dtd 790402.to assist in application revision Requests revision by 790502 MACDONALD.C E Transportation Branch 79/04/27 3pp

#### DOCKET 71-0158 X-RAY INDUSTRIES, INC

7905240285 Forwards info to clarify GA program for License 21-03472-01, in response to 790413 ltr THAMBOR W X-Ray, Inc 79/04/24 2pp

### DOCKET 71-0161 CURTISS-WRIGHT CORP

7905250354 Responds to NRC 790406 ltr re radioactive sealed source shipping procedure Forwards revised QA program JACKEON.C. Curtiss-Wright Corp. 79/05/01 1g

--7905250364 Revised QA program
JACKEON.C Curtiss-Wright Corp. 79/05/01. 4pp.

### DOCKET 71-0162 EBASCO SERVICES, INC

7905010185 Forwards request for add1 info to complete raview of GA program
MACDDNALD.C E. Transportation Branch 79/04/13 2pp

### DOCKET 71-0166 NEW YORK TESTING LABS: INC

7905150178 Forwards request for add1 info to complete review of QA program
MACDONALD, C E Transportation Branch 79/04/13, 2pp

### DOCKET 71-0147 FINLAY TESTING LABORATORIES

7905010169 Forwards request for addl info to complete review of GA program
MACDONALD.C E Transportation Branch 79/04/13 2pp

# DOCKET 71-0168 QUALITY ASSURANCE LABS

7905150205 Forwards request for add1 info to complete review of GA program
MACDONALD, C E Transportation Branch, 79/04/13 255

### DOCKET 71-0149 FLORIDA POWER & LIGHT CO.

7905240834 Forwards QA program approval for radioactive matl packages MACDONALD, C E Transportation Branch 79/05/04 ip.

---7905240839 GA program approval for radioactive mati packages MACDONALD.C E Transportation Branch. 79/03/04, ip

# DOCKET 71-0174 SOUTHERN CALIFORNIA EDISON CO.

7905240395 Ferwards chronology of FSAR amend re GA program, in response to NRC 790320 request
BASKIN, K.P. Southern California Edison Co. 79/04/27 3pp.

### DOCKET 71-0175 GC SERVICES, INC

7909020394 Forwards request for add1 info to complete review of QA program
MACDDNALD.C E Transportation Branch 79/04/13 2pg.

### DOCKET 71-0178 ENERGY PRODUCTS GROUP

7905020399 Forward's request for add1 info to complete review of QA program MACDDNALD.C E Transportation Branch 79/04/13 2pp

### DOCKET 71-0180 HARTFORD STEAM BOILER CO

7905020392 Forwards request for addl info to complete review of GA program MACDONALD.C E Transportation Branch 79/04/13 2pp

### DOCKET 71-0181 CONSOLIDATED X-RAY SERVICE CORP

7905110095 Proposed QA program does not meet raquiraments of App E to 10CFR71 Forwards sample QA program for industrial radiography licensees dtd 790402; to assist in application revision Requests revision by 790502
MACDONALD.C E Transportation Branch 79/04/27 3pp.

### DOCKET 71-0188 MAYNARD STEEL CASTING CO

7905130137 Proposed GA program does not meet requirements of App E to 10CFR71 Forwards sample GA program for industrial radiography licensees dtd 770402; to assist in application revision Requests revision by 790527 MACDONALD, C E Transportation Branch 79/04/27 Spp

### DOCKET 71-0189 TODD SHIPYARDS CORP

7905150167 Proposed GA program does not meet requirements of App E to 100FR71. Forwards sample GA program for industrial rediography licensees odd 790402, to assist in application revision Requests revision by 790527

MACDONALD, C E. Transportation Branch 79/04/27. 3pp

### DOCKET 71-0202 PACIFIC GAS & ELECTRIC CO

7903290011 Responds to 790313 itr Liets references to specific docketed info describing operational QA program CRANE:P A. Pacific Qas & Electric Co 79/04/20 ip.

### DOCKET 71-0205 GUALITY TESTING, INC.

-7908250016 Forwards GA program for use of approved packages in shipment of sealed sources MASTERSON, D. J. Quality Testing, Inc. 79/05/01. ip.

---7905250019 GA program for use of approved packages in shipment of sealed sources. MASTERSON:D J Guelity Testing: Inc 79/05/01 5pp.

# DUCKET 71-0207 CONNECTICUT YANKEE ATOMIC POWER CO

7905240503 Informs that latest revision to operational QA program is described in Revision 3A to QA rept NU-QA-1.forwarded to NRC on 790426 COUNSIL.W G. Connecticut Yankse Atomic Power Co. 79/04/26 ip

### DOCKET 71-0209 JACKSONVILLE SHIPYARDS, INC.

7905110065 Proposed GA program does not meet requirements of App E to 10CFR71 Forwards sample GA program for industrial radiography licensees dtd 790402, to assist in application revision, Requeste revision by 790502.

MACDUNALD, C. E. Transportation Branch. 79/04/27. Gpp.

DOCKET 71-0213 INTERMOUNTAIN TESTING CO

7905020386 Forwards request for add! info to complete review of GA program
MACDDNALD.C E Transcortation Branch 79/04/13 2cc.

DOCKET 71-0214 GAS RENTALS. INC

7905110067 Proposed QA program does not meet requirements of App E to IGCFR71 Forwards sample GA program for industrial rediography licensees dtd 790402; to assist in application revision Requests revision by 790502
MACDONALD.C E Transportation Branch 79/04/27 3pp

DOCKET 71-0215 SPACE SCIENCE SERVICES

7905100340 Proposed QA program does not meet requirements of App E to 10CFR71 Forwards sample QA program for industrial radiography licensees dtd 790402; to assist in application revision Requests revision by 790502 MACDONALD,C E Transportation Branch 79/02/15 3pp

DOCKET 71-0216 NUCLEAR ENERGY SERVICES, INC

7905020384 Forwards request for addl info to complete review of QA program MACDONALD, C E Transportation Branch 79/04/13 2pp

7905240632 Forwards GA Program 99-09-002
GAMBLE, 0 C Obsolete code , 79/04/27 1p

--7703240638 Responds to Dec 1978 application requesting approval of GA program Requests addl info re operating logs & results of insp MACDONALD.C E Transportation Branch 79/04/13 2pp

--7905240643 GA Program 99-0P-002
GAMBLE: 0 obsolete code 78/11/01 9pp

DOCKET 71-0217 PULLMAN KELLOGG. INC.

7905250227 Forwards request for add1 info to complete review of GA program
MACDONALD, C E Transportation Branch 79/04/04 2pp

7905150647 Responds to 790406 Itr requesting add1 info re GA program for License 42-165/3-01 Lists changes which will be incorporated into program TURNER:J E Pullman, Inc 79/04/17 1p

DOCKET 71-0220 GENERAL DYNAMICS CORP

7905020376 Forwards request for add1 info to complete review of GA program
HACEDNALD.C E Transportation Branch 79/04/13 2pp

DOCKET 71-0222 ST LOUIS YESTING LABS, INC

7905240273 Responds to 770406 request for info re GA program sections concerning radioactive math shipping package design & responsibility for performing critical handling b storage TROMBRIDGE, C D St Louis Testing Labs, Inc. 79704/24. 1p

DOCKET 71-0223 B F SHAW, INC

7905240291 Forwards request for add1 info to complete review of QA grogram MACDONALD.C E Transportation Branch 79/04/13 2pp.

DOCKET 71-0225 NAVY, DEPT OF

7905020194 Forwards request for add1 info to complete review of QA program \*\*ACCOMALD.C.E.\*\* Transportation Branch 79/04/13 2pp.

DOCKET 71-0226 NEW YORK, STATE UNIV. OF

7905020193 Forwards request for add1 info to complete review of GA program
MACDONALD, C E. Transportation Branch 79/04/13, 2pp

DUCKET 71-0234 X-RAY, INC

7905250066 Proposed QA program does not meet requirements of App E to iOCFR71. Forwards sample QA program for industrial radiography licensees, dtd 790402, to assist in application revision Requests revision by 790527 MACDONALD. C E Transportation Branch 79/Q4/27 3pp

DOCKET 71-0235 ARMY, DEPT OF

7905100342 Proposed QA program does not meet requirements of App E to 10CFR71 Forwards sample QA program for industrial radiography licensees.dtd 790402.to assist in application revision Requests revision by 790502
MACDDNALD.C E Transportation Branch 79/04/27 3pp

DOCKET 71-0238 AGRICULTURE, DEPT OF

7903:00167 Proposed GA program does not meet requirements of App E to 10CFR71 Forwards sample GA program for industrial radiography licensees, dtd 790402, to assist in application revision Requests revision by 790502 MACDONALD.C E Transportation Branch 79/04/27 3pp

DOCKET 71-0239 NAVY, DEPT OF

7908020191 Forwards request for add1 info to complete review of GA grogram MACODNALD.C E Transportation Breach 79/04/13 29p

DOCKET 71-0241 UNITED NUCLEAR CORP

7905240974 Forwards request for add) info to complete review of GA program MACDONALD,C E Transportation Branch 79/04/20 lips

DOCKET 71-0251 WESTINGHOUSE ELECTRIC CORP

7903290096 Responds to 790328 ltr Confirms that package suppliers need not have GA program approved per App E of 100FR71 Usar is responsible to ensure that all transportation activities meet specified criteria MAGDQNALD.C E Transportation Branch 79/04/26 ip

DOCKET 71-0255 WALWORTH CO

7905100347 Proposed GA program does not meet requirements of App E to 10CFR71 Forwards sample GA program for industrial radiography licensees dtd 790402, to assist in application revision. Requests revision by 790502 MAGDONALD.C E Transportation Branch 79/04/27 Spp

DOCKET 71-0257 INDUSTRIAL LASS, INC.

7905100352 Proposed GA program does not meet requirements of App E to 10CPR71 Forwards sample GA program for industrial radiography licensees dtd 790402, to assist in application revision, Requests revision by 790502 MACDONALD, C E Transportation Branch 79/04/27, 3pp

DOCKET 71-0260 ABTROTECH: INC

7905110199 Proposed GA program does not meet requirements of App E to IOCFR71. Forwards sample GA program for industrial radiography licensees, dtd 790402, to assist in application revision Requests revision by 790320 HACDDNALD, C E Transportation Branch. 79/04/20 3pp.

DOCKET 71-0261 NAVY, DEPT OF

### DOCKET 71-0266 DUKE POWER CD

- 7905240214 Commits to applying Revision 4 to QA topical rept.Duke-1-A, to comply w/10CFR71 15 requirements.in response to 790402 ltr PARKER.W O Duke Power Co 79/04/11 ip
- 7905240835 Forwards QA program approval for radioactive matt package MACDONALD.C E Transportation Branch. 79/05/01 ip
- ---7905240845 GA program approval for radicattive matl packages issued to Duke Power Co MACDONALD.C © Transportation Branch 79/05/01 ip

### DOCKET 71-0268 NAVY, DEPT OF

7905100339 Proposed GA program does not meet requirements of App E to 10CFR71 Forwards sample GA program for industrial radiography licensees dtd 790402. to assist in application revision Requests revision by 790502 MACDDNALD.C E Transportation Branch 79/04/20 3pp

#### DOCKET 71~0273 NAVY, DEPT OF

7905100448 Proposed QA program does not meet requirements of App E to 10CFR71 Forwards sample QA program for industrial radiography licenses, dtd 790402. to assist in application tevision Requests revision by 790502 MACDONALD, C E Transportation Branch 79/04/20 3pp

### DOCKET 71-0277 ALLIED CHEMICAL CORP

- 7905070228 Forwards request for add1 info to complete review of QA program MACDDNALD.C E Transportation Branch 79/04/11 12pp.
- 7905240867 Responds to 7904i1 ltr Will discuss GA program during 790502 meeting Will rewrite program to meet NRC requirements
  NEWMAN.R I Allied Chemical Corp 79/04/27 ip

### DOCKET 71-0280 ABCO PERFORATORS, INC

- 7905150214 Forwards QA program for License 4-1723, authorizing shipment of radioisotopes COOX.C L Abco Perforators, Inc 79/03/12 2pp
- --7905150474 GA program for License 4-1723; outhorizing shipment of radioisotopes COOK.C L Abou Perforators, Inc. 79/03/12 3pp

### DUCKET 71-0282 NKM WELLHEAD SYSTEMS, INC.

7905290251 Forwards GA program for License LA-2365-LOI CANNON:E WKM Wellhead Systems: Inc. 79/03/14 Spp.

# DOCKET 71-0286 BPB INSTRUMENTS, INC

1

A STATE OF THE STA

- 7905150026 Forwards QA program for License 13-17342-01 ORACE, J. O BPS Instruments: Inc 79/03/19, 1p.
- --7905150027 GA program for Litense 13-17342-01.for compliance w/10CFR71. App E. GRACE J.O BPB Instruments, Int. 79/03/19 App

### DOCKET 71-0287 CARSON NON-DESTRUCTIVE TESTING

7905290318 Forwards request for add1 info to complete review of GA program MACDONALD, C.E Transportation Branch. 79/04/13 2pp.

### DOCKET 71-0288 NORTH DAKOTA STATE WATER COMMISSION

- 7905100393 Forwards QA program for License 33-06501-01 BURKE,P A North Dakota, State of. 79/03/16, 1p.
- ---7905100398 "GA program of ND State Hater Commission" for compliance w/100FR71,App E.
  BURKE,P.A North Dakota, State of 79/03/15 3pp

### DOCKET 71-0290 UNITED TESTING SERVICES, INC

7905250281 Forwards QA program of United Testing Svc implemented for LA-2717-L01 per 10CFR71. App E requirements W/two oversized pages

# United Testing Services. Inc 79/03/20 4pp

### DOCKET 71-0296 IOHA ELECTRIC LIGHT & POWER CO

- 7905100400 Plans to modify GA program in order to implement shipping activities No further shipments of Type B radwaste will be 'made until approval is received from NRC LIV.L. Iowa Electric Light & Power Co 79/03/16 ip
- 7905150723 Forwards GA program approval for radioactive matl package MACDONALD, C E Transportation Branch 79/04/10 2pp

### DOCKET 71-0297 E LEWIS COOK & ASSOCIATES

- 7905270463 Forwards QA program for License R-3333-L5 HUCKABEE.K W E Lewis Cook & Associates 79/03/21 ip
- --7905290469 QA program for Litense R-3933-L5 HUCKABEE:K W E Lewis Cook & Associates 79/03/21 4pp

### DOCKET 71-0299 QUALITY CONTROL SERVICES. INC

- 7905240175 Forwards GA program for License 13-14856-01 SACHSE, J. Quality Control Services, Inc. 79/03/30. 1p
- --7905240183 QA program for License 13-14856-01 BACHSE, J Quality Control Services, Inc. 79/03/30. 24pp

### DOCKET 71-0300 INDEPENDENT TESTING LABORATORIES

- 7905170296 Forwards GA program for License 03-15981-02 SWAIN.W E Independent Testing Laboratories 79/03/26 ip
- --7905170299 GA program for License 03-15981-02 SWAIN.W E Independent Testing Laboratories 79/03/26 5pp

### DOCKET 71-0304 TELEDYNE BROWN ENGINEERING CO.

- 7705290305 Forwards GA program for State of AL License 579 HEYER:W A Teledyne Brown Engineering Co 77/03/27 ip
- --7905290309 GA program for State of AL License 599
  MEYER.W A Teledyne Brown Engineering Co 79/03/27 3pp

### DUCKET 71-0305 AMERICAN X-RAY & INSPECTION, INC

- 7705100361 Forwards GA program for License 21-15455-01 QRASHAW.T D American X-Ray & Inspection 79/03/30. 1p.
- --7905100365 GA program for License 21-19458-01. GRASHAW, T D. American X-Ray & Inspection 79/03/01. Spp

# DOCKET 71-0307 TEXAS PIPE BENDING CO OF PUERTO RICO

- 7905100368 Forwards GA program for License 52-13632-01 WARREN.H.C. Texas Pips Bending Co (subs of Bendix Corp ). 79703/30 ip.
- ~~7905100367 GA program for License 52~13632~01 WARREN.M C. Texas Pipe Bending Co. (subs. of Bendix Corp.). 79/03/27 5pp

# DOCKET 71-0309 WORTHINGTON PUMP CORP. (UBA)

7903150763 Forwards QA program for License 27-02210-02 MOLYNEUX, E. L. Worthington Pump, Inc. (subs of Studebaker-Worthington, Inc.). 79/03/30, ip

~-7905180766 GA program for License 29-02210-02 HOLYNEUX,E L. Worthington Pump, Inc. (subs. of Studebaker-Worthington, Inc.) 79/01/01 7pp

DOCKET 71-0311 LOGWELL, INC.

7705150689 Forwards 0A program for License 35-13365-01 BAILEY.F 9 Logwell 79/03/30 1p

--7905150693 GA program for License 35-13565-01 BASLEY.F 0 Logwell 79/03/30 4pp

DOCKET 71-0312 METALFORMS, INC

7905130626 Porwards GA program for License 8-2261. BENNETT.C Metalforms, Inc. 79/03/29 1p

--7905180632 0A Program for License 8-2261 BENNETT C Metalforms Inc 79/03/29 43pp

DOCKET 71-0317 HUDSON PRODUCTS CORP

7705240R06 Forwards QA program for License 8-2370 BENEFIELD,W E Hudson Products Corp 79/04/16 ip

--7905240210 QA program, for License 8-2370 BENEFIELD.W E Hudson Products Corp 79/04/16 49p

DOCKET 71-0322 CONTROL COMPONENTS INTERNATIONAL

7905290081 Forwards QA program of Control Components Intl.implemented for License 3265-30,8tate of CA LAHRENCE.H Babcock & Wilcox Co 79/04/11 1p

--7905290084 QA program implemented for License 32A5-30 State of CA LAWRENCE,M. Babcock & Wilcox Co ' 79/04/11 3pp

SOCKET 71-4986 MODEL RA-2, EXXON NUGLEAR CD . INC

7705240D17 Forwards Revision 4 of Certificate of Compliance 4986 for shipping package Models RA-1,2,3 % J
MACDONALD,C E Transportation Branch 79/04/26. 2pg

--7903240020 Certificate of Compliance 4986.Revision 4.for radioactive mati shipping package Models RA-1.2.3 & J MACDONALD.C E Transportation Branch 79/04/26 App

DOCKET 71-5026 MODEL BC-48-220, ATCOR, INC

7905240608 Informs that operations & assets of Protective Packaging, Inc were transferred from Nuclear Engineering Co to Teledyne Energy Sys in Jan 1979, Requests applicable certificates of compifence to changed to this effect. HALL, W.C. Teledyne, Inc 79/04/06. 1p

DOCKET 71-5450 MODEL RCC-1, -2, -3, WESTINGHOUSE ELECTRIC CORP.

7905020307 Withdraws proprietary portion of application for revision of Certificate of Compliance 5450 to include authorization of RCC-4 type shipping package Matl being reclassified as nonproprietary DIPIATZAR P. Westinghouse Electric Corp 77/04/06 ip.

7705240209 Requests registration as user of Model 5450 DUNN: C N Duquesne Light Co 77/04/10 lp.

DOCKET 71-5790 MODEL A1-M3, ENGERY, DEPT OF

790523069: Informs that Albuquerque Operations Ofc 790:30 ltr responding to NRC 78:10: request for addl info for Models AL-M3 & AL-M6 packages did not fully answer questions Requests advisement of further info within 30 days. MACDONALD, C.E. Transportation Branch 79/03/30 1p DOCKET 71-5791 MODEL A1-M6, ENERGY, DEPT OF

7905230691 Informs that Albuquerque Operations Ofc 790130 ltr responding to NRC 781101 request for add1 info for Models AL-M3 & AL-M6 packages did not fully answer questions Requests advisement of further info within 30 days MACBONALD.C E Transportation Branch 79/03/30 ip

DOCKET 71-5795 MODEL NONE, ENERGY, DEPT OF

7905140053 Forwards 790226 itr requesting registration as user of ORNL feamglass shipping container Since this is DOE-approved package.DUE field ofc should be contacted MAGDONALD.C E Transportation Branch 79/04/13 ip

--7905160098 Requests authorization as shipper of ORNL foamglass shipping container under same terms & conditions listed in Certificate of Compliance 5795
KREENEY, W.P. Argonne National Laboratory 79/02/26 lp

DOCKET 71-5805 MODEL ATCOR VADB CASK, ATCOR, INC

7905230847 Requests add1 info to complete review of 790124 application for amend to Model Vandenburgh packaging Requests delineation of changes made to Drawing 0999-D-07.Revision F MACDONALD.C Transportation Branch 79705/10 ip

DOCKET 71-5908 MODEL. DOT-GM TYPE B. BARCOCK & WILCOX CO

7705300490 Requests revised Certificte 3708 for 6M packaging MOTT.W E Energy, Dept of 77/04/20 ip

DOCKET 71-5926 MODEL 100, GENERAL ELECTRIC CO

7905180627 Forwards updated version of drawings of GE Model 100 shtpging container due to incremental editorial changes W/12 drawings CUNKINGHAM. GE General Electric Co 79/04/09 5pp

DOCKET 71-5957 MODEL BM1-1: ENERGY DEPT OF

7905080180 Notification of registration as user of Model BMI~1 in response to 790223 request MACDUNALD.C E Transportation Branch 29/04/20 1p

DOCKET 71-6058 MODEL 83-1, NUCLEAR ENGINEERING CO

7905070047 Notifies that Model B3-1 packaging may not conform to design approval in Certificate of Compliance 8058. Revision 3 Users should confirm that packages were properly fabricated before use.

MACDONALD.C E Transportation Branch 79/04/02 2pp

--7905070088 Follows up 770312 ltr re review which disclosed that shipping cast Model 83-t lifting lugs have been fabricated out of stainless steel rather than Cor-ten as specified in Certificate of Compliance 6058 VOTH,M M Union Carbide Corp 79/03/22 ip

7905240608 were tran Energy Sy compliant HALL.W C

7905150281 Heat shie & found c VOTH, M H

7905100126 Radioacti Inc Ship; of cask BURIAN, R, 79/04/21

7905250219 shipping MACDONALI

--7905250226 Certificate of Compliance 6058 Revision 4 for radioactive mat1 shipping package Model 83-1 MACDONALD C E Transportation Branch 79/04/27 3pp

### DOCKET 71-6144 MODEL 6144. NUCLEAR ENGINEERING CO

- 7905240608 Informs that operations & assets of Protective Packaging, Inc were transferred from Nuclear Engineering Co to Teledyne Energy Sys in Jan 1979 Requests applicable certificates or compliance be changed to this effect HALL, W C Teledyne. Inc 79/04/06 ip
- 7908070075 Forwards Revision 3 of Certificate of Compliance 6144 for thipping package Model 6144 MACDONALD, C E Transportation Branch 79/04/23 3pp
- --7905070081 Certificate of Compliance 6144.Revision 3.for radioactive matl shipping package Model 6144. MACDONALD.C E Transportation Branch 79/04/23 3pp

# DOCKET 71-6244 MODEL 6244, CHEM-NUCLEAR SYSTEMS, INC

- 7905240187 Notifies that info requested in 790316 ltr will be forwarded by 790330 REYNOLDS.L E Chem-Nuclear Systems. Inc 79/04/i1. Ip
- 7905240112 Notifies that Certificate of Compliance 6244 for shipping package Model 6244 expires 790531 Renewal must be requested MACDUNALD.C E Transportation Branch 79/04/12 ip
- 7905300636 Responds to 790412 notice of 790531 expiration of Certificate of Compliance 6244 Expects to submit application for license renewal & amend by 790530 REYMOLDS.L E Chem-Nuclear Systems, Inc 79/04/20 1p
- DOCKET 71-6272 MODEL POLY PANTHER, NUCLEAR ENGINEERING CO
- 7905240608 Informs that operations & assets of Protective Packaging, Inc were transferred from Nuclear Engineering Co to Teledyne Energy Bys in Jan 1977 Requests applicable certificates of compliance be changed to this effect HALL-W C Teledyne, Inc 79/04/06 ip
- 7905070302 Forwards Revision 2 of Certificate of Compilance 6272 for shipping package Model Poly Pankher MACDONALD, C E Transportation Branch 79/04/23 2pp
- --7905DY0307 Certificate of Compliance 6272, Revision 2, for radioactive mat1 shipping package Hodel Poly Panther MACDONALD, C E Transportation Branch 79/04/23 2pp.

### DOCKET 71-6273 MODEL: 48X, F. A. Y. ALLIED-GENERAL NUCLEAR SERVICES

7905240128 Responds to 781108 ltr requesting review of "U Hexafluoride Handling Procedures & Container Criteria."ORG-651.
Revision 4.dtd Apr 1977 Unacceptable replacement for Revision Gigeneral notes deleted MACDONALD, C E Transportation Branch 79/04/26, 1p.

### DOCKET 71-6346 MODEL: FSV-1, GENERAL ATOMIC CO.

7905020387 Forwards add1 info supporting application for shipping cask dasign using alternate closure configuration Derived analyses show impact limiter protects cask closure, assuring radioactive matis will not be released to environ.

MOMRY, W R Deneral Atomic Co (subs. of Gulf Oil Corp ) 79/04/06
5300.

### DOCKET 71-6386 MODEL 235ROO1, ENERGY, DEPT, OF

- 7903250341 Forwards Revision A of Certificate of Compliance 6386 for shipping package Model 233R001. MACDONALD.C.E. Transportation Branch. 79/05/01 1p.
- --7903250346 Certificate of Compliance 6386, Revision 4, for radioactive mat1 shipping package Model 235R001, MACDONALD, C E Transportation Branch. 79/05/01, 3pp

- DOCKET 71-6387 MODEL: 40. BATTELLE MEMORIAL INSTITUTE
- 7909020270 Forwards 790319 ltr from HEDL requesting mods of NRC certificate of compliance to reflect new types & sizes of fuel pins FITZBIMMONS, T.R. Energy, Dept of 79/04/05 Spp
- DOCKET 71-6400 HODEL-SUPER TIGER, WESTINGHOUSE ELECTRIC CORP
- 7905:50664 Informs that info requested re amend to Certificate of Compliance 6400 will be submitted by 790430 MICHEL.C J Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.) 79/03/23 1p
- 7905300136 Forwards request for exemption from 10CFR71 42(b) re shipment of waste matl in Model Super Tiger shipping container. DIPIAZZA.R P Hastinghouse Electric Corp 79/04/03 1p
- ---7905300142 "Info for Pu Waste Drum Shipments "
  # Westinghouse Electric Corp 79/04/03 9pp
- 7905240608 Informs that operations & assets of Protective Packaging, Inc were transferred from Nuclear Engineering Co to Teledyne Energy Sys in Jan 1979 Requests applicable certificates of compliance be changed to this effect HALL.N C Teledyne, Inc 79/04/06 in
- 7905240036 Forwards Revision 5 of Certificate of Compliance 6400 for thipping package Model Super Tiger MACDONALD, C E Transportation Branch 79/04/26 3pp
- --7903240039 Certificate of Compliance 6400.Revision 5, for radioactive math shipping package Model Super Tiger HACDONALD.C E Transportation Branch 79/04/24 69p

#### DOCKET 71-6553 MODEL PADUCAH TIGER, ENERGY, DEPT, OF

- 7905240128 Responds to 781108 ltr requesting review of "U Hexafluoride Handling Procedures & Container Criteria,"GRG-651, Revision 4, dtd Apr 1977 Unacceptable replacement for Revision Gigeneral notes deleted MACDONALD, C.E Transportation Branch 79/04/26 1p
- DUCKET 71-6679 MODEL 1/2 SUPER TIGER, NUCLEAR ENGINEERING CO
- 790524060B Informs that operations & assets of Protective Packaging inc were transferred from Nuclear Engineering Co To Teledyne Energy Bys in Jan 1979, Requests applicable certificates of compliance be changed to this effect HALL, W C Teledyne, Inc 79/04/06 ip
- 7905250305 Forwards Revision 2 of Certificate of Compliance 6679 for shipping package Model Half Super Tiger MAGDDNALD, C. E. Transportation Branch. 79/04/26. 2pp
- --7909250316 Certificate of Compliance 6679.Revision 2, for radioactive matl shipping package Model Half Super Tiger MACDUNALD,C E Transportation Branch 79/04/26. Spp.

### DOCKET 71-6697 MODEL. 8500 PKG. GENERAL ELECTRIC CO.

- 7905240327 Forwards Revision 4 of Certificate of Compliance 6697 for shipping package Model GE-8300 MAGDGNALD, C. E. Transportation Branch 79/05/08, 2pp
- --7908240331 Certificate of Compliance 6697. Revision 4, for radicactive mat1 shipping package Model GE-8500.
  MAGDONALD.C E. Transportation Branch 79/05/08. 2pp
- DOCKET 71-6698 MODEL. NFS-4, NUCLEAR FUEL BERVICES, INC
- 7905020282 Reports deviation of NAC-1 cask from specs in certificate of compliance Corrective action being taken ROLLING.J D. Nuclear Assurance Corp. 79/04/02 2pp

- 7905020176 Forwards order to show cause, effective immediately, which prohibits further use of Model NFS-4 package, requires syalustion of deviations from design approval & requires further order of NRC to return packagings to svc DIRCKS.W J Office of Nuclear Material Safety & Safeguards 79/04/06 2pp
- --7905020180 Order to show cause effective immediately prohibiting further use of Model NFS-4 package requiring evaluation of deviations from design approval & requiring further order of NRC to return packaging to svc DIRCKS.W J Office of Nuclear Haterial Bafety & Safeguards 79/04/06 3pp
- 7705300668 Responds to NRC 770406 itr Util has no plans to use NFS-4 packaging to thip nuclear fuel in near future.

  BAYNARD, P Y Florida Power Corp 77/04/16 1p
- 7903240414 Requests extension until 790515 to respond to 790406 order to show cause re Nuclear Assurance Corp cask Model NFS-4, MCGARRY, J.M. Debeyoise & Lieberman 79/04/30 ip.
- DOCKET 71-6744 MODEL POLY TIGER: NUCLEAR ENGINEERING CO
- 7905240608 Informs that operations & assets of Protective Packaging Inc were transferred from Nuclear Engineering Co To Teledyne Energy Bys in Jan 1979 Requests applicable contificates of compliance be changed to this effect HALL, H C Teledyne, Inc 79/04/06 1p
- 7905090089 Forwards Revision 2 of Certificate of Compilence 6744 for shipping package Model Poly Tiger
  KACDONALD,C E Transportation Branch 79/04/24 Spp
- DOCKET 71-6771 MODEL SN-1, NUCLEAR ENGINEERING CO
- 790324060B Informs that operations & assets of Protective Packaging Inc were transferred from Nyclear Engineering Go to Teledyne Energy Sys in Jan 1979 Requests applicable certificates of compliance be changed to this effect HALL, W.C. Teledyne: Inc. 79/04/06. 1p
- 7905070290 Forwards Revision 2 of Certificate of Compliance 6771 for shipping package Model BN-1 MACDDNALD.C E Transportation Branch 79/04/24. 2pp
- --7905070295 Certificate of Compliance 6771, Revision 2, for radioactive math shipping package Model SN-i MACDOMALD, C E Transportation Branch 79/04/24 2gp.
- DOCKET 71-9009 MODEL FL 10-1, GENERAL ELECTRIC CO
- 7903240910 Requests amend to Certificate of Compliance 9009 Revision 2 re Model FL 10-1 shipping package Diagram of container arrangement enci
  CUNNINGHAM G E General Electric Co , Nuclear Energy Products Div
  79/04/16 4pp
- 7905290091 Forwards Revision 3 of Certificate of Compliance 9009 for shipping package Model FL 10-1
  MACDONALD.C E Transportation Branch, 79/05/04. 2pg
- ---7905279046 Certificate of Compliance 9009, Revision 3, for radioactive mat1 shipping package Model FL 10-1 MACDQNALD.C E. Transportation Branch. 77/05/04 4sp.
- POCKET 71-9010 MODEL NLI-1/2, NL INDUSTRIES, INC.
- 770B290071 Requests registration of listed parties as users of Model MLF-1/2 cask. Users have Revision 4 of certificate of compliance Requests forwarding of future revisions RQSS, D. M. Energy, Dept. of. 79/05/01 1p
- 7905150576 Notification of registration as user of Model NLI-1/2 package 9010, in response to licensee 790501 request MACDONALD, C.E. Transportation Branch. 79/05/02 1p.

- DOCKET 71-9023 MODEL NL1-10/24, NL INDUSTRIES, INC
- 7905250211 Informs that licenses will provide requested info by 790615 MILLIAMS, C.E. NL Industries, NL Nuclear Div. 79/03/28 ip
- DOCKET 71-9033 MODEL, 640 & 640E. TECHNICAL OPERATIONS, INC.
- 7905240348 Requests revision to Certificate of Compliance 9033, Revision 2, to include correct address for American Airlines ANDERSON, C.R. American Airlines, Inc. 79/04/06 1p
- DOCKET 71-9044 MODEL GE-1600, GENERAL ELECTRIC CO
- 7905290076 Requests registration as user of Model GE-1600 radioactive matl shipping package OPEKA-J F Northeast Utilities 79/04/27 1p
- DOCKET 71-9070 MODEL N-\$5, ENERGY, DEPT. OF
- 7905240244 Notification of registration as user of Model N-85, in response to licensee 790222 request.

  MACDONALD, C E Transportation Branch 79/08/04 ip
- DOCKET 71-9079 MODEL: MN-100 SERIES 2, HITTMAN NUCLEAR & DEVELOPMENT
- 7905100079 Responds to 790312 ltr re driver checklists submitted w/ BARs for various radwaste packages Unless checklists are specifically required by certificate of compliance users may develop their own procedures MACDONALD.C.E Transportation Branch 79/04/13 ip
- DOCKET 71-9080 MODEL HN-600. HITTMAN NUCLEAR & DEVELOPMENT CORP
- 7905100079 Responds to 790312 ltr re driver checklists submitted w/ BARs for various radwaste packages Unless checklists are specifically required by certificate of compliance users may develop their own procedures

  MACDONALD.C E Transportation Branch 79/04/13 ip
- DOCKET 71-9086 MODEL EN-100 SERIES 1. HITTMAN NUCLEAR & DEVELOPMENT
- 7903100079 Responds to 790312 ltr re griver checklists submitted w/ BARs for various radwaste packages Unless checklists are specifically required by certificate of compliance users may develop their own procedures MACDONALD. C. E. Transportation Branch. 79/04/13 1p
- DOCKET 71-9089 HODEL NH-100 8, HITTMAN NUCLEAR & DEVELOPMENT CORP.
- 7905100079 Responds to 790312 ltr re driver checklists submitted e/ BAR4 for various radwaste packages. Unless checklists are specifically required by certificate of compliance, users may develop their own procedures. MACDONALD.C E Transportation Branch 79/04/13 is.
- DOCKET 71-9090 MODEL: 480M, ALLIED CHEMICAL CORP.
- 7905240128 Responde to 781108 itr requesting review of "U Herefluoride: Handling Procedures & Container Criteria: "ORD-651; Revision A.dtd Apr 1977. Unacceptable replacement for Revision 3; general notes deleted.
  MAGDONALD, C Trânsportation Branch. 79/04/26 1p.
- DOCKET 71-9091 MODEL 30 AJ GENERAL ELECTRIC CO.
- 7905240128 Responds to 781108 ltr requesting review of "U Hsxaflouride:Handling Procedures & Container Griteria," DRD-651.Revision 4.466 Apr 1977. Unacceptable replacement for Revision 31 general notes deleted MACDONALD.C E Transportation Branch 79/04/24. 1p.

# **DOCKETED ITEMS**

DOCKET 71-9092 MODEL HN-300, MITTMAN NUCLEAR & DEVELOPMENT CORP

7905100079 Responds to 790312 ltr re driver chacklists submitted w/ BARs for various radwaste packages Unless checklists are specifically required by certificate of compliance, users may develop their own procedures

MACDONALD. C Transportation Branch 79/04/13 1p

DOCKET 71-9093 MODEL HN-400, HITTMAN NUCLEAR & DEVELOPMENT CORP

7905100079 Responds to 790312 ltr re driver checklists submitted w/ SARs for various radwaste packages. Unless checklists are specifically required by certificate of compliance, users may develop their own procedures MACDONALD. C E Transportation Branch 79/04/13 1p

DOCKET 71-9116 MODEL CN6-BOB, NUCLEAR PACKAGING, INC.

7905240497 Requeste info re status of application for certificate of compliance authorizing shipment of nuclear matl in NuPac CN6-BOB shistoid cask HANSEN, L. J. Nuclear Packaging, Inc. 79/04/26 ip

DOCKET 71-9120 MODEL TN-12, TRANSNUCLEAR CORP

7905150788 Withdraws method proposed in 790131 ltr to demonstrate fracture toughness of Tn-12 containment vessel steels Outlines new aproach GCLDMAN, K Transnuclear, Inc. 79/04/06 3pp

7905230066 Forwards Revision 1 to SAR of TN-12 packaging, in response to 780907 request for add1 info
MACKLIN,L Transnuclear, Inc. 79/04/30 500pp

DUCKET 71-9132 MODEL T-3, NUCLEAR PACKAGING, INC

7905150786 Notifies that licensee will respond to 790305 request for add1 info re T-3 shipping cask by 790601 SINCHUR, J D Nuclear Packaging, Inc. 79/04/05 1p

DOCKET 71-9506 MODEL MS27684-2, ENERGY, DEPT OF

7905220105 Forwards drawings for shipping container Model 9806.as requested in 790302 memo BLAUVELT.R K Monsanto Co 79/03/27 18pp

7905240099 Requests add1 info re Model MS 27684-2 package Albuquerque Operations Ofc 790302 response not sufficient Requests 30-day notification if info will be provided MACODNALD.C E Transportation Branch 79/04/27 ip

DOCKET 71-9785 HODEL SZW/SZWA, ENERGY, DEPT OF

7905020264 Forwards response to NRC 781221 comments re SAR for shipment of S2H/S2Ha spent core cartridge shipping container.
BRODSKY,R S Energy, Dept of 79/04/05 12hp

DOCKET 71-9852 MODEL DT-14, ENERGY, DEPT. OF

7905020170 In ref to 780802 ltr, requests addl info for review of Hodel DT-14 shipping package MACDONALD, C E Transportation Branch 79/04/06 2pp

- 7f04130020 Informs of review of all category A.B.C & D generic technical activities & categorization according to risk. Requests comments on Ofc of Nuclear Regulatory Research rept & draft Commission paper by 781101. DEYOUNG, R.C. Division of Site Bafety & Environmental Analysis, 78/10/27 2pp
- PP04160268 Forwards Rept 7 on status of generic items re LLRs In effort to simplify referencing numbering sys for generic items has been revised CARBON.M W ACRS Advisory Committee on Reactor Safeguards 79/03/21 35ec.
- 7904170091 Research Info Ltr 46 discusses effectiveness of cable tray coating mats & barriers in ratarding combustion of cable trays subjected to exposure fires & in preventing propagation between cable trays.

  LEVINE, 8 Division of Reactor Safety Research 79/02/04 11pp.
- PTG4170363 Responds to 780906 memo re NMSS/NRC interface on input from different branches. Environ Projects, Geosciences, Mateorology (Agriculary & Accident Analysis, DeyOuNo, R.C. Division of Site Safety & Environmental Analysis, 78/10/26 6pp
- 7904170521 Responds to request for comments on U Hill Tailings Refletion Act of 1978 MRC has regulatory jurisdiction over mill tailings until Bill09 & should conduct specific mill tailings licensing proceedings. BCHIFTER, R.O. Fried, Frank, Harris, Shriver & Kampelman. 79/03/30 Zas
- P904180171 Forwards rept of Review Oraup for EPA, "Risk Assessment of Radioactive Neste Isolation in Deep Declogic Formations" ROBERTS, I C. Assistant Director for Siting Standards. DULLINGFORD, M. Probabilistic Analysis Branch 79/03/16 Spp.
- ---T904180175 "Risk Assessment of Radioactive Haste" Isolation in Desp Geologic Formations: " from 781204-08 meeting of Review Group for EPA. \* Assistant Director for Siting Standards. 78/12/08 55pp
- -- 7704180179 Responds to 781129 memo re status of AD Little repts & EPA planned use in developing radioactive waste stds. Repts are in draft stages & will be used as partial support for waste stds.

  MARTIN, J E Environmental Protection Agency. 78/11/30 1p
- 7904190311 Summary of 781111 meeting w/NRC GA Review Team re plans to review GA practices. BENNETT.G.L. Research Support Branch. 79/04/12. SOpp.
- 77042100&1 Burmary of 79040& meeting w/Research Review Group re future tourse of project "Post~Licensing Studies of Socioeconomic impacts of Nuclear Power Plant Biting." FRICHARD.C. Environmental Effects Research Branch. 79/04/06 3pp.
- 7904210768 Responds to 790224 ltr re perimeter fence requirements. Forwards portion of "Barrier Technology Handbook" which discusses perimeter fences. PRELL-J.A. Safeguards Standards Branch, 79/03/19, 21pp.
- --7904210770 Responds to 790224 1tr re perimeter fence requirements. Inquiry has been forwarded to NRC headquarters. ARRAMAN. K. Region 1, Philadelphia, Office of the Director. 79702728. (p.
- --7904210774 Requests info re regulations & stds re fence design for nuclear plants.
  800TT.R. Bartlett Consolidated, Inc. 79/02/24, ip.
- 7904240389 Forwards product promotional info for iron oxide mortar to be used as fail-safe passive heat sink for reactors. If each plant can contain worst possible accident, antiquolear forcas will be rendered ineffective.

  MRLL.N.C. Chemtree Corp. 79/04/12. 2pp.
- ~-7704240392 Ack receipt of 760805 ltm concerning reduction of probability of extended reactor outages by using high thermal reactivity concrete. NRC cannot mendate use of product Urges continued scales affort.

  HEINEMAN.R.E. Division of Systems Safety. 76/08/31. 1p.
- --- 7704240395 "Assured Above & Below Ground Containment of a Class 9 Accident to a Nuclear Power Reactor." HALL, M. C. Chemtree Corp. 79/03/30, 21pp.
- 7704300173 Certificate of disposition of matte under License 20-05838-01 Matte transferred to Tracerlabilec. MEISS, N. M. Metals & Controls Corp. 70740. 45/08/13. 1p.

- --7904300258 Matis under License 20-5838-2 have been transferred to Curtise-Hright Co. DUFF,P A Metals & Controls Corp. 63/05/20 1p
- --7904300319 Application for amend of Matl/Byproduct License 20-05838-1 authorizing 8r-90 to be used in beta gauge 8ANDERB, H. E. Metals & Controls Corp. 34251. 61/04/27. 2pp.
- --7904900328 Certificate of disposition of matts under License 20-05838-03 disposing of Er-90 by burial at Nuclear Engineering sits in Morshead.KY on 770628.

  JOLANN D B Texas Instruments, Inc. 3101. 77/08/22. 1p
- --7904300341 Certificate of disposition of matts under License-05838-03 20-05838-03 transferring Co-60 to Tracerlab, Inc WEISS.N.M. Metals & Controls Corp. 76474 67/08/18, 1p
- --7904300342 Matl/Byproduct License 20-03838-3 for Netals & Controls, Inc is amended per 650820 application authorizing any byproduct matl. Co-60 k 8r-90 to be used for repair & mod of non-fuel reactor components & film calibr BRIMMAN, R.E. Atomic Energy Commission (Pre 1975). 63/09/16. 3pp
- ~-7904300354 Certificate of disposition of matts under License 20-05838-03 by transfer of Co-60 to Tracertab, Inc. WEI88, N. M. Texas Instruments, Inc. 30165. 72/08/25 1p
- 7904300233 Emphasizes importance of need for free & open communications between all organizations levels in course of managing NRC confirmatory safety research program. KOUTS, H J Office of Nuclear Regulatory Research. 76/03/04 1p
- 7904300260 Notifies of personnel change in Power Reactor Licensing Div. as of 790515. HINZINGA: H J. General Atomic Co. (subs. of Gulf Gil Corp.). 79704/20. ip
- 7905010032 Appeal of initial FDIA decision to deny request for Section 4 C of contract between New Chemical Co & Consumert Power Co. FREEDKIN, 8. Public Interest Research Group. 79/03/15. 2pp.
- 7905010041 Response to appeal of denial of FOIA request for Election 4.C of 780621 general agreement contract between Dow Chemical Co & Consumers Power Co Requested info remains exempt from public disclosure.

  OSSICK.LV. Office of the Executive Director for Operations. 79/04/23. 229.
- 7905010473 Forwards responses to NRC 790227 request for add1 info re topical rept ATC-132-A dtd 790227.

  BROWNSTEIN,M ATCOR. EC 2995. 79/04/24. 65pp.
- 7905010556 Requests Executive Branch position re Ediow Intl Coapplication for license to export special nuclear matl to Argentina. OOSSICK, L. V. Office of the Executive Director for Operations, 79/04/13. 1p.
- 7903010560 In response to request for additinfo re OE core spray distribution program, forwards "Pretest Prediction for Sector Steam Test Facility Core Spray Tests."
  LEVING.A.J. General Electric Co., Nuclear Energy Products Div. MFN-106-79. 79/04/17. ipp.
- --7903010361 "Pretest Prediction for Sector Steam Test Facility Core Spray Tests." RNOW, S. K., SANDOZ, S.A., General Electric Co., Nuclear Energy Products Div. 79704/13 26pp.
- 7903010648 FOIA request for info re govt contracts on low level radioactive waste mgt.name of contractor, contract number, beginning & completion detec & brief description of purpose, LOOKARILL.T NUS Corp. CAMBD 79-087. 79/03/20, ip.
- 7405010652 Response to FOIA request for info re govt contracts on low level radioactive waste mgt. name of contractor. contract number & start & completion dates. Forwards lists of contracts. W/o encl. FELTON, J. M. Division of Rules and Records. 74/04/25, ip.
- 7903010634 FOLA request for info justifying previous failure to use boron to flood facility, preventing release of radioactivity into atmosphere.

  SCOUTEN,J. W. Affiliation Unknown. 78/03/31, 1p.

5.1

- 7905010657 Response to FDIA request for records re-non-use of boron to flood reactor core. Forwards IE Bulletin 79-05A & discusses reactor scram incident. W/o encl FELTON.J M Division of Rules and Records 79/04/24 lp.
- 7905010660 Response to FDIA request for transcripts of closed NRC meetings re IMI-1 from 790328-790405 Transcripts for 790330-0405 meetings are available in PDR FELTON.J.M Division of Rules and Records 79/04/23. ip
- 7905020004 "Heavy-Section Steel Technology Program", quarterly progress rept for Oct-Dec 1978 WHITMAN, G D , BRYAN, R H Oak Ridge National Laboratory FIN 8-0119 DRNL/NUREO/TH-2 79/04/30 72pp.
- 7905020022 NUREO/CR-0283
  "Behavior of Defective PWR Fuel Rods During Power Ramp & File Boilting Operation "
  CROUCHER,D.W Idaho National Engineering Laboratory, FIN A-6046 TREE-1267, 79/02/28 37pp
- 7905020037 FOIA request for info re test scores for licensing C Faust & E Fraderict as reactor operators & K Bryon & BO Smith as senior operators. SCHAMMER CBB News. CBB, Inc. 79/04/06. ip.
- 7905020038 Forwards per Public Law 95-601, "Means for Improving State Participation in Siting.Licansing & Davelopment of Federal Nuclear Haste Facilities," NUREG-0539 HENDRIE,J H. Commission 79/04/19 tp.
- --79050200A3 NUREQ-0539 7/30/20063 NORES-1039
  "Heans for Improving State Participation in Biting,
  Licensing & Development of Federal Nuclear Waste
  Facilities " Office of State Programs. 79/03/31. 82pp
- 7905020052 Response to FOIA request for into re test scores for licensing C Faust & E Frederick as reactor operators & K Bryon & 80 Smith as senior operators.
  FELTON.J.M Division of Rules and Records. 79/04/24. ip
- 7905020056 FOIA request for winning proposal re evaluation of reactor radiation streaming to be provided at requested 790329 debrisfing MERIGOLD: 0 Science Applications: Inc K-1903 79/03/27. 1p
- 7905020059 Response to FDIA request for winning proposal for RFP RB-REB-78-193 Forwards relevant correspondence considered acceptable for public disclosure M/o encl FELTON-J M Division of Rules and Records. 79/04/19. 2pp
- 7905020080 FOIA request for outline of NRC structural organization, nature of administration's existence, basic health & safeguard stds & important cases of past & present, CONLEY.M E Bentley College 79703/18, ip.
- 7905020084 Response to FCIA request for various info re NRC organization & activities Forwards appropriate documents, including organization charts, 1978 Annual Rept & other NRC issuances, Discusses two types of NRC atds W/o encl, FELTON, J. M. Division of Rules and Records 79/04/25, 2pp.
- 7905020088 FOIA request for final rept on Jan 1961 SL-1 prototype reactor accident resulting in death of three maval personnel at Natl Reactor Testing Station, Idaho Falls, ID HUNTER, R. Affiliation Unknown, 79/04/04 ip.
- 7905020094 Response to FOIA request for final rept on 1961 SL-1 reactor accident at Natl Reactor Testing Station Forwards press announcement & final investigation rept, FELTON, J. H. Division of Rules and Records 79/04/25, 9pp
- --7705020101 Forwards final rapt on SL-1 accident occurring at Natl Reactor Testing Station on 610103. Concludes main cause was manual withdrawal of central control rod blads from core beyond specified limits. NELSON, C. A. Atomic Energy Commission (Pre 1975), 62/09/05 10pp
- 7905020136 License for Mitsui & Co Inc to export 25,463 pounds of Zircalog-4 tube shells to Japan OPLINGER,O.Q Assistant Director for Export/Import & International Safeguards 79/04/13, ip.
- 7908020142 Proposed Revision 4 to Reg Quide 8.8, "Info Relevant to Ensuring that Occupational Radiation Exposures at Nuclear Power Stations Will Be As Low As Is Reasonably Achievable."

  \* Office of Standards Development. 79/03/31. 42pp.

- 7905020151 "Investigation of Post-Critical Heat Flux Transfer for Mater-Cooled Reactor Application & Development of Two Phase Flow Instrumentation." progress rept Oct-Dec 1978 1978 CHEN,J C , SUNDARAM,R.K., LONDON,E J. Lehigh Univ. NRC-04-74-180 79/01/01 13pp
- 7903020154 "Creare Refill Effects Program." Creare Project 345-10 progress rept Har 1979 ROTHE,P H , CROWLEY,C J Creare, Inc. NRC-04-75-162 79/04/05,
- 7905020162 Agenda of ACRB 781005 meeting to discuss FFTF project # ACRB Advisory Committee on Reactor Bafeguards 78/10/05, 1p
- 7905020169 Application for extension of time to respond to intervenors' & NRC comments on Stanislaus commitments Certificate of Syc WATTB: M J McCutchen: Doule: Brown & Emerson 79/03/07. 500
- 7905020177 Notification of contract execution "Bys Maint Programming," awarded to Small Business Administration.

  KAGAN.T F. Administrative Contracts Branch. NRC-10-79-372

  BB3-4-0-8(A)79-. 79/04/10 1p.
- --7903020182 Contract for "Sys Maint Programming" awarded to Small Business Administration HATSON,C Administrative Contracts Branch NRC-10-79-372 NRC-10-79-372 79/04/02 lopp
- 7905020290 Requests Amend 1 to License XT-8429 to extend expiration from 791201 to 801201 MATSON: V Transnuclear: Inc 79/04/05 1p
- 7905020297 Requests Amend to Litense XM-8450 to modify intermediate consignes W/o ancl.

  GROSS:W T. Fanstsel, Inc. 79/03/28 ip.
- 7905020328 Discusses LOCA evaluation model. Leibnitz rule approximation justification is appropriate & affect of high heat transfer on calculated peak clad temp will result in reduction by several hundred degrees STROUPE, E P General Electric Co., Nuclear Energy Products Div MFN 108-79. 79/04/19 iipp
- 7703020348 In response to NRC 770424 meeting w/B&H & 177 fuel assembly plant owners.B&H agreed to describe scope & status of addl analytical work Requested info should be provided by 770304 TAYLOR, J H Babcock & Wilcox Co. 79/04/25, 6sp.
- 7905020349 License for Westinghouse to export 92 Ir tubes & miscellaneous specially designed or prepared parts & components for use in reactors to Italy. OPLINGER.Q.Q. Assistant Director for Export/Import & International Safeguards, 79/04/13, ip.
- 7903020335 License for Mitsui & Co Inc to export 77,600 lb of Zircalog-2 tube shells to Japan OPLINOER,Q.Q Assistant Director for Export/Import & International Safeguards 79/04/13 ip
- 770302036; License for Mitsuiline Travel Byc of America: Inc to export miscellaneous specially designed parts for use in reactors miscardineous to Japan. OPLINGER, & Q Assistant Director for Export/Import & International Bafeguards, 79/04/19, ip
- 7903020366 License for Mitsvi & Co Inc to export 25,463 lb of Zircaloy-2 tube shells to Japan OPLINGER.G.O. Assistant Director for Export/Import & International Safeguards. 79/04/13 lp.
- 79030203B1 License for Harshaw Chemical Co to export two mCl Sr-90 beta ray sources incorporated in Sr-90 calibrators to Paople's Republic of China. OPLINOER.0 0 Assistant Director for Export/Import & International Safaguards. 79/04/13. 2pp.
- 7905020385 License for Kawecki Berylco Industries, Inc. to export 417 33 lb of Zircaloy-2 seamless tubing to Camada. OPLINGER, G O Assistant Director for Export/Import & International Safeguards. 79/04/17, ip
- 7905020409 License for Westinghouse Electric Corp to export fuel tubes, fuel rod springe & end plugs (top & bottom) to Bweden.

  OPLINGER, G. G. Assistant Director for Export/Import & International Safeguards 79/04/17. ip.

- 1905020434 Amend 1 to license for Exxon Nuclear Co.Inc to import U from Mast Germany, increasing amount licensed from 43,340kg to 86,480 i kg OFLINEER G G Assistant Director for Export/Import & International Safeguards 79/04/20 ip
- 703020464 Forwards matl describing process for modeling procedures for distribution to licensees MATHONI.A. Lawrence Livermore Laboratory 8 79-245-D 79/04/23
- 7983020469 Natification of contract execution. Mod 1 to "Economic Assistance Related to Antitrust Hearings for South TX Froceedings " Contractor. Trenscomm! Inc QLA00LA.A.F. Technical Assistance Contracts Branch FIN 8-6593.
- --7905020477 Mod 1.extending period of performance until 790531 to "Economic Assistance Related to Antitrust Hearings for South TX Proceedings."

  DUOHRTY: D J. Technical Assistance Contracts Branch FIN B-6090 79704/12. ip.
- 7905020482 Forwards acceptance of Revision 3 to GA topical rept NU-GA-1 submitted 790309.
  MADS.M.P Assistant Director for Quality Assurance & Operations 79704/13 19
- 7903020483 License for Westinghouse to import 92,281 kg U from Busden OPLINGER, 0 0 Assistant Director for Export/Import & International 84feguards. 79/04/20 3pp.
- 7905020486 License for Exxon Nuclear Co. Inc to import 40:000 kg U-235 from UBBR. OPLINOER: 0.0 Assistant Director for Export/Import & International Bafaguards. 79/08/20. 2pp
- 7905020449 License for Westinghouse to export one compensated ionization chamber to West Germany.
  OPLINGER, 0.0. Assistant Director for Export/Import & International Refoguards. ZE-10227 79704/18. 1p.
- 7905020806 License for Transnuclear, Inc to export 2,059 75 mCi Gf-252 as coment wire to France.
  OPLINGER, O. O. Assistant Director for Export/Import & International Bafuguards. 79-108/01 (TNP2, 79/04/18 2pp
- 7903020310 License for Helco USA. Inc to export 1 BF-3 counter type redistion detector to Japan.
  ORLINGER, 0 0. Assistant Director for Export/Import & International Safetywards. 79/04/18. ip.
- 7903020318 License for Transnuclear, Inc to export 20,526 kg U-235 to Heat Germany.
  OFLINGER 9.0 Assistant Director for Export/Import & International Safeguards, 79/04/17. 2pp.
- 7905020522 License for Sigma Chemical Co to export 1 kg heavy water to France OFLINGER. Q G. Assistant Director for Export/Import & International Offsquards, 79/04/18 1p.
- 7905020538 Comments on proposed Reg Guide 1.44: issuance of proposed guide will result in increase in number of internal & external audits conducted by utils BOYER: V. S. Philadelphia Electric Co. 79/03/20, 6pp.
- 7405030068 License for Mitaubishi Intl Corp to export pressure tubes, Intuitive, reactor intervals, control rod drive mechanisms & other tubes, reactally designed reactor parts, except pressure vessels, control rods, primary coolant pumps & fuel machines, OPLINGER, 9, 8. Assistant Director for Export/Import & International Bafeguards, 79/04/16, 2pp.
- 79050G00082 License for TX Nuclear Div to export 1.415 mg Pu-238 to the Netherlands OFLINOER, Q. 9. Assistant Director for Export/Import & International Exfequence. T~1451. 79/04/20, 2pp.

- 7905030087 Amend 3 to license for GAC.extending expiration cate for export of matt to Japan DPLINGER.0 Q Assistant Director for Export/Import & International Safeguards IEL-740 79/04/20 is
- 7903030090 Dept of Hater Resources reply to brist of Southern CA Edition to which appeals denial of motion to quest substance duces tecum Certificate of Svc ent.

  STRUMHABSER H J. DEUMHEJIAN, O. ORUSKIN, S. M. Ceisfornie, State of 79/03/30 45pp
- 7905030092 Forwards application by Ediow Intl Co for license to seport 49,000 to U-308 to Brazil HARMONID W Ediow International Co UM9 2 79/04/17 ip
- --7905030100 Application by Edlow Intl Co for license to expert
  48:000 kg U-308 to Brazil
  HARMON: D W Edlow International Co 79/04/16 ip
- 7903030106 Application by GE for license to esport specially designed pipe whip restraints to Belgium
  MILSON.B D General Electric Co BDH-79095 79/Q4/13 ip
- 7905030109 Application by Sigma Chemical Co for license to expert equivalent of 2 kg DgD liquid in compounds containing destarion to Argentina 

  \* Sigma Chemical Co (subs of Sigma Aldrich Corp ) D-13
  79704/16 1p
- 7905030123 Application by QE for license to export 18,452 to UO2 powder to Japan.
  HILBON. B. D. General Electric Co. BDM-79097 79/04/13 ip
- 7905030127 License for Westinghouse to export pressure tubes. In tubes, control rod drive mechanisms & other miscellaneous specially designed parts to Japan.

  QPLINGER, Q Q Assistant Director for Export/Import & International Bafeguards 79/04/13 iP
- 7903030142 NUREO/CR-0494
  "Dose-Rate Conversion Factors for External Exposure to
  Photon & Electron Radiation from Radionuclides Occurring in
  Routine Releases from Nuclear Fuel Cycle Fatilities"
  KOCHER, D C Dat Ridge National Laboratory FIN 8-0188
  ORNL/NUREO/TK-2 79/04/30 168pp
- 7905030144 Forwards QA Program Insp Rept 99900322/79-02 on 790205-08 No noncompliance moted POTAPOVS.U Region 4, Delles, Vendor Inspection Erenck 79/02/22 2pp
- --7903030150 GA Program Insp Rept 97900522/79-02 on 790205-08 No noncompliance noted Major areas inspected previous insp findings, pips support fillet welds, control of drawings & calculations & design insp BRICKLEY, R H , HALE, C J Region 4, Dellas, Vender Inspection Branch 79/02/20 Spp
- 7905030187 Ack receipt of 781128 itr discussing Reactor Bafeguards itemsing Branch Review Guideline 23 re security at nuclear plants Beliaves Quideline 23 should not be withdrawn as requested KMC 781128 itr encl DENTON; H.R. Office of Nuclear Reactor Regulation 79/04/17 Spp.
- --7905090176 "Study to Assess Radiological Sabotage Potential of Operating Nuclear Power Plants " 4 KMG, Inc. 78/11/28 23pp
- 7905030161 Transcript of 790418 Bubcommittee on Waste Mgt meeting in Richland, NA to discuss update of waste mgt, seased disposal disruptive phenomena in various media & acid disposal disturbive phenomena in various media & acid disposal disposal
- 7903030180 Notification of contract execution Hod i to "Beleatcity
  Study of Nothwestern IL & Bouthsestern Wi." Contractor
  Univ of MI.Milusukse
  HAGEY, H. Research Contracts Branch. FIN 8-6314 NRC-04-78-232.
  79/04/24 19.
- 7905030194 Forwards nonpropriatory topical rept BAM-10085, Ravision 3 TAYLOR, J H Babcock & Milcox Go. 79/04/12 is

- --7905030205 BAN-10QB5 R3
  "Reactor Protection Sys," Revision 3, nonproprietary
  varsion,
  ORGERA,E G., GILBERTBON,L.A , FAIRBROTHER,D Babcock & Wilcox Co.
  77/03/31 200pp
- 7905090196 Notification of contract execution Mod 1 to "Liquefaction in Lake Amatitlan Area During Feb 1976 Quatemalan Earthquake " Contractor Univ of CA.Bertley.
  HA0EY.H. Research Contracts Branch FIN 8-6279 NRC-04-78-219.
  79/04/24 1p
- --7905030203 Mod inchanging performance date from 790531 to 790930 to "Liquefaction in Lake Amatitian Area During Feb 1976 Gustemalan Earthquake"
  MORTON: X V Research Contracts Branch. FIN 8-6279
  NRC-04-78-219. 79/04/02 2pp.
- 7905030199 Notice of taking of deposition of RH Gerdes on 790502 Certificate of Svc encl MATT,P K Spiegel & McDiarmid 79/03/26, 5pp.
- 7905030221 NUREO/CR-0599
  "Analysis of Superheated Wall Effects During Refill at Small Scale."
  GROWLEY, C. J., ROTHE, P. H. Creare, Inc. FIN A-4070 CREARS TN-287
  79/04/30 174pp Available at NTIS. 98,00
- 7905030226 Notification of contract execution. Mod 1 to "Confirmatory Research Related to Dating of Ground Mater." Contractor Univ of Al.
  HYNATIA Research Contracts Branch FIN 8-6736 NRC-04-78-272
  79/04/19. 1p.
- --7905030234 Mod 1, increasing funding from \$133,835,00 to \$185,148 46 & allowing for purchase of gas chromatograph-mass spectromater to "Confirmatory Research Related to Dating of Oround Nater" HORTON, K V Research Contracts Branch FIN 8-6736 79/04/01 4pp
- 7905030231 NUREO/CR-0446
  "Determining Effectiveness of ALARA Design & Operational Features"
  HALL, T. M., DODD, A. M., HAIGHT, R.F. United Nuclear Corp. FIN 8-2069.
  UNI-TR-G. 79/04/30 532pp. Available at NTIS, \$15.50
- 7905030233 Supplemental answers by PG&E to third set of interrogatories submitted by CA Dept of Water Resources Verifications & Certificate of Svc encl.

  DOYLE,M.M.; HOULIHAN, T.J., ARMSTRONG,W.H. McCutchen, Doyle, Brown & Emerson. 79/03/14, 18pp.
- 7905030246 NUREO/CR-0523
  "MEBODIF-II. Variable Trajectory Piume Esgment Hodel to
  Assess Ground-Level Air Concentrations & Deposition of
  Effluent Releases from Nuclear Power Facilities "
  PONELL.D. C. MEGLEY, H. L., FOX.Y. D. Battelie Memorial Institute,
  Pacific Northwest Laboratory, NRC-03-77-181, PNL-2419, 79/03/31,
  320pp Available at NTIS \$11,75.
- 7905030237 Notification of 790425 meeting w/Exxon Nuclear Co in Sethesda.MD to discuss Exxon neutronics calculations for reloads.

  MEI85, S. H. Reactor Safety Branch 79/04/20 1p.
- 7905030340 Describes Mark III tests of pressure suppression test facility: Series 6002 & 6003 8080N.L.J. General Electric Co., Nuclear Energy Products Div MFN-118-79 79704/27. 17pp.
- 7905030306 Forwards schedule & scope for reliability enalysis of integrated control sys & schedule for developing auxiliary feedwater control independent of integrated control sys TAYLOR, J. H. Babcock & Nikox Co. 79704/28 4pp
- 7905040003 Ack receipt of 790305 ltr'requesting NRC to issue 6-month extension of comment period re NUREO-0499, "Policy Statement on Generic Rulemaking to Improve Nuclear Power Plant Licensing," M/790405 Congressional correspondence DENTON, H. R. Office of Nuclear Reactor Regulation. 79/04/04 App.
- --7905040015 Request for extension of initial comment period to permit adequate public consideration of NUREO-0499, "Policy Statement on Generic Rulemaking to Improve Power Plant Licensing."

  BROWN, J. W. Affiliation Unknown. 79/03/05, 1p.
- 7905040024 Notification of contract execution Mod 5 to "Study of Pattern & Ages of Poet-Metamorphism Faults in Part of Northern Piedmont of VA & NC " Contractor VA Polytechnic Institute & State Univ MAGEV, M. Research Contracts Branch FIN A-9027 NRC-04-75-237. 79/04/24. 1p.

ì

- ---7905040034 Mod 5, changing period of performance from 790114 to 790515 to "Study of Pattern & Ages of Post-Metamorphism Faults in Part of Northern Piedmont of VA & NG "HORTON, K V. Research Contracts Branch FIN A-9027 NRC-04-75-237 79/01/15 2pm
- 7905040028 Forwards response to NRC questions re Mark II improved chugging load definition 8080N.L.J. General Electric Co MFN-120-79 79/04/30 31pp
- 7905040042 Notification of contract execution. Mod 1 to "Axial Photography for Droplet Size Distribution of Two-Phase Dispersed Flow Through Reactor Grid." Contractor. Hichita State Univ HAGEY. H Research Contracts Branch FIN 8-6250 NRC-04-77-133
- --7905040052 Mod 1, changing period of performance from 790630 to 800630 to "Axial Photography for Droplet Size Distribution of Two-Phase Dispersed Flow Through Reactor Orid "HORTON K.V. Research Contracts Branch FIN 8-6250 NRC-04-77-133, 79/04/09, 2pp
- 7905040064 Notification of contract execution, Mod 2 to "Meteorological Conditions Unique to Tornado Development Through Proximity Analysis " Contractor. Univ of HO HAGEY. H Research Contracts Branch. FIN 8-6196. NRC-04-77-055, 79/04/24 is
- --7905040069 Mod 2, changing performance date from 790331 to 790630 to "Meteorological Conditions Unique to Tornado Davelopment Through Proximity Analysis " HORTON K. V Research Contracts Branch FIN 8-6196 NRC-04-77-055 79/04/01 2pp
- 7905040079 Notification of contract execution, Mod 5 to "Steady & Transient Natural Convection in Enclosed Fluid Layers w/ Volumetric Energy Sources " Contractor OH State Univ Research Foundation
  HAGEY,H Research Contracts Branch, FIN A-4061, NRG-04-74-149
  79/04/24 1p
- --7905040090 Mod 5, changing period of performance from 790331 to 800331 to "Steady & Transient Natural Convection in Enclosed Fluid Layers w/Volumetric Sources "HORTON K. V. Research Contracts Branch FIN A-4061 NRC-04-74-149 79/04/01 Zpp
- 7905040098 Application by Kawecki Berylco Industries for license to export Zircaloy tubing to Canada
  GILBERT, Y K Kawecki Berylco Industries, Inc. 79/04/16 2pp
- 7905040137 License for Trensnuclear, Inc to import 22 071 kg U from France.
  DPLINOER, 0 O Assistant Director for Export/Import & International Bafeguards 79/04/20 2pp
- 7905040150 Summary of 780712 meeting w/Mark I owners in Betheada. HD re methodology for defining safety relief valve discharge loads for quencher discharge device & steam condensation observed in full scale test facility (Rs-9A Mark I) GRIMEB. 9 Plant Systems Branch. 79/04/26 Spp
- 7905040171 Requests Executive Branch position re OE application for license to export components to Belgium. M/o encl. CPLINGER. G O. Assistant Director for Export/Import & International Bafaguards. 79/04/18. 1p.
- 7905040177 Requests Executive Branch position re Mitsuf & Co (USA) application for license to export Zircaloy-4 tube shells to Japan M/o encl
  DPLINGER.O.O. Assistant Director for Export/Import & International Bafeguards. 79/04/18. ip.
- 7905040186 Requests Executive Branch position re Mitsui & Co (USA) application for license to export Zircaloy-2 tube shells to Japan. 4/o encl. OPLINGER, G. O. Assistant Director for Export/Import & International Safeguerds 79/04/18, ip.
- 7903040189 Forwards application for export license for minor nuclear export Ltr of assurance required M/o encl. DPLINDER, G. 9. Assistant Director for Export/Import & International Bafeguards, 79/04/18. 1p
- 7905040207 Comments on proposed rule 10cFR20; Ford, Bacon & Davis approach to intrusion scenario underestimates dose commitments by several orders of magnitude W-becl handwritten notes & article from "Health Physics."

  BARD.S T. Environmental Protection Agency. 79/01/22 10pp.

- 7905040247 Comments on proposed rule 10CFR19 & 20 adequate basis (see not exist for calling hearing on occupational dose limiting stds Btudies referred to have all been repudiated by proposed exposure limits too low LEMIB. C. Edison Electric Institute. 79/04/16 2pp
- 1905040250 Comments on proposed rule iOCFR50.opposes any proposed regulations which permit greater flexibility in meeting public health & safety stds TMI-2 proves need for more regulation DAVIS.H A Affiliation Unknown 79/04/09, ip
- 7905040261 Comments on proposed rule 10GFR50: urges Commission not adopt proposed rule Resexamination of any relaxation of equirements re nuclear power safety mechanisms should be conducted THI-2 indicates need for more study JUSTICE, R. L. Affiliation Unknown 79/04/03 ip.
- 7905040265 Comments on proposed rule 10CFR20 supports revocation of 10CFR20 504

  ARRDE: H H. West Virginia, State of, 79/01/15 ip.
- 1905040274 Comments on proposed rule 100FR50,790328 notice was untimely opposes streamlining of licensing procedure Francisca to amend App H is good as it will protect vessel integrity. Opposes change to App G. MNDREHELJ C Affiliation Unknown. 79/04/16. ip.
- 7905040283 Comments on proposed rule 10CFR20, encourages proposed changes, Any disposal of radionuclides should be licensed a Affiliation Unknown. 79/04/19 ip
- 7905040274 Comments on proposed rule 10CFR20, calendar quarter should be defined as std quarter to avoid use of different dose info seporting particles
  RENDFROER.D L. Washington Public Power Supply System 79/04/06
- 7905040305 Comments on proposed rule iOCFR19 & 20 suggests wording be clarified & replacement of word "dose" w/"occupational dose" wherever it occurs.

  BTALLINGS, C.M. Virginia Electric & Power Co. 79/04/06 5pp
- 7905040313 Comments on proposed rules 10CFR19 & 20. some airlines use radicisotopes for insp of aircrafts & enginesimost ATA aeaber airlines support proposal Comments from American Airlines & Air Canada encl.

  TECHAS.E. & Air Transport Association. 79/04/17 4pp
- 7905070016 Comments on proposed rule re new sys of recordseping using magnetic tape along w/transcription of individual interviews w/NRC employees.believes program may contradict President Carter's wish to raduce govt costs COONEY, M J Affiliation Unknown, 79/09/24, ip.
- 7905070042 Ltr of assurance certifying mati mentioned in application for license to export 143.2 mg U containing 133.1 mg U-235. L transfer of this mati is subjected at terms & conditions of 600728 addl mgreement for cooperation.

  ODPPEL.M. Euratom Supply Agency (Belgium), 79/03/28, ip.
- 7903070086 Notification of 790426 meeting w/OE in Bethesda, MD to discuse two lump test apparatus & model development. HODGES, M N. Analysis Branch 79/04/20, ip
- 2703070094 Responses to NRC 781228 Questions re "Mount Taylor U Mill Project Woversized drawings. e Quif Oil Corp., Gulf Mineral Resources Co 79/04/13. 46pp
- 7705070105 Urgas issuance of license for QE to export neutron detectors containing U to India to replace failed detectors which might endanger Tarapur reactor safety WILBON, B. D. General Electric Co. 77/04/23. 1p.
- 7905070111 Comments on proposed Reg Quide 3.8:reg guide should conform to procedural provisions established by CEQ for NEPA. Portion of environ rept should contain description of mining activities.

  HERBLOFF.L.M Rocky Mountain Energy Co. 79/03/14 4pp
- 790507017f Comments on proposed rulemaking 10CFR20-13: certification by American Board of Health Physics is preferable to NRC certification plan. DCLEY.J.W. Affiliation Unknown. 79/04/12. 2pp.
- 790507018: Comments on proposed rulemaking iOCFR20-13 andorses proposition & notes address of Natl Registry of Radiation Protection Technologists.

  SHITH, H. P. Affiliation Unknown. 79/04/09 2pp

- 7905070201 Forwards "Probable Har Flood from Cenon de Marques watershad for Designing U Tailings Impoundment Drainage Diversion 843 Marques.NM " M/supplemental agreement TOPP.A New Metico, State of 79/03/30 6pp
- --7905070213 "Probable Has Flood from Canon de Harques Watersted for Dasigning U Tailings Empoundment Drainage Diversion Sys. Marques.NM. Botum Resources Corp " 81MONG.D B . Li.R M Colorado Btate Univ 79/03/30 34pp
- 7905070222 Requests PO&E supply Northern CA Power Authority w/rames of all persons util deems to have been members of "control group" for periods from which documents claimed as priviledged have arisen
  ADRAGNALU M Spiegel & McDiarmid 2 79/04/04 2pp
- 7905070382 Comments on proposed rulemaking 10CFR20-13 opposes patition & believes public certification programs sufficient KASPERSKI.D C Affiliation Unknown 79/04/10 1s
- 7905070406 Comments on proposed rulemating 10CFR20-13 formal certification of health physicists unnecessary 8CHAFER; K H IOWA-Illinois Gas & Electric 79/04/02 2pp
- 7905070417 Comments on proposed rulemaking 10CFR2-6 strongly supports recognition that licensing proceedings should be conducted in timely manner CASSAN.V J Power Authority State of New York 79/04/06 3pp
- 7905070424 Comments on proposed rulemaking IOCFR2-7 opposes patition due to potential for abuse & delays in licensing process a Isham. Lincoln & Beale 79/04/05 Spp
- 7905070432 Comments on proposed rulemaking IOCFR2-7 rejects proposal & suggests more rigid rules & requirements to prevent unnecessary intervention + Affiliation Unknown 79/04/05 3pp
- 7905070442 Comments on proposed rulemating 10CFR20-13 appeass patition because objectives are currently being achieved under sxisting regulations No evidence of need for further regulation
  JENS.W M Detroit Edison Co 79/04/05 2pp
- 7905070495 Forwards initial evaluation of Div of Operating Reactors' fire protection meeds for 1980 HALL.R E Brookhavan National Laboratory 79/04/30 499
- 7905070555 Forwards proprietary rept BAM-10085P.Revision 6. "Reactor Protection Bys "
  TAYLOR, J H Babcock & Wilcox Co 79/04/12 2pp
- 7905070564 Informs that add1 info re ATHS mitigating capability of plants which use C-E NSSS will be submitted approx 790601 rather than 790501 SCHERER: A E C-E Power Systems LD-79-026 79/05/01 19
- 7905070658 Forwards Revision 3A to QA program rept NU-QA-1 COUNSIL, N Q Northeast Utilities QA-3187 79/04/23 1p
- --7905070660 Accepts Revision 3A to GA Topical Rapt MU-GA-1 HAASS: W P Quality Assurance Branch 79/03/13 2pg
- --790507066G Topical rept evaluation of QA program Rept NU-QA-1 Rept commits util to comply M/requirements of App B to 10CFR30 p Quality Assurance Branch 79/03/09 ip
- ---7905070666 NU-GA-1
  GA program rept. Revision 3A
  # Northeast Utilities 79/03/09. 9lpp
- 7905080028 FOIA request for NRC rept & recommendations on petition for rulemaking filed by PIRO DICKBON:K B. California. State of 79/03/28 ip
- 7905080031 Response to FOIA request for NRC rept & recommendations on petition for rulemaking filed by PIRO Forwards relevant info.
  FELTON.J M Division of Rules and Records. 79/05/01 1p
- --79050B0035 SECY-78-13C
  Attempts to obtain NRC approval of response to PIRQ patition
  for rulemaking
  MINDQUE,R.B. Office of Standards Development 78/12/19 9pp

1

The state of the s

- --7905080036 Petition for rulemaking to promulgate regulations for nuclear power plant decommissioning SQHALTI.H B . ABBOTTS.J Public Interest Research Group 77/07/05 tipp
- --7905080040 Forwards comments supporting of patition in response to 770808 NRC notice 42FR40063 Five add1 groups have requested inclusion as co-patitioners Forwards assured patition Corrects erroneous listing of J Abbotts as esquire ABBOTTS.J. Public Interest Research Group 77/10/07 7pp
- --790808047 Forwards comments in support of petition, responding to NRC notice of 42FR59574 on 771114 Natl Consumer Law Ctr Energy Project requests participation as co-petitioner ABBOTTB-J. HANKCOFT, M. H., SCHKALTZ, W. B. Public Interest Research Group 78/01/03 42pp.
- 7905080055 "Hater Reactor Research Directorate Monthly Rept." Feb YBARRONDO, L J Idaho National Engineering Laboratory 79/02/28. 200pp
- 7905080070 Transcript of 790418 meeting in Hashington DC Pp 1-53 Initial discussion of upgrade rule & supporting guidance. Supporting documentation encl. OLLINSKY.V , KENNEDY,R T , BRADFORD,P.A Commission 79/04/18.
- -7905080082 BECY-79-187 905080082 BECY-7Y-18/
  Discusses strengthened physical protection requirements for fuel cycle facilities & transportation involving formula quantities of strategic SNH Bupporting documentation encl HINOGUE, B Office of Standards Development DIRCKG, M. J of Nuclear Haterial Bafety & Bafeguards 79/03/16 172pp Office
- 7905080081 Responds to 790322 ltr re processing sits designation for Canonsburg, PA, supporting draft engineering evaluation & environ analysis repts Forwards relevant NRC comments Will arrange meeting as requested DIRCKS.H J. Dffice of Nuclear Material Bafety & Safeguards 79/04/18 ip.
- --7905080087 Comments on draft engineering assessment by Ford, Bacon & Davis Utah of former Vitro Rare Metals plant at Canonsburg. PA discusses radioactive contamination & costs of ramedial actions

  MARTIN.J B Assistant Director for Fuel Cycle Hafety &
  Licensing 78/08/21 2pp
- --7905080101 Reviews summary evaluation of radiation exposures for workers at former Vitro Rare Metals plant in response to 781023 request Proposed EPA criteria should be considered in corrective action selection MARTIN.J 8

  Assistant Director for Fuel Cycle Bafety & Licensing 79/11/24 ip
- --7903080108 Requests review of encl proposed designation of processing site at Canonsburg.PA. Requests mesting between NRC & DOE to discuss site & other relevant info.

  CLUSEN.R C. Energy. Dept. of. 79/03/22 App
- 7905080109 TFBP-TR-209 "PBF-LGGA Test Series.Test LGC-11"
  LANSON, J.R., ALLISON, C.M. EG & G, Inc. FIN A-6041. YFSP-TR-209
  79/03/19. 87pp.
- 7908080114 Forwards request for add1 info to complete review of GE rept.NEDO-21059. "BWR Radioactive Waste Treatment Bys." PARR: 0 D. Light Water Reactors Branch S. 79/04/19. 2pp.
- 7905080137 Responds to 791226, 790112 & 790202 ltrs noting instances of lack of timeliness & suggestion that policy be implemented for prompt board notification. Forwards sys procedures & case analysis of these failures. Office of Nuclear Reactor Regulation. 79/04/12, 2pp
- --7905080144 Office Ltr 19 establishing procedures for board notification of relevant & new info Forwards notification procedure, J Yore 780207 owen & A Rosenthal 780208 Messo.
  CASE, E. Q Office of Nuclear Reactor Regulation. 78/07/06 26pp
- --7905080154 Submits ABLB comments & suggestions re NRC board notification of relevant & new info re licensing cases. Suggests different procedures before & after publication of referenced NRC documents.

  YORE, J.R. Atomic Safety and Licensing Board Penel. 78/02/07.

- --7905080163 ABLAB comments re NRC notification to boards of relevant new info re licensing cases Endorses ABLB suggestion of different procedures before & after publication of NRC documentation RDEENTHALA S Atomic Safety and Licensing Appeal Panel
- ---7905080171 Forwards package of info re ciriteria for buckling of steel containment shells Info Judged too preliminary for board notification at this time M/o encl VASSALLO, D B Assistant Director for Light Water Reactors
- --7908080178 Informs that Sibwell memo contains expert opinions which are relevant info for plants w/design concern of steel containment shell buckling Requests identification of cases in hearing process w/similar design criteria GROSSMAN, M J. Hearings Division 78/04/10 1p
- ---7905080217 Board notification buckling of steel containment shells Infais still preliminary & NRC position not yet clear Encl question is representative of info supplied to applicants Recommends consideration of free standing steel shells VABSALLO, D B Assistant Director for Light Water Reactors, 78/04/18 2pp
- -7905080230 Board notification buckling of steel containment shells Recommends waiting for results from technical assistance program before making further determination VASBALLO, D. B. Assistant Director for Light Water Reactors. 78/09/28, 10
- --793080249 Expresses puzzlement over reasons for not informing boards re buckling of steel containment shells If info indicates inadequete or nonconservative techniques, boards should be BCINTCoJ F Hearings Division 78/10/11, 1p
- --7905080259 Board notification containment buckling Porwards backup info from original memo & list of boards to be notified, Backup info consists of Allens Creek PSAR questions & answers VASBALLO, D B Assistant Director for Light Water Reactors 78/10/31 700
- --7903080263 Notes draft rept on containment buckling is preliminary & will be greatly revised before issuance in Feb 1979. Suggests NRC wait until final rept is issued before notifying board. Supporting info encl GCHAUER,F Structural Engineering Branch 79/01/11 10pp
- --7905080278 Board notification EO&O, Inc analysts on asymmetric leads Suggests forwarding entl R Stiger 771104 memo to boards for PHR plants, Sample forwarding ltr entl, VASSALLO,D B Assistant Director for Light Hater Reactors, 78/02/24 App
- --- 7905080286 Notes delay of almost one year for release of rept questioning steel containment buckling criteria NRC should gromptly transmit such data to licensing boards & public. ROISMAN. A Z. Netural Resources Defense Council. 78/12/26 2pp
- --7905080296 Forwards I Bihwell 780130 memo re need to notify ACRS & licensing boards on containment buckling criteria. Memo underscores problems outlined previously.

  ROISMAN.A Z. Natural Resources Dafense Council. 79/01/12 ip
- 7905080139 Forwards MI House of Representatives resolution femanding investigation re allegations of safety problems at plants in BRYANT.W.R Michigan, State of. 79/04/12. 3pp
- 7903080163 Requests Executive Branch position re GE application for license to export 18.432 kg U to Spain OPLINGER, Q G. Assistant Director for Export/Import & International Safeguards. 79/04/23 ip.
- 7903080174 Forwards application by Transnuclear, Inc for license for minor nuclear export Ltr of assurance required.

  OPLINGER, O. O. Assistant Director for Export/Import & International Safeguards 79/04/24 1p
- 7905080190 Forwards 790409 export license amend request H/o encl. 008816K.L.V Office of the Executive Director for Operations, 79/04/24, ip.

- 7905080219 Comments on proposed Reg Guide 1 144 frequency of audits should be established based upon type of activity, experience & other relevant factors ANSI N45 2 12-1977 provides such latitude

  LINO: J American Society of Mechanical Engineers 79/03/23. 2pp
- 7905080242 Forwards "Operating Procedure Quidelines for Small Breaks "
  W/beckground info that will be used as training aid for
  sperature.
  TAYLOR.J. H. Babcock & Wilcox Co. 79/08/05 28pp
- 7935080364 Forwards 790426 documents re B&W transient & accident analysis methods HATTSON, R J Division of Systems Safety, 79/04/26. 1p
- ---7905080372 Forwards background info re 8&H operating plant response to transients w/postulated equipment malfunctions. 8&H will submit detailed analyses per schedule to be decided at 790426 meeting w/RRC RRY.D H Babcock & Wilcok Co 79/04/26. 64pp
- 7905080393 Forwards results of LOFY Test L2-3,in response to NRC 790117 ltr OMSLEY, Q.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.), 79/04/30 Bipp
- 7705080405 Forwards handouts from 790208 midgear review & subsequent program review meetings on ORNL safety-related operator action study Handouts include preliminary results rederator time margin FARHER, M.S. Research Support Branch 79/04/13 lipp
- 7905080440 Forwards "Test Results For Sciencid Valve Performance Test," final rept,NEDE-23887; per F Clemenson request.

  BHERHOOD, Q Q Gameral Electric Co. MFN 110-79. 79/05/01 ip
- --7905080442 NEDE-23887
  "Test Results For Solenoid Valve Performance Test," final test.
  " Quantum Control of the Control of th
- 7905090004 Lists all NRC contracts & repts of 1978-79 re low level radioactive waste 
  Commission 79/04/25 Spp
- 7905090011 FDIA request for 1978 diary-calendar & telephone log of Commissioner Oilinsky
  MANN.J.R. Affiliation Unknown, 79/04/02 Ip
- 7905090013 Response to FOIA request for 1978 diary, calendar & telephone log of Commissioner Ollinsky. Commissioner does not asintain talephone log or diary Calendar is being placed in PPR FELTONIJ H. Division of Rules and Records 79/05/01 ip
- 7905090014 Notice of 790915 meeting w/ACRS Subcommittee on Fort St Vrain Nuclear Power Station, util & NRC staff om Longmont, CO to review operating experience, refueling operations & proposed mode for facility. HOYLE, J C ACRS - Advisory Committee on Reactor Safsguards, 79/02/22, 2pp
- 7705070018 Notice of proposed meetings from 790223-790512 of ACRS tubcommittees & working groups.
  HOYLE,J.C. ACRS Advisory Committee on Reactor Safeguards.
  79/02/22, Spp.
- 7905090023 Notice of proposed meetings from 790323-790719 of ACRB subcommittees & working groups meetings from 790323-0719. MOYLE, J.C. ACRB Advisory Committee on Reactor Bafeguards. 79/03/20 pp.
- 7905090025 FGIA request for info re const of proposed nuclear power plants before year 2000; specific locations, svc areas & FM output of each plant, DOWNES-L.T. Affiliation Unknown. 79/04/16 2pp.
- 7903090030 Response to FOIA request for info re proposed const of nuclear power plants to be built by year 2000 % info concerning presently operating plants. Forwards site map FELTON, J. M. Division of Rules and Records. 79/04/27, 1p
- 7905090031 "PA 37 Pipe Rupture Study". CLARKE, H.L. General Electric Co. NRC-04-75-202, 79/03/09, App.

- 7905070032 FOIA request for outline of NRC structural organization, nature of administration's existence, basic health & safequards stds & "important post" & present cases CONLEY, M E. Affiliation Unknown 79/09/18 ip
- 7905090034 Response to FOIA request for records re NRC organization health & safeguards stds & "important" cases. Lists documents available from OPO FELTON, J. M Division of Rules and Records. 79/04/25 2pp
- 7905090048 NUREG-0553
  "Cost & Funding of State & Local Govt Radiological Emergency Response Plans & Preparadness in Support of Commercial Nuclear Power Stations"
  BALOMON.B. Office of State Programs. 79/03/30. 131pp
- 7903090111 Transcript of 790329 public meeting in Washington, DC recontinuation of discussion of SECY-79-34A, final rept "Regulation of Pederal Radioactive Waste Activities." Pp 1-51. SECY-79-34C encl.
  HENDRIE J M., GILINSKY, V, KENNEDY, R T. Commission. 79/03/29 52ep.
- --7905090117 SECY-79-034C
  Provides followup to NRC requirements re inital briefing on SECY-79-34A dwaft rept, "Regulation of Federal Radioactive Watts Activities "
  DENTON:H.R. Office of Nuclear Reactor Regulation, 79/03/26
- 7905090158 Responds to request for info re H Peeples 790221 ltr protesting 10cFR71. App E because its packaging requirements are unjustified Requirements apply generally to shippers of fissile mat1 & Type B quantities
  CORNELL.E K Office of the Executive Director for Operations, 79/04/02 6ps
- 7905090161 Minutes & apps of 781207-09 224th AGRE meeting in Mashington: DC re NRC safety research program (NUREO-0496). ATMS resolution & combination of dynamic loads in nuclear facilities design.FR notice of meeting encl. 

  \*\* ACRE Advisory Committee on Reactor Safeguards 78/12/09 150pp.
- 7905090163 "Application of Internal Friction Nundestructive Evaluation Technique for Detecting Inciplent Cracking of Bypass Lines & Pipes in BHR Piping" Progress Rept 9.
  YEAGER.L L Daedalean Associates, Inc. NRC-04-78-242 79/04/09.
- 7905090168 Porwards generic letter to all BWR licensees re relief & safety relief valves which are installed in reactor coolant sys &/or automatic depressurization sys CLEMENBON.F Plant Bystems Branch 79/04/05 ip.
- ---7905090171 Concludes that implementation of requirement for increased survaillance testing is not most effective way of assuring safety relief vaiva reliability. Requests answers to questions we target rock safety relief valves. GRIMES. B. K. Assistant Director for Engineers & Projects. 79/04/05. 49p.
- 7905090176 Comments on proposed Reg Quide 3 8.Revision i:recent CEG rule for EIS should be reviewed Changes in EIS processs could be used in guide.

  WOLFF.T. New Merico, State of, 79/03/16 Spp.
- 7905090194 790426-28 review 19 CHILK: 8. J
- 7905090197 instrumen BLOTCKY
- 7905090203 for Nucl arrestor alternat THORRE, J
- --79050900 Plants # Off

- --7905090384 Preliminary value/impact assessment supporting draft rag guide. "Lightning Protection for Nuclear Power Plants " "Proposed Alternate Regulatory Position" enci # Office of Standards Development. 78/12/12 ip.
- 7905090261 Comments on proposed Reg Quide 8 8, Revision 4: notes editorial mistates re certain footnotes MEBER. # D American Nuclear Society. 79/04/12 ip.
- 7905090262 Comments on proposed Reg Guide 3 3 believes NRC should address only radiation safety & not general safety No need for detailed corporate organization repts in application if general competence is described YELDERMAN, J C US Steel Corp. 79/03/19 3pp.
- 7905090266 Notice of 790329 seeting of ACRE Subconnittee on Pale Ver6s Nuclear Generating Station, Units 4 & 5, its consultants & NRC staff in Mashington, DC to review const application HOYLE, J.C. ACRS Advisory Committee on Reactor Safeguards 79/03/08. 2pp
- 7903090267 Notice of date change of meeting of ACR8 Subcommittee on Evaluation of LERs in Washington DC from 790322-24 to 790322-24. HOYLE, J. C. ACR8 - Advisory Committee on Reactor Safeguards. 79/03/09 ip
- 7905090268 Forwards Revision 1 to MPL-TOP-1A: "Operational GA Manual," per NRC 781211 instructions
  REAVES.T E Mississippi Power & Light Co. AECH/79-36. 79/05/01
- ---7905090271 "Operational GA Hanual " GTAMPLEY,N L Mississippi Power & Light Co 79/05/03 18ps.
- 7905090270 Notice of 790403 meeting of ACRS Subcommittee on Combination of Dynamic Loads, its consultants & NRC in Washington DC to review tecnical basis of order to shut down five plants w/safety-related priping nonconformities HOYLE, J C. ACRS Advisory Committee on Reactor Safeguards, 79/03/15 2pp.
- 7905090276 Notice of 790923-24 meeting of ACR8 Bubcommittee on Evaluation of LERs.its consultants & NRG staff in Hashington.DC to review LERs of 1976-78 HOYLE.J.C. ACR8 Advisory Committee on Reactor Bafeguards 79703/01
- 7905090270 Forwards review of updated MCAP-8691, "Fuel Rod Bowing." Acceptable basis has been provided for calculating critical heat flux on bowed rods BTOLZ.J F Light Water Reactors Branch 1 79/04/05 1p.
- ---7905090294 Topical rept evaluation of MCAP-8691, "Fuel Rod Bowing "
  Rept provides acceptable data base for critical heat flux
  bowed to 85% of bow necessary for contact

  \* Light Mater Reactors Branch 1 79/04/05, 9pp.
- 7905090306 Details changes to Tech Specs re use of reflector elements & fuel element positions
  BALDWIN.M.N. Rebook & Wilcox Co 79/05/02, 2pp
- 7905090327 Summary of 790426 meeting w/Hestinghouse to discuss capabilities of natural circulation for Nestinghouse plants. Forwards responses to questions raised re power operated pressurizer relief valve opening ANDERSON, T. H. Westinghouse Electric Corp NS-TMA-2078. 79/05/01. 3pp
- 7905090366 Due to increased workload from TMI.ATMS data per NRC 790215 request will be submitted 790501.
  ANDERSON,T. H. Hestinghouse Electric Corp. NS-THA-2077. 79/05/01.
- 7905090396 Notification of contract execution: "Design of NRC Bupply & Maint Modules of Property & Bupply Bys." Awarded to Small Business Administration & subcontract awarded to Rehab Group, Inc.
  HAGAN, T.F. Administrative Contracts Branch, NRC-10-79-378, BB3-44-8A79044, 79/04/03, 1p.
- ---7905090399 Contract for "Design of NRC Supply & Maint Modules of Property & Supply Sys" awarded to Small Business Administration & subcontract awarded to Rehab Group, inc. MATTIA.M. J. Administrative Contracts Branch, NRC-10-79-378, 79/03/19. 12pp.
- 7905090401 NUREO/CR-0255
  "CONTEMPT-LT/028; Computer Program for Predicting
  Containment Pressure-Temp Responses to LOCA."
  HAROROVES D. W. NETCALFE, L. J. EQ & Q. Inc. FIN A-6009. 79/03/31.
  244pp. Available at NTIB

- 7905090406 NUREO/CR-0728
  "Test Plan Large Scale Molten Balt-Water Vapor Explosion
  Studies to be Conducted at Ispra-Italy "
  HENRY R E. Argonne National Laboratory FIN A-2026 79/02/28
  27pp Available at NTIB
- 7905090408 NUREO/CR-0590
  "An Evaluation of Fuel Rod Behavior During Test LOC-11."
  COOK.T F. E0 & G. Inc FIN A-6041 79/03/31 105pp Available at NTIS.
- 7905090413 Forwards NRC computer security program, responses to 0A0 recommendations & NRC Hanual Chapter 2101 "NRC Security Program "
  HENDRIE, J M Commission 79/04/12 87pp
- 7703090416 Comments on proposed Reg Quide 1 28.Revision 2 language of ANSI N45 2-1977 should be maintained Requirements for specific procedures eliminate desirable flexibility.
  SULLIVAN.T J. Consumers Power Co 77/04/03 ip
- 7905090417 NUREO/CR-0754
  "An Exploratory Study of Inhibition of Intergranular Stress Corrosion Cracking in Sensitized Type 304 Stainless Steel."
  SROWN B.F. ("DeLL.C.S., FOLEY, R.T. American Univ FIN B-5607 79/04/30. 125pp Available at NTIS
- 7905090422 NUREQ/CR-0642
  "Ref Critical Experiments," progress rept Oct-Dec 1978
  0058EL.0 R . OH.I., PECORA.D. Rockwell International Corp FIN
  A-1036 RFP-2888 79/04/30 S9pp
- 7905090428 NUREO/CR-0434
  "Effects of Nuclear Power Plants on Community Growth & Residential Property Values," final rept;770930-781115
  OAMBLE,H B : DOMNING,R H : SAUERLENDER, O H Pennsylvania State Univ FIN B-6173 79/04/30 85pp Available at NTIS 86 00.
- 7905090430 Comments on proposed rule 100FR50 re acceptable criteria for EGG8 for LNRs, supports relevant research & forwards list of research repts LEVENSON.M Electric Power Research Institute 79/03/19 ilpp.
- 7905070431 Comments on proposed rule re generic rulemaking to improve nuclear gower plant licensing agrees w/NRC proposed thange & forwards suggestions
  HEDEMAN W. N. Environmental Protection Agency. 79/03/15 4pp.
- 7905090433 Comments on proposed rule re generic rulemaking to improve nuclear power plant licensing, endorses concept if it does not delay or cause expensive & complicated backfits on plants already in licensing process.

  LINBLAD.W J. Portland General Electric Co. 79/03/09 3pp.
- 7903090435 Comments on proposed rulemaking 10CFR2-7:proposed change has potential for addl costs & delays w/o corresponding benefits to public. Should not be adopted BAUM-E A Virginia Electric & Power Co. 134 79/03/20. 2pp.
- 7905100004 Forwards corrected motion to reschedule RH Gerdes deposition on 790326. Certificate of Bvc encl. BTREBEL, S. J. Spiegel & McDiarmid, 79/04/12 ip.
- --7905100007 Corrected motion for rescheduling of RH Gardes deposition served on 790326. Certificate of Svc encl.
  MATT.P.K., STRESEL.B J. Spiegel & McDiarmid, 79/04/12 7pp.
- 7905100020 Transcript of 790419 briefing in Washington, DC on operational safety data-gathering & analysis, Pp 1-99. OILINSKY, V , BRADFORD, P. A. , KENNEDY, R. T Commission. 79/04/19.
- ---7905100026 Requests briefing on operational safety data-gathering & analysis Outline & relevant LER encl CHILK, S. J. Office of the Secretary of the Commission. 79/02/22 15ps.
- ---7905100030 BECY-79-207
  Proposes itr be prepared from Secretary denying Kranish FOIA Appeal 79-A-3. Ltr should state that deleted portions are properly classified.
  BICKMIT.L. Office of the General Counsel 79/03/23 Spp.
- --7905100045 Responds to FOIA 781107 request for transcript of 781106 Commission meeting re Gossick testimony, Portions of transcript withheld Appeal possible.
  FELTON-J. M. Division of Rules and Records, FOIA-78-318 79/03/01. ip.

- ~-T905100047 Commission determination re public disclosure of 781106 transcript of Cossick testimony Portions of record withheld.

  CHILK:8 J Office of the Becretary of the Commission 79/02/26.
- ~~7905100050 Appeals deletions from 781106 Commission meeting transcript supplied in response to FOIA 78-310.
  KRANISH,A Trands Publishing.Inc 79/03/09 ip
- --7:05:100408 Responds to 790309 appeal of initial determination in FDIA 78-318 requesting transcript of Commission meeting on 78:106 Govt in Bunshine Act precludes making deleted portions available CHILK-8 J Office of the Secretary of the Commission 79/03/09
- 7905100021 "Steamline Rupture Analysis for Generic C-E Plant (Including Concurrent Steam Generator Tube Rupture) Phase 1."
  CONNELL, H R. LEVINE, M M . BHIER, M O Brootheven National Laboratory. FIN A-3005 BNL-NUREG 25855 79/03/31. 72pp.
- 7905100023 informs of circuit breaker failure indicating defects affecting safety of nuclear power plants Bhaft mounting ratched driving pawl broke at weld & cotter pin securing latching pawl shaft broke CONNORS.J E Golden Gate Switchboard Co 79/03/30 3pp.
- 7905100028 Responds to 790316 1tr re Lawis rept. Would welcome apportunity to meet & discuss issue in future Testimony of HR Denton on 790321 before Congress encl. HENDRIE, J. M. Commission 79704/23 lp.
- --T903100032 Believes NRC press release of 790119 was major source of confusion since positive findings of Lewis rept were not mentioned & release put entire HASH~1400 on same level as executive summary.
  HUDSON: 9. R Illinois: State of 79/03/16, 3pp
- --7905100035 Transcript of 790321 statement before Subcommittee on Energy & Hater Development re computer code readings on seismic design of pipe stress analysis Supporting documentation encl DENTON, H R. Office of Nuclear Reactor Regulation 79/03/21. 52pp.
- 7905100036 Forwards notice of denial of petition for rulemaking reamending 100FR20, "Btds for Protection Against Radiation," Reg guide will be issued to clarify meaning of regulation HINDQUE, R. B. Office of Standards Development. 79704/05 ip
- 7905100043 Forwards relevant press releases & preliminary notifications issued to date in response to 790330 telex re TMI incident KAMMERER: C. Office of Congressional Affairs. 79/04/10 4pp.
- 7905100049 Ack receipt of 790406 ltr re info on nuclear safety & emergency evacuation plans.

  KAMMERER: C. Office of Congressional Affairs. 79/04/10. App
- 7905100051 Ack receipt of 790402 ltr requesting security status rept on security at Oconee 1.2 & 3 in light of TMI incident KAMMERER:C. Office of Congressional Affairs. 79/04/10. App.
- 7905100053 BECY-79-270
  Forwards, for Commission consideration, application from Ediow
  Intl Co for license to export U hexaflouride to Argentina
  SHEA.J R Office of International Programs. 79/04/16. ip
- 7705100056 Recommends license be granted to Westinghouse to import 92,281 kg U from Bweden Requests notification of licenses.
  CHILK, B. J. Office of the Becretary of the Commission. 79/04/20.
- 7705100059 Draft evaluation of Bokum Resources proposal will not include radiological assessment section due to insufficient info.

  SCARANG.R.A. Assistant Director for Wasta Management (Præ 770501).
  79704/09. ip.
- 7905100092 Forwards JR Cavanaugh 790403 ltr expressing support for faderal central status ctr for US nuclear plants Requests (nfe necessary for reply, PRICE: M. House of Rep. 79/04/09. 5pp.
- 7905100090 Minutes of ACRS A/E Balance of Plant Subcommittee 790126 meeting in Mathington, DC to review Fluor Power Sycs, Inc BD98BAR a relationship to 84% Std Ref Bys BBAR-205 for preliminary design approval ACRS Advisory Committee on Reactor Safeguerds, 79/01/26, 16pp.

- 7905100091 Ack receipt of 790330 ltr re TMI incident Complete response will be forwarded as soon as possible Forwards NRC press releases & preliminary notifications re incident KAMMERER.C Office of Congressional Affairs. 79/04/10 3pp.
- 7905100101 Responds to 790319 ltr Northern CA Power Authority (NCPA) does not agree that it is time to move shead w/previously authorized discovery directed toward individual NCPA member NCPA will not perait will to search member city files MCDIARMID.R C Spiegel & McDiarmid 79/03/30 2pp
- 7905100136 Ack receipt of 790405 ltr re TMI incident Complete response will be forwarded as soon as possible Forwards NRC press releases & preliminary notifications re incident KAMMERER, C Office of Congressional Affairs 79/04/10 Spp
- 770510013B Supports ASLB 7700125 order denying Southern CA Edison Co's 770305 motion to quash subpoens duces tecum. Supporting documentation & Certificate of Svc enci OCLDBERG.J., VOLGER.B H Anti-Trust Division 77/04/18 49pp
- 7905100142 Response by util to NRC & intervenors' preliminary comments re-commitments. Discusses specific suggested changes to commitments Supporting documentation & Certificate of Svc enci.

  DOYLEIM M. ARMSTRONO, S. H., HATTS, K. J. McGutchen, Doyle, Brown & Emerson 79/04/16 130pp
- 7905100153 Forwards revision to HPI operator instructions per IE Bulietin 79-05a TAYLOR, J H Babcock & Wilcox Co. 79/04/17, 3pp.
- 7905100159 Ack receipt of 790402 ltr re TMI incident. Complete response will be forwarded as soon as possible Forwards relevant releases & preliminary notifications.

  KAMMERER.C Office of Congressional Affairs. 79/04/09 3pp
- --7705100166 Requests into re-design or operational problems generic to BMM facilities & relationship to similar problems experienced at TMI. FAZIG/V House of Rep. 79/04/02. Spp
- 7905100165 NUREC/CR-0643
  "Matl Compatability Tests for LOFT Nuclear Reactor Fuel Centerline Thermocouples"
  CHAN.A I., MEYERS,S.C., BEUTLER,P.S. Hanford Engineering Development Laboratory, FN B-6228, HEDL-THE-78-75
  79/03/31, 65pp
  Available at NTIS. #5.25.
- 7905100174 Ack receipt of 790403 ltr re safety of Bouth TX project in light of TMI KAMMERER, C. Office of Congressional Affairs 79/04/10, 3pp
- 7705100185 Forwards third submittal to App D of NEDE-24011-P-A "Ogneric Reload Fuel Application " Entl withheld (ref 100FR2 770).

  OUIRK, J.F. General Electric Co , Nuclear Energy Products Div. MC 682 79/08/08 Spp
- 7905100190 NUREO/CR-0736
  "Transportation of Radioactive Matl in IL," 770604-780606
  \* Illinois, State of, 79704/30 30pp. Available at NTIS \$4.50.
- 7905100194 Forwards second submittel to App D of NEDE-24011-P-A; "Oeneric Reload Fuel Application " Encl withheld (ref 100FR2, 790).

  BUIRK, J.F. Oeneral Electric Co., Nuclear Energy Products Div. MC 682, 79/02/28, App.
- 7705100198 In response to 770401 ltr re TMI incident, forwards press release & preliminary notifications issued to date & NRC response to Governor Brown's request to close Rancho Seco. KAMMERER, C. Office of Congressional Affairs. 79/04/10. Spp.
- 79051002:3 NUREG/CR-0673
  "Radiation Dose Estimates & Hazard Evaluations for Inhaled
  Radionulclides," annual progress rapt, July 1977-June 1978.
  HEHHINNEY, J. A. Lovelace Biomed & Environmental Research Institute.
  LF-63. 79/03/31, B4pp. Available at NRC, &7 00.
- 790510021B Ack receipt of 790402 itr re TMI incident. Complete response will be forwarded as soon as possible. Forwards NRC press releases & preliminary notifications re incident.

  KAMMERER, C. Office of Congressional Affairs. 79/04/09. 3pp.
- 7905100229 NUREG/CR-0724
  "Bludy of Reverse Camosis Applicability to LNR Radwasts
  Processing."
  MARKIND.U., VAN TRAN.T. Abcor, Inc. 79/04/30, 132pp. Availabis & 1

- 7905100230 Bupplements 790117 ltr Licensing action on application for export of components to the Philippines not yet completed Case presently under consideration GHEA. J. R. Office of International Programs 79/04/27. 1p
- 7905100240 NUREO/CP-0005
  "Proceedings of Conference on High Level Radioactive Solid
  Haste Forms Dec 19-21, 1978 at Denver, CO "
  CASEY, L A Office of Nuclear Haterial Bafety & Bafeguards
  78/12/19 800pp. Available at NTIS. \$21.50
- 7905100243 "Biocide Byproducts in Aquatic Environ," quarterly progress rept for Oct-Dac 1978
  ANDERSON, D. R., BEAN, R. M., QIBSON, C. I. Battelle Memorial Institute, Pacific Northwest Laboratory FIN 8-2098-9, PNL-2931, 79/03/31 41pp
- 7905100253 NUREG-0380 V3 N4
  "Program Summary Rept." Vol 3,No 4
  " Office of Management and Program Analysis 79/04/20 103pp
  Available at NTIS 912 50,
- 7905100264 On behalf of Marubeni Canada.Ltd.requests extension of expiration date of License XU-8395 to 800401 To date.50.000 kg U-308 exported against license HARMON.D.W Ediow International Co 79/03/15 7pp
- 790510026B Comments on proposed draft reg guide "Qualification of QA Program Audit Personnel for Nuclear Power Plants " ASME code activities would be excluded in ANSI/ASME N45 2, 23 unless otherwise indicated.

  TRIMBLE, D C Arkaneas Power & Light Co 019-4 79/03/23 ip
- 7905100277 Summary of 790226-27 meeting w/GA Co in San Diego.CA re OFFBR & HTGR program descriptions:licansing overview.R&D programs & inservice insp requirements. HTLLIMMS.P M . MEYER.J F Advanced Reactors Branch. 79/04/17
- 7905100278 Weekly info rept for week ending 790420 REHMITA. Office of the Executive Director for Operations 79/04/27 27pp
- 7905100287 Requests info re application for license to export to IAEA .22 microgram PU-239 & whether or not it is subj to terms of UB-IAEA agreement for cooperation PETERBON.H Office of International Programs 79/03/01, ip
- 7905100323 Ltr of assurance in response to NRC 790322 ltr re Reuter-Stokes application for license to export U-235 to Norway, Transfer will be suby to all terms & conditions of 670603 agreement for cooperation, RINDAL, A. Norway, 79/03/30. 2pp
- 7905100330 Bummary of 780620 meeting w/Bacramenta Kunicipal Util District & B&W re cooldown transient of 780320 ZWETZIG,O.B. Operating Reactors Branch 4, 78/07/13, 6pp
- 7905100343 Ack receipt of 790330 itr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 9990400779-01. POIAPDVS,U. Region 4. Dallas, Vendor Inspection Branch, 79/04/11 1p.
- --7905100351 Responds to NRC 790301 ltr re deviation noted in GA Program Insp Rept 99900400/79-01. Corrective actions: change inquiry/authorization is being processed to correct design incomesistencies & review of contracts will be conducted MACMILLAN, J. H. Babcock & Wilcox Co 79/03/30, 4pp.
- ---7905100356 Forwards GA Program Insp Rept 9900400/79-01 on 790212-16 & notice of deviation. POTAPOV8.U. Region 4. Delles, Vendor Inspection Branch. 79/03/01. 2pp
- ---7905100360 Notice of deviation from insp on 790212-16

  Region 4, Dallas, Vendor Inspection Branch. 79/02/26. ig
- ---7905100366 GA Program Insp Rept 99900400/79-01 on 790212-16.
  Noncompliance noted equipment spec & sys description valves
  for safety-related sys did not agree e/sys requirements
  spec.
  ANDERSON, D. G., HALE, C. J.
  Branch. 79/02/26. 10pp.
- 7905100338 Requests extension of expiration date for export license X8NM-1270 from 790801 to 800801.
  MATSON, V. Transnuclear, Inc. 79/04/04. 1p.

- 7905100410 Forwards GA Program Insp Rept 99900521/79-01 on 790226-0301 & notice of deviation POTAPOV8.U Region 4, Dallas, Vendor Inspection Branch 79/03/09 2pp
- --7905100413 Notice of deviation from insp on 790226-0301
  \* Region 4, Dallas, Vandor Inspection Branch 79/03/08 to
- --7905100418 GA Program Insp Rept 99900521/79-01 on 790226-0301 Noncompliance noted Section 11 of project internal procedures menual not revised by 790129 as committed. BRICKLEY,R H. MALE.C.J Region 4, Dallas, Vendor Inspection Branch. 79/03/08 6pp
- 7903100415 BECY-79-269
  Forwards, for Commission consideration, application from Transnuclear, Inc for license to export U-235 to the Netherlands.
  BHEA, J. R. Office of International Programs 79/04/16 is
- ---7905100417 Forwards application for license to export U-235 to the Netherlands MATBON, V Transnuclear, Inc 79-121/01, 79/04/11 1p
- 7903100424 Forwards Abnormal Occurrence 50-312-75-3 for Rancho Seco 1, \* Bacramento Municipal Utility District 75/03/11. ip.
- ---7705100430 Abnormal Occurrence 50-312-75-3 on 750212, turbine/generator tripped when overspeed trip relay became falsely de-energized due to calibr drift Faulty transmitter replaced

  \* Sacramento Municipal Utility Dietrict 75/03/11 lp
- 7903100436 Informs of review completion of util data re 780320 reactor trip & resultant cooldown transient Concurs w/util's intent to return plant to power operation at level below 75% full power, w/certain recommendations JANIS, J T Babcock & Wilcox Co 78/03/23 2pp
- 7905100445 Confirms transfer of lead responsibility made verbally 781223 re steem generator level control during auxiliary feedwater operation ORDANA, E. Division of Reactor Operations Inspections, IE.ROI.TP-79-01, 79/01/16 2pp
- 7905100447 License for Hoke, Inc to export bellows sealed instrument isolating valves to Canada.
  OPLINGER, O. O. Assistant Director for Export/Import & International Safeguards 79/04/27. 1p
- 7905110025 Requests extension of License XBNM-909 from 790501 to 781231. KEENAN.R.P. Westinghouse Electric Corp. 79/03/19. 1p.
- 7705110026 Comments on proposed rulemaking 10CFR20-13; petition should be denied. Supports certification of health physics personnel although NRC should not have function of certification.

  8H00P.P.R International Brotherhood of Electrical Workers. 79/04/09. 2pp.
- 7905110033 Project on structural integrity of water reactor pressure boundary components, monthly progress rept for Mar 1979. LOSS,F J. Navy, Dept of, Naval Research Laboratory. 79/04/10 6pp
- 7905:10055 Comments on potential effect of loop seals in a pressurirer surge line, greater emphasis must be placed on this matter in light of TMI-2 NOVAK, T. Reactor Bystems Branch. 78/01/10, 1p.
- ---7905110060 Comments on potential affects of loop seals in a pressurizer surge line.recommends bases for design requirement be studied for all CP reviews to determine if loop seal can be siminated.

  NOVAK.T. Reactor Systems Branch. 78/01/10. 2pp.
- 7905110061 Presents Analysis Branch contribution to task group evaluation of protection of operating B&W plants against feedwater transients. Info typically provided is not sufficient.
  ROSZTOGZY, Z. R. Analysis Branch 79/04/10. 9pp.
- 7905:10064 Assigns R Tedesco as group leader of Task Group on Generic Review of Feedwater Transient in B&N-Designed Reactors.
  CASE.E. Office of Nuclear Reactor Regulation. 79/04/09 ip

- 7705110096 Forwards HCAP-9402, "Verification Testing & Analyses of 17si7 Optimized Fuel Assembly," nonproprietary ANDERSON, T.M. Hastinghouse Electric Corp. NS-YNA-2074, 79/04/27
- --7903110098 HCAP-9402 (NP)
  "Verification Testing & Analysis of 17x17 Optimized Fuel
  Assembly," nonproprietary
  KRAMER,F.W., CADEK,F.F., ANDERSON,T.H. Westinghouse Electric Corp.
  79/03/31 70pp
- 7903110116 Clarifies uncertainties re ODYN evaluation & proposed licensing basis Evaluation completed re neutron effective void correlation uncertainty Evaluation withheld (ref 10cFR2, 790) Affidavit enci COOK, K W Oeneral Electric Co MFN 123-79 79/04/30 6pp
- 7905110137 Comments on proposed rulemaking 100FR2-6 endorses petition. STEVENS,J R. New England Power Co. 79/04/06 2pp
- 7905110141 Comments on proposed rulemaking 10CFR2-7-it would only serve to complicate already rigorous licensing process Streamlining of nuclear plant licensing procedures is needed SIALINSKI.P.A Affiliation Unknown 79/03/28. 1p
- 7905110143 Board notification BN-79-10 reactor inspector concerns re BAN plants Recommends Boards be notified Supporting documentation encl, VASSALLO, D.B. Assistant Director for Light Water Reactors 79/03/04, 5pp,
- 7905110145 Comments on proposed rulemaking 100FR2-7, present rules reintervention are adequate.
  PRINCE, R.J. Affiliation Unknown, 79/03/26 ip
- 7905110146 Comments on proposed rulemaking 100FR2-7 opposes amenda wording of "good cause" is vague.
  FINGLU K. Affiliation Unknown. 79/04/02. 1p.
- 7905110150 Comments on proposed rulemaking 10CFR20-13.would place unjustified & potentially unsafe requirements on operation exergency planning.

  MRNDTHat K. Arizona Public Service Co. 79/04/06. 2pp.
- 7905(10)54 Forwards charter & member list of Task Oroup on Owneric Review of Feedwater Transients in B&H Designed Reactors DAVIB-D K Systematic Evaluation Programs Branch, 79/04/02 220
- 7905110179 Forwards info on possible nuclear incidents in UBSR. Proposes briefing by DRNL.
  QILINGKY-V. Commission. 79/04/23, 7pp.
- 7705110180 Discusses Tech Space for reactor coolant sys heatup & cookdown rates & pressure/temp limits.
  STELLO.V. Division of Operating Reactors. 78/04/17. 2pp.
- 7905110182 Ack receipt of 790414 memo defining mat1 subj to FOIA request Requests clarification re personal diaries & tapes. GILINSKY, V Commission 79/04/16 1p.
- 7703110208 Summarizes status of HEW briefing, evacuation plan & talks w/Osvernor Brown re B&W reactor problem 91LINSKY, V. Commission 79/04/03. ip.
- 7905110224 Requests views on Rosstoczy 790410 memo re feedwater transients.

  OILINSKY, V. Commission. 79/04/12. 1p
- --7905110R26 Presents Analysis Branch contribution to task group evaluation of generic feedwater transients in B&W reactors ROSZTOCZY, Z. R Analysis Branch, 79/04/10, 9pp
- 7705110239 Determines that little benefit would result from reducing all B&W plants to 50% power should event similar to TMI occur.
  TEDESCO.R.L. Assistant Director for Plant Systems 79/04/04.
- 7905110283 Tabulates reactor rafety research supplemental funding MURLEY, T.E. Division of Reactor Safety Research. 79/04/24. 3pp.
- 790510208 Forwards "C-E Best Estimate Pre-Test Analysis of LOPT Test L2-3," BCHERER, A.R. C-E Power Systems, LD-79-029, 79/05/08, 1p.

- --7905110294 LD-79-029
  "C-E Bast Estimate Pro-Test Analysis of LOFT Test L2-3,"
  May 1979
   C-E Power Systems 79/05/08 56pp
- 7908:10341 Noves for postponement of 790402 deadline for discovery & 790418 prehearing conference due to THI incident.
  BCOTT-8 M. Texas Public Interest Research Group 79/04/05. 3pp
- 7905110342 Motion for postponement of 790418 prehearing conference sending full investigation of TMI DOMERTY, J. F. Affiliation Untnown. 79/04/04, App.
- 7903110347 Motion by intervenors to reopen record indefinitely & postpone decision on generic safety issue considerations pending full investigation of TMI.
  PEEFFERKORN.H O. PISHKO.D.C. Pfefferkorn & Cooley. P. A. 79/04/03.
- 7905:10349 Discusses & clarifies actions for Emergency Procedure 5, loss of letdown w/radiological control program.
  TEDEBEO,R L Assistant Director for Plant Bystems 77/04/09.
  San
- 7905110355 Requests comments to environ qualification & instrumentation to follow course of an accident HANADER, B. H. Assistant Director for Plant Bystems 79/04/06 200
- 7905110379 Notification of ACRS Subcommittee on Power & Electrical Sys 790330 meeting w/its consultants & NRC staff in Washington. DC to review interconnection of protection & safety sys w/reactor cotrol sys on REBAR-414 design HOYLE-J C ACRS Advisory Committee on Reactor Safeguards. 79/03/14 2pp
- 7905110398 Forwards GA Program Insp Rept 99900104/79-01 on 790205-08 No noncompliance noted. POTAPOVB,U. Region 4, Dallas: Vendor Inspection Branch 79/03/08. 2pp.
- --7905110404 GA Program Insp Rept 99900104/79-01 on 790205-08. No noncompliance noted Major areas inspected: implementation of 100FR30. App B.criteria & applicable codes & stds including action on previous findings, insp & tests.
  HUNTER, V. M., WHITEBELL, D.E. Region 4. Dalias, Vendor Inspection Branch, 79/02/28, Spp.
- 7905110412 Natification of contract execution "Development of Improved Techniques for Analyzing Matl Control & Accounting Data," awarded to Science Applications, Inc. BONNER, J. Technical Assistance Contracts Branch FIN 8~6399-9, NRC-02-79-028, 79/04/20 19.
- ---7905110415 Contract: "Development of Improved Techniques for Analyzing Matl Control & Accounting Data," awarded to Science Applications, Inc. DOUGHERTY, D. J. Technical Assistance Contracts Branch. FIN B-6399-9. NRC-02-79-028. 79/04/20 20pp.
- 7905110414 Board notification. IE reactor inspector concerns re BLW plants. VABSALLO, D.B., Assistant Director for Light Water Reactors 79/04/02. 10.
- --7903110420 790329 m MOSELEY, 79/03/29
- --7905110421 HOSELEY: 79/03/28
- 7905140019 im Richlan MOELLER, D Reactor B.
- 7905140043 of Protec Disaster

- 7905140056 Summery of 790320 meeting w/BNL personnel to discuss mid-year review of progress on FY79 reactor physics technical assistance progress DUMENFELD: M Core Performance Brench 79/04/17. 3pp
- 7905140059 Notification of contract execution: "Consultation & Revisu of Nuclear Power Plant Sites," awarded to US Dept of Interior CLAODLA:A F Technical Assistance Contracts Branch FIN 8-6548 NRC-03-79-145 79/04/13 ip.
- ---7905140069 Contract "Consultation & Review of Nuclear Power Plant Sites: " awarded to US Dept of Interior DOUGHERTY, D. J Division of Contracts, FIN 8-6548 NRC-03-79-145 79/04/13 Sp
- 7905140089 Motion by Cities of Anabelm & Riverside, CA to reschedule deposition of RH Gerdes for 790502 Urges ASLB vacate 790405 order deferring deposition & reinstate 790326 notice of deposition Certificate of Svc encl.

  MATT, P. K. Spiegel & HcDiarmid 79/04/11, 7pp.
- 7905140093 Application by Sigma Chemical Co for license to export 5 kg deuterium liquid to Canada + Sigma Chemical Co. (subs. of Sigma Aldrich Corp.) 79/04/25 ip
- 7905140096 Application by Mitsubishi Intl Corp for license to export 250 mCl:encapsulated cement wire:Ce-252 to Japan TANAKA:N Hitsubishi International Corp. (subs of Hitsubishi Corp.) 79/04/27 ip
- 7905140099 Notification of contract execution, Mod 4 to "Various Task Agreements." Contractor Battelle Columbus Lab. MRC-04-76-293 79/04/01 MYNATTA Research Contracts Branch. MRC-04-76-293 79/04/01
- --7905140105 Mod 4, updating contract by adding new clause to "Verious Task Agreements" HORTON K. V Division of Contracts, NRC-04-76-293 79/04/01
- 7905140102 Ack receipt of 790404 request for all NRC documents & communications re THI.Lists records already in PDR: others to be placed there upon disclosure.
  FELTON.J M Division of Rules and Records. 79/05/03. 1g.
- 7905140128 Application by Nuclear Valve Div of Borg-Warner Corp for license to export 3/4-inch & i-inch 600 lb carbon steel globe valves:manual & air actuated. HAN.8. Borg-Warner Corp. 79704/18 ip.
- 7905140149 NUREQ/CR-0649 "Spant Fuel Heatup Following Loss of Water During Storage"
  BENJAMIN:A B , MCCLOSKEY, D. J , FOWERS, D. A. Bandia Laboratories FIN
  A-2050. BAND77-1371 79/03/31. 171pp, Available at NTIS
- 7905140158 FDIA request for ACRS 690831 rept.AEC 690630 internal staff study re safety of large nuclear reactors AEC 691112 rept on reactor safeguards & ltr to Seaborg concerning safety questions KENDALL.M.C. Indiana, State of, 79/04/12, 2pp.
- 7905140160 Response to FOIA request for ACRS 670331 rept on reactor safeguards. AEC 670630 internal staff study re safety of large nuclear reactors. ACRS 671112 rept on reactor safeguards. & it to Beaburg concerning safety questions FELTON, J. M. Division of Rules and Records. 79/05/09. 2pp.
- --7905140164 "ACRE, Its Role in Nuclear Safety " LAHROSKI, S. Argonne National Laboratory, MOELLER, D. W. Harvard Univ. 78/09/26. 39pp
- ---7905140165 Forwards communts on water reactor safety research program. Emphasizes importance of public health & safety HENDRIE: J. H. ACRS Advisory Committee on Reactor Bafeguards. 69/03/20 19.
- ~~7905140169 Comments on water reactor safety program plan. Coverage needed on proposed large water reactors Understanding of fuel failures needed Urges support be given to capable personnel Analysis of accident prevention needed.
  HENDRIE, J.H. AGRS Advisory Committee on Reactor Safeguards.
  69/03/20. 9pp.
- --7905140174 Reamphasizes previous recommendations re need for safety research. Urgas add1 R&D re seismic affects on sodium-cooled fast reactors & environ effects. Hore affort needed in axamining fuel failure.

  MENDRIE: J.H. AGRS -- Advisory Committee on Reactor Safeguards. 69/11/12. ", 3pp

- 7903140170 Notification of contract execution: "Implementation of Mod to NRC Contract Info Sys," awarded to Small Business Administration HEDROW, L A 79/04/27 1p Administrative Contracts Branch NRC-10-79-381.
- ---7905140179 Contract for "Implementation of Mod to NRC contract info Sus." awarded to Small Business Administration w/Social Research Application Corp as subcontractor MATTIA:H J. Contract Policy Branch NRC-10-79-381 79/04/30
- 7905140177 FOIA request for winning technical proposal for NRC-02-79-035, "Safeguards for High Level Waste Repositories."
  RAGANIK M Kinetic Research, Inc. NRC-02-79-035, 79/02/19
- 7905140180 Forwards RFP & winning technical proposal for NRC-02-79-035, "Safeguards for High Level Maste," in response to FDIA request request FELTON, J M Division of Rules and Records NRC-02-79-035
- 7905140183 FQIA request for internal NRC memo alleging that Idaho Falls. ID law power plant accident involved lovers' triangle. WILLIAM.M.A. Adfiliation Unknown. 79/04/05 Ip
- ---7905140187 Addresses potentiality of Idaho Falls. ID stationary low power plant incident, involving lovers' triangle Cautions against shortcomings in technological development & screening, supervision & surveillance of personnel HANAUER. 8 H Atomic Energy Commission (Pre 1975) 71/09/10, ip.
- 7703140184 Forwards 710910 memo in response to FDIA request for internal NRC memo alleging that stationary Idaho Falls, ID low power plant accident involved lovers' triangle. FELTONIJ.M Division of Rules and Records. 77/04/24. 1p
- 7905140191 FQIA request for documents prepared or received re-environ impacts & health effects possibly resulting from nuclear tests conducted for Project Plowshare Program during 1960s & early 1970s
  STRAIN:P. The Denver Post 79/04/02 1p.
- 7905140197 Forwards documents in response to FOIA request for info re impacts of nuclear tests for Project Plowshare Program Addl info available from CO Public Health Dept & DOE. FELTON,J M Division of Rules and Racords. 79/05/01. 2pp.
- ---7905140200 Informs of completion of reorganization of Div of Peaceful Nuclear Explosives Ploushare activities & personnel positions of Special Projects Div transferred to headquarters on 690518 Lists personnel assignments. KELLY,J 8 Atomic Energy Commission (Pre 1975). 69/07/31. Opp
- --7905140203 "Development of Regulatory Criteria for Control of Radiation Exposures to Population from Consumer Products Produced by Ploushare Applications: " (R&D-3 Ploushore) ROGERS, L. R., MESTERN, F. Atomic Energy Commission (Pre 1975) 69/04/11. 26pp.
- 7905140213 Forwards IE Circular 79~06 "Failure to Use Byringe & Bottle Shields in Nuclear Medicine" & list of addresses PAPFAS.H. Region 3. Chicago, Office of the Director 79/04/25
- 7905140237 Notice of 790404 meeting of ACRS Subcommittee on Regulatory Activities, NRC & consultants in Hashington, DC to discuss various proposed reg guides.
  HOYLE, J. C. ACRS Advisory Committee on Reactor Safeguards.
  79/03/14. Gpp.
- 7905140248 Notice of 790312 meeting of ACRS Subcommittee on Sequence Nuclear Power Station in Mashington, DC to review TVA application for OL. HOYLES C. ACRS Advisory Committee on Reactor Sefeguards. 79/02/22. 2pp.
- 7905140252 Forwards mat1 provided 790404 & relevant B&H & NRC memos refeasibles events at B&H plants.

  ORNSTEIN:H Office of the Executive Director for Operations 79/04/06. 19pp
- 7905140274 Addl info requested in 790209 ltr re two loop test apparatus test results being reviewed to determine schedule for response Review results expected by 790417. Heeting suggested for wesk of 790423 for addl test date evaluation.

  SHERMOOD: 0.0 General Electric Co., Nuclear Energy Products Div MFN-099-79, 79/04/06. 2pp.

- 7903140297 Clarifies application of Leibnitz rule in integration of conservation of mass equations in SAFE code STROUPE.E P. General Electric Co., Nuclear Energy Products Div RENO78-79. 79/03/20. 2pp.
- 7705140013 Forwards draft NUREO-0553, "Beyond Defense-in-Depth Cost & Funding . In Support of Commercial Nuclear Power Stations." Requests comments by 770507 W/o encl. RYAN.R. G. Office of State Programs. 79/04/10 1p
- ---7905140320 Forwards NUREO-0553, "Beyond Defense-in-Depth Cost & Funding. . in Support of Commercial Nuclear Power Stations "Requests comments by 790509. W/o encl. RYAN. R O Office of State Programs. 79/04/10 ip
- --7905140325 Forwards draft NUREO-0559, "Beyond Defense-in-Depth-Cost & Funding... in Support of Commercial Nuclear Power Stations," & requests comments before 790809. Final rept will be issued shortly after 790809. H/o encl.
  RYAN, R. U. Office of State Programs, 79/04/10 ip
- --7905140329 Forwards draft NUREO-0533, "Beyond Defense-in-Depth.Cost & Funding. . In Support of Commercial Nuclear Power Stations."

  Requests comments by 790509. N/a encl.

  RYAN.R O Office of State Programs 79/04/10 ip
- --7903140331 Forwards draft NUREO-0553, "Beyond Defense-in-Depth Cost & Funding... in Support of Commercial Nuclear Power Stations "Requests comments by 790309 H/o encl.
  RYAN.R.O. Office of State Programs 79/04/10. ip.
- 7703140314 Comments on DF Ross to EQ Case memo summarizing meeting renatural circulation considerations. Devis-Besse 1 771029 transient resulted in subcooling of BO F or more Erroneous implications made re Michelson Rept.

  TAYLOR. J H. Babcock & Hilcox Co. 79/05/04. 1p.
- 7903140326 Forwards new application for export license w/requested corrections.
  HARTIMEZ:F P. Brain. 79/04/09, ip.
- --7905140320 Corrected application by German Dominguez for license to export 51 kg U.as U hexafluoride to Spain = Spain. 79/02/28. ip.
- 7405140372 Forwards proprietary rept NEDE-21983-P. "Submergad Structures Model: Main Vent Air Discharges Evaluation Rept." Affidavit enti. Rept available in Central Files. 8080NA. J. General Electric Co., Nuclear Energy Products Div. HFN-121-79. 79/04/30. Opp.
- 7905140426 Bubmits requested info re 2-100p test apparatus & evaluation model reactor calculations, vaporization correlation data, & response to NRC question re vaporization in 2-100p test apparatus. M/encl 790129 ltr.
  BTROWE, E. P. General Electric Co MFN-022-79, 79/01/30 74pp
- --7905140428 Discuss NRC concern re heat transfer coefficient of 4-inch SAFE code & OE clarification. BYROUPE.E.P. General Electric Co. MFN-021-79. 79/01/29. 3pp
- 7903140469 Forwards slides presented at 790315 meeting w/NRC re ECCS swalvation model. Bubmittal contains proprietary info fref 10cFRC 7903.
  ANDERBON, T H. Westinghouse Electric Corp. NS-THA-2068, 79/04/18.
  19.
- Y905140509 Porwards map furnishing info % list of burial sites in response to FOIA request for info re all nuclear plants; either completed under const & all nuclear waste burial sites M/o enci.

  FELTON.J.H Division of Rules and Records. 79/05/10. ip.
- 79051405t1 FOIA request for map & current geographical listing of all nuclear plants either completed or under const & all nuclear waste burlal sites.
  COMBAR 8 Affiliation Unknown. 79/05/01. ip.
- 7903140321 Comments on draft reg guide & value/impact statement re
  "Ruclear Analysis & Design of Concrete Radiation Shielding."
  Brecific criteria for design of concrete radiation shielding
  structures should be provided.
  QAVIQAN, F. X. Energy, Dept of, 79/04/02. ip.
- 7905140525 Response to FOIA request for info re drawings & specs of model Theratron 80:00-60 teletherapy unit. Forwards various documents: drawing & list of drawings withheld as proprietary. Documents & drawings not enci. FELTON: J. M. Division of Rules and Records. 79/05/09. 2pp.
- 7905140827 FOIA request for internal files of facilities. SLOCKH.J J. Milwaukee Sentinel. 79/04/12. ip.

- --7905140534 Forwards FOIA request for access to documents in regional office
  KEPPLER.J G Region 3. Chicago. Office of the Director
  79704/20 ip
- 7905140530 Response to FOIA request for records not in NRC PDR refacilities
  FELTON, J M Division of Rules and Records 79/03/08 19
- 7905140573 NUREO-0344
  "Handbook of Acronyms & Initialisms "
  # Office of Administration 79/03/31 121ps
- 7905140575 NUREG/CR-0645
  "Multidimensional Analysis of Fluid Flow in LOFT Cold Leg
  Blowdown Pipe During Loss-of-Coolant Ergeriment "
  DEMMIE,P N , HOFFANN,K R I idaho National Engineering Laboratory
  FIN A-6048 TREE-1323 79/03/31 77pp Available at NTIB 63 00
- 7905140576 NUREO/CR-0646
  "Computer Program K-FIX/MOD1 Nod of Computer Program K-FIX
  for Application to Fluid Flow Simulation in LOFT Sys
  Piping "
  DEMMIE.P N . HOFMANN.K R Idaho National Engineering Laboratory
  FIN A-6048 TREE-1324. 79/03/31 84pp Available at NTIS #3 00
- 7905150003 Transcript of 79046 open meeting for NRC briefing on five shutdown plants (seismic design) Pp 1-67. HENDRIE, J. H., OILINSKY, V., KENNEDY, R. T. Commission 79/04/26 6800
- 7903150005 Ack receipt of 790313 itr w/statement on "Probalistic Risk Assessment & Its Application in Reactor Bafety & Licensing "Forwards MRC policy statement re Lewis Rept & instructions to NRC & testimony before Udall subcommittee HENDRIE, J. M Commission 79/04/23 ip
- ---7905150008 Forwards copy of "Probalistic Risk Assessment & Its Application in Reactor Bafety & Licensing" submitted to Committee on Interior & Insular Affairs RICKARD.C.L. General Atomic Co (subs of Quif Oil Corp ) 79/03/13 App.
- ---7905150009 Testimony of PA Bradford before Subcommittee on Energy & Environ of House Committee on Interior & Insular Affairs BRADFORD, P A Commission 79/02/26 App
- --7905150010 Testimony of JK Hendris before Bubcommittee on Energy & Environ of House Committee on Interior & Insular Affairs HENDRIE, J K Commission 79/02/26 26pp.
- 7905150014 NUREO-0540 VI N3
  "Title List of Documents Hade Publicly Available for Mar
  1979"

  \* Office of Administration 79/03/31, 381pp. Available at NTIS.
  83 00.
- 7905150029 License for Transnuclear, Inc to export 413 by U-235 & 0.0325 kg U-235 to Nest Germany OPLINGER, G O Assistant Director for Export/Import & International Bafaguards 79/04/27 2pp
- 7905150031 License for Transhuclear Inc to export 635 to U-235 to 0.035 kg U-235 to West Germany OPLINGER 0.0. Assistant Diractor for Export/Import & International Bafeguards, 79/04/27 App.
- 7905150032 License for Exxon Nuclear Cq. Inc to export 1940 4 to U-235 to Beiglum
  DPLIMOER. G O. Assistant Director for Export/Impert & International Safeguerds. 79/04/27. 2pp.
- 7905150033 License for Hoke, Inc to export hellows sealed globe valves, needle & globe valves to Carada. Delimorr. 0. O Assistant Director for Export/Import & International Safeguards 79/04/27. ip.

i

 $\left. +\right\} _{i}$ 

- İ

A STATE OF THE STA

- 7905150035 License for Hoke Inc to export ballows scaled instrument isolating valves scaled valves & valve manifolds to Isolating variations of Canada.

  OPLINGER, 0 0 Assistant Director for Export/Import & International Safeguards 79/04/27 ip
- 7905150037 License for Hoke, Inc. to export beliows sealed instrument isolating valves & spares, valve manifolds & sealed instrument valves to Canada OptiNoER. Q O Assistant Director for Export/Import & International Safeguards 79/04/27 ip

- 7905150038 License for Hoke, Inc to export believs sealed instrument isolating valves to Canada OPLINGER, Q. G. Assistant Director for Export/Import & International Safeguards 79/04/27 ip.
- 7905150040 License amendment for GE to export 2.48 kg Pu & 61 kg natural U to France.

  OPLINGER, Q. Q. Assistant Director for Export/Import & International Safeguards 79/04/26. 1p
- 7903150047 Ltr of assurance certifying fuel elements mentioned in Qeneral Atomic 790222 application will be sub; to conditions of 600725 addi agreement for cooperation QCPPELIM. European Communities. Commission of. 79703/27 ip
- 7905150066 Notice of 790319-20 ACRS Subcommittee on ECCS meeting. W/its consultants & NRC in Los Angeles CA to discuss status of physical code inputs current licensing actions & assymatric bloudown forces.
  HOYLE, J. C. ACRS Advisory Committee on Reactor Safaguards. 79/02/26, 2pp
- 7705150093 Responds to 790312 itr requesting NRC extend comment period for NUREO-0479, "Preliminary Statement on General Policy for Rulemaking to Improve Nuclear Power Plant Licensing "No extensions planned DENTON: HR Office of Nuclear Reactor Regulation 79/03/16 2pp Office of Nuclear Reactor Regulation 79/03/16 2pp
- ---7905150098 Comments on NUREC-0499, "Preliminary Statement on General Policy for Rulemaking to Improve Nuclear Plant Licensing," Alternative energy sources should be considered & believes there is no need for adding baseload capacity HITT.R.E Appalachian Research & Defense Fund, Inc. 79/03/12
- 7903130093 Executive Branch position re Mitsuline Travel Svc of America, Inc application for license to export reactor components & parts to Japan. License should be issued NOSENZO, L.V. State, Dept. of, Bureau of Doeans & Internati. Environ & Scientific Affairs XCOM-152 79/04/23. 19
- 7905150099 "Water Reactor Gafety Research, Heat Transfer Highlights" Jan 1979. LOTTES,P.A Argonne National Laboratory. DOE 40⇒550-75 78/11/30.
- 7905130101 Notification of contract execution, Mod 6 to "A/E Consulting Bycs." Contractor. Burns & Ros. Inc.
  MYNATTIA. Research Contracts Branch. FIN 8-6220 NRC-04-77-097, 79/03/31, 1p.
- --7905150109 Mod 6.no-cost time extension through 800331 to "A/E Consulting Bycs"

  MORTON, K. V Research Contracts Branch. FIN 8-6220.
  NRC-04-77-097 79/03/31 2pp.
- 7903130103 Application by Hoke. Inc for license to export motorized & isolating valves & spare parts to Korea.

  LINDWER.T P Hoke. Inc. 79/04/16. ip.
- 7905130106 Application by Hoke Inc for license to export bellows sealed instrument isolating valves & valve manifolds to Korea.

  \* Hoke, Inc. 79/04/19. 2pp.
- 7905150123 Executive Branch position re Mitsubishi Intl Corpapplication for license to export 342 kg U-235 to Japan.
  License should be granted.
  NOSENTOL V. State, Dapt. of, Bureau of Oceans & Internatl. Environ & Scientific Affairs. 79/04/16. 3pp.
- 7705150140 Monthly ltr rept for Feb 1979 re technical project status of "Aerosol Measurements & Modeling for Fast Reactor Bafety."
  OIESEKE, J. A. Bettelle Memorial Institute, Columbus Laboratories. 79/03/28. Эрь.
- 7905130134 Summary of 790330 meeting w/OE re Target Rock safety relief valves & review of progress toward reducing number of BMR blowdowns. NOWICKI, B. J. Operating Reactors Branch 2. 79/04/12, 16pp.

- 7905150155 Forwards patition to intervene & request for hearing on behalf of Ctr for Development Policy & two other intervenors as application for export license M/o anci.
  ASHERT R Asher T R. PC XBNMD 1471. 79/04/20. ig
- 7905150158 License for Mitsuline Travel 8vc of America. Inc to export miscellaneous reactor parts to Japan OPLINGER, O G Assistant Director for Export/Import & International Bareguards 79/04/13. 1p
- 7905150161 Application by Sigma Chemical Co for license to export compounds containing equivalent of 4 kg deuterium liquid over 2-year period to Australia Bigma Chemical Co (suba of Sigma Aldrich Corp.). 79/04/11.
- 7905150162 License for Mitsuline Travel Byt of America, Inc to export aiscellaneous specially designed or prepared parts for use in reactors to Japan OPLINGER, G. O. Assistant Director for Export/Import & International Safeguards 79/04/13, 1p
- 7905130179 Requests approval of proposal to expand scope of DDR generic issue 8-23, "Degraded Orid Voltage," to accommodate causes of degraded voltage identified by Arkansas Nuclear One abnormal occurrence VOLLMER, R. Assistant Director for Systems & Projects. 79/04/03
- 7905150183 Executive Branch position re Ediow Intl Co application for license to export 800,000 Gi of tritium to Switzerland, License should be granted MOSENZGL V State, Dept. of, Bureau of Oceans & Internati, Environ & Bcientific Affairs 79/04/18. 2pp
- 7905150186 Erecutive Branch position re Westinghouse application for license to export fuel rod tubes, springs & end plugs to Bweden License should be granted NOSENZOL V. Bette, Dept of, Burgau of Oceans & Internatl Environ & Scientific Affairs 79/04/12 2pp
- 7705150188 Responds to 770307 ltr.Since GA program description does not meet NUREO-0370, it will not be introduced to NRC topical rept program Wencl topical rept program description HAASS, M P L K Constock Engineering Co. 77/03/28 9pp.
- 7905150191 Executive Branch position re Mitsuiline Travel Svc of America. Inc application for license to export 18,000 poison tubes to Japan License should be granted.
  NOSENZO.L. V State. Dept. of. Sureau of Oceans & Internati. Environ & Scientific Affairs. 79/04/19. 2pp.
- 7905130195 Application by Transnuclear, Inc to amend export license to include addl quantity of 0.2 g of U-235.

  MATSON, V. Transnuclear, Inc. 79/04/18, 1p.
- 790513019B Application by Edlow Intl Co to amend export license to show ABEA ATOM as only intermediate consignee. HARHON, D. M. Edlow International Co. 79/04/10, 1p.
- 7905150199 Responds to SECY-79-88 "Timing of Certain Requirements of U Mill Tailings Radiation Control Act of 1978." Details gosition re federal-state authority to license mills w/regard to requirements of AEC Act Section 274.
  KING.B. New Mexico, State of. 79/03/07. Spp.
- 7905150203 Application by GE to amend license to export matl to Japan Requete rescheduling of first shipment to 790831.

  HILBON, B. D. General Electric Co., Nuclear Energy Products Div BDH-79098. 79/04/13. 1p.
- 7905150208 Application by General Atomic Co to amend license to espert fuel elements containing U to Japan Requests extension of expiration date to 800701, MOHRY, U.R. General Atomic Co. (subs. of Guif Cil Corp.). IEL-1048, 79/04/13, 1p.
- 7905150213 NUREO/CR-0595
  "Assessment of Intergranular Fracture Within Unrestricted UO2 Fuel Due to Film Boiling Operation."
  CRONENBERO: A V YACKLE.T.R. E O & G: Inc. FIN A-6046. TREE-1000. 79/00/01. 93pp. Available at NTIS.
- 7905130217 NUREO/CR-0513
  "Reactor Safety Research Programs." quarterly programs rept
  Jul-Bapt 1978
  KOUTB.H.J., KATO.W.Y., ROMANO.A.J. Brookhaven National Laboratory.
  EY-7A-C-02-0016 BNL-NUREO-50931. 78/11/30 215pp. Available at

- 7905180229 Commants on proposed rules 10CFR19 & 20 endoress proposed limit for mandating monitoring of minors 18 years of age or under who are exposed to radiation above natural background levels LAMPKA.J V Bunker Hill Community College 79/03/15 2pp
- 1905130238 Petition to separate NRC into two entities one covering power reactors. U mining, nuclear weapons mfg. nuclear fuel processors & other dealing w/byproduct metl PEEPLES. W P. Non-Destructive Testing Management Association 79/04/12 2pp
- 790513DG11 Responds to 790212 ltr re application for license to export monarite one to India. Application was forwarded to Executive Branch on 780621 for review BHEA. J.R. Assistant Director for Export/Import & International Bafeguards 79704/13. ip.
- 7905150314 Application by Borg-Warner Corp. Nuclear Valve Div for license to export globe & check valves, carbon steel & stainless steel to Helgium. ANDERGON.B. Borg-Warner Corp 79/04/16 1p.
- 7903130327 Ack receipt of 790321 1tr providing views on NRC interpretation & implementation of U Mill Teilings Radiation Control Act of 1978.
  BHAPAR, H K. Office of the Executive Legal Director 79/03/07 1p
- 7905150332 Weekly info rept for week anding 790427.
  REPRIT A Office of the Executive Director for Operations
  79/04/01 29pp
- 7705130342 NRC review of application need not be completed by 780331 due to probable change of ownership & mgt for MY Mineral Corp Keata project.Forwards Resources Corp 770313 ltr to CO Dept of Health HAZLE, A J Colorado, State of 79/03/16 4pp
- 7905150:149 Comments on NUREO-0523: "Bummary of Operating Experience w/ Recirculating Steam Generators " Considers this one of the Best repts on subj. BURBYEIN B Wisconsin Electric Power Co. 79/05/10 2pp
- 7905180368 Moves for protective order to prevent deposition of RM Qerdes Certificate of Svc encl.
  WATTE-M.J. DOYLE-M M. McCutchen, Doyle, Brown & Emerson, FURBUSH-M.H. Pacific Que & Electric Co. 79/03/31, 12pp
- 7903150369 Requests that GE rept NEDE-21944-P "Guarter Scale Pressure Euppression Pool Ewell Test Program:Plant Unique Tests" be included in docket.
  PILANT. J. H. Nebraska Public Power District. 79/05/08 1p
- 7905130474 Comments on proposed rule 10CFR19 & 20 adequacy of present occupational dose limiting stds is assential.
  BTRELOW:R. Commonwealth Edison Co. 79/04/19 ip.
- --7405150498 Comments on proposed rule 10CFR19 & 20: preferable to address dose accumulation & occupational exposure at reparate hearings Current proposel has not been thoroughly evaluated & potential consequences ignored. STRELOH, R. Commonwealth Edison Co 79/03/13, 5pp.
- 7903130824 FOIA request for info re all records of LERs & NRC insprepts on NL Industries, Inc Nuclear Div plant in Wilmington, DE.
  - BIVENE, T. News-Journal Co WI, Delware 79/03/19. ip
- 7903130528 Response to FOIA request for info re all records of LERs & MCC inserget on NL Industries, Inc Nuclear Div plant in Hithmington, DE. No LERs for NL Industries, Inc Forwards four facility licenses & insprecords. M/D encl. FELTON, J. M Division of Rules and Records. 79/05/10 is
- 7405150573 Certifies mati mentioned in GA Co license application to expert fistion chamber to Italy will be subj to all terms a conditions of amended 600725 addl agreement for representation. European Communities, Commission of, 79/03/26. ip. coseration.
- 7905150581 Forwards QA Program Insp Rept 99900060/79-01 on 790206-09.

  No nencompliance notes.
  POTAPDVS, U. Region 4. Dallas, Office of the Director 79/03/06.
- ---7903150585 GA Program Insp Rept 99900060/79-01 on 790206-09. No moncompliance noted. Major areas inspected: implementation of IOCFR50. App B & other applicable regulations. KELLY, W. D.: JOHNSON, J. M., WHITESELL, D. E. Region 4, Daliss, Vendor Inspection Branch. 79/03/02, 13pp.

- 7905150582 Informs that FR notice of denial of petition for rulemaking has been modified to indicate that five rether then four people have submitted comments on patition for rulemaking PRM 20-9 Revised page of notice en
- --7905150588 Comments on PRH 20-9 re allowable radiation levels for radiographer safety & radioactive transport suggests 50 is better level than 100 (at 5 cm), but 75 may be suitable compromise HHITE,M C . JACK, O C Atomic Energy Control Board, Canada 77/07/18 ip
- --7905i50592 Comments on PRN 20-9 & PRN 34-1 present limits are pragmatic providing necessary protection Recommends patition be denied as compliance would be too difficult to document & enforce SCHENDEL.K.R. Westinghouse Electric Corp. MRD-LSLS-273 77/07/18
- --7905150597 Comments on PRM 20-9 & PRM 34-1 new regulations not needed to overcome impracticality & inconsistency of results in determining radiation intensities at surfaces Changes will be too restrictive Niagara Hohawk Power Corp 77/07/18 1p
- ---7905150605 Comments on PRM 20-9 change restricts operations at nuclear power plants & does not follow ALARA philosophy Present rule is adequate UMRIOR E Florida Power & Light Co L-77-229 77/07/25 2pp Florida Power & Light Co L-77-229 77/07/25 2pp
- ---7905150611 Comments on PRM 20-9 confirms opposition expressed in 770718 telegram Finds first proposal reasonable, but second & third proposals are unacceptable JACK, 0 C. HHITE, M C. Atomic Energy Control Board, Canada 77/08/03 5pp
- --7905150617 Comments on PRM 20-9 change does not improve quality of survey, nor does it provide better control of external dose rates Proposed mods would be more impractical than existing regulations

  DEMERITTLE L Rochester Que & Electric Corp 77/08/10 ip
- 7903130614 Comments on proposed rules 10CFR19 & 20 endorses retention of quarterly dose limit & approves of proposed dose per CY BAIETTI.A L Affiliation Unknown 79/03/26 2pp
- 7705150652 Comments on proposed Reg Quide 8 23 acceptable contamination limits are too restrictive STRAUSB.K, J. Michael Reese Hosp. & Medical Center 79/03/21 1p
- 7903130702 Responds to 790303 ltr commenting on proposed deletion of dass avaraging formula 5(N-18) Forwards draft rept of interagency Task Force on Ionizing Radiation W/o encl ALEXANDER: R E Occupational Health Standards Branch 79/03/15
- --7905150706 Requests citations re-epidemiological data & associated recommendations for noncomulative lower stds FRDQQE.J L Affiliation Unknown 79/03/05 ip
- 7905150705 Forwards application amend request from GE to change date of first scheduled shipment from 791201 to 790831 W/o encl OPLINGER: 0 0. Assistant Director for Export/Import & International Safeguards 79/04/23 1p
- 7905150710 Gral argument ABLB 790125 order will DUFLO.H E Atomic Sa
- 7905150716 Denies Ci 790502 as date for MILLER, M E.
- 79051507 valuab in dec their GABRIE
- 79051507 USETS

,1

1 1

111

1 4

A CONTROL OF THE PARTY OF THE P

'n

- 7905150731 Notification of 790510 meeting w/util & NY State in Btuyverant.NY to provide NRC review team apportunity to visit alternate site in order to discharge NEPA obligation BELLS.D E Environmental Projects Branch 2 79/04/27 2pp
- 7905150734 Comments on proposed Reg Guide 10 8 "thin window" survey mater not necessary to detect low radiation. Sensitivity requirement for area wipe tests too low GORRAN. H C Laksview Medical Center DA. Illinois 79/04/03. 1p.
- 790515073B Comments on proposed rulemaking 10CFR2 714 recommends denial of petition as destructive of present balance between citizen interest & administrative needs. Proceedings could be indiscriminately re-opened & continued TROWBRIDGE.O.F Bhaw. Pittman. Potts. & Trowbridge 79/04/18 4pp
- 7905190741 Comments on proposed Reg Guide 1.8.Revision 2-believes staffing requirements for technical competence are much too low HILLIS,C A Philippines, 79/04/02 ip
- 7905130752 Comments on proposed Reg Quide 3 B opposes provisions requesting into an one body location & openings of related mines because mill operator should only be responsible. WALPOLE, J. R. American Mining Congress 79/03/14 13pp
- 7903150777 "Study of Plutonium Oxide Leak Rates from Shipping Containers," quarterly progress rept Oct-Dec 1978 SCHMENDIMAN,L.C. MADIA:M.J. MISHIMA,J Battelle Memorial Institute, Pacific Northwest Laboratory FIN 8-2093, PM.-2260-9, 79/02/01. 43pp Available at NTIS,
- 7905150784 Requests quantity of matt be raised to 75 kilos of ThF4 & attension of expiration date to 791231 for license to export thorium to Scotland.
  COLTON: E Cerac, Inc. 79/04/27 2pp
- 7905130785 Comments on proposed rulewaking 20-13 amend may be appropriate for nuclear power plants, but should not cover airline amployees AMPERSON, C.R. American Airlines, Inc. 79/04/12, 1p.
- 7905150787 License for GE to export four NA 200 local power range annitors to India.

  OPLINGER, 0 G. Assistant Director for Export/Import & International Safeguards 79/04/30 ip
- 7905150792 Forwards GA Program Insp Rept 99900077/79~01 on 790226~0301 No noncompliance noted. POTAPOVS, U Region 4, Delias, Vendor Inspection Branch, 79703/15 2p.
- ---7905150797 GA Program Insp Rept 99900077/79-01 on 790225-0301 No noncompliance noted. Major areas inspected; implementation of iOCFR30, App B criteria, applicable codes & stds & actions on previous insp finding ROBERDS, H W. HUNNICUTT, D M. Region 4, Dailes, Vendor Inspection Branch. 79/03/14 Spp.
- 7905150803 Supplemental answer by util to first set of interrogatories.

  Affidavit & Certificate of Svc encl.

  DOYLE,M M., HOULTHAN.T.J. McGutchen, Doyle, Brown & Emerson

  HEISS,R L. Pacific Gas & Electric Go. 79/04/16 6pp.
- 7905180804 License for Air Products & Chemicals, Inc to export 100 g 'deutsrium to United Kingdom OPLINGER, Q O Assistant Director for Export/Import & International Safeguards. 79/04/27. Zpp.
- 7905150807 Executive Branch position re Eddaw Intl Go application for license to export 593 kg U-235 to United Kingdom for debrication into fuel assemblies for reload in Italy License should be granted Ltr of assurance sncl. NOSENZO.L V. State. Dept of, Bureau of Oceans & Internat). Environ. & Scientific Affairs. 79/04/24. 2pp.
- 7905150B08 Responds to 790323 request Provides comments & recommendations re-proposed revision of Reg Guide 1.89. Btatements conflict re-length of time that equipment must function eafely VOLIMER:R Assistant Director for Bystems & Projects, 79/04/19.
- 7905190810 License for Teledyne Wah Chang Albany to export 16,000 1b Zirceloy to Canada CPLINGER, G G. Assistant Director for Export/Import & International' Safeguards. 79/04/27. ip.
- 7905150813 License for Sigms Chamical Co to export 2 kg heavy water to Belgium. OPLINGER, 0.9 Assistant Director for Export/Import & International Safeguards. 79/04/27. 2pp.

- 7905150815 License for Transnuclear, Inc to export 360 kg U-235 to Belgium OPLINGER, 0 Q Assistant Director for Export/Import & International Bafeguards 79/04/27 2pp
- 7905160105 Comments on 790306 request for transmission of info to ASLB re reactor inspector's concerns about BMM plants
  SHAPAR,H K Office of the Executive Legal Director. 79/03/29 2pp
- --7905160109 Forwards procedures for notifying ASLB: ASLAB & NRC of new info SHAPAR: H, K Office of the Executive Legal Director 78/07/12
- 7905160228 Executive Branch position re Eberline Instrument Corpaphication for license to export 81.6 micrograms Pu-239 to Indonesia MOSENZO,L. V State, Dept of, Bureau of Oceans & Internati. Environ & Scientific Affairs 79/04/24 2pp
- 7905160234 Executive Branch position re Cordis Corp application for license to export 45 g U-238 to Baudi Arabia & Jordan. NOSENZO.L.V. State, Dept of, Bureau of Oceans & Internati Environ & Scientific Affairs. 79/04/23 2pp
- 7905160230 Transcript of 790426 meeting of Subcommittee on Licensea Evaluation Repts in Mashington. DC Pp 1-242 MOELLER.D. W. ETHERINOTON.H., RAY.J.J. ACRS - Advisory Committee on Reactor Safeguards. 79/04/26 244pp.
- 7903160370 Responds to 790307 request for add1 info re "Evaluation of Transient Behavior & Small RCS Breakt in 177 Fuel Assembly Plant." Forwards ref matl & add1 info re App 2, TAYLOR: J. H Babcock & Wilcox Co. 79705710
- 7905i40373 Responds to NRC request for add1 info re small break analysis in "Evaluation of Transient Behavior & Bmall RCB Breaks in 177 Fuel Assembly Plant," Forwards requested analysis.

  TAYLOR, J. H. Babcock & Wilcox Co. 79/05/12 44pp.
- 790316038B Responds to NRC request for info on R&W 790307 rept re "Evaluation of Transient Schavior & Small RGS Breaks in 177 Fuel Assembly Plant." Discusses pump status.operating limits & position on pump integrity TAYLOR.J.H. Bebcock & Wilcox Co. 79/05/10 3pp.
- 7903160391 Bubmits schedule for completion of generic licensing topical rept in response to NRC 790426 request.
  CLARK.C.N. Ederer, Inc (subs. of Formac International, Inc.)
  79708/11. 1p.
- 7905160441 Comments on NUREO-0531, "Investigation & Evaluation of Stress Corrosion Cracking in Piping of LWR Plants: " more detailed recommendations for inservice insp being prepared. Requests add! info ORIDLEY.R.L. General Electric Co., Nuclear Energy Products Div. HFN-130-79, 79/05/04, 9pp
- 7905170277 Forwards "Upward Fire Propagation in Vertical Cable Tray Fire Propagation Over Central Thermally Thin Cables" & "Fire Resistance of Cable Penetration Seals: Theory for Radially Isothermal Cables." FEIT.R. Division of Reactor Safety Research 79/04/12. 2pp
- ~-7905170279 TR-39

  "Upward Fire Propagation in Vertical Cable Tray Fire
  Propagation Over Central Thermally Thin Cables."
  HUNTER, L. W. Johns Hopkins Univ. 79/03/12. 12pp
- ---7905170282 TR-40

  "Fire Resistance of Cable Penetration Sesis: Theory for Radially Isothermal Cables."

  HNTER:L.W Johns Hopkins Univ. 79/03/30, 9pp.
- 7905170280 Application by Hoke. Inc for license to export bellows-spaied instrument isolating valves to Canada, LINDNER. T. P. Hoke, Inc. 79/04/06. App.
- 7905170283 Application by Hoke, Inc for license to export beliaws-sessed instrument isolating valves to Canada.

  LINDNER, T. P. Hoke, Inc. 79/04/04. App.
- 7905170288 Application by Hote, Inc for license to export hellows-sealed sealed globe pattern, nonrising stem valves to Canada.

  LINDNER, T. P. Hote, Inc. 79/04/05. App.
- 7905170289 Application by Hoke, Inc for license to export bellows-sealed valves, three valve manifolds & bellows-sealed instrument isolating valves to Canada.

  LINDNER, T. P. Hoke, Inc. 79/04/09. 4pp.

- 1903170293 Application by Hoke, Inc for license to export belieus-sealed valves, three valve manifolds, globe valves & instrument isolating valves to Canada, LINONER, T. F. Hoke, Inc. 79/04/03 9pp.
- 1903170039 Lists contract codes/previous employee codes for previous radiation exposure.

   Uffice of Inspection & Enforcement. 79/02/12, 11pp
- 7905170063 Responds to 790115 ltr Porwards requested addl info re electrical equipment qualification AMDERSON, Y. M. Westinghouse Electric Corp NB-TMA-2059. 79/05/14 Clop
- 1903190064 Discusses execute of TLDs to radiation under specified conditions in response to NRC requests EIBERNOMERS E IC Commerce, Dept of, National Bureau of Standards 19/04/20 ip
- 7903190065 Forwards addit requested info re small brook ECCB analysis ANDERBON, T. M. Nestinghouse Electric Corp. N8-THA-2085. 79/03/16 Dipp.
- 1905190161 Forwards "Evaluation of Transient Schavior & Small RCS Steals in 177 Fuel Assembly Plant:" Vols 1 & II.App TAYLON, J. H. Babcock & Wilcox Co. 79/05/07 2pp
- ---7905190164 "Evaluation of Transient Schavior & Small RCS Breaks in 177
  Fuel Assembly Plant," Vols I & II.App.
  \* Babcock & Wilcox Co. 79/08/07. 500pp
- 7903170200 Discusses organizational changes in OA dept which will be implemented during next revision to StM 9A plan. BMS0AP 1-74A

  MELLY-R B Stone & Hebster Engineering Corp. 79/05/09 2pp
- 7905210094 Commants on IEEE 379 draft of May 1976; not accepted because of confusing language HANAVER, B H. Office of the Executive Director for Operations 76/06/17 1p
- 7905210136 Forwards "Mark-BZ Demonstration Assemblies Licensing Reptr" graphistary & nonpropriatary versions Affidevit for withholding encl (ref 100FR2, 770) TAYLDR, J. H. Babcock & Hilcox Co. 79/05/03. 7pp
- "-7905210130 NAW-1833
  "Hark-BZ Demonstration Assemblies Licensing Rept,"
  nonproprietary Version
  a Babcock & Wilcox Co. 79/04/30. 11pp.
- 7905210146 Responds to 780926 ltr Forwards additinfo re reactor core response to excessive secondary steam releases Remaining questions will be answered by 790701.
  ANDERBON.T M Hestinghouse Electric Corp. N8-TMA-2080. 79705/07 22pp.
- 7903210132 Forwards "Mark I Containment Program Bafety/Relief Valva Analytical Models for Use M/Remembed Discharge Davices,"
  Tast 7, i. t. 1, Maffidavit for withholding tref 100FR2, 790), 
  808001. J. General Electric Co (Nuclear Energy Products Div. 
  MEN-5.29-79 79/08/07. 190pp.
- 7903210166 FBAR Amend 35 incorporating changes to Section 13 9.

  # Hanford Engineering Development Leboratory HEDL-T1-75002-3
  79704/30. 65pp.
- 7405210184 Forwards FSAR Amend 30 revision of Chapter 17 "FFTF Tech Bjecs." Goes not constitute DDE technical approval for fuel lead.

  ### BAIRD G.L. Henford Engineering Development Leboratory 00285
  77/03/14 ip.
- ---7905210187 Revision of chapter 17 "FFTF Tech Space," submitted as Amend 30 to FSAR.

  # Hanford Engineering Development Laboratory, HEDL-TI-75002-3 79/03/31. 275pp.
- 7905210232 Bummary of "Decay Heat Removal During Small Break LDCA for BLM 205 Fuel Assembly PMR." MICHELBON.C. Sabcock & Wilcox Co. 78/01/31. 3689
- 7905220023 Porwards BN-TOP-4 Revision 1. "Bubcompartment Pressure & Temp Transient Analysis."
  JUDD, J. C. Bechtel Power Corp. (subs. of Bechtel Corp.). 79/05/10. is.

- 7905220034 Comments on proposed rule 10cFR19 & 20 concurs w/proposed radiation limit Recommends that MPC Formed be radiational to rule by individual in disclosing previous substance records to licenses BRONSON, F Health Physics Society 79/03/16 4pp
- 7908220043 Research Info Ltr 49 in vitro dissolution of U product tampites from four U mills
  LEVINE.S Office of Nuclear Regulatory Research LF-59 79/04/04
  5bb
- 7905220051 BECY-79-256
  Notifies of MRC review of proposed issuence of license to
  Esson Nuclear Co.Inc to import 40.000tg U-235 from Russia
  Recommends license by issued
  SHEA.J.R Office of International Programs 79/04/12 3pg
- --7903220060 License for Exton Nuclear Co. Inc to import 40,000 kg. enriched to max of 3 i% in U-235 (sotope as U herafluoride. from Russia UPLINGER,0 0 Assistant Director for Export/Import & International Safeguards 79/01/25 2pp
- 7905220036 Provides further response to DB Comey 781005 ltr requesting documents re NUREO-75-D67 & 02 SUR gipe creating problems accurring since 1975 Forwards biblingraphy of available documents
  FELTON-J M Division of Rules and Records 79/04/18 Dpp
- 7905220079 Transcript of 790502 briefing on steam generator denting & replacement, held in Mashington, DC Pp 1-69
  HENDRIE, J H , OILINSKY, V , KENNEDY, R T Commission 79/05/02
  70pp
- 7903220080 Forwards nonproprietary & proprietary versions of Amends 3-NP & 3P to CENPD-183. "Evaluation of Uncertainty in Muclear Form Factor Measured by Belf-Powered Fixed Incore Detector Sys " Hyaffidavit for withholding (ref 10CFR2 790)
  SCHERER. A E Combustion Engineering. Inc. LD-79-025 79/04/30
- --7905220083 CEMPD-153 3-MP
  Nonproprietary version of Amend 3-MP to CEMPD-153,
  "Evaluation of Uncertainty in Nuclear Form Factor Measured
  by Self-Powered Fixed Income Detector Sys," revised Chapter
  4; rod power calculation error
  e Combustion Engineering, Inc. 79/04/30 53pp
- 7905220324 Forwards Suppl 1 to Section 6 of "Evaluation of Transient Behavior & Small RCS Breaks in 177 Fuel Assembly Plant," atd 790507
  TAYLOR, J H Babcock & Wilcox Co 79/05/12 1p
- ~~7905220330 "Evaluation of Transient Bahavior & Email RCS Breaks in 177 Fuel Assembly Plant," Vol 1, Section & 0, Suppl 1 # Sabcock & Wilcox Co 79/05/12 41pp
- 7905220348 Discusses Leibnitz rule simplification b high heat transfer in LOGA models. Provides verified results demonstrating that current LOGA evaluation model is conservative in calculation of peak clad temp BTROUPE.E.P. General Electric Co. MEN-124-79 79/03/02 11pp.
- 7905220409 Forwards Suppl 1 to App 2: "Steam Generator Tube Thermal Stress Evaluation " TAYLOR: J H Babcock & Milcox Co 79/05/10 1p
- ---7705220410 "Steam Generator Tube Thermal Stress Evaluation, " Suppl 1 to App 2 # Babcock & Hilcox Co 79/05/10 25pp
- 7905220422 Responds to IE Builstin 79-06A re TMI incident Forwards addited to clarify position on Item 7 re operating procedures & training instructions
  ANDERSON, T. M. Nestinghouse Electric Corp. NS-TMA-2087. 79/05/17.
- 790322044B Requests Erscutive Branch position to Signa Chastcal Co application for license to export heavy water to Argentina OPLINGER: 0 Assistant Director for Export/Import & International Befoguards 79/04/23 lp.
- 7905220449 Requests Executive Branch position re Ediow Inti Co application for license to export source mati to Brazii GPLINOGR.0 G. Assistant Director for Esport/Import & International Gefeguerds 79/04/23 ip
- 7905220468 Forwards distribution list for bundle test interim data repts.
  PICKLEGIMER, M L Fuel Behavior Branch 79/04/17 App.

- 7905230098 Summary of 790501 meeting w/C-E in Bethesda.MD re natural circulation in C-E operating reactors + Reactor Systems Branch 79/05/01. 88pp
- 7905230280 Bubmits info re renewal of License 818-678 Application to be filed 30 days before expiration date of existing license LAYFIELD,R L Atomic Energy Commission (Pre 1975) 64/07/06 1p
- --770523073B Submits add1 recommendations re mfg procedure controls Proposes radiation measures conducted to assure sufficient radiation control Includes results of survey conducted re radioactivity in controlled & uncontrolled areas CARRIQAN.R H Fellows Medical Hfg Co., Inc., Fellows-Testagar Div 64/12/17. 3pp.
- --7908230247 Requests extension from 641122 to 641222 of submission deadline for procedures of controlling agreed of contamination.

  CARRIGAN: H Fellows Medical Mfg Co . Inc . Fellows-Testager Div 64/11/04. Ip
- --7903230586 Ack receipt of 680126 ltr notifying of license expiration Forwards application for renewal of License STB-678 CARRIGAN,R H Fellows Hedical Hfg Co., Inc., Fellows-Testagar DIV. S76. 68/08/07 ip
- --7905230470 Notifies that License STB-478 expires 680331, NUSSBAUMER, D.A. Atomic Energy Commission (Pre 1975) 68/01/26
- 7905230124 FOIA request for info re Thorotrast, licensing, manufacturers & licensees, FELDMAN:S M Feldman & Feldman 79/04/06. 1p
- 7905240174 Application by GE for license to export 29,526 kg low enriched U oxide powder, enriched to max of 3 65% U-235, to Japan. WILSON: 8, D â,D. General Electric Co ,Nuclear Energy Products Div 79/04/03. 4pp. 77073
- 7905230188 Agenda for ACRS 790416-17 maeting w/NRC & nuclear industry representatives in Washington.DC to discuss IE Bulletin 79-05A. "Nuclear Incident at TMI," & other related items.

  \* ACRS Advisory Committee on Reactor Sateguards, 79/04/11, 3pp
- 7905230301 Executive Branch position re Mitsuiline Travel 8vc application for license to export components & parts for test reactors to Japan License should be issued NOSENZOL V. 8 Japan bet, of, Bureau of Oceans & Internati. Environ. & Scientific Affairs. 79/04/19, 2pp.
- 7905230396 FOIA request for related documents on WASH-1400 & SECY-78-137.as identified in HR Denton 781211 memo to LV BURT.L Massachusetts, State of 79/04/18 Spp.
- 7905230400 Response to FDIA request for related documents on WASH-1400 & BECY-78-137 Forwards 14 requested documents; others not yet reviewed by NRC FELTON.J M Division of Rules and Records. 79/05/11 2ps. Division of Rules and Records, 79/05/11 2pp.

liscusses review of draft liquid pathway generic study i to subje re WASH-1400 Contemination risks should id realistically, per recommended revisions.

Office of Nuclear Regulatory Research. 76/08/09 9pp

rds draft responses for CA Energy Resources : Development Commission in response to 740723 'robabilistic Analysis Branch 76/08/23, 12pp,

ints on EPA draft publication concerning technical projection methods to be used as basis for Jones for nuclear accidents; rept is of little only hypothetical conditions evaluated. Vice of Nuclear Regulatory Research. 76/10/07. Spp

isses technical errors noted in Judge JB McMillan irolina Environ Study, Inc. et al. vs AEC, et al ferstanding of Levine's testimony & error in its heat rejected by plants is significant. Probabilistic Analysis Branch. 77/05/17. App.

ents on draft NUREO-0396. "Modified Planning Basis for P State & Local Govt Radiological Emergency I in Support of LWR:" use of 10-mile & 30-mile 10 radii is excessive Fice of Nuclear Regulatory Research. 78/03/22. 3pp

- ---7905230443 Comments on sections of QBA draft environ statement re disposal of Charlestown Naval Auxiliary Landing Field: "hazards" should be referred to as "risks " BURLAR Probabilistic Analysis Branch 78/06/06 2pp
- --7908230449 Discusses review of ATHS suppl (NUREO-0460) ATHS is not overwhelming safety problem in plant design ATHS risk estimates cannot be substantially improved BUHL-A.R Probabilistic Analysis Branch. 78/09/21 2pp.
- --7905230453 Forwards comments on "Investigation of Probability of Hypothetical Catastrophic Accidents in Oyster Creek Nuclear Power Plant." by PR Davis upper bound estimate of protection sys failure probability is not justified LEVINE.8 Office of Nuclear Regulatory Research 76/11/09 10pp
- --7903200460 SECY-78-624
  Requests approval of NRC response to PIRO, at al, petition for rulemaking to amend 10CFR100 rs population density criteria around nuclear reactor sites
  MINOGUE, R B Office of Standards Development 78/12/04. 137pp
- ---7905230470 Comments on SECY-78-624, PIRC petition for rulemaking on population density around reactor sites, proposed response by NRC is deficient.
  PEDERSEN.K B. Office of Policy Evaluations KELLEY, J. Office of the Coneral Coursel 79/01/04. 11pp.
- --7905230701 Informs that NRC will seek recommendation of Siting Policy Task Force before taking action on SECY-78-624. CHILK, S J Office of the Secretary of the Commission 79/01/04
- ---7905230494 Requests progress briefing by Biting Policy Task Force rework status, problems, plans & principal issues receiving task force attention Comments on role of certain concepts in policy for site evaluation CHILK. B J Office of the Secretary of the Commission. 79/01/05.
- -7705230494 Comments on SECY-78-624:PIRG petition for rulemaking on population density around reator sites:NRC should not respond to petition until further info is received Agraes W/request for task force briefing.

  AHEARNE, J F. Commission 79/01/09 ip
- -7905230499 Comments on SECY-78-624.PIRG patition for rulemaking on population density around reactor sites Gommissioner Ahsarne believes task force should be informed of specific questions re petition or proposed responses. CHILK, S. J. Office of the Secretary of the Commission. 79/01/11
- --7905230713 Comments on SECY-78-624.PIRO petition for rulemaking on population density around reactor sites:RT Kennedy proposed response to petition is acceptable SHAPER.H.K Office of the Executive Legal Director. 79/01/11
- --7905230508 Proposed Reg Guide 1.3. "Assumptions Used for Evaluating Light Water Power Reactor Biting Distances for Purposes of 100FR100."
  - Office of Standards Development 78/12/31, 13pp.
- ---7905230311 Proposed Reg Quide 1.4 "Assumptions Used for Evaluating Potential Rediciogical Consequences to Public from Design Basis Accidents in LHRs for Purposes of 10CFR30 & 51." Proposed revision to 10CFR100 encl.

  \*\* Office of Standards Development. 78/12/31. 4ipp.
- 7905230524 Requests Executive Branch position re Hoke, Inc application for license to export components to Argentina.

  OPLINGER, O. O Assistant Director for Export/Import & International Safeguards 79/04/26 ip
- 7905230533 Requests Executive Branch position re Transmuclear.Inc application for license to export SNM to Denmark. GOSSICK.L. V Office of the Executive Director for Operations. 79/04/26. ip.
- 7905230537 BECY-79-272 Informs Commissioners of receipt of withdrawal of 780608 license application by Samincorp, Inc to export mati to SHEALJ R. SHEA.J R. Assistant Director for Export/Import & International Safequards, 79/04/17, 19

- --7905290835 Responds to 790212 ltr re application for licence to expert monazite ore to India. Application forwarded 780621 to Executive Branch for review. Review close to completion when application was cancelled in Dec 1978.

  BHEA-J.R. Office of International Progrems. 79/04/13. ip
- F703230541 Gumments on proposed rulemaking 100FR2-7 existing rules are adequate for protection of rights of parties & necessary to give finality to proceedings. PORTER.M.L. Duke Power Co. 79/04/13 2pp
- 7905230533 BECY-79-271
  Provides background info re proposed issuence of license for Edlow Intl Co to import enriched U from Japan Recommends License be granted 影響者, J R, Office of International Programs 79/04/16, 3pp.
- 7909230559 Executive Branch position re Byron Jackson Pump Div application for license to export components & parts to Bultzerland License should be granted MOSENIOL V. State. Dept of Bureau of Oceans & Internati Environ. & Buleautific Affairs 79/04/24 Spp
- 7903230367 Requests license to import fuel assemblies being returned to US from Japan for reprocessing on behalf of British Nuclear Fuels, Ltd Unsigned import license encl EDLOH, J Edlow International Co 79/02/07. 3pp.
- 7905230572 Agenda of 790308-10 227th AGRS meeting in Washington DG to discuss various AGRS repts re status of LMR generic items & dynamic loads as design basis for nuclear facilities & AGRS Advisory Committee on Reactor Safeguarás 79/02/28 5pp
- 7905230575 Executive Branch position re Syron Jackson Pump Div application for license to export parts for use in reactor coolant pump to Italy. License should be granted MOSENTOL. V. State. Dept. of. Bursau of Oceans & Internati. Environ & Scientific Affairs. 79/04/24 2pp.
- 7903230777 Comments on proposed Rep Ouids 8,23 guide is too specific & leaves no leaway for health physicists to follow best course of action. Guide simed at procedure & not protection. EVHAETB, J C. Health Physics Society. 79/04/17. 2pp
- 7405230581 Forwards GA Program Insp Rept 99900510/79-01 on 790226-0302 & notice of violation FOTAPOVG.U. Region 4. Dallas, Vendor Inspection Branch 79/03/18. 2pp.
- --7905230587 Notice of deviation from insp on 790226-0302 Region 4: Dallas, Vendor Inspection Branch. 79/03/14 1p
- --7905230593 GA Program Insp Rept 99900510/79-01 on 790226-0302.

  Moncompliance noted released atrest repts not revised by committed corrective action completion date COSTELLO, J. R., BROHN, R. L., HALE, C. J. Region 4, Dallas, Vendor Inspection Branch, 79/03/14 15pp.
- 7908230897 Executive Branch position re DE application for license to apport components & parts to Japan, License should be granted.
  NOBENZO, L. V Brate, Dept. of, Bureau of Oceans & Internati, Environ, & Scientific Affairs, 79/04/24, 25p.
- 7903230608 Notifies of current status of PRM-71-6 re emergency response for transportation accidents involving radioactive matis Draft rept of NRC/DOT study of transportation hazards released for public comments which NRC must consider MINGOUS R. B. Office of Standards Development, 79/04/17. ip.
- 7403230624 Amend 4 to License IBNM-1610 for Transnuclear, Inc. extending expiration date from 790630 to 800630.

  DPLINGER, Q. Q. Assistant Director for Export/Import & International Bafeguards. 79/04/13. 1p.
- 7905230634 Provides NRC conclusions re Exxon Nuclear Co. Inc Sept 1978 application to export 85,400 kg U to Esigium License should be Isaved based on Executive Branch position & end use statement.

  MODRE, R. N. Office of International Programs 79/04/27, ip.
- 7908230638 Notification of contract execution: "Two Phase Flow Aspects of Reactor Bafety," awarded to Dartmouth College, Reactor Bafety, awarded to Dartmouth College, FIN 8-6525, MARC-03-79-102, 79/04/24 ip.

- ---7905230647 Contract "Two Phase Flow Aspects of Reactor Bafety."

  awarded to Dartmouth College

  DOUCHERTY. D 1 Division of Contracts FIN 8-6525

  NRC-03-79-102 79/04/24 16pp
- 7903230669 Executive Branch position re SW Shattuck Chemical Coapplication for license to export 10 3 16 depleted U to Mexico License should be granted MOSENZO.L V State, Dept of Bureau of Oceans & Internetl Environ & Scientific Affairs 79/04/30 2pp
- 7903230682 Notification of contract execution:Mod 8 to "Assessment of Nuclear Industrial Impact on Environ" Contractor Univ of HA HAGEY, H Research Contracts Branch FIN 8-3679 NRC-04-75-222 79/04/94 In
- --7905230690 Mod 8. continuing funding & work on Task 4 to "Assassment of Nuclear Industrial Impact on Environ" HORTON, K.V. Research Contracts Branch FIN 9-3679 NRC-04-75-222 79/04/19 Spp
- 7905230696 Notification of change in 790328 talegram & 790331 lir to read "Uranio" instead of "Uranios" WILBON.B.D General Electric Co, 79/03/30 Jp
- 7905230697 Notification of contract execution Mod 3 to "Improvement of Lider Tachniques for Analyzing Atmospheric Dispersion of Nuclear Power Plant Effluents "Contractor Btanford Research Inst HAGEY, N. Research Contracts Branch FIN 8-6222 NRC-04-77-147 79/04/25. in
- --7905230702 Mod 3. changing period of performance to 790430 at no cost, to "Improvement of Lider Techniques for Analyzing Atmospheric Ofspersion of Nuclear Power Plant Effluents " HORTON K V Research Contracts Branch FIN 8-6222 NRG-04-77-147 79/04/25 2pp
- 7903230708 Executive Branch position re Edlow Intl Corp application for license to export 2,190 kg U-235 to Swaden License should be granted. Ltr of assurance ancl NOSENIOL V State. Dept of Suresu of Oceans & Internet! Environ & Scientific Affairs 79/03/01 2pp.
- 7905230716 Bubmits MRC conclusions or Transnuclear, Inc application for license to export 18,951 kg U to West Germany License should be issued MCQRE, R N. Office of International Programs. 79/04/27 1p
- 7905230717 Notification of contract execution, Mod 5 to "NBB Control Room Infiltration Program." Contractor Dept of Commerce HENCZER.W B Technical Assistanca Contracts Branch FIN 8-5327. 79704740. 1p.
- --7903230720 Mod 5. decreasing funding by \$80 47 to "NBB Control Room Infiltration Program"

  DOUGHERTY, D. J Division of Contracts FIN 8-3329 79/04/30
- 7905230741 Research Info Ltr 49.invitre dissolution of U product tamples from four U mills.Forwards NUREO/CR-0414 H/o encl LEVINE.S. Office of Nuclear Regulatory Research 79/04/04 5pp
- 7905230749 Forwards UCR petition requesting that NRC order immediate reanalysis of operating plants to determine adequate earthquake protection.
  WEISB.E.R Sheldon: Harmon & Roisman. 79/03/28 2pp.
- --7903230760 UCS emergency petition for reanelysis of capacity of operating US nuclear power plants to withstand earthquakes WEISS.E.R. Sheldon, Harmon & Roleman. 79/03/28. 10sp
- 7905230761 Comments on proposed Reg Quide 1, 144; flaxibility provided by ANSI N45, 2 12-1977 is extremely beneficial to auditing operation while still ensuring that goals of program are achieved.

  SULLIVAN, T. J. Gonsumers Power Co. 79/03/20. 2pp.
- 7903230743 Agenda for 781207-09 224th ACRS meeting in Washington DC to discuss ACRS annual rept to Congress on NRC safety research progress. # ACRS Advisory Committee on Reactor Bafeguards 78/11/21. 2pp
- 7905230778 Comments on proposed Reg Quide 1, XXX. "Functional Spec for Bafety-Related Valve Assemblies in Nuclear Fower Flents" doubts industry acceptance of ANSI N278.1 & applicability. OAVIOAN.F. X Energy: Dept. of. 79/04/12 is.

46.5

- 7905230781 Confirms understandings re 781013 application for license to export 110,230 lb Zircalog-4 tube shalls to Hest Germany License action will be withheld panding retransfer assurances from Iranian govt.

  OPLINGER.O O Assistant Director for Export/Import & International Safeguards 79/04/13 lp
- 7905230787 Agenda of 790104-05 225th ACRS meeting in Washington, DC to discuss ATHS & reg guides # ACRS ~ Advisory Committee on Reactor Safeguerds. 78/12/23 3pp
- 7905230788 "Dosimetry & Biotransport Models to Implement ALARA," quarterly progress rept, Oct-Dec 1978
  KILLOUGH, Q O , KOCHER, D C Dak Ridge National Laboratory FIN B-0188 ORN./HASRD-21. 78/12/22 4pp
- 7905230801 Notifies that C Hait is Plant Sys Branch representative to follow meths aspects of qualification testing evaluation.
  STELLO, V. Division of Operating Reactors 79/04/06 ip
- 7905230814 Requests plant shutdowns be scheduled to avoid blactouts. Firm's production is directly dependent upon availability of electric cooling sys MAY.K N Affiliation Unknown 79/04/26 1p
- 7905230820 BECY-79-142A

  Notifies of NRC review of proposed Westinghouse license to import low enriched U from Sweden. Recommends license be issued

  BHEA, J. R. Office of International Programs. 79/04/12. 3pp
- 7905230822 SECY 79-255
  Informs of completion of NRC review of proposed emend to Erron license to import partially completed fuel assemblies from Hest Germany Amend should be Issued.
  SHEA.J.R Office of International Programs 79/04/12. Spp
- --7705230828 Amend i to Erron Nuclear Co, Inc license to export increased quantity of U-235 to Hest Germany GPLINGER: 0 O Assistant Director for Export/Import & International Safeguards 79/01/02 ip.
- ---7903230839 License for Exxon Nuclear Co, Inc to export 2.557 kg U-235 to West Germany OPLINGER.00 Assistant Director for Export/Import & International Safeguards 77/08/23 2pp.
- --7905230846 Amend 1 to Exxon Nuclear CorInc license to import increased amount of U from West Germany.

  OPLINGER, O G Assistant Director for Export/Impurt & International Safeguards 78/12/04 ipp.
- 7905230849 Forwards request for add1 info re NEDO-21868, "Mark I Long-Tarm Program Load Definition Rept " EISENHUT, D O Division of Operating Reactors. 79/05/03. 5pp
- 7905240001 SECY-79-102A
  Provides NRC refew of proposed issuence of license to Mitsubishi Intl Corp to export source matl to Canada, Request Commissioner comments by 790330, SHEA.R. Office of International Programs, 79/03/30, 3pp
- ---7905240005 Forwards application for license to export source matl to Eldorado Nuclear Ltds Ganada.
  TBUJI,K Mitsubishi International Corp (subs. of Mitsubishi Corp ). NYC/HA-646. 78/09/14 ip.
- --7905240010 Application for Mitaubiahi Intl Corp to expert 538,511 to U contained in 635,036 tg U-308 to Camada.
  TBUJI,K. Mitaubiahi International Corp. (subs. of Mitaubiahi Corp.) H8A-5686-01. 78/09/14 2pp.
- 7905240021 NRC position re Transnuclear, Inc application for license amend to export low enriched U to Switzerland, License should be granted tiORETR, N. Office of International Programs. 79/04/09. 1p
- 7905240023 Forwards application for export license for minor nuclear asport. Ltr of assurance required. M/o encl. OPLINGER, 0.0. Assistant Director for Export/Import & International Safeguards 79/04/26, 1p.
- 7905240025 NUREO/CR-0040 V1 N4
  "Licatese, Contractor & Vendor Insp Status Rept," quarterly rept.

   Office of Inspection & Enforcement, 78/06/30, 308pp. Available at NTR, 412 50.

- 7903240028 NUREO-0040 V3 Ni
  "Licenses, Contractor & Vendor Insp Status Rept," quarterly
  rept
  # Office of Inspection & Enforcement 79/03/31 130pp Available
  at NTIS #12.50
- 7905240031 NUREQ-0040 V2 N6
  "Licenses:Contractor & Vandor Insp Status Rept," quarterly
  rept
  # Office of Inspection & Enforcement 78/12/31. 237pp Available
  at NTIS #12 50
- 7703240035 NUREG-0040 V1 N3
  "Licensee Contractor & Vendor Insp Status Rept," quarkerly
  rept
  + Office of Inspection & Enforcement 78/03/31. 227pp. Available
  at NTIS #7 50
- 7905240047 NUREO-0040 V1 N2
  "Licenses, Contractor & Vendor Insp Status Rept," quarterly rept
  # Office of Inspection & Enforcement. 77/12/31 284pp. Available at NTIS \$7.50
- 7903240050 Requests Executive Branch position re Borg-Harner Corp application for license to export globs & check valves to Beigiom OPLINGER: 0 0 Assistant Director for Export/Import & International Bafeguards 79/04/26 ip
- 7905240051 NUREG-0040-77/2
  "Licenses: Gontractor & Vendor Inap Status Rept." quarterly rapt.
  " Office of Inspection & Enforcement. 77/06/30, 149pp. Available at NTB 87 30
- 7905240053 NUREQ-0040-05
  "Licenses Gontractor & Vendor Insp Status Rept," quarterly rept
  # Office of Inspection & Enforcement. 77/03/31 173pp. Available at NTIS 612 50.
- 7905240058 NUREQ-0040-02
  "Licensee, Contractor & Vendor Insp Status Rept." quarterly rept.
  \* Office of Inspection & Enforcement. 76/06/30 158pp. Available at NTIS, \$6 75.
- 7905240059 SECY-79-120A
  Forwards backgound info ra proposed issuance of license to Exion Muclear Co. Inc. to import low enriched U. License should be granted.

  SHEA.J.R. Office of International Programs 79/04/02 2pp
- 7905240061 NUREQ-0040-01
  "Licensee, Contractor & Vendor Insp Status Rept," quarterly rept.
  4 Office of Inspection & Enforcement 76/03/31. 67pp. Available at NTIS 44.50.
- 7905240065 NUREO-0040-03
  \*Licensee, Contractor & Vendor Inep Status Rept. \* quarterly rept
  \* Office of Inspection & Enforcement, 76/09/30, 144pp. Available at NTIS #6 00.
- 7905240068 Confirms 790420 telcon informing that Ofc of General Counsel will serve Executive Secretary of DOS & HK Shaper:NRC Executive Legal Director; re Meetinghouse application to export SMM Meetinghouse has been served.

  ASHER:T R Asher: T. R. PC. 79/04/20. 1p.
- 7905240090 Agenda of 790405-07 228th ACRS meeting w/NRC & DOE in Washington DC to discuss various ACRS repts re generic items & selected reactors = ACRS Advisory Committee on Reactor Safeguards, 79/02/28 App.
- 7905240102 Notification of 790501 meeting w/Exxon Nuclear Co to discuss Exxon rod bow model.

  HANNON: J M. Operating Reactors Branch 3, 79/04/10, 2pp
- 7905240103 Comments on 790116 ACRS meeting in Washington, DC specs of dA code applications should be provided as fully & clearly as possible WurT Y. Wu,T.Y. 79/02/16. 2pp.

- 7905240107 Notification of contract execution, Mod 4 to "Antitrust Gonsultants." Contractor Charles River Associates
  LEBO: C D Technical Assistance Contracts Branch FIN 8-5141
  79/04/24. 1p
- ---7905240111 Mod 4, decreasing amount obligated by \$3,902.92 to "Antitrust 7905240281 BECY-79-258
  Consultants "
  DOUGHERTY, D. J Division of Contracts. FIN 8-5141 79/04/30 Notifies NRC of receipt of Transnuclear, Inc application for license to export highly enriched U to Busden BREA, J R Office of International Programs 79/04/12 19
- 7905240113 "Accountic Emission/Flaw Relationships for Inservice Hemitoring of Nuclear Pressure Vessels," Mar 1979 progress rept re flaw growth in AS33B pressure vessel steel. HWITON, P. HS., BCHHENK, E.B., KURTZ, R.J. Battelle Memorial Institute, Pacific Northwest Laboratory. FIN 8-2088. 79/04/17 11p.
- 7903240116 Application by Isotope Products Labs for license to export 10 mCi Cm-244, contained in ceramic disc, to Canada AHLAUER, K Isotope Products Laboratories W/O 6835 79/04/23
- 7905240118 Notification of contract execution "Computer Package for Bayesian Analysis of Attribute Data w/Arbitrary Prior Distributions," awarded to KS State Univ HACEV.H. Research Contracts Branch FIN 8-6705 NRC-04-79-182. 79/04/24. 1p
- ---F905240125 Contract "Computer Package for Bayesian Analysis of Attribute Data w/Arbitrary Prior Distributions:" awarded to K8 State Univ. HORTON, K V. Research Contracts Branch, PERRY, R H. Kansas State Univ. FIN 8-6705 NRG-04-79-182, 79/04/17 App.
- 7905240119 Forwards application for license to export movemble incore detector to Belgium KEENANR.P. Westinghouse Electric Corp ICS-8556 79/04/19. ip
- --7905240123 Application by Westinghouse for license to export one movable incore detector containing 0,0041 g U-308 to Belgium KEENAN, R P. Westinghouse Electric Corp. 79/04/20
- 7905240121 Requests expiration date of License IBNM-1610 be extended from 790630 to 800630. MATBON, V. Transnuclear, Inc. 79/04/10. 1p.
- 7903240130 Hummary of 790418 meeting w/BkW in Bethesda:MD renatural circulation in BkW reactors
  ROBB:D F Division of Project Management 79/04/24 14pp
- 7405240147 SECY-79-248 ruperular deut remarker hoteles application for titles NRC of receipt of British Embasey application for license to export source matl to United Kingdom.
  SHEA, J. R. Office of International Programs 79/04/06 to
- 7905240153 Heakly info rept for weak ending 790406. REPM T.A. Office of the Executive Director for Operations 79/04/11 26pp.
- 7905240155 Waskly info rapt for week anding 790330 REM.T.A. Office of the Executive Director for Operations, 79704705. 21pp
- 7900240164 Forwards RE Hilliams 790328 ltr re groundwater contamination at Cotter site: Shukle 790216 memo re tailings lapoundment & WA Hahler response.

  MCGRATH.E. J. McGrath. E. J. 79/04/11. ip.
- 7905240173 BEDY-79-249
  Informs of receipt of license application from GE to export low enriched U oxide powder to Japan. BH版A.J.R Office of International Programs. 79/04/06. ip
- 7705240202 Requests comments or Nissho-Iwai American Corp amend to export license application, changing address of intermediate consignes.

  ORBSICK, L. V. Office of the Executive Director for Operations, 79/04/30. to.
- 7905240208 Transcript of 790510-12 227th ACRS meeting in Washington, DC. Pp 1-968. CARRON.K.H., PLESSET.M.S., BENDER.H. ACRS - Advisory Committee on Reactor Safesulards 79/05/10. 968pp Reactor Safequards

- 7905240264 Notification of 790531 presentation by Harry Diamond Lab to Gualification Testing Evaluation Research Review Group to discuss fluidic development re nuclear plants FEIT,R Division of Reactor Safety Research 79/05/02 2pp
- 7905240315 Informs that Commissioners have reviewed License ISNM-78004 of Exxon Nuclear Co.Inc & accepted SECY-79-255 recommendation to amend license to increase quantity of lowentiched U to be imported from Nest Germany CHILK.S.J Office of the Becretary of the Commission 79/04/20
- 7905240316 Research Info Ltr 48 forwards NUREG-0382, "Tectonic Overview of Central Midcontinent "
  LEVINE, 8 Office of Nuclear Regulatory Research 79/04/03 4pp
- --7905240326 NUREQ-0382 "A Tectonic Overview of the Central Midcontinent"
  HINZE,N J , BRAILE,L W Purdue Univ KELLER,G R
  of 77/11/30 106pp Available at NTIS \$6 50 Teras, Univ
- 7905240320 "Fire Protection in Operating Nuclear Power Stations," Indian Point Unit 3 BER review KALL,R E Brookhaven National Laboratory FIN A-3107 79/09/21
- 7905240325 Application by Hoke, Inc. for license to export nuclear components to South Korea
  LINDNER, T.P. Hoke, Inc. 1132 79/04/16, 5pp
- 7905240337 Requests addi info to complete review of BVTR-1-0, "QA Program Description "
  HAASS.W P Guelity Assurance Branch BVTR-1-0. 79/04/30 14pp
- 7905240346 "Environ Statements Project.Cost/Benefit Analysis Group," progress rept for Feb 1979
  TEPEL.R C Dak Ridge National Laboratory FIN 8-0411 79/03/22
- 7905240353 \*BWR Blowdown/Emergency Core Cooling Program" monthly rept BURNETTE, O. W. General Electric Co , Nuclear Energy Products Div NRC-04-76-215. 79/04/05 App
- 7905240358 Notifies that Commission has reviewed & accepted
  Transnuclear, Inc. license to export 4, 23 kg U. enriched to
  93 3% U-235, to Canada (SECY-79-157).
  CHILK, S. J. Office of the Sacretary of the Commission 79/05/07
- 7905240359 Summary of 790425 meeting w/util in TN re visit to facility to acquire info for further development of fault trees by Sandia Labs.

  ANGELO, J Light Water Reactors Branch 1, 79/05/04 2pp.
- 7905240366 Informs that Commissioners have reviewed & accepted Transnuclear, Inc. license to import 5,500 kg U, enriched to 2 3% U-235, from France (BECY-79-286), CHILK, B J. Office of the Secretary of the Commission. 79/05/07
- 7903240371 SECY-79-28814

  Informs Commission of receipt of QE 790413 application for license to export low enriched U to Japan SHEA, J.R. Office of International Programs. 79/04/24. 1p
- 7905240377 Forwards Bokum Resources 790418 reply to NRC 790323 request for info re tabulation of date & assumptions reairborne emissions for Bokum U mine.
  TOPP, A. A. New Mexico, State of, 79/04/20 27pp.
- 7905240389 "LNR Thermal Hydraulic Davelopment Program," monthly highlights for Mar 1979. JONES:0 C Brookhaven National Laboratory FIN A-3045. 79/03/31
- 7905240398 Forwards NUREO-0511, Vols 1-2, \*Draft GEIS on U Hilling. \*
  Requests review & comment.
  SCARAND, R. A Uranium Recovery Licensing Branch. 79/04/18. ip

Charles Co.

···

---7905240406 NUREO-0511 VI
"Draft OEIS on U Milling," Vol 1, summary & text
"Draft oEIS on U Milling," Vol 1, summary & text
"Draft of Nuclear Material Safety & Bafequards 79/04/30. 36000.

### NONDOCKETED ITEMS

- --7905240413 NUREQ-0511 V2
  "Draft QEIS on U Hilling." Vol 2.Apps
  # Office of Nuclear Material Safety & Bafeguards 79/04/30 27086.
- 7905240401 Forwards state agencies' comments on NUREO-0499. "Preliminary Statement on General Policy for Rulemaking to Improve Nuclear Power Plant Licensing "YOUNGELOOD, J Artions State of 79/02/13 18pp
- 7903240404 "Physical Protection of Nuclear Facilities," progress rept for Feb 1979 CHAPMAN, L D Sandia Laboratories FIN A-1060 79/03/16 9pg
- 7905240409 Natification of contract execution. Hod 3 to "Investigation of Use of Cyclic. Torsional Screw Plate Test to Determine Insitu Liquefaction Potential of Gohesionless Soils."
  Contractor Univ of FL HAGEV, H Research Contracts Branch. FIN B-6254 NRC-04-77-171 79/04/24 ip
- --7905240420 Mod 3, adding funds for second year of 3-yr contract, to "Investigation of Use of Cyclic. Torsional Screw Plate Test to Determine Institu Liquefaction Potential of Cohestonless Soils."
  HORTON, K V Research Contracts Branch FIN B-6254.
  NRC-04-77-171. 79/04/24. 4pp
- 7905240410 Forwards state agencies' comments on NUREQ-0479, Suppl 1. "Preliminary Statement on General Policy for Rulemaking to Improve Nuclear Power Plant Licensing " VOLNOBLODD, J. Arizons, State et. 79/02/07 Spp
- 7905240415 "Thermal Hudraulic LMFBR Bafety Experiments: " monthly highlights for Mar 1979 JUNES: O C Brookhaven National Laboratory FIN A-3024 79/03/31.
- 7905240417 Offers no comments on NUREO-0499, Suppl i, "Preliminary Statement on General Policy for Rulemaking to Improve Nuclear Power Plant Licensing"
  WALLACE, A Towa, State of. 79/01/26. ip.
- 7905240424 Offers no comments on NUREG-0499, "Preliminary Statement on General Policy for Rulemaking to Improve Nuclear Plant Licensing"
  TEMPEST.L Utah, State of. 79/01/03 1p.
- 7905240427 "Short Begmented Cask Code Development & Validation." projet highlights for Mar 1979. AGRAHAL, A K. Brookhaven National Laboratory FIN A-3015-8 79/03/31 7pp.
- 7905240431 Executive Branch position re Caran Precision Engineering & Mfg Corp application for license to export 20,000 diamond incomel springs to India.License should be granted NGSENGL.V. State, Dept. of, Bureau of Docams & Internatl. Environ. & Scientific Affairs. 79/04/30. 2pp.
- 7905240433 Comments on proposed rule: outlines biographical statement emphasizing nuclear plant siting experience MCGORUM-H.B. Ohio, State of 79/03/02 2pp.
- 7905240435 Details discussion of extension of interim fuel cycle rule through 790515. Notes NRC request for asseting re "Statement of Consideration for U Fuel Cycle Rule" (RM 50-3), subsequently scheduled for 790502 CHILK.S.J. Office of the Secretary of the Commission. 79/05/01. io.
- 7905240438 Offers no comments on NUREO-0499, "Preliminary Statement on Oeneral Policy for Rulemaking to Improve Nuclear Power Plant Licensing "
  YOUNGBLOOD, J. Arizona, State of. 79/03/06, 2pp.
- 7903240439 Notification of contract execution, Mod S to "Institutional Radioactive Wastes," Contractor: Univ of MD, HADEY, H Research Contracts Branch. FIN 8-3939 NRC-04-76-344, 79/04/24, ip.
- ---7908240447 Hod 3. extending peroid of performance until 790630 to "Institutional Radioactive Wastes."
  MORTON:K.V Research Contracts Branch FIN 8-5454.
  NRC-04-76-344. 79/04/24. 2pp.
- 7903240446 Requests 781214 FR notice(Vol 430241,Pp 58379-81)be sent to parties listed.

  LEMIS.M. Affiliation Unknown. 79/02/16, 2pp.
- 7905240476 Summary of 790425 meeting w/G-E re natural circulation capabilities
  THADANIA C Reactor Systems Branch. 79/05/02 40cc.

- 7905240494 Forwards "Rept on Analysis Methods for RCS Natural Circulation." TAYLOR.J H Babcock & Hilcox Co 79/05/18 1p
- --7903240495 "Rept on Analysis Methods for RCS Natural Circulation \* Babcock & Wilcox Co 79/05/16 33pp
- 7905240496 Notice of availability of NUREQ-0511. "Draft GEIS on U Milling " SCARAND, R.A. Uranium Recovery Licensing Branch 79/04/16, 4pp
- 7903240529 "Advanced Reactor Safety Analysis Technical Assistance, Reactor Projects." monthly highlights for Mar 1979 BARI.R A Brookhaven National Leboratory. FIN A-3000 79/04/10 500.
- 7905240540 "Bafaguards Analysis for Byproduct Matls & Small Quantities of ShM," monthly progress rapt for Mar 1979 CHESTER,R.O., KIRKSCEV,K.A., RANDUPH,M.L. Dak Ridge National Laboratory FIN 8-6109 DRNL/HASRD-34, 79/04/09 5pp
- 7905240542 Forwards list of documents on file in support of Gulf Taylor U mill license application HACKIN,J, New Mexico, State of 79/04/25 App
- 7905240552 "First Quarter FY79 Progress Rept on Refill Effects Program" CROMLEY,C J , ROTHE,P H , CARY,C.N Creare, Inc NRC-04-75-162 CREARE TN-292, 79/04/30 26pp
- 7905240553 "Physical Protection of Nuclear Matl In Transit Project," monthly rept for Har 1979 CHAPMAN, L D Sandia Laboratories FIN A-1173 79/04/17 App.
- 7903240335 "Rept on Foreign Travel of T8 Kress to Karlsruhe, Germany & Caderache, Francs." KRESS, T. 8 Oak Ridge National Laboratory, FIN 8-0121 ORNL/FIR-586, 79/04/19 37pp
- 7705240567 Application by Westinghouse for license to export reactor internals, reactor control drive mechanisms, components for reactor fuel charging & discharging mechanisms to Switzerland KEENAN, R.P. Westinghouse Electric Corp. 108-8574 79/04/23 2pp
- 7905240576 "Environ Assessments of Fusi Cycle Facilities," monthly progress rept Fab 1979, IIITEL.H.E Oak Ridge National Laboratory, FIN 9-0279, URNL/ED/EIS-88 79/02/28, App.
- 7705240577 Application by Westinghouse to amend license to export aquipment, parts & components for nuclear reactors to Belgium & France
  HERBCH.M M. Westinghouse Electric Corp. ICS-8580, 79/04/24, pp.
- 7905240587 "Evaluation of Docket Files of Terminated Licenses." monthly progress rept for Mar 1979.
  HOLDMAY.C F., LANTZ.P., H., DICKSON.H. M., Oak Ridge National Laboratory FIN A-9085-7. GRNL/HASRD-39. 79703/31. 6pp.
- 7905240669 Notification of contract execution. Hod 4 to "Radionuclide Retention & Land Form Mod in Surface Pathways." Contractor. Univ of State of NY HAGEY. H. Research Contracts Branch FIN 8-6008 NRG-04-77-169 79/04/25.
- --7905240669 Mod 4, extending period of performance to 790331 at no cost, to "Radionuclida Ratention & Land Form Mod in Burface Pathway."
  MORTON, K. V. Research Contracts Branch FIN 8-6008 79/04/25, 2pp.
- 7905240776 Requests denial of UCS 771104 patition for emergency k remedial action & UCS 780503 patition for reconsideration of NRC 780413 memo & order.
  EDMARDS.D. Vantes Atomic Electric Co. 79/05/16. 10pp.
- 7905240787 Notification of contract execution, Mod 3 to "Antitrust Hearings." Contractor; Charles River Associates.
  LEBC. C D. Technical Assistance Contracts Branch. AT(49-24)-0085 79704/24. 1p.
- --7905240808 Mod 3, decreasing amount obligated for "Antitrust Hearings"

  DAUGHERTY,D,J.

  Division of Contracts AT(49-24)-0085.
  79/06/30. in

#### **NONDOCKETED ITEMS**

- 7905240820 Accepts recommendation for Dept of Army to export 250 kg depleted U to United Kingdom Requests notification of issuence & delivery of license to Dept of Army by 790507 CHILK, S. J. Office of the Secretary of the Commission. 79/05/01 is
- 7903240860 Requests Executive Branch position re TX Nuclear Div application for license to export SNM to Peru. OPLINGER, Q O Assistant Director for Export/Import & International Bafaguards 77/04/03 1p
- 7905240863 Confirms 790425 teleon approving agreement between NRC & PO&E for extension of time to file motion to compel discovery to NRC first set of supplemental interrogatories EVANB, D J. Anti-Trust Division 79/04/25 ip.
- 7905240875 Executive Branch position re Byron Jackson Pump Div application for license to export two rotating elements & two mechanical seal cartridges & accessories to Japan ticense should be granted. MOSENZO,L V State, Dept of 79/05/02 2pp
- 7905240883 Executive Branch position re Spax Industries, Inc application for license to export 0 09825 g U-235, contained in 5 g U for use in mass spectrographic analysis to Japan License should be granted, Japanese 1tr of assurance encl NOSENZO, L V State, Dept of 79/05/07. 3pp
- 7905240886 NUREO/CR-0785
  "COMMIX-1: Three-Dimensionnal Transiant Singls-Phase
  Component Computer Program for Thermal Hydraulic Analysis "
  H/arrata sheet correcting NUREO/CR-0415 to NUREO/CR-0785
  SHA, H T., DOMANUS; H M; BCHKITT, R C Argenne National Laboratory,
  FIN A-2045 78/09/30 120pp
- 7905240889 Executive Branch position re QE application for license to export 331 kg U-234, contained in 11,965 kg U enriched to mex of 3 1% to Japan, License should be granted. Japanese 1tr of assurance encl NOSENZO, L V State, Dept of 79/05/07. 3pp
- 7905240897 Executive Branch position re GE application for license to syport, over 10-ur period, specially designed or prepared reactor parts & components to Sweden, License should be granted, NOSENZO, L V State, Dept of 79/05/07. 2pp
- 7905240925 NUREO/CR-0486
  "Burvey of Postiradiation Heat Treatment as Means to
  Hitigate Radiation Embrittlement of Reactor Vessel Bleels."
  HAWTHORNE, J. R. Navy, Dept of, Naval Research Laboratory
  NRC-RE8-79-103, NRL REFT 8287, 79/02/14 34pp. Available at NTIS.
- 7703240977 Advises that add! mat! to CENPD-169-P re method for determining overall uncertainty in DNB operating margin is acceptable. Forwards revised evaluation. BAER.R.L. Light Water Reactors Branch 2, 79/04/05. 7pp.
- 7905240979 Notifies of NRC position change re application of ANSI 45, 2, 13, referenced in Reg Quide 1, 123, Discusses current position & requests acceptance or alternative proposal within 30 days.

  HAABS. N. P. Quality Assurance Branch. 79/05/02. 1p.
- 7903240990 Requests add1 info to complete review of NEDE-21821 & NEDE-21821-01, "BWR Feedwater Nozzle/Sparger," final rept & Bupp1 i,respectively, EIREMHUT.D 0. Division of Operating Reactors. 79/05/08 | 2pp.
- 7903240991 Forwards license application summary & safety review submitted by Cotter Corp to CO Dept of Health.W/o encl. HCGRATH/E.J. McGrath/ E. J. 79/04/11. 1p.
- 7905240997 Lists licensees who received IE Bulletin 79-058. "Nuclear Incident at THI-Suppl " Bulletin encl. PAPPAS.H. Region 3. Ghicago, Office of the Director. 79/04/23 2pp.
- 7905250033 BECY-79-183A
  Discusses NRC review of proposed issuance of export license to Mitsubishi Intl Corp.
  SHEA, J. R. Défice of International Programs. 79/04/02. 4pp
- ---7903280037 Application by Mitsubishi Intl Corp for license to export 348 kg U-235, contained in 16,341 kg U, to Japan. TSUJI.K. Mitsubishi International Corp. (subs. of Mitsubishi Corp.), XSNM-1386, 78/09/29, 3pp.

- --7903250041 Forwards application for license to export enriched U hexafluoride to Japan to be used for fabrication of fuel assemblies HATANABE.N Mitsubishi International Corp (subs of Mitsubishi Corp ). HBA-5478-08 78/09/29 3pp
- --7905250045 Forwards 780914 end use statement, WATANABE,N Mitsubishi International Corp (subs of Mitsubishi Corp.) XEMM-1396 78/10/19, 2pp.
- --7905250054 Executive Branch position re Mitsubishi Intl Corpapplication for license to export 545 kg U-235 to Japan Japanese ltr of assurance encl NOSENZO,L V State, Dept of Bureau of Oceans & Internati Environ & Scientific Affairs XSNM-1386 79/03/05 4pp.
- ---7905250059 License for Mitsubishi Intl Corp to export 545 kg U-235. contained in 16.341 kg U,to Japan OPLINGER, 0 9 Assistant Director for Export/Import & International Safeguards 79/04/02 3pp
- 7905250038 Responds to 790121 ltr re 10CFR20 304 & Watts Retreat Farm Farm is licensed by State of NG.not by NRC.Proposal to amend 10CFR20 304.presently under consideration, would allow burial of radioactive matl w/NRC approval.

  KERR.O.W Office of State Programs 79/04/17. 1p
- 7905250050 Requests additinfo & clarifications to complete evaluation of generic licensing topical rept EDR-1. Requests schedule for responses so rept review schedule can be drawn up. BAER.R L. Light Water Reactors Branch 2. 79/04/26 Spp.
- 7905250063 Advises that Commissioners have approved proposed license by Transnuclear Inc to export 19.8 kg U.enriched to 93 3% U-235, to Netherlands Requests description of security measures CHILK:8 J. Office of the Secretary of the Commission. 79/04/11.
- 7703250049 Comments on proposed rule 10CFR19-20 forwards talk presented at AIF 770402 conference re regulation of radiation. Proposal would be very costly to implement. LEE, B. Commonwealth Edison Co. 79704706. 24pp.
- 7903250086 Summary of ACRE Subcommittee on Procedures & Administration 790207 meeting in Washington, DC re-work assignments of ACRE fallows & possible fellows appointments. Encl withheld (ref 10CFR2, 770)

  \*\*ACRE Advisory Committee on Reactor Safeguards. 79/02/07 5pp
- 7905250102 Notification of 790501 meeting w/C-E in Bathesda, MD to discuss plant transient responses & Michelson rept. THADANI, A G Reactor Systems Branch 79/04/26. 1p
- 7905230106 Summarizes ACRS ECCS Subcommittee 790319-20 meeting in Los Angeles,CA re std problem program. ZUDANS,I. Franklin Institute Research Laboratory. 79/03/30 2pp.
- 7905250111 Evaluates Bandia 790226 mid-year review re upper heat injection RELAP model development statistical LOGA study, two-phase jets steam explosion phenomena & molten core interactions.
  CATTON I. California: Univ. of, Los Angeles. 79/03/22. 4pp
- 7905250113 Notification of 790502 meeting w/OE in Bethesda.MD to discuss two loop test apparatus & model devalopment. HODGES, H. Analysis Branch. 79/04/26. 1p.
- 7905250114 Notification of contract execution Mod S to "Review of Proposed Pile Foundations for Bailly Nuclear Generating Station." Contractor: MY Davisson. PERLMAN. J. Purchasing Section. NRC-03-78-166. NRC-03-78-166 79/05/07. 1p
- --7905230120 Hod 3, extending period of performance to 790424, to "Review of Proposed File Foundations for Bailly Nuclear Generating Station."
  HARCETT, D. J. Division of Contracts. NRC-03-78-166.
  NRC-03-78-166, 79/04/11, 1p.
- 7905250115 Ltr of assurance confirming govt authorization for licensee to receive & possess nuclear meth identified in application.
  Transfer will be subj to all conditions of 660808 agreement for cooperation between Switzerland & US.
  MULLER, R E Switzerland. 651.513 SKM-MR/. 79/03/26. 1p.

- 790525011B Reviews LERs Better operator training is needed Discusses several incidents indicating operator problems & requests marrative follows repts covering noted LERs CATION, I. California, Univ. of, Los Angeles 79/04/17 Spp.
- 7905250122 Summary of 790425 meeting w/Black & Vestch Consulting Engineers in Manass City.MD re topical rept BVTR-1-0, "QA Program Description" SPRAUL, J Guality Assurance Branch 79/04/27 2pp
- 7903230124 Requests comments on NUREO-0660 re operating experience of emergency onsite diesel generators at LWRs.
  VASBALLO,D B Assistant Director for Light Water Reactors
  79/04/18 3pp.
- 7903250133 Comments on ACRS ECCS Subcommittee 790319-20 meeting re-code work on transient two-phase flow.LOFT L2-2 test.BWR core spray test program.CREARE downcomer program & std problem program ZALOUDEK,F.R. Battelle Memorial Institute, Pacific Northwest Laboratory 79/03/28 2pp
- 7905250139 Comments on Mark I owners group 790213 meeting re vent clearing & pool swall phase of suppression pool load definition study. CATTON, I California: Univ. of, Los Angeles. 79/03/08 2pp.
- 7703230160 "Rept on Foreign Travel of BG Eads, Manager for Advanced Instrumentation for Reflood Studies Program " EADS, B. & Oak Ridge National Laboratory ORNL/FTR-381 79/04/20
- 7905250166 Informs that itr of assurance has been sent re Eberline Instrument Corp license to export 0.22 micrograms Pu-239 to Austria 79/04/13 ip
- 7905250167 Ack receipt of invitation to speak to Univ of VA Student Legal Forware luctant to give firm commitment at this time HENDRIE; J K. Commission 79/04/26 1p.
- ---7705250169 Extends invitation to speak at Student Legal Forum at Univ of VA School of Law HENDRIE, J M Virginia. Univ of 79/04/12. 1p
- 7905250189 Summary of 79030B-10 227th ACRS meeting in Hashington DC rs review of request for OL for Zimmer Nuclear Power Station Unit 1. alternatives for resolution of ATMS & review of "Status of Generic Items Relating to LMRs."

  CARBON.M. H ACRS Advisory Committee on Reactor Safeguards.
  79/03/22 3pp.
- 7905250195 Ack 790321 itr requesting joint hearing re licensee application concurs w/suggestion. Soft organizations have already developed processures to be proposed to any joint hearings.
  HENDRIE J M Commission 79/04/24 ip.
- --7905250209 Proposes joint hearing for consideration of issues over which NRC & NY State Public Svc Commission have concurrent jurisdiction.
  ZIELINSKI.C A New York, State of, 79/03/21, 2pp.
- 7905250207 Notifies that NRC has not completed licensing action on application to export low enriched U fuel to Japan, Favorable Executive Branch view received on 790307. Final matters under review SHEA.J.R. Office of International Programs. 79/05/07. 1p.
- 7905250214 "Crack Arrest Technology" monthly progress rept for Har 1979. ROSEMFIELD, A.R. Battelle Memorial Institute, Columbus Laboratories NRC-04-74-293-04. 79/04/11 3pg.
- 7905250224 Transcript corrections of 790119 hearing LINKER, H. Natural Resources Defense Council. 79/02/27. ip
- 7905250231 Notification of 790426 meeting w/EPRI & util re IE Bulletin 79-01.

  JORDAN, E. L. Division of Reactor Operations Inspections. 79/04/19, 208.
- 7905250252 License for Edlow Int) Co to import 115 kg U as irradiated MTR fuel slaments. OPLINGER.Q. O Assistant Director for Export/Import & International Bafeguards 79/05/09. 2pp
- 7903230235 License for Consolidated Controls Corp to export twenty 425 LDI resistance temp detectors to Italy DPLINGER.O.Q. Assistant Director for Export/Import & International Bafeguards. 79/03/09. 1pp

- 7905250257 License for Ediaw Intl Co to export 2,190 kg U-235,contained in 61:750 kg U hexafluoride,to Bweden OPLINGER. 9 9 Assistant Director for Export/Import & International Safeguards 79/05/09 2pp
- 7905250264 BECY-79-268
  Forwards application from Aerojet Ordnance Co to export source wastl to Canada
  BHEAJ R. Office of International Programs 79/04/16 1p
- --7903250270 Application for amend & renswal of license to export 100.000 kg U to Canada BCHWARTZ.H. Asrojet Ordnance Co 79/04/06. 2pp.
- 7903230265 Application by Reuter-Stokes, Inc. for license to export Reuter-Stokes Model RS-C1-1210-135 compensated ion chamber to France
  EKARUPA, J. D. Reuter-Stokes, Inc. U-8129 79/04/27 ip
- 7905250272 License for Hoke, Inc to export needle valves, bellows-sealed instrument isolating valves, bellows-sealed manually & pneumatically operated valves, bleed & drain valves & three valve manifolds to South Korsa
  OPLINGER, G O Assistant Director for Export/Import & International Bafeguards 79/03/09 ip
- 7905250276 License for Hoke, Inc to export bellows-realed instrument isolating valves to Korea DPLINGER, O G. Assistant Director for Export/Import & International Bafeguards 79/05/09 Ip.
- 7905250282 License for Hoke, Inc to export bellows sealed manually & pneumatically operated valves, bleed & drain valves & three valve manifolds to Korea OPLINGER, O G Assistant Director for Export/Import & International Safeguards 79/05/09 ip.
- 7905250287 Amend 2 to License XU-8342, increasing quantity of matl to 135,059 kg U, contained in 136,000 kg depleted U, for export to Canada OPLINGER, O O, Assistant Director for Export/Import & International Safesuards 79/05/09, ip
- 7905250291 Amend 1 to License XBNM-0937.deleting Transnuclear as other party to export & substituting Niesho-Iawai Go.Ltd.for transport purposes only SHEA.J.R. Assistant Birector for Export/Import & International Bafeguards. 79/05/09. 19
- 7705230295 License for Hoke, Inc to export bellows-sealed instrument isolating valves & three valve manifolds to Bouth Kores.

  OPLINGER, O. Q. Assistant Director for Export/Import & International Bafeguards 79/03/09 ip.
- 7903250299 Notification of contract execution: "Reactor Vessel Irradiation Damage," awarded to Naval Research Lab. OLAGDLA, A.F Technical Assistance Contracts Branch FIN B-6809. 20-19-04-02-2. 79/04/03 ip.
- ---7908250309 Updates contract for "Reactor Vessel Irradiation Damage."
  Extends period of performance & increases cost estimate
  DOUGHERTY, D. J. Technical Assistance Contracts Branch. FIN
  B-6809. NRC-03-79-148. 79/04/02 7pp.
- 7905230300 License for Hoke, Inc to export bellows-sealed instrument isolating valves & three valve manifolds to Bouth Korea. OPLINGER, G O Assistant Director for Export/Import & International Safeguards. 79703709. ip.
- 7905250306 Application by Isotope Products Labs for license to export 0.01 micrograms 0f-252 neutron source welded in stainless steel capsule to Australia, AMLANER, K. Isotope Products Laboratories, 79/05/01. 1p.
- 7905250312 Notifies of shipment of 1 g Th-232,0.6 g U-238 & 0 05 g Np-237 to Russia between Jun & Oct 1979. Requests procedural instructions.
  CHETIRKIN-P. V National Aeronautics & Space Admin. LB-236-5.
  79/04/13. 1o.
- 7905280321 Comments on H R. 544, H. R. 2 & H. R. 1059 per, request. Forwards comments on 8 2 which is similar to H R. 2. Objects to duplicative budget review but supports objectives of bills to eliminate overlapping federal programs.

  HENDRIE: J M. Commission. 79/03/16. 2pp.
- --7905280326 Responds to request for review of 8.2 bill passed by Sanate on 791011. Supports legislation to eliminate waste & duplication in federal gove, Guestions effectiveness of citizens 'commission, due to statutory limitations.

  STOIBER, C. Office of the General Counsel. 78/12/19 2pp.

- -- 1903230329 Forwards H R 544 to require authorization of new budget authority for govt programs at least every five years & to establish procedure for zero-based budgeting. Requests review Comments House of Rep , Government Operations 79/01/29. 39pp
- --7905250336 Forwards H R 1059 to require authorization of new budget authority & review for govt programs at least every five years Requests review & comments.

  BROCKS.J House of Rep , Government Operations. 79/02/07. 52pp House of Rep , Government Operations. 79/02/07. 5299
- --7903250337 Forwards H R.2 requiring new budget authority & program review at least every ten years BROOK8.J House of Rep., Government Operations 79/01/24 66pp.
- 7705250322 Research Info Ltr 52 earthquake intensity scale. USOS should promulgate new intensity scale based on analysis described in ltr.

  DENTON, H R Office of Nuclear Reactor Regulation MINOGUE, R B Office of Standards Development. 79/04/23 App.
- 7905250323 Authorizes issuance of license to Ediow Intl Co for export of 61,750 kg U.enriched to 3.55% U-235, to Bweden MOGRE, R W Office of International Programs, 79/05/09 is
- 7905250327 Application by Unipax Intl for license to export 900 kg depleted U to Korea
  YUN.J.W Unipax International 79/03/29 App.
- 7905250331 Advises that Commissioners have approved proposed license by Edlow Entl Co to import enriched U from Japan (SECY-79-271). Requests notification of issuance & delivery of license to Edlow by 790511
  CHILK, B J Diffice of the Secretary of the Commission. 79/05/08
- 7905250333 Application by MELCO USA: Inc for license to export radiation detector to Japan NAKATANI:T. Melco U S.A.:Inc. 79/03/23. 4pp.
- 7905250334 Summary of NRC 790503 discussion in Washington, DC re 8-3 rulemaking. CHILK.B.J Office of the Secretary of the Commission. 79/05/04
- 7905250338 Summary of 790425-26 meeting w/ANL in Argonne. IL re preparation of final OEIS on handling & storage of spent LHR fuel. ROBERTS, J. P. Fuel Reprocess & Recycle Branch 79/03/02 1p.
- 7905230345 Requests Executive Branch position re Westinghouse application for license to export miscellaneous parts & components to Buitterland OPLINGER, 0, 0, Assistant Director for Export/Import & International Safeguards, 79/05/09, ip.
- 7905230376 Comments on proposed rule 10CFR19-20: rule does not allow flaxibility provided by 5(N=18) dose averaging formula SDRENSON, B. H. Radiation Services, Inc. 79/03/14. 1p.
- 7903230379 Informs that conference w/counsel will be held on 790515-17 re-brief & responses filed by parties & objections to util's faurth set of interrogatories & motions for protective order. HILLER: M.E. Atomic Safety and Licensing Board Panel, 79/04/17, ip
- 7905230442 Executive Branch position re Nissho-Iwai American Corpaphication for license to export 5 448 kg U-235 to Japan License should be granted.
  NDBENZOL V. State. Dept. of. Bureau of Oceans & Internati. Environ. & Bc
- 7905250444 Forwards comments received as of 790330 re NUREQ-0396, "Planning Sasis for Development of State & Local Govt Radiological Emergency Response Plans in Support of Light Hater Nuclear Power Plants."

  COLLING, H. E. Assistant Director for Emergency Preparedness, 79204/05.
- ---7905250447 Notice of availability of NUREQ-0396, rept of NRC/EPA Task Force on Emergency Planning. RYAN.R.O Office of State Programs. 78/12/15 ip
- --7903230450 PCBE-79137
  Comments on NUREO-0396; emergency tone should be planned for small area around reactor. Once tested & perfected rone could be expanded to appropriate size.
  CLEARY, P. Citizens for a Satter Environment. 79/03/29. 9pp.

- ~~7903250435 Comments on NUREQ-0396 NRC/EPA task force is not representative of public.Protective action & guides rely on subjective evaluations Reliance on Reseases rest calculations are questionable Rept should be recalled. LEHIS.H I Affiliation Unknown 79/01/31. ip.
- --7905250458 Comments on NUREQ-0396 Lack of NRC sanctions against inadequate plans shows fundamental flaw Reliance on HABH-1400 is misplaced RDISMAN,A Z Natural Resources Defense Council 79/01/19. 3pp.
- --7905250460 Comments on NUREQ-0396.objects to absence of regulatory impact assessment & questions reliability of info used to support planning baris elements Placing parameters on emergency planning ione is premature.

  REED: C Commonwealth Edison Co 79/03/26. 5pp
- --7903250462 Comments on NUREQ-0396 emergency planning tones unnecessary & inappropriate Rept is overly conservative & unrealistic Implementation of rept items will be very costly & lead to possible public misinformation.

  MMITMER, C.F. Georgia Power Co. 79/03/28. 2pp
- --7905250466 Comments on NUREQ-0376.50-wile radius emergency plan is absurd. Rept not reponsive to state program directors' needs Utils may be required to finance state emergency plans Cails for realistic planning PARKER, M. D. Duke Power Co. 79/03/27. 2pp.
- ---7905280467 Comments on MUREG-0396 planning for Class 9 actions is not justified questions validity of info supporting rept Establishment of emergency planning zones will be very costly.
  RENBERGER, D. L. Washington Public Power Supply System. 79/03/28
- --7905250469 Comments on NUREQ-0396, planning for Class 9 accident is illogical, rept lacks perspective on public risks & implementation costs & feasibility are misrepresented Requests value impact assessment & withdrawal of rept. HARD, J E Atomic Industrial Forum 79/03/30, 6pp
- --7905250473 Comments on NUREO-0396 rept is premeture & based on incomplete info leaving rept could complicate licensing process.Planning for Class 9 events should be reconsidered, VANDEMBUROH.D. Yankse Atomic Electric Co 79703/28. 9pp
- ---7905250476 Comments on NUREQ-0396 potential exists for confusion relicensess' emergency planning obligations Requests additional clarification prior to NRC adoption of rept. REIS.H F. Lowenstein Newman, Reis, Axelrad & Toll 79/03/30 7pp.
- ---7705280478 Comments on NUREO-0376, adoption of rept could be very costly. Requests NRC provide adequate support in planning & implementation. Requests withdrawal & reconsideration of rept BULLIVAN.T.J. Consumers Power Co. 79/03/23. 2pp.
- ---7905250491 Comments on NUREO--0394. present plans are adequate. Guestions validity of emergency planning zones implementation would be very costly.

  ALLEN, O. J. Citrus County, FL 79/03/19. 4pp.
- --7905230493 Comments on NUREO-0396: suggests rept be advisory only Expanded emergency planning tones are excessive & burdensoms. Five & twenty-mile radii zones are more
- --7905250494 Comments on NURE9-0396; rept could be helpful if used early in planning process. Use of rept would lead to interjurisdictional planning & substantial costs. HEUBNER. A. T Connecticut, State of 79/03/09. ip.
- ---7905250496 Comments on NUREO-0396: current emergency plans are adequate.

  Questions standardized approach. Supports rept validity.

  KOSS, R. R. Kewaunee County, WI. 79/03/06, 2pp.
- --7903250497 Comments on NUREG-0396, planning for Class 9 event is unreasonable, Questions validity of dosimetry data. KOHLER,R. Florida, State of. 79/03/23. 3pp.

- ---7905230498 Forwards comments on NUREQ-0394 planning based on Class 9 accident is not realistic Emergency plan criteria should be consistent with licensing criteria Ten & fifty-mile radii should be eliminated LEWISL Affiliation Unknown. 79/03/22 3pp
- --7905280499 Civil Defense Ofc has no comments on NURE9-0396 BOYD, M. K. Richland County, SC 79/02/98 1p
- --7905250500 Comments on NUREO-0395 few county govts have expertise to prepare emergency plans More guidance needs KAUNEY,B.R. Aiken County, BC 79/01/15 1p
- --7905250502 Comments on NUREO-0396 local govts do not have expertise to understand or implement rept Rept provides no objective means to measure emergency RIOOR.R R Contra Costa County, CA 79/03/28 3pp
- --7905250503 Ack receipt of NUREO-0376 Requests add1 info for preparing comments Requests info on MASH-1400 reevaluation & its impact on NUREO-0396 consideration schedule RADACK/E D. Affiliation Unknown 77/01/29 to
- ---7905250504 Comments on NUREQ-0396 comprehensive emergency response plan aiready exists for CT Rept does not address real health & tafety useds of public Buggest future inclusion of medical meteorological & transportation expertise in repts MANCUSO:F Connecticut, State of, 79/01/08 2pp
- ---7905230505 Comments on NUREQ--0396.cost effectiveness is not adequately treated in rept H/article from 790320 Charlottesville Daily Progress re Louise County investigation of fallout facilities near North Anna plant HOUD,N C Virginia. Univ of 79/03/22. 2pp
- --7905250506 Comments on NUREG-0396 questions reliance of rept on MASH-1400 Rept should provide detailed description of worst case LOCA: avoid evaluation of event probability & suggest public evaluation drills
  IBSER,H H California State Univ , Sacramento, 79/03/26 2pp
- --7903280507 Forwards summary of 790214 public hearing No one present supported extension of present 3-25 mile emergency planning zones to 10-50 mile radii proposed in MUREO-0396 County Commissioners oppose rome extension.

  ORANT, J. Citrus County: FL. 79/03/19. 1p
- --7905250508 Comments on NUREQ-0396: agrees w/views of 60 Bureau of Radiological & Environ Control County is outside plume exposure pathway for accidents discussed no addit cost for emergency planning KINO,R B Anderson County, 80. 79/01/12. ip.
- ---7903250510 Comments on NUREO-0396.rept is vague re level of planning required for amergency planning zones More consideration should be given to Class 1-8 accidents MODRE.T C South Carolina. State of. 79/01/15 ip
- --7903250511 Comments on NUREO-0396: establishment of emergency planning zones of std distances from all facilities is inappropriate Suggests zones be established as required for each facility. W/Z80811 itr commenting on draft NUREO-0396.
  HENDERSON.Q.K Pennsylvania: State of 79/03/16 5pp
- --7705250512 Comments on NUREO-0396: guidance useful/but expects considerable costs in implementing 50-mile emergency planning zones Plant siting & emergency planning should be inseparable.

  EPPERSON.L M Arkanses, State of 79/01/12. 3pp.
- ---7905250513 Comments on proposed amends to 10CFR50.App E:proposal is unnecessary. Guestions rationals for imposing interim regulations, Amends would be very costly, Requests defeat of proposal COUNSIL, N Q, Northeast Utilities 78/10/10 2pp.
- --7905250514 Comments on NUREO-0376; most local civil defense directors do not have expertise to understand rept.

  BLACK.B. Oconee County, BC. 79/01/15. 1p.
- --7905250518 States no comments should be made on MUREO-0396 until after region & state civil defense preparedness agencies conduct briefings & conferences w/local representatives. PRICE:N H., Florence County, SC 79/01/15. ip.

A STATE OF STATE OF

- --- 7905250519 Comments on NUREO--0396 criticizes rept methodology for calculations of accident probabilities Offers alternative Funding not available for implementation of rept PARROTIM M. Oregon. State of 79/02/08 2pp
- ---7905250521 Comments on NUREO-0396 expanded emergency planning rones not necessary & costly to implement Buggests inclusion of guidence for local adjustments to rone radii
  BHANAMAN, W.R. Humboldt County, CA 79/01/16 2pp
- ---7903250523 Comments on NUREO-0396 rept implementation would be very costly Questions feasibility & legal basis Rept lacks historical perspective & technical basis in using Class 9 accident as planning basis.

  COUNSIL, H O Northeast Utilities 78/11/13 4pp
- --7905250525 Comments on NVREQ-0396 unilateral adoption of rept methodology by NRC will probably not have desired results Rept is good for bldg consensus in absence of significant mods to HASH-1400. JASKE,R T Office of State Programs 78/09/25 4pp
- --7905250482 Comments on NUREO-0396 revision is cosmetic in nature & previous comments still apply. Forwards 781129 comments on draft of same rept KABPERSKI, D. C. Olibert Associates, Inc. 79/02/23 ip
- --7905250485 Forwards comments on Draft 2 of NUREG-0396 planning for Class 9 accidents is unnecessary Disputes NRC use of MASH-1400 Questions appropriateness of dose calculation methodology Rept will increase public confusion KASPERSKI.D C. Gilbert Associates, Inc. 78/11/29. 4pp.
- --7903250501 Forwards requested infordemographic statistics on reactor sites repts on adequacy of composite population distribution & meteorlogical transport used in reactor safety study & maps showing nuclear plant locations COLLINS, H.E. Assistant Director for Emergency Preparadness 79/02/01 ip
- ---7905250492 Requests demographic info for use in preparing comments on NUREO-0396.
  .NOOD, H C. Virginia, Univ of 79/01/24 1p.
- --7905250509 Comments on NUREO-0396. requests info re relationship of rept to existing safety analyses & extensiveness of emergency plan Buggests rept be used guide not regulation HMPER. H J. Bechtel Power Corp (subs. of Bechtel Corp.). 79/01/16 ip
- --7905250516 Ack receipt of 790116 ltr re NUREG-0396.Rept not intended as regulation No relationship exists to past analysis performed on plant siting, Forwards NUREG-0396 & NUREG-75/11.W/o enci COLLING, H E Assistant Director for Emergency Preparadness 79/01/16 p.
- --7905250517 Ack receipt of 790223 ltr commenting on NUREO-0396 Clarifies concept of 50-mile emergency planning zone. Rept implementation should not present substantial costs. Objects to suggestion that planning be based on historical events. COLLINS: HE Assistant Director for Emergency Preparedness 79/03/26 2pp.
- --7705250520 Comments on NUREO-0376:would be very costly to implement NRC should bear the cost. Bt Lucie County Commission voted to object to 50-mile concept at 770220 meeting RDDI.P.J. Bt Lucie County. FL. 79/02/23. 2pp.
- 7705250448 No comments on NUREO-0499. Suppl 1: "Preliminary Statement on General Policy for Rulamaking to Improve Nuclear Power Plant Licensing."

  WALLAGE. A T. Town State of. 79/01/19. ip.
- 7903230431 No comments on NUREO-0499. Suppl 1, "Preliminary Statement on General Policy for Rulemaking to Improve Nuclear Power Plant Licensing."
  HAYMARD.N. Delaware, State of, 79/02/06, ip.
- 7905250453 Requests info re NUREO-0499, "Preliminary Statement on Ogneral Policy for Rulemaking to Improve Nuclear Power Plant Licensing." JOLHSRUD, J. H. Pennsylvania, State of. 79/02/01. 1p
- 7903250454 Comments on proposed rule 100FR19-20 questions justification of expense of changing regulation which is currently acceptable Buggests continuation of present regulations to protect populate from radiation.

  CASH. A. Yuba Heat Transfer Corp. 79/03/27. 2pp.

- 7905250457 Comments on NUREO-0499, "Preliminary Statement on General Policy for Rulemaking to Improve Nuclear Power Plant Licensing:" new licensing for nuclear plants is futile since utils are not requesting new plants LE
- 7903250463 No comments on proposed rule "Preliminary Statement on General Policy for Rulemaking to Improve Nuclear Power Plant Licensing "
  HILL.R.M. Nevada. State of 79/02/06 ip
- 7905250468 Comments on proposed rule "Preliminary Statement on Ceneral Policy for Rulemaking to Improve Nuclear Power Plant Licensing " proposed project does not adversely affect state plans DEOAEYA.P V. Kansas: State of 79/02/12 7pp.
- 7905250470 Comments on NUREO-0449, Suppl 1, re nuclear plant licensing temprovements as simple as possible. YOUNDELOOD. J Arizona, State of, 79/02/06 18pp.
- 7903230483 Rmg Quide 3.11 i. "Operational Insp & Surveillance of Embantment Retention Sys for U Mill Tailings."

   Office of Standards Development 79/04/30 Spp
- 7905230407 Comments on proposed Reg Quide 7 9. serious technical error. Fuel rods cannot contain anything within cladding Quide should not be distributed, LEMEB. H L. Affiliation Unknown. 79/04/13 ip.
- 7905250522 Forwards comments on NUREO-0376 mergancy planning should be done by licensee prior to GL Planning zones are adequate Implementation of rapt would be very costly. CLACK, B. J. Georgia, State of. 79/02/21. Spp.
- 7903230331 Comments on proposed Reg Guide 1 2B.Revision 2 recommends clarification of term "safety-related." & believes Section C 1 is too restrictive.

  VECLETIC.J B. Bechtel Power Corp (subs of Bechtel Corp ).

  JBV-79-70. 79/03/30. 2pp
- 7903230539 Forwards NRC determination statement re-public withholding of transcript of 790420 discussion of personnel matter CISILK-B J. Office of the Secretary of the Commission 79/05/08
- P905230340 Forwards 770316 ltr & end use statement from Radium-Chemie Ltd.as addl info to export license application. HOR.H. H. M. Radium Chemical Co., Inc. 79/04/18, 3pp
- 7905240008 Transcript of 790502 Affirmation Session 79-10 in Washington, DC, Pp 1-3. MENDER, J M. Q ILINSKY, V. KENNEDY, R. T. Commission. 79/05/02 4pp.
- 7905290015 Responds to 790409 itr to UM Hendris requesting info reoperator license requirements Forwards Reg Quide 1.134, "Medical Evaluation of Nuclear Power Plant Personnel Requiring OL " BOYD, R B Assistant Director for Light Water Reactors. 79/04/19. 18.
- ---7905290018 Reg Guide 1.134, Revision 1: "Medical Evaluation of Nuclear Power Plant Personnel Requiring Operator Litenses." # Office of Standards Development. 79/03/31 2pp
- --7903290024 Requests info on nuclear power plant personnel regulations on alcohol before & during duty hours.

  4 United Christian Action, Inc. 79/04/09. 1p.
- 7403240038 Comments on proposed rule 10CFR19 & 20.approves elimination of accumulated dose averaging formula.

  AAROE.W.H. West Virginia, State of, 79/04/06, ip.
- 7405290043 Comments on proposed rule 10CFR19 & 20: failure of individual to disclose exposure rates could engender fine.
  MCCDRMACK. J B. Affiliation Unknown. 79/04/04. 1p.
- 7903290047 Comments on proposed rule 100FR19 & 20; favors making 3 rems/yr dose limit for whole body exposure. Limit for calender quarter should be abolished. Regulations should reflect most conservative annual limits QALLACHER; F. E. Galifornia, Univ. of, Santa Barbara, 79/04/04. 3pp
- 7908290067 Lists northern CA electric repacity margins in event of shutdown of plant Hargins are insufficient to prevent customer load curtailment should addl forced outages occur. W/790422 telegram to public util commission. BROWN.H.P. Sacramento Municipal Utility District. 79/04/26. 2pp

- 7905270085 Ack receipt of 790327 itr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 9900403/79-01
  POTAPOVB.U. Region 4. Dailar, Vendor Inspection Stanck 79/04/23 1p
- --7905290091 Responds to NRC 790228 ltr re deviation noted in GA Program Insp Rapt 99900403/79-01 Corrective actions audit rept content will be added to checklist for internal audits prior to next scheduled internal audit BARNARD.J General Electric Co .Nuclear Energy Products Div 79/03/27 5pp
- --7905290097 Forwards GA Program Insp Rept 99700403/79-01 on 790205-09 & notice of deviation POTAPOVS.U. Region 4. Delias, Vendor Inspection Brench 79702/28 2pp
- --7903290104 Notice of deviation from insp on 790205-09.
  Region 4. Dallas, Vendor Inspection Branch 79/02/26 Spp
- --7903290113 the Program Insp Rept 99900403/79-01 on 790205-69
  Noncompliance noted audit summary rept did not mention audit
  team meetings, did, not lisentify checklists used & did not
  list persons contacted during audit
  COSTELLO. J. R., BROHN. R. L., HALE, C. J. Region 4, Dallas, Vendor
  Inspection Branch. 79/02/26 22pp
- 7705290101 Forwards specific info re proposed end uses of tritium gas for export license submitted on 770213 W/o encl OPLINGER, Q G Assistant Director for Export/Import & International Safeguards 77/04/26 ip.
- 7705290107 Forwards Quif Nuclear Inc comment on proposed rule 10CFR19 & 20.
  PAUL:R. House of Rep. 79/04/18 1p.
- --7905290110 Comments on proposed rule 10CFR19 & 20 opposes rule because no latitude allowed & wording indicates overexposures are deliberate PEEPLEG.W.P. Affiliation Unknown, 79/04/11 3pp.
- 7905290115 Comments on proposed Reg Guides 1 144.1 125 Revision 1.1 72 Revision 2 & 1 9 Revision 1. GILLELAND.JE Tennessee Valley Authority 79/04/05 5pp
- 7905290118 Forwards export license application for Transnuclear, Inc to export kg U, to Denmark.
  MATGON, V. Transnuclear, Inc. 79/04/20 1p
- --7905290121 Application by Transhuclear.Inc for license to export 15 03B kg U.in form U-235 Whited to Max 93 3% to Denmark HATSON.V Transhuclear. Inc 79/04/20 3pp.
- 7905290124 Comments on proposed Reg Guide 1.144 suggests deletion of paragraph 3:0A guidance is provided in Reg Guide 1 33 CAHILL.W J. Consolidated Edison Co of New York. 79/03/20 3pp.
- 7905290127 License for Ebstline Instrument Corp to export 0 22 kg p-239 to Austria.
  OPLINGER.O. Q. Assistant Director for Export/Import & International Bafeguards. 79/04/23. 2pp
- 7905290128 License for Edlow Intl Co to export 800,000 Ci tritium to Switzerland OPLINGER: O.O Assistant Director for Export/Import & International Safeguards 79/04/23 ip
- 7905290131 Dafers RH Gerdes' deposition, served on 790326, until after 790515-17 prehearing conference.
  HILLER, M. E. Atomic Safety and Licensing Board Panel 79/04/05
- 7903290133 License for Mitsuiline Travel Syc to export miscellaneous specially designed or prepared parts & components for use in nuclear reactors to Japan. DPLINGER.0.0 Assistant Director for Export/Import & International Safeguards, 79/04/23 ip
- 7905290135 Applies for license to export reactor internals, reactor control drive mechanisms, components for reactor fuel charging & discharging machines to Spain KEENAN, R. P. Westinghouse Electric Corp. 79/04/18. Rpp.
- /905290136 Applies for license amend to increase enrichment in U-235 from 3, 14 to 3, 20 m/o max.

  DAMLSTROM.C.O. Hestinghouse Electric Corp. 79/04/17. 1p

- 7903290139 Application by Mitsuiline Travel Svc of America, Inc for license to export 20 pieces of water tubing for S18 BHR fuel to Japan YAMAZAKI.K Mitsuiline Travel Service of America, Inc. 79/04/13.
- 7903290141 Application by Edlow Intl Co for license to export 3 ampoules of SRM 4.335 Pu-242 to Sweden HARHOM, D. H. Edlow International Co. 79/04/19 2pp
- 7905290168 Application by Air Products & Chemicals, Inc for license to export 1,886 liters of deuterium to England MOVAKARD, D Air Products & Chemicals, Inc. 79/04/17 ip
- 7905290181 Requests participation in rulemaking re radioactive exposure of workers
  LEMISM Environmental Coslition on Nuclear Power. 79/03/23 ip
- --7905290187 Requests that J Johnsrud & C Repford be granted participation in rulemaking re-radioactive exposure of workers.

  LEWIS.K Environmental Coalition on Nuclear Power 79/03/23. 1p
- 7905290186 Advises of correction to Ediow Co application for license to export source matl to Brazil Matl is natural U & element weight should read 711%
  OPLINGER, 0 0 Assistant Director for Export/Import & International Bafeguards 79/04/26 ip
- 7905290190 Bubmits application by Nissho-Iwai American Corp to amend license by changing intermediate consignee TBUJI:K Nissho-Iwai American Corp 79/04/20, ip.
- 7905270231 Notification of contract execution Mod 18 to "Geologic & Beismologic Review & Appraisal of Nuclear Facilities, Miscellaneous Investigations & Technical Support "Contractor US Dept of Interior OLAGOLA: A.F Technical Assistance Contracts Branch. NRC-03-75-113. 79/04/24 ip.
- --7905290242 Mod 18.estending period of performance to 781030 w/no change in cost, to "Geologic & Beismologic Review & Appraisal of Nuclear Facilities, Miscellaneous Investigations & Tecnical Supports "
  DOUGHERTY, D J Division of Contracts, NRC-03-75-113, 79/04/24
- 7905290298 Application by Aerojet Ordinance Co to emend & renew license to export 100,000 kg U to Caπada BCHMARTZ,Η Aerojet Ordinance Co 79/04/06 2pg.
- 7905290259 Forwards NEDE-21944-P."1/4 Scale Pressure Suppression Pool Swell Test Program Plant Unique Tests." Vols 1-4 Affidavít for withholding encl. Rept withhold (ref 10CFR2 790). SBBONL. J. General Electric Co., Nuclear Energy Products Div. HFN-113-79 79/04/24. Spp.
- 7905290262 Transcript of 790508 meeting in Mashington.DC Pp 1-220. BHEUMON.P Q., MARK.J.C., ETHERINOTON.H ACRS - Advisory Committee on Reactor Safeguards 79/05/08 220pp.
- 790529026B Transcript of 790516 Asseting in Bethesda, MD. Pp. 2436-2662. MILLER, M. E., LUTON, E., MENNER, B., Atomic Safety and Licensing Board Panel. 79/05/16. 226pp
- 7903290311 Comments on proposed Reg Ouide 1.8 paragraph C.1 is contradictory paragraph C 2 provides needed definition of equivalency & value/impact statement is unsatisfactory DERMYER.W.D Affiliation Unknown 79/03/20, ap.
- 7903290424 Suggests subsurface explorations in bedrack & sails to reveal true stratigraphic & structural conditions prior to const. (Author's name & affiliation deleted).
- 7905290431 Notification of contract execution Mod 2 to "Antitrust Hearings Consulting Byce " Contractor:RM Beck, MENCZER, M. 8 Technical Assistance Contracts Branch. FIN B-1119, AT(49-24)-0268, 79/04/30 ip,
- --7905290438 Mod 2.dsobligating \$12,995.27 & closing out contract "Antitrust Hearings Consulting Sycs,"
  DOUGHERTY, D J Davision of Contracts, FIN 8-1119.
  AT(49-24)-0268, 79/04/30. 1p.

. 1

7903290435 Forwards memo of agraement between EPA Region II & NY State Siting Board on Electric Generation Siting & Environ Hemo delegates Siting Board authority to issue permits for major steem electric generating stations, CIANCI, J. M. New York, State of, 79/05/22. 21pp.

- 7905290465 Responds to request for comments on Sunset bills, H R 2 & H R 65 Supports plan to promote govt efficiency by eliminating overlapping federal programs, MENDRIE, J M Commission 79/03/16 Spp.
- ---7905290478 Forwards H.R 2 which would require budget authority & review of govt programs every 10 years, & H.R 65 to improve Congressional oversight of federal programs Requests response by 790309
  BOLLING.R House of Rep., Committee on Rules. 79/02/26 155pp
- 7705290491 "Dynamic Photoelastic Study of Crack Arrest," monthly progress rept for Mar 1979 DALLY, J. W. Maryland, Univ. of NRC-04-76-172 79/04/02 5pp
- 7905290498 "Kethods in Dosimetry for Nuclear Regulation," quarterly progress rept for Oct-Dec 1978
  BERNARD, S. R. GRIBTY, H. FORD, H. R. Dak Ridge National Laboratory
  FIN 8-0410-8 ORNL/HASRD-22 79/01/04 4pp
- 7905290503 Requests proposed amend to regulations which would eliminate accumulated dose overaging formula mentioned in encl article. "Radiation: Task Force Rept Fears Hazards May Be Greater that Previously Suspected"

  ELLIDT.J C Tennessee Valley Authority. 79/04/03 Gpp
- 7705290523 Requests info re cracking of BWR feedwater nozzle mockup & development of improved ultrasonic testing procedures Info will be used to resolve generic feedwater nozzle inservice issue
  SNAIDER, R P Systematic Evaluation Programs Branch 79/04/16,
- 7905290573 Application by Air Products & Chemicals, Inc for license to export 8 4 g of deuterium to England.
  NOVAKOVICH, D Air Products & Chemicals, Inc. 79/04/24. 1pp.
- 7905290579 Application by Wastinghouse for license to export compansated ionization chambers to France. POUCHAL, W. F Wastinghouse Electric Corp. 79/04/30. ipp.
- 7705270589 Application by Air Products & Chemical Inc for license to export 7 cu ft deuterium to United Kingdom
  EBERT.R Air Products & Chemicals, Inc. 79/03/08, ip.
- 7705270597 Notification of time change of 770501 meeting  $\omega/C-E$  in Bethesda, HD to discuss plant transient responses & Hichelson rept THADANI, A. C Reactor Systems Branch. 79/04/27, 1p.
- 7705270673 Progress rept 18 for Har 1779 on NRC-01-77-180 discussing irradiations desimpters & finances PLATO, P. Hichigan, Univ. of. NRC-01-77-180. 79/03/30. 13pp.
- 7905300078 NUREQ/CR-0682
  "Guarterly Progress Rept on Fission Product Behavior in LHRs
  from Oct to be 1978"

  MALINAUSKAS: A.P. Oak Ridge National Laboratory. FIN 8-0127.
  ORML/NUREG/18-3 79/04/30. 20pp. Available at NTIS.
- 7905300082 Responds to 790424 ltr to HR Denton requesting that x-ray technician training at Passaic County NJ Community College be investigated.

  YOUNG, F. H Assistant Director for Program Development, 79/05/11.
- ---7905900088 Requests intervention in x-ray technician training at Passaic County NJ Community College. Forwards 760402 & 780117 ltrs from NJ EPA.
  PICKETT, J. F. Affiliation Unknown. 79/04/24, 7pp.
- 7705300114 Comments on proposed Reg Quide "Quide for Preparation of Applications for Use of Quamma Irradiators:" severely harmful to small companies & too detailed Notes four new rules not in referenced documents, STEIN, M. H. RBA Corp. 79/04/11 Spp.
- 7905300152 Notification of contract execution: "BDA to Develop Regulatory Framework for Nuclear Wests Mgt," awarded to Kaman Briences Corp.
  LEBO, C. D. Technical Assistance Contracts Branch.
  NRC-02-77-201-43 79/04/24, ip.
- --7909300161 Contract: \*BDA to Develop Regulatory Framework for Nuclear Weste Mgt, \* awarded to Kaman Belences Corp. DOUGHERTY, D. J. Division of Contracts. NRC-02-77-201-43. 79/04/24. 1p.

- PROSPOOITB Notification of contract execution "Const of Nuclear & Forst! Fueled Power Plants," awarded to US Dept of Labor GLAGOLD, A F. Tachnical Assistance Contracts Branch FIN B-6540 NRC-03-79-125 79/04/20 1p.
- ---7905300186 Contract "Const of Nuclear & Fossil Fueled Power Plants" awarded to Dept of Labor DOWGHERTY, D. J Technical Assistance Contracts Branch FIN B-6940. NRC-03-79-125 79/04/18. 4pp
- 7905300180 \*Reactor Operator Training Programs Utilizing Nuclear Power Flant Simulators "
  COLLING.P F. Operator Licensing Branch. NS 16(4) VI B
  79/05/23 20pp
- 7905000194 Notification of contract execution. Mod 2 to "Review of Proposed Pile Foundations for Bailly Nuclear Generating Station." Contractor HT Davisson PERLMAN, J Division of Contracts NRC-03-78-166 79/04/24 ip
- 7905300228 Notification of contract execution Mod 2 to "Application of ILLIAC IV TRES for Determining Seismic Environ at Nuclear Power Sites " Contractor NASA-Ames Research Ctr CLAGOLA F Technical Assistance Contracts Branch FIN 8-6494, NRC-03-78-162, 79/04/24 ip
- -->7903300237 Hod 2.deobligating \$49.961 00. to "Application of ILLAC IV TRES for Determining Seismic Environ at Nuclear Power Plant Sites \* DOUGHERTY, D J Division of Contracts FIN 8-6494, NRC-03-78-162 79/04/24 2pp
- 7905300247 Notification of contract execution "BOA to Develop Regulatory Framework for Nuclear Waste Mgt," awarded to FUCRD-Inc.
  LEBO.C D. Yechnical Assistance Contracts Branch.
  NRC-02-77-201-44 79/04/26. ip
- --7703300260 Contract: "BUA to Develop Regulatory Framework for Nuclear Haste Mot." awarded to FUGRO, Inc DOUGHERTY, D J Division of Contracts. NRC-02-77-20-144 77/04/26 ip
- JP03300269 Notification of contract execution. "Economic Consulting Svc in Connection w/FL Power & Light Co's Application for License to Const St Lucie, Unit 2, Nuclear Power Plant," awarded to J Kuhman. OLAGOLA: A F Technical Assistance Contracts Branch. FIN B-6503-9 NRC-03-79-147 79/04/24, 1p.
- --7905300280 Contract. "Economic Consulting Eve in Connection w/FL Power & Light Co's Application for License to Const St Lucie. Unit 2. Nuclear Power Plant," awarded to J Kuhlman. DOUGHERTY, D. J. Division of Contracts, FIN 8-6503-9. NRC-03-79-147 79/04/24, 4pp
- 7905000278 "Licensing & Certification of Personnel at Nuclear Power Plants" # 0ffice of Nuclear Reactor Regulation. 79/05/22 12pp
- 7903300282 "NRC Examination Results for Nuclear Power Plant Personnel" App Ac1971-74, Commission 74/12/31, 14pp.
- 7405300285 IAEA-8M-178/34

  \*Reactor Operator Training Programs Utilizing Nuclear Power
  Plant Simulators, "
  COLLINS, P.F. Atomic Energy Commission, Directorate of Licensing
  (Pra-1975). 74/12/31 26pp.
- 7905300289 "License Examination Results Update, 1975-1978." HOLMAN, J Operator Licensing Branch. 78/12/31. 27pp.
- P905300290 Notification of contract execution Mod 1 to "Electric Engineering Contractural Assistance for Bouth TX Antitrust Proceeding." Contractor.RW Back & Associates. 94.4004.a.F. Technical Assistance Contracts Branch. NRC-03-79-129. 79/04/24. 1p.
- --- 1703300297 Mod 1, extending period of performance to 790630 & changing principal engineer to "Electric Engineering Contractual Assistance for South TX Antitrust Proceedings."

  DOUGHERTY, D. J. Division of Contracts, NRC-03-79-129, 79/04/24 2pp.

- 7903300295 NUREO-0560
  "Staff Rept on Generic Assessment of Feedwater Transients in PMRs Dasigned by B&H"
  # Office of Nuclear Reactor Regulation. 79/05/25 380pp.
  Available at NTIS
- 7903300303 Notification of contract execution. Mod 2 to "Bafeguards for High Level Haste Repositories" Contractor Science Applications MENCZER. N. Technical Assistance Contracts Branch FIN B-6376-9 NRC-02-79-035, 79/04/24 ip
- ---7905300309 Mod 2 changing key personnel to "Bafeguard for High Level Haste Repositories " DOUGHERTY, D J Division of Contracts FIN B-6376-9 NRC-02-74-035 79/04/24. 1p
- 7905300317 Responds to DO Eisenhut 7B1023 ltr. Bubmits info re axially varying R-factors in order to broaden scope of NRC approval of NEDE-24011-P-A, "Generic Reload Fuel Application." W/o encl. EXOEL, R E General Electric Co., Nuclear Energy Products Div MC 682 79/05/15 5pg.
- 7908300321 Forwards application for export license
  MCHRY, N R. General Atomic Co (subs of Gulf Gil Corp.). IEL-1053
  79/04/26 ip
- ---7905300326 Application by Ceneral Atomic Go for license to exportsultirange picoammeter, linear power channel, wide range log gower channel, flux controller & bistable trip module to Egypt MOHRY-H.R. General Atomic Go. (subs. of Gulf Gil Gorp.). 79/04/26 ip
- 7905390332 Forwards application for export license. HOADLEY, 8. D Monsanto Co. 79/04/25 ip
- --7903300339 Application by Monsanto Research Corp for license to export 0.33 g Pu 80% enriched in Pu-238 sealed neutron source encapsulated to Turkey.
  HOADLEY.E. Monsanto Co 79/04/25 ip.
- 7903300342 Forwards minutes of Risk Assessment Review Group 780829-31 meeting AUSTIN, J H Office of Policy Evaluations. 79/02/27 ip.
- --7903300350 Summary of 780829-31 Risk Assessment Review Group meeting in Washington, DC FR notice, attendance list & list of available documents encl # Office of Policy Evaluations 77/02/27 5pp.
- ---7903300355 Responds to 780804 FR notice requesting comments re agenda for meeting of Risk Assessment Review Group. Bebotage & evacuation issues should be resxamined. GARRETT, E. O. Affiliation Unknown 78/08/13. 1p.
- 7903300356 Submits preliminary info re natural circulation cooling at THI-2. LAFLEUR, J D. Office of International Programs 79/04/28 2pp
- 7903300359 Submits preliminary info which is subj to confirmation of regulatory action re BMW plants.

  LAFLEUR, J. D. Office of International Programs 79/04/27. 2pp
- 7905300365 Forwards IE Bulletin 79-058 re procedures & training for establishing & maintaining natural circulation & reactor vessals integrity at BMW plants. N/o ench. LAFLEUR: J D. Office of International Programs. 79/04/23 1p.
- 790530036B Forwards responses to NRC questions re heat transfer & flow distribution aspacts of revised flow blockage model Requests approval of model for future licensing submittals. Scherer A.E. C-E Power Systems. LD-79-030. 79/05/23. 14pp.
- 7903300369 Forwards IE Bulletine 79-06, 79-06A, 79-06B & 79-08 addressing aspects of TMI incident which apply to Westinghouse or C-E reactors, M/o encl.

  LAFLEUR, J. D. Office of International Programs. 79/04/18. 1p.
- 7905300370 Submits preliminary info on TMI incident Further actions should be considered for all LMRs. since pressure level indication problem may be generic in nature LAFLEUR, J. D. Office of International Programs. 79/04/11. 2pp.
- 7905300374 Comments on training, examination & licensing program for plant operators. Program has serious flaws & needs prompt attention MEDELROB, M. B. Reactor Systems Standards Branch. 79/04/20. 7pp.

7903300379 Responds to FDIA 790413 & 0426 requests for transcripts of closed NRC meetings as TMI incident Describes process involved in obtaining info List of closed Commission meetings are TMI incident encl
FELTON.J M Division of Rules and Records. 79/05/23 6pp.

- 7903300383 FOIA request for transcripts of NRC meetings, public statements & internal memos re TMI incident.
  ETHEREDOE, L Hassachusetts Institute of Technology 79/04/15
- 7905300385 FOIA request for tapes of NRC meetings re TMI incident ETHEREDGE, L. Massachusetts Institute of Technology 79/04/26 is
- 7905300389 Responds to FOIA 790428 request & forwards WASH-1400 & WASH-740, Lewis rept & NRC 790118 policy statement FELTON, J. M. Division of Rules and Records. 79/05/15 1p
- ---7905300374 FOIA request for Rassmussen rept(WASH-1400) MAY, H Affiliation Unknown 79/04/28 1p
- 7905300400 Forwards charter of Task Group on Generic Review of Feedwater Transients in B&W Designed Reactors.

  CABE.E G Office of Nuclear Reactor Regulation, 79/04/02 2pp
- 7703300414 Notification of contract execution. Mod 3 to "Mooring Bys for Floating Nuclear Power Plants." Contractor. US Naval Facilities Engineering Command. MENCIER. W. B. Technical Assistance Contracts Branch FIN B-5304 AT(49-24)-0112. 79/04/24. 1p.
- --7905300423 Mod 3.fecreasing funds by \$10.209,48.to "Mooring Bys for Floating Nuclear Power Plants" DOUGHERTY,D.J Division of Contracts FIN 8-5304 AT(49-24)-0112 79/04/24 ip
- 7705300449 Comments on NUREO-0531.insufficient justification for reclassifying recirculation-riser piping to nonconforming syc-sensitive category UTLEY,E E. Caroline Power & Light Co. OD-79-1338 79/05/21 ia
- 7905300460 Forwards signed executive personnel delegation performance agreement in response to 790410 memo.
  HENDRIE: J. M. Commission. 79/04/20. 2pp.
- 7905300464 Extends gratitude for 790419 ltr te recommendations for improving regulatory process HENDRIG.J.H Commission 79/05/01 ip
- ---7903300467 Forwards copy of ltr to President Carter & 790417 ltr to New York Times re recommendations for improving regulatory process SMITH.M E Mateorological Evaluation Services, Inc. 79/04/19
- 7905300481 Responds to 790430 & 790504 request for meeting transcripts Explains status of classified & unclassified portions of transcripts.come of which will be made available following classification review Office of the Secretary of the Commission. 79/05/14.
- --7905300487 Requests disclosure of transcripts of listed NRC meetings re export of nuclear reactors & matts Cites applicable portions of Sunshine Act JACOBS.T.J Project for Open Government. 79/04/30. 3pp.

ins NRC export licensing authority over zirconium which desiened or prepared" for nuclear facility btained generic retransfer assurances rading partners 79/05/11. 2pp

requirement for licensing export of Zr in concerns of constituent that

79/04/02 1e

- omments on freedom of eply.
- of comment on first amend ins that comment ing rise to

- ---7905300531 Requests explanation of meaning of statement made re-opposition to first amend made at 790331 press conference on THI FREIDHEIM, J. W. American Newspaper Publishers Association
- 7703300532 Forwards "Evaluation of Effects of Corrosion Particles on Control Rod Drive Operation " Rept will assist in evaluation of OE proposal to delete control rod drive return line SH矩RWOOD, © O General Electric Co · Nuclear Energy Products Div. MPN-146-79 77/05/22 ip
- --- 7905300538 "Evaluation of Effects of Corrosion Particles on Control Red Drive Operation

  \* General Electric Co . Nuclear Energy Products Div 79/05/22
- 7905300558 Forwards rept. "Technical Description of Ring Vortex Model. Har 1978 " mar 1978 \* SQEON,L J General Electric Co ,Nuclear Energy Products Div MEN-144-79 79/05/22 in.
- -7905300361 "Technical Description of Ring Vortex Model, Mar 1978 "
  CHU, C K. Quaeral Electric Co , Nuclear Energy Products Div
  LEE, T T. Queeral Electric Co 78/03/31 32pp
- 7905300562 Discusses markup of Senats Bill 8,562.NRC authorization for FYBO, which omitted three of four NRC proposals Requests meeting to discuss how best to proceed HENDRIE.U H Commission. 79/05/09 2pp
- 7903300363 Apologizes for use of term "blind man" in derogatory manner to describes it as "slip of tongue" HENDRIE, J. M. Commission 79/04/26 ip.
- --7903300371 Protests ref to "blind men stumbling around making decisions" & requests more care be taken w/comments in future. tuture. SHED,J P. Affiliation Unknown. 79/04/18. ip.
- 7905300548 Forwards summary of info which led to order to shut down five nuclear plants on 790313 Reviews NRC actions taken to expedite return to operation
  HENDRIE J. H. Commission. 79/05/02, 7pp.
- --7903300972 Forwards prompt examination of independent evaluation which concludes that piping supports comply w/NRC stds.Critical energy situation exists in ME.Urges immediate return of plant to full operation

  HRENNAN.J E Mains. State of. 79/03/23 ip
- 7903300577 Extends gratitude for 790416 ltr & offer of assistance Requests to be informed of new developments re Energy Ctr concept. Will forward resume to other Commissioners HENDRIE, J. M. Commission 79/05/01. ip.
- ---7903300587 Offers personal svc to nuclear industry in areas of equipment design & design philosophy maintroperational control & organization Suggests US adopt Energy Generation Ctr programs DIGKEMAN, R. L. Affiliation Unknown, 79/04/16 6pp.
- 7905300596 Responds to President 790410 memo requiring 5% reduction in agency energy use. Bupports reduction effort. NRC employee announcement enci.
  HENDRIE.J.M. Commission. 79/04/27. ip
- -7905300606 Requests conservation efforts to decrease consumption by BX & details specific actions to achieve goals. White House memo to agency & dept heads encl.

  HENDRIE-J H. Commission 79/04/27 3pp
- 7905300613 Ack receipt of 790321 ltr re fire protection. NRC will consider comments in its response to group 780502 petition. CHILD S. J. Office of the Secretary of the Commission 79/05/0 79/05/03
- ---7705300619 Asserts relative risk of serious reactor accidents from electrical cable fires is higher than risk from serthquakes. Cites AEC concerns re problem. Requests action be taken FORD D. F. Union of Concerned Scientists. 77/03/21. 2pp
- -7903300632 Summary rept of 730119 meeting of ad-hoc working group in Hashington DC re-fire protection \* ACRS Advisory Committee on Reactor Safeguards. 73/01/19

- P90330064B Weekly info rept for week ending 790413
  REPH.T.A. Office of the Executive Director for Operations
  79704/18 30pp
- PR05300652 Explains misunderstanding arising from lack of details in Pr0316 weakly info rept to PIPESTRESS code error. Responds to 190322 ltr. Related FR notice end, MENDRIE. J H Commission 79/05/11 3pp
- ~~7903330657 Discusses differing impressions created by NRC testimony & 790316 weekly info rept re PIPEBTRE88 code error or "unconservative" calculational technique.
  UDALL.H K House of Rep 79/03/22, 2pp.
- 7903300672 Responds to 790215 ltr re proposed interim export of reactor components to Philippines under License XCOM-0013 Case under review Ruting on petition to consolidate application \( \psi \) XR-120 to be issued before final decision.

  FENDRIE, J. M. Commission 79/05/02, ip.
- --7903300677 Advises final Executive Branch recommendation on reactor esport license application for Philippines plant is pending. Urges issuance of XGOM-0013 to avoid reactor const delays PICKERINO, T.R. State, Dept. of, Bureau of Oceans & Internati. Environ & Scientific Affairs. 79/02/15 2pp.
- 7:00300718 Discusses support needed to implement Reg Ouide 1.97.
  'Instrumentation of LWR Plants to Assess Plant Conditions
  During & Failowing Accident "
  LAIMAB.O Plant Systems Branch, 79/04/10. 2pp.
- PROSPORTED Concurs w/RQ 1 140. Revision i, "Design. Testing & Maint Criteria for Normal Ventilation Exhaust Sys Air Filtration & Adsorption Units of Light-Water Cooled Nuclear Power Plants \* CARBON, M. H. ACRB Advisory Committee on Reactor Safeguards, 79/04/10, 14
- 7903300727 Certifies that 0041 g U-235 will be subj to all terms & conditions of 600725 addl agreement for cooperation & that EBES M. Y of Belgium is authorized consignes GOPPEL. M European Communities, Commission of. 79/05/07 is.
- 7405310015 "Bleam Generator Tube Integrity Program," progress rept for Mar 1977. CLARK.R.A. Battelle Memorial Institute, Pacific Northwest Laboratory. FIN 8-2097 79/04/11. Spp

- 7903310067 Responds to 790404 itr.Forwards list of documents placed in PDR W/o encl. PELTON.J M Division of Rules and Records 79/05/23 ip
- 7905310069 Forwards application by TX Nuclear Div for license to export 1.76 mg Pu-238 to Holland HENDRICK/H Q Ramsey Engineering Co 79/04/25 1p
- --7905310074 Application by TX Nuclear Div for license to export 1 76 mg Po-238 to Holland HENDRICK:W O Ramsey Engineering Co 79/04/25 1p
- 7903310321 Forwards magnetic tape of time histories used to generate comulative damage function curves for NMSB applications gresented in NEDE 24010-P Index of contents, into on formatting & example printouts of time history encl SOBON-L. J General Electric Co., Nuclear Energy Products Div MFN-150-79 79/03/29. 7pp
- 7905310339 Requests proprietary computer program PIBYS & NEDE-24077. "PIBYS Users Manual" 6td Mar 1978, be withheld (ref 100FR2 790) Affidavit encl SHERNOOD, 0. O. General Electric Co , Nuclear Energy Products Div HFN-143-79 79/05/22. Spp
- 7905310343 Clarifies commitment contained in JH Taylor 790428 ltr re scheduls for daveloping auxiliary faedwater control sys independent of integrated control sys TAYLOR: J. H Babcock & Wilcox Go 79/05/22 2pp
- 7905310377 Forwards Suppl 3 to Vol 1.Section 6 of "Evaluation of Transfent Behavior of Small RCS Breaks in 177 Fuel Assembly Plant" dtd 790524. TAYLORIJ.H Babcock & Wilcox Co 79/05/24. ip
- ~-7905310386 Suppl 3 to Vol 1, Section 6 of "Evaluation of Transient Schavior of Small RCS Steaks in 177 Fuel Assembly Plant " # Babcock & Wilcox Co. 79/05/24 Spp
- 7903310406 Forwards affidavit supporting request for proprietary classification of BAN-4689. "Pressurizer Ref Leg Effervescence Test." dtd 770301. TAYLOR.J.H Babcock & Wilcox Co 79/05/19 8pp

				To the last of the
				THE THE STATE OF T
				B - To defending to
				Al Table ship any management
				VIDOT VIDA PROGLES
		•		
	•			Ą
•			,	

AUTHUR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
MAROE N H	7905040265			ASHER, T R	7705240048		*************
AROE, H H	7905290038 7905080034			ABRELL, D. L. ABRELL, D. L	7903110260 7903150264	50-382	
ABBOTTB. J	7905080040	50-22		ASHELL, D. L	7905150408	50-392 50-392	
ABEOTTS: J ABRAHAN: K,	7905080047 7904210770			ASHELL, D. L ASHELL, D. L	7905170228 7905170231	50-392	
ARAHAM, K	7905150207	50-363		AUSTIN, M. A	7705150137	50-382 70-364	
ABRAHAM, K ABRANSON, L	7905150298 7905090220	50-363 50-320		AUSTIN, M.A. Austin, M.A	7905240594 7905240763	70-135	
ADAMS, N. E.	7905150414	50~255		AUSTIN, H. A.	7905250049	70-135 70-135	
Adragna, j m Adragal, a k	7905070222 7905240427		7905240427	AUSTIN, M, A AUSTIN, M. A	7905220077 7905090060	70-135	
A TEARNE, J. F	7905230494	-a -a-a		A MINITEUA	7705240087	70-135 70-364	
MEARIE, J.F. MEARIE, J.F.	7905160097 7905160177	50-320 50-320		H L,MITBUA	7905300342 7905110317	50-29	
ALEXANDER U. F	7905160056	50-320		A H-DITUA	7905150422	50-27	
ALEARNE, JF ALEARNE, JF	7905160084 7905160169	50-320 50-320		AUTIO, H. A. AUTIO, H. A.	7905150433 7905190126	50-29 50-29	
外を(根)を ゴ ド	7705020024			AXELRAD, M	7905030158	50-344	
MEARIE, J.F. MEARIE, J.F	7905160073 7905160259	50-320 50-320		AXELRAD.M. AXELRAD.H	7905150722 7905240959	50~344 50~376	
MEARINE J F.	7900160107	50-320 50-320		AXELRAD, H.	7905240970	50-376	
MEARNE, J. F. MEARNE, J. F.	7905160140 7905020046	50-320		AXELRAD. J. A AXELSON: 41. L.	7905100269 7905230442	50-348 70-1368	
AMEARNE, J. F.	7905160114	50~320 50~320		AYCOCK, M	7905140038	50-320	
AMEARNE J F	7905160119 7905160088	50-320		Backusir a. Backusir, a	7905010323 7905010329	50-443 50-443	
AMEARNE, J. F.	7905160147	50-320		BACKUB.R A	7905020422	50~443	
AHEARNE, J. F. AHEARNE, J. F.	7905030055 7905290003			BACKUS, R. A BACCN, J. L	7905080398 7905090307	50-443 50-329	
AIN.F P ALDEN, H. H	7905240149	50~574 50~277		BAERIR.L.	7905240977		
W.DEN. H K	7908140344 7908170241	50-277 50-277		BAERIR L. Baerir L	7905250050 7905240936	50-580	
ALEXANDER, R. E. ALLAN, J. K	7905150702 7905210036	50-320		BAER, R. L.	7705100112	50-382	
ALLAN, J H	7905210039	20-320		BAIETTI A L Bailey, F G	7905150614 7905150689	71-311	
ALLENIO J. ALLENIJ	7905250491 790530003	50-320		BAILEY, F. Q.	7905150693		
ALLEON: C H	7905080109		TF8P-TR-209	BAIR, O O Baird, G L.	7905110169 7905210184	50-344	
ALVAREZ, B. AMBLER, E.	7905240199 7905240354	50-280 50-184		Baird. J B Bajaa B S	7905040366	50~344 50~400	
AMLAUER, K	7905240116	00 1404		BAKER, J. R.	7905240459 7905250304	40-8452	
AMLAUER, K. AMDERSON, L	7905250306 7905140029	50-320		BAKERIC E. Bakeric, e.	7905300132 7905240544	40-8681 40-8681	
ANDERBON, G. R.	7905240348	71-9033		BAKER, K. R	7705020208	50-315	
ANDERSON, C. R. ANDERSON, 9	7905150785 7905150314			BALDHIN, H. A Baldhin, H. N	7905250052 7905090306	50-275	
ANDERBON, T. M.	7705310418	50-482		BALL, R	7905220453	50-320	
ANDERBON, T. M ANDERBON, T. M	7905110098 7905140469		HCAP-9402 (NP)	BALLARD, R. L. Ballard, R. L	7905090141 7905150043	50-502 50-477	
ANDERBON, T. M	7905110094			BALLARD, R. L.	7905150126	50-376	
ANDERSON, T. M. ANDERSON, T. M.	7905090327 7905090344			BALLARD, R. L. Ballard, R. L	7905150132 7905150124	50-376 50-463	
ANDERSON, T M	7905210146 7905190063			BALLARD, R. L.	7905150296	50-546	
ANDERSON, T. M. ANDERSON, T. M.	7905190065			BALLARD, R. L. Ballard, R. L.	7905230855 7905240914	50-362 50-599	
ANDERSON, T. M. ANDERSON, T. M.	7905220422 7905250393	50-320		BALLARD, R. L	7905240919	50~599	
AHDERSON, L., F	790530050\$	40-8722		BALLARD;R.L BALLARD;R.L,	7905240926 7905240966	50-599 50-59 <del>9</del>	
ANDERSON, D. R. ANDERSON, O. C.	7905100243 7905240330	50-255	7905100243	BALLARD,R L BALOUGH,R C	7905090296 7905230793	50~546 50~445	
AMDERBON, D. Q.	7905100364			ĐALTAZAR, R, Z,	7905080534	50-329	
ANDERSON, C. J. ANDCONINT, C. C.	7905040314 7905010542	50-322 50-293		BANGROFT, M. Bangroft, H. H	7905140072 7905080047	50-320	
ANDOONINE, Q. C	7905090501	50-293		BANKS, H R.	7905230604	50-261	
ANDOONINI, O. C. ANDOONINI, O. C	7905170235 7905170230	50-293 50-293		BANKBEH R. Bankseh R.	7905190010 7905190086	50-241 50-241	
ANDOONINI, O. C. ANDREHS, J. C.	7905310352	50-293		BANKS, H. R	7903220106	30-261	
ANDREHS, R. D	7905040274 7905100223	40-8452		BANKE, H. R. BANKE, H. R.	790523061 5 7905220342	50-324 50-325	
ANDREHS: R. D ANDREHS: R. D	7905100233 7905240283	40-8452 40-8462		BANKS, H. R.	7705220361	50-325	
AMDRENS: N.	7905240223	50-367		BANKS: H. R. Banks: H. R.	7905220367 7905220406	50-325 50-324	
ANDRENS M ANDRENS R L	7905230452 7905070541	50-276 50-238		BANKS, H. R	7905250413	50-325	
ANDREWS, R L.	7905210256	50~285		Banke, H. R. Banke, H. R.	7905290219 7905300384	50~261 50~324	
ANDRENS, R. L. ANDRENS, R. L	7705210268 7705220300	50-285 50-285		BANKS, H. R. BANKS, H. R.	7905300425 7905300371	50-325 50-324	
ANDREWS, R. L.	7905300548	50-265		BANKB, H. R.	7905300375	50-324	
ANDRUS: H. ANO: H. P.	7905230735 7905020117	50-466 50-391		BANKE, H. R. BANKE, H. R.	7905300387 7905300512	50-324 50-325	
ANO, H P	7905010243	50-389		BARD, S. T.	7905040207		
ANGELO: J. ARLOTTO: O. A	7905240359 7905090226	50-390 50-320		Bardeg, C. R. Barhan, C. D.	7905110090 7905170233	50-280 50-261	
ARMSTRONG, H. H.	7905030233			HARI.R.A	7905240529		7905240529
ARMSTRONG, H. H. ARMOLD, R. C.	7905100142 7905230117	50-320		BARKER, R. F Barnard, J.	7905150502 7905290041		
ARHOLD R.C.	7905230110	50-320		BARNES, R. D	7905080568	50-397	
ARHOLDIR, C. ARHOLDIR, C.	7905230082 7905190113	50-320 50-320		BARNETT, E. N Barnett, E. N	7905310020 7905150190	50-445 50-445	
ARNOLDIR, C ARNOLDIR, C.	7905190111	50-320 50-320		BARNETT, E. W	7905230651	50-445 50-445	
ARNOLD R.C.	7905190093 7905190120	50-320		BARNETT, E. W. Barnes, J. D.	7905230624 7905040506	50-397	
ARNOLD R.C.	7905190187 7905190089	50-320 50-320		BARNES, L.	7905150561	50-445 50-373	
ARNOLD: R. C. ARNOLD: R. C.	7905230013	50-320		BARRETT, P. A. Barrett, P. A	7905030074 7905150419	50-341	
ARNOLD-R, C. ARNOLD-R, C.	7905140025 7905230005	50-320 50-320		BARRETT, L.	7905300255 7904260292	50-320 50-320	
ARNOLD, R. C.	7905230024	50-320		BARRETT: L. H Barrons: H. L.	7905090441	40-8698	
ARNOLD, R. C. ARNOLD, R. C.	7905100420 7905110333	50~289 50-320		BARRONS, H. L. BARTH, C. A.	7905090345 7 <del>90</del> 5250368	50~592 50~400	
ARNOLD R. C	7905110165	50~320		BARTH, C. A.	7905240144	50~255	
ARNOLDIR.C. ARNOLDIR.C.	7905110170 7905110174	50-320		Barth, C. A Barth, C. A.	7905080379 7905300034	50-358 50-48 <b>8</b>	
ARNOLD: R. C.	7905110178	50-267		BARTH, C. A.	7905300091	50-350 50-400	
ABHER: T. R.	7905150155			BARTH, C. A.	7905230829	JU-700	

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUKBER	REPORT NUMBER
BARTH, C A.	7905020334	50-358		BERNERO, R.	7905160220	50-320	
BARTH:CA Barth:CA	7905220075 7905250093	50-358 50-400		BERNERO, R M BESAW, W J	7905230611 7905300169	50-320	
BARTH, C A	7905020147	50-446		BESKID, N	7905170292	40-1162	
BARTHICA Barthica.	7905070216 7905070225	50-400 50-580		BEGSETTE, D. E. Beth, R. M	7905140011 7905240387	50-320 50-141	
BARTH, C A	7905080341	50-358		BETTENHAUSEN, L	7905300752	50-311	NURE9/CR-0643
BARTH-C A Barth-C A	7905090359 7905090377	50~491 50~580		BEUTLER, P. S. Beyer, B	7905100165 7905100345	50-346	NOREV/CK-DQ45
BARTHIC A Barthig A	7905090147	50-491 50-580		Bickel, J. H. Bickwit, L	7905140049 7905140170	50-320 50-320	
BARTH.C A.	7905150495 7905220443	50-400		BICKWIT, L	7905100030	50-320	BECY-79-207
BARTH, C A Barth, C A,	7905240635 7905240703	50-488 50-400		BICKWIT, L. BICKWIT, L.	7905090256 7905140163	50-320 50-320	
BARTH, C A	7905240738	50-491		Bickwit, L	7905140166 7905140188	50-320 50-320	
Barth, C. A. Barth, C. A	7905290195 7905030079	50~491 50~448		BICKHIT, L. BICKHIT, L	7905090250	50-320	
BARTH/C A. Barth/C A	7905030152 7905250099	50-400 50-488		BICKWIT, L. Biden, J R	7905300319 7905240512	50-320 50-450	
BARTH, C A	7905110046	50-255		Bielawski, a p.	7905160504	50-556	
BARTH, C. A. BARTH, C. A	7905240306 7905300140	50-358 50-255		Bielawski.a.p. Bielawski.a.p.	7905090185 7905300022	50-556 50-295	
BARTON, A.R. Barton, M.C	7905150357 7905160424	50-348 50-367		BIEN, F N Billio, J	7905250371 7905220045	50-315 50-250	
Baskin, K, P.	7905160319	50-204		BILLINGTON, 9	7905230744	50-466	
Baskin, K. P Baskin, K. P	7905240395 7905210160	50-204 50-361		BIRD,PE. BIRKEL,RA	7905300£18 7905240£08	50-320 50-437	
BASTO, B	7905220065	50-250		BIRKEL, R. A.	7905150759	50-599	
BATES, A BATES, A	7905140031 7905140034	50-320 50-320		BIBCHOFF,C A BIBHOP,M Q	7905100002 7905030247	50-592 50-549	
BATES, J N Battist, L	7905020161 7905160129	70-1151 50-320		BIAENS' L	7905150524 7905110287	50-320	
BATTIST, L	7905160202	50-320		BIXBA'M M	7905300054	50-320	
BATTIST.L Battist.L	7905190107 7905300300	50~320 50~320	NUREG-0558	BIXEL,D A. BIXEL,D A	7905040099 7905080480	50-155 50-155	
BAUER, E Q BAUM, E A.	7905030352 7905090435	50-277		BIXEL, D. A	7905290278 7905150457	50~155 50~155	
BAUNACK, H. H	7905070182	50-266		BIXEL.D A.	7905250075	50-155	
BAUNACK, W H BAUSER, M A	7905290166 7905300035	50-336 50-250		BIXEL.D A Black.b.	7905310449 7905250514	50-155	
BAUSER, M. A.	7905150793	50-250		BLACK R L.	7905250126	50-522	
BAUSER, M.A. BAUSER, M.A	7905150799 7905240207	50-250 50-369		BLAKE, E.L. Blake, E.L.	7905090247 7905100133	50-320 50-484	
BAXLEY, B X Baxley, B X.	7905080524 7905070646	50-321 80-364		BLAKE, J. J BLANSETT, V.	7905240665 7905310401	50-324 50-123	
BAXLEY, S X.	7905300660	50-321		BLAU, J.	7905290106	50~514	
BAXTER.R C BAYNARD,P Y	7905230782 7905300668	50-332 71-6698		BLAUVELT, R. K. BLOND, R	7905220105 7905160131	71-9506 50-320	
BAYNE, J. P BAYNE, J. P	790507016B 7905030181	50-286 50-286		BLOTCKY, A. J. Blotcky, A. J.	7905140192 7905140198	50-131 50-131	
BAYNE, J. P	7905250172	50-284		BLOTCKY, A J	7905090197		e
BAYNE, J. P. BAYNE, J. P.	7905250241 7905010516	50-284 50-284		BLUMBERQ; N J BLUMBERQ; N	7908070182 7905070158	50-264 50-272	*
BAYNE, J. P	7905090301 7905150302	50-284 50-284		BLUHE, M. B	7905100273	50-445	
BAYNE, J. P	7905230551	50-284		BLUME, M. B. BLUME, M. B.	7905100106 7905230466	50-445 50-445	
BEAN, R. M BEATON, R. H	7905100243 7905190154	50-73	7905100243	BODTKE, P. J. BOEKNERT, P	7905150416 7905140154	50-255 50-320	
BECHHOEFER, C BECHHOEFER, C,	7905100381 7905300690	50~255 50~358		BOGDEN, Q.	7905300147	40-1162	
BECHHOEFER, C.	7905250208	90~395		BOODEN, O BOODEN, O	7903240437 7903240442	40-1162 40-1162	
BECHHOEFER, C BECHHOEFER, C.	7905290036 7905150284	50~358 50~358		BDHANNON; J. R. BDHN; R. J.	7905310452 7905010534	50-8 50-347	
Dechhoefer, C Deckman, D. A.	7905240330 7905290173	50~255 50~244		BIOHNIR J.	7705140308	50-367	
BECKMAN, D. A.	7905296157	50~334		90HN, R. J. 90HN, R. J.	7905110306 7905220207	50-367 50-367	
BECKNER, W. D. BECKNER, W. D.	7905110363 7905110328	50~320 50~320		BOHN, R. J. BOLLING, R.	7905300329 7905290478	50-367	
BECKURTS, K. H Behling, B	7905140260 7905230486	50~320 50~320		HOND, O. R.	79052203A8 7905210270	50-219	
BEILMAN, T. P BEILMAN, T. P	7905070613 7905150441	50-315 50-315		BOND: QR. BONNER; J	7705110412	50-219	
BEXLMAN, T. P.	7905220326	50~315		BOOK, H. E Book, H. E	7905020513 7905020520	50-142 50-142	
BEILMAN, T. P Beilman, T. P.	7905220333 7905220339	50~315 50~315		800K, H. E. 800K, H. E	7905150686	70-1257	
BELANGER: J. L BELCHER: T.	7905150775 7905100353	50~295 50~554		POOK, H. E.	7905150701 7905230656	70-1257 50-323	
BELEH, Q. L.	7905010567	50~270		BOOK, H. E. Book, H. E.	7905230664 7905040362	50-323 50-344	
BELL, N BELL, N	7905250260 7905110160	50~344 50~320		BOOK₁H. €	7900040366	50-344	
BELL: J. M. BELL: M. J	7905110156 7905140035	50-320 50-320		Bordenick, B. M. Bordenick, B. M.	7905110418 7905240278	50-320 50-516	
BELL, H, J.	7905160036	50~320		BORER, P. S BORES, R.	7905150526 79051900 <b>5</b> 7	50-278 50-320	
BELLOTTI,F X. BELLOTTI,F, X.	7905100324 7905090411	50~471 50-471		BORGMANN, E. A.	7905100210	50-358	
BENAROYA, V. BENDER, M.	7903190203 7903140021	50-320 50-320		BORGHANN, E. A. Borgmann, E. A.	7905100222 7905140083	50-358 50-358	
BENDER, M	7905240205			BORGMANN, E. A. BORGMANN, E. A.	7905140111 7905020451	50~358 50~358	
BENEFIELD, H. E. BENEFIELD, H. E.	790524020 <i>6</i> 7905240210	71-317 71-317		BDROHANN, E. A.	7905290449	50-358	
BENJAMIN.A.S. BENNEDEN.H.B.	7905140149 7905010618	40-8698	NUREO/CR-0649	Boromann, E. A. Boromann, E. A.	7905080439 7905110148	50-358 50-358	
BENNETT, C.	7905150626	71~312		Boromann, E. A. Boris, W. R.	7905160494 7905150484	50-358 50-155	
BENNETT, C. BENNETT, D. E.	7905150632 7 <del>9</del> 05140 <i>0</i> 32	71-312 50-320		BORIS, W. R	7905250303	50-155	
BENNETT, C. L. BENNETT, G L.	7904190311 7905110330	50-320		BOROCHOFF, I.D. BOSKEY, B.	7905070166 7905100196	50-382 50-348	
BERECHER J.	7905240667	50-488		BOSKEY, B. BOTT, T. F.	7905150665 7905300438	70-1821 50-320	ORNL/TH-6853
Berger, D. 4 Berger, M. G.	7905230019 7905300058	50-320 50-445		BOUKNIGHT, J. A BOUKNIGHT, J. A.	7905150190	50-445	Services or Manage
BERGER, M C BERGGREN, J.	7905100288 7905230729	50-445 50-466		BOUKNIGHT, J A.	7905230651 7905230624	50-445 50-445	
BERGLAND, B. BERICK, D.	7905090090	50-522		BOUKNICHT, J. A. BOURNIA, A.	7905240853 7905290021	50-38 <del>7</del> 50-373	
JERKY, J. A.	7905240199 7905240965	50-280 50-313		BOHDEN, T. J. BOHERS, C. E.	7905150391 7905250236	50-348 70-820	
BERNARD, B. R	7905290498		7903290498	BOHERS, C. E.	7905240086	70-820	

AUTHOR	ACCESSION NUMBER	DOCKET NAMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
POMERBIE B.	7905240479	50-250		BROWN, 8 C	7905110297	50-404	
PONERS, E S	7905290114 7905230853	50-275		BROWN, S.C.	7905160418	50-339	
POMERBIE B.	7905220053	50-445 50-445		ERDAN, S.C. ERDAN, S.C.	7905220111 7905220344	50-404 50-339	
POWERS, E. S	7905140567	50-250		BROWN, S. C.	7905230022	50~338	
FOWERS, E.S.	7905290489 7905250499	50-250		BROWN, S. C.	7905290375	50-338	
POYD, HK	7905140087	50-295		erdands, c. erdands c	7905290404 7905300017	50-339 50-339	
FOYD, R 6	7905240813	50-546		BROWN O D	7905230491	00 007	
IOYD, R S	7905250439	50-331		BROWN, Q D	7905230693		
POYDIR B POYDIR B	7905150080 7905240211	50-424 50-424		BROWN, C D BROWN, R L	7905100266 7905290113	50-267	
MOYD.R 8	7905220030	50-263		BROWN R L	7905230593		
BOYD, R B	7905220033	50-263		BROWN R 8	7905160028	50-320	
BOYD, R. G. BOYD, R. S	7905070452 7905010664	50-495 50-596		BRUE, N. L. BRUGGE, R. O	7905310261 7905170269	50-271 50-260	NEDO-24169A
BOYD, R 6	7905230582	50-275		BRUHNER, E J	7905300388	50-249	THE REPORT OF THE PERSON OF TH
BOYD, R B	7905300392	50-424 50-382		BRUNNER, E J	7905140208	50-317	
BOYD, R B BOYD, R B	7905140516 7905230837	50-596		BRUNNER, E. J. BRUNNER, E. J	7903220461 7905290169	50~320 50~244	
BOYD, R 6	7905150118	50-275		BRUNNER, E J	7905210042	\$0-320	
POYD,R 6 POYD,R 8	7905240662 7905240676	50-344 50-532		BRUNNER, E J Brunner, E J	7905290116	50-277	
POAD' & 8	7905290015	30~33k		BRUNNER, E. J	7905070172 7905070145	50-286 50-272	
BOYD, R G	7905150315	50-331		BRUNNER, E J	7905090142	50-213	
MOYER, R. L.	7905090383	50-404		BRUNNER, E J	7905070189	50-247	
BOYER, V. S. BOYER, V. S	7905020538 7905290345	50-277		BRUNNER, E. J. Brunner, E. J.	7905080099 7905110216	50-286 50-219	
₽OYTER,N C.	7905010395	50-313		BRUNNER, E J.	7905110362	50-247	
BRADFORD, H H BRADFORD, H, H	7905230503 7905230503	50-269		BRUNNER, E. J. BRUNNER, E. J.	7905110368 7905240430	50-271 50-287	
BRADFORD, P A	7905300667	50-322		BRUNNER, E. J.	7905240492	50-245	
BRADFORD, P A	7905150009			BRUNNER, E. J	7905300743	50-311	
BRADFORD, P. A BRADFORD, P. A	7905160038 7905160072	50-320 50-320		BRUNNER, E. J Brunner, E. J	7905290123 7905290140	50-334 50-245	
BRADFORDIP A	7905020024	oo~aku		BRUNNER, E. J	7905290154	50-245 50-334	
#RADFORD,₽ A.	7905160134	50-320	•	BRUNNER, E J	7905290160	30-334	
BRADFORD, P A	7905160101 7905020046	50-320		BRUNNER, E J BRUNNER, E J	7905070133 7905070161	50-272 50-286	
BRADFORD, P. A. BRADFORD, P. A.	7905020046 7905080070			BRUNNER, E. J.	7905070161 7905150507	50-286 50-277	
SRADFORD, P.A.	7905100020	50-320		BRUSVEN, A. D	7905150225	50-263	
BRADFORD, P A	7905080125	50-320		BRYANT, H. R	7905080139		
#RADFORD:PA #RADFORD:PA.	7905030055 7905290003			BRYANIR H BRYANIS E.	7905020004 7905110200	50~286	
BRADLEY, E J	7905030348	50-277		BRYAN, S E	7905110009	50-312	
BRADLEY, E J	7905030352	50-277		BRYAN, S. E.	7905140067	50-320	
SRADLEY, E. J SRADLEY, E. J	7905110073 7905220347	50-277 50-277		BRYAN, S. E. BRYAN, S. E.	7905110218 7905110413	50-320	
SRADLEY, R D	7905250020	50-400		BRYANT, J C	7905290117	50-375	
BRADY, R. J	7905160006	50-320		BRYANT, J. C	7905020352	50-369	
BRADY,R J BRADY,R J	7905160005 7905160161	50-320 50-320		BRYANT, J. C. Bryant, J. C.	7905020442 7905020117	50-327 50-371	
BRADY, R. A.	7905160179	50-320		BRYANT, J. C	7905070358	50-389	
BRADY, R. A	7905160171	50-320		BRYANT, J C	7905240307	50-327	
BRAILE, L W.	7905240326 7905030268	50-395	NUREO-0382	BRYANT, J. C BRYANT, J. C	7905010243 7905290398	50-389 50-281	
BRAND, H E BREMAECKER, D. E.	7905220057	50~466		BRYANT, J C	7905090426	50-395	
BRENNAN, J. E	7905300572	50-309		BRYANT, J. C.	7905230752	50-491	
BRENNER, L. BRENNER, L.	7905020448 7905020456	50~546 50~546		BRYANT, J.C. Bryant, J.C.	7905250431 7905240537	50-508 50-491	
BRENNER, L	7905240343	50-443		BRYANT, J. C.	7905240509	50-424	
BRENNER, L.	7905290028	50-485		BUCHANAN, J	7905160129	50-320	
BRENNER, L	7905290353	50~443		BUCHANAN, J. BUCHANAN, J	7905190107 7905300300	50-320 50-320	NURE0-0558
BRETTHAVER, E BRICKLEY, R. H	7905230175 7905030150	50-320		BUCK, P.	7905160427	50~409	HOME 4-033B
BRICKLEY, R. H	7905100418			BUDENHOLRER, R.	7905300232	50-320	
BR LOOS, K.	7905150303	40-8698		BUDNETZ, R. J. BUDNETZ, R. J.	7905110291 7905110293	50-320	
BRIOGE, L. E. BRINDLEY, J. H.	7905110217 7905080510	50-219 50-375		BUDNITZ, R. J.	7905110299	50-320 50-320	
BRINKER, W. F.	7905100201	50-320		BUDNETZ, R. J.	7905110301	50-320	
BRINGHAN, R. E	7904300342			BUDNITZ, R. J. Budnitz, R. J.	7905110302	50-320 50-330	
BRODSKY,R 8. BROEFL: D. J.	7905020264 7905040520	71-9785 50-344		BUDNITZ, R. J.	7905160452 7905110286	50-320 50-320	
BROEHL: D. J.	7905090291	50-344		BUDNETZ, R. J.	7905110289	50-320	
BROEHL, D. J	7905150387	50~344		BUDNITZ.R.J BUHL.A.R.	7905110308 7905230443	50-320	
BRONSON: F BROOKS: J.	7905220034 7905250337			BUHL, A.R	7905230449		
BROOKE, J	7905250329			BUNTENO, R. L.	7905100251	50-285	NUREO/CR-0755
BROOKS, J.	7905250336			BUONANNO,N A. BURCHETTE,W H.	7905230711 7905240332	50-352 50-445	
BROWN, J. W. BROWN, P. D	7905040015 7905230409	50-596		BURCH, C. L.	7905300347	50-320	
BROWN B. F.	7905090417		NUREO/CR-0784	BURDETTE, T. E.	7905150081	50-518	
BROWNSTEIN, M.	7905010473	** *		BURDETTE, T. E. Burdette, T. E	7903240468 7903240507	50~395 50-518	
BROWN, E G.	7905100364 7905240713	50-320 50-275		BURGER, A.	7905240507	50-29 50-318	
BROWN, M. S.	7905040002	50~316		BURTAN, R. J	7905100126	71-4059	
BROWN, H. S.	7905110124	50-315		BURKE, P. A.	7905100398	71-200	
BROWN, H. S. BROWN, H. S.	7905150430 7905230330	50-315 50-316		BURKE, P. A. BURKE, D. J.	7908100393 7908020019	71-288 50-280	
BROWN, N. S. BROWN, H. P.	7905290067	50-312		BURKHARDT₁₩.	7905230706	50~364	
SROWN, R. A.	7905040132	50-346		BURN, R. R.	7905090298	50-2	
BROWN, D. H.	7905090273	50~346 80~338		BURN, R. R. Burneta O.	7905090367 7905140489	50-2 50-116	
BROWN, B.C. BROWN, B.C.	7905100070 7905100076	50-339 50-339		BURNETTE, Q. II.	7905240353		7905240353
BROWN, B. C.	7905100055	50-339		BURNETT, P. T.	7905240491	50-327	
BROWN, B. C.	7905290529	50-339		BURNETT, P. T. BURNETT, R. F.	7905240534 7905230754	50-339 70-1193	
BROWN, S. C. BROWN, S. C.	7903040126 7903240407	50~338 50~338		BURNETT, R. F.	7905240139	70-1193	
BROKN, B. C.	7905070404	50-339		BURNETT, R. F.	7905020041	50-320	
BROSN, S. C	7905080511	50-339		Burbtein, 9. Burbtein, 8.	7905020289 7905020304	50~301 50~301	
BROWN, B. C. BROWN, B. C.	7905100317 7905060434	50-338 50-339		BURSTEIN, 6,	7905010489	50-502	
BROWN, S. C.	7905080443	50~339		BURGTEIN₁6.	7905020310	50~266	
BROWN, B. C.	7905080452	50-339		Burbtein, 6. Burbtein, 6.	7905020318 7905290078	50-266 50-266	
BROWN, S. C. BROWN, S. C.	7905090297 7905110214	50-339 50-339		BURSTEIN: 6.	7905010513	50-502	
Management of Mr. 1911							•

AUTHOR	ACCEBBION NUMBER	DOCKET NUMBER	REPORT NAMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
Burstein, S. Burstein, S.	7905030337 7905240519	50-502 50-266		CARRIER, W. C.	7905220352		*******
Burstein, S Burstein, 6	7905100256 7905100263	50-301		Carrier, H C Carrigan, R. H	7905290285 7905230390		
BURSTEIN, S.	7905240303	50-301 50-266		CARRIGAN, R. H. CARRIGAN, R. H.	7905230388 7905230380		
BURBTEIN, S. Burbtein, S.	7905020271 7905100314	50-244 50-301		CARRIGAN, R. H.	7905230370	40-2407	
BURSTEIN, S BURSTEIN, B	7905100315 7905300316	50-301 50-266		CARRICAN, R. H. CARRICAN, R. H.	7905230357 7905230352	40-2407 40-2407	
BURSTEIN, 8 Burstein, 8,	7905240831 7903080470	50-266		CARRIGAN, R. H Carrigan, R. H.	7905230351 7905230345	40-2407 40-2407	
BURSTEIN, S BURSTEIN, S,	7905150202	50-502 50-266		CARRIGAN, R. H Carrigan, R. H.	7905230338 7905230332	40-2407 40-2407	
BURSTEIN, S	7905150446 7905240611	50~266 50~266		CARRIGAN.R.H. CARRIGAN.R H	7905230328 7905230320	40-2407	
BURSTEIN, S. BURSTEIN, S	7905240627 7905290284	50~266 50~266		CARRIGAN, R H CARRIGAN, R H	7905230315	40-2407 40-2407	
Burstein, S. Burstein, S	7905160362 7905150349	20~266		CARRIGAN, R. H	7905230306 7905230299	40-2407 40-2407	
BURSTEIN, S BURSTEIN, S	7905150378 7905150381	50-301 50-502		CARRIGAN, R. H. CARRIGAN, R. H	7905230284 7905230276	40-2407 40-2407	
BURSTEIN, 8. BURSTEIN, 8.	7705240397	50-301		CARRIGAN, R. H. CARRIGAN, R. H	7905230261 7905230247	40-2407 40-2407	
BURT, L.	7905310359 7905070026	50~266 50~443		Carrigan, R. H. Carrigan, R. H.	7905230758 7905230233	40-2407	
BURT, L. BURT, L.	7905240943 7905090411	50-471 50-471		CARRIGAN, R. H. CARRIGAN, R. H	7905230226	40-2407	
BURT, L. BURT, L.	7905230396 7905240794	50-471		CARRIGAN, R. H.	7905230586 7905230214		
BURWELL, B B BUBCH, R. W.	7903140040 7903140159	50~445 50~522		CARROLL, J. T.	7905010528 7905190083	50-317 50-317	
BUSCH, R. W BUSKIN, K. P.	7905140161 7905230514	50-522 50-206		CARROLL, J. T. CARROLL, J. T.	7905290430 7905070557	50-317 50-219	
BUTLER, R M BUTLER, R M.	7905290654	50-471		CARROLL, J. T Carroll, J. T.	7905090329 7905140327	50-219 50-219	
BUTLER, R. M. BUTLER, R. M	7905140435 7905150397	50-471 50-293		CARSON, J. E GARTER, T. F.	7905040462 7905070141	50-329	
BUTLER, R. H	7905220021 7905300011	50-471 50-471		CARTER, T.	7904270399	50-320	
BUTLER.R K. BUTZEL.A K.	7905300013 7905240983	50~471 50-549		CARTHRIGHT, K CARTHRIGHT, J, E,	7905100089 7905150063	40-2061 50-556	
CABA, E. C. CADEK, F. F.	7905140235 7905110098	30-346	11745-0400 Mg	CARTHRIGHT, W. R. CARTHRIGHT, W. R.	7905020396 7905020403	50-338 50-338	
CAHILLIH J Cahillih, J	7905290124		MCAP-9402 (NP)	CARTHRIGHT, H R. CARTHRIGHT, H. R.	7905020464 7905020246	50-338 50-338	
CAHILLIN. J	7905290185 7905250248	50-3 50-3		CARTURIOHT, W. R. CARTURIGHT, H. R.	7905070533	50-338	
CAHILLIN.J.	7905040004 7905070549	50-247 50-3		CARTHRIGHT, H R	7905070459 7905070462	50-338 50-338	
CAHILL, W. J. CAHILL, W. J.	7905090287 7905190015	50-247 50-3		CARTHRIOHT, N. R. CARTHRIOHT, N. R	7905080447 7905080449	50-338 50-338	
CAHILLIH J. Cahillih, J.	7905190021 7905170244	50-3 50-247		CARTURIOHT, W. R Carturioht, W. R	7905110147 7905110152	50-338 50-338	
CAHILLIH, J. CAHILLIH, J.	7905230365 7905310396	50-3		CARTHRIGHT, W. R Carthright, H. R	7905160437 7905160444	50-338 50-338	
CAHILL, H J CAHILL, H. J	7905300354	50-247 50-247		CARTHRIGHT, N R CARTHRIGHT, N. R	7905160434	50-336	
CALDMELL, R A	7905300359 7905230248	50~247 50~265		CARTHRIGHT, W R.	7905160458 7905210260	50-338 50-338	
CALDHELL, R. A. CALIFAND, J. A.	7903150584 7904170110	50-112 50-320		CARTHRIGHT, H, R. CARTHRIGHT, H. R.	7905220296 7905230071	50-338 50-338	
CALKINS.O.D. CAMP.O.T.	7905160015 7905160399	50-320 50-295	•	CARTHRIGHT, H. R. CARTHRIGHT, H. R.	7905300404 7905300408	50-338 50-338	
CAMPBELL, J. CAMPBELL, M.	7905100310 7905160194	59-304		CARTHRIGHT, H. R. Cary, C. N.	7905300412 7905240352	50-338	7558546885
CAMPBELL, M. CAMPBELL, M	7905160077	20-350 20-350		GASE, E Q. Gase, E Q.	7905080144 7905300400		7905240552
CANNON, E	7905140007 7905290251	50-320 71~282		CASE, E. CASEY, L. A.	7905110064		
CANDVA, H. A.	7905090342 7905080561	50-318 50-317		CABH, A.	7905100240 7905250454		NUREO/CP-0005
CANTER, H.L. CANTRELL, F. S	7905110086 7905290174	50-312 50-335		CASHELL, B, CASHMAN, T. J,	7905010488 7905230813	50-201	
CANTRELL, F. B. CANTRELL, F. B.	7905290717 7905020049	50-369 50-280		CABUENS, L. CASSAN, V. J.	7905250201 7905070417	40-8481	
CANTRELL, F. S. CANTRELL, F. S.	7905020019 7905020471	50~260		CATALANO, G. R. CATCHPOOLE, G. J	7905100078 7905100172	40-2061	
CANTRELL, F. B.	7905020423	50-339 50-349		CATTON, I CATTON, I.	7905250139	40-8693	
CANTRELL, F. S.	7905010275	50~250 50~250		CATTON, I.	7905250111 7905250118		
		50-348 50-320		CAVANAUOH, W.	7905070483 7905110082	50-313 50-313	
		50-311 50-320		CAVANAUGH, W. CAVANAUGH, W	7905140279 7905170265	50-313 50-368	
		50-320		Cavanaugh, H. Cavanaugh, H.	7903190053 7905210264	50-313 50-313	
				CAVANAUGH, W. CERNE, A. C.	7905300002 7905240684	50-368 50-363	
		50-320		CHADNELL, H. M. CHAN, J.	7905070604 7905040561	50-315	
		50-10 50-320		CHAN, J. CHAN, A. E.	7905300573	50-237 50-237	
		50-320 50-320		CHANANIA, F. D.	7905100165 7 <del>9</del> 05230622	50~250	NUREQ/CR-0643
		50~320		CHANANIA, F. D. CHANANIA, F. D.	790515021 <u>4</u> 7905230743	50-395 50-395	•
		50-334 50-271		CHANDLER, L. J. CHANDLER, L. J.	7905250271 7905250143	50-445 50-445	
		50-367		CHANDLER, L. J. CHAPELL, D.	7905300362 7905040262	50-445	
		50-387 50-289		CHAPHAN, L. D. CHAPHAN, L. D.	7905240404	90-350	7905240404
		50-322 50-563		CHEN, J. C CHERNO, J. C.	7905240553 7905020151		7905240553 7905020151
		30-277 50-387		CHESTER, R. O.	7905100290 7905240540	50-305	XN-NF-79-27 7903240540
		50-387 50-309		CHETIRKIN, P. V. CHIANGI, N. J.	7905280312 7905140419	50-400	,,44270470
	1	50~113		CHILDS, W. V.	7905010503 7905010508	50-333	
	!	50-344 50-344		CHILDS, W. V. CHILDS, W. V.	7905150477 79053300416	50-333 50-333	
		50-294 50-294		CHILDS, W. V. CHILDS, W. V.	7905300514 7905300527	50-333 50-333	
	;	90-320		CHILD, B. J.	7905300527 790530Q613	50-333	

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESS ION NUMBER	DOCKET NUMBER	REPORT NUMBER
CHILKIS J.	7905230701 7905230484			COLLINS, H E COLLINS, H E,	7905250444 7905090214	50-320	
CHIFK'S 1	7905230499			COLLINS, D M	7905230202	50-320	
CHILKIS J. CHILKIS J.	7905100026 7905090283	50-320 50-313		COLLINS, J T	7905230056 7905230074	50-320 50-320	
CHILK. B J.	7905100047	50-320		COLLINS, J T	7905210230 7905230105	50-320 50-320	
CHILK.B J. CHILK.S J	7905100408 7905090192	50-320		COLLINS, J T	7905230143	50-320	
CHILK. S J	7905090215 7905090194	50-320		COLLING, J T	7905230293 7905230157	50-320 50-320	
CHILKIS J	7905140033	50-344		COLLINS, P F	7905070070	50-574 50-252	
CHIFK'S 1	7905300268 7905230678	50-320 50-485		COLLINS, PF COLLINS, PF	7905240166 7905250204	50-267	
CHITK'S 1	7905250063 7905230646	50~280		COLLINS, P F COLLINS, P F	7905300180 7905300285		IAEA-SK-178/34
CHICK'S Y	7905100056	00 400		COLOMBO, P. W	7903110039	50-312 50-312	
CHICK, B J	7905240315 7905230661	50~344		COLOMBO, R W COLOMBO, R W	7905100282 7905110307	50-312	
CHILKIB J.	7905230573	50-305 50-424		COLOMBO, R W	7905250437 7905290004	50-312 50-312	
CHILK.S J.	7905240918 7905150260	50~599		COLOMBO, R W	7905300409	50-312	
CHIEK, S J CHILK, S J	7905240435 7905240820			COLTON, E COMBS, R B	7905150784 7905140311		
CHILK'S 1	7905240510	50-338		COMEY, D D	7905230239 7905160129	50-320 50-320	CBE-7865
CHICK'S 1	7905250165 7905250334	50~400		CONGEL, F CONGEL, F	7905190107	50-320	
CHILLK'S J	7905240358 7905240366			CONGEL, F CONLEY, M. E	7905300300 7905090032	50-320	NUREQ-055B
CHILKIS J.	7905250479	50-320		CONLEY, M E	79050200BD	50-302	
CHILK. 6 J CHILK. 8 J	7905250205 7905250331	50-389		CONLON, T E	7905010471 7905240518	50-348	
CHILK.8 J	7905250539			CONNERT T B CONNERT T. B	7905290171 7905290176	50~358 50~358	
CHICK'S 1	7905300481 7905220434	50~320		CONNER, T B	7905150151	50-358	
CHOEKO! K	7905220436 7905090175	50~320 50~409		CONNERT B CONNERT B	7905300067 7905100225	50-358 27-39	
CHOM, E T CHRISTMAN, J N	7905230668	50-338		CONNER, T. B.	7905030214	50-395	
CHRISTHAN, J N	7705240814 7905030207	50~338 50~338		CONNERT B. CONNERT B	7905310010 7905100237	27-39 27-39	
CHRISTMAN, J CHRISTMAN, J	7905030209	50~338		CONNERT B.	7905240138	27-39 50-277	
CHRISTOFFER OM CHU, C K	7905110047 7905300561	50-162		CONNERT B CONNERT B.	7905230512 7905140137	50-395	
CHURCHELL, B W	7905250339	50~502 50~344		CONNECT: J H CONNECT: J H.	7905300270 7905300277	50-206 50-206	
CHURCHILL, BW ClassCI.JH	7905300104 7905290435	30-344		CONNECL: C	7905150304	50-264	2004100001
CLEBIK LENICZ, 8.	7905160359	50-10		CONNECLIH R CONNORBIJ E	7905100021 7905100023		7905100021
CLACK: B J CLARK: L	7905250522 7905250350	50-576		CONNOLLEY, J L	7905140494	50-265	
CLARKI C	7905040480 7905160391	50-20 50-329		CONNOLLEY, J. L. CONNOLLEY, J. L	7905210259 7905210271	50-265 50-265	
CLARK.C H CLARKE.H L	7905090031		7905090001	CONSTABLE, O.L.	7905150604 7905070158	50-188 50-272	
CLARK, J. R. CLARK, R. H.	7905020214 7905300058	50~201 50~445		CONTE.R J CONTE.R J	7905290145	50-245	
CLARK, R. H	7905100208	50~445		CONVERTS T L VAHACO	7905190199 7905140090	50-320 50-320	
CLARKIF R CLARKIR A	7905220387 7905310015	50-333	7905310015	CONWAY: W. F.	7905080352	50-271	
CLARK, A. T	7705270282 7705240846	50-201 50-259		CONWAY, H. F. CONWAY, H. F.	7905080553 7905290037	50-271 50-271	
CLARKIR A CLAYFE.L	7905240069	50-335		CONHAY, W. F. COOK, C. L	7905290040 7905150214	50-271 71-260	
CLAY, E. L. (LAY, E. L	7905240336 7905240312	70-1151 70-1151		COOK, C L	7905150474	71-260	
CLAYTONIF L	7905230777	50-348 50-348		COOK, T F	7905090408 7905110116		NUREO/CR-0590
CLAYTON, F. L CLAYTON, F. L	7905100279 7905020242	50-348		COOK, J R	7905250245	50-568 50-338	
CLAYTON F L	7905240443 7905300710	50-348 50-348		COOKE, P. S.	7905250296 7905250042	50-329 40-8498	
tLAYTON, F. L. CLAYTON, F. L	7905020247	50~348		COOLEY, W. J. COOLEY, R. A	7905150701 7905140117	70-1257 50-320	
CLAYTON, F. L. CLAYTON, F. L.	7905300554 7905070631	50-348 50-348		COONEY, K. J	7905070016		
CLAYTON, F L	7905090075	50-348		COONEY, H J.	7905220280 7905220284	50~277 50~277	
CLAYTON, F. L. CLAYTON, F. L.	7905250034 7905110242	50-348 50-348		COONEY, H J.	7905080464 7905040578	50-277	
LAYTON, F L.	7905140306 7905160403	50~348 50~348		COONEY, M J.	7905040077	50-277 50-277	
LAYTON F L	7903170266	50-34B		COGNEY, H J	7905040092 7905020347	50-277 50-277	
LAYTON F. L LAYTON F. L	7905230361 7905230414	50~348 50-348		COGNEYIK J	7905020356	50-277	
LAYTON, F. L.	7905300500	50-348 50-348		COONEY, K. J	7905040591 7905160383	50-277 50-277	
LAYTON, F. L LEARY, P. C	7905310376 7905230239	50-320	CBE-7865	COONEY, M. J.	7905170236 7905290214	50~277 50~277	
LEARY: P	7905250480 7905170251	50~443	PCBE-79137	COONEY: M. J. COONEY: H. J	7905290216	50-277	
LEARY, J V	7905290295	50-471		COOPER, K. F. COOPER, J.	7905070551 7905040050	50-272 50-302	
LEETON, A. R LEMENSON, F.	7905290292 7905090148	50-471		COGPER, J	7905040094	50-302	
LEHONE: P	7905110113	30-6134		COOPER, J. COOPER, J	7903070602 7903070624	50-302 50-302	
LUSEN, R. C. OALWELL, T. N.	7905080108 7905150359	50-264		¢ooper.J	7905070540 7905070648	50-302 50-302	
088. L. I.	7905100022 7905140079	50-320 70-2623		Cooper.j. Cooper.j	7905040632	50-302	
OCHRAN, T. B. OCHRAN, B. J.	7905150805	50-590		COOPER, J COOPER, J.	7905070654 7905090261	50-302 50-302	
OEN, R.	7905080540 7905170229	50-237 50-237		COOPER, J	7905110244	50-302	
OEN, R. OHEN, W. S.	7905300686	50-309		COOPER, J. COOPER, J.	7905190028 7905230373	50-302 50-302	
OHEN, I	790523029 <del>8</del> 7905300035	70-33 50-250		COOPER, J.	7905300503 7905250385	50-302 50-302	
OLE, H. A.	7905150755	50-250 50-250		COOPER: J. COOPER: J.	7705300491	50-302	
OLL: N. A.	7905150793 7905150799	50-250		COOPER, J. COOPERSTEIN, R.	7905310403 7905300691	50-302 40-8102	
OLL N. A	7905240973 7905240838	50-250 50-389	•	COOPERSTEIN, R	7905150634	40-8721	
OLL INS. C G.	7905240940	50~568		Cooperstein.r. Cooperstein.r	7905240855 7905150806	40-8663 40-8502	
OLL THIS, H. E.	7905230248 7905250516	50-320		COOPERSTEIN, R.	7905250012 7905060387	40-8714 50-466	
OLL INS. H. E.	7905250501 7905250517			COPELAND, J. C COPELAND, J. C	7905080387	50-466	
OLLING, H E.	/TUQ#0001/						

326			LITOOISALA				
AUYHOR	ACCESSION NUMBER	DOCKET	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
	7905230230	30-466		CRONEBERGER, D	7905230011	50-320	
COPELAND, J G COPELAND, J G	7905250230	50-437		CROMEBERGER.D CROSSHAN.H A	7905230009 7905070209	50-320 50-445	
COPELAND, J G	7905300066	50-466 50-466		CROSSMAN,W A	7905150570	50-554	MIREA (CD., AGES
COPELAND, J G COPELAND, J G	7905310407 7905290068	50-466		CROWCHER, D W	7905020022 7905080027	70~135	NUREO/CR-0283
COPELAND, J G	7905240310	50-466 50-466		CROW, W T. CROW, W T	7905090265	70-143	
COPELAND, J O COPELAND, J O	7905240043 7905250239	50-466		CROW, W T	7905240080 7905090003	70-1317 40-8027	
COPELAND, R L	7905020293	50-537		CROW, W T CROW, W T	7905090008	40-8027	
CORBETT, J B CORE, M	7905220434 7905070545	27~47 50~285		CROW, N T	7905220029 7905100064	40-8663 40-2061	
CORE, M	7905220306	50~285		CROW, W T CROW, W T	7905290479	40-8027	
CORNELL, E K	7905090158 7905020157	27-39		CROW, W T. CROW, W T	7705250067 7705240855	40-8035 40-8663	
CORNELL, E X	7905220451	50-320		CROW, W T	7905240180	70-2838	
CORREA, C COSTELLO, J	7905290089 7905150273	50-272 50-392		CROWLEY, C. J.	7905020154 7905030221		7905020154 NUREG/CR-0599
COSTELLO, J	7905150415	50-382		CROWLEY.C J	7905240552		7905240552
COSTELLO, J R COSTELLO, J R	7905290113 7905230593			CROWLEY, B R	7905240518 7905080051	50-34B	NUREG-0484
COTTLE, # T	7905020423	50-369 50-369		CUDLIN.R. Culp.H G.	7905220232	50-495	,
COTTLE:N.T.	7905290717 7905140097	50-546		CULP,R H	7905080387 7905080331	50-466 50-466	
CONCHERMA	7905250433	50~546 50~546		CULP,R H CULP,R H	7905250170	50-498	
CONGHITMIN	7905080415 7905160400	50-546		CULP₁R H CULP₁R H.	7905080311 7905080320	50-466 50-466	
COUGHLIN, J	7905310420	50-546 50-213		CULPIR H.	7905250225	50-466	
COUNCIL.W G	7905250446 7905240392	50-213		CULP.R H	7905140057 7905250328	50-466 50-498	
COUNSIL, # G	7905240503	50-213 50-213		CULP,R H CULP,R H	7905100391	50-466	
COUNSIL, N G	7905310473 7905070542	50~213		CULP.F H	7905250239 7905290002	50~466 50~498	
COUNSIL, N G	7905300323	50-213 50-245		CULP, R H CUNNINGHAM, Q. E	7905150627	71-5926	
COUNSIL, H O	7905010485 7905010496	50-245		CUNNINGHAM, G E	7905290062 7905240588	70~754 70~1007	
COUNSIL, H G	7905250513			CUNNINGHAM, G E	7905250218	70-754	
COUNSIL, W. O COUNSIL, W. O	7905250523 7905070658	50-213		CUNNINGHAM, G E	7905240910 7905160227	71~4009 50~320	
COUNSIL, H. O	7905040053	50-336 50-336		CUNNINGHAM, R E	7905220028	70-1318	
COUNSIL, W.O.	7905040135 7905070359	50-336		CUNNINGHAM, R E	7905310132 7905220442	70-2623 50~320	
COUNSIL, W O	7905070621	50-245 50-245		CUNNINOHAM, M CUNNINGHAM, M,	7905220432	50-320	
COUNSIL, H G. COUNSIL, H G	7905080562 7905080454	50-245 50-245		CUNNINGHAM, M	7905110315	50-320 50-320	
COUNSIL, W.C.	7905080404	50-336		CUNNINGHAH, M CUNNINGHAH, M	7905110312 7905160064	50-320	
COUNSIL, W C	7905100320 7905160262	50-336 50-336		CUNNINGHAM, M	7905160139	50-320 50-206	
COUNSIL, W Q	7905160376	50-336		CURRAN, J. K. CURRAN, J. K	7905060425 7905110139	50-206	
COUNSIL, H Q COUNSIL H.Q.	7905220116 7905290073	50-336 50-213		GURRAN, J. M.	7905150409	50~206	
COUNSIL, ₩ Q	7905300005	50~245		CURRAN, J M CURRAN, J M	7905150512 7905310444	20~206 20~206	
COUNSIL, W G	7905300009 7905300241	50-336 50-336		CURTIB: N. W.	7905030149	50-397	
COUNSIE, H O	7705310183	\$6-336		CURTIS, N. W. CURTIS, N. W.	7905250184 7905020242	50-397 50-397	
COUSINS, R	7905220068 7905250290	50-250 50-437		CURTIB, N. W.	7905040504	50-387	
COMOILL,C J.	7905290145	50-245		CURTIE, N. W CURTIE, N. W	7905090344 7905090365	50-397 50-397	
COX. C.	7905230175 7905090374	50-320 50-449		CURTIS N W	7905110300	90-397	
COX, E. T. CRABTREE, R. A	7905230528	50-309		CURTIE, N. W. CURTIE, N. W.	7905150224 7905240574	50~387 50~387	
CRADDICK, W.G. CRAFTON, M	7905140572 7905250495	50-546	NUREO/CR-0539	CURTIS, N. W	7905250421	50-397	
CRANE, P A	7905030244	50-275		CUTCHIN, J. M.	79052400B1 7905240641	50-387 50-568	
CRANE, P A.	7905140303 7905140554	50-133 50-275		DACKO, B S	7905140284	50-445	
CRANE, P. A CRANE, P. A	7905140556	50-275		DAHLSTROM, G. Q. Dailie G.	7905290134 7905230699	50-471	
CRANE, P. A CRANE, P. A.	7905230490 7905020244	50-275 50-275		DAIL, L. G.	7905140167	50~413	
CRANE, P. A	7905150807	50-133		DAIL.L C Dail.L C	7905240520 7905190100	50-491 50-413	
CRANE, PA. CRANE, PA	7905290011 7905020302	50-133 50-275		DALE, L. F	7905080450	50-414	**************************************
CRANE, P. A.	7905090318	50-133		DALLY, J W DALTROSB, S. L	7905290491 7905230710	50-277	7908290491
CRANE, P. A.	7905090380 7905240701	50-275 50-275		DALTROFF.S L.	7905250152	50-277	
CRANE, P A	7905140406	50~103		DALTROFF.B L. DALY,H	7905240184 7905250353	50-277 50-596	
CRANE, P. A CRANE, P. A	7905190054 7905210172	50-275 50-275		DAMBLY, D. C	7905240493	50-329	
CRANE, P. A	7905210169	50-275		DAMBLY, D DAMERON, M. G.	7905310028 7905290051	50-329 70-27	
GRANE, P. A GRANE, P. A	7905300169 7905300364	50-133 50-275		DANCE H. C.	7905310024	50-302	
CRANE, P. A.	7908300361	50-275		DANCETH C DANCETH C.	7905230243 7905230592	50-324 50-241	
CRANE, P. A Creitz, W M	7905300510 7905160174	50-133 50-320		DANCE: H. C	7905150107	50-259	
CRESWELL, J. 8,	7905110094	30~346		DANCE:H C DANCE:H C	7905250110 7905150147	50-321 50-259	
CRESHELL, J 8	7905090175 7905230605	50-409 50-395		DANCE: H. C.	7905020497	50-321	
CREWS, E. H.	7905300692	50-395		DANIELGON, T. DANIELG, R. W	7905100332 7905240200	50~592 40~3453	
GREWS, J.L. GREWS, J.L.	7905110044 7905110083	50-312 50-312		DANIEL, J A.	7905210120	50-320	
CREWS, J L	7905110086	50-312		DANIELSON, D. H. DANIELSON, D. H.	7905230308 7905080211	50-341 50-331	
CREWS, J L. CREWS, J L	7905230617 7905150533	50-275 50-312		DANIELS, F. T.	7905150163	50~156	
CREWS, J L.	7905290147	50-275		DANIELB, F. T.	7905140087 7905240748	50~295 50~456	
CRISTY, M Crnich, J.	7905290498 7905130415	30-382	7905290498	DANIELBON, D. H. DANIELBON, D. H.	7905290569	50-155	
CROCKET, L.	7905140570	50-219	NUREO/CR-0634	DANIELBON, D. H.	7905240714 7905040349	50-373 50-461	
CROCKER, H. N GROCKER, H. N	7905240306 7905230750	50-244 50-277		DANIELBON, D. H. DANIELBON, D. H	7905150434	50-331	
CROCKER, H W.	7905110113	30-6134		DANIELSON, D. H	7905150535 7905110207	50-359 50-329	
CROCKER, H. W CROCKER, H. W.	7905290196 7905090140	50-3 50-220		DAGUD:L DARMITZEL:R W.	7905150207 7905150382	70-754	
CROCKER, L. P.	7903100325	90-275		DARMITZEL, R. W	7905160428	50-70 50-546	
CROCKER, L.P. GROCKER, L.P.	7905300396 7905300381	50-320		DATTILO: T. M. DATTILO: T. M.	7905110353 7905240872	50-546	
CRONENBERG, A W	7903150213	50-320	NUREO/CR-0595	DATTILO, T. M	7905240964	30-346	
CRONEBERGER, D. K	7905230014	50-320		DATTILO, T. M.	7905150220	50-546	

		気に作り返す					
A. 化特别引持 动物物系统	}ир ист РфФбфрМ	in mat is	Auth	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	DOCKET
لْمَا فَدِينَا الْمِينَا	विभ अञ्चल		OFPENAL I	7903230227	50-244	144100	HANDER .
E 42 E 2 C 1	But 145		оениуса, и в	7905240421 7905290311	50-10		
** 414 - 43	511 321 51 351		OF TRUBE LEB. R LA	7905290633 7905070027	50-471		
4 2 2 2 1 1 2 2 2 4 4 2 2 4 4 4 2 2 4 4 4 2 2 4 4 4 2 2 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4			E4 (1) 140 1 17	7905030090 7905090364	50-373		50-572 56-973
ቀው ንም፡፡ 'ታጀፃ • ተ	9: 18d 9:1 187		centucii i.	7905310357	50-18 50-409		50-478 50-478
** * * * *** ** 7: * ~ ***	ትላ መጀመ ዓያ ቤተል		9 L. "11A"M M	7905240207 7905150352	50-225 50-259		50~546
· · · · · · · · · · · · · · · · · · ·	ስ፣ና ካካል ከ4 ሽክል		(ACMEY) L	7905150346 7905230622	50~259 50~250		50-376
を	ባ ፥ ዓላይ		iknitt'n D iknitt'n D	7905110085 7905150309	50-255 50-255		50~347 50~311
・	¥ዲጭ ፣ ቁ ማዲዉ የ∾ዕ		ifixithiy D Texandida	7905020280 7904170363	40-299		50-311 50-436
· 在	Org Mital Di, Spit		የፋ ነ (ዶታለህ - በ - C ጊዜ ነ (ዶታለህ - በ - C	7904130020 7905020390	E0 20.		50~4 <b>6</b> 8 5 <b>6~</b> 5 <b>9</b> 2
·安 智力等 (1) 等外	Print in		CATTEMAN, N. C. CATTEMAN, N. C.	7905230541	50-596 50-463		90-326 90-392
1 世 3 草 4 集 3 其 節 韓	5-4 435.5 5-1 21 *		DECEMBER 1,	7905240955 7905300587	20-313		54-392 10-387
*** *** *** *** *** *** *** *** *** **	Day brid		DICEBNATH B	7905080028 7905240587		7905240587	)O~ 452
· pri 1 20 g · pr 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	ው። ያቸው የተተ \$1456\$		ከታሉ። ከሃታል ነፃ ነፃ ከታሉ። ለሃታል ነፃ	7905110234 7905190140	50~320 50~320		)0−3 <b>67</b> 10− <b>6</b> 73
· * * * * * * * * * * * * * * * * * * *	ው ( ይዩል ሙ ( ያዩት		DIELABIKKHEN DIELABIKKHEN	7905240129 7905310422	50-346 50-592		'≎−496 <i>≎</i> −4892
1 + * 14 4 EK	4. 具在3 4.4 【本件】		OPPAREATED P	7905240826 7905230621	70-1143 70-1151		
****** **** **************************	F 1 1 3 7 7		hirtatan h p	7905250206	70-1151 70-1151		0-413 9-46ô
1 44 3 4 31 43 4 4 1 44 3 4 31 43 4 4	数: 34章 本 ) g 4		DIPEATEA. H. P.	7905300712 7905090190	70-1151		5~G#G
aga ng g g g gara aga ng	0 #3∳ 5- ####		14 M ANSASMO 11 M ANSASMO	7905300136 7905020187	71-6400 70-1151		0-956 >~927
4 大小女子	4: \$7\$6 8: \$6*1		V W.ATLA1910	7905020307 7905080002	71-5450	BECY-79-187	)-300 )-877
*** #** ***	ର । ୬୬୬		្រី មេ ២៩, ២៤.5 ប្រ ម	7905020176 7905020180	71-6678		}~3ef }~397
ர் இரு முழ்த் மழ்ந்தின் இவரி மிழித்திர்க்க	B I Not		timend m )	7905310152 7905110172	70-2623		}-54è ≻-340
会会 ( イッタング ガン21年 海を育り返り	03. χη <sup>ων</sup> ( "1, 1,00×40.		r w patelo	7905080081			, 4.2
本語を a y ガンキャ 1 年 1 年 2 年 1 1 1 1 1 1 1 1 1 1 1 1 1 1	" \$ 7% 1% Br   7 E S		614A4 551. A 1.14A4 551. A	7905230036 7905160016	50-320		
· 即: 路線 39 / 北京节	क्षेत्रदर्भ व		\$ \$ \$ \$ \$ \$ \$ \$ \$ \$	7405150156 740531022	1 20-550		~300
न्द्रत के इस्ताहरू स्टब्स	b (230)		present to 0	790516008 790503023	1	NUREO/CR-0446	-282
1 新 1 新 2 5 5 5 5 7 5 4 5 5 6 5 6 5 6 5 6 5 6 5 6 5 6 5 6 5			<b>阿哈斯</b> 1	790510007 790507003	7 40-4492		-267 200
· 中,李安里 · 中山	2		terments of t	790515018 790524034	5 30-466		-213
· 如,新学生"丰曜	as γ γγαςανι		behante i f betakte f	790511034 790531038	2 -0-466		-215
· · · · · · · · · · · · · · · · · · ·	B H # 2 4 4		terrusy. Fr	790511033	36 50-466		- <u>ଥି</u> କ୍? - ୟକ୍
· 斯·加克斯·斯斯 · 斯·斯森斯 兹	Wata Man		greens of F tracesty of F	79052501/ 79053103	81 50-466		344
· 新山湖 1年 2017年 11年 11年 11年 11年 11年 11年 11年 11年 11年	ing 19 35°3 sag 250 35°3°		terminal of the	79053001 E0053097	86 50-315		920
+ 4+1 3 1 € 1 0 1 0 1 1 1 1 1 1 1 1 1 1 1 1 1 1	5 3 X X X X		şa k Ada il K Şi k Ada iş	79050704 79050204	.01 50-313		247 247
1 40 2 7 3 7 7 7 10	21.		tok AM is K buk AM is k	79050400 79051503	156 50-315	)	267 267
2 100 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	(da) - 1 1 2 1 1		gala dost d K bria dost d K	79053104 79052901	120 30-31		390 767
ջ բուլել ֆուտն Հարւել ել Վե	5 M 4 F	ments o meta	ter see ? t	79052903	366 30-3		<b>304</b>
4 1-4 21 4 1-4 4 2 + 2 12 4 14 4 4	¥ 	W 11/2	GREE AND I B	79053104 7905240	864	MOHEO) CK-0100	380
· 1900年版上学 · 博 - 新日本   1901年	(\$1/ \$0 BE-		cents ( d	7905010 7905150	660 70-18	21	<u> </u>
e person of the	1 <b>5</b> th	That is the confe	property of a	7905160 7905160	026 50-32	:0	300 120
·斯·南北南小路 +	## × × × × × × × × × × × × × × × × × ×	ı	CENT A A	7905220 7905160	166 50-32	80	120
大宮 保護な事が カート	P Water		人 被 美国 (A)	7905160 7905160	190 50-3	50	120
中 東ルロ <b>第</b> 277 日本代	以下: 第 200 200 200 200 200 200 200 200 200 2		extended to the second	7905030 7905100	2072 50-20	<b>a</b> 0	කිර කිර
大海水牛 野花前 1			ا الاستعداد من م	790510- 790525	0328 ** :	39	210
(1) 中央公司 · · · · · · · · · · · · · · · · · · ·	MI TOTAL		DELEMBERT OF	+d0525	0270	37	#O
大 100mm 中 100mm	appears the \$1	18	grange att th	790514	0647		
·斯尔斯文相 ·李斯斯曼 孫	TOTAL SE STEEL SE	ł.	AND PROPERTY D	790527	00161		24 20 20 20 30 10 10
かいまする 事の ない	: 1. 후 레 나녕나는 및 전		STATE OF THE PARTY	790530	00280 00280		10 10
部 : 衛 : 神 : 神 · 山 · 山 · 市 · 市 · 市 · 市 · 市 · 市 · 市 · 市	10th 30th 1 1275 11	3-1 3-14	THE PARTY OF THE P	790539	00277		10
かりまりまりを	ARCONDO -	\$% 394	STANGETT. D	79053	004%3 00360		ю́
10 miles (教育中	State of the state	\$ <b>3</b> .4	Total and Mills W.	) 79052 J 20052	40111		)) ()
的數字 的數字數字 1	本語	herit	ter state it. b	79052	50309		
ermentisch national	emprojence and a	<b>►€</b> ♦	2011年4月17・フ	J 70050			4
<b>に関する。数字が</b>	(福) (1) (1) (1) (1) (1) (1) (1)	<b>於新</b> 徒	DEL CARREST DE	4 79050 J <del>3</del> 9051	10415	NUREO/CR-0454	4
Analogije page na Kanggarangan	<b>神</b> 衛星 章 年	***		4 79050	09042B	Witten	4, 3
(1) (1) (1) (1) (1) (1) (1) (1) (1) (1)	Marie Marie		SCHOOL S II	7405	845050		A .
\$\$\$\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	of the control of the	<b>SA</b>	SOUTH N. N.	7900	4/903	7-47	<u> </u>
NO MANUAL PROPERTY OF	Property of	<b>新教</b>	100 mark	7403	230225 50	g206	3
1 40 40 40 A	<b>建设工程</b>		Spring I.E.		090347	0-204	•
######################################	THE PARTY NAMED IN		DENNE S	-			
▶ ####################################							

AUTHOR	ACCEBBION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
DRAKE, J H	7905090325	50-206	•	ELLIS, J	7905240929	50-445	*****
DRAKE,J H DRAKE,J H	7905150400 7905170257	50-204 50-206		ELROD, S A ELSASSER, T C	7905020049 7905090254	50-280 50-320	
DREY, K	7905020533	50-10		ELSASSER, T.	7905090248	50-320	
DREY, K DROMERICK, A. W	7905020234 7905020459	50-10 50-339		ELBABSER, T C EMAL, H A	7905220439 7905210070	50-320 50-320	
DUCK, JR	7905010527	50-327		ENDREG, O H	7905030015	00 020	NURE0/CR-0426 V1
DACK'N K	7905100304 7905160396	50-348 50-348		ENGEL,R E ENGEL.D A	7905300317 7905030239	50-549	
DUCK, J. R. DUDA, E.	7905300469 7905160394	50-348		ENGEL, D.A.	7905150266	50-596	
DUDA, E	7905300496	30-220 50-220		ENGELHARDT, T.F ENGELHARDT, T.F	7905090255 7905150321	50-320 50-492	
DUFF,PA DUFIG,ME	7904300258 7905140332	50-553		ENGELHARDT.YF Engelken,r h	7905150726 7905010283	50-275	
DUFLO, M E	7905090249	50-320		ENGELKEN R H	7905010287	50-528 50-133	
DUFLO,M E DUFLO,M E	7905220070 7905100067	50-278 50-344		ENGELKEN, R H ENGELKEN, R H	7905010289 7905010291	50-344 50-312	
DUFLO, K. E. DUFLO, M. E	7905240135	50~33B		ENGELKEN, R H	7905010292	50-206	
DUFLO, M E	7905240487 7905250318	50-339 50-498		ENGELKEN, R. H ENGELKEN, R. H	7905010294 7905030073	50-397 50-458	
DUFLO,M.E. DUFLO,M E	7905250035 7905150710	50-369		engelken, R, H Engelken, R, H	7905040076	50-528	
DUFLO, M E.	7905140332	50~320		ENGELKEN, R. H	7905040081 7905040086	50-133 50-344	
DUFLO,K E DUFLO,K E	7905150233 7905150542	50-329 50-320		ENGELKEN,R H ENGELKEN,R H	7905010216 7905010218	50-133 50-344	
DULEY,J W BUFLO,M E	7905240585	50-277		ENGELKEN, R H	7905010220	50-206	
DULLINGFORD, M	7905070171 7904180171			ENGELKEN,R H ENGELKEN,R H	7905010222 7905010225	50-312 70-984	
DUNBAR, J DUNBAR, J,	7905300447 7905300499	50~237 50~237		ENGELKEN R H	7705010228	70-1257	
DUNDAS, W. J	7905230463	50-244		ENGELKEN,R H ENGELKEN,R H	7905010290 7905010234	70-754 70-734	
DUNENFELD; M DUNN; C, N	7903140036 7903240209	71-5450		ENGELKEN, R. H	7905010239	70-25	
DUNN, C N	7905140322	50-334		engelken, r. h Engelken, r. h	7905010423 7905010428	50-133 50-344	
DUNN, C. N DUNN, C. N.	7905090066 7905250461	50-334 50-334		engelken, r h Engelken, r, h	7705010431	20~509	
DUNN, C. N.	7905010491	50-334		ENGELKEN, R H	7905010433 7905150057	50-312 50-528	
DUNN, C N. DUNN, C N.	7905090373 7905140300	50-334 50-334		ENGELKEN, R. H ENGELKEN, R. H	7905150060 7905150062	50-133 50-344	
DUNN, C. N. DUNN, C. N.	7905110011	50-334		ENGELKEN, R H	7905150064	50-204	
DUNN, C N.	7905110070 7905150267	50-412		engelken, r h Engelken, r h,	7905150065 7905150069	50-312 50-397	
DUNN, C, N DUNN, C N	7905150269 7905220081	50-412 50-334		ENGELSKEN, R. H	7905150145	50-528	
DUNIN, C. N	7905220093	50~334 50~334		engelken, r. h Engelken, r. h	7905150167 7905150168	50~133 50-344	
DURHAN, J. H DURHAN, J. H	7905110004 7905220187	50-312 50-344		engelken, r h	7905150170	50-206	
DYER, N C	7905100251	50-295	NUREG/CR-0755	ENGELKEN, R H ENGELKEN, R H	7905150171 7905150173	50-312 50-397	
DYER,JA DYER,JA	7905020423 7905090135	50-369 50-338		ENGELKEN, R H. ENGELKEN, R H	7905040121	50-528	
DYER, J. A	7905240534	50-339		ENGELKEN, R H	7905040123 7905040125	50-133 50-344	
EAGLETON, T F	7905250160 7905020212	50-483	7909250140	ENGELKEN, R H ENGELKEN, R H	7905040128 7905040130	50-206	
EARLY,P J Early,P J.	7905040505	50-333		ENGELKEN, R H	7905040134	50-312 50-397	
EARLY, P. J	7905040513 7905080565	50-286 50-333		ENGELKEN, R. H. ENGELKEN, R. H	7905150136 7905150141	50-528 50-133	
EARLY, P. J. Early, P. J	7905090315 7905090343	50-333 50-333		ENGELKEN, R H.	7905150142	50-344	
EARLY, P. J.	7905100186	50-286		ENGELKEN, R H ENGELKEN, R H,	7905150145 7905150150	50-206 50-397	
EARLY, P. J. EARLY, P. J.	7905100175 7905100179	50~333 50~333		ENGELKEN, R H ENGELKEN, R, H	7705010013	50-312	
EARLY, P J	7905140307	50-333		ENGELKEN, R H.	7905010015 7905010016	50-397 50-528	
EARLY, P. J. EARLY, P. J	7905150452 7905220380	50-333 50-286		engelken, R. H Engelken, R. H	7905010020 7905010023	50-206 50-133	
EARLY, P. J. EARLY, P. J.	7905190073	50-333		ENGELKEN, R H	7905010025	50-361	
EARLY, P J	7905230430 7905240697	50-333 50-333		ENGELKEN, R. H. ENGELKEN, R. H.	7905010027 7905030018	50-344 50-397	
EARLY, P. J. EASTMAN, P. H	7905310443 7905240604	50-286 50-284		ENGELKEN # H.	7905030024	50-206	
EBERT, D D	7905010547	30-77		ENGELKEN, R H. ENGELKEN, R H	7905030028 7905030030	50-312 50-344	
EBERT, R. EBNETER, & D	7905290589 7905100433	50-367		ENGELKEN, R. H ENGELKEN, R. H	7905030045	50-133	
ENNETER, 8 D	7905290132	50-277		engelken, r. h	7905030050 7905040497	50~520 50~344	
т т н.	7905150620 7905010471	50-528 50-302		engelken, R. H Engelken, R. H	7905040507 7905040508	50-528 50-133	
	7905240821 7905290098	50-400 50-400		ENGELKEN, R. H.	7905040509	50-275	
E	7705140330	50-217		ENGELKEN, R. H. ENGELKEN, R. H.	7905040511 7905040512	50-206 50-361	
	7905220064 7905240879	50~556 50~556		ENGELKEN, R H ENGELKEN, R. H	7905040515	50-312	
	7905230567			ENGELKEN, R. H.	7905040516 7905040614	50-397 50-528	
	7905220089 7905240776	50-123		engelken, R. H. Engelken, R. H.	7905040616 7905040619	50-344 50-206	
₩. ₩	7705020241	50-424		encelken, R. H	7905040622	50-312	
•	7 <b>90523</b> 0398 7905090226	50~424 50~320	8ECY-A-78-49	ENGELKEN, R. H. ENGELKEN, R. H	7905040625 7905070098	50-397 50-528	
	7905090221 7905090225	50-320 50-320		ENGELKEN, R. H.	7905070099	50-133	
	7705090230	50-320		engelken, R. H Engelken, R. H.	7905070102 7905070104	50-344 50-206	
H,	7905090232 7905210062	50-320 50-320		ENGELKEN, R. H. ENGELKEN, R. H	7905070108	50-312	
н.	7905190064	<del></del>		ENGELKEN, R. H.	7905070110 7905030286	50-397 50-526	
	7905110039 7905110114	50-312 50-312		engelken R H. Engelken R. H.	7905030288	50-133	
	7905140287	50-524		ENGELKEN, R. H	7905030291 7905030293	50~275 50~344	
	7905150119 7905230849			ENGELKEN, R, H ENGELKEN, R. H.	7905030296 7905030299	50-361	
	7903240990 7905140112	#0.00°		ENCELKEN, R. H.	7905030300	50-206 50-312	
	7903110193	50-320 50-320		ENGELKEN, R. H. ENGELKEN, R. H.	7905030305 7905020525	50-397 50-528	
	7905090219 7905040604	50-320 50-263		ENGELKEN, R, H.	7905020527	50-133	
	7905150561	50-445		ENGELKEN, R. H ENGELKEN, R. H.	7905020529 7905020532	50-344 50-206	
	7905220090 7905140222	50-123 50-445		ENGELKEN, R. H. ENGELKEN, R. H.	7905020535	50-312	
	7905290503			ENGELKEN, R. H.	7905020536 7905010420	50~397 50~528	
						_	

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
ENCELKEN, R. H ENGELKEN, R. H	7905010422 7905010425	50-344 50-133		FASANO, A N FASANO, A N	7905300752 7905290137	50-311 50-309	
ENGELKEN, R H	7905010425	50-206		FAULKENBERRY, B	7905150539	50-312	
ENGELKEN, R H.	7905010437	50-312 50-397		FAY, C W FAY, E B	7905300453 7905160046	50-301 50-320	
ENGELKEN.R H	7905010439 7905060365	50-528		FAZIO, V	7905100166	50-320	
ENGELKEN, R H ENGELKEN, R H	7905080344 7905080348	50-275 50-133		FECYCH, W FEIT, R	7905090331 7905170277	50-20	
ENGETKEN'S H	7905080369	50-344		FEIT, R	7905240264		
ENGELKEN, R. H ENGELKEN, R. H	7905080371 7905080374	50-206 50-312		FELDMAN, 8. M FELTON, J. M	7905230124 7905100045	50-320	
ENGELKEN R H	7905080378	50-397		FELTON, J M	7905140194 7905220429	50~320 50-320	
ENGELKENIR H	7905010442 7905010444	50-526 50-133		FELTON, J M. FELTON, J M.	7705220056	JO DEG	
ENGELKEN R H.	7905010445	50-344 50-206		FELTON, J. M FELTON, J. M.	7 <b>90</b> 5020059 7905010460	50-320	
ENGELKEN, R. H ENGELKEN, R. H	7905010449 7905010450	50~312		FELTON, J M	7905010024	50-498	
ENGELKEN, R. H ENGELKEN, R. H	7905010452 7904300484	50-397 50-320		FELTON, J. M. FELTON, J. M	7905010657 7905020052	50-320 50-320	
ENGELKEN, R H	7905010456	50-528		FELTON, J M	7905010652 7905020084		
ENGELKEN, R. H ENGELKEN, R. H	7905010458 7905010460	50-344 50-312		FELTON, J. M FELTON, J. M	7905020074		
ENGELKEN, R. H	7905010462	50~206		FELTON, J M FELTON, J M	7905090034 7905140184		
ENGELKEN, R. H ENGELKEN, R. H	7905010463 7905020227	50-397 50-133		FELTON, J M.	7905090030		
ENGELKEN, R. H ENGELKEN, R. H	7905090038 7905090039	50~528 50~344		FELTON, J M FELTON, J M	7905080031 7905090013		
ENGELKEN R H	7905090041	50-204		FELTON; J. M FELTON; J. M	7905140197 7905140102		
ENCELKEN, R. H ENCELKEN, R. H	7905090045 7905090047	50-312 50-397		FELTON, J M	7905140155	50-115	
ENGELKEN, R H.	7905020256	50-275		FELTON, J M FELTON, J M.	7905140180 7905140530	50-266	
ENGELKEN, R. H. ENGELKEN, R. H	7905090053 7905090054	50-528 50-344		FELTON, J K	7905140160 7905140525		
ENGELKEN, R H	7905090057	50-206 50-312		FELTON, J M FELTON, J M	7905140537	50-320	
ENGELKEN, R H. ENGELKEN, R H.	7905090058 7905090059	50-397		FELTON, J K. FELTON, J M	7905230115 7905140509	40-2407	
ENGELKEN: R. H ENGELKEN: R. H	7905310012 7905040359	50-361 50-320		FELTON, J M	7905150528		
ENGELKEN, R H.	7905070025	50-528		FELTON, J K FELTON, J M	7905230400 7905300389		
ENGELKEN,R H Engelken,R H	7905070028 7905070031	50~344 50~204		FELTON, J M	7905300379 7905310067	50-320 50-320	
ENGELKEN, R H	7905070033	50-312		FIELDER, J	7905060370	50-259	
ENGELKEN, R. H. ENGELKEN, R. H.	7905070034 7905040355	50-460 50-528		FIELDER.J. FIELDER.J	7905080394 7905080430	50-257 50-321	
ENGELKEN, R H	7905070007 7905070010	50~193 50~344		FIELDER. J	7905080432	50-321	
ENGELKEN, R. H.	7905070012	50-206		FIELDER, J. FIELDER, J.	7905080474 7905080476	50-302 50-302	
ENGELKEN, R. H EKGELKEN, R. H	7905070015 7905070018	50-312 50-460		FIELDER, J	7905100314 7905100307	50-250 50-250	
ENGELKEN: R. H	7905170072	50-133 50-397		FIELDER, J. FIELDER, J	7905100309	50-335	
ENGELKEN, R. H. ENGELKEN, R. H.	7905310037 7905310044	50-204		FIELDER, J FIELDER, J	7905100311 7905300301	50-335 50-250	
ENGELKEN, R. H ENGELKEN, R. H.	7905310050 7905310053	50-312 50-344		FIELDER, J	7905300311	50-250 50-445	
ENGELKEN, R. H	7905310059	50-528		FIKAR, L. F FINFROCK, I R	7905140224 7905070466	50-363	
ENGELKEN, R. H ENGELKEN, R. H	7905240651 7905240657	50-275 50-460		FINFROCK. I R	7905300733 7905070633	50-219 50-219	
ENOLEKEN, R. H.	7905090005	50~133 50~528		FINFROCK, I.R FINFROCK, I R	7905040478	50-219	
ENGLEKEN: R H ENGLEKEN: R H.	7905090115 7905090116	50-344		FINFROCK, I R. FINFROCK, I R	7905140241 7905150470	50-219 50-219	
ENGLEKEN, R. H. ENGLEKEN, R. H	7905090119 7905090120	50~206 50~312		FINFROCK, I R.	7905150275 7905240347	50-219 50-219	
ENGLEKEN, R. H.	7905090121	50-397 50-290		FINFROCK, I R FINFROCK, I R	7905210210	50-219	
ENNIS, E. R Epperson, L. M.	7905010567 7905250512			FINFROCK.I.R FINFROCK.I R	7905210274 7905220381	50-219 50-219	
ERB.C. M	7905240748 7905140239	50-456 50-280		FINFROCK, I R	7905210174	50-219 50-219	
ERLEWINE, J A ERVIN, A. M	7905170269	50-260	NEDO-24169A	FINFROCK, I R FINFROCK, I.R	7905220088 7905290014	50-219	
E8810, T. H E8810, T. H.	7905090131 7905230442	50-282 70-1309		FINFROCK, I R. FINFROCK, I R	7905290023 7905290164	50-219 50-219	
E8810, T. H	7905150820 7905240454	50-315 50-10		FINFROCK, I R.	7905210265	50-219 50-219	
EBBIO, T. H. ETHEREDGE, L.	7905300383	50~320		FINFROCK, I.R FINFROCK, I.R.	7905210267 7905290351	50-219	
ETHEREDOE, L ETHERINGTON, H	7905300385 7905140031	50-320 50-320		FINFROCK, I.R	7905290394 7905290178	50-219 50-219	
ETHERINGTON, H.	7905140034	50-320		FINFROCK, I R FINFROCK, I.R	7905290194 7905290172	50-217 50-217	
ETHER INGTON, H. ETHER INGTON, H	7905160250 7905290262			FINFROCK, I R. Fink, J K	7905110146		
ETHER INGTON, H	7905190235 7905300215	50-320 50-510		FINKEL, A. E	7905290132 7905150754	90-277 70-1308	
EYANB, R. EYANB, D. J.	7905150232	50-369 50-346		FINLEY, A. Q FINN, J A.	7905150646	70-1379 50-546	
EVANBID.J. EVANBID J.	7905240978 7905100249	50-34B		FICRELLI.G. FICRELLI.G	7905020521 7905090386	50~546	
EVANS, D J	7905230622 7905240863	50-250		FIORELLI.G.	7905030054 7905020172	50-373 50-329	
EVANS. D. J. EVANS. C. A.	7705230268	50-285		FIORELLI,Q. Fiorelli,Q.	7903020461	50-500	
EVRAETS, J C	7905150730 7905230577			FIORELLI,0	7905040347 7905230302	50-341	
EVRAETS, J G EWALD, B. C.	7905010207	50-124 70-27		FIORELLI,0. FIORELLI,0.	7905290048 7905290330		
EWING, J. F. EHING, T. N.	7905040114 7905250029	° 50-556		FIORELLI, Q. FIORELLI, Q.	7905080204	50-331	
EHING, T. N	7905230424 7905240393	50-556 50-556		FIORELLI, Q	7905150410 7905150529	50-358	
ewing, T. N. Eybymontt, O	7905110209	50-320 50-320		FIORELLI,O FIORELLI,O.	7905250283	50-329	
EYBYMONTT, O FAHRNER, W. J	7905220445 7905090351	50-341		FIORELLI, O. FIORELLI, G	7905070009 7905080024	50-341	
FAIN, T. Q.	7905290399 7905310111	50-390 50-466	WM28-1-85-101	FIORELLI	7905240549 7905240724	50-327	
Fainter, J. H. Fainter, J. H	7905140060	50-466	BAH-10085 R3	FIORELLI, Q. FIORELLI, Q.	7905290554	50-155	
FAIRBROTHER, D.	7905030205 7905080405		WITH AWMEN IN	FIORELLI, G FIORELLI, G	7905290699 7905240749	50-456	
FARMER: H S FARRIS: J R.	7905290273	50-556 50-556		FIORELLI.O.	7905240711 790514009	50-373	
FARRIS, J. R. FARRIS, J. R.	7905140547 7905140550	50~554		FIORELLI.G FIORELLI.G	790514010	50-358	
FARRIS, J. R.	7905240924 7905040156	50-556 50-387		FIORELLI.0	790511010	, 10-070	
FABANDIA N.							

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION REMUN	DOCKET NUMBER	REPORT NUMBER
FIDRELLI.0 FIDRELLI.0	7905100354 7905110097	50-346 50-346		OARCIA, O	7905240632 7905240256	71-216 50-275	
FIORELLI.O FIORELLI.O	7905110092 7905110089	50-346 50-346		GARNAJ GARNETTAH,	7905250542 7905310397	40-8698 50-556	
FIGRELLIO FISCHER, B R	7905250266 7905190158 7905230486	50~331 50~320 50~320		QARRETT,E Q QARRETT,B H QARRETT,H	7905300355 7905250357 7905090184	50-344 50-445	
FISCHER, S FISHBACK, N FISHER, W.L	7905250060 7905030046	50-250 50-155		GARY, R. J GARY, R. J	7905240196 7905300761	50-445 50-445	
FISHER, W L FISHER, W L	7905010140 7905230424	50-266 50-331		CARY, R J CARY, R. J	7905290648 7905030365	50-445 50-445	
FITZBIMMONS, T R FLANNIGAN, R D	7905020270 7903140336	71-4387 50-298		QARY,R J QAVIGAN,F X	7905210192 7905140321	50-445	
FLEISCHAKER, D S FLEISCHAKER, D S	7905030166 7905030174	50-275 50-275		GAVIGAN, F X GAY, O M	7905230778 7905090154	50-445	
FLEIBCHAKER,D8 FLEMING,BT	7905310104 7905040070	50-275 50-213		GAY, Q M GEHR, A C	7905240115 7905100002	50-445 50-592	
FLNFROCK, J R FLONHAY, H	7905070470 7905070462	50-363 50-271		GEHR, A.C. GEDROE, H.H.	7905300007 7905150417	50-275 50-382	
FLYNN,P.	7905080453 7905250438	50-241 50-329		GEORGE, K. D. GEORGE, K. D	7905010531 7905010495	50-54 50-54	
FLYNN, P FLYNN, P.	7905240891 7905240899	50-329 50-329		GERAG.T GERETY.H F	7905100163 7905220362	50-10 50-320	
FLYNN, J. D FOLEY, R, T	7905300284 7905090417	50~358	NUREG/CR-0754	OETTY, B C OIBBONS, T D	7705140304 7705240307	50-133 50-327	
FOLEY.T. FONTANTA,L FORD,D F.	7905110394 7905290151 7905300619	50-27 i 50-382		OIBBONS, T. D OIBBON, T OIBBON, T	7905290117 7905160154 7905160184	50-395 50-320 50-320	
FORD, M R FOREMAN, H	7905290498 7905140565	50-382	7905290498	T WORETO	7905160125 7905160125	50-320 50-320	
FORTER, H. FORTER, H	7905140321 7905100419	70-1151 70-1151		GIBBON, T	7905160110 7905160003	50-320 50-320	
FOSTER, H FOSTER, S. C	7905140315 7905210125	70-1151 50-255		T, NOBBIO	7905160049 7905100147	50-320 50-255	
FOSTER, E R FOUCHARD, J J	7905150439 7905230242	50-423 50-320		GIBBB.M E	7905250238 7905250163	50-329 50-329	
FOUCHARD, J J FOULSHAM, P A	7905020163 7905290208	50-320 50-273		01888, M E 01860N, A F	7905290540 7905290142	50~329 50~338	
FOX.H S FOX.H S	7905090314 7905110196	50-259 50-296		OIBEON, C I	7905100243 7905190061	50-320	7905100243
FOX.H S FOX.H S	7905110313 7905230078	50-260 50-260		GIBSON, A F Gibson, A F	7905010207 7905230679	50-124 50-338	
FOX.H, 8, FOX.H 8	7905310362 7905310425	50-260 50-296		GIBSON, A F GIBSON, A F	7905230623 7905241005	50~261 50~25	
FOX.H S FOX.B	7905310368 7905160364	50-260 50-305		GIBSGN, A. F Gibseke, Ja	7905070101 7905150140	70-1113	7905150140
FOX.T D FRALEY.R.F	790503024 <i>6</i> 7905140037	50-320	NUREG/CR-0523	GIGLIGTTI,R GIGLIGTTI,R.J	7905150628 7905250532	70-820 70-820	
FRALEY, R F FRALEY, R F	7905040201 7905140014	50~10 50~320		GILBERTSON, L A. GILBERT, Y K	7905030205 7905040098		BAW-10085 R3
FRANKLIN, W. J.	7905230477 7905230624	50-466 50-445		GILINSKY.V	7905150550 7905090111	50-382	
FRANKLIN, W. J. FRANKLIN, W. J.	7905240248 7905240824	50-498 50-498	r	OILINSKY. V	790511020B 7905020024	50-320	
FRANSEN, C. D FRANTZI J. R	7705300523 7705100104 7705010032	50-360 71-127		OILINSKY, V.	7905230220 7905110224	80-320	
FREEDKIN, S FREEMAN, M D FREEMAN, M D	7905250056 7905250538	40-8064 40-8064		OILINSKY, V	7905110253 7905110246 7905110182	50-320 50-320	
FREIDHEIM, J W FRIEDMAN, L F	7905300531 7905100374	30-8535		GITINSKA'A GITINSKA'A GITINSKA'A	7905020046 7905080070	20-320	
FRILING, R. FROGGE, J. L	7905250471 7905150706	50-272		OILINSKY, V.	7905110198 7905140171	50-320 50-320	•
), R J, K	7905070647 7905230637	50~272 50~267		OILINSKY, V. GILINSKY, V	7905140175 7905100020	50-320 50-320	
JK IDER. S. P	7905030321 7905100332	50-267 50-592		GILINSKY, V GILINSKY, V.	7905080125 7905030055	50-320 50-320	
	790515055B 7905150559	50-293 50-293		OILINSKY, V.	7905110179 7905300345	50-320	
		50-293 50-466	•	OILINSKY, V. OILINSKY, V.	7905150003 7905220079		
		50-275		OILINBKY, V.	7903290008 7903190233	50-320	
		50-324 50-324		GIFINBKA'A	7905290003 7905290031	50-219 50-309	
		50~261 50~325 50~324		GILINSKY, V.	7905190127 7905170252	50-320 50-315 50-316	
		50-324 50-325		OILLETT, W T OILLELAND, J. E. OILLELAND, J. E.	7905170262 7905160455 7905140496	50-316 50-327 50-327	
		50-325 50-325		QILLELAND, J. E. QILLELAND, J. E.	7905140444 7905140478	50-327 50-518	
		50-325 50-324		OILLELAND, J. E. OILLELAND, J. E.	7905290115 7905140352	50-327	
		50-261 50-261		GILLELAND, J. E. GILLELAND, J. E.	7905230733 7905080176	50-566 50-259	
		50-261 50-261		GILLELAND, J. E. GILLELAND, J. E.	7905140468 7905140490	50-327 50-390	
		50-324 50-325		OILLELAND, J.E. OILLELAND, J.E.	7905140458 7905140495	50-327 50-327	
		50-27		GILLELAND, J E. Gilleland, J E.	7905140503 7905250344	50~390 50~259	
		50-267 50-267		GILLELAND, J E. GILLELAND, J E	7905010481 7905010518	50-390 50-390	
		50-267 50-267		Gilleland, F. E.	7905240972 7905010564	50-25 50-390	
		50~267 50-267 50-267		OILLELAND, J. E. OILLELAND, J. E.	7905300745 7905030343	50-259 50-259	
		50-463		GILLELAND, J. E. GILLELAND, J. E.	7905040348 7905300253 7905040345	50-390 50-327	
		30-329 50-556		GILLELAND, J. E GILLELAND, J. E GILLELAND, J. E	7905040345 7905040562 7905010475	50-553 50-327 50-239	
		50-556	NUREG/CR~0454	gilleland.j, e gilleland.j e gilleland.j, e	7905010475 7905070420 7905090333	50~259 50~327 50~327	
		71-216		OILLELAND, J E	7905090334	50-327 50-327	

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	report Number	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT REMNA
GILLELAND, J E	7905240652	50-259		90881CK, L. V	7905240202	#0 nan	
GILLELAND.JE GILLELAND.JE	7905080541 7905110177	50~518 50~259		GOSSICK'F A	7905090243 7905250089	50-320 50-492	
GILLELAND, J E. GILLELAND, J E.	7905110191 7905110225	50~327 50~370		GOSSICK, L V.	7905290483 7905240265	50-250 50-275	
GILLELAND, J E.	7905110228 7905090341	50-370		COSSICK'F A	7905240334	50-454	
GILLELAND, J E	7905110211	50-327 50-276		GOSSICK'F A	7905240509 7905160052	50-450 50-320	
GILLELAND, J E. GILLELAND, J E	7905140270 7905140272	50-553 50-327		90881CK, L V 9000E, M J.	7905240609 7905230753	50-219 50-566	
GILLELAND, J E	7905140371 7905110008	50-259 50-327		GRACE, J G	7903230153 7905150026	50-387 71-286	
GILLELAND, J E.	7905110024	50-259		ORACE.J O	7905150027	71-284	
GILLELAND, J E GILLELAND, J E	7905150322 7905160317	50-296 50-390		GRACE, R H GRAHAM, N E	7905010506 7905040599	50-271 50-324	
OILLELAND, J E OILLELAND, J E	7905190197 7905150286	50-327 50-518		GRAHAH.H.E GRAHAH.H.E	7905040607 7905140337	50-324 50-261	
O(LLELAND, J E.	7905140303 7905190217	50-327 50-390		GRAHAM, P. D. GRANT, J	7905150523 7905250307	50-277	
OTLLELAND, J E. OTLLELAND, J E.	7905170268	50-260		GRANT, J 8	7905110099	50-346	
OTLLELAND, J E. OTLLELAND, J E	7905230378 7905230562	50-260 50-327		GRANT, J E	7905110091 7905150121	50-346 50-346	
OILLELAND, J E.	7905230381 7905230519	50-390 50-327		B L.TMARD B L.TMARD	7905240097 7905250198	50-346 50-346	
OILLELAND, J E	7905230548 7905230645	50-436 50-327		GRANT.J 8 GRANT.W B	7905150402 7905240454	50-344 50-10	
OILLELAND, J E	7905300462	50-516		GRABHAW, T. D	7905100365	71-305	
OILLELAND, J E	7905290363 7905290390	50-327 50-390		GRASHAW.T D GRASSO.E	7905100361 7905300647	71-305 50-245	
QILLELAND, J E QILLELAND, J E	7905310314 7905300305	50-327 50-327		GRAVES,R H GRAVES,R H	7905040061 7905210211	50-213 50-218	
OILLESPIE, F P	7905230641	50-302		GRAVES,R H GRAY,R	7905310446 7905250495	50-213 50-546	
OILLESPIE, F. P. OILLESPIE, F. P.	7905240336 7905240312	70-1151 70-1151		GRAY, J R	7905100208	50-344	
OILLESPIE, F P.	7905230689 7905020087	70-143 50-269		GRAY.J R Gray.J R	7905070147 79051400[3	50-344 50-320	
OILLESPIE, F P OILLESPIE, F P	7905150114 7905070283	70-1201 70-1151		ORAY, J.R ORAY, J.R	7905250030 7905160158	50-344 50-320	
OILLESPIE, F P.	7905300021	70-1201		GRAY, J. R. GRAY, J. R	7705250148 7705250153	50-344 50-463	
OILMAN,O OILRAY,J	7905250233 7905230287	50-336 50-320		QRAY, J R	7905150114	50~463	
GLAGOLA: A. F. GLAGOLA: A. F.	7905250299 7905020469			GRAY.J.R. Gray.J.R	7905150811 7905230246	50~344 50~463	
CLACOLA A F	7905140059 7905300178			GRAY,J R. Gray,J R	7905240989 7905100110	50-548 50-548	
CLACOLDIA F.	7905290231			GRAV.J R	7905140280 7905240224	50-524 50-344	
GLAGOLA, A.F. GLAGOLA, A.F.	7905300228 7905300269			GRAY, J R GREENE, T V	7905010470	50-366	
QUAQOUA, A.F. QUECKHAN, D	7905300290 7905040299	50-320		GREENE.T V.	7905080530 7905150549	50-321 50-321	
CODDARD, R J	7905300711 7905230846	50-275 50-237		GREENE,T V GREENE,T V	7905300638 7905300688	50-321 50-321	
ÇODDARD, R. J	7905070154	50-275		GREENE, T. V. GREENMAN, E O	7905300603 7905290120	50-321 50-277	
ÇODDANDIR J. ÇODDANDIR J	7905240995 7905250258	50-295 50-237		GREENMAN, E O	7905150523	50-277	
CODDARD, R. J. COEBEL: O R.	7905100121 7905090422	50-295	NUREO/CR-0642	OREER,R J ORECER,L R.	7905150820 7905010160	50-315 50-266	
<b>QOLDBERO, R</b> <b>QOLDBERO, B. C</b>	7905100217 7905030209	50-348 50-338		OREHER.E ORIDLEY.R L	7905230171 7905090275	50-320 50-183	
COLDBERG, S. C	7905300722 7905100137	50-250 50-338		ORIDLEY.R L Grier.b H	7905160441 7905300122	50-320	
COLDBERG.S C	7905240286	50-502		GRIER, B H GRIER, B, H	7905010100 7905010101	50~293 50~317	
COLDBERG.S.C.	7905250347 7905030207	50-295 50-338		GRIER. B H	7905010103	50-213	
OOLDBERG, J. R.	7905020316 7905240502	50-592 50-592		GRIER, B. H. Grier, B. H	7905010105 7905010106	50-334 50-412	
QQLDBEFQ, J.	7905100138 7905150788	71-9120		GRIER, BH Grier, BH,	7905010110 7905010112	50-219 50-363	
OOLDSMITH, R	7905140136	50-320		ORIER, B. H ORIER, B. H	7905010116 7905010118	50-322 50-289	
QOLDSMITH, R	7905140132 7905140129	50-320 50-320		ORIER, B H.	7905010119	50-309	
COLDSMITH, R.	7905140134 7904180377	50-320 50-320		GRIER, BH. Grier, BH.	7905010121 7905010125	50-245 50-410	
OOLDSHITH, R.	7904270088 7905090231	50-320 50-320		GRIER.B H Grier.B.H.	7905010126 7905010127	50-220 50-333	
GONTALES, S	7905240078	70-93 27-89		GRIER, B H GRIER, B H	7905010129 7905010131	50-286 50-277	
COOPHIDEE, A. C. COOPHIN, H. L.	7905240579 7905020150	70-1151		orier. B. H.	7905010134 7905010134	50-352 50-387	
COODMIN.C.	7905290078 7905150812	50-344 50-344		ORIER, B. H. ORIER, B. H.	7905010139	50-272	
COODMIN.C	7905240908 7905020478	50-344 50-344		ORIER. B. H Orier. B. H.	7905010140 7905010143	50-311 50-443	
9000H1N/C	7905030361	50-344 50-344		GRICA, E H Griir, E H.	7905010145 7905010148	50-465 50-244	
GOODHING. GOODHING	7905230492 7905230407	50-344		GRII R. B. H.	7905010130 7905010152	50-271 50-29	
COONEY M J.	7905150443 7905150047	50-277		GRIER, B. H Grier, B.,H.	7905030266	50-293	
GOPPEL.H.	7905300727 7905070042			ORIER B. H.	7905030270 7905030272	50-317 50-3	
CORMAN-H.C COSSICKIL, V	7905150734 7905150679	70-1821		GRIER, B. H. Grier, B. H.	7905030276 7905030279	50-266 50-266	
QOSSICKIL Y.	7905300079	50-320		GRIER, B. H. Grier, B. H	7905030281 7905010034	50-29 50-293	
OOSSICKILV.	7905300085 7905300089	50-320 50-320		GRIER, B H	7905010036 7905010040	· 50-317 50-213	
OOSSICKIL, V.	7905190198 7905300302	50~320		Grier, B. H Grier, B. H.	7705010042	50-334	
QOSSICKIL V.	7905140110	50-320 50-483		Grier, B. H. Grier, B. H	7905010046 7905010047	50-219 50-269	
OOSSICK,L.V.	7905020210 7905140291	50~463		GRIER, B. H. GRIER, B. H	7905010050 7905010053	50-309 50-245	
GOSSICKIL V. GOSSICKIL V.	7905010554 7905090260	50-320		GRIER, B. H	7905010055 7905010058	50-286 50-220	
COSSICKIL V. COSSICKIL V.	7905300100 7905300105	50-320 50-320		GRIER, B. H. GRIER, B. H.	7905010060	50-333	
GOSSICKIL V. GOSSICKIL V.	7905010041 7905080190			ORIER, B. H. Orier, B. H.	7905010045 7905010049	50-277 50-272	
GOESICKIL V.	7905230533			ORIER, B. H	7905010073	50-244	



AUTHOR	ACCEBBION NUMBER	DOCKET	REPORT NUMBER	AUTHOR	ACCEBSION NUMBER	DOCKET NUMBER	REPORT NUMBER
ORIER, B H	7905010075	50-271		ORIER. B H	7905040183	50-3 50-213	
ORIERIB H ORIERIB, H	790501007 <i>7</i> 7905010080	50-29 50-364		GRIER. B H Grier. B H	7905040188 7905040198	50-334	
ORIER, BH ORIER, BH	7905010002	50-201		ORIER, B H Orier, B H	7905040200 7905040204	50-412 50-219	
ORIER, B H	7905010086 7905010282	70-1143 50-293		GRIER, BH	790504020B	50-322	
ORIER, BH.	7903010286 7903010290	50-317 50-213		ORIER.B.H. Orier.B.H	7905040210 7905040211	50-289 50-309	
GRIER, B H	7905010297	50-334		ORIER.B.H	7905040214	50-336	
GRIER.8 H GRIER.8 H	7905010298 7905010300	50-219 50-289		ORIER.B H Orier.B H	7905040224 7905040235	50-245 50-410	
ORIER.B H ORIER.B H	7905010301 7905010304	50-309 50-336		GRIER, B. H. Grier, B. H.	7905040237 7905040245	50-220 50-286	
GRIER, B H.	7905010307	50-220		GRIER, B H Grier, B. H	7905040249 7905040259	50-333 50-277	
ORIER.B.H. ORIER.B.H	7905010310 7905010313	50-333 50-284		ORIER.B H	7905040264	50-352	
ORIER, BH ORIER, BH	7905010315 7905010320	50-27 <i>7</i> 50-272		GRIER, B H Grier, B H	7905040269 7905040273	50-387 50-272	
ORIER.B H.	7905010322	50-244		GRIER, B. H Grier, B. H	7905040282 7905040284	50-311 50-443	
ORIER B H ORIER B H	7905010326 7905010327	50-271 50-29		GRIER, B H	7905040295	50~465	
GRIER.B H Grier.B H	7905190194 7905190098	50-320 50-320		GRIER, B H. Grier, B H.	7905040297 7905040301	50-271 50-27	
ORIER, B H	7705210095	50-320		GRIER, B H Grier, B H	7905140103	50-272 50-320	
ORIER, B H	7905210097 7905210102	50-320 50-320		GRIER, B H	7905300187 7905010079	50-3	
ORIER.B H	7905020026 7905020030	50-293 ` 50-317		ORIER, B H Orier, B H.	7905030052 7905030054	50-293 50-317	
ORIER, B H	7905020036	50-213		GRIER, B H Grier, B H	7905030059 7905030060	20-513	
ORIER, BH.	7905020039 7905020043	50-334 50-412		ORIER, BH	7905030063	50-334 50-412	
GRIER, B. H GRIER, B. H	7903020045 7903020051	50-219 50-322		GRIER, B H GRIER, B, H	7905030064 7905030065	50-219 50-363	
CRIER, BH	7905020053	50-269		GRIER, B H	7905030070	50-322	
ORIER.B H ORIER.B H	7905020055 7905020061	50-309 50-336		GRIER, B H, Grier, B H	7905030072 7905030075	50-289 50-309	
GRIER, B. H Orier, B. H	7905020066 7905020069	50-245 50-220		ORIER, B H. Orier, B H	7905030077 7905030078	50-245 50-220	
GRIER, B. H	7905020071	50-410		GRIER. B H	7905030081	50-410	
ORIER, B. H. ORIER, B. H.	7905020072 7905020075	50-333 50-284		ORIER, B H ORIER, B H	7905030083 7905030084	50-333 50-284	
ORIER, B. H ORIER, B. H	7905020077 7905020082	50-352 50-277		GRIER, B H Grier, B H	7905030086 7905030088	50-352 50-277	
ORIER B H,	7905020085	50-387		GRIER, B H	7905030093	50-387	
GRIER, B. H. Grier, B. H.	7905020095 7905020100	50-272 50-311		GRIER, B H Grier, B H	7905030098 7905030101	50-272 50-311	
GRIER, B. H GRIER, B. H	7905020103 7905020104	50-443 50-244		GRIER, BH. Grier, BH.	7905030105 7905030108	50-443 50-244	
ORIER, S H	7905020111	50-485		ORIER, B H	7905030110	50-485	
GRIER, B H Grier, B, H	7905020113 7905020116	50-271 50-27		ORIER, B H Orier, B H	7905030111 7905030112	50-271 50-29	
GRIER, B. H Grier, B. H	7905210046 7905020295	50-286 50-286		GRIER, B H Grier, B H	7905010632 7905010633	50-293 50-317	
ORIER, B. H	7905020300	50-245		GRIER, B H.	7905010636	50- <b>3</b>	
ORIER, B. H. Orier, B. H	7905020308 7905020311	50-271 50-27		ORIER, B H Orier, B H	7905010439 7905010641	50-247 50-213	
ORIER, B. H. ORIER, B. H	7905020315 7905020321	50-244 50-333		ORIER, B. H. Orier, B. H	7905010643 7905010645	50-334 50-412	
GRIER, B. H. Grier, B. H	7905020323	50-277		GRIER, B. H	7903010646	50-219	
ORIER, B. H	7905020329 7905020332	50-410 50-220		QRIER, B. H. Grier, B. H.	7905010650 7905020263	50-343 50-322	
ORIER, B.H. ORIER, B.H	7905020337 7905020342	50-219 50-309		ORIER, B. H. Orier, B. H.	7905020275 7905020278	50-287 50-307	
GRIER, B. H Grier, B. H	7905020346 7905020350	50-334 50-3		ORIER, B. H. Orier, B. H.	7905020284 7905020288	50-245	
GRIER, B, Ĥ,	7905020354	50-213		GRIER, B H	7905020292	50-220 50-410	
ORIER, B. H ORIER, B. H,	7905020357 7905020360	50-293 50-485		GRIER, B H Grier, B H,	7903020294 7903020298	50-333 50-286	
ORIER, B H ORIER, B, H	7905020364 7905020369	50-443 50-311		ORIER, B. H. Orier, B. H.	7905020305 7905020309	50-352 50-277	
GRIER, B H	7905020372	50-352		GRIER, B H	7905020314	50-387	
ORIER, B. H. Orier, B. H.	7905020377 7905020389	50-287 50-317		GRIER, B. H Grier, B. H	7905020317 7905020322	50-272 50-311	
GRIER, B. H. Grier, B. H.	7905020393 7905020395	50-343 50-322		GRIER, BH, GRIER, BH	7905020324 7905020331	50~443 50-485	
QRIER, B. H	7905020398 7905020402	50-412		ORIER, B. H.	7905020335	50-244	
ORIER, B. H. ORIER, B. H	7905030324	50-397 50-273		GRIER, B. H. Grier, B. H.	7905020338 7905020341	50-271 50-29	
GRIER, B. H. GRIER, B. H.	7905030328 7905030373	50-317 50-3		GRIER, B. H GRIER, B. H	7905230334 7905230194	50-320 50-320	
GRIER, B H, Grier, B H	7903040010 7903040014	50-213 50-412		ORIER, B H ORIER, B, H,	7905230392	50-3	
ORIER, # H.	7905040018	50-334		GRIER, B. H.	7905210052 7905190066	50-320 50-21 <del>7</del>	
ORIER, B. H. Orier, B. H.	7905040020 7905040025	50-363 50-217		GRIER.B.H Griffin.B.L	7905210284 7905020291	50-320 50-302	
ORIER, B. H. ORIER, B. H.	790504003B 7905040040	50-322 50-287		GRIFFIN, B L GRIGALAUSKI, G T	7905020276	50-302	
ORIER, B H	7905040046	50-309		GRIMEB, BK	7905100094 7905090171	40-2061	
ORIER.B.H. Orier.b.H.	7905040049 7905040059	50-334 50-245		grimes, B. K Orimes, B. K	7905080239 7905110231	50-271 50-320	
ORIER, B. H ORIER, B. H.	7905040068 7905040071	50-410 50-220		ORIMES, B. ORIMES, C	7905230523 7905040150	50-320	
GRIER, B H	7905040074	50-333		GROCE, R. H	7905250456	50-219 50-309	
ORIER, B. H ORIER, B. H	7905040078 7905040083	50~286 50~352		QROCE, R. H. QROCE, R. H.	7905090330 7905080435	50-307 50-30 <del>7</del>	
GRIER, B. H. GRIER, B. H	79050400B7 7905040091	50-277 50-367		QROCE, R. H.	7905090061	70E-05	
orier, B. H	7905040093	116-06		ORDCE, R. H.	7905090372 7905150434	50-309 50-309	
GRIER, B. H. GRIER, B. H	7905040095 7905040100	50~272 50-443		GROCE, R. H GROCE, R. H.	7905210157 7905210130	50-309 50-309	
ORIER, B. H. ORIER, B. H.	7905040104 7905040109	50-485 50-244		GROCE, R. H. GROCE, R. H	7905240636	50-309	
ORIER, B. H.	7905040111	50-271		OROCE, R. H.	7905070435 7905100319	50-271 50-271	
ORIER, B. H. ORIER, B. H.	7905040113 7905040167	50-29 50-293		GROCE, R. H. GROCE, R. H.	7905290088 7905210197	50-271 50-271	
ORIER, B. H.	7905040174	50-317		GROCE, R. H.	7905030333	50-27	

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
CROCE, R. H.	7705250452	50-29		HANDRAHAN, E	7905150268	71-33	***************************************
GROCE.R. H GROCE.R. H	7905040039 7905070548	50-271 50-27		HANDRAHAN, E HANLEY, N. C	7905150274 7905070230	71-33 50-502	
CROSS.W T	7905020297			HANLEY, W C	7908310267	50-502	
Grossman, M. J. Groteniel, K.	7905080178 7905150645	50~492		H LINDNIAH H LINDNIAH	7905240102 7905230620	50-325	
CRUSKIN, B N CUIROIR, D C	7905030090	E0074		HANNON, J W.	7905150922	50-325	
SUMBLE, F W	7905070462 7905010522	50-271 50-286		HANNUM, D HANSEN, L. J.	7903170260 7905240497	50-254 71-9116	
COMBLE, F	7905090305	50-286		HANSELL, D.	7905140153	50-115	
CANNIH T.	7905110374 7905110337	50-320 50-320		HANSELL, D HANSELL, D.	7905150521 7905070364	27-39 27-39	
CORN, H T	7905110370	50-320		HANSEN, R C.	7905240301	40-8681	
CURN, H T CURN, H T	7905110367 7905110357	50-320 50-320		HANGEN, P HANSEN, P W	7905020282 7905100302	50-295 50-304	
OURN, U.T.	7905110354	50-320		HANSEN, W A.	7905250296	50-329	
CURN, U. T CURN, U. T	7905110401 7905110397	50-320 50-320		HANSTODIA A HARDINIA K.	7905160358 7905240527	50-282 50-348	
CUMPI, M. T.	7905110395	50-320		HARDWICK, T. J	7905020352	50-349	
CUM, H. T CUMI, H T	7905110392 7905110393	50-320 50-320		HARGETT, D. J. HARGETT, D. J.	7905250120 7905300200		
COMM. W T	7905110406	50-320 50-320		HARGROVES, D H	7905090401		NUREO/CR-0255
puneu, W. T puneu, W. T	7905110409 7905110405	50-320		HARMON, D W HARMON, D W	7905100264 7905180198	40-8658	
DUMN, LI T	7905110402	50-320		HARMON, D. W	7905030100		
CURN, U. T. CURN, U. T	7905110400 7905110396	50~320 50~320		HARMON, D. H. HARMON, D. H.	7905030092 7905290141		
GUNN, U T	7905110389	90-320		HARMON D F	7905230145	40-2407	
CURNIN T CURNIN T.	7905110385 7905110384	50-320 50-320		HARNON D F HARNON D F	7905230219 7905230139	40-2407 40-2407	
CURNIU T	7905110382	50-320	•	HARHON, D. F.	7905230132	40-2407	
CURNINI T CURNINI T.	7905110378 7905110376	50-320 50-320		HARPSTER, T. L HARPSTER, T. L	7905110111 7905290846	50~346 50~263	
GUNNIN T	7905110373	50-320		HARPSTER, T. L	7905240729	50-359	
CURNIN T CURNIN SI. T.	7903110368 200110967	50-320 50-320		Harris, p Harris, r,	7905240667 7905230529	50-466	
GUTTERMAN, A. H.	7905240874	50-518		HARRIS, J L	7905300058	50-346 50-445	
OUTHAN, D M 9. BAAH	7905240853 7905300438	50-389 50-320	ORNL/TM-6853	HARRIS, J.L. HARRIS, J.L.	7905100288 7905140070	50~445 50~499	
HAASS, W. P.	79051501日日			HARRIE, P B.	7905230473	50-452	
HAASS,W P	7905290006 7905020482	50-29		HARRIE, J R HARRIE, J R.	7905240509	50-424	
HAASS.N P.	7905070660	50-213		HARRIE, J R	7905070358 7905230752	50-389 50-491	
HAASS,W P HAASS,W P	7905070553 7905240337	50-29		HARTIGAN, J P	7905020330	50-346	
HAASB, W. P.	7905240411	50-397		HARTIGAN, J. P HABKIN, F. E.	7905020438 7905230496	50-346 50-320	
MASSIW P MAGAIP.B.	7905240979 7905250313	50-437		HASTINGS, H. HAUGHNEY, C. J	7905270042 7905030035	50-344 50-304	
HAGA: P. B	7905040133	50-437		HAUPTIC A.	7905250091	50~201 50~599	
HAGA, P. B. HAGA, P. B	7905190112 7905220022	50~437 50~437		HAVERKAMP, D HAWTHORNE, B	7905240437 7905090154	50~269 50-445	
HAGA, P. B.	7705310455	50-437		HANTHORNE, J. R.	7905240925	30-443	NUREQ/CR-0484
HAGANIT F HAGANIT F	7905090394 7905020177			HAYEB, D. H	7905020172	50-329	
HAGEY. H	7905030180			HAYES, D W HAYES, D W	7905020470 7905240734	50~500 50~329	
HAGEY, H HAGEY, H	7905030194 7905040024			HAYES, D. W.	7905150419	50-341	
HAGEY. H.	7905040042			HAYNES, J. Q HAYNES, J. Q	7905150374 7905110035	50-206 50-206	
HAGEY, H	7905040064 7905040079			HAYNESIR C	7905150620	50~528	
HAGEY, H.	7705240118			HAYWARD, J. HAYWARD, N	7905290161 7905250451	30-1673	
HAGEY, H.	7905240409 7905240439			HAZLE, A J Head, J. T.	7905150342 7905290069	50-206	
HAREY, H.	7905230697			HEAD, J T	7905290500	50-206	
HAGEY, H	7905240663 7905230682			HEAD, J. HEAD, J. T	7905240073 7905040586	50~206 50~206	
HAIGHT, R F	7908030231		NUREO/CR-0446	HEAD: J. T	7905110134	50-204	
Kairston, W. C. Kairston, W. C	7905140368 7905140357	50-348 50-348	•	HEAD, J. T. HEAD, J. T	7905150503 7905310439	50-206 50-206	
HAIRBTON, W. O.	7905150568	50-34B		HEDEHAN, W. N	7905090431		
Hairbton, W. Q. Hairbton, W. G	7905020249 7905230362	50~348 50~348		HEIDER,L H HEINEMANN,J M.	7905270050 7905100407	50-29 40-4602	
HAIRBTON, H. Q.	7905140311	50~34B		HEINEMAN, R.E.	7904240392		
HAIRBTON, W Q HALE, C J	7905300504 7905030150	50-34B		HEISHMAN, R.F. HEISHMAN, R.F.	7905290534 7905020202	50~263 50-315	
HALE, G, J HALE, G J	7905100346 7905290113			HEISHMANIR F	7705080084	50-255	
HALE, G. J.	7905100418			HEISHMAN, R. F. HEISHMAN, R. F.	7905010333 7905070020	50~155 50~373	
HALE, G, J, HALL, H C	7905230593 7904240395			HEISHHAN RF.	7905090165	50-331	
HALL, W. C.	7904240389			HEIBHMAN, R.F. HEIBHMAN, R.F.	7905090173 7905150159	50~409 50~156	
HALL, N. C. HALL, T. M.	7905240608 7905030231	71-5026	NUREG/GR-0446	HEIBHMAN, R. F.	7905150126	50-331	
HALL: E. E	7905030248	50-395		HEISHMAN,R.F. HEISHMAN,R.F.	7905240719 7905140084	50-358 50-295	
HALLIR.E. HALLIR E.	7905240320 7905160415	50~284 50~254	7905240320	HEISHMAN R F	7905090167	50~255	
HALLIR E.	7905300466	50-244		HEISHMAN, R. F. HEISHMAN, R. F	7905040161 7905150113	50-294 50-346	
HALLIR, E. HALLIR, B. B.	7905070495 7905140567	50-250		HETSHMAN, R. F	7905150152	50-315	
HALLIR E.	7905150570	50-556		HELDISH, J. F. HELLER, L. W.	7905090320 7905100093	50-320 50-553	
MALLIR, E. MALLIR, E	7905010312 7905010383	50~492 50~498		HELLER, L. W.	7905240249	50-452 50-269	
HALLER: N. M.	7905140073	50-320		HELMB, J. HELTEMEB, Ç. J.	7905250131 7905100117	50-584	
HALMAN, E. L. HAZMER, B. J.	7705300134 7 <del>7</del> 05080438	50-320 50-263		HENDERSON, O. K.	7905250511		
HAMMOND, E. L	7905020251	50-331		HENDRICK, W. Q. HENDRICK, W. Q.	7905310049 7905310074		
HAMMOND, E.L. HAMMOND, E.L.	7905160363 7905160386	50-331 50-311		HENDRIE: J. M	7905250169		
HANNOND, E. L.	7905210220	50-331		HENDRIE, J. M. HENDRIE, J. M.	7903140163 7903140169		
HAMMOND, E.L. HAN, B.	7905290182 7905140128	50-331		HENDRIE, J. M.	7905140174		
HANAUER, S. H.	7905210094			HENDRIE, J. M. HENDRIE, J. M.	7905150010 7905250321		
HANAUER, S. H HANAUER, S. H	7905110316 7905110355	50-320 50-320		HENDRIE, J. M.	7905290465		
HANAUER, B. H.	7905140187			HENDRIE: J. M. HENDRIE: J. H	7905090111 7905090259	50-320	
HAND, C. H.	7905100186	94E-05		HENDRIE, J. M.	7905170270	50-320	

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
HENDRIE, J H HENDRIE, J H	7905020024 7905110197	50-320 50-320		HIGGENBOTHAM, L HIGGINS, J C.	7905210060 7905240437	50-320 50-289	
HENDRIE, J H	7905110230	50-320		HILL,R M	7905250463		
HENDRIE, JM HENDRIE, JM	7905210044 7905090413	30-320		HILLYARD, H W HILLYARD, H W	7905140294 7905140323	50-267 50-267	
HENDRIE, J M HENDRIE, J M	7905230792 7905020046	50-309 50-320		HIMMELSBACH, L HINCKLEY, D Q	7905160159 7905250110	50-320 50-321	
HENDRIE, J H	7905100016	50-320		HIND: J A	7905110047	50-182	
HENDRIE, J M HENDRIE, J M	7905110190 7905140020	50-320 50-320		HIND'T Y TIND'T Y	7903160488 7905180775	50-114 50-295	
HENDRIE, J M HENDRIE, J M	790502003B 790514025B	50-320		A L.GNIH A L.GNIH	7905150297 7905150744	70-1308 70-1308	
HENDRIE, J H	7905300460			A L, CHIH	7905150754	70-1308	
HENDRIE, J K HENDRIE, J K	7905030055 7905100028	50-320		A L.GNIH A L.GNIH	7905130768 7905230206	50-273 50-10	
HENDRIE, J K HENDRIE, J K	7905110220 7905150005	50-320		HINDERSTEIN, C HINDERSTEIN, C	7905240360 7905150087	50-466 50-466	
HENDRIE, J H HENDRIE, J H	7905250195 7905150003	50~596		HINDERSTEIN. C	7905250130	50-466	
HENDRIE, J M	7905250147			HINDERSTEIN, C HINDERSTEIN, C	7905310042 7905310077	50-466 50-466	
HENDRIE, J M HENDRIE, J K	7905300543 7 <del>9</del> 05300596			HINDERSTEIN.C Hinze.W J	7905310080 7905240326	50-466	NUREQ-0382
HENDRIE, J H	790530060 <i>6</i> 7905300525			HITTLE, L O	7905150098	<b>5</b> 0 044	HOILE COUR
HENDRIE, J M HENDRIE, J M	7905300464			HJELMFIELT, D C	7905300429 7905100217	50-344 50-348	
HENDRIE, J H	7905300577 7905220079			HLUCHAN,R M HOADLEY,B D	7905240954 790530 <u>0</u> 33 <i>2</i>	50-272	
HENDRIE, J. H HENDRIE, J. H	7905290008 7905300568	50-309		HOADLEY, 8 HOADLAND, K E	7905300339 7905140570	E0-215	W.D.C. 450 . 64 M4
HENDRIE, JM, HENDRIE, JM,	7905300672 7905300681	50-309		HOCEVAR, C J	7905110223	50-219 50-320	NUREG/CR-0634
HENDRIE, J M.	7905190233	50-320		HODDER, M H HODGDON, A	790529028 <i>9</i> 7905110202	50-389 50-320	
HENDRIE, J H. HENDRIE, J H	7905290003 7905290031	50-219 50-309		HODODON, A. HODODON, A	7905110235 7905110212	50-32	
HENDRIE, J K	7905300315 7905090236	50~320		HODGDON, A	7705110249	50-320 50-320	
HENDRIE, J H HENDRIE, J H	7905300076	50-320		HODGES, J. W	7905230689 7905070283	70-143 70-1151	
HENDRIE J M	7905300094 7905300101	50-320 50-320		Hodoes, W Hodoes, W	7905070086 7905250113		
HENDRIE, J M. HENDRIE, J K	7905300103 7905300107	50-320 50-320		HOEFLING, R K.	7705090438	70-2623	
HENDRIE, J K	7905300115	50-320		HOEFLING, R K HOEFLING, R, K	7905090440 7905230766	70-2623 70-2623	
HENDRIE, J M	790530011 <i>9</i> 7905300120	50-320 50-320		HOEFLING, R K, HOEFLING, R. K	7905230775 7905310028	70-2623 50-329	
HENDRIE, J M. HENDRIE, J M.	7905300123 7905300124	50-320 50-320		HOEFLING, R K	7905080053	50~322	
HENDRIE, J M HENDRIE, J M	7905300126 7905300128	50-320		HOEFLING, R K HOFFMAN, W. C	7905250053 7905230384	50-322 50-188	
HENDRIE, J M	7905300131	50-320 50-320		HOFFMAN.D.P. HOFFMAN.D.P.	7905090172 7905240309	50-255	
HENDRIE, J M HENDRIE, J M	7905300134 7905300135	50-320 50-320		HOFFMAN, D. P. HOFFMAN, D. P.	7905310078	50-255 50-155	
HENDRIE, J M HENDRIE, J M	7905300137 7905300139	50-320 50-320		HOFFMAN D P	7905040386 7905250364	50-255 50-255	
HENDRIE, J M	7905300144	50-320		HOFFMAN, D. P HOFFMAN, D. P	7905080537 7905100249	50-255 50-255	
HENDRIE, J M HENDRIE, J M	7905300562 7905190127	50-320		HOFFMAN, D P HÖFFMAN, D P.	7705100255	50-255	
HENDRIE, JM HENDRIE, JM	7905300495 7905300645	50-245		HOFFMAN, D P	7905110085 7905140211	50-255 50-155	
HENDRIE, J M HENDRIE, J M	7905300652 7905300325	50-320		HOFFMAN, D.P. HOFFMAN, D.P	7905150309 7905150615	50~255 50~255	
HEMMESSEY, R J	7905020033	50-280		HOFFMAN, D. P. HOFFMAN, D. P.	7705210150 7705220020	50-255 50-255	
HENNESSEY, R J	7905300026 7905090406	50-338	NUREO/CR-0728	HOFFMAN, D. P. HOFFMAN, D. P.	7905220329	50-255	
HENRY, J	7905160068 7905100423	50-320 70-143		HOFFHAN, D P	7905220340 7905210163	50-255 50-155	
HERBEIN, J G HERBEIN, J G	7905230024	50-320		HOFFMAN, D, P HOFFMAN, D, P	7905230052 7905230095	50-255 50-255	
HERBE IN, J Q	7905110149 7905110173	50-320 50-289		HOFMANN, K. R. HOFMANN, K. R	7905140575	00 200	NUREG/CR-0645
HERBEIN, JO HERBEIN, JO	7905160141 7905190209	50-320 50-320		HOHENBOKEN, P	7905140576 7905080151	50~237	NUREQ/CR-0646
HERBEIN, J G HERBEIN, J G	7905190169 7905190229	50-320 50-320		HOLLAND, P. HOLLY, J. T	7905140324 7905100292	50~249 50~305	
HERBEIN, J Q HERBEIN, J Q	7905190231	50-320		HOLM,W M. HOLMAN,J J	7905250540 7905300289		
HERBEIN, J Q	790519023 <u>4</u> 7905190215	50~320 50~320		HOLOWAY, C. F. HOOD, D. 8	7905240587		7905240587
HERBEIN, J. Q HERBEIN, J. Q	7905020294 7905020468	50-289 50-320		HOOPER, F F,	7905290415 7905290583	50-329 50-395	
HERBE IN, J. O. HERBE IN, J. O.	7905160135 7905230005	50-320 50-320		HOOPER, F. F. HOSFORD, S.	7905140016 7905080051	20-255	MIRES SADA
HERBE IN, J. O HERBE IN, J. O	7905080445	50-289		HOULIHAN, T. J. HOULIHAN, T. J.	7705030233		NUREG-0484
HERBEIN, J Q	7905080542 7905070587	50-289 50-289		HUWARD, M	7703130803 7703170176	50-320	
HERBEIN, J Q HERBEIN, J Q	7905080521 7905090337	50-320 50-320		HOWE, P. W. HOWE, P. W.	7905080330 7905250015	50-400 50-400	
HERBEIN, J. Q. HERBEIN, J. Q	7905290350 7905140282	50-289		HOWELL, 8, H HOWELL, 8, H,	7905140219 7905030308	50-329	
HERBEIN, J Q	7905220318	50-287 50-289		HOWELL, 8 H HOWELL, 8, H.	7905030358	50-329 50-329	
HERBEIN, J. O HERBEIN, J. O	7905190115 7905220371	50-320 50-289		HOWELL, S H.	7905030362 7905090082	50-329 50-329	
HERBEIN, J. Q. HERBEIN, J. Q.	7905230375 7905240558	50-289		HOWELL, 8, H HOWELL, 8, H	7905030327 7905080532	50-329	
HERDT, A. R.	7905070118	50-281		HOWELL, 8 H	7905250526	50-329 50-329	
HERDT, A R	7905230733 7905230169	50~5 <u>66</u> 50-339		HOHELL, 8 H,	7905300252 7905300478	50-329 50-329	
HERDT, A.R. HERDT, A.R.	7905230153 7905150081	50~389 50~518		HONELL, J. C. HOWLETT, O. H	7905150775 7905150505	50-295	
HERDT, A.R. HERDT, A.R.	7703240468	50-395		HOYLE, J. C. HOYLE, J. C.	7905090014	50-336	
HERDT, A.R.	7905240507 7905250020	50-518 50-400		HOYLE, U C	7905090018 7905140248		
HERDT, A. R. HERBCH, H. H.	7905130805 7905240577	50-590		HOYLE, J C.	7905150066 7905090276		
HERSLOFF, L. W. HEUSNER, A. T.	7903070111 7905250494			HOYLE, J. C.	7905090266		
HIATT, J. N. HIATT, J. W	7905010140	50-266		HOYLE, J. C.	7905090267 7905110379		
HICKLE, B. J.	790523042 <u>6</u> 7905140240	50-331 50-285		HOYLE, J. C HOYLE, J. C.	7905110379 7905140237		FRN-790314
				HOYLE, J. C.	7905090270		

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT REMUN	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
HOYLE, J C. HOYLE, J C	7905090023 7905090028			JOHNSTON O H JOHNSON D H	7905150539 7905140054	50-312 50-320	
HOYF, U B HUBACEK, U O	7905150732 7905010383	50-201 50-498		JOHNSON, L. JOLAN, D. B	7905230204 7904300328		
HUBACEK, H. O HUCKABEE, K. W	7905150570 7905290463	50-556 71-297		JOLMSRUD, J H JONES, L L	7905250453 7905290151	50~382	
HUCKABEE, K W HUDSON, O R	7905290469 7905100032	71-297		JONES, G. L JONES, W. C	7905230515 7905140487	50-285	
HUFHAM, J. M HUGHES, J	7905070084 7905150419	50-327 50-341		JONES.O C	7905240369 7905240416		7905240389 7905240415
HUGHES, J HURPHREYS, L. L	7905290720 7905230806	50-358 50-458		JONES'D H JONES'J 6	7905300098 7905040124	50-320 70-27	
HARPINEYS, L. L. HURRICUTT, D. H	7905150453 7905150797	50-459		JONES.C E	7905150116 7905020470	70-1201 50-500	
HURISTAD, A. A. HURISTAD, A. A.	7905010511 7905030367	50-282 50-282		JOOSTEN, J K JORDAN, E D	7903240555 7905010547	50-30 <b>4</b> 50-77	
A A GATESAUH A A GATESAUH	7905150499 7905080569	50~292 50~292		JORDAN, E D JORDAN, W	7905010539 7905140565	50-77 50-382	
HUNGSTAD, A. A. HUNGSTAD, A. A.	7905110131 7905150468	50-292 50-292		JORDAN, E.L. JORDAN, E.L.	7905100445 7905250231	50-346	
HANSTADIA A HANTERIR.	7905220118 7905020088	50-306		JORDANIE L JORGENSONIB L.	7905290162 7905080093	50-255 50-255	
HANTER, L. H HANTER, L. H	7905170279 7905170282		TR-39 TR-40	JOSEPH, P JOYNER, J H	7905220061 7905220092	50-592 70-135	
HUNTEL H HUNTER V H	7905230448 7905110404	50~445		JOYNER, J H JOYNER, J H	7905110036 7905230288	70-820 70-33	
HURLEY, J HUTTON, P. H	7905150255 7905240113	50-574	7905240113	JOYNER, J H JUDD, J G	7903240784 7903220023	70-135	
Himan, C R Ibser. H W	7905140572 7905250504		NUREG/CR-0537	יממטר ד איממטר ב	7905220391 7905250044	50-225 50-309	
TEPOLITO, T A. TEPOLITO, T A	7905090183 7905090186	50-366 50-331		JUDDIH T JULIAN,G_A	7905250046 7905240480	50-307 50-124	
IPPOLITO, T A IPPOLITO, T. A	7905090189 7905300598	50-366 50-271		JUSTICE, R. L JUTRAS, R	7905040261 7905070411	50-220	
IPPOLITO, T A. IPPOLITO, T A	7905080246 7905030067	50-333 50-10		KAFIN.R J KAFIN.R J	7905240098 7905240106	50-596 50-596	
IPPOLITO, T A IPPOLITO, T A.	7905080141 7905150089	50-237 50-321		KALLVIANAKIS, N	7905290099 7905100296	70-1113 50-254 50-254	
IPPOLITO, T A	7905090196 7905090199	50-331 50-331		KALIVIANAKIS N	7905090389 7905240678	50-265 50-265	
IPPOLITO, T A. IPPOLITO, T A	7905090201 7905150108	50-331 50-324		KALIVIANAKIS, N	7905240702 7905240691	50-255 50-254	
TEPOLITO, T A	7905110001 7905110002	50-298 50-298		KALIVIANAKIS'N KALIVIANAKIS'N	7905240597 7905170250	50-254 50-244	
IPPOLITO, T.A.	7905110005 7905250430	50-298 50-250		KALMAN, G. KAMMERER, C	7905290173 7905090264	50-522 50-320	
IRVINO,8 M ISCOE.D	7905290300 7905240178	50-382 50-466		KAMMERER, C KAMMERER, C	7905160225 7905160035 7905100012	50-320 50-320	
ISCOE.C JABLON.R A	7905240190 7905150234	50-466 50-250		KAMMERER, C KAMMERER, C	7905100127 7905100212	50-320 50-320	
JABLON, R. A. JABLON, R. A.	7905150729 7905150733	50~250 50~250		KAMMERER, C KAMMERER, C	7905100212 7905100218 7905160025	50-320 50-320	
JABLON, R. A JABLON, R. A	7905240859 7905140151	50-387 50-445		KAMMERER, C KAMMERER, C	7905160027 7905300307	50~320 50-320	
JACK.O C	7905150588 7905150611			KAMMERER, C KAMMERER, C.	7905100049 7905100049	50-320 50-251	
JACKEN, I. N JACKSON, C.	7705150134 7705250354	50-331 71-161		KAMMERERIG. KAMMERERIG	7705100051 7705100061	50-320 50-320	
JACKSON, C. JACKSON, F. D.	7905250366 7905020222	71-161 40-4492		KAMMERER, C KAMMERER, C	7905100091 7905100136	50-320 50-320	
JACKSON, F. D JACKSON, F. D	7905070032 7905240444	40-4492 40-4492		KAMMERER, C KAMMERER, C	7905100176 7905100178	50-320 50-320	
JACKSON, L. L. JACKSON, L. L	7905241005 7905241005	20-52		KANMERER, C KANMERER, C	7905160040 7905160041	50-320 50-320	
JACOBB.T J JACOBB.B.B.	7905300467 7905040615	50-200		KAMMERER, C. KAMMERER, C	7905160051 7905100181	50~320 50~320	
JAPESID K	7905150249 7905220128	50-335 50-250		KAMMERER, C KAMMERER, C KAMMERER, C	7905160044 7905100206	50-320 50-320	
JAMES D. K.	7905250392 7905250324	50-250 50-10		KAMMERER, C. KAMMERER, G	7905160023 7905160146	50-320 50-320	
JAMECEK, R. F. JAMECEK, R. F.	7903010524 7903040603	50-254 50-237		KAMMERER, C. KAMMERER, C	7905140098 7905160021	50-320 50-320	
JAMECEK, R. F. JAMECEK, R. F.	7905090370 7905140273	50-10 50-10		KAMMERER, C. KAPLAN, S. N	7905160152 7905210178	50-320 50-224	
JAMEGEK, R. F.	7903140276 7903190097	50-249 50-237		KAPLAN, A. L. KAPLAN, A. L	7905290087 7905150791	70-1113 70-1113	
JANECEK, R. F. JANECEK, R. F.	7905250533 7905310364	50-254 50-237		KAPLAN, A. L. KAPLAN, A. L.	7905240600 7905070091	70-1113 70-1113	
JAN (B. J. T JANSEN, T.	7905100434 7905300705	50-312 50-249		KAPLAN, A L. KAPLAN, A L	7905240811 7905220025	70-1113 70-1113	
JAMUSKA, A C JASKE, R. T.	7905150646 7905250525	70-1377		KAPLAN, C. H. KAPPLE, A. N	7905030080 7905140230	30-272	
ENACTINE, H. D.	7905090056 7905230679	50-339 50-338		KAPPLE, A W.	7905010535 7905040541	50-272	
JENSKINS, O. R. JENSKEKENS, J. H.	7905230623 7905110369	50-261 50-320		KAPPLE, A. H KAPPLE, A. H	7905040371 7905080525	50-272	
JENNINOS, D. W. JENS, W. H.	7905240462 7905070442	50-62		KAPPLE, A. N. KAPPLE, A. N	7905150446 7905150464	50-272	
JOHRI: D. F JOHRI: D. F.	7905250488 7905230448	50~445 50~445	XN-NF-79-27	KAPPLE, A.W.	7905220132 7905220314	50-272	
JOHERSON, B. L.	7905100290 7905150282	50-305 50-592 50-309	nis in - 1 = 1	Karraschi B. A. Karperski D. C.	7905140028 7905070382		
JOHRASON, N. P.	7905040514 7905250189	50-309 50-309		KASPERSKI, B. C. KASPERSKI, D. C	7905250495 7905250495	ž	NUREO/CR-0513
JOHNSON R G.	7905230394 7905290093	50-263 50-344		KATO, W. Y. KAUFHAN, N.	7905150219 7905110413 7905230363	7 50-320 7 50-3	
JOHANSON, R. H.	7905030158 7905150722	50-344 50-344		KAHULA L. KEATEN R. H.	790519008° 790519008° 790511002	50-320	
JOHNSON, R. H	7905240948 7905090420	50-395 50-395		KEENAN, R. P KEENAN, R. P.	790529013 790524011	5	
JOHPASON, M. C. JOHPASON, M. C	7905010483 7905290105	50-395 50-296		KEENAN, R. P. KEENAN, R. P.	790524012 790524012 790524036	3	
JOHNSON, D.	7905080110 7905090135	50-338 50-188		KEENAN, R P. KEENE, W. E.	790501054 790524042	7 50-77	
JOHNSON, E. H.	7905150604 7905150585	25. thm		KEENE, J P.	1 to object to the		

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCEBBION NUMBER	DOCKET NUMBER	REPORT NUMBER
KEENEY, W P	790516005B	71-5795		KEPPLER, J Q KEPPLER, J Q	7905010265	50-546	
KEHOE, D	7905240148 7905070210	50-594 50-247		KEPPLER, J O	7905010267 7905010269	50-346 50-483	
KEILHAN, T J KEILMAN, T J	7905020255 7905020259	71-77 71-77		KEPPLER, J Q KEPPLER, J Q,	7905010270 79050{0273	50-266 50-305	
KEIMIO, R. R	7905300192	50~320		KEPPLER, J Q	7905090155	50-409	
KEIMIQ, R, R KEIMIG, R, R	7905240437 7905090146	50-207 50-213		KEPPLER, J Q KEPPLER, J Q	7 <b>705</b> 030370 7 <b>705</b> 030372	50-10 50-358	
KEIHIQ, R R	7905080110	50-286		KEPPLER, J G	7705040021	50-440	
KEIMIG, R. R KEIMIG, R. R	7905110371 7905290173	50-247 50-244		KEPPLER, J Q KEPPLER, J Q.	7905040026 7905040027	50-155 50-409	
KEIMIG.R R KEIMIG.R R	7905190175 7905290157	50~320 50~334		KEPPLER, J Q. KEPPLER, J Q	7705040030 7705040031	50-341 50-331	
KELBER, C	79051103B7	50-320	1810-4 0000	KEPPLER, J. G	7905040035	50-461	
KELLER, Q R KELLEY, P J	7905240326 7905300334	50-338	NUREG-0382	KEPPLER, J Q. KEPPLER, J Q.	7905040037 7905040041	50-315 50-367	
KELLEY, J L	7905150310 7905090235	50-295 50-320	SECY-A-78-10	KEPPLER, J Q KEPPLER, J Q	7905040045 7905040048	50-484 50-263	
KELLEY, J L	7905090246	50~320	SECY-A-78-34	KEPPLER, J Q	7705040051	50~546	
KELLEY, J L	7905090222 7905230470	50-320	BECY-A-78-47	KEPPLER, J Q. KEPPLER, J Q	7905040055 7905040058	50~346 50~483	
KELLOGO, P J KELLOGO, P J	7905210314 7905140210	50-320 50-317		KEPPLER, J O KEPPLER, J O	7905040060	30-246	
KELLOGO.P J	7905230503	50-249		KEPPLER, J 0	7905040065 7905080529	50-305 50-329	
KELLOGO,P J KELLY,R B	7905090056 7905190200	50-339		KEPPLER, J Q KEPPLER, J G	7705130424 7705010155	50-331 50-10	
KELLY,W Ø	79051505B5			KEPPLER, J G	7905010162	50-155	
KELLY,J S KENDALL,M C	7905140200 7905140158			KEPPLER, J. Q. KEPPLER, J. O	7905010165 7905010167	50-407 50-331	
KENDRICK,J R KENNA,W B	7905250290 7905240361	50-437 70-143		KEPPLER, J G	790501 <u>0171</u> 7905010174	50-315	
KENNA, W B	7905240352	70-143		KEPPLER, J Q	7905010176	50-243 50-346	
KENNA,W B	7905020078 7905040118	50-269 70-27		KEPPLER, J Q KEPPLER, J Q	7905010181 7905010186	50-266 50-305	
KENNA, W B	7905020433 7905240054	70-143		KEPPLER, J G	7905010191	70~B	
KENNA, W B	7905020156	50-395 70-1151		KEPPLER, J. O KEPPLER, J. O	7905010197 7905010384	70-1193 50-10	
KENNA,W B	7905230632 7905230684	50-302 70-143		KEPPLER, J. G. KEPPLER, J. G	7905010390 7905010394	50-155 50-407	
KENNA, W B	7905070252	70-1201		KEPPLER, J G	7905010398	50-331	
KENNA, W B. KENNA, W B	7905240323 7905240295	70-1151 70-1151		KEPPLER, J Q KEPPLER, J Q	7903010404 7903010410	50-315 50-263	
KENNA, W, B KENNA, W B	7905040105 7905020025	70-27 50-280		KEPPLER, J Q KEPPLER, J Q	7905010413 7905010417	50-346 50-266	
KENNA,W B KENNA,W B	7905020048	50-269		KEPPLER, J O.	7905240933	50-346	
KENNA, W B.	7905020146 7905020417	70-1151 70-143		KEPPLER, J. Q KEPPLER, J. Q	7905030006 7905030007	50-315 50-275	
KENNA,W 8 KENNA,W B	7905150112 7905230628	70-1201 50-302		KEPPLER, J Q KEPPLER, J. G	7905030013 7905030017	50-10 50-358	
KENNA, W B KENNA, W B.	7905070240 7905070269	70-1201		KEPPLER, J O	7905030019	50-440	
KENNA, W. B.	7905300016	70-1151 70-1201		KEPPLER, J. Q Keppler, J. Q.	7905030022 7905030023	50-329 50-255	
KENNEDA'M 1 KENNY'M B	7905300023 7905070446	50-338 50-495		KEPPLER, J. Q KEPPLER, J. Q	7905030025 7905030026	50~155 50~409	
KENNEDY, H J	7905140245 7905140382	50-280 50-280		KEPPLER, J Q	7905030029	50-341	
KENNEDY, W J	7905140335	50-28Q	•	KEPPLER, J. Q KEPPLER, J. Q	7905030031 7905030033	50-331 50-461	•
KENNEDY, W. J	7905210111 7905290335	50-280 50-280		KEPPLER.J.G KEPPLER.J G	7905030036 7905030040	50-367 50-282	
KENNEDY, R. W KENNEDY, R. T	7905210154 7905090111	50-30⊋		KEPPLER, J G KEPPLER, J G.	7905030047 7905030049	50-484 50-544	
KENNEDY, R T	7905300096	50-320		KEPPLER, J Q	7905030053	50-346	
KENNEDY, R. T KENNEDY, R. T.	7905020024 7905230220	50-320 50-320		KEPPLER, J. Q. KEPPLER, J. Q	7905030058 7905030062	50-483 50-266	
KENNEDY, R. T KENNEDY, R. T.	7905020046 7905080070	50-320		KEPPLER, J. G. KEPPLER, J. Q	7905030069 7905190096	50-305 50-320	
KENNEDY, R T	7905100020	50-320		KEPPLER, J. Q	7905100162	50-14	
KENNEDY,R T KENNEDY,R T	7905160192 7905160142	50-320 50-320		KEPPLER, J. Q KEPPLER, J. Q	7905010569 7905010572	50-10 50-275	
KENNEDY, R. T KENNEDY, R. T	7905080125 7905140079	50-320 50-320		KEPPLER: J. Q. KEPPLER: J. Q	7905010574 7905010576	50-358 50-440	
KENNEDY, R T. KENNEDY, R T	7905030055 7905140144	50-320		KEPPLER, J. Q.	7905010579	50-155	
KENNEDY, R T	7905160175	50-320 50-320		KEPPLER, J. Q KEPPLER, J. Q.	7905010583 7905010585	50-329 50-409	
KENNEDY, R. T. KENNEDY, R. T	7905150003 7905220079			KEPPLER, J. Q KEPPLER, J. Q.	7903010386 7903010388	50-341 50-331	
KENNEDY, R. T. KENNEDY, R. T	790529000B 7905190233			KEPPLER, J. Q	7905010590	50-461	
KENNEDY R T	7905290003	50-320 50-219		KEPPLER, J. Q KEPPLER, J. Q.	7905010592 7905010593	50-315 50-367	
KENNEDY, R. T. KENNEDY, R. T.	7905290031 7905190127	50-309 50-320		KEPPLER, J. G KEPPLER, J G	7905010597 7905010599	50~484 50~263	
KENNEKE, A. KENNEKE, A	7905090257 7905090233	50-320 50-320		KEPPLER, J. G	7905010600	50-282	
KENNEKE, A	7903070239	50-320		KEPPLER, J. G. KEPPLER, J. G	7905010602 7905010604	50-546 50-346	
KENNEKE, A. KENNEKE, A.	7905090258 7905090234	50-320 50-320		KEPPLER, J. Q KEPPLER, J. Q	7905010610 7905010613	50-483 50-266	
KENNEKE, A. KENNINGTON, G. S	7905090212 7905070037	50-320 40-4492		KEPPLER, J. O, KEPPLER, J. G	7905010615	50-305	
KENT, B,	7905160031	50-320		KEPPLER, J Q.	7905040324 7905040328	50-255 50-155	
KENT, 8 KEPFORD, C, P	7905160047 7905140519	50-320 50-320		KEPPLER, J. Q. KEPPLER, J. Q.	7905040331 7905040334	50-329 50-10	
KEPPLER, J Q KEPPLER, J, G	7905290183 7905020166	70-1379 50-329		KEPPLER, J. Q KEPPLER, J. Q.	7905040351	50-358	
KEPPLER, J. G.	7905010233	50-315		KEPPLER, J. Q.	7905040382 7905040384	50-440 50-409	9
KEPPLER, J. O. KEPPLER, J. O.	7905010236 7905010242	50-10 50-358		KEPPLER, J. G. KEPPLER, J. G	7905040367 7905040369	50~341 50~331	
KEPPLER, J. Q KEPPLER, J. Q,	7905010246 7905010247	50-440 50-155		KEPPLER, J. O. KEPPLER, J O	7905040394	50-461	
KEPPLER, J. Q. KEPPLER, J. Q.	7905010249	50-329		KEPPLER, J. Q.	7905040398 7905040405	50-367 50-263	
KEPPLER, J G,	7905010251 7905010253	50-409 50-341		KEPPLER, J. G KEPPLER, J. G	7905040418 7905040425	50-484 50-546	
KEPPLER, J. Q KEPPLER, J. Q.	7905010256 7905010257	50-331 50-461		KEPPLER, J. Q. KEPPLER, J. Q	7905040427 7905040428	50-346 50-483	
KEPPLER, J. O. KEPPLER, J. O	7905010258 7905010261	50-367 50-484		KEPPLER, J. O KEPPLER, J Q.	7905040431	50-266	
KEPPLER, J. O	7905010262	50-263		KEPPLER, J. Q.	7905040434 7905040435	50-305 50-331	

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
KEPPLER: J O	7705040438	50-266		KIDDS, N S	7905010275	50-338	
KEPPLER, J Q KEPPLER, J Q	7705040440 7705040443	50-407 50-305		KILLOUGH G G KILLNGER G	7905140067 7905230788	50-320	7905230788
KEPPLER, J O	7905040445 7905040451	50-484		KING, R B.	7905250508		
KEPPLER, J. Q KEPPLER, J. Q	7905040452	50~263 50~358		KING. B KINNEY, W	7905150199 7905230516	50-320	
KEPPLER, J. Q KEPPLER, J. Q	7905040456 7905040459	50~315 50~461		KINTIGH, A E Kintigh, A E	7905220120 7905310342	50-576 50-576	
KEPPLER, J 0	7905040460	50-341		KINTIOH A. E	7905300477	50-576	
KEPPLER, J O KEPPLER, J O	7905040461 7905040465	50-493 50-327		KINTNER, L. KIRK, W. F	7905150630 7905290059	50-341 70-371	
KEPPLER, J G	7905040522	50-315		KIRKBCEY.K A	7905240540		7905240540
KEPPLER, J. O KEPPLER, J. O	7905040527 7905040529	50-295 50-10		KISTER, H B Kister, H B	7905070182 7905070158	50-286 50-272	
KEPPLER, J O KEPPLER, J O	7905040534 7905040537	50-358 50-440		KISTÉR¦H B, Kistér¦h, B	7905070210 7905290166	50-247 50-336	
KEPPLER, J Q	7905040546	50-327		KISTER, H B,	7905290126	50~334	
KEPPLER, J Q KEPPLER, J Q.	7905040548 7905040550	50-255 50-155		KISTER, H B Klinger, O.	7905290145 7905100375	50~245 50~346	
KEPPLER, J G	7905040553 7905040556	50-409 50-341		KLINGLER, O R	7905110009	50-312	
KEPPLER, J Q KEPPLER, J Q	7905040560	50-331		KNIGHTON, G. N KNIGHTON, G	7905110123 7905230326	20~350 20~350	
KEPPLER, J G KEPPLER, J G	7905040566 7905040566	50-461 50-367		KNOP:R C KNOP:R C	7905110111 7905090393	50-346 50-544	
KEPPLER, J O	7905040576	50~263		KNOP, R C,	7905030074	50-373	
KEPPLER. J Q	7905040587 7905040589	50-484 50-546		KNOPJR.C KNOPJR C	7903020470 7903290720	50-500 50-358	
KEPPLER. J O KEPPLER. J O	7905040591 7905040595	50-346 50-483		KNOPJR.C. KNOTTJM	7905230296 7905020286	50-329 50-312	
KEPPLER, J. O	7905040598	50-266		KNOTTS, J B.	7905100228	50-445	
KEPPLER.J Q KEPPLER.J Q	7905040600 7905070162	50-305 50-155		RNOTTO, J.B. E. J. BTTONN	7905150821 7905090036	50-445 50-445	
KEPPLER, J Q	7905070164	50-367		KNOTTB: J. B	7905090042	50-445	
KEPPLER, J Q KEPPLER, J Q	7905070167 7905070170	50-544 50-440		KNOTTS, J B KNOY, R C,	7905090050 7905100362	50-346	
MEPPLER, J O KEPPLER, J. O	7905070174 7905170089	50~346 50~315		KOCH,L J KOCHER,D C.	7705270563 7705230788	50-461	7905230788
KEPPLER, J Q	7905010380	50-373		KOCHER, D.C.	7905030142		NUREQ/CR-0494
KEPPLER, J. G KEPPLER, J. G	7905010387 7905010396	50-329 50-440		KOESTER, O.L. KOESTER, O.L.	7905300626 7905080514	50-482 50-482	
KEPPLER, J. Q	7905010400	50-359		KOESTER, G L	7905110311	50-402	
Keppler, J. O	7905010405 7905010411	50-483 50-546		KOESTER, O. L. KOHLER, R	7905290326 7908250497	50-402	
KEPPLER, J. O KEPPLER, J. O	7905010415 7905010419	50-341 50-484		KOLTAY,PB	7905100433 7905290132	50-307 50-277	
KEPPLER, J. O	7905010426	50-461		KOPLAN, A. L	7905140309	70-1113	
KEPPLER, J. Q KEPPLER, J. Q	7905010429 7905030204	50-347 50-315		KORNOL I TH. L KORNOL I TH. L	7905230540 7905140568	50-272 50-272	
KEPPLER, J O	7905030204	50~10 50~35£		KORNBL I TH, L	7705140561	50-272	
KEPPLER, J. Q KEPPLER, J. Q	7905030215 7905030217	50-440		KORNBLITH, L. KORNBLITH, L	7905140558 7905230563	50-272 50-510	
KEPPLER, J. O. KEPPLER, J. O	7905030219 7905030220	50~329 50~155		KORNBLITH, L. KOSIBI, R E	7905250070 7905190072	50-510 50-320	
KEPPLER, J O	7905030222	50-409		KOSIK,L S	7905130227	50-35B 50-358	
KEPPLER, J G.	7905030224 7905030227	50-341 50-331		KOSTK, L. B. KOSTK, L. B	7905150212 7905150221	50-358	
KEPPLER, J. O. KEPPLER, J. O.	7705030228 7705030232	50-461 50-367		KOBIK, L. B	7905140156 7905140157	50-358 50-358	
KEPPLER, J O	7905030235	50-484		KOSIK, L. 6	7905140369	50-358	
KEPPLER, J. O. KEPPLER, J. O.	7905030237 7905030241	50~24# 50~54#		KOSIKIL. B.	7905010223 7905290464	50-358 50-358	
KEPPLER: J. Q.	7905030245 7905030249	50-346 50-483		KOSIK,L B KOSB,R R	7905240104 7905250496	50-358	
KEPPLER, J. O. KEPPLER, J G.	7905030253	50-266		KOBTHAYER, P. H.	7905240626	50-219	
KEPPLER, J. Q. KEPPLER, J. Q.	7905030255 7905010380	50-305 50-455		KOUTØ, H. J. KOUTØ, H. J.	7905150219 7904300253		NUREO/CR-0519
KEPPLER, J O	7905040368	50-350		Kramer. F W	7905110098 7905140284	50-320	WCAP-9402 (NP)
KEPPLER.J Q KEPPLER.J Q.	7905140534 7905040142	50-26 <i>6</i> 50-10		Kramish, a Kranen, J. F.	7905240616	71-110	
KEPPLER: J. O KEPPLER: J. O	7905080397 7905080400	50-359 50-440		Kranish, A. Kreoer, W e	7905100050 7905150139	50~320	
KEPPLER, J. O.	7905080404	50-327		KRESS, T 8.	7905240556	50-275	7908240556
KEPPLER. J. Q KEPPLER. J. Q.	790 3080486 790 3080490	50-155 50-409		KRISTOVICH, Ø. KRISTOVICH, Ø	7905030174 7905310104	50-275	
KEPPLER.J.G. KEPPLER.J.G.	7905080492 7905080496	50~341 50~331		KROOT, I. KUHNS, W Q	7905030209 7905140065	50-338 50-320	
KEPPLER.J O.	7905080498	50~461		KURTZ+R. J	7905240113		7905240113
Keppler, J. G Keppler, J. G.	7905060499 7905080502	50-315 50-367		KUSHNER, W. L. KUSHNER, W. L.	7905240784 7905220092	70-135 70-135	
KEPPLER. J. O.	7905080503 7905080505	50~484 50~263		KUBSIE.R R. Kuzmycz.g.	7905230417 7905010179	50-244 50-267	
KEPPLER, J. G. KEPPLER, J. G	7905080507	30-346		LADUN; R. H.	7705240287	50-225	
KEPPLER, J. Q. KEPPLER, J. Q.	7905080509 7905080512	50~346 50~483		LAFLEUR, J. D LAFLEUR, J. D	7905140150 7905140093	50-320 50-320	
KEPPLER, J O	7905080515	30-266		LAFLEUR, J. D.	7905160156	50-320 50-320	
KEPPLER: J. G KEPPLER: J. G.	7905080519 7905150355	50-305 50-155		LAFLEUR, J. D. LAFLEUR, J. D	7905160196 2010416097	50-320	
KEPPLER, J. O KEPPLER, J. O	7908140488 7905240887	50~10 50~358		LAFLEUR, J.D. LAFLEUR, J.D.	7905140165 7905140012	50-320 50-320	
KEPPLER, J. O.	7905240892	50-440		LAFLEUR, J. D.	7905140211	50-320 50-320	
KEPPLER, J. G KEPPLER, J. G.	7905240893 7905240896	50~155 50~409		LAFLEUR:JD. LAFLEUR:JD	7905160011 7905160204	50-320	
KEPPLER, J. O	7905240898 7905240902	50-341 50-331		LAFLEUR, J. D.	7905160010 7905160178	50-320 50-320	
KEPPLER, J. O. KEPPLER, J. O.	7905240906	50-461		LAFLEUR, J. D. LAFLEUR, J. D.	7905140055	50-320	
KEPPLER, J. G KEPPLER, J. G	7905240907 7905310466	50-367 50-315		LAFLEUR, J. D. LAFLEUR, J. D	7905140214 7905090242	50-320 50-320	
KERR, U	7905230402	50-2		LAFLEUR, J. D	7905140009 7905140181	50-320 50-320	
KERR, O. W. KETCHEN, E. O.	7905250038 7905300044	50-275		LAFLEUR; J. D. LAFLEUR; J. D	7905160066	50-020	
KETCHEN, E. O. KETCHEN, E. O	7905030103 7905030116	70-2623 70-2623		LAFLEUR, J D LAFLEUR, J D.	7905160188 7905160004	50-320 50-320	
KETCHEN, E. C.	7705030120	70-2623		LAFLEUR, J D.	7905160195	50-320	
KETCHEN, E. O. KEY, H. J.	7905100157 7905080211	50-275 50-331		LAFLEUR, J.D. LAFLEUR, J.D	7905090245 7905300370	50-320 50-320	
KEY, W J.	7905150436	50-331		LAFLEUR, J. D	7908300407	50~320	

AUTHOR	NO188333A RABMUN	DOCKET NVMBER	REFORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
LAFLEUR, J D LAFLEUR, J D	7405160001 7705300420	50-320 50-320		LEWIB, M I LEWIB, M	7905250487 7905290181		
LAFLEUR, J D	7905300369	50-320		LEWIS, M	7905290187		
LAFLEUR,J D LAFLEUR,J D	7905300365 7905300424	50-320		LEWIS.R LEWIS.J R	7905240251 7905290410	50-443 70-364	
LAFLEUR, J D LAFLEUR, J D	7905300359 7905300410	50-320		LEWIS, L LEWIS, S R	7905040247	50-267	
LAFLEUR, J D	7905300356	50-320		LEWIS 8 R	7905080527 7905020340	50-269	
LAFLEUR.J D LAINAS.G C	7905300415 7905230041	50-320 50-320		LEWIS, B R	7905230305 7905250408	50-269 50-269	
Lainas. Q Lainas. Q	7905300718 7905110130	50-320		LEWIS, S R	7905250427	50-249	
LAINAS. O	7903110133	50-320		FEMIS'S H FEMIS'S B	7905310410 7905230841	50-287 50-549	
Lainas. Q Lainas. Q	7905150798 7905240302	50-335 50-206		LEWIS, S H	7905080401 7905140194	50-482 50-261	
LAINAS. Q Lainas. Q	7905240253 7905240471	50-336 50-305		LEWIS, S H	7705250039	50-286	
LAINAS. C	7705240731	50-255		Lehib, S. H Lehib, S. H	7905040131 7905070134	50-482 50-549	
LAMB, J. C LAMB, J C	7905140568 7905140561	50-272 50-272		LEWIS, S H	7905240603 7905240771	50-261 50-261	
LAMB,J C Lampka,J V	7903140358 7903150229	50-272		LEWIS, S H	7905110418	50-320	
LANTZ, P M	7905240587		7905240587	LEWIB, B H Lewie, R C	7905300367 7905290167	50-549 50-33 <b>5</b>	
LAGOMARSINO,R LARKINS,J T	7905240273 7905110259	50-275 50-320		LEWIB,R C, Lewis,R C	7905230229 7905020040	50-324 50-280	
LARSON, J. R LARSON, L. K	7905080109 7905150074	50-485	TFBP-TR-209	LEWIS,R C	7905230482	90~269	
LAWRENCE, H	7905290081	71-322		LEWIS, R. C Lewis, R. C	7905020012 7905010465	50-280 50-324	
LAWRENCE, M LAWROSKI, S	7905290084 7905140164	71-322		LEWIS,R C Lewis,R C	7705020412	90E-05	
LAWROSKI.S LAWROSKI.S	7905230476 7905230480	50-320 50-320		LEWIE,R C	7905010255 7905010466	50-338 50-395	
LAWROSKI N	7905230471	50-320 50-320		LEWIS.R C LEWIS.R C	7905230583 7905090051	50-261 50-339	
LAWROSKI,S LAWROSKI,S	7905030161 7905140019			LEWIS, R C Lewis, R. C	7905250105	50-321	
LANROSKI, H LANYER, S	7905230445 7905220438	50-320 50-320		LEWIS R C	7905290707 7905020458	50-369 50-339	
LAYFIELD, R L	7905230280	40-2407		LEWIS,R C LEWIS,R C	7905020489 7905090129	50-321 50-338	
LAYFIELD,R L LAYFIELD,R L	7905230270 7905230255	40-2407 40-2407		LEWIB, R C	7905150138	50-259	
LAYFIELD,R L LAZARUS,W J	7905230250	40-2407		LEWIS.R C LEWIS.R C	7905150251 7905250396	50-250 50-302	
LAZO, R M	7905090146 7905090178	50~213 50~592		LEWIS R C LEWIS R C	7905210047 7905240474	90-320	
LAZO,R M LAZO,R M	7905290576 7905100186	50-369 50-369		LEWIS.R C.	7905240483	50-124 50-327	
LAZSON, L. K. LEASE, R. S.	7905230497	50-485		LEWIS, R C LEWIS, R C	7903240523 7903240530	50-346 50-339	
LEBERSTEIN, J H	7905150438 7905040472	50-315 50-280	VEP-FRD-32	LEWIS, R. C LEWIS, R. C	7905230209	50-324	
LEBO,C D Lebo,C D	7905240107 7905300152			LEWIB, R C	7905250173 7905250381	50-369 50-302	
LEBO, C D, LEBO, C D	7905300247			LI,R M Libarkin,M,H	7905070213 7905140022	50-320	
LEE, B	7905240787 7905250069			LIBARKIN, M W.	7905140013	50-320	
LEE, B LEE, E W.	7905030366 7905040349	50-10		LIBRIZZI,F P LIBRIZZI,F,P	7905030360 7905010525	50-272 50-272	
LEE, T T	7905300561	50~461		LIBRIZZI,F P LIBRIZZI,F.P	7905040538 7905040370	50-272	
LEE, T D LEE, H S.	7905020439 7905010550	70-143 50-269		LIBRIZZI,F P.	7905080485	50-272 50-272	
LEE, W 8. LEECH, P. H	7905020283 7905090211	50-249 50-522		LIBRIZZI,R,P Librizzi,f p.	7905140227 7905170263	50-272 50-272	
LEEDS LEGEL, R. A.	7905140564	50-329		LIBRIZZI,F,P LIBRIZZI,F P	7905150280 7905150444	50-272 50-272	
LEHMAN, H	7905160390 7905220100	50-320 50-250		LIBRIZZI, F P	7905150462	50-272	
Lehman, W Lehman, W.	7905290486 7905240864	50-250 50-250		LIBRIZZI,F P. Librizzi,r p.	7905220127 7905220308	50-272 50-272	
LEMPOES, T E LENAHAN, J J	7905300486	20-220		Lichtenberoer, H Lichtenberoer, H	7905240269 7905250013	70-1100	
LEONARD, J D	7905090426 7905010584	50-395 50-333		LICITRA, E. A	7905090180	71-90 50-592	
LEONARD, J. D. LEONARD, J. D.	7905250142 7905240290	50-333 50-333		LICITRA, E, A. Licitra, E, A	7905230731 7905230858	50~482 50~482	
LEONARD, J D LEONARD, J D	7905010499	50-333		LICITRA, E A Like, i	7905240869	50-498	
LEONARD, J D	7905010505 7905250194	50-333 50-333		LINBLAD, H J,	7905240234 7905090433	50-322	
-	7905110254 7905150475	50-333 50-333		LINDBERG, C. Linder, F	7905080556 7905020238	50-249 50-409	
	7905300411	50-333		LINDER, F. LINDER, F	7905290334	50-409	
	7905300506 7905300522	50-33 <u>3</u> 50-333		LINDER, F.	7905010504 7905020243	50-409 50-409	
	7905140335 7905150522	50-298 50-298		LINDER, F LINDER, F.	7905240516 7905040373	80-409 50-409	
	7905100386	50-445		LINDER, F. LINDER, F.	7905090043	50-409	
	7905240967 7905250129	50-445 50-445		LINDER, F	7905090352 7905240698	50-40 <del>9</del> 50-409	
	7905100106 7905250191	50-445		LINDER, F. LINDER, F.	7905140231 7905150517	50-409 50-409	
	7905090430	50-498		LINDER, F. LINDER, F.	7705160425	50~409	
	7905010540 7905100021		7905100021	LINDER, F.	7905250404 7905220401	50-409 50-409	
	7905230413 7905230425		- · · ·	Linder, F. Linder, F	7905290086 7905290417	50-409 50-409	
	7905230453			LINDER, F. LINDER, F.	7905300012	50-409	
	7905230441 7905240316		7905240316	LINDER, F.	7905300314 7905110303	50~409 50~409	
	7905220043 7905230741		7905220043	LINDNER, T P LINDNER, T, P	7905170293 7905170283	•	
	7905160083	50-320	7905230741	LINDNER, T, P	7905170285		
	7905110285 7905110248	50-320 50-320		LINDNER, T.P. LINDNER, T.P.	7905170280 7905170289		
	7904170091 7905100336			LINDNER, T. P. LINDNER, T. P.	7905150105 7905240325		
	7905240233	50-471 50-471		Linehan, J, J, Linehan, J, J,	7905150616	40-6659	
	7908230438 7905230457			LINEHAN, J. J.	7905150613 7905150624	40-299 40-8584	
	7905240446 7905250498			linenberger, Q. A Linenberger, Q. A	7905290583 7905230182	50-395	
	7905230736	50~466		LINENBERGER, Q. LING, J.	7905140016 7905080219	50-466 50-522	

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
LINGENFELTER, J	7905150456	50-346		HACDONALD, C E	7905110210	71-116	
LINKER, H LIGU, C. P.	7905250224 7905250530	50~3 50~329	45-79/M124AF	MACDONALD.C €	7905240565	71-70	
LIPINSKI R J	7905110267	50-320	40-747/1124AF	MACDONALD.C E MACDONALD.C E	7905240974 7905241000	71-241 71-109	
LITTLE, L. W.	7905240579	27-39		MACDONALD, C E	7905290255	71-241	
LITTLE,L W LITTLE,L W	7905230563 7905250070	50-510 50-510		MACDONALD.C E MACDONALD.C E	7905070075 7905070081	71-6144 71-6144	
LITTLE, W. B.	7905090169	50-331 80-338		MACDONALD.C E	7905070302	71-6272	
LETTLE: NS. LETTLE: NS	7905140087 7905110094	50-295 50-346		MACDONALD.C E MACDONALD.C E	7905070307 7905070290	71~6272 71-6771	
LITTLE H S	7905150163 7905100400	50-156		MAGDONALD,C E	7905070295	71-6771	
LTU, L LTU, L	7905110163	71-296 50-331		MACDONALD.C.E MACDONALD.CE	7905090089 7905240017	71-6744 71-4986	
L[U, L L[U, L	7905150050 7905300272	50-331 50-331		MACDONALD, C E	7905240020	71-4906	
F10. F	7905040491	50-331		MACDONALD,C E MACDONALD,C.E	7905240036 7905240039	71-6400 71-6400	
LTU, L LTU, L	7905080469 7905090368	50-331 50-331		MACDONALD,C E	7905240128	71-6273	
LIO, LEE	7905080465	50-331		MACDONALD,C E MACDONALD,C,E	7905250305 7905250316	71-6679 71-6679	
110, L 110, L	7905230522 7905310447	50-331 50-331		MACDONALD, C. E	7905290094	71-251	
LIVINGSTON, R L	7905150055	50-320		MACDONALD,C.E MACDONALD,C.E	7905100167 7905100342	71-238 71-235	
Froad'D E Fiathgalon'B	7905240330 7905110298	50-255 50-134		MACDONALD, C. E	7905100347	71-255	
LLOYD, R. D	7905140361	50-346		MACDONALDIC E. Macdonaldic E	7905100352 7905110043	71-257 71-154	
LOCHBIET, N. A. LOCHBIET, N. A.	7905300130 7905100403	40-8498 50-320		MACDONALD, C E	7905110065	71-209	
LONDON, E, J	7905020151		7905020151	MACDONALD,C E Macdonald,C E	7905110047 7905110049	71-214 71-72	
LONG, R. L. LONG, R. L.	7905190121 7905230082	50-320 50-320		MACDONALD, C E,	7905110071	71-74	
COMO: J	7904270399	50-320		MACDONALD, C E Macdonald, C, E,	7905110075 7905110078	71-111 71-120	
LOOKABILL,T LOSS,FJ	7905010648 7905110033		7905110033	MACDONALD, C. E	7905110081	71-128	
LOTTES, P. A	7905150099		7905150099	HACDONALD, C. E. Macdonald, C. E	7905110084 7905110095	71-141 71-181	
LOFZ,JB LOHE,VP.	7905230735 7905150479	50-466 50-77		HACDONALD, C. E Hacdonald, C. E	7905140119	71-131	
LOWERSE, R H	7905310111	50-466		MAGDONALD, C E	7905150149 7905150157	71-31 71-108	
LOWERRE, R. W LU, T	7905140060 7905230010	50-466 50-320		MACDONALD,C E Macdonald,C E	7905150160 7905150169	71-66 71-189	
LUCHAX, Q	7905110409	50-272		MACDONALD, C E	7905150176	71-48	
LUCHAX.O. LUEBXE.E A	7905250235 7905100186	50-272 50-369		MACDONALD,C.E Macdonald,C.E.	7905240041 7905240046	71-2 71-24	
LUEBKE	7905140564	50-327 50-317		MACDONALD, C. E	7905240099	71-9506	
LUNDVALL, A E LUNDVALL, A E	7905110118 7905290712	50-317		MACDONALD,C E	7905240140 7905240156	71~39 71~121	
LUNDVALL, A E. LUNDVALL, A E	7905300742	50-317 50-317		MACDONALD C E	7705240161	71-143	
LUTON, E	7905090049 7905300032	50-456		MACDONALDIC E MACDONALDIC,E	7905240165 7905240582	71-77 71-65	
LUTON, E	7905090187 7905100327	50-454 50-471		MACDONALD, C E	7905250066	71-234	
LUTON, E.	7905150243	50-295		MAGDONALD.C E Magdonald.c E	7905250219 7905250226	71~6058 71~6058	
CYTON, E CYTON, E	7905290268 7905290699	50-471		MAGDONALD.C E MAGDONALD.C E,	7905240835 7905240845	71-266	
LYNCH, H D	7905150607	50-397		MACDONALD C E	7905240847	71-266 71-8	
HACARTHUR, T. C HACDONALD, C. E	7905070084 7905100340	50-327 71-215		MAGDONALD;C.E Magdonald;C.E.	7905240854 7905250341	71-8 71-6386	
HACDONALD, C.E.	7905150318	71-50		MACDONALD, C E	7905250346	71-6386	
HACDONALD, C. E. HACDONALD, C. E	7905150323 7905150329	71-50 71-38		MACDONALD,C E MACDONALD,C E	7905150576 7905240244	71-9010 71-9070	
MACDONALD, G. E. MACDONALD, G. E.	7905150333 7905170278	71-36 71-1		MACDONALD, C. E	7905240311	7168 7168	
MACDONALD, C E	7905230691	71-5790		MACDONALDIC E MACDONALDIC E	7905240318 7905240834	71-169	
MACDONALD, C.E. MACDONALD, C.E.	7905070047 7904200311	71-6058 71-110		MACDONALD, C. E. MACDONALD, C. E.	7903240B39 7903290041	71~169 71~9009	
MACDONALD, C E	7905020170	71-9852		MACDONALD, C. E	7905290046	71-9009	
HACDONALD, C.E. HACDONALD, C.E	7905250227 7905150723	71-217 71-296		MACDONALD, G E MACDONALD, G E	7905240327 7905240331	71-6697 71-6697	
MACDONALD, C. E	7905020185	71-6		MAGDONALD, C. E	7905230847	71-5805	
MACDONALD, C. E MACDONALD, C. E	7905020407 7905070228	71-88 71-277		MACQUINEA: D. B. MACKIN: J.	790510019 <i>6</i> 7905240542	50-348	
MACDONALDICE MACDONALDICE.	7905240109 7905240112	71~5364 71~6244		MACKLIN, L. MACMILLAN, J. H	7905230066 7905100351	71-9120	
KACDONALD, C. E	7905010169	71-167		MACHILLAN, J. H	7905300391	50-320	
MACDONALD, C. E. MACDONALD, C. E.	7905010185 7905020191	71-162 71-239		MACRAE, C. F MACRAE, C. F.	7905090358 7905310243	50-265 50-265	
KACDONALD, G E	7905020193	71-226		MADEDA, T J	7905110047	50-182	
KACDONALD, C. E. KACDONALD, C. E	7903020196 7903020198	71-225 71-34		MADIA:H J MADISON:B R.	7905150777 7905250080	50-549	7905150777
KACDONALD, C.E.	7905020376	71-220		MADISON, W R.	7905190193	50-338	
MACDOMALD, C. E MACDOMALD, C. E	7905020384 7905020386	71-216 71-213		MADSEN.O.L. MADSEN.O.L.	7905010529 7905010530	50-313 50-298	
MACDONALD, C. E.	7905020392	71-180		MADBEN, Q. L.	7905010533	50-285	
MACDONALD, C. E MACDONALD, C. E.	7905020394 7905020399	71-175 71-178		HADBEN, O. L. MADBEN, O. L.	7905010535 7905010536	50-267 50-313	
HACDONALD, C. E	7905070257 7905070267	71-119 71-89		MADBEN, O.L.	7905010544	50-298 50-285	
HACDONALD, C. E HACDONALD, G. E.	7905070272	71-99		MADBEN, O. L. MADBEN, O. L.	7905010546 7905010548	50~267	
MACCONALD, C. E. MACCONALD, C. E.	7905070279 7905070282	71-103 71-127		MADBEN, Q.L. Madben, Q.L.	7905010554 7905010558	50-313 50-298	
MACDONALD, C. E.	7905070287	71-130		MADSEN, C. L.	7905010539	50~285	
MACDONALD, C.E. MACDONALD, C.E.	7905070292 7905100079	71~104 71~ <del>9</del> 079		Madsen, C. L Madsen, O. L	7905010367 7905010375	50~313 50-298	
HACDONALD, G. €	7905150178	71-166		MADSEN, G L	7905010401	20-265	
HACDONALD, C. E. HACDONALD, C. E.	7905150205 7905150682	71-168 71-63		MADBEN, Q.L. MADBEN, Q.L.	7705010406 7705010395	50-267 50-313	
MACDOMALD, C. E.	7905150739	71-47		MADSEN, Q. L.	7905240451	50-313	
MACDONALD, C. E. MACDONALD, C. E.	7905150742 7905160053	71-126 71-5795		Madsen, O. L. Madsen, O. L.	7905010385 790515030A	50-313 50-285	
MACDONALD, C. E	7905240291	71-223		MADBEN, O. L.	7905150310	50-295	
KACDONALD, C. E. KACDONALD, C. E.	7905240638 7905290318	71-216 71-287		Madren, O.L. Madren, O.L.	7905150604 7905150596	50-198 50-188	
MACDONALD, C.E. MACDONALD, C.E.	7905080180 7905100339	71-5957 71-268		MADSEN, C. L.	7905010354 7905010655	50-247 50-72	
KACDONALD, G. E.	7903100448	71-273		MADBEN, Q. L. MADBEN, Q. L.	7905020122	50-278	
MACDONALD, C. E MACDONALD, C. E	7905110199 7905110204	71-260 71-87		MADSEN, G.L. MADSEN, G.L.	7905100261 7905150578	50-267 50-112	
A SAME BANK MANUFALL AS AN	1.04114544	, , , , , ,		(Minorili 4 F)	r ruws wow r G	~~ ^ ~~	

ήq

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET	REPORT NUMBER
MADSEN, Q L	7905020325	50-368		MATERS, B R	7905160443	50-341	
MADSEN, Q L MADSEN, Q L	7905150110 7905150117	50-247 50-313		MATHEWS, E R MATHEWS, E R	7905240319 7905290501	50-305 50-305	
MADSEN, G L	7905150120	50-298		MATHENS, E R	7905240289	50-305	
MADSEN, G L MADSEN, G L	7905150122 7905040106	50-295 50-313		MATHEWS, E R MATHEWS, E R	7905150330 7905100289	50~305 50~305	
MADSEN, O L	7905040110	50-278		MATHEWS, E R	7905150563	50-305	
Madsen, G L Madsen, G L	7905040112 7905040115	50-265 50-267		MATHEWS, E R MATHEWS, E R	7905240384 7905300028	50-305 50-305	
MADSEN, Q L	7905150223	50-2A7		MATHENS, E R	7905310365	50-305	
MADSEN, O L MADSEN, G L	79051 50253 79051 50258	50-313 50-298		MATHENS, E R MATHENS, P R	7905300395 7903210068	50-305 50-320	
MADSEN, O L	7905150261	50-295		MATHIAS,C M MATHIS,C J	7905300244 7905010540	50-320	
MADSEN, O L	7905230248 7905230257	50-285 50-285		MATHIB, C J	7905020267	50~293 50-293	
MADSEN Q L MADSEN Q L	7905030008 7905150795	50-313 50-267		MATHIB, C. J MATHIB, C. J	7905140247 7905160423	50~293	
MADSEN, O L	7905150584	50-112		MATHIB, C J	7905290100	50-293	
MADSEN, O L MADSEN, O L	7905150096 7905150097	50~313 50-298		MATHIS, C, J HATHIS, H	7905300543 7905030161	50-273	
MADSEN, Q L	7905150100	50-285		MATHIB, W MATIN, L E	7905140019	<b>50</b> 500	
MADSEN, G. L. HADSEN, G. L.	7905150102 7905240428	50-267 50-267		MATSON, V	7903150550 7905100358	50-382 70-2084	
MADSEN, O L MADSEN, O L	7905240440 7905240445	50-265 50-298		HATBON, V NOBTAN	7905020290 7905240121	70-219B	
MADSON, S	7905310392	27-39		MATSON, Y	7905100417	70-2170	
MAGERS, J E MAIMONI, A	7905150312 7905020464	50-331		MATBON, V. MATBON, V	7905150195 7905290118		
MAKEPEACE, J M	7905040006	50-247		MATSON, V	7905290121		
MAKEPEACE, J M HALINAUSKAS, A P	7905040279 7905300078	50-247	NUREO/CR-0682	MATBUI,R T MATT,P K	7905020011 7905030199	50-320	
MALLORY,R MALONEY,Q P	79051A0103 7905110183	50-320 50-315		MATT,P K	7905140089		
MANCUBO. F	7905250504	30-310		MATT,P,K HATFIMOE,J.J	7905100007 7905110032	50-312	
MANGZER,W B MANN,J R	7905230638 7905090011			MATTIMOE, J. J MATTIMOE, J J	7905110153 7905020306	50-312 50-312	
HANRY: M.	7905140316	50-321		HATTIMOE, J J	7905100293	50-312	
HANRY: M HANRY: M	7905010469 7905010502	50-366 50-321		MATTIMOE, J. J MATTIMOE, J. J	7905190156 7905240710	50-312 50-312	
MANRY, M	7905080546	30-321		MATTIMOE, J J	7905190134	50-312	
MANRY, M MANRY, M	7905080473 7905080520	50-321 50-321		MATTIMOE,J J WATTIMOE,J J	7905250434 7905290369	50-312 50-312	
KANRY: M KANRY: M	7905070639 7905150465	50-344 50-366		HATTIMOE, J. J.	7905300405	50-312	
MANRY, M	7905150519	50-321		L M.AITTAM L M.AITTAM	7905090399 7905140179		
MANRY, M MANRY, M	7905150543 7905150344	50-321 50-366		MATTEON, R. J MATTEON, R. J	7905050046 7905140299	EG .EG4	
MANRY, M	7905300627	50-321		L RINDBITAM	7905080044	50-324	
MANRY, M MANRY, M	7903300644 7905300683	50-321 50-321		MATTRON, R. J MATTRON, R. J	7905140292 7905080041	50-524	
MANRY, M	7905300591	50-321		MATTEON, R. J	7905230123	50-320	
MANRY, M MANSER, W. C	7905300664 7905020425	50-321 70-143		MATTBON, R J MATTBON, R J	7905190194 7905110292	50-320 50-320	
MANBER, W. C MANBER, W. G	7905250535 7905150024	70-143 70-143		MATTEON, R J	7905190250	50~32Q	
MANSER, W C	7905240344	70-143		MATTSON, R. J MATTSON, R. J	7905110219 7905110282	50-320 50-320	
MANZER, N MARCHI, M L	7905240279 7905300399	50~275 50~305		MATTBON, R. J MATTBON, R. J	7908230070 7905300075	50-320 50-320	
MARCHEBE, A	7904270399	50-320		MATTEON, R J	7905210092	50-320	
MARGOLIB.K R MARINOS.E C	7905230789 7905090210	50-275 50-320		MATTRON, R. J MATTRON, R. J.	7905190172 7905080364	50-320	
MARINO, OP MARINO, OP	7905110351 7905110343	50-320 50-320		MATTEON, R J.	7905160091	50~320	
MARKI J. C	7905290262	OD GRD		MATTSON, R. J MATTU, R	7905220455 7905080051	50-320	NUREG-0484
MARKIND.J MARKOWSKI.R	7905100229 7905290126	50-334	NUREQ/CR-0724	MAUNEY, B R MAURA, F A	7903250500 7905070027	50-373	
MARKB, Q. H.	7905230104	50-255		MAXHELL, Q. F	7905090393	50-546	
MAROTTA, C R MAROTTA, C R	7905300433 7905300434	50-320 50-320		MAY, E. L. MAY, E. L.	7905150428 7905150437	50-29 50-29	
MARGUARDT, PA MARGUARDT, PA	7905150285 7905310451	50-452 50-16		MAY, E L	7905190128	50-29	
MARRANZINO, A P.	7905150481	50-274		MAY, H. MAY, K. N	7905300394 7905230814	50-270	
MARRIOTT, P. W. MARRIOTT, P. W.	7905210328 7905210324	50-320 50-320		MAYER, B M. MAYER, L C.	7905240120 7905020236	50~466 50~282	
MARRIOTT, D MARRONE, J	7905150061 7905020274	40-8698		MAYER, L. D.	7905040415	50-263	
MARECH, R	7905210057	50-320 50-320		MAYER, L. O MAYER, L. D.	7905090369 7905010509	50-263 50-282	
MARSHALL:E M MARTIN:A.	7903020232 7905230751	50-445 50-466		MAYER, L. O. MAYER, L. O	7905010474 7905030364	50-282	
MARTINEZ, F P.	7905140326	THE		MAYER, L. O.	7905080413	50~263 50~263	
MARTIN, J E Martin, W. G.	7904180179 7905220087	70-135		MAYER,L. () MAYER,L., ()	7905040011 7905070366	50-263 50-263	
MARTINIH G. Martinih G	7905110029 7905230277	70-820		MAYER, L. O	7905070459	50-282	
MARTIN, W. O	7905240775	70-33 70-135		MAYER, L. O. MAYER, L. O.	7905080543 7905080424	50-202 50-263	
Martin, H. Q Martin, H. Q.	7905240277 7905220072	50-225 70-135		MAYER, L. O.	7905090388	50-263	
MARTIN: W. G	7905240756	70-135		MAYER, L. O MAYER, L. O	7905110127 7905150496	50-282 50-282	
MARTIN.R.D MARTIN.R D	7905090135 7905010467	50-330 50-395		MAYER, L. O MAYER, L. O.	7905160352 7905160379	50-262 50-263	
MARTINIR D. MARTINIR D	7905240480 7905240491	90-124		MAYER, L, O	7903130466	50-262	
HARTIN, R. D,	7905240534	50-327 50-339		MAYER, L. O. MAYER, L. O	7905190033 7905210279	50~263 50~263	
MARTIN, L. E. Martin, J. B.	7905010383 7905080087	50~498		MAYER, L. O.	7905220114	30-306	
MARTIN, J. B.	7905080101			MAYER, L. O. MAYER, L. D	7905240560 7905300406	50-243 50-262	
MARTIN, R MARTIN, R.	7905210295 7905230088	50-320 50-320		MAYOR, L. O. MAZZONE, J	7905240681 7905020383	50-243	
MARX.D J.	7905070588	50-271		MGBREARTY, R. A	7905040156	50-293 50-387	
MASCIULLI:S MASCIULLI:S	7905190018 7905190025	50-3 50-3		MCBREARTY, R. A. MCBRIDE, M. F.	7905240673 7905240195	50-322 50-485	•
MASRI, S. F. MASSE, R. E.	7905030051			MGBRIDE, M, F.	7905150074	50-465	
MASTERSON, D. J.	7905150163 7 <del>9</del> 05250016	50-15 <i>6</i> 71-205		MCGABE, E, C MCGABE, E, C,	7905110217 7905110394	50-219 50-271	
MASTERBON, D. J. MASTER, V. P	790525001 <i>9</i> 7905090085	71-205 50-592		MGCABE, E, C. MGCABE, E, C.	7905240704 7905290120	50-245	
				**************************************	TOORTOIRE	50-277	

Color   Colo	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	POCKET NUMBER	REPORT NUMBER
CAMPILL   7   700000000   50-207   700000000   50-207   700000000   50-207   700000000   50-207   700000000   50-207   700000000   50-207   700000000   50-207   700000000   50-207   700000000   50-207   700000000   50-207   700000000   50-207   700000000   50-207   700000000   50-207   700000000   50-207   700000000   50-207   700000000   50-207   700000000   50-207   700000000   700000000   700000000   700000000						7905290546		
## CALLED   7   7   7   7   7   7   7   7   7								
C.C.					MERICOLD.C.	7905020054		
## CLEBRY D. 1700-2001 56 - 20-1873  **CLEBRY D. 1700-2001 56 - 20-1873  **CLEBRY D. 1700-2001 57 - 20-1844  **RITERIAL M. 1700-2001 50 - 20-0844	MOULINTOCK, R O	7905290165	30-1873		MERGON, S D	7905230356		
Marticle   10   7700210046   50-200   Marticle   10   Martic								
Marie   Processing   Processi	ACCLINIOCK R O	7905210246			METCALFE L J	7705090401		NUREQ/CR-0255
CODAL   1   790200123   50-464   FETGL   6   FETGL   6   79020013   50-201			50-466	NUREG/CR-0649			50-320	NUREO / CP = 0.4.7.3
COMMAND   1   700300001   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71-004   71	MCCORNLE, B	7905310123	50-466		MEYERS, J E	7905250031		TONE OF THE PROPERTY OF THE PR
Proceedings   Proceedings   Processed			50-466					
COLORIDAD   700500001					MEYER, M B	7905100326	50-471	•
COMPAND   700000001   70-1173	POCORKLE: O H				MEYERS. 8 C		2U-275	NUREG/CR-0643
CCELLEST O							50-466	
CECHANIT   7	MCCRELESS, T. G.	7705140026	50-320		MICHELEON, C.	7905210232		
Transport   Tran								
## ## ## ## ## ## ## ## ## ## ## ## ##	ACCULLOUGH, H	7905160155	50-320		MI DDLETON: Q	_7905150594	40-8698	
F.C.   Proceedings			30-346			7905290070		
COURT   790310072   50-308								
MCOMPAN   77903700179   50-472	H; DONALO, T.	7905150757	50-358		MEDURA: H. J.	7905080489	50-272	
MCQAMAL   A						7905250421 7905250441		
March   Proposed   10	HODONALD, J A	7905090056	50-337		MIDURA, H J		50-272	
### ACCOUNTY OF THE PROPERTY O		7705090348	50-400		MIDURA, H. J	7905150295	50-272	
CFAMILY IN								
CAMPAT J   P. 190340041   P. 190310029   P. 19034003   P. 190310029   P. 190310	MOFARLAND, C R	7905230169	50-339		MIDURA, H J	7905300363	50-272	
CAMPIT J   7003100097   50-880								
CCAMPY J P	HCGARRY, J K	7905110040	70-2623		MIHURBKY.J A	7905300270	50-206	
School   7-908-2006-1   90-491							50-382	
SCAMPIN J P		7905150440	70-2623		MILHOLLIN, O.L.			
RÖJBER J P. 790310539 50-416 HILLER II. C. 790320540 30-222  RÖJBER J P. 79030455 50-416 HILLER II. C. 790310550 50-272  RÖJBER J P. 79030451 50-416 HILLER II. C. 790310550 50-272  RÖJBER J P. 79030451 50-416 HILLER II. C. 790310550 50-272  RÖJBER J P. 79030451 50-416 HILLER II. C. 790310550 50-272  RÖJBER J P. 79030451 50-416 HILLER II. C. 790310550 50-272  RÖJBER J P. 79030451 50-416 HILLER II. C. 790310550 50-272  RÖJBER J P. 79030452 50-422  RÖJBER J P. 79031055 50-422  RÖJBER J P. 790310550 50-423  RÖJBER J P. 7	acqaary, J M	7905290475	50-48日		MILHOLLIN, O. L	7905150681	50-27	
Miller   F.   7700300455   50-416								
MCANAPH J P	HCGAUGHY, J. P.	7905020455	50-416		HILHOLLIN, Q L	7905140568		
MONORING   P					MILHOLLIN, G L	7905140558	50~272	
MAILER   1								
March   Marc	HCGAUCHY, J P	7905040636	50~41 <b>6</b>		MILLER.H I	7905100147	50~255	
March   Marc							50~492	
NOTE   1	HCGGRUH, H B	7905240433			MILLER, J H.			
KÖQIJER, P. J.         7903002048         50-293         HILLER, H. E.         7903020480         50-449           KÖQIJER, P. J.         7901140240         50-293         HILLER, H. E.         7903200131         50-403           KÖQIJER, P. J.         7903140340         50-293         HILLER, H. E.         7903201081         50-443           KÖQIJER, P. J.         7903200393         50-293         HILLER, H. E.         7903201071         50-343           KÖQIJER, P. J.         7903200472         50-293         HILLER, H. E.         790320041         70-2630           KÖQIJER, P. J.         7903200473         50-293         HILLER, H. E.         790320048         70-2630           KÖQIJER, P. J.         7903200493         50-293         HILLER, H. E.         790320044         70-2630           KÖQIJER, P. J.         7903200618         50-293         HILLER, H. E.         790320064         70-2630           KÖQIJER, P. J.         7903200619         50-294         HILLER, H. E.         790320064         70-2630           KÖQIJER, P. J.         7903200619         50-498         HILLER, H. E.         7903200673         50-448           KÖQIJER, P. J.         7903200619         50-498         HILLER, H. E.         7903200673         50-449 <td>HCGRATH, E J</td> <td></td> <td></td> <td></td> <td>HILLEN, C. K</td> <td>7905150800</td> <td>50~267</td> <td></td>	HCGRATH, E J				HILLEN, C. K	7905150800	50~267	
Modeling   J								
KOUIRE, P. J. 7903150355   50-293	MCGUIRE P J.	7905140244	50-293		MILLER, M. E	7905290131		
MOURE, P. J						7905100412	50-445	
NOTIFIED   1							50-329	
RODIEL   F   790320399   50-46	HCQU(RE, P J	7905300472	50-293		MILLER, M E	7905220048		
KORREN, H. J.   7903800316   50-498   HILLER, H. E.   790310078   50-445   KORREN, H. J.   790330061   50-498   HILLER, H. E.   790330677   50-445   KORREN, H. J.   790330072   50-498   HILLER, H. E.   790330677   50-445   KORREN, H. J.   790330072   50-421   HILLER, H. E.   790340875   50-427   KORREN, H. J.   790330072   50-421   HILLER, H. E.   790330673   50-327   KORREN, H. J.   790310354   50-170   HILLER, H. E.   790330353   50-310   KORREN, H. J.   790310367   70-820   HILLER, H. E.   790330363   30-310   KORREN, H. J.   790310367   70-820   HILLER, H. E.   79033067   30-310   KORREN, H. J.   790310367   70-820   HILLER, H. E.   79033068033   30-310   KORREN, H. J.   79031031   30-320   HILLER, H. E.   79033068033   30-312   KORREN, H. J.   790320131   30-320   HILLER, H. G.   790350064247   50-348   KORREN, J.   790320131   30-320   HILLER, H. G.   790320033   30-312   KORREN, J. J.   790320131   30-320   HILLER, H. G.   790320033   30-312   KORREN, J. J.   790320131   30-320   HILLER, H. G.   790310019   40-8584   KORREN, J. J.   790320131   30-320   HILLER, H. G.   790310019   40-8584   KORREN, J. J.   790320131   30-320   HILLER, H. G.   790310019   40-8584   KORREN, J. J.   790320131   30-320   HILLER, H. G.   790310019   40-8584   KORREN, J. J.   790320131   30-320   HILLER, H. G.   790310019   40-8584   KORREN, J. J.   790320131   30-320   HILLER, H. G.   790320030   30-311   KORREN, J. J.   790320131   30-320   HILLER, H. G.   790320030   30-312   KORREN, J. J.   790320131   30-320   HILLER, H. G.   790320030   30-312   KORREN, J. J.   790320131   30-320   HILLER, H. G.   790320030   30-312   KORREN, J. J.   790320131   30-320   HILLER, H. G.   790320030   30-312   KORREN, J. J.   790320131   30-320   HILLER, H. G.   790320030   30-313   KORREN, J. J.   790320031   30-320   HILLER, H. G.   790320030   30-320   H						7705150663		
No. Comment   J.   7903200044   50-498		7905250386	50-499				50-445	
Miller, H. E.   790310354   790320392   790310363   790310393   790320363   790320363   790320363   790320363   790320363   790320363   790320363   790320363   790320363   790320363   790320363   790320363   790320363   790320363   790320363   790320363   790320363   790320363   790320363   790320363   790320363   790320363   790320363   790320363   790320363   790320363   790320363   790320363   790320363   790320363   790320363   79032036   79032036   79032036   79032036   79032036   79032036   79032036   79032036   79032036   79032036   79032036   79032036   79032036   79032036   79032036   79032036   79032036   79032036   79032036   79032036   79032036   79032036   79032036   79032036   79032036   79032036   79032036   79032036   79032036   79032036   79032036   79032036   79032036   79032036   79032036   79032036   79032036   79032036   79032036   79032036   79032036   79032036   79032036   79032036   79032036   79032036   79032036   79032036   79032036   79032036   79032036   79032036   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   7903206   790320	PROGUMERAL H. J.	7905300044	50-498		MILLER, H. E	7905230677	50-445	
K.Y.MOC.P. D. 790310394 50-170 MILLER, M. E. 7903230963 50-510 MILLER, M. E. 7903230963 50-510 MILLER, M. E. 7903230970 50-510 MILLER, M. E. 7903230970 50-510 MILLER, M. E. 7903290020 50-510 MILLER, M. E. 7903290020 50-510 MILLER, M. E. 7903290020 50-297 MILLER, M. E. 7903290020 50-297 MILLER, M. E. 7903290020 50-320 MILLER, M. E. 7903290024 50-321 MILLER, M. E. 7903290024 50-321 MILLER, M. E. 7903290024 50-320 MILLER, M. E. 7903290024 50-321 MILLER, M. E. 7903290039 50-312 MILLER, M. E. 7903290039 50-312 MILLER, M. E. 7903290039 50-312 MILLER, M. E. 7903290039 50-320 MILLER, M. E. 7903290039 50-320 MILLER, M. E. 7903290039 50-311 MILLER, M. E. 790329039 50-311 MILLER, M. E. 790329039 50-311 MILLER, M. E. 790329039 50-320 MILLER, M. E. 790329039 50-320 MILLER, M. E. 790329039 50-320 MILLER, M. E. 790329039 50-321 MILLER, M. E. 790329039 50-320 MILLER, M. E. 790329039 50-320 MILLER, M. E. 790329039 50-320 MILLER, M. E. 790329039 50-321 MILLER, M. E. 7903290437 50-320 MILLER, M. E. 7903290424 50-321 MILLER, M. E. 790329039 50-322 MILLER, M. E. 7903290424 50-322 MILLER, M. E. 7903290424 50-320 MILLER, M. E. 7903290424 50-322 MILLER, M. E. 7903290424 50-320 MILLER, M. E. 7903290424 50-320 MILLER, M. E. 7903290327 50-320 MILLER, M. E. 7903290424 50-320 MILLER, M. E. 7903290327 50-320 MILLER, M. E. 7903290327 50-320 MILLER, M. E. 7903290329 50-320 MILLER, M. E. 79032903			ED 0/4					
Miller,   790510036   70-820   Miller,   E.   790520268   NCMINEY,   C.   790520036   S0-320   Miller,   H.   C.   790520036   S0-321   Miller,   H.   C.   790520036   S0-312   Miller,   H.   C.   790520036   S0-320   Miller,   H.   C.   790520036   S0-321   Miller,   H.   C.   790520037   S0-320   Miller,   H.   C.   790520036   S0-321   Miller,   H.   C.   790520036   S0-322   Miller,   H.   C.   790520036   S0-323   Miller,   H.   C.   790520036   S0-323   Miller,   H.   C.   790520036   S0-324   Miller,   H.   C.   790520036   S0-324   Miller,   H.   790520037   S0-324   Miller,   H.   790520030   Miller,   H.   790520030   Miller,   H.   790520030   Mille	MCINCOE, D. N	7905310356	50-170		MILLER, M E			
MILLER, H					MILLER, M. E.	7905290268		
MILLER, H			50-320					
MCCSARI, J. J. 7903210282 50-320 HILLER, H. D. 7903190290 50-261  MCCSARI, J. J. 790320319 30-320 HILLER, H. D. 7903190482 30-311  MCCSARI, J. J. 7903203184 50-320 HILLER, H. D. 7903190482 50-321  MCCSARI, J. J. 7903203163 50-320 HILLER, H. D. 7903190485 50-2819  MCCSARI, J. J. 7903203163 50-320 HILLER, H. D. 7903204100 50-315  MCCSARI, J. J. 7903203163 50-320 HILLER, H. D. 7903204100 50-315  MCCSARI, J. J. 7903203163 50-320 HILLER, H. D. 7903204100 50-315  MCCSARI, J. J. 7903203163 50-320 HILLER, H. D. 7903203193 50-321  MCTIERIAM, T. J. 7903203163 50-335 HILLER, H. D. 7903203193 50-321  MCTIERIAM, T. J. 790310310 50-335 HILLER, H. H. 7903203193 50-321  MCCAL, J. F. 790310310 50-322 HILLER, C. F. 7903110331 50-320  MCCAL, J. F. 790310372 50-322 HILLER, C. F. 7903110331 50-320  MCCAL, J. F. 790310372 50-322 HILLER, L. M. 7903040375 30-409  MCCAL, J. F. 790310312 50-322 HILLER, R. P. 790310313 50-320  MCCAL, J. F. 790310372 50-322 HILLER, R. P. 7903040375 30-409  MCCAL, J. F. 790310372 50-322 HILLER, R. P. 790310032 50-320  MCCAL, J. F. 790310313 50-320 HILLER, R. P. 790320400 50-387  MCCAL, J. F. 790310313 50-320  MCMARS, B. J. 790300270 50-206 HINER, R. P. 790320400 50-387  MCMARS, B. J. 7903000270 50-206 HINER, R. P. 790320400 50-387  MCMARS, B. J. 7903000270 50-206 HINER, R. P. 7903200082 HILLER, R. P. 790300034  MCMINDOUE, R. B. 790300034  MCMARS, R. J. 790300034 40-8698 HINDOUE, R. B. 79032000082  MCMARS, R. J. 790300034 40-8698 HINDOUE, R. B. 7903200008  MCMARS, R. J. 790300034 HINDOUE, R. B. 7903200008  MCMARS, R. B. 790320017 HINDOUE, R. B. 79032000008  MCMARS, R. B. 790320017 HINDOUE, R. B. 79032000008	HCHILLAN, Q. D.	7905010577	40~8698		MILLERIG O.	7905040267	50-348	
MCGSCAR, J. J.   7908210319   50-320					KILLER, W. O.	7905150290	50-261	
MCSCAR, J. J. 7903230154 50-020 MILLER, M. O. 790510486 50-0289 MILLER, M. O. 7905240100 50-0315 50-0320 MILLER, M. O. 7905240104 50-0249 MILLER, M. O. 7905103104 50-0249 MILLER, M. O. 7905240980 70-0311 MILLER, M. M. 7905240980 50-0311 MILLER, M. M. 7905240980 50-0311 MILLER, M. M. 790510031 50-0320 MILLER, C. F. 790510031 50-0320 MILLER, C. F. 790510031 50-0320 MILLER, S. 7905240124 50-466 MILLER, S. 790510032 50-0320 MILLER, S. 7905240124 50-466 MILLER, S. 790510310372 50-0320 MILLER, M. 7905040375 30-409 MILLER, M. 7905040375 30-409 MILLER, M. 7905040375 30-409 MILLER, S. 7905240040 MILLER, S.	MCOSCAR, J. J.	7905210319	50-320		MILLER.W G			
RCGGGR, J. J. 7905230143 50-320   HILLER, W. O. 7905130104 50-267   RCDGGR, J. J. 7905220414 50-320   HILLER, W. O. 7905130104 50-267   RCTIERMAN, T. J. 7905130130 50-3359   HILLER, W. H. 7905290398 70-371   RCTIERMAN, T. J. 7905130130 50-3359   HILLER, W. H. 7905290398 50-281   REARS, D. B. 7905140159 50-522   HILLER, D. F. 7905230426 50-331   REARS, D. B. 7905140161 50-522   HILLER, D. F. 790510311 50-320   RECGL, J. E. 7905140347 50-522   HILLER, B. R. 7905240124 50-466   RECGL, J. E. 790510372 50-522   HILLER, L. M. 7905040500 50-327   RECGL, J. E. 7905310372 50-522   HILLER, L. M. 7905040500 50-327   RECGL, J. E. 7905310372 50-522   HILLER, B. 790500207 50-409   RECGL, J. E. 7905310393 50-522   HILLER, B. 790500224 50-409   RECGLA, J. E. 7905310393 50-522   HILLER, B. 790500224 50-327   RECGLA, J. E. 7905300370 50-206   HILLER, B. 7905200400   RECGLA, J. E. 7905300374   RECGLA, J. E. 7905300375   HINDOUE, R. B. 7905300082   RELIGNITO, L. E. 7905300339   SO-471   HINDOUE, R. B. 7905300032   RELIGNITO, L. E. 7905300339   SO-320   RELIGNITO, L. E.	MCOSCAR, J. J.	7905230154	50-320		HILLER, W. O.	7905150486	50-289	
## PASS					MILLER, W. O. MILLER, W. O.			
HEARS, D. B. 7905140159 50-522 MILLER, D. F. 7905100345 50-331 HEARS, D. B. 7905140159 50-522 MILLER, C. F. 790510031 50-320 HECCA, J. E. 7905160347 50-522 MILLER, B. 790540050 30-327 HECCA, J. E. 790510372 50-522 MILLER, C. F. 7905040575 30-466 HECCA, J. E. 790510373 50-522 MILLER, C. F. 7905040575 30-407 HECCA, J. E. 790510383 50-522 MILLER, B. 7905040575 30-407 HECCA, J. E. 790510383 50-522 MINER, B. 7905040274 50-387 HECCA, J. E. 79051030270 50-206 MINER, B. 7905240806 50-387 HECKA, B. J. 7905300277 50-206 MINER, B. 7905240806 50-387 HECKA, B. J. 7905300374 HINDOUE, R. B. 7905800082 BECY-78-524 HECROTO, L. E. 7905300134 40-9698 MINDOUE, R. B. 7905800082 BECY-79-187 HEIRRITO, L. E. 790500134 50-471 MINDOUE, R. B. 7905200008 HEIRRITO, L. E. 790510593 50-471 MINDOUE, R. B. 7905200008 HEIRRITO, L. E. 790510593 50-320 HEIRRITO, L. E. 790510593 50-361 MINDOUE, R. B. 7905200022 HEIRRITO, L. E. 7905300314 MINDOUE, R. B. 7905200022 HEIRRITO, L. E. 7905300314 MINDOUE, R. B. 7905200322 HEIRRITO, L. F. 7905300314 MINDOUE, R. B. 7905310015 MINDOUE, R. B. 7905310015 MINDOUE, R. B. 7905300608	PCT (ERNAN, T. J.	7905220084	50~359		MILLER,W O	7905230850		
MEMSIO 8, 7905140161 50-582 MILLER, C. F 790510031 50-320 FECCAL, J. E. 7905160347 50-522 MILLER, B. 7905240124 50-466 50-522 MILLER, B. 7905240124 50-466 50-522 MILLER, B. 7905240124 50-466 50-527 FECCAL, J. E. 7905310383 50-522 MILLER, L. M. 7905040375 50-607 50-522 MILLER, L. M. 7905040375 50-409 FECCAL, J. E. 7905310383 50-522 MILLER, B. 7905040375 50-409 FECCAL, J. E. 7905310383 50-522 MILLER, B. 7905304070 50-624 MILLER, B. 7905304070 50-624 MILLER, B. 7905304050 FECCAL, J. E. 7905300277 50-624 MILLER, B. 7905304050 FECCAL, J. E. 7905300374 FECCAL, J. E. 79053000374 FECCAL, J. E. 7905300374 FECCAL, J. E. 7905300375 FECCAL, J. E. 7905300303 FECCAL, J. E. F.	HEANS, D. B.		50-335 50-522		MILLER, D. F.	7905230426	50~331	
PECCA J E 7703290457 50-522 HILLE, L. M 7905040500 50-327  PECCA J E, 7905310383 50-522 HILLE, L. M 7905040375 50-409  PECCA J E, 7905310383 50-522 HILLE, L. M 7905040375 50-409  PECCA J E, 7905310383 50-522 HILLE, L. M 7905040375 50-409  PECCA J E, 7905300370 50-826 HILLE, L. M 7905040375 50-409  PECCA J E, 7905300370 50-826 HILLE, L. M 7905040375 50-409  PECCA J E, 7905300370 50-826 HILLE, L. M 7905040375 50-409  PECCA J E, 7905300374 FILLE, L. M 7905040375 50-409  PECCA J E, 7905300374 FILLE, L. M 7905040375 50-409  PECCA J E, 7905300374 FILLE, L. M 7905040375 FILLE, L. M 7905040375 FILLE, L. M 7905040375 FILLE, L. M 7905040374  PECCA J E, 7905040372 FILLE, L. M 7905040375 FILLE, L. M 7905040375 FILLE, L. M 7905040375 FILLE, L. M 7905040374  PELEBOTTO, L. E, 7905040473 FILLE, L. M 10004E, R. B, 7905040034  PELEBOTTO, L. E, 7905040473 FILLE, L. M 10004E, R. B, 7905040034  PELEBOTTO, L. E, 7905040473 FILLE, L. M 10004E, R. B, 7905203042  PELIS, R L 790510553 FO-361  PENCIER, R B, 7905300303  PELIS, R B, 7905300414  PENCIER, R B, 7905300414  PENCIER, R B, 7905300414  PENCIER, R B, 7905300414  PENCIER, R B, 790530077		7905140161	50-522					
PECCALUE, 790310383 50-522 MINER: 8 7905100224 80-387  PECKALAS: B. J. 7903300277 50-206 MINER: 8, 790320806 50-387  PECKALAS: B. J. 7903300277 50-206 MINER: 8, 790320400 8ECY-78-624  PEDEROS: M. 8. 7903300374 MINER: 8, 7903800039 8ECY-78-133  PECROS: M. 8. 790300314 40-9698 MINER: 8, 7903800082 8ECY-79-187  ME IEROTTO, L. E. 790300134 40-9698 MINDOUE: R. B. 7903100036  PEIROTTO, L. E. 790310833 50-471 MINDOUE: R. B. 7904270178 50-320  PEIROS: M.	MECCA, J E	7905250459	50-522		HILLE, L. M	7905040500	50-327	
#ECKILAB, B. J. 7905300270 50-206 HINGOLE, R. B. 7905204080 50-387  #ECRIVA, B. J. 7905300277 50-206 HINGOLE, R. B. 7905204080 8ECY-78-624  #ELEROS, H. B. 7905300374 HINGOLE, R. B. 7905300039 8ECY-78-130  #ELEROTTO, L. E. 7905300134 40-8678 HINGOLE, R. B. 7905100034  #ELEROTTO, L. E. 7905040473 30-471 HINGOLE, R. B. 7905100034  #ELEROTTO, L. E. 790510533 50-361 HINGOLE, R. B. 7904270376 50-320  #ELLON, K. 790510533 50-361 HINGOLE, R. B. 7905203042  #ELKER, R. B. 7905300414 HINGOLE, R. B. 7905203022  #ENCIER, R. B. 7905300414 HINGOLE, R. B. 7905200302  #ENCIER, R. B. 7905300414 HINGOLE, R. B. 790520015 50-320  #ENCIER, R. B. 7905300717 HINGOLE, R. B. 7905200680					MINER, B	7905100224	50-387	
HENGROW, H. B. 7905300374 HENGOLF, R. B. 790530039 HEROW, L. A 790510170 HEROW, L. E. 7905300374 HINDOUE, R. B. 790510032 HEROTTO, L. E. 790500134  ME IEROTTO, L. E. 7905000134  ME IEROTTO, L. E. 790510033 HINDOUE, R. B. 790510034  ME ISS, R. L 790510033 HINDOUE, R. B. 7904270376  MELLON, K 790510533 SO-361 HINDOUE, R. B. 7905203040  MELLON, K 7905300414 HINDOUE, R. B. 7905203032  MENCIER, H. B. 7905300414 HINDOUE, R. B. 790520015  MENCIER, H. B. 7905300414 HINDOUE, R. B. 790520015  MENCIER, H. B. 7905300414 HINDOUE, R. B. 790520015  MENCIER, H. B. 7905300414 HINDOUE, R. B. 7905300405  MENCIER, H. B. 7905300414 HINDOUE, R. B. 7905300405  MENCIER, H. B. 7905300415 HINDOUE, R. B. 7905300405  MENCIER, H. B. 7905300415 HINDOUE, R. B. 7905300405  MENCIER, H. B. 7905300415  MENCIER, H. B. 7905300410  MENCIER, H. B. 7905300415  MENCIER, H. B. 7905300410  MENCIER, H. B. 7905300410  MENCIER, H. B. 7905300405  MENCIER, H. B. 7905300405  MENCIER, H. B. 7905300410  MENCIER, H. B. 7905300405   HECHALAS, B. J.	7905300270	50-204		MINER, 8.	7905240806	50-367	BECY-79-624	
METERRITO, L. E. 790300194 40-8698 MINDOUE, R. B. 7903100036 METERRITO, L. E. 790300473 30-471 MINDOUE, R. B. 790427017B 50-320 METERRITO, L. E. 7905150803 S0-471 MINDOUE, R. B. 790427017B 50-320 METERRITO, L. E. 790510833 S0-361 MINDOUE, R. B. 7905230408 MENCHER, M. B. 7905300303 MINDOUE, R. B. 7905230422 MENCHER, M. B. 7905300414 MINDOUE, R. B. 7905230422 MENCHER, M. B. 790530717 MINDOUE, R. B. 7904300260 MENCHER, M. B. 790520717 MINDOUE, R. B. 7903100260 MENCHER, M. B. 790520717 MINDOUE, R. B. 7903100260	MEDEIROS, M B.	7905300374	20~208		MINDOUE, R. B.	79050B0035		8ECY-78-13C
RETERDITO, L. E. 7908040473 50-471 MINOQUE, R B 7904270178 50-320 MINOQUE, R B 7904270178 50-320 MINOQUE, R B 7905200608 MINOQUE, R B 7905200600 MINOQ		7905140170	40-8408			7905100034		8#C1-/4-18/
MELLON, K 790300533 50-361 MINOGUE, R B. 7905230608 MENCIER, H, B. 7905230414 MINOGUE, R, B. 7905210015 50-320 MENCIER, H, B. 7905230717 MINITADA, N. J. 7904300260 MENCIER, H, B. 7905290431 MIRAGLIA, F, J. 7905110139 50-320	ME LEROTTO, L. E.	7905040473			MINDQUE, R B	7904270178		
MENCIER, H. B. 7905300303 HINOGUE, R. B. 7905300322 MENCIER, H. B. 7905300414 HINOGUE, R. B. 7905310015 50-320 MENCIER, H. B. 7905230717 HINITINOA, M. J. 7904300260 MENCIER, H. B. 7905290431 HIRAGLIA, F. J. 7905110598 50-320	MELLON, K		50-361		MINOQUE, R B.	790523060B	JU-34V	
MENCIER, H. B. 7905230717 HINZINGA, N. J. 7904300260 MENCIER, H. B. 7905290431 HIRAGLIA, F. J. 7905110138 50-320		7905300303					50-320	
77007040	MENCZER, W B.	7905230717			minzinga, H. J.	7904300260		
			50-250			7905110322		

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
HIRAGLIA,F J	7904270152 7905110151	50-320		MOHRY,W R MUELLER,E E	7905300326 7905240132	50-466	
HIRAGLIA.F J	7905110126 7905070005	50-320 50-320		MUGLLER,R MULKEY,M E	7905300557 7905030048	50-265 50-133	
HIRACLIA, F J HIRACLIA, F J	7905110140 7905110121	50-320 50-320		MULLER,R E MULLEARY,T	7905250115 7905230169	50-320	
MIRAGLIA.F J Hiraglia.F Hishiha.J	7905110119 7905100335	50-320 50-320	2000/2012	MULLINS, C B MULLON, T. P	7905140572 7905140201	50-131	NUREO/CR-0539
HITCHELL, D Q	7905150777 7905230376	50-289	7905150777	MUMPER, H J MUNDTH, L. K	7905250509 7905110150		
MITCHELL,DO MITTL,R L	7905220325 7905290384 7905070552	50-289 50-289 50-354		MURDOCK,L T MURDOCK,L T	7905030136 7905030132	40-299 40-299	•
HITTLIR L	7905040519 7905060481	50-311 50-311		MURLEY, T E MURLEY, T E	7905140017 7905110283	50-320	
KITTL,R L KITTL,R L	7905090308 7905220349	50-311 50-272		MURPHY, P M MURPHY, P M	7905140504 7905090185	50~554 50~554	
HITTLIR L HITTLIR L	7905250100 7905250415	50-311 50-311		MURPHY, J D.	7905250284 7905290148	50-454 71-1	
MOELLER, D W MOELLER, D W	7705140164 7705030161			MURPHY, C E	7905290146 7905070590	71-1 50-316	
MOELLER, D W MOELLER, D W	7905140019 7905160250			MURPHY, C E, MURPHY, C E	7905010418 7905290112	50-302 50-395	
MOLYNEUX, E L	7905150766 7905150763	71 <del>-</del> 309 71-309		MURPHY, C, E MURPHY, C E	7905240498 7905240661	50-518 50-324	
MONDICS, D MONTGOMERY, D M	7905220428 7905210305	50-320 50-320		MURPHY,C E Murphy,C E Murphy,C,E	7905010403 7905020326	50-302 50-369	
MONTI, W A	790522037 <i>6</i> 7905030185	50-3 50-309		MURPHY, C E	7905020435 7905020097	50-327 50-391	
MOODY, DE MOODY, DE	7905150516 7905300019	50-309 50-309		MURPHY, C E	7905070352 7905230740	50-369 50-566	
MOODY, D E	7905070693 7905080423	50-271 50-271		MURPHY, C. E MURPHY, C. E	7905010235 7905070115	50-38 <del>7</del> 50-281	
MOODY, D E	7905070462 7905160253	50-271 50-271		MURPHY, C E	7905230129 7905240292 7905290383	50-339 50-327	
MOGDY, D E	7905150341 7905080075 7905250359	50-271 50-29		MURPHY, C E MURPHY, C. E	7905230137 7905090424	50-261 50-369	
MOODY, D E MOORE, D	7905150334 7905020281	50-29 50-29		MURPHY, C E MURPHY, C E	7905150802 7905150072	50-395 50-390	
HOORE, J D HOORE, J B	7905080517 7905110077	50-320 50-375	ESG-79-7	MURPHY, C E	7705230726 7905240464	50-518 50-491	
MOORE,T C MOORE, G N	7905250510 7905010532	30-6134 50-334		HURPHY, C E	7905250422 7905240514	50-395 50-518 50-348	
MOORE, O C	7905010537 7905150206	50-334 50-302		MURPHY, C. E MURPHY, C. E	7905240525 7905240500	50-491 50-424	
HOORE, J B	7905090277 7905080418	50~361 50~206		MURPHY, C. E MURPHY, C. E	7905020285 7905020074	50-369 50-391	
MOORE, J B MOORE, H O MOORE, R N	7905310423 7905070554	50-361 50-327		MURPHY, C. E MURPHY, C. E	7905080325 7905230698	50-400 50-566	
HOORE, R N HOORE, R N	7905240021 7905230634			MURPHY.C E. MURPHY.C E	7905250017 7905140162	50-400 50-413	
HOORE, H	7905230716 7905250323			MURPHY, J A	7905290361 7905210027	50-320 50-281	
HOORE, J E HOORE, T F	7905150180 7905150187	50-272 50-272		MURRAY, T D MURRAY, T D MURRAY, T D.	7905100380 7905100341	50-346 50-346	
HOORE, J E HOORE, J E	7905150192 7905220038 7905100150	50-272 50-272		MURRAY, T D MURRAY, T D	7905020266 7905100286	50-346 50-346	
MOORE, J E MOORE, R	790506019B 7905090220	50-549 50-284 50-320		MURRAY, T. D. MURRAY, T. D	7905020303 7905020418 7905020488	50-346 50-346	
HOORE, R HOORE, R H	7905090224 7905090216	50-320 50-320		MURRAY, T D MURRAY, T D	7905020427 7905020443	50-346 50-346	
MOORE, V A MORIARTY, J M	7905110013 7905100099	50-376 50-423		MURRAY, T. D. MURRAY, T. D	7905040129 7905090249	50-346 50-346 50-346	
MORIARTY, J M MORIARTY, J M MORIN, H F	7905100103 7 <del>9</del> 05100107	50-412 50-395		MURRAY, T. D.	7905140233 7905150455	50-346 50-346	
MORIN, J P MORRIS, K J	7903290210	50-338 50-322		MURRAY, T. D MURRAY, T. D	7905140404 7905220124	50-346 50-346	
MORRIS, K J. MORRIS, K J.	7705080446	50-295 50-285		MURRAY, T. D MURRAY, T. D	7905220096 7905220117	50-346 50-346	
MORRIS,K J MORRISSEY, J C	7903240562	50-285 50-285	,	MURRAY, J F	7905250134 7905100406	50-346 50-320	
MORRISSEY, J. C MORRILL, P. Q	7905300007	50-275 50-275		MURRAY, J. P MURRAY, B MURTAGH, W, J	7905160208 7905100266	50-320 50-267	
MORTON, K V MORTON, K V	7905140105 7905040034	50-275		MUSCARA, J. MYERS, J. A.	7905240258 7905110319	40-8681 30-320	
HORTON, K. V.	7905030184 7905150109			MYNATT, A MYNATT, A	7905150101	\$0-320	
MORTON, K V MORTON, K V MORTON, K V	7905030234 7905040069			MYNATT, A. NAIDUK, R	7905140099 7905030226 7905150535		
MORTON, K. V. MORTON, K. V.	7905040090 7905030203			nakatani, t. Napuda, q	7905250333	\$0-358 \$	
HORTON, K. V. HORTON, K. V.	7905040052 7905240125			NARBUT, P. P NARDI, A. J	7905130620	50-247 50-528	
HORTON, K. V. HORTON, K. V	7905230690 7905240420 7905240447			NARDI, A. J. NATARAJA, M.	7705250314	70-1084 70-1084 80-409	
MORTON, K V.	7905230702 7905240669			NAUGHTON, W. F.	7905070396	00-107 10-295 10-897	
MOSCHNER, R A MOSELEY, N C MOSELEY, N C	7905230730 70 7905110187 50	0-754 0-320		NAUGHTON, W. F. NAUGHTON, W. F. NAUGHTON, W. F.	7905170246 7905240664	50-599 50-899	
MOSELEY, N C	7905110184 80 7905110421 80	0-320 0-329		NAUGHTON, W. F. NAUGHTON, W. F.	7905150351 5 7905170264 5	0-454 10-599	
HOSELEY, N. C. HOSELEY, N. C.	7905160216 30 7905110420 80	0-320 0-329		NAVGHTON, N. F NAYLOR, R. W	7908310393	10-295 10-599	
MOSELEY, N C	7905160209 30 7905110413 50	0-320 0-320		NEAL, 8, L NEELY, D, R	7905020101 5 7905020149 5	0-346  0-488	
MOSLEY, N.C.	\A02190579 90	0-320 0-500		NEELY, D. R. NEIGHBORB, D.	7905290196 5	0-277 0-3	
HOTT, W. E HOWRY, W. R.	7905300490 71	)-335  -5908		NEIGHBORS, J. D. NEIGHBORB, J. D.	7905150789 5	0-580 0-580	
MOHRY, H. R. MOHRY, H. R.	7905150208 7905300321	-6346		NEIGHBORB, D. NEIL, R. M.	7905290405 5	0-280 0-280	
				MCI TO N. M	7905030074 5	0-338 0-373 0-320	
					•-		

	Accession		_		<b>-</b>		34
AUTHOR	ACCESS ION REMUM	NUMBE NUMBE			ACCESSION	*****	
NELSON, D. D.	7905240602			ACHTUA.	NUMBER	DOCKET	REPORT
NELSON, J M	7905020500	2 50-315 50-346		O'NEILL, J H	75055		NUMBER
NELBON, J M.	7905160409	9 50-346		D'NEILL, J, H	7705140255 7705140261	50~400	
NELSON, J M NELSON, C C.	7905250142	2 50-346		O'REILLY, J P.	7905070460	50~400 50-250	
NELSON C C	7905070373 7905240367	50-309 50-309		O'REILLY, J P.	7905150103	30-239	
NELEON, C A	7905020101			O'REILLY, J P	7905010158 7905010161	50-437	
NEMETHY, E NEUMAN, J R	7905240625			O'REILLY, J P.	7905010168	50-348 50-261	
NEWACHECK, R L	7905250328 7905240357			O'REILLY, J P	7905010177	50-269	
NEHMAN, J R	7905240043	50-466		O'REILLY, J P.	7905010193 7905010192	30-413	
NEHMAN, J R	7905080387 7905080331			O'REILLY, J P	7905010198	50-250 50-302	
NEWHAN, J R	7905250170			O'REILLY, J P	7905010200 7905010204	50-321	
NEWMAN, J R NEWMAN, J R	7905080311	50-466		O'REILLY, J P	7905010205	50-416 50-395	
R LIAMHAN	7905080320 7905250230	50-466 50-466		O'REILLY, J P	7905010211	50-259	
NEHMAN, J R.	7905250225	50-466		O'REILLY, J. P	7905010224 7905020404	50~280	
NEWMAN, J R NEWMAN, J R	7905300046	50-466		D.WEILTA' D 6	7905030290	50-302 50-348	
NEWMAN, J R	7905310407 7905290068	50-466 50-466		O'REILLY, J P.	7905030294	50-261	
NEHMAN, J R	7905070239	50~466		O'REILLY, J P	7905030301 7905030307	50-413	
NEWMAN, J R NEWMAN, J R	7905140057	50-466		O'AEILLY, J. P	7905030310	50-269 50-250	
NEHMAN, J. R	7905240310 7905100391	50-466 50-466		O'REILLY, J P.	7905030312	50-321	
NEWMAN, J. R. NEWMAN, J. R.	7905250239	50-466		O'REILLY, J P	7905030314 7905030317	50-416	
NEWMAN, R. I	7905290002 7905150674	50-498		O'REILLY, J.P	7905030319	50-395 50-280	
NEHMAN, R. I	7905220109	70-1821 40-3392		a LILLY, J. P	7705030323	50-437	
Newman, R I Nieschmidt, E. B	7905240867	71-277		O'REILLY, J P	7905010093 7905010095	50-348	
NIMITZ, R. L	7905100251 7905230750	50-285	NUREO/CR-0785	O'REILLY, J. P	7905010098	50-261 50-269	
NIMITZ, R L	7905110113	50-277 30-6134		D'REILLY, J. P	7905010102	50-302	
NIX, R. T NIX, R. T	7905150467	50-366		C'REILLY, J P	7905010104 7905010107	50~250 50~224	
MIX.R T	7905150525 7905300676	50-321		O'REILLY, J p	7705010113	50-321 50-259	
NOLAN, F.	7905100375	50-321 50-346		C) REILLY, J P	7905010123 7905010132	50-280	
NOLAN, F. NOLAN, F.	7905110006	50-312		O'REILLY, J P.	7905010132	50-332 70-143	
NOLAN, F	7905110200 7905140067	50-320 50-320		O'REILLY, J P.	7905010339	50-34g	
NORDERHAUG, L. R	7905100048	70-734		O'REILLY, J. P	7705010346 7705010350	50-325	
NORDERHAUG, L. R NORELIUS, C E	7905150289 7905020172	70-1257		O'REILLY, J P	7905010353	50~269 50~302	
NORTH, H. S	7905230464	50-329 50-323		O'REILLY, J P.	7703010358	50-250	
NORTHIN S NORTHIN S.	7905040366	50-344		O'REILLY, J. P	7905010360 7905010363	50-321	
NORTON, B	7905240768 7905300007	50-275		O'REILLY, J. P	7905010369	50-259 50-280	
HOSENZO, L., V	7705240875	50-275		O'REILLY, J P O'REILLY, J P	7703310017	50-302	
NOSENZO, L. V. NOSENZO, L. V	7905240883			O'REILLY, J P	7905020124 7905020125	50-348	
NOSENZO, L. V	7905240889 7905240897			O WEILTA' A B	7905020127	50-261 50-250	
NOSENZO, L., V	7905250054			O'NEILLY, J P	7905020133	50-339	
NOSENZO, L. V. NOSENZO, L. V.	7905150186			D'REILLY, J P	7905080534 7905070137	50-280	
MOSENZO, L. V	7905150123 7905150183			q ,L,YJJ139° D	7905070136	50-124 50-124	
NOSENZO, L V	7905150191			O'REILLY, J. P. O'REILLY, J. P.	7905070142	50-83	
NOSENZO, L. V NOSENZO, L. V	7905230301			O'REILLY, J. P.	7905070146 7905070148	50-111	
NOSENZO, L. V	7905150095 7905160234			O'REILLY, J P	7905070152	50-42 50-406	
NOSENZO, L. V	7905150807			O'REILLY, J P	7905070193	50-538	
NOSENZO, L. V NOSENZO, L. V.	7905160228			O'REILLY, J P.	7905070156 7905070159	50-129	
NOBENZO, L. V	7905230559 7905230575			n.ketrrain b'	7905030188	50-13 50-437	
NOSENZO, L. V.	7905230597			O'REILLY, J. P. O'REILLY, J. P	7905030198	50-375	
MOSENZO, L. V NOSENZO, L. V	7905230669			O'REILLY, J. P	7905030368 7905040141	30~259 50-00€	
NOSENZO, L. V	7905240431 7905250442			O'REILLY, J. P.	7905040145	50-335 50-437	
NOSENZO, L. V	7905230708			O.UEILLA' O b'	7905040148	50-348	
NOTLEY, D. P. NOVAKARD, D.	7705300428 7705270169	50-320		O'REILLY, J. P		50-261 50-269	
NOVAKOVICH, D	7905290573			O'REILLY, J P.	7905040185	50-413	
NOVAK, T. M. NOVAK, T. M	7905230281	50-320		O'REILLY, J P.	7905040209	50-302	
NOVAK, T. M.	7905230298 7905230109	50-320		O'AETLLY, J, P,		90-290 50-321	
NOVAK, T	7905110055	50~320		O'REILLY, J. P.	7705040223	00-416	
NOVAK, T. NOVARRO, J. P	7905110060			O'RETLLY, J P	7905040225 7905040233	50-395	
MOVARRO, J P.	7703240996 7703040439	50-322 50-322		O.WEILTA' 1 6		10-259 50-280	
NOVARRO, J. P. NOVARRO, J. P.	7905040318	20-355		O'REILLY, J. P. O'REILLY, J. P	7700040263	10~269	
NOVARRO, J. P	7905240639 7905080500	50-322		O'REILLY, J. P.	7903040271	80~413 80~280	
NOWICKI, B J	7905150154	20~355		O'REILLY, J. P. O'REILLY, J. P.	7905040281	10-261	
MONICKI, S. J. NUGENT, E. L.	7905100239	50-155		O'REILLY, J. P.	7905040298	84E-0i	
MUNN, C. N	7905100025 7905030342	40~2259		O'RETLLY, J. P.		10-302 10-302	
NUSSBAUHER, D A	7905230312	50-334 40-2407		O, WEITTA, Y' b' O, WEITTA, Y' b'	7905040308	0-250	
MUSSBAUMER, D. A. MUSSBAUMER, D. A.	7905230193	40-2407		O'REILLY, J'P	7905040312 5 7905040322 5	0-416	
NUSSBAUMER, D A	7700230177	40-2407		O'REILLY, J P.	7903040329 5	0-348 0-261	
MU68BAUHER, D. A	7905230342	40-2407 40-2407		O'REILLY, J P	7903040346 5	0-413	
MUSSSAUMER, D.A. MUSSSAUMER, D.A.	7905230183	40-2407		O'RETLLY, J. P	7905040381 5 7905040395 5	0-302 0-269	
NUBBBAUMER, D. A.	7905230291	40-2407 40-2407		O'REILLY, J P	7905040404 5	0~590 0~305	
MUSSBAUMER, D. A. NUSSBAUMER, D. A	7905230150	40-2407		O'REILLY, J P	7905040413 8	0-424	
MUTANT, J. A.	7705230670	40-2407		O'REILLY, J. P.		D-416 5-395	
MEYMAN, C J	7905310232	50~437 50-27		O'REILLY, J. P.	7905040448 8	0-580 3-340	
myguibt, R. O Ø "Brien, O. M.	7905250528	50-329	45-79/HI24AF	O'REILLY, J. P.	7905040457 5	J-437	
C) 'BRIEN, O, M	7705150675	50~10	THE PERSONAL PROPERTY.	O'REILLY, J. P.		7-327 7-324	
O'BRIEN, J,	7905110280	50-454 50-320		O'REILLY, J P.	7905150700 50	)~257	
CO CONNOR, L. A.	7905190075	50~245		O'REILLY, J P.	7905010317 50	)~33 <del>9</del>	
ID "CONNOR, P. W.	/700250097 *	50-320 50-10		O'RETLLY: J. P.	7905010335 50	)-400 )-369	
O'DELL, C. B. O'KEEFE, A. J	7905090417		NURFO /CD. ATT	O'REILLY, J. P.	7905010341 50	)-327	
w; A. U	7905160431 5	50-47	NUREQ/CR-0754	D'REILLY, J P.		)-413 )-424	
				O'RETULY, J. P.		-416	

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
O'REILLY, J P	7905010374	50~395		OPLINGER, G G	7905080145		
O'REILLY, J P	7905030133 7905030137	50-437 50-348		OPLINGER, O O OPLINGER, O O	7905150705 790522044B		
O'REILLY, J P O'REILLY, J P	7905030141 7905030153	50-261 50-413		OPLINGER, 0 0 OPLINGER, 0 0	7905220449 7905290127		
O'REILLY, J P	7905030160	50-269		DPLINGER, O O	7905290128		
O'REILLY, J. P	7905030162 7905030164	50-302 50-250		OPLINGER, G G OPLINGER, G G	7905290133 7905080174		
O'REILLY, J P	7905030165	50-321		OPLINGER, Q Q	7905150030 7905150040		
O'REILLY, J P O'REILLY, J P	7905030167 7905030169	50-416 50-3 <del>7</del> 5		OPLINGER, O O OPLINGER, O O	7905230524		
O'REILLY, J.P O'REILLY, J.P	7905030172 7905030191	50~259 50~338		OPLINGER, O O OPLINGER, O, O	7905240023 7905240050		
O'REILLY, J P	7905010324	50-403		OPLINGER, Q Q	7905290101		
O'REILLY, J. P O'REILLY, J P	7905010331 7905010337	50-364 50-389		OPLINGER, O O OPLINGER, O O	7905290186 7905100447		
O'REILLY, J P. O'REILLY, J P	7905010341 7905010356	50-391 50-489		OPLINGER, G G OPLINGER, G G	7905150029 7905150031		
O'REILLY, J P	7905020365	50-364		OPLINGER, G G	7905150032		
O'REILLY, J P O'REILLY, J P	7905020370 7905020373	50-348 50-324		OPLINGER, C C OPLINGER, C C	7905150033 7905150035		
O'REILLY, J P O'REILLY, J P	7905020426 7905020429	50-261 50-269		OPLINGER, G G OPLINGER, G G	7905150037 7905150038		
D.KEILTA' 1 b	7905020453	50-413		OPLINGER, 0 0	7905150804		
O'REILLY, J P	7905020460 7905020463	50-367 50-302		OPLINGER.G G OPLINGER.G G	7905150810 7905150813		
O'REILLY, J P	7905020465	50-335 50-321		OPLINGER, G. G OPLINGER, G. G	7905150815 7905150787		
O'REILLY, J P	7905020467 7905020472	50-416		OPLINGER, O O	7905250252		
O'REILLY, J P	7905020473 7905020475	50-395 50-395		OPLINGER, 0 0 OPLINGER 0, 0	7905250255 7905250257	'	•
D'REILLY, J. P	7905020479	50-259		OFLINGER, 0 0	7905250272		
O'REILLY, J P	7905020495 7905020496	50-327 50-280		OPLINGER, Q Q OPLINGER, Q, Q	7905250276 7905250282		
O'REILLY, J P O'REILLY, J P	7905020502 79051 <b>400</b> 95	50-339 50-437		OPLINGER, G G.	7905250287 7905250295		
O'REILLY, J P	7905290150	50-335		OPLINGER, Q, Q	7905250300		
OBERO,C R. OBLIGADO,A	7905010312 7905040375	50-482 50-409		OPLINGER. 0 0. Drgera, e. 0	7905250345 7905030205		BAW-10085 R3
OCHSTEIN.D S DESTMANN,M J	7905160410 7905090131	50-483 50-282		ORLOSKY, P M ORNSTEIN, H, L.	7905190019 7905140055	50-57 50-320	
OH, I.	7905090422		NUREG/CR-0642	ORNBTEIN, H	7705140252		
OKRENT, D OKRENT, D	7905030210 7905100052	50-320 50-320		ORTLOFF, G D OSTER, J	7905150070 7905210262	40-8102 50-254	
OKRENT, D OLDHAM, W A	7905190235 7905240619	50~320 50~201		OTTOBON, H.L. OTTOBON, H.L.	7905040592 7905240689	50-206 50-206	
DLMSTEAD, W J	7905310028	50~327		OVERMAN, R F	7905140267	50-320	
OLMSTEAD,W J OLMSTEAD,W J	7905160033 7905150240	50-320 50-329		OWEN, H. H	7905250156 7905050371	50-322 50-269	
OLSEN, A. F OLSEN, A. F	7903140411 7905140414	50-99 50-99		DWSLEY,O F PAGLIARD,J A.	7905080393 7905150646	70-1379	
OLSEN, A F OLSEN, A F	7905140409	50-77		PALLADINO, N. J.	7905230058	50-320	
OLSEN, A F	7905140383 7905110309	50-99 50-99		PANETTA, L E PAPADAKIS, C, N	7905300501 7905250530	50-320 50-329	45-79/HI24AF
OLSEN, A F OLSHAN, L	7905290427 7905310402	50-13 50-241		PAPERIELLO, C. J PAPERIELLO, C. J.	7905230144 7905230038	50-320 50-320	
OLSHAN, L. OLSHINSKI, J	7905240229 7905230172	50-247 50-320		PAPPAB, H PAPPAB, H	7905240997 7905140213		
OLSZANSKI,S M	7905240223	50-367		PAPWORTH, L. Q	7905010510	50-409	
ONGAVAGE, H. P	7905150182 7905150175	50-250 50-250		PAPWORTH, L G PAPWORTH, L G	7905010520 7905140234	50-409 50-409	
ONCAVACE, H P ONG. C.	7905290026 7905220416	50-250 50-320		PAPWORTH, L. O PARCELL, M	7905150530 7905160385	50~409 50-237	
ONSDORFF.K A OPEKA,J F.	7905240789 7905290076	50-272 71 <b>-</b> 9044		PARCELL, M.	7905300480	50-237	
OPEKA, J F	7903080456	50-336		PARIS, O. H. PARKER, D. L.	7905140567 7 <del>9</del> 05240178	50-250 50-446	
OPEKA, J. F OPEKA, J. F	7905150502 7905220395	50-334 50-245		PARKER, D. L. PARKER, W. O	7903240190 7905100299	50-466 50-269	
OPEKA, J. F. OPEKA, J. F	7903300452 7905300533	50-336 50-245		PARKER, W. O.	7905100303	50-269	
OPEKA, J F.	7905290221	50-334		PARKER, W. O. PARKER, W. O.	7905230770 7905020064	50-369 50-269	
OPLINGER.O O. OPLINGER.O O.	7905230839 7905230846			PARKER, W. O. PARKER, W. O.	7905140506 7905230272	50-287 50-249	
OPLINGER, O. O OPLINGER, O. Q.	7905230828 7905230840			PARKER, W O PARKER, W O.	7905250466 7905230279	50-249	
OPLINGER, Q. Q OPLINGER, Q. Q	7905250059 7905240860			PARKER, H. O	7905140483	50~287	
OPLINGER, O. Q	7905020136			PARKER, W. D. PARKER, W. O.	7905020408 7905100298	50-24 <del>9</del> 50-24 <del>9</del>	
OPLINGER, O Q OPLINGER, O. O	7905020349 7905020355			PARKER, W. O PARKER, W. O.	7905020301 7905240214	50-369 71-266	
OPLINGER, 0 0 OPLINGER, 0 0	7905020361 7905020366			PARKER, W. O	7905100046	50-269	
OPLINGER, O O,	7905020381			PARKER, W. O. PARKER, W. O	7905140373 7905150254	50-269 50-369	
OPLINGER, O. O. OPLINGER, O. O.	7905030127 7905150158			PARKER, W. O PARKER, W. O	7905220463 7905290700	70-2623 50-369	
OPLINGER, O G OPLINGER, O G.	7905150162 7905230629	70-2178		PARKER, W. O.	7905240452	50-269	
OPLINGER, G. Q	7905230781	14		PARKER, W. O. PARKER, W. O.	7905240426 7905240505	50-369 50-269	
OPLINGER, O O. OPLINGER, O O	7908030068 7908020385			PARKER, W. © PARKER, W. O.	7905010521 7905040047	50~269 50-269	
OPLINGER, O Q. OPLINGER, O O	7903020409 7903020518			PARKER, W C	7905020327	50~269	
OPLINGER, O Q OPLINGER, O. O	7905020499			PARKER, W. O. PARKER, W. O	7905040352 7905070481	50-269 50-369	
OPLINGER, Q. G	7905020504 7905020510			PARKER, W. O. PARKER, W. O.	7905080433 7905080566	50~269 50~269	
OPLINGER, G. Q. OPLINGER, G. Q.	7905020522 7905040171			PARKER, W. O. PARKER, W. O.	7905080388	50-269	
OPLINGER, Q. Q. OPLINGER, Q. Q	7905040177 7905040186			PARKER, W 🗊	7905240466 7905080523	50-269 50-267	
DPLINGER, O. C.	7905040189			PARKER, W. O. PARKER, W. O	7905110264 7905110268	50~269 50~269	
DPLINGER, G G DPLINGER, G, G	7905020454 7905020483			PARKER, W. O PARKER, W. O	7905140189 7905240231	50-269 50-269	
OPLINGER, O. O. OPLINGER, O. O.	7905020486 7905030082			PARKER, W O.	7905150317	50-269	
OPLINGER, O. O. OPLINGER, O. O.	7905030087			PARKER, W. O. PARKER, W. O	7905140361 7905140283	50~269 50~269	
··· watterity V. V.	7905040137		ı	PARKER, W. D.	7905140365	50-269	

AUTHOR	ACCEBBION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
PARKER, W. D	7905140268	50-269		PILANT, J M	7705020129	50-298	
PARKER, W O PARKER, J P	7905160389 7905150534	50-269 50-270		PILANT, J. M PILANT, J. M	7905020269 7905080478	50-278 50-298	
PARKER, W O	7905220270	50-267		PILANT, J H	7705080487	50-278	
PARKER, W O	7905220235	50-269 50-269		PILANT, J. M	7905140228	90-298 50-300	
PARKERIN O PARKERIN O	790522035B 7905300541	50-257		PILANT, J. M PILANT, J. M	7905150369 7905150384	50-298 50-298	
PARKER, W O	7905220351	50-269		PILANT, J H	7705160127	50-278	
PARKER, W. O PARKER, W. O	7905230487 7905230543	50-207 50-269		PILANTIJ M PISHKODD,C	7905230355 7905110347	50~298 50~488	
PARKER, W O	7905240593	50-207		PLATO, P	7905290673		
PARKER, W. C	7905230303 7905240475	50-26 <del>9</del> 50-269		PLESBET, N S PODOLAK, E M	7905240205 7905100018	50-320	
PARKER, W O PARKER, W O	7905240478	50-269		PODOLAK, E. H	7905100034	50-320	
PARKER, H D	7905250401	50-269		PODOLAK, E K	7905100017	50-320	
PARKER, W O PARKER, W D	7905250423 7905310346	50-269 50-269		PODOLAK,E H POIRER,H R	7905100029 7905030175	50-530 50-445	
PARKER, W. O.	7905310404	50-207		POIRIER, HR	7903140115	50-445	
PARKER,W O PARR,O D	7905310211 7905250240	50~269 50~568		POIRIER, M.R. PORTER, F.L.	7903140151 7903300208	50-445 50~133	
PARR.O D	7905100069	50-49B		PORTER, W L	7905230541		
PARR, O D	7905150794 7905040260	50-387 50-373		PORTER, U.C. PORTER, I	7905240921 7905300155	70-2623 50-320	
PARR,O D. PARR,O D	7905080114	00-07-0		PORTER, I	7905230018	50-320	
PARR, Ø. D	7905300594	50-311 50-592		POTAPOVS, U.	7905150581 7905030144		
PARR.O D PARR.O D	7905300616 7905290066	50-576		POTAPOVS, U POTAPOVS, U	7905290097		
PARR.O D	7905300372	50-478		POTAPOVS, U.	7905100356		
PARR, O.D PARR, O.D	7905300376 7905240226	50-438 50-311		POTAPOVS, U POTAPOVS, U	7905110398 7905100410		
PARR, O D	7905310461	50-438		U BYOTAPOS	7905150792		
PARR, O D	7905310464 7905090304	50-596 50-338		POTAPOVS, U POTAPOVS, U.	7905230581 7905100343		
PARR, O. D PARROT, M W	7905250519	50-55 <b>0</b>		POTAPOVS, U	7905290085		
PARSONT, M A	7904180377	50-320		POTTER, J P	790529009 <i>9</i> 7905290247	70-1113 50-466	
Partlon, J. G Partlon, J. G	7905230798 7905300680	70-371 70-754		POTTHOFF, F H POUCHAL, W. F.	7905290579	30-406	
PARTLON, J. 0	7905020530	70-364		POWELL, R E	7905100271 7905030246	50-445	NUREO/CR-0523
PARTLOH, J. 0 PARTLOH, J. C	7905140141 7905150135	70-143 50-143		POWELL,DC POWERS,DA	7905140149		NUREC/CR-0649
PARTLONIJ G.	7905240222	70-1119		PRALLIT F	7905290671	30-471	
PARTLOW, J Q, PARTLOW, J Q,	7905230852 7905250184	70-1151 70-1201		PRELL,JA PREBSESKY,AJ	7904210768 7905150639	50-462	
PATON, H D	7905170162	50-3		PRICE M H	7905250518	~ 4004	
PATON, H. D PATON, H. D	7905100402 7905100226	50~369 50~554		PRIGE, W. J Prige, H	7905150683 7905100082	70-1821 50-320	
PATON H D.	7905240154	50-367		PRICE, DS.	7905150147	50-259	
PATTERSON, K. P PATTERSON, J. P	7905150458 7905150754	50-394 70-1308		PRICHARD, C PRIETO, R	7904210061 7905090272	50-594	
PAUL, R.	7905290107			PRIETO, R	7905230432	50-584	
PAULUSIR C PAULUSIR.C.	7905020260 7905040276	50-320 50-320		PRINCE:R J. Guattrochhi.J.	7905110145 7905070497	50-3	
PAULUS, R C	7905140253	50-320		GUI CK+ D	7905250410	50-302	
PECK.C. PECK.C H	7905040147 7905040107	50-244 50-244		GUINTENZ,T E GUINK,JF	7905090332 7905100194	50-217	
PECK, C. H	79050401 <i>9</i> 1	50-244		QUIRK, J. F	7905100185		
PECORA, D. PEDERBON, D. E.	7905090422 7905160381	50-263	NUREG/CR-0642	RADACK, E.D. RADER, R	7905250503 7905100225	27-39	
PEDERBEN, K S	7905230470			RADERIR H	7905030214	50-395	
PEEPLES, W. P. PEEPLES, W. P.	7905290110 7905150238			RADER,R M RADER,R M	7905290077 7905140137	50~498 50~395	
PELTIER I A	7905010659	50-359		RAFFETY,8 J	7905160427	50~409	
PELTIER, I. A PELTIER, I A	790510025B 7905230558	50-322 50-322		RAGAN, K. K RAGONE, B	7905140177 7905290296	50-280	
PENNER, K L	7905020265	50-320		RANDALL, J. D.	7905220097	50~128	MADOCIANE I O
PENNER,P. PERDUE,W D.	7905040330 7905140539	50~461 50~320		RANDOLPH.H L. RANGEL.C.	7905240540 7905100013	50-320	7905240540
PERKINS, L,	7905240667	50~488		RAY, J J.	7905150250		
PERKINS, T. J PERKINS, T J	7905020367 7905150511	20-550 20-550		RAY, M. J REAVES, R	7905010494 7905300163	50~596 40~8681	
PERLMAN, J	7905300194	00 ER0		REAVES, T. E.	7905090269		
PERLMAN, J. PERROTTI, D.	7905250114 7905230527	50-320		reavib.j.a Rebelowski.t	7903220365 7903080110	50-269 50-286	
PERRY, R. H	7905240125			REBELOWSKI,T	7905110371	50~247	
PERRY, J. C PERRY, J. C	7905040458 7905100270	50~344 50~344		REDEMEYER, P. C REED, C	7905100113 7905020421	40~299 50~10	
PERRY, J. C	7905170247	50~344		REED, C	7905250460	=0.45	
PERRY, J.C. PERRY, J.C.	7905220293 7905220316	50-344 50-344		REED, C REED, C.	7903250280 7905150074	50~10 71~8	
PERRY, W. W.	7905010468	50-324		REED, C,	7903250215	50-10	
PERBON, L. B PERBON, L. S	790511025B 7905160029	50-320 50-320		REED, C. REED, C	7905010523 7904270366	50-373 50-10	
PERY, W. W.	7905070084	50-327		REED, C	7905020312	50-373	
PEBONEN, D. E. PETERBON, Q.	7905070227 7905140494	50133 50285		REED, C. REED, C	7905240633 7905150148	50-10 50-10	
PETERBON, C.	7905070545	50~285		REED, C.	7905040502	50~275	
PETERBON, C. R. PETERBON, H. E.	7905210259 7905160382	50-265 50-265		REED, C. REED, C	7905300242 7905070567	50-10 50-454	
PETERBEN, H E	7909160406	50-285		REED, G.	7905170237	50-275	
PETERSON, O. PETERSEN, H. E.	7905220304 7905300349	50-285 50-285		REED G. REED C	7905190016 7905220337	50~237 50~454	
PETERBON, M	7905100287			REED, G.	7905220102	50~599	
PETERBON, H. T. PETERBON, T.	7905160096 7905190153	50-320 50-320	•	REED, C. REED, C.	7905250391 7905310361	50-10 50-373	
PETRICK, N. A.	7905310411	50~492		REGAN: W. H.	7905070087	50~339	
PETRICK, N. A.	7905070649 7905100294	50-492 50-313		REOAN: H. H. REOAN: H. H	7905150783 7905240151	50~550 50~471	
PETTIT, A. P. PFAFF, 8. J.	7905100284	40-6659		REGAN: W. H.	7905220038	50-592	
PFEFFERKORN, W. O PHELAN, M. K.	7905110347 7905150265	50-488 71-151		REGAN, H. H. REGAN, H. H.	7905070316 7905150115	50-594 50-594	
PHILL IPB, J. R.	7905030174	50-275		REHM, T. A.	7905150332		
PHILLIPS, J.R. PICKETT, J.F.	7905310104 7905300088	50-275		REHMIT. A REHMIT. A	7905240155 7905240153		
PICKERINO, T. R.	7905300677	=0 ***		REHM, T. A.	7905300648 7905100278		
PICKINGTON, C. PICKLEBINER, M. L.	7905230744 790522046Ø	50-466		REHM, T. A. REID, R. W.	79051100278		



AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
REID, R W	7905250014	50-269		RIGBERG, 8.	7905150757	50-358	
REID, R W REID, R W	7905250018	50-269 50-309		RIGORIR R RILEYIB W.	7905250502 7905230243	50-324	
REID, R W	7905070011 7905070332	50-336		RINAGA, J. M	7705030258	50-336	
REID,R W REID,R W	7905070337 7905070351	50-336 50-336		RINDAL,A. RISCHLING,J L	7905100323 7905070596	50-316	
REID.R W '	7905150772	50-128		RITSHERIJA	7905010447	50-443	
REID,R W	7905070231	50-335		A LINGHETIR	7905170245 7905210129	50-443	
REID.R W Reid.R W	7905070234 7905070299	50-335 50-335		RIVARDIJE	7905110267	50-443 50-320	
REID, R W	7903090300	50-313		ROBART, A W	7905300352	50-320	
REID,R W REID,R W	7905090200 7905090279	50-302 50-77	•	ROBERTB.D M ROBERTB.D	7905070582 7905110205	50-3 70-364	
REID, R W	7905030155 7905250076	50-309		ROBERTS, V M ROBERGE, J C	7905290514 7905250528	71-154	## *** *** ***
REID,R W. Reid,R W	7905250079	50-313 50-313		ROBERTSON, L	7905160043	50-329 50-320	45-79/H124AF
REID.R W Reid.R W	7905250090	50~313 50~317		ROBERTSON, J S ROBERTSON, J S C	7905020161 7905070259	70-1151 70-1201	
REID, R W	7705080123 7705150372	50-317		ROBERTOOR O	7905150797	10-1501	
REID,R W Reid,R W	7905290556 7905080130	50-269 50-269		ROBERTS, J P. ROBERTS, I C	7905250338 7904180171		
REID, R W	7905240819	50~309		ROBERTS, I C	7905140052	50-320	
REID.R W REID.R,W	7905150278 7905250002	50-335 50-317		T .HOUABNAJOR	7905230001 7905310349	50-320 50-592	
REID.R W	7905250003	50-317		RODGERS, W.	7905230024	50-320	
REID.R W. Reid.R W	7905250007 7905230836	50-317 50-128		RODI,P,J RODRIGUEZ,J P	7905250520 7905150411	50-206	
REID, R W	7905240982	50-269		RODRIGUEZ, R. J.	7905100281	50-312	
REID,R W Reid,R W,	7905250263 7905250049	50-335 50-313		ROE, L. E ROE, L. E	7905240671 7905080416	50-346 50-346	
REID,R W	7905250055	50-313		ROE, L E	7905090353	50-346	
REID.R W REIFF.D	7905250065 7905110229	50-313 50-320		ROE, L. E ROE, L. E	7905190031 7905240586	50-346 50-346	
REIFF.D D.	7905110323	50~320		ROE, L E	7905220095	50-346 50-346	
REILLY, M K REINERT, B	7905250373 7905290473	50-416 50-485		ROE, L E ROE, L E.	7905230371 7905240403	50-344	
REINERT, 8	7905310203	50~485		ROE, L E	7905290419	50-346 50-346	
REIS.H F. REIS.H F	7905250170 7905080311	50-498 50-466		ROE, L E ROE, L E	7905310450 7905300493	50-346 50-346	
REIB, H F	7905080320	50-466		ROE, L E	7905310375	50-346 50-346	
REIS, H F REIS, H F.	7905250225 7905250476	50-466		ROE, L E. ROGERB, H W	7905300418	50-346	
REIS,H F	7905140057	50-466		ROGERS, C S	7905240904 7905240275	71-55 50-556	
REIS, H. F REIS, H F	7905100009 7905100011	50-38 50-389		ROGERS, C S. ROGERS, C	7905150063 7905230759	50-556	
REIB,H F	7905100019	50-389		ROGERS, C L	7905240546	50-556 50-275	
REIS, H. F REIS, H. F	7905250328 7905100391	50~498 50~466		ROGERS, W. H. ROGERS, R. F	7905080479 7905020497	50-321 50-321	
REI8.E J	7905100249	27-39		ROGERS, L. R	7905140203	30-321	
REIS,E J REIS,E J	7905030168 7905160039	27-3 <i>9</i> 50-320		ROHRER, E ROISMAN, A, Z	7905220125 7905080286	50-346	
REIB, E J	7905240299	27~39		ROISMAN, A Z.	7905080296		
REIS.E J Reis.e. j	7905100372 7905150562	27-39 50-400		ROISMAN,A Z ROISMAN,A Z	7905250458 7905240178	50~466	
REITER, E K	7905250477	70-1151	Ÿ	ROIBHAN, A. Z	7905240190	50-466	
REITER, E K REIZEN, M S	7903230474 7903230304	70-1151 50-315		ROIBMAN, A. Z Roibman, A. Z	7905030034 7905240482	70-2623	
REKEHEYER,P C REKEHEYER,P C	7905010501 7905290033	50-299		ROISMAN, A Z,	7905080184	50-437	
REMICK,F J	7905240579	40-299 27-39		ROISMAN,A Z ROISMAN,A.Z	7905080202 7905220458	50-437 50-437	
RENBERGER, D. L. RENBERGER, D. L.	7905070453 7905250467	50-397		ROISMAN, A. Z.	7905250292	50-437	
RENBERGER, D L	7905040294			ROISMAN,A Z Roisman,a,z,	7905140079 7905140094	70-2623 50-320	
RENBERGER, D. L. RENBERGER, D. L.	7905010478 7905040379	50~397 50~808		ROISMAN, A Z	7905290679	70~2623	
RENBERGER, D. L.	7905010486	50~397		ROLLINS, J, D ROMANO, F R	7905020252 7905210058	71-6698 50-334	
RENBERGER, D. L. RENBERGER, D. L.	7905090069 7905070499	50-397 50-397		ROMANO, A. J.	7905150219		NUREO/CR-0513
RENBERGER, D L	7903090284	50~508		RONE, A. H. ROOD, H.	7905070651 7905230589	50-219 50-341	
RENBERGER, D.L. RENBERGER, D.L.	7905040601 7905110232	50-397 50-397		ROOD; H. ROOK; H, E	7905290411 7905240747	50-361	
RENBERGER, D. L.	7905160337	50-508		ROOK: H. F.	7905240768	50-275 50-275	
RENBERGER, D. L. RENBERGER, D. L.	7905190067 7905190076	50-460 50-397		ROPBON, D. J. ROSENFIELD, A. R.	7905100292 7905250214	50-305	7008080014
RENBERGER, D. L. RENBERGER, D. L.	7905190117	50-397		ROBENTHAL, A B.	790508014		7905250214
RENBERGER, D. L.	7905230534 7905250537	50~460 50~397		ROSENBERO, A. B ROSOLIE, E.	7905150561 7905250279	50-445 50-444	
RENY,R H RESNIKOFF,M R	7905010549 7905230768	50-309 50-295		ROSOL IE, E	7905250273	50-344	
REST, J	7905110348	50-275 50-320		ROSOLIE, E ROSOLIE, E	7905230550 7905230544	50-344 50-344	
REVELEY,W T REYNOLDS,N S.	7905100152	50-516		ROSS, D. M.	7905290071	71-9010	
REYNOLDS, N 8,	7905100228 7905150821	50-445 50-445		ROSB, D. A ROSB, D. A,	7905250349 7905040481	50-219 50-219	
REYNOLDS, N S REYNOLDS, N S	7905100193 7905230639	50-445		ROSS, D A	7905140243	50-219	
REYNOLDS, L. E	7905240187	50~445 71 <b>~624</b> 4		ROSS, D. A. ROSS, D. A.	7905150472 7905160369	50~219 50~219	
REYNOLDB, L.E. REYNOLDB, L.E	7905241004 7905300636	27-39		R068, D. A	7905160374	50-219	
REYNOLDS, N. S	7905240901	71-6244 50-513		ROSS, D. A. ROSS, D. A.	7905250077 7905210217	50-219 50-219	
RHODES, L RHODE, O K	7905100332 7905150597	50-592		ROSS∴D, A.	7905210281	50-217	
RHODE, O. K.	7905080414	50-220		ROSE, D. A ROSE, D. A	7905220388 7905290017	50~219 50~219	
RHOW, S K RIB, L, N	7905010541 7905110255	50-320		ROSS, D.A.	7905290025	50-219	
RIB, L. N.	7905110257	50~320		ROSS, D. A ROSS, T. K	7905290175 7905040472	50~219 50~280	VEP-FRD-32
RIB, L. N. Rice, J. K	7905110263 7905140226	50-320 50-445		ROBB, D. F.	7905190252	50-320	Appl tilln_gg
RICHARDS, C	7903240515	50-358		ROSS, D F ROSS, D, F.	7905210238 7905100384	50~320 50~320	
RICHARDSON, J. E RICKARD, C. L	7905110281 7905150008	50-320		8068, D. F.	7905240130		
RIDOWAY, K. R.	7905010336	50-155		ROBS, D. F. ROBS, D. F.	7905241001 7905080361	50~548 50~491	
RIDONAY, K.R. RIEDEL, W.R.	7905290549 7905250168	50-155 40-8681		RO88, D. F.	7905230037	50-320	
RIGBERG, 8.	7903290464	50-358		ROSS: D. F. ROSS: D. F.	7905230048 7905230212	50~320 50~320	
Riobero, S. Riobero, S	7905290468 7905290520	50-358 50-358		ROBSBACH, L. W. ROBZTOCZY, Z. R.	7905250011 7905110061	40-2257	
				nestingelf & R.	, 1491 1009 J		

AUTHOR	ACCEBBION NUMBER	DUCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
ROSITOCIY, Z R	7905110226 7905110069	50-269		BALTIMAN, J BALTIMAN, J	7905160167 7905160170	50-83 50-263	
ROSZTOCZY, Z. R ROSZTOCZY, Z. R.	7905110074	50-269	PROFIDE LEA	BALTZMAN, J BALTZMAN, J	7905160172 7905160176	50-255 50-267	
ROTHE, P. H. ROTHE, P. H.	7905020154 7905030221		7905020154 NUREG/CR-0599	SALTZMAN, J	7905140180	50-273	
ROTHE, P. H ROTHFLEISCH, J.	7905240552 7905240658	40-8698	7905240552	SALTIMAN, J SALTIMAN, J	7905160183 7905160186	50-261 50-244	
ROTHFLEIBCH, J. E	7905250022	40-8698 70-2623		BALTIMAN, J BALTIMAN, J	7905160187 7905160189	50-344 50-241	
ROUSE, L. C. ROUSE, L. C	7905090164 7905290090	50-269		BALTZMAN, J	7905160192 7905160193	50-139 50-395	
ROUSE, L. C. ROUSE, L. C.	7905240370 7905240383	70-1308 70-1308		BALTZHAN, J BALTZHAN, J	790514019B	50-335	
ROUSE, L. C. ROUSE, L. C.	7905090138 7 <del>90</del> 5150669	70-2623 70-1821		BALTZMAN, J BALTZMAN, J	7905160199 7905160203	50~334 50~113	
ROUSSELLOT: M. C	7905250335 7905190223	50-275 50-320		BALTZMAN, J BALTZMAN, J.	7905160205 7905160207	50~134 50~129	
ROY, D. H. ROY, D. H.	7905230507	50~320		BALTZMAN, J BALTZMAN, J	7905160215 7905160219	50-271 50-433	
ROY, D. H. ROY, D. H.	790519006B 7905190079	50-320 50-320		BALTIMAN, J BALTIMAN, J	7905160221 7905160222	50-326 50-394	
ROY, D. H. RUDOLPH, J. J	7905080372 7905220121	50-346		SALTZMAN, J	7905160224	50-349	
RUETER, D. A. RUETER, D. A.	7905020343 7905100318	80-368 50-313		SALTZMAN, J. SALTZMAN, J	7905160230 7905160231	50-327 50-346	
RUETER, D. A.	7905310387 7905210283	80-368 50-306		BALTZMAN, J BALTZMAN, J.	7905160232 7905160233	50-340 50-340	
RUETHER, J. C. RUITER, Q. H	7905150567	50-305		BALTIMAN, J BALTIMAN, J.	7905160235 7905160236	50-142 50-112	
RUITER, O. H. RUITER, O. H	7905300399 7905310366	50-305 50-305		BALTZMAN, J BALTZMAN, J	790516023B 7905160240	50-208 50-274	
RUSCHE, B RUSCHE, B.	7905230005 7905230024	50-320 50-320		BALTZMAN, J	7905160243	50-312 50-274	
RUSH: B. RUSHMORE	7905150293 7905150291	50~363 50~220		SALTZMAN, J SALTZMAN, J	7905160244 7905160249	50-87	
RU88: Q. D.	7905160223	50-320 50-317		SALTZMAN, J. SALTZMAN, J	7905160252 7905160254	50-302 50-406	
RUSSELL, L. B.	7905100348 7905110122	50-317		SALTZMAN, J SALTZMAN, J	7905160258 7905160260	50~182 50~173	
RUSBELL, L. B. RUSBELL, L. B.	7905010524 7 <del>90</del> 5080494	50-317 50-310		BALTZMAN, J	7905160265 7905160266	50-298 50-225	
RUSSELL, L. B RUSSELL, L. B.	7905080555 7905190080	50-317 50-317		BALTZMAN, J BALTZMAN, J	7905160268	50-223 50-358	
RUSSELL, L. 9 RYAN, C. R.	7905290426 7905090007	50-317 50-498		BALTZMAN, J. BALTZMAN, J.	7905160272 7905160273	50-305	
RYAN, T Q.	7905240127	50-445 50-445		BALTZMAN, J SALTZMAN, J	7905160275 7905160276	50-331 50-146	
RYAN: T. O. RYAN: T. O.	7905070040 7905070045	50-445		SALTZMAN, J SALTZMAN, J.	7905160278 7905160280	50-47 50-30	
RYAN R. Q. RYAN R. Q.	7905250447 7905090217	50-320		BALTZMAN, J	7905160281 7905160282	50~1 84 50~1 88	
RYAN, R. O. RYAN, R. O.	7905090252 7905140313	20-320		BALTZMAN, J. BALTZMAN, J.	7905160285	50-29 50-220	,
RYAN, R O.	7905140320 7905140325			Baltzman, J. Baltzman, J.	7905160286 7905160289	50-213	
RYAN, R. C. RYAN, R. C.	7903140329			EALTZMAN, J. U. NAMSTJAB	7905160291 7905160292	50-155 50-219	
RYAN; R. C. RYAN; R. C.	7905140331 7905090244	50-320		BALTZMAN, J. BALTZMAN, J.	7905160298 7905160300	50-133 50-27	
RYAN, R. Q. Ryan, R. Q.	7905090241 7905090240	50-320 50-320		BALTZMAN, J BALTZMAN, J.	7905160306 7905160308	50-156 50-124	
RYAN R. J. BAAR R. P.	7905090237 7905090400	50≁320 50~320		L NAMSTLAR	7905160311 7905160314	50-201 50-206	
BABOL⊢A. R.	7905040146 7905240175	50-387 71-297		SALTZKAN, J.	7905140320 7905140322	50-94 50-20	
BACHBE, J. BACHBE, J.	7905240183	71-299	NURE9-0553	BALTZHAN, J BALTZMAN, J.	7905160326	50~106 50~5	
BALOHON, B. BALTZHAN, J.	7905090048 7905030154	50-445	14414-14	BALTZMAN, J. BALTZMAN, J.	7905160329 7905160329	50-252	
Baltzman, J. Baltzman, J.	7905140404 7905140407	50-10 50-3		BALTIMAN, J. BALTIMAN, J	7905160332 7905160334	50-57 50-284	
BALTZMAN: J. BALTZMAN: J.	7905140415 7905140422	50-171 50-245		BALTZHAN, J. BALTZHAN, J	7905160336 7905160339	50-123 50-186	
BALTZHAN, J. BALTZHAN, J.	7905140431 790514043B	50-266 50-269		BALTZHAN, J.	7905160341 7905160343	50-2 50-59	
BALTZMAN, J.	7905140444 7905140449	50-280 50-250		BALTZMAN, J. BALTZMAN, J.	7905160345	50-187 50-54	
BALTIMAN, J. BALTIMAN, J.	7905140456	50-254		BALTZMAN, J. BALTZMAN, J	7905160348 7905160351	50-22	
BALTZHAN; J. BALTZHAN; J.	7903140462 7 <del>9</del> 03140470	50-259 50-275		BALTZMAN, J. BALTZMAN, J	7905160353 7905160355	50-16 50-192	
BALTZMAN, J. BALTZMAN, J	7908140477 7908140481	50-282 50-315		BALTZMAN, J. BALTZMAN, J.	7905160357 7905230456	50-264 50-62	
BALTZHAN, J. BALTZHAN, J.	7905140486 7905140489	50-289 50-313		SALTZKAN, J SALTZKAN, J.	7905300034 7905300036	50-72 50-97	
BALTZHAN, J. BALTZHAN, J.	7905140493 7905140499	50-321 50-317		BALTZMAN, J	7905300045 7905300052	50-160 50-84	
BALTZMAN: J.	790514050B 7905140512	50-324 50-275		BALTZHAN, J. BALTZHAN, J.	7905300059 7905300065	50-32 50-4	
BALTZHAN; J. BALTZHAN; J.	7905140523	50-339		ealtzman, J. Saltzman, J.	7905300049	50-8 50-19	
Baltzman, J Baltzman, J	7903140538 7903140546	50-369 50-373		SALTZMAN; J. SALTZMAN; J	7905300190 7905300202	50-37	
BALTZMAN, J. BALTZMAN, J.	7905150360 7905150365	50-309 50-298		SALTZHAN, J. SALTZHAN, J	7905300714 7905140281	50-13 50-72	
BALYZMAN, J.	7905150367 7905150370	50-272 50-151		BALTZHAN, J. BALTZHAN, J.	7905190171 7905150308	50-30 50-18	
BALYZHAN, J. BALTZHAN, J. BALTZHAN, J. BALYZHAN, J.	7903150373 7903150375	50-170 50-262		SALTZMAN, J.	7905150382 7905160297	70-754 50-131	
BALTZHAN, J. BALTZHAN, J. BALTZHAN, J.	7905150376	50-166		BALTZMAN, J. BALTZMAN, J.	7905150363		
BALTZHAN, J. BALTZHAN, J.	7905150377 790515038 <u>4</u>	50-199 50-141		BALTZMAN, J. BALTZMAN, J.	7905190049 7905220354	50-267	
BALTZMAN, J. BALTZMAN, J.	7905160100 7905160106	50-116		SALTZMAN, J SANDE, R. D.	7905240675 7905310232	50-27	,
BALTZMAN, J.	790516010B 7905160116			BANDERS, H. E.	7904300319 7905150273		
BALTZMAN, J. BALTZMAN, J.	7905160117	50-150		BANDIFORTH, D. BANDOZ, B. A.	7909010561		
Baltzman, J. Baltzman, J.	7905160122 7905160123	70-1257		SANDVIK,R M SANGER,H.B.	7905250180 7905240874	50-518	
BALTZMAN, J. BALTZMAN, J.	7905160148 7 <del>9</del> 05160151	70-754		SARATHY, P. K SATTERFIELD, R. M	7905150273   7904300123	50-320	NUREO/CR-0454
BALTZMAN, J.	7905160157 7905160160	50-409		BAUERLENDER, O. H BAUER, R. C.	7905090428 7905240493	i 50~327	MODES OF SANA
BALTZHAN, J.	7905160162	50~333		SCARANO, R. A.	790529048		
BALTZMAN, J.	7905160164	4V-RD1					



AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT Number	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
SCARANO, RA SCARANO, RA	7905250174 7 <del>9</del> 05240592	40~2259 40-8681		SCHWENCER, A	7905080080		
SCARANG, R A	7905220039	40-2259		SCINTO, J F SCINTO, J F	7905090190 7905080249		
SCARANO,RA SCARANO,RA	7905250011 7905240849	40-2259 40-2259		BCINTO, J SCINTO, J F	7905110203	50-320	
SCARANO, RA SCARANO, RA	7905150806	40-8502		SCINTO, J	7905160163 7905160050	50-320	
SCARAND, R A	7905100059 7905240496			BCINTO, J F BCINTO, J F	7905010115 7905160191	50-320	
SCARAND,R A SCHAFER,K H	7905240398			BCINTO, J F	7905110418	30-320	
SCHAKNE, R	7905070406 7905020037	50-320		M L,TTOD8 M L,TTOD8	7905240232 7905300177	50-424 50-466	
SCHAUER, F SCHENDEL, K R	7905080263 7905150592			SCOTT.J M	7905250242	50-466	
SCHENDEL, K R	7905240267	40-8502		SCOTT, J M SCOTT, S M	7905110339 7905110341	50-466 50-466	
SCHERER, A E SCHERER, A E	7905220080 7905070564			BCDTT,R BCOTT,H J	7904210774		
SCHERER, A E SCHERER, A E	7905110288 7905300368			SCOUTEN, J H	7905250372 7905010654	27-39 50-320	
SCHERER, A E	7905300526			SEELINGER, J L SEIDE, P	7905110079 7905030051	50-320	
SCHIFTER.R O SCHLMIDT,A D	7904170521 7905150241	50-335		BEIDLE, W C	7905070191	50-445	
SCHMIDT, A D	7905080467 7905080554	50-250		BEIDLE, W C	7905010302 7905010303	50-482 50-445	
SCHMIDT, A D	7705080567	50-251 50-251		SEIDLE, H C	7905010376 7905150556	50-478	
SCHMIDT, A D SCHMIDT, A D	7905090067 7905090074	50-250 50-250		BEIDLE, W G.	7905150564	50-445 50-556	
SCHMIDT, A D SCHMIDT, A D	7905090062	50-335		SEIDLE, W C	7905150541 7905030085	50-392 50-445	
SCHMIDT, A D	7905220091 7905220103	50-335 50-250		BEIDLE, W, C SEIDLE, W C	7905030089	50-458	
SCHMIDT, A D SCHMIDT, A D	7905220122 7905250388	50-250 50-250		SEIDLE, H. C	7905030094 7905030097	50~498 50~482	
SCHMITT, R C SCHNEIDER, R R	7905240886		NUREQ/CR-0785	GEIDLE, W.C SEIDLE, W.C	7905030113 7905030091	20-385	
SCHNEIDER, R R	7905100421 7905070401	50-220 50-220		SEIDLE, W C	7905030095	50-458 50-498	
SCHNEIDER, R R SCHNEIDER, R R	7905150808 7905160392	50-220		SEIDLE,W C SEIDLE,W C	7905030099 7905030102	50-482 50-362	
SCHNEIDER, R R	7905230293	50-220 50-220		BEIDLE, W C	7905030107	<b>50-445</b>	
SCHNEIDER, R R SCHNEIDER, F W	7905230478 7905070140	50-220 50-272		SEIDLE, W C	7905030139 7905030143	50-458 50-478	
SCHNEIDER, F W SCHNEIDER, F W	7905290045	50-272		SEIDLE, W.C SEIDLE, W.C	7905030146	50-482	
SCHNIEDER. J R	7905250072 7905310394	50-272 50-286		BEIDLE, W C	7905030147 7905030151	50-392 50-445	
SCHOPPMAN, M. A SCHOPPMAN, M. A	7905080471 7905080559	50-250		BEIDLE, W. C SEIDLE, W. C	7905030117 7905030118	50-458	
SCHOPPMAN, M A	7705080571	50-251 50-251		SEIDLE, W. C SEIDLE, W. C	7905030119	50-498 50-482	
SCHOPPMAN, M. A SCHOPPMAN, H. A	7905090072 7905090081	50-250 50-250		SEIDLE, W C	7905030122 7905030124	50-382 50-445	
Schopphan, M. A Bchopphan, M. A	7905090064 7905220098	50-335		SEIDLE, H, C, SEIDLE, H, C	7905030186	50~45B	
BCHOPPMAN, M A	7905220113	50~335 50~250		SEIDLE, W C	7905030189 7905030193	50~478 50~482	
SCHROEDER, F SCHULER, U	7905220392 7905070134	50-528 50-320	•	SEIDLE, W. C.	7905030197 7905030201	20~3B5	
SCHULTZ, W B. SCHULTZ, W B	7905080036	22.040		SEIDLE, W C	7905030057	50~445 50~482	
SCHUMACHER. M C	7905080047 7905030046	50-185		SEIDLE, W. C.	7905030044 7905030071	50~382 50~498	
schutt, r schutt, r	7705250365 7705250370	50-596 50-596		SEIDLE, W C SEIDLE, W C	7905030076	50-445	
SCHUTZ, D H SCHUTT, R	7905220067	70~820		SEIDLE, W C	7905030238 7905030240	50-458 50-498	
SCHWARZ, M D.	7905240160 7905290002	50~596 50~498		SEIDLE, W.C.	7905030248 7905030250	50~4 <i>92</i> 50~382	
SCHWARTZ, H SCHWARTZ, H	7905250270 7905290258	40-8495 40-8495		SEIDLE, W. C	7905030254	50~448	
SCHWARTZ, S A SCHWENDIMAN, L C	7905300053	50-320		SEIDLE, H C	7905020514 7905020516	50~445 50~498	
SCHWENK, E B	7905150777 7905240113		7903150777 7903240113	BEIDLE, W.C.	7905020524 7905020528	20~392	
SCHWEIBINZ, ER SCHWENCER, A	7905090393 7905070311	50-546	,,032,40113	SEIDLE, W, C SEIDLE, W C	7905020534	50~458 50~482	
SCHNENCER, A SCHNENCER, A	7905070315	50-284 50-284	•	SEIDLE, W. C.	7905020498 7905020503	50~450 50~462	
SCHWENCER, A	7905040307 7905070109	50-261 50-250		SEIDLE, W. C. SEIDLE, W. C.	7905020505 7905020508	50~498	
Schwenger, a Bchwenger, a	7905070114 7905070124	50-250		SEIDLE, W. C	7905020511	50~445 50~382	
SCHWENCER, A SCHWENCER, A	7905020490	50-250 50-272		BEIDLE, W. C.	7905300621 7905040391	30-482 30-320	
SCHWENCER, A		50-266 50-266		SEIDLE, W. C. BEIDLE, W. C.	7905040575	80~4B2	
SCHHENCER, A SCHHENCER, A	7905240895	50-305 50-305		SEIDLE, W. C.	7905040579 7905040580	50~382 50~445	
SCHWENCER, A SCHWENCER, A	7905240911	30~305		SEIDLE, W.C. SEIDLE, W.C.	7905040584 7905240686	50~458	
SCHWENCER, A	7905090068	50-266 50-266		BEIDLE, W. C. Beidle, W. C.	7905290431	50~498 50~445	
SCHWENCER, A SCHWENCER, A	7905090076	50~266		BEIDLE, W. C.	7905070046 7905070180	50~492 50~458	
SCHWENCER, A SCHWENCER, A	7905250190	50-295 50-295		BEIDLE, W.C.	7905070195 7905070198	50~498	
SCHWENCER. A		50-305 50-305		SEIDLE, W. C. SEIDLE, W. C.	7905070193	50~382 50~445	
SCHWENCER, A SCHWENCER, A.	7705240382	50-305		BEIDLE, W. C.	7905310206 7905310216	50~482	
SCHMENCER, A SCHMENCER, A.	7705070125	50-241 50-241		SEIDLE, W. C. BEIDLE, W. C.	7905310222	50~498 50~382	
SCHHENCER, A.	7905070130	50-261 50-348		BEIDLE, W. C.	7905310226 7905310230	50~458 50~445	
SCHNENCER, A SCHNENCER, A	7905090084	50-348		BEIDLE, W.C.	7905240374 7905240385	50~362	
BCHHENCER, A	7795100442 s	30-266 30-266		SEIDLE, H C.	7905240394	50~498 50~458	
SCHWENCER, A. SCHWENCER, A.	7905100446 5	10-585 10-599		SEIDLE, W. C	7905240399 7905240418	50~445 50~482	
SCHHENCER, A SCHWENCER, A	7905240322 5	i0~28 <u>2</u>		SEKULER, 8 N SEKULER, 8, N.	7905250372	27~39	
ECHNENCER, A	7905240333 5 7905290050 5	90-282 90-305		BEKULER, S. N.	7905150256 7905310273	50~295	
BCHNENCER, A BCHNENCER, A.	7905290054 5	0-305		SEKULER, S N SELLS, D E	7905150248 7905250107	50~295	
SCHWENCER, A	7705250425 5	10-305 0-295		SELLS, D E. SERABIAN, J. A.	7905150731	50~596	
SCHWENCER. A	7905250432 5	0-295 0-295		SEWELL, R. B.		50~3 40~8698	
BCHNENGER, A. BCHNENGER, A	7905230556 5	0-286		SEYFRIT, K, V SEYFRIT, K, V,	7905150079	50~313	
SCHWENCER, A.		0-25 <sub>0</sub> 0-25 <sub>0</sub>		SEYFRIT, K. V. SEYFRIT, K. V.	7905150065	50~298 50~285	
		-		BEYFRIT, K. V.	7905150086	50~267	
					···	50~313	

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	ROHTUA	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
BEYFRIT, K V	7905010451	50-298		SHALLER, D V	7905040611	50-315	
SEYFRIT, K V SEYFRIT, K V	7903010453 790301045 <b>4</b>	50-285 50-267		SHALLER, D, V SHALLER, D, Y	7905070583 7905070598	50-316 50-315	
SEYFRIT K V	7905020440 7905020441	50-285 50-313		BHALLER, D. V GHALLER, D. V	7905110120 7905150423	50~315 50~315	
SEYFRIT, K V SEYFRIT, K V	7905020444	50-298		SHALLER, D. V	7905150488	50-31 <i>6</i>	
SEYFRIT, K V SEYFRIT, K V	7905020446 7905010276	50-267 50-382		SHALLER, D. V SHALLER, D. V	7905240602 7905170248	50-315 50-315	
SEYFRIT, K V	7905010277	50~45B		SHALLER, D. V	7905170261	50-315	
BEYFRIT, K V	7905010279 7905010280	50-499 50-482		SHALLER, D, V SHALLER, D V	7905210135 7905220320	50-315 50-315	
SEYFRIT, K V SEYFRIT, K V	7905010281 7905020268	50~445 50~265		SHALLER, D. V SHALLER, D. V	7905230325 7905310367	50-31& 50-31&	
SEYFRIT, K V	7905020273	50-298		Shanahan, H. R	7905250521 7905300756	50-280	
SEYFRIT, K V SEYFRIT, K V.	7905020277 7905020279	50-313 50-267		SHANNON, P C SHAPAR, H K	7905160109	20~880	
SEYFRIT, K, V SEYFRIT, K, V.	7905020411 7905020413	50-267 50-285		SHAPARIH K SHAPARIH K	7905150327 7905010215	50~35#	
BEYFRIT K V	7905020415	50-298		SHAPAR, H K	7905240412	50-358	
SEYFRIT, K V SEYFRIT, K V.	7905020419 7905020428	50-313 50-298		GHAPAR,H K BHAPAR,H K	7905160105 7905300403	50~320	6ECY-79-235
SEYFRIT.K V	7905020431 7905020434	50-267 50-285		GHAPARIH K SHAPARIH K	7905160017 7905090213	50-320 50-320	
BEYFRIT, K V.	7905020436	50-313		SHAPER H K	7905230713		
BEYFRIT.K.V BEYFRIT.K.V	7903140143 7905140146	50~267 50~285		SHAPIRO,R SHAPIRO,R.	7905240941 7905240915	50-322 50-322	
BEYFRIT.K V	7905140148	50-278 50-313		SHEA:R SHEA:JR	7905240001 7905240059		SECY-79-102A SECY-79-120A
SEYFRIT.K V.	7905140152 7905150045	50-313		SHEAJJ R	7905250033		8ECY-79-183A
SEYFRIT, K V SEYFRIT, K V	7903150044 7905150049	50-298 50-285		SHEA.J R SHEA.J R	7905240147 7905240173		SECY-79-249 SECY-79-249
SEYFRIT, K. V	7905150051	50~267		SHEA.J R	7905220051 7905230020		BECY-79-254 BECY-79-142A
SEYFRIT.K.V SEYFRIT.K V.	7905010455 7905010457	50~458 50~498		SHEA, J R	7905230022		BECY 79-255
BEYFRIT, K V BEYFRIT, K V.	7905010459 7905010461	50-492 50-382		SKEA-J R SKEA-J R	7905240281 7905230835		BECY-79-258
SEYFRIT, K V	7905010464	50-445		6HEALJ R	7905300111	50-320	9 SECY-79-270
SEYFRIT, K V. SEYFRIT, K V	7905030104 7905030131	50-492 50-458		SHEA: J. R SHEA: J. R	7905100053 7905100415		8ECY-77-269
SEYFRIT, K. V	7905030134 7905030138	50-382 50-498		SHEALJ R. SHEALJ R	7905230553 7905250264	40-8695	8ECY-79-271 8ECY-79-248
SEYFRIT, K. V SEYFRIT, K. V	7905030140	50-445		BHEA: J. R.	7905240371		SECY-77-28814
BEYFRIT, K. V. BEYFRIT, K. V.	7905210030 7905210035	50-320 50-320		SHEA, J R SHEA, J R.	7905100230 7905250207		
SEYFRIT, K V	7905140088 7905040486	50-368 50-285		SHEA, JR SHEA, JR	7905150311 7905230537		BECY-79-272
SEYFRIT, K, V. SEYFRIT, K, V	7905040488	50-313		SHEA, J R	7705250271 7705300426	50-344	
GEYFRIT, K V BEYFRIT, K V	790504048 <i>9</i> 7905040492	50-458 50-498		SHEDECOR, E SHEDLOSKY, J T	7905240704	50-245	
BEYFRIT, K. V	7905040494	50-482		SHEKETOFF, C SHEKETOFF, C	7905300615 7905300607	50-271 50-271	
BEYFRIT, K. V. BEYFRIT, K. V	7905040496 7905040498	50-382 50-267		SHELLEY, W J	7905090425 7905290083	40-8027 50-443	
SEYFRIT, K V SEYFRIT, K V	7905040501 7905040557	50-445 50-298		SHEPARD, A M SHERMAN, F L.	7905240078	70-33	
SEYFRIT, K V.	7905040606 7905040610	50-313 50-458		SHERWDDD. G O	7905080440 7905140274		
SEYFRIT, K V. SEYFRIT, K V.	7905040413	50~498		BHERWOOD, 0 0. BHERWOOD, 0 0	7905300532 7905310339		
BEYFRIT, K. V. BEYFRIT, K. V.	7905040617 7905040618	50-482 50-382		BHENKON'S C	7905140012	50-320	
BEYFRIT, K. V.	7905040621 7905040623	50-278 50-285		BHEWMON, P O BHIDELER, J J.	7905290262 7905080516	50-462	
BEYFRIT, K. V. BEYFRIT, K. V.	7905040627	50~267		SHIER, W O	7905100021 7905100235	50-307	7905100021 BNL-NUREQ-25781
SEYFRIT, K. V. SEYFRIT, K. V.	7905040629 7905070043	50-445 50-313		SHIMSHAK, R E	7905250407	50~409	NUREG/CR-0426 V1
SEYFRIT, K. V. SEYFRIT, K. V.	790507005 <i>0</i> 7905070055	50~45B 50~49B		SHIPLER, D B SHIVELY, G N.	7905030015 7905150601	50-368	
BEYFRIT, K V	7905070062	50-482		SHIVELY, C. N SHIVELY, C. N	7905140176 7905140182	50-36 <del>0</del> 50-369	
BEYFRIT, K Y BEYFRIT, K Y	790507006 <i>6</i> 7905070072	50-382 50-298		SHIVELY, C N.	7905140185	50-368 50-368	
BEYFRIT, K V	7905070073	50-285 50-267		SHIVELY, C. N. SHIVELY, C. N.	7905170239 7905140263	50-319	
BEYFRIT, K. V BEYFRIT, K. V.	7905070077 7905070080	50-445		SHIVELY, C N.	79051505B0 79051505B7	50-368 50-368	
BEYFRIT, K. V BEYFRIT, K. V	7905010435 7905010440	50-362 50-445		SHIVELY, C N.	7905170232	50-348	
BEYFRIT, K. V.	7905010441 7905010443	50-498 50-458		SHIVELY,C N. SHIVELY,C N.	7905170259 7905220400	50-346	
SEYFRIT, K. V SEYFRIT, K. V.	7905090096	50-313	5	SHIVELY, C N	7905220405 7905290109	50-369 50-313	
SEYFRIT, K. V. SEYFRIT, K. V	7905090098 7905090099	50-458 50-498		SHIVELY, C N	7905300517	50-368 50-317	
SEYFRIT, K. V.	7905090100	50-462 50-382		SHOEMAKER, C L SHOOP, P. R	7905160325 7905110026		
BEYFRIT, K. V. BEYFRIT, K. V.	7905090101 7905090103	50-298		SHORB, E M SHORT, T E	7905210277 7905290222	50-347 50-285	
SEYFRIT, K V. BEYFRIT, K V	7905090104 7905090106	50~285 50~267		SHORT, T. E	7905150211	50~285 50~285	
BEYFRIT, K. V.	7905090108 7905030265	50-445 50-313		SKORT, T. E. SKORT, T. E	7905230618 7905100128	50-265	
BEYFRIT, K. V. BEYFRIT, K. V	7905030267	50-458		SHORT, T.E.	7909240672 7905290499	50-265 50-265	
BEYFRIT, K. V. BEYFRIT, K. V.	7905030271 7905030273	50-498 50-492		SHORT, T. E.	7905090044 7905090363	50~295 50~295	
8EYFR1T, K. V	7905030274 7905030277	50-392 50-298		8HORT, T.E. 8HORT, T.E.	7905140238	50-205	
BEYFRIT, K. V. BEYFRIT, K. V.	7905030280	50-285		SHORT, T. E. SHORT, T. E.	7905150319 790523045B	50-265 50-265	
BEYFRIT, K. V BEYFRIT, K. V.	7905030282 7905030283	50-267 50-445		SHORT, T E.	7905310248 7905030210	50-205 50-320	
SEYFRIT, K Y	7905010446 7905080346	50-482 50-313		81E88. C. 81E88. C.	7405100052	50-320	
SEYFRIT, K. V. SEYFRIT, K. V.	7905080348	50-36B		BIOH.H BILK.E.J.	7905030332 7905070245	50-409 70-1201	
SEYFRIT, K. V SEYFRIT, K. V.	7905080352 7905080354	50-278 50-285		BIMCHUK, J. D	7905150786 7905020447	71~9132 50~320	
SEYFRIT, K. V.	7905080355 7905240886	50-267	NUREQ/CR-0785	BIMONS, D. B.	7905070213	50-255	
SHA, W T SHACKELFORD, B	7905300364	50-275 50-312		BINGLÁIR: M BJOGREN: R. M.	7905290691 7905150520	50-309	
BHACKELFORD, B. BHAFER, W. D.	7905150053 7905250410	50-302		SJOGREN, R. M SJOGREN, R. H	7905150343 7905150337	50-271 50-29	ı
BHALLER, D. V. BHALLER, D. V.	7905250352 7905040001	50-315 50-316		SKARUPA, J. D.	7405280265		
	•						

AUTHOR	ACCEBBION NUMBER	DOCKET	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
GKOGEN, F. B	7705100290	50-305	XN-NF-79-27	SPENCER, W C.	7905070473	50-280	
GKOLDB, J L GLAGGIE, E L	7905020471 7905220426	50-337 50-320		SPENCER, W C. BPENCER, W C.	7905070610 7905250092	50-280 50-280	
SLICKEY, F K	7905150545	50-445		SPENCER, W C.	7905250132	50-280	
SLOBODIEN, H J	7905210108	50-320		SPESSARD, R L.	7905150134	50-331	
erobodien' k 1	7905210144 7905210247	50-320 50-320		SPRAUL, J STACHOM, E Q.	7905250122 7905230818	50-522	
BLOBODIEN, M J	7905210246	50-320		STAENBERG, M. R	7905100157	50-275	
Brocomin n Brobodievik n	7905210293 7905140527	50-320 50-266		STAFFA,R W STAFFA,R.W	7905100244 7905300309	50-321 50-321	
SMITH, W R	79052504B1	50-250		BTAFFA, R. H	7905240489	50-424	
SMITH, H. P SMITH, M. E.	7905070181 7905300467			STAHL, D M STAHL, D	7908250361 7905140138	50-445 50-445	
SKITH, C V.	7905070584	50-243		STAHL, D.M	7905030260	50-445	
SMITH, R E SMITH, J, R	7905300422 7905290641	50-182 50-471		STAHL,D M STAHL,D	7905240241 7905100118	50-445 50-445	
SMITH. J R	7905290637	50-471		STAHL, D	7905100123	50-445	
SMITH, I W SMITH, I W	7905240105 7905290583	50~389 50~395		STAHL,DM STAHLE,CR	7905100271 7905100220	50-445 50-390	
BMITH, I W	7905150796	50-389		STALLINGE, C M	7905040305		
SMITH, I W SMITH, B H	7905250362 7905250137	50-400 50-272		Stallings, C M	7905290125 7905230658	50-338 50-338	
SMITH, B. H	7905150180	50-272		STALLINGS, C H	7905140401	50-338	
SMITH.BH SMITH.B, H	7905150187 7905150192	50-272 50-272		STALLINGS,C M STALLINGS,C M	7905290372 7905080164	50-281 50-280	
SMITH, B H	7905030020	50-272		STALLINGS, C M	7905230431	50-338	
H B.HTIMS H B.HTIMS	7905070131 7905290055	50-471 50-471		STALLINGS, C M	7905020245 7905020474	50-338 50-338	
SMITH, B H SMITH, B, H	7905070129	50-471		STALLINGS, C M	7905020512	50-280	
SMITH, O H	7905150068 7905210110	50-272 50-320		STALLINOS, C. M STALLINOS, C. M	7905240181 7905010484	50~260 50~261	
SMITH, O H	7905210112	50-326		STALLINGS, C. M	7905010492	50~280	
BMITH, Q. H	7905190173 7905210072	50-320 50-320		STALLINGS, C M STALLINGS, C M	7905020358 7905020391	50-338 50-338	
SMITH, OH SMITH, OH	7905210261 7905210308	50-320		STALLINGS, C M	7905040036	50-280	
BMITH, CH	7905210299	50-320 50-320		STALLINGS,C M STALLINGS,C M	7905040626 7905300734	50-338 50-338	
SMITH, O C SMITH, O H	7905110036 7905300108	70-820		STALLINGS, C M	7905040380	50-280	
SMITH O H	7905210273	50-320 50-320		STALLINGS, C M. STALLINGS, C M	7905040396 7905070637	50-280 50-280	
SMITH, O H SMITH, O H	7905110102 7905110105	30-6134 30-6134		STALLINGS, C. H	7905080441	50-339	
H C'HINB	7905230724	50-277		STALLINGB.C M, STALLINGS.C M.	7905070530 7905070655	50-338 50-280	
SMITH, G H	7905290188 7905090134	50-3 50-220		stallings, C. M Stallings, C. M	7905070656	50~338	
EMITH, O. H.	7705240274	50-244		BTALLINOS, C. N	7905240481 7905300706	50-280 50-280	
SMITH, Q H SMITH, Q H,	7905110072 7905230694	30-6134 50-277		STALLINOS, C M STALLINOS, C M	7905080428 7905080444	50-338 50-338	
SMITH, O H	7905290177	50-3		STALLINGS, C M.	7905080504	50-338	
SMITH.R BMDLINSKY.J H	7905110340 7905030247	50-320 50-549		STALLINGS, C. M. STALLINGS, C. M.	7905080538 7905110142	50-280 50-338	
BMOLINSKY, J	7905030350	50-549		STALLINGS, C, M	7905190062	50-338	
SMOLINSKY, J, SNAIDER, R, P	7905070467 7905290523	50~596		STALLINGB.C M. Stallings.C.M	7905110087 7905110157	50-280 50-280	
SNIEZEK' N H	7905100375 7905110006	50-346		STALLINGB, C M	7905150510	50~280	
SNIEZEK, J H	7905210253	50-312 50-320		Stallings, C. M. Stallings, C. M.	7905150270 7905160432	50-338 50-338	
SNOM'S V SNIEIEK'Y H	7905220412 7905220223	50-320 50-244		STALLINGS, C M	7903190191	50-338	
SNYDER, A. W	7905300061	50-320		STALLINGS, C. M Stallings, C. M	7905190119 7905210176	50-260 50-338	
SNYDER, G. L. SNYDER, B. J	7905300090 7905160102	50-320 50-320		STALLINGS,C M STALLINGS,C M.	7905210258 7905210275	50-338 50-280	
5090N, L J	7905040028			STALLINGS, C M	7905220142	50-280	
8080N,L J,	7905210173 7905290259	50-219		STALLINGS, C. M. Stallings, C. M	7905230536 7905220287	50-338 50-338	
SOBONIL J.	7905030340 7905140392	50-219		STALLINGB.C M	7905230060	50-339	
SOBON, L J	7905210152	30-214		STALLINGS, C M	7905230341 7905240342	50-281 50-338	
8080N, L. J.	7905300558 7905310321			STALLINGS, C. M.	7905240485	50-280	
SOHINKI'S W	7905310013	50-466		STALLINGS, C M STALLINGS, C M	7905250108 7905250141	50-280 50-280	
SOHINKI, S. M. SOHINKI, S. M.	7909210981 7905150127	50-466 50-592		STALLINGS, C. M.	7905290005	50-260	
SCHINKI, S K	7905100276	50~466		STALLINGS, C.M.	7905290032 7905290001	50-280 50-280	
SOHINKI, S. M. SOHINKI, S. M	7905300072 7905150125	50-466 50~335		STALLINGS, C. M. STALLINGS, C. M.	7905300018 7905300312	50-280 50-280	
SOHINKI, S.M. SOHINKI, B.M.	7905150737 7905150740	50-452		STALLINGB, C. M.	7905300401	50-338	
SOHINKI,8 M	7903130745	50-466 50-485		STALL, D. H. STAMPLEY, N. L.	7905240391 7905090271	50-6	
SOHINKI, S. M. SOHINKI, S. M	7905150748 7905300537	50-592 50-592		STAMPLEY, N. L.	7905300439	50-416	
SOHINKI, S. M.	7905100125	30-466		STANCIL,R Stanley,W s	7905150348 7905080451	50-366 50-289	
SOHINKI, S.M. SOHINKI, S.M.	7905100146 7905100122	50-466 50-437		STANLEY, K. S.	7705080547	50-289	
BOHINKI, B, M	7905240133	50-592		STANLEY, H. S STARKEY, R. B	7905140296 7905040535	50-289 50-261	
BOHINKI, B. M. BOHINKI, B. M	7905240296 7905240149	50-466 50-466		STARKEY, R B.	7905150451	50-261	
SCHINKI, S, M SOLBERG, D E.	7905240528	50-466		STARKEY,R.B. Starkey,r B.	7905150463 7905190030	50~241 50~261	
SOLBRIO, C. W	7905110273 7905040482	50-320 50-10		STARKEY, R B Starkey, R B.	7905190088 7905220110	50-261 50-261	
SORENSON, S M. SOUCY, A R.	7905250376			STARKEY, R. B.	7905290230	50-261	
BOUCY, A R	7905160309 7905310390	50-29 50-29		STEINER, R. STEINHARDT, S.	7905070143 7905240469	50-320 50-271	
SPAAK, F, SPARKB, E	7905150573 7905150692	71-47		STEIN, M H.	7905300114		
SPARKS, D W.	7905170302	50-272		STELLO, V. STELLO, V.	7905020128 7905110050	50-320 50-312	
SPECTOR, S SPECTOR, S,	7905110104 7905310435	50-244 50-244		STELLO, Y	7905110180	50-312	
SPEIS, T P.	7905310160	50-267		STELLO, V. STELLO, V	7905090284 7905080347	50-313 50-280	
SPEIS, T. P SPEIS, T. P	7905310171 7905310186	50-267 50-267		STELLO, V. STELLO, V.	7905070017 7905230123	50-309	
SPEIS, T. P. SPELMAN, H J.	7905300210	50-267		STELLO, V	7905190194	50~320 50~320	
BPENCER, W C	7905240114 7905300520	40-2061 50-280		STÉLLO, V. STELLO, V	7905230801 7905230081	50-320	
SPENCER, W. C. SPENCER, W. C.	7905240162 7905240783	50-338 50-339		STELLO, V.	7905230085	50-320	
	COTUPAGES S	JU-337		STELLO, Y.	7905150174	50-313	

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
STELLO, Y.	7905100158	50-260		STOODLEY.D @	7905100934	50-471	
GTELLO, V.	7905230125	50-320		STOODLEY, D G	7905240233 7905290626	50-471 50-471	
STELLO, V. STELLO, V.	7905230128 7905230135	50-320 50-320		O divandons	7905220282	50-317	
STELLO, V.	7905070014	50-295		STRAIN P	7905140191	** ***	
STELLO, V.	7905290552 7905210055	50-296 50-320		etratkan R. A Strause K. J	7905300457 7905150652	50-936	
STELLO, V. STELLO, V	7405230175	50-320		STREDEL, B J	7705100004		
STELLO, V	7905030212	50-320 50-320		STREBEL, S J STREETER, J F	7905100007 7905070027	50-373	
STELLO, V STENSVAGO, J	7905100054 7905080411	20-263		STREETER, J. F	7905090175	50-409	
STENBVAAO, T	7905080482	50-263		STRELOW, R	7905150498 7905150494		
STEPHENS, PW. STEPHENSON, BB	7905300263 7905040432	50~133 50~237		BTRELOW, R STRICHT, R L	7905240218	50-592	
STEPHENSON, B S	7905080535	50-237		STROTZ, R H	7905170243 7905140428	50-598	
STEPHENSON, B. B STEPHENSON, B. B	7905080548 7905220257	50-249 50-237		BTROUPE, E.P. BTROUPE, E.P	7705140426		
STEPHENSON, B B	7905140318	50-249		BTROUPE, E P BTROUPE, E P	7905220348 7905140297		
STEPHENSON, B B	7905160384 790516035 <b>4</b>	50-237 50-10		BTROUPE, E.P.	7905020328		
STEPHENBON, B B	7905170226	50-237		STRUMNASGER, M J	790503009 <i>0</i> 7905110021	70-1318	
STEPHENSON, B B. STEPHENSON, B B	7905300567 7905300443	50-237 50-237		STUKENBROEKER, O SU, T, M	7905020235	50-219	
STEPHENBON, B. B	7905300485	50-237		GUDBECK, R. R.	7905160296	50-116	
STEPHENSON, B B STEPHENSON, B B.	7905300579 7905300697	50-249 50-249		BULLIYAN, T J BULLIYAN, T, J	7905230761 7905230478		
STEPHENSON, B B.	7905300475	50-237		SULLIVAN, T J	7705070416	** ***	
STEPTOE, P STERNBERG, D M	7905250158 7905230640	50-295 50-275		SULLIVAN: R. F SUNDARAM: R. K.	7905150107 7905020151	50-259	7903020131
STERNBERG, D M	7905290152	50-275		BUTHERLAND, J T.	7905070070	50-327	
STETKA, T F STEVENSON, W M	7905110394 7905220037	50-271 50-382		GUTHERLAND, J. T BUTHERLAND, J. T	790501019 <i>3</i> 7905290130	50~124 50-338	
STEVENS. J R	7905110137			SUTHERLAND, J T.	7905230672	50-338	
STEWART, W. P	790507053B 7905010408	50-302 50-302		BUTHERLAND, J. T BUTHERLAND, J. T	7905230610 7905290092	50-261 70-1113	
STEWART, W. P. STEWART, W. P	7905080095	50-302		SUTHERLAND, J T	7905240992	50-25	
STEHART, W. P	7905100238	50~302 \$0~302		SUTHERLAND, J. T SUTHERLAND, J. T	7905070095 7905230648	70-1113 50-338	
STEWART, W.P. STEWART, W.P	7905250390 7905240802	50~302		BUTHERLAND, J T	7905230598	50-261	
STEWART, N P	7905040043	20-305		GUTHERLAND, J T GUTHERLAND, J T	7905240947 79052900B2	50-25 70-1113	
STEWART, W. P STEWART, W. P	7905030351 7905040088	50-302 50-302		SUTHERLAND, J T	7705270062	50-336	
STEWART, W. P	7905040530	50-302		BHAIN, W.E.	7905170296	71-300 71-300	
Stewart, W. P Stewart, W. P.	7905070537 7905070597	50-302 50-302		SWAIN, H E SWALES, J	7905170299 7905240699	50-265	
STEWART, W. P	7905070611	50-302		SWAN, W B.	7905250431	50~5GB	
STEHART, W. P STEHART, W P	7905070424 7905070445	50-302 50-302		BHANIH B BHANBEROFF,	7905240537 7905110275	50-491 50-320	
STEWART, W. P.	7905070652	50~302		BHANBON, D. O	7905030339	50~437	
STENART, N. P. STENART, N. P.	7903080429 7905290493	50~302 50~302		BHANSON, Y.A. BHANSON, D. T	7905080313 7905290053	50-375 50~596	
STEWART, N P	7905090278			BWANSON, D.T.	7905100178	50~596	
STEWART, W. P	7905290013 7905110241	50~302 50~302		T D NOBNAWB T D NOBNAWB	7905241006 7908240255	50-338 50-338	
STEWART, W P STEWART, W P	7705170023	50~302		SWART, F E.	7705140288	50-247	
STEMART, N P	7905210153	50~302 50~302		SWART, FE SWART, FE	7905140319 7905300222	50-267 50-267	
STEWART, W.P. STEWART, W.P.	7905210272 7905230349	50~302		BWED₁ J. P	7905300571		
STEWART, W. P	7905250375	50~302 200~302		BWEENY, M BWINDLE, D L	7905220423 7905150389	50-320 51E-05	
STEWART, W P STEWART, W P	79052503B3 7905300497	50~302 50~302		SWITZER, D. C	7905160262	50-334	
STEWART, W. P	7905310298	50~30g		BWITZER, D. C BZALINBKI, P. A	7905160376 7905110141	50-336	
STENART, W P STENART, W, P	7905300158 7905300185	50-302 50-302		TALWANI, P	7905300700	50-395	
STEWART, W P.	7905300484	50~302		TAMBLING: T.N TAMBLING: T.N	7905110111 7905100362	50-34 <i>6</i> 50-34 <i>6</i>	
STEWART, W. P STEWART, W. P.	7905300544 7905310391	50~302 50~302		TAMPLIN, A.R.	7905140079	70-2423	
STEWART, W L	7905020519	20~380		TANAKA, N. TANNER, H. A.	790514009 <u>6</u> 7905310360	80-329	
STEWART, W. L. STEWART, W. L.	7905010497 7905010498	50~281 50~280		TAPIA, J I	7905010312	50-492	
STEWART, W L	7905040414	50-280		TAVERNIER, O. N	7905140045 7905030194	50-312	
STEWART, D. STEWART, W. L	7905150515 7905110164	50~260 50~260		TAYLOR, J. H. TAYLOR, J. H	7908070555		
STEHART, W. L.	7905190123	50-280		TAYLOR, J. H TAYLOR, J. H	7905100153 7905020348		
STEHART, H. L STEHART, H. L.	7905230344 7905250150	50~281		TAYLOR, J H	7905030356		
STEHART, H. L.	7905250154	50-280		TAYLOR, J. H. TAYLOR, J. H.	7905210136 7905140314		
STEWART, W. L. STEWART, W. L.	7905250157 7 <del>9</del> 05290010	50-280 50-280		TAYLOR, J. R	7905080242		
STEWART, R. C.	7905150550	50-392		TAYLOR, J. H. TAYLOR, J. H	7905190161 7905160370		
STEYER, K. Q STODDART, P.	7705160104 7 <del>7</del> 05230141	50-320 50-320		TAYLOR, J. H.	7905160388	70-135	
BTODDART, P.	7905230152	50-320		TAYLOR, J. H.	7905220408 7905160373		
STOHR, J. P. STOHR, J. P.	7905190148 7905190170	50-320 50-320		TAYLOR, J. H TAYLOR, J. H	7905220324		
STOHR, J. P	7905190177	50-320		TAYLOR, J. H. TAYLOR, J. H	7905240494 7905310406		
STOHR, J. P. STOHR, J. P	7905210133 7905210140	50-320 50-320		TAYLOR, J. H.	7405310343		
STOHR: J. P	7905210124	50-320		TAYLOR, J H.	7905310370	50-313	
STOHR, J. P. ETOIBER, C	7905210245 7905250324	50-320		TAYLDR, J. H TAYLOR, R. L.	7705310377 7705140225	50-250	
STOIBER, C.	7905090218	50-320		TAYLOR, P. A TAYLOR, R. Q TAYLOR, R. Q.	7905230503	50~249	
STOIBER, C STOLZ, J. F.	7905090223 7 <del>90</del> 5070674	50-320 50-275		TAYLOR, R. G.	7905070209 7905010370	50-445 50-445	
BTOLZ, J. F.	7705070270			TAYLOR, K.	7905300259	50~320	
STOLZ, J. F. STOLZ, J. F.	7905230578 7905290528	50-275 50-341		Tedebco, R. L Tedebco, R. L	7905110239 7905110290	50-320 50-320	
STOLZ, J. F	7905230826	50~522		TEDESCO.R L	7905110334	50~320	
STOLZ, J.F. STOLZ, J.F.	7905240572 7905100431	50-359 30-416		TEDEBCO, R. L. TEDEBCO, R. L.	7905190155 7905220457	50~320 50~320	
STOLZ, J. F.	7905240857	50-522		TEDEBCO, R. L.	7908110349		
STOLZ, J. F. STOLZ, J. F.	7905250049 7905310083	50~313 50~341		TEDEBCO, R. L. TELFORD, J. T	7905010198 7905230278	50-320 50-320	
STONE, L. R.	7905220397	50-520		TELFORD, J. T.	7905230245	80-320	
BTONE.R. BTONE.R.	7905240718 7905300742	50-250 50-250		TELFORD, J. T. TEMPEST, L	7905210073 7905240424	90-320	
- <del> </del>		AA MAA		······			

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET	REPORT NUMBER
TEMPLE, J	7905250493 7905240346		700824024;	TRIMBLE, D C	7905110007	50-368	
TEPELIR C TERNEY, H B	7905230104	50-255	7905240346	TRIMBLE.D C	7905150215 7905040008	50-313 50-313	
TERRY, B H TERRY, B H	7905040168 7905040165	50-294 50-294		TRIMBLE.D C	7905070490 7905110066	50-313 50-313	
THADANI, A C	7905250102			TRIMBLE, D C TRIMBLE, D C.	7905140172	50-368	
THADANI.A C	7905290597 7905240476			TRIMBLE.D C	7905150460 7905140250	50-313 50-313	
THADANI.A C THADANI.A C	7905250210 7905230087	50-255 50-255		TRIMBLE,D C	7905150572 7905170227	50-348 50-348	
THAMS, R. W THIELSCH, H	7905240285 7905080128	71-158 71-36		TRIMBLE, D C TRIMBLE, D C	7905170254 7905190167	50-313	
THIEBING, J W	7905230496	50-320		TRIMBLE, D C	7905230020	50-313 50-313	
THIESING, J W	7905230468 7905230065	50-320 50-320		TRIMBLE,D C	7905220248 7905210266	50-313 50-313	
THIESING, J W	7905230069 7905110125	50~269 50~320		TRIMBLE,D C	7705220398 7 <b>70524</b> 0365	50-348 50-313	
THIES, A C THOMAS, E B	7905110129 7905030346	50-269		TRIMBLE, D C	7905240712	50-313	
THOMAS, E B	7905030357	50-220 50-244		TRIMBLE, D C	7905290155 7905300488	50-313 50-313	
THOMAS, E B THOMAS, E B	7905040085 7905310218	50-485 50-220		TRIMBLE, D C Trimble, D C,	7905290103 7905300001	50-313 50-313	
HOHAS,E B HOHAS,J H	7905040007 7905290665	50-341 40-3392		TRIMBLE, D.C. TRIPP, L	7705300509 7905210240	50~346	
THOMAS, E.L. THOMAS, Q	7905040313			TRIPP,L	7905020140	50-320 50-289	
THOMAS, Q	7905240275 7905150063	50-55 <u>6</u> 50-58 <u>6</u>		TRIPP,L TRIPP,L	7905290137 7905040156	50-307 50-387	
THOMAS, W N THOMAS, R D	7905040469 7905020520	50-260 50-142		TROCHESSET,K P TROFFER.O J	7905230744 7905030338	50~466 50~289	
THOMAS, C O THOMPSON, M W	7905150641 7905020254	50-556 50-269		TROFFER.0 J	7905090320	50-320	
THOMPSON: D	7905110416	50-500		TROUP, O L TROWBRIDGE, C D	7905070101 7905240293	70-1113 71-222	
THOMPSON, D THOMPSON, D	7905020260 7905040296	50-320 50-320		TROWERIDOE, Q. F TROWERIDOE, Q. F	7905090247 7905300698	50-320 50-400	
THOMPSON, D THOMPSON, D	79051402 <b>5</b> 3 7905160201	50-320 50-320		TROWERIDGE, O F	7705080232	50-400	
THOMPSON H L	7905160113	50-320		Troweridge, Q, F	7905250340 7905140221	50-382 50-400	
THORNBURGH, D	7905090140 7905190251	50~220 50~320		TROWBRIDGE O F	7905140241 7905150738	50-400	
THORNBUROH: D	7905140092 7905230857	50-320 50-482		TROWBRIDGE, O F TSUJI, K	7905220459 7905240005	50-320	
THORPE, J R THRASH, C Q	7905090203 7905250230	50-466		TSUJI, K	7905240010		
THRASH, C. Q	7905300066	50-466		TSUJI, K TSUJI, K	7905250037 7905290190		
THRASH, C Q THRASH, C Q	7905310407 7905290068	50-466 50-466		TURLEY, R E. TURNER, J E.	7703010661 7703130647	50-72 71-217	
THRASH, C G THRASH, C G	7905240310 7905240043	50-466 50-466		TURNEY, W G	7905140251	14E-06	
THURLOW, E W	7905230803	50-309		TURNER, E. A. TURNER, E. A.	7905240699 7905030336	50~498 50~498	
TIBBITTS, D L. TIBBITTS, D L.	7905230686 7905240340	50-395 50-395		TURNERIE A. TURNERIE A.	7905080408 7905150236	50~498 50~498	
TIERNEY F P TIETZ, Q	7905040521 7905240707	50-2 <u>82</u> 50-265		UDALE, M. K UGRIG: R E	7905300657		
TILBE,H.E. Tilbe,H r	7905160124 7905300175	50-320		UHRIG.R E	7905040585 7905150405	50-335	
TIMKO,D R	7905140302	50-320 50-334		UHRIG, R E Uhrig, R E	7905300040 7905290159	50-250 50-335	
TIPTON, T. E TOALSTON, A L	7905240513 7905230832	50~217 50~329		UHRIG,RE UHRIG,RE	7905240045 7905150247	50-935	
TOALBTON, A L TOBIN, W J	7905310373 7905020087	50-361 50-269		UHRIO, R E	7905240434	50-250 50-250	
TOBIN, W J. Tobin, W J	7905020033	50-280		UHRIQ,R.E UHRIQ,R.E	7905240169 7 <del>9</del> 05070410	50-335 50-335	
TODD, C. A	7905300026 7905240069	50-338 50-335		UHRIO, R. E. UHRIO, R. E	7905140217 7905140220	50-250 50-250	
۹ ۱. Q. K	7905300021 7905090229	70-1201 50-320		UHRIG, R. E UHRIG, R. E	7905140310	50-335	
1: A C	7905030347 7905080518	50-324 50-325		UHRIQ.R E	7905210121 7905300015	50-335 50-250	
ţ	7905090289	50-324		UHRIG, R. E. Uhrig, R. E	7905220027 7905240486	50-335 50-251	
	7905090311	50-324		UHRIO,R E Uhrio,r,e.	7905240547 7905250397	50~250	
				UHRIG: R E	7905250411	50-335 50-250	
				UHRIGIR.E UHRIGIR E.	7903290143 7905310214	50~250 50~335	
				UHRIQ,RE. UHRIQ,RE.	7905300014 7905310305	50-335 50-335	
				UHRIQ,R E ULLMAN,A	7905310309	50-335	
				ULRICH: W T,	7905300507 7905140346	50-277	
				ULRICH, W. T. URBAN, M.	7905230861 7905240598	50-277 50-392	
				URHIO, R. E. URHIQ, R. E.	7905080412 7905250426	50-250 50-250	
				UTLEY, E. E UTLEY, E. E.	7905190013	50~261	
				UTLEY, E E	7905100241 7905230613	50-324 50-261	
				UTLEY, E. E. UTLEY, E. E.	7905010517 7905030331	50-261 50-261	
				UTLEY, E. E. UTLEY, E. E.	7905030353 7905010557	50-324	
				UTLEY, E E. UTLEY, E, E,	7905240192	50-261 50-324	
				UTLEY, E. E	7905040084 7905010552	50-261 50-261	
				UTLEY, E, E UTLEY, E, E,	7905020333 7905040032	50-261 50-261	
				UTLEY, E E. UTLEY, E. E.	7905040624	50-324	
				UTLEY, E. E.	7905300263 7905060402	50-324 50-324	
				UTLEY, E. E. UTLEY, E. E.	7905080417 7905080436	50-324 50-324	
				UTLEY, E E UTLEY, E. E.	7905080437 7905300294	50-261	
				UTLEY, E. E. UTLEY, E. E.	7905310379	50-261 50-324	*
				UTLEY, E. E.	7905150328 7905210165	50-261 50-324	
				UTLEY, E. E. UTLEY, E. E	7905250121 7905220346	50-261 50-261	
				•			

AUTHOR	ACCEBBION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
UTLEY, E E	7905290374	50~261		WALERIDGE, W C	7905010477	50-443	
UTLEY, E E	7905300449 7905290370	50-324		HALKERIR B HALKERIR D	7905020123 7905150134	50-320 50-331	
UTLEY, E. E. UTLEY, E. E.	7905290388	50-261		WALL I B	7905230419		
VAHRENWALD, J	7905100297 7905240687	50-254 50-265		WALL, I B WALLACE, A	7905230434 7905190070	50-320	
VAHRENWALD, J VALORE, C	7905230525	50-272		HALLACE A T	7905250448		
VALORE: C	7905230532	50-272 50-272		WALLACE, A WALLACE, E G	7905240417 7905230015	50-320	
VALDRE, C	7905150801 7905230453	50-272		WALLACE, J A	7905250213	50-331	
VALORE, C	7905250024	50-272		WALLACE, L E Wallace, J J	7905240874 7905150335	50-518 50-305	
VALORE, C. VAN BRUNT, E E	7905250028 7905220386	50-272 50-529		HALLACE, J R	7905300162	50-320	
VAN BRUNT, E E	7905310378	50-592 50-592		WALPOLE, J R WALBKE, C	7905150752 7905140086	50-320	
VAN BRUNT, E. E. VAN BRUNT, E. E.	7905300287 7905150409	50-528		WALTERS, D K	7905020442	50-327 50-289	
VAN BICKEL, J	7905020253 7905160368	50-331 50-331		WALTON, G A WANDKE, N E	7905020140 7905020272	50-295	
VAN BICKEL, J.	7905160387	50-331		WANDKE, N E	7905090322	50-295 50-304	
VAN BICKELIJ	7905210224 7905290191	50-331 50-331		HANDKE N E	7905100300 7905100306	50-304	
VAN BICKEL, J VAN TRAN, T	7905100229		NUREG/CR-0724	WANDKE N E	7905240543 7905240550	50-295 50-304	
VANBRUNT, E E	7905290054 7905290072	50~528 50~528		WANDKE N E WANDKE N E	790524 <b>05</b> 3B	50-295	
VANBRUNT, E E VANDENBURGH, D E	7905250355	50~309		WANG, C H	7905070584 79052 <b>5</b> 0469	50-243	
VANDENBURGH, D	7905210161 7905010480	50-309 50-271		HARD, J E Ward, E C	7905020462	50-282	
VANDENBURGH, D. VANDENBURGH, D. E.	7905010500	50-271		WARD, E C.	7705140214 7705230308	50-282 50-341	
VANDENBUROH, D E	7905240613 7905250473	50-271		WARD,K D WARD,K D	7905290569	50-135	
VANDENBURGH, D VANDEL, T.E.	7905290720	50~358		WARD, K D.	7905240716 7903010507	50-373 50-247	
YANNESS, S C	7905240789 7905070665	50~272 50~556		Warembourg, D Warembourg, D	7905040374	50-267	
VARGA:8 A VARGA:8 A	7905230795	50~397		HAREHBOURG, D WAREHBOURG, D	7905080544 7905080455	50-267 50-267	
VARQA:8 A	7905090299 7905100171	50-466 50-546		WAREMBOURG, D	7905160367	50-267	
VARÇAIB A VARÇAIB A	7905100435	50-413		WAREMBOURG, D WAREMBOURG, D	7903160372 7905160315	50~267 50~267	
VARGALE A	7905150649 7905080497	50-327 50-321		HAREHBOURG, D	7905230025	50-267	
VASGUEZ,R D VASSALLO,D B.	7905080278	00 OK1		Harembourg, D Warnick, R. F	7905230393 7905020208	50-267 50-315	
YASSALLO, D B	7905080171 7905080217			WARNICK, R F	7905080093	50-255	
VASSALLO, D. B. VASSALLO, D. B	7809050087	50-457	NUREG-0219	HARNICK, R. F. WARNICK, R. F	7905290546 7905240729	50~243 50~358	
VASSALLO, D B.	7905080230			WARREN, H. C.	7905100369	71-307	
VASSALLO, D. B VASSALLO, D. B	7905080259 7905110143			WARREN, K C WARRENBOURG, D	7905100368 7905250464	71-307 50-267	
VASSALLO, D B	7905160185 7905020400	50-320 50-367		WATANABE, N	7905250041		
VASSALLO, D B	7905020406	50-382		WATANABE, N WATERHOUSE, E	7905250045 7905300720	50-275	
VASBALLO, D. B.	7905020414 7905020420	50-395 50-437		WATERHOUSE, H	7905300719	50-275 50-261	
VASSALLO, D B. VASSALLO, D B.	7905020424	50-440		WATFORD, M. L. WATFON, B	7905150426 7905240725	50-546	
YASSALLO, D B.	7905020432 7905020437	50~492 50~458		WATSON, C.	7905020192	50-358	
VASSALLO, D. B. VASSALLO, D. B.	7905020445	50-546		WATTERHAHN, M J WATTE, M J	7905170303 7905020169	30-300	
VASSALLO, D. B	7905020452 7905010156	50-556 50-320		L MIBTTAN	7905150368		
YASSALLO, D. B. YASSALLO, D. B.	7905110158	50-320		HATTS:H J Webbir E.	7905100142 7905150691	50-295	
VASSALLO, D B	7905110414 7905100395	50-320		WEBER, S	7905250353 7905090261	50-596	
VASBALLO, D B.	7705160112	50-320		WEBER, M D WEBSTER, L	7905020246	50-320	
VARBALLO, D. B.	7905100372 7905100370	50-320 50-320		WEBSTER, E. H.	7905290174 7905190130	50-335 50-133	
VASSALLO, D B	7905100389	50~320		WEEKS, J R.	7905150196	50-27	BNL-NUREG-23021 BNL-NUREG-25582
VASBALLO, D. D. VASBALLO, D. D	7905250126 7905100388	50~522 50~320		HEEKS, J. R	7905150201 7905030246	50-272	NUREG/CR-0523
VASSALLO, D. D.	7905230840	50-368		HEGLEY, H. L. HEHRLE, R. R.	7905290511	71-104 50-458	
YERDERY, E. H. YIOLETTE, J. B.	7905150259 7905250531	50-250		HEIGAND, J. G. Heiland, R H	7905310429 7905300658	71-57	
H HATHOLOV	7905300025	50-341 50-485		HE ENGARTEN, V. I.	7905030051	50~443	
VOTOHT, H. H. VOTOHT, H. H	7905240195 7905150074	50-485		WEINHOLD, E H WEISER, J L.	7905300334 7905210018	50-320	
ACIOHI'H H	7905240801 7905100138	50-549		HEISER, J. L	7905210021 7905030262	50-339	
YOLOER, B. H YOLLHER, R. H	7905140287	50-524		WEIBB.E.R. WEIBB.E.R	7905230749		
YOLLHER, R. H.	7905150119 7905230023	50-320		WEISS, E.R.	7905230760 7904300173		
YOLLHER, R. H YOLLHER, R. H	7905230029	50-320		Weiss, N. M	7904300341		
VOLLMER, R. H	7905230126 7905230032	50-320 50-320		WEISS, N. M	7904300354 7905100013	80-320	
VOLLHER, R. H. VOLLHER, R. H.	7905230040	50-320		Weiss, T. Weiss, D	7905240984	70-371	
VOLLHER, R. H	7905190224 7905190247	50~320 50~320		WE188, D.	7905110052 7905150790	70-364 70-8	
VOLLMER, R. H. VOLLMER, R. H	7905230176	50-320		weiss, D. Weiss, D.	7905240230	70-754	
VOLUMER, R. H	7905230116 7905230118	50~320 50~320		weissiero, s. Weissiero, s.	7905240944 7905140111	50-320	
VOLLHER, R. H. VOLLHER, R. H.	7905020128	50-320		WEISSBERG, B	7905160126	50-320	
VOLLHER, R. H. VOLLHER, R. H.	7905230165 7905100054			WEISS,S H. WENNER,S,	7905030257 7905250347		
VOLLMER, R. H.	7905210012	50-320		HENNER, 8.	7905290268		
YOLLHER, R. H. YOLLHER, R.	7905230130 7905150179			HERLING, J. A HERLING, J. A.	7905310384 7905080460	50~334	
VOLLHER, R. H.	7905100073	50-280		WERLING, J. A	7905080468 7905080545		
YOLLHER, R YOTH, M. H.	7905150808 7905070058	71-6050		Herling, J. A Herling, T. A.	7905080551	50-334	
VOTH, M. H.	7905150281	71-6058		WERLING, J A.	7905150531 7905150531	50-334	
WACHTER, L. J WACHTER, L. J.	7905070344 7905140104	50-282		HERLING, J. A. HERLING, J. A.	790524056	g 50-334	
MACHTER, L. J.	7905150575	50-263		WEBTERMAN, T. F.	790501039 790514020		
WAGHTER, L. J. WAGHTER, L. J.	7905290321 7905040517	50-263		HESTERN, F. HETMORE, J. B	790510032	4 50-409	
WACHTER, L. J.	7905040022	50-263		WETTERHAMN, M J.	790515013 790515013	3 50-35B	
MACHTER, L. J. MACHTER, L. J.	7905290290 7905230515	50-263		HETTERHAHN, M. J. WETTERHAHN, M. J.	790529017	1 50-358	
NACHTER: L. J.	7905250429 7905220465			WETTERHAMM, M J.	790529017	g 30-398	
HALBRIDGE, W. C.	, 1945E0100						

AUTHOR	ACCEBBION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
WETTERHAHN, M J WETTERHAHN, M J	7905290180 7905150151	50-358 50-358		WOLFE, 8 J WOLFE, 8 J	7905230182 7905150677	50-466 50-437	
WETTERHAHN, M J	7905300062	50-358		WOLFE, S J	7905150491	50-556	
WETTERHAHN, M J	7905300067 7905170301	50-358 50-358		WOLFE, 8 J WOLFE, 8 J	7905220071 7905230560	50-554	
WETTERHAHN, M J WETTERHAHN, H J	7905100169 7905250117	50-358 50-358		WOLFE, 8 J. WOLFE, 8 J	7905230570 7905250541	50-556	
WETTERHAHN: H J	7905250123	50-358		WOLFF, C. E	7905140541	50-392 40-9602	
WETTERHAHM, M J WETTERHAHM, M J	7905310093 7905240094	50-358 50-272		WOLFF,C E WOLFF,C E	79050303 <u>6</u> 3 7905290063	40-8602 40-8602	
HHITE, H C.	7905150589 7905150611			WOLFF.T WOLIVER.J D	7905090176		
WHITE, H	7905310111 7905140060	50-466 50-466		Waliver, J D	7905150144 7905150218	50-358 50-358	
WHITE, L D	7905250181	50-244		WONG,S WOOD,W C	7905300265 7905250492	50-206	
WHITE, LD	7905040101 7905040180	50-244 50-244		WOOD, W. C. WOOD, J. C	7905250505 7905070251	50-498	
WHITE, L D	7905070484 7905070380	50-244 50-244		WOOD, E. C WOOD, E. C	7905090382	50-309	
WHITE, C D	7905100149 7905110101	50-244		WOOD, E. C.	7905230467 7905190151	50-309 50-309	
WHITE, L D	7905220377	50-244 50-244		HOOD, E. C HOOD, E. C	7905220243 7905220251	50-309 50-309	
MHITE'L D	7905220031 7905300474	50-244 50-244		WOOD, E F WOODARD, J R	7905040506 7905140550	50-397 50-556	
MHITE'F D	7905310395 7905310431	50-244 50-244		WOODHEAD, C P	7905080392	50-444	
WHITESELL, D E WHITESELL, D E	7905110404			WOODHEAD, C P. WOODHEAD, C P	7905080039 7905090419	50-219 50-219	
MHITLOCK, W N	7905150585 7905090292	50-546		WOODHEAD, C. P. WOODHEAD, C. P	7905150143 7905100226	50-510 50-554	
WHITLER, J D WHITHAN, J H	7905240983 7905240548	50-349 40-6659		HOODRUFF,R W. HOOLEVER, E J	7905110028 7905010541	50-312	
WHITMER.C F WHITMER.C F	7905240227 7905250462	50-424		MOOLEVER, E. J	7905080370	50-412 50-334	
WHITMER, C F	7905080427	50-321		WDOLSTENHULME, J WOZNIAK, 8 F	7905310453 7905100292	50-466 50-305	
WHITMER, CF	7905190213 7905170234	50-321 50-321		WRIGHT, R L WRIGHT, K H	7905190077 7905020222	50-320 40-4492	
WHITMER, G F WHITMER, G F	7905190059 7905230047	50-321 50-321		WRIGHT.F S	7905090411	50-471	
WHITHER, C F	7905230538 7905290184	50-321 50-366		WRIGHT.M WRIGHT.R W	7905220264 7905230153	50-237 50-389	
HHITMER.C F	7905300006	50-321		WRIGHT, G. C. Wright, E. Q	7905090169 7905110144	50-331 50-320	
WHITMAN, O D WHITTEMORE, F C.	7905020004 7905100152	50~516		WRIGHT, E G. WRIGHT, E G	7905110174	50-320	
WHITTEMORE, F C	7905250311 7905150207	50-322 50-322	•	WRIGHT R W	7905110171 7905110265	50-320 50-320	
WHITT-K W	7905110006	50-312		WRIGHT, R. W. WU, T Y.	7905110266 7905240103	50-320	
WHITT, K W. WIDNER, W A	7905250410 7905290029	50-302 50-321		WYLER, E WYMAN, E H	7905230789 7905220341	50-275	
WIDNER, W A WIGGINTON, D	7905290035 7905290723	50~3 <u>21</u> 50~334		HYRICK, R	7905250430	50-309 50-250	
WILBER, M WILBORN, L	7905220450 7905230693	50-320		YACKLE, T. R YAGER, D. M	7905150213 7905150603	50-275	NUREG/CR-0575
WILCOX,W H	7905110227	50-320		YALE, A. H. YAMAZAKI, M,	7905040375 7905290139	50-409	
WILKENS,P C	7905070118 7905150393	50-281 50-244		YBARRONDO, L. J. YBARRONDO, L. J.	7905110287 7905080055	50-320	
WILKINS, T D. WILLEMSEM, B	7905150116 7905240605	70-1201 50-254		YEAGER L L	7705070163		7905080055 7905090163
WILLIAM,W A WILLIAMS,R E	7905140183 7905240170			YELLIN, J.	7905090262 7905160138	50-020	
WILLIB, C A WILLIAMS, C E	7905150741	71 770		YIN,L T YORE,J R	7905150535 7905080154	50-358	
WILLIAMS, D, H	7905250211 7905070491	71-7023 50-368		YORE, J. R. YORE, T. R.	7905250330 7905020105	50-275 50-488	
MILLIAMSON, E A	7905230104 7905150638	50-255 50-324		YORE, J. R. YOUNG, R. E.	7905240762	50-514	
WILLIAMS, J L, WILLIAMS, F P	7905110014 7905190150	50-514 50-204		YOUNGBLOOD, J	7905150084 7905250470	71-63	
WILLIAMS, O H WILLIAMS, O H	7905020161 7905020439	70-1151		YOUNGBLOOD, J.	7905240410 7905240401		
WILLIAMS, Q H	7905240069	70-143 50-335		YOUNGBLOOD, J YOUNG, R	7905240438 7905220404	#0 -04#	
Williams, Q, H Williams, Q H	7905040124 7905070259	70-27 70-1201		YOUNG, F. H.	7905300082	50-245	
HILLIAMS, C C	7905080211 7905130434	50-331 50-331		YOUNGBLOOD, B J	7905290152 7905100338	50-275 50-320	
. P. M. . E	7905100277			YUHABIO P YUNIJ W.	7905240304 7905250327	50-244	
D	7905310232 7905230696	50-27		YUSPEH, A.R. ZAHN, L. L.	7905250340 7905150301	50-382 70-1308	
D, D	7905030104 7905030123			ZALOUDEK, F R ZANIS, L	7905250133		
D a, b	7905070105 7905240176			ZAVADOSKI, R. W.	7905230010 7905290142	50-320 50-338	
D R	7905150203 7905150548	50-270		ZEBRAK, I.L.	7905250365 7905250370	50-596 50-596	
, c,	7905250436	90-250		Zebrak, I. L. Zebrak, I. L.	7905150164 7905240160	50-596	
. R.	7905190116 7905020308	50-320 50-344		ZIBULBKY, H ZIELINBKI, C A	7905230288	50-596 70-33	
. F.	7905220078 7905150435	50-344 50-156		ZIEMANN, D. L.	7905250209 7905140520	50~59 <u>6</u> 50~266	
E .	7905070209 7905020128	50-445 50-320		ZIEMANN.D.L. ZIEMANN.D.L.	7905100321 7905090160	50-219 50-245	
8 D 8, D.	7905040449 7905100267	50~344		ZIEMANN, D. L. ZIEMANN, D. L.	7905030126 7905080381	50-244	
<b>8</b> D	7905080431	50-344 50-344		ZIEMANN, D. L. ZIEMANN, D. L.	7905080382	50-245 50-245	
B. D B D	7905110167 7905170238	50-344 50-344		ZIEMANN, D.L.	7905020449 7905020450	50-206 50-206	
B. D B. D	7905220289 7905220311	50-344 50-344		ZIEMANN, D. L. ZIEMANN, D. L.	7905020457 7905150648	50-204 50-155	
ÞĎ,	7905310350	50-344		ZIEMANN, D. L. ZIEMANN, D. L.	7905150707	50-155	
G.	7905110261 7905150493	50-320 50-314		ZIEMANN, D L	7905150715 7905060570	50-155 50-237	
, G, G,	7905150501 7905210142	50~316 50~315		ZIEMANN, D. L. ZIEMANN, D. L.	7905080337 7905080339	50-10 50-237	
, J ⊅ ⊕. ₩	7905110086 7905240369	50-312 50-322		ZIEMANN, D, L, ZIEMANN, D, L	7905080343 7905090016	50-245 50-213	
	7905140565 7905160045	50-362		ZIEMANN, D. L. ZIEMANN, D. L.	7905090020 7905090022	50-206	
اق	7905310409	50-320 50-466		ZIEMANN, D. L. ZIEMANN, D. L.	7905090024	50-29 50-219	
					7908090026	50-244	

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
ZIEMANN, D. L.	7905090029 7905240271 7905230402 7905020218 7905020343 7905090363 7905090205 7905090205 7905090203 7905100174 7905230599 7905100132 7905100132	50-255 50-155 50-295 50-295 50-206 50-244 50-29 50-244 50-244 50-244 50-409 50-255 50-409		ZIEMANN. D L ZITTEL H E ZUDANB. Z ZUFELT. E ZURAKANSKI. P R ZHETZIO. O B	7905250343 79052900729 7905290007 7905290012 7905290019 7905150489 7905290166 7905230176 7905250106 7905110256 7905100330	50-255 50-245 50-245 50-245 50-245 50-135 50-336 30-358 50-339 70-1257 50-312	7903240576

		i
	N	
	ı	;

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
CITIZEN GROUP/INDIVIDUAL/MEDIA			Abco Perforators, Inc	7905150474	71-280
Another Mother for Peace	7905240168	30-574	Abcor, Inc.	7905150214 7905100229	71-280
Appalachian Research & Defense Fund, Inc Citizens Association for Sound Energy	79051 50098 7905240929	50-445	Aerospace Corp American X-Ray & Inspection	7905030339 7905100345	50-437 71-305
Citizens for a Better Environment	7905230239 7905250450	20-320	Bertlett Consolidated, Inc	7905100361 7904210774	71-305
CBS News, CBS, Inc Citizens Concerned About Nuclear Power,	7905020037 7905090007	50-320 50-498	Bechtel Power Corp (subs of Bechtel Corp )	7905220026	
inc Council of Energy Resource Tribes	7905150718			7905080536 7905250509	50-329
Citizens Energy Forum Citizens for Safe Environment	7905030209 7905140519	50-338 50-320		7705220023 7705250531	
Citizens Action For Safe Energy Intervenors Cleaton	7905290273 7905290295	50-554 50-471	Capitol International Airways, Inc	7905150699	71-47
Center for Law in the Public Interest	7905290292	50-471	Creare, Inc	7705150692 7705030221	71-47
Coalition for Safe Power	7905030174 7905310104	50-275 50-275		7905240552 7905020154	
Apartered in Sta Lower	7905250279 7905230818	50-344 50-522	Daedalean Associates: Inc Dames & Moore	7705090163 7705030136	40-299
	7905250273 7905250357	50-344 50-344		7905030332 7905030132	50-407 40-297
	7905230550 7905230546	50-344 50-344	EDS Nuclear, Inc. EO & O, Inc	7905300208 7905090401	50-133
Citizens United for Responsible Energy	7905150312 7905250031	50-331 50-331		7905090408 7905150213	
The Denver Post Ecology Action of Oswego	7905140191 7905250353	50-596		7905100251 7905110287	50-265 50-320
•	7905270473 7905310203	50-465 50-465		7905230486	50-320
Environmental Coalition on Nuclear Power	7905100403 7905290181	50-320	Mark and a Mark Mark and American	7905090109 7905190159	50-320
Fultan Orange #66	7905290187	50-463	E Lewis Gook & Associates	7905290469 7905290463	71-297 71-297
Orest Lates Energy Alliance Kudzu Alliance	7905230595 7905290691	50-255	Oage-Babcock Associates, Inc. Oilbert Associates, Inc	7905080568 7905250482	50-397
Lovisiana Consumer's League, Inc	7905290098 7905290300	50-400 .50-382	Gibbs & Hill, Inc. (subs. of Drave Corp.)		50-584
Hiami Valley Power Project	7905290464 7905290468	50-358 50-358		7905230435 7905090272	50-584 50-584
	7905290520 7905150757	50-358 50-358	H R Inspection Service	7905230432 7905240904	50~584 71~55
	7905150227 7905150212	50-358 50-358	Independent Testing Laboratories	7905170299 7905170296	71-300 71-300
Hid-Hudson Nuclear Opponents, Inc	7905150221 7905230409	50-358 50-596	Industrial Testing Laboratory Services Corp.	7905150274	71-33
Milwaukee Sentinel Nautilus Allianca	7905140527 7905150255	50-266 50-574	International Structural Engineers: Inc.	7905150268 7905030042	71-33
News-Journal Co. WirDelware Natural Resources Defense Council	7905150524 7905250224	50-3	KHC, Inc	7905030051 7905030176	
	7905240178 7905240190	50-466 50-466	L K Cometock Engineering Co Logwell	7905150168 7905150493	
	7905240482	70-2623		7905150689	71-311
	7905080184 7905080202	50-437 50-437	London Nuclear Decontamination, Ltd	7905160124 7905300175	50-320 50-320
	7905250292 7905140079	50-437 70-2623	Metals Testing Co . Inc	7905150088 7905150078	71-137 71-137
	7905140094 7905290679	50-320 70-2623	Meteorological Evaluation Bervices, Inc. MHB Technical Associates	7905300467 7905070551	50-272
	7905080284 7905080294		Midstate Testing Laboratory, Inc.	7905020259 7905020255	71-77 71-77
	7905030034 7905080286		Nuclear Assurance Gorg. Nuclear Energy Service, Inc.	7905020252 7905040375	71-669B 50-409
	7905080296 7905250458		NUS Carp.	7905160427 7905010648	50-407
Nuclear Free State	7905220458 7905150279	50-437 50-556	Ozark Airlines	7905150094 7905150084	71-63 71-63
Prairie Alliance Public Citizen Litigation Group	7905040330 7905140072	50-461 50-320	Plateau Resources. Ltd Guality Testing, Inc.	7905100040 7905250019	40~8498 71~205
Public Interest Research Group	79050B0036 7905010032		Quality Control Bervices, Inc.	7905250016 7905240183	71-205 71-299
	79050B0040 79050B0047	20-55	Ransey Engineering Co.	7905240175 7905310074	71-299
Potomac Alliance	7905030207 7905100328	50-338 50-280	R & D Associates	7905310069 * 7905140254	50-320
	7905250233 7905100262	50-236 50-236	Rocky Mountain Energy Go.	7905100223 7905100233	40-8452 40-8452
Project for Open Government Palo Verde Nuclear Intervenors	7905300487 7905100332			7905240283 7905070111	40-8452
Safe Energy for New Haven	7905250350	50-592 50-596	Science Applications, Inc.	7905020056	
01 01-1	7905310267 7905070230	20-205 20-205	St Louis Testing Labs. Inc.	7905230527 7905240293	50-320 71-222
Sierra Club Seaccast Anti-Pollution League	7905300215 7905240251	50-510 50-443	Stone & Webster Engineering Corp	7905040615 7905140245	50-280 50-280
Sea Alliance of Ocean County Ban Luis Obispo Mothers for Peace	7905150293 7905250052	50-363 50-275		7905140239 7905210111	50-260 50-260
Bave the Valley - Save Marble Hill	7905240872 7905240964	50-546 50-546		7905290335 7905140382	50-260 50-260
Texas Public Interest Research Oroup	7905240232 7905300172	50-424 50-466		7905160335 7905070446	50~260 50~495
	7905300177 7905250242	50-466 50-466		7905190200 7905220232	50-495
	7905110339 7905110341	50-466 50-466	Teladyne Brown Engineering Co.	7905290309 7905290305	71-304 71-304
Trends Publishing, Inc. United Christian Action, Inc.	7905100050 7905290024	50-320	United Testing Services, Inc. Woodward-Clyde Consultants	7905250281 7905010418	71-290 40-8698
Union of Concerned Scientists Vermont Public Interest Research Group	7905300619 7905240469	50-271	WKM Wellhead Systems: Inc. WurT.Y.	7905290251 7905240103	71-202
•	7905300615	50-271	X-Ray, Inc.	7905240285	71-150
ENGINEER INO/CONSTRUCTION/CONSULTANTS/SERVI			EDUCATIONAL INSTITUTIONS		
American Airlines, Inc.	7905240348 7905150785	71-9033	American Univ.	7905090417	
			Bentley College	7905020080	



AUTHOR AFFILIATION	ACCESSION NUMBER	POCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
Bunter Hill Community College Catholic Univ	7905150229 7905010547 7905150479	50-77 50-77	berel & boss	7905080387 7905080331 7905250230	50-466 50-466 50-466
Colorado State Univ California Polytech State Univ California State Univ , Sacramento	7905010539 7905070213 7905150458 7905250504	50-77 50-394		7905310020 7905300066 7905310407 790529006B 7905150190	50-445 50-446 50-466 50-466 50-445
Eastern Hashington Univ Georgetown Univ Law School	7905140539 7905240178 7905240190	50-320 50-466 50-466		7705230651 7705230624 7705240310	50-445 50-445 50-466
Hervard Univ	7905140164 7905160138	50-320		7905240043 7905250239	50-466 50-466
Iowa State Univ	7905160489 7905160296	30-116 50-116 50-284		7905290002 7905250177	50-498 50-497
Idaho State Univ Illinois Instituta of Technology Johns Hopkins Univ	7905240604 7905300232 7905170279 7905170282	50-320	Cherry, M. H. /Cherry, Flynn & Kanter	7905240983 7905250438 7905240891 7905240899	50~549 50~329 50~329 50~329
Kansas State Univ	7905240125 7905230384	50-188 50-217	Conner, Moore & Corber	7905150193 7905290171	50-358 50-358
Lehigh Univ	7905140570 7905020151	50-214		7905290176 7905290180	50-358 50-358
Michigan State	7905040168 7905040165 7905040480	50-294 50-20		7905150151 7905300067	50-358 50-358
Massachusetts Institute of Technology	7905090331 7905300383	50-20 50-320		7905100225 7905030214	27-39 50-395
March Caraltan Chafe Univ	7905300385 7905310452	50~320 50~8		7905310010 7905170303	27-37 50-359
North Carolina State Univ Northwestern Univ	7905170243 7905070584	50-598 50-243		7905100237 7905240138	27-39 27-39
Oregon State Univ Pennsylvania State Univ	7905090428 7905230058	50~320		7905230512 7905100169	50-277 50-358
Purdue Univ	7905240326 7905300422	50~182		7905250117 7905250123	50-358 50-358
Reed Collège Rensselaer Polytechnic Inst	7905140341 7905220391	50-286 50-225		7905290077 7905140137	50-498 50-395
Stanford Univ New York, State Univ of, Buffelo	7905240387 7905190019	50-141 50-57		7905310093 7905150131	50-358 50-358
Tustages Inst Texas A & H Univ	7905240675 7905220097	50-404 50-128		7905300062 7905170301	50-358 50-358
Arizona, Univ of California, Univ of, Berkeley	7905240607 7905210181	50-113 50-224		7908240094 7908240941	50-272 50-322
California, Univ. of, Los Angeles	7905210178 7905250139	50-224	pattilo, T.M.	7905240915 7905150220	50-322 50-546
	7905250111 7905250118			7905170233 7905100228	50-261 50-445
California, Univ of Banta Barbara Idaho, Univ of	7905290047 7905240170			7905150921 7905090036	50-445 50-445
Maryland, Univ of Michigan, Univ of	7905290491 7905230406 7905090298	50~2 50~2		7905090042 7905090050	50-445
	7905230402 7905230402 7905090367	50-2 50-2		7905100193 7905230639	50-445 50-445
Missouri, Univ of	7905290673 7905220090	50-123		7903240317 7903240414	70-2623 71-6698
MISSOUTI ONLY OF	7905310401 7905220089	50-123 50-123		7905140159 7905140161	50-522 50-522
South Carolina, Univ. of Texas, Univ. of	7905300700 7905240326	50-375	Fried, Frank, Harris, Shriver & Kampelman	7905230124 7904170521 7905030166	50-275
Virginia, Univ of	7905250492 7905250505		Ligitation of	7703030174 77033310104	50-275 50-275
	7905240462 7905250169	50-62	Fontana, i. Garry, Dreyfus, McTernan, Brotsky,	7905290151 7905070227	50-382 50-133
Utah, Univ of Wisconsin, Univ of, Madison	7903010661 7903130435	50~72 50~156	Herndon & Pesonen, Inc Green, Feldman, Hall & Woodard	7905140547	50-556
Wyoming, Univ. of Worcester Polytechnic Inst.	7905070037 7905110298	40~4492 50 <b>~</b> 134	ALTERNATION CONTRACTOR AND	7905140550 7905240924	50-556 50-556
Washington State Univ	7905310236 7905310239	50-27 50-27	Goldberg, Fieldman & Letham, P.C Gillespie & Jones	7905100217 7905290151	50-348 50-382
	7905310242 7905310245	50-27 50-27	Hunton & Williams	7905030258 7905100152	50-338 50-316
	7905310232 7905240472	50-27 50-27		7905230448 7905250311	20-338 20-338
_				7905230668 7905240814	50-338 50-338
8 -	7054005411		Huber, Magill, Lawrence & Farrell	7905250365 7905250370	50-594 50-594
:anada	7905250166 7905110369 7905150588 7905150611	50-320	Hodder, M, H, Isham, Liηcoln & Beale	7905150164 7905290289 7905100147	50-594 50-389 50-255
en at	7905150573 7905150047			7905160504 7905090185	50~556 50~556
	7905300727 7905100323			7905250361 7905140138	50-445 50-445
	7905150741 7905140328			7905300022 7905250294	50-295 50-454
	7905140326 7905250115			7905100116 7905100123	50-445 50-445
				7905100271 7905250179	50-445 50-834
MIES				7905250238 7905250163	50-329 50-329
	7905230448 7905250488	50-445 50-445		7905290540 7905220062	50-327 50-534
	7905020383 7905020274	50-293 50-320		7905250174 7905250158	50-556 50-295
	7905070497 7905080530	50~3 50~320		7905240127 7905250238	50-445 50-329
	7905220352 7905290285	50~320 50~320		7905070040 7905070045	50-445 50-445
	7905150155 7905240068			7905250163 7905290540	50-329 50-329

AUTHOR	ACCESSION	DOCKET	AUTHOR	ACCESSION	DOCKET
AFFILIATION	NUMBER	NUMBER	AFFILIATION	NUMBER	NUMBER
	7905220062	50-556	Northcutt Ely	7905240332	50-445
	7905250174 7905070424	50-556	Nuclear Energy Liability Insurance Association	7905100163	50-10
	7905030260 7905240241	50-445 50-445	Danger Mer Gil	7905110107 7905110107	50-280 50-337
Johnson & Higgins Insurance	7905300334	50-338	Davies Marchan	7905110090	50-280 50-275
KafiniR J	7905160399 7905240098	50-295 50-596	Bruce Norton O'Neil, Beckus, Spielman	7905300007 7905010329	50-443
Kosit, L 8	7905240106 7905140157	50-346 50-358		7905020422 7905010323	50-443 50-443
	7905140369 7905290464	50-358 50-358		7905020416 7905080398	50-443 50-443
	7905140156 7905240104	50-358 50-358	Pfefferkorn & Cooley, P A <sup>.</sup> Roges & Grey	7905110347 7905100334	50-488 50-471
LeBourf, Lamb, Luiby & MacRae	7905010223 7905300025	50-358 50-341		7405240233 7405170245	50-471 50-443
	7905230497 7905240195	50-485 50-485		7905010447 7905210127	50-443 50-443
	7905150074 7905240801	50-485 50-548	Steel, Hector & Davis	7905150793 7905150799	50-250 50-250
	7905030346 7905030357	50-220 50-244		7905240836 7905150755	50-387 50-250
	7905040085 7905090358	50-485 50-285	Sheldon, Harmon & Roisman	7905240973 7905030262	50-250 50-338
	7905150316 7905310218	50-285 50-220	1.10 man	7905230760 7905230749	
	7905310243 7905040007	50-265 50-341	Spiegel & McDiarmid	7405030199 7405150234	50-250
Lowenstein-Mewman, Reis, Axelrad & Toll	7905080387 7905300035	50-466 50-250		7405150733 7405140115	50-250 50-445
	7905080331 7905250170	50-466 50-498		7903140089 7903100007	*** ***
	7905080311 7905080320	50-466		7905140126 7905240853	50-445 50-399
	7905030158	50-466 50-344		7905140151 7905030175	50-445 50-445
	7905150722 7905250230	50-344 50-466		7905070222	00-440
	7905250225 7905150793	50-466 50-250		7905100101 7905030175	50-445
	7905150799 7905300066	50-250 50-466		7905100004 7905150729	50-250
	7905310407 7905240207	50-466 50-387	Snell & Wilmer	7905100002 7905300007	50~592 50~275
	7905290068 7905150190	50-466 50-445	Shaw, Pittman, Potts, & Trowbridge	7905090247 7905300698	50-320 50-400
	7905230651 7905140057	50-445 50-466		79050B0232 7905100133	50-400 50-484
	7905100011 7905100019	50-369 50-369		7905240999 7905250339	50-484 50-502
	7905250328 7905230624	50-498 50-445		7905250340 7905140255	50-362 50-400
	7905240310 7905100391	50~466 50~466		7903140261 7905300104	50-400 50-344
	7903240853 7905250239	50-389 50-466		7905140221 7905220459	50~400 50~320
	7905290002 7905240970	50-498 50-376	Valore: C	7905150738 7905230532	50-272
	7905070239 7905100009	50~466 50~38	1270101	7905230525 7905150801	50-272 50-272
	7905070239 7905240248	50-466 50-498	Volpe, Boekey & Lyone	7908100196 7908150665	50-348 70-1821
	7905240959	50-376	Hest Texas Legal Services	7905090154 7905240115	50-445 50-445
Metford & Pattilo	7905240624 7905250476	50-498	Horsham, Foreythe & Sampels	7905150545 7905150144	50-445 50-356
Mutual Atomic Energy Liability Underwrit	7905160212 7905070582	50-3 50-3	Weliver: J.D.	7905150218	50-358
	7905110205	70-364	LOCAL GOVERNMENT AND AGENCIES		
Marsh & McLenon, M & M Nuclear Consultants: Inc. Div.	7905010527	50-327	Alken County, 80	-	
	7905080390 7905080394	50-259 50-259	Anderson County, BC Austin, TX		
	7905080430 7905080432	50-321 50-321	Citrus County, FL		
	7905080474 7905080476	50-302 50-302	Contra Costa Cc Cumberland Cour		
	7905100316 7905100304	50~250 50~348	Florence County Cardiner, NY	7905240148	50-596
	7905100307 7905100309	50-250 50-335	@arfield County, UT Grundy County, IL	7905150594 7905250493	40-8478
	7905100311 7905140361	50-335 50-346	Humboldt County, CA Kewaunee County, HI	7905250521 7905250496	
	7905160396 7905290089	50~348 50~272	Lower Alloways Creek: NJ	7905230653 7905250235	50-272 50-272
	7905300301 7905300311	50-250 50-250		7905250024 7905250028	50-272 50-272
McGrath, E. J.	7905300448 7905240991	50-348	Oconee County, SC Pennsyille, MJ	7905250514 7905170302	50-272
McCutchen, Douls, Brown & Emerson	7905240164 7905020169		Richland County, SC	7905170300 7905250499	50-272
•	7905030233 7905150368		Saluda Township, IN Santa Barbara County, GA	7905250445 7905150603	50-546 50-275
	7905100142 7905150803		8t. Lucia Gounty: FL	7905150598 7905250520	50-275
Means, Donald S.	7905140159 7905140161	50-522 50-522	Buffolk County, NY West Chicago, IL	7905240234 7903100078	50-322 40-2061
Manros & Lemann Morgan: Lewis & Sockius	7905220037 7905220064	50-382 50-356	·····	7905240114	40-2041
The property of the state of th	7905240879 7905220064	30-556 30-556	HEDICAL INSTITUTIONS/LABORATORIES		
McQinnis, Lochridge & Kilgore	7905240879 7905230448	50-556 50-445	Holyaka Hosp. Ho: Massachusetta	7905290161	30-1873
Matthews, Nowlin, Macfarlana & Barrett	7905070231	50-498	Lakeview Medical Center DA: [ lingis	7905150734	



AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
Michael Reese Hosp & Hedical Center Vet Admin Hosp NE/OM	7705150452 7705140204 7705140192 7705140198 7705140201	50-131 50-131 50-131 50-131	C-E Power Systems	7905240269 7905250013 7905220080 7905110294 7905300526 7905070564	70-1100 71-90
MANUFACTURERS/EQUIPMENT AND SUPPLIES			Course Inc	7905110288 7905300368	
Allied Chemical Corp , Nuclear Services	7905290665	40-3392	Cerec, Inc Chemtree Corp	7905150784 7904240395	
Div Aerojet Ordnance Cu	7905250270	40-8695	Chicago Bridge & Iron Co	7904240389 7905290514	71-104
Aerotest Operations Allied General Nuclear Services	7905290258 7905240357 7905150674 7905230782	40-8695 50-92 70-1821 50-332	Chem-Nuclear Bystems, Inc	7905290511 7905240187 7905300636 7905220454	71-104 71-6244 71-6244 27-47
Allied Chemical Corp	7905150683 7905210070 7905220109	70-1821 50-320 40-3392	Colt Industries, Inc.	7905241004 7905100099 7905100103	27-39 50-423 50-412
Anafcor Inc	7905240867 7905290148	71~277 71~1	Curtiss-Wright Corp.	7905100107 7905250366	50-395 71-161
Air Products & Chemicals, Inc	7903290146 7903290589 7903290168 7903290573 7903010473	71-1	Dow Chemical Co E I du Pont de Nemours & Co . Inc Ederer, Inc (subs of Formac Internatio nal. Inc	7905250354 7905150359 7905140247	71-141 50-264 50-320 50-329
Bear Cresk Mining Co (subs of Kenneco: Core )		40-8452	Edlow International Co	7905150198	
Borg-Warner Corp	7905150314			7905030100 7905290141	
BPB Instruments. Inc	7905140128 7905150027	71~286		7905230567 7905100264	40-8458
Buckeye International, Inc , Steel	7905150026 7905240715	71-286 71-110	Energy Fuels Nuclear, Inc	7905030092 7905300132	40-8691
Castings Biv	7905240616	71~110	Euratom Supply Agency (Belgium)	7905240544	40-8681
Babcock & Wilcox Co	7905210232 7905140384	50-99	Exxon Nuclear Co . Inc. (subs. of Exxon Corp.)	7905100290	50-305
	7905030205 7905140028	50~320	Exxon Minerals Co., USA	7905090393	
	7905290084 7905300391	71~322 50~320		7705150070 7705280538	40-8102 40-8064
	7905210138 7905190164		Exxon Corp.	7905280056 7905250538	40-8064 40-8064
	7905220410 7905220330		Fansteel, Inc	7905300658 7905020297	71-57
	7905240495 7905310386		Pederal American Pertners	7905240752 7905240444	40-4492 40-4492
	7905190072 7905190070	50~320 50~320	<b>*</b> • • • • • • • • • • • • • • • • • • •	7905020222 7905070032	40-4492 40-4492
	7905190077 7905190074	50~320	Fellows Medical Mfg Co . Inc . Fellows-Testager Div.	7905230390	
	7905230507	50~320 50~320		7905230274 7905230233	40-2407 40-2407
	7905210076 7905190079	50~320 50~320		7905230388 7905230380	40-2407
	7905100436 7905090383	50~312 50~404		7905230370 7905230357	40-2407 40-2407
	7905230019 7905240763	50-320 70-135		7905230352 7905230351	40-2407
	7905140411 7905140414	50- <i>99</i> 50-99		7905230345	40-2407 40-2407
	7905140408 7905140383	50-99 50-99		7905230338 7905230332	40-2407 40-2407
	7905040114 7905070245	70-27 70-1201		7905230328 7905230320	40-2407 40-2407
	7905100351 7905150137	70-344		7905230315 7905230312	40-2407 40-2407
	7905290081 7905240594	71-322 70-135		7905230304 7905230299	40-2407 40-2407
	7905250048 7905290051	70-135 70-27		7905230284 7905230261	40-2407 40-2407
	7905190068 7905030356	50-320		7905230247 7905230758	40-2407 40-2407
	7905290427 7905310343	50-13		7905230226 7905230586	
	7905090306 7905110309	<b>50</b>	General Atomic Co. (subs. of Quif Dil	7905230214 7905150208	
	7905210136	50-99	Corp. )	7905300326	
	7905140314 7905030194			7904300240 7905300321	
	7905070555 7905310406			7905020367	71-6346
	7905310370 7905190223	50-313 50-320		790515000B 7905300561	
	7905100153 7905020348			7905080442 7905030104	
	7905090 <u>372</u> 7905090242			7905030123 7905070105	
	7905190161 7905160370			7905150382 7905210324	70-754 50-320
	7905220408 7905160373			7905230696 7905290087	70-1113
	7905220324 7905240494			7705150791 7705150627	70-1113 71-5926
Bahenek & Milar	7905310377 7905160388	70-135		7905210328 7905080440	50-320
Babcock & Wilcox Co , Nuclear Material Div.	7905220077	70-195		7903190154 7903210173	50-73 50-219
Babcock & Wilcox Co., Nuclear Material	7905090040 7905240089 7905290410	70-135 70-364 70-364		7905040028 7905140428 7905140426	VV"617
Combustion Engineering, Inc.	7905240276	70-1100		7905110116 7905080440	
	7905090055 7905220083	50-317	·	7905220348 7905090031	

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
General Dynamics Corp , Guincy Shipbuilding Div	7905290516	71-154	Ogie Petroleum, Inc.	7905100172	40-8693
Ganeral Electric Co., Nuclear Energy Products Div	1900E5097		Offshore Power Systems (subs of Nestinghouse Electric Corp )	7908250313	50-437
	790 <b>524</b> 0176 790 <b>5</b> 010561			7905250290 7905310458	50-437 50-437
	7905150203 7905170269	50-240		7905040133 7905220022 7905190112	50-437 50-437 50-437
	790530053B 7905300263	50-133	Pathfinder Hines Corp.	7905310455 7905100025	50-437 40-2259
	7705070091 7705240811	70-1113 70-1113	Petrotomics, Inc.	7905100284 7905240348	40-6659 40-6659
	7905150301 7905290091	70-1308	Pulimen, Inc. Redium Chemical Co , Inc	7905150547 7905250540	71-217
	7903240588 7905100426	70-1007 70-1308	Rediation Services, Inc Reuter-Stokes, Inc	7905250376 7905250245	
	7903140305 7903140309	70-1308 70-1113	Rockwell International Corp	7905080513 7905080517	50-375 50-375
	7903220025 7903240910	70-1113 71-9009		7905090422 7905060510	50-375
	7905230730 7905240600	70-754 70-1113	RSA Corp.	7705220397 7705300114	50-528
	7905230730 7905290062	70-784 70-754	Sigma Chemical Co (subs. of Sigma Aldrich Corp )	7905150161	
	7905250218 7905290259	70-754		7905030109 7905140093	
	7905140392 7903210152	50-217	Snupps-Standardized Nuclear Unit Power Plant System	7905070650	50~482
	7905160428 7905300532	50-70		7905310411	50-462
	7905090275 7905010560	50-163	Taladuna. Tr-	7905070649	50~482
	7905160441 7905310339		Teledyne: Inc Texas Instruments, Inc.	7905240608 7904300384	71-5024
	7905300317 7905300558		Trane Co	7904300328 7905240078	70-33
	7905100185		Transnuclear, Inc	7905230529 7905150193	50-546
	7903100194 7903140274			7903290121 7905106358	70~2084
	7905300532 7905310321			7905020290 7905240121	70-2198
	7905140297 7905020328			7905100417 7905290118	71-0100
	7905030340 7905240353		Characters Come Yuka Yanga Bila	7905150788 7905230066	71~9120 71~9120
Golden Gate Switchboard Co. Gulf Gil Gorp., Qulf Mineral Resources	7905100023 7905070094		Chemetron Corp., Tube Turns Div Texas Pipe Bending Co (subs of Bendix	7905150417 7905100369	#0-382 71-307
Go. Hess Gil Virgin Islands Corp.	7905150265	71-151	Carp.; Union Carbids Carp	7905100368 7905070058	71-307 71-6058
Hoke, Inc.	7905170293 7905170283		United database delp	7905010501 7905290033	50-299 40-299
	7905170285 7905170280			7905100113 7905150281	40-299 71-6058
	7905170289 7905150105			7905010531 7905010495	50-54 50-54
Underen Broston a	7903240323 7905150104		United Nuclear Corp.	7905030231 7905220047	70-820
Hudson Products Corp.	7905240210 7905240206	71-317 71-317		7905250236 7905140	70-820
Isotope Products Laboratories	7905240116 7905250306			790503C 790524/	
International Telephone & Telegraph Corp	7905080134 7905080128	71-36 71-36		790515 790577	
Rawecki Berylco Industries, Inc. UB Nuclear, Inc.	7905040098 7905090425	40-8027		7905 7905	
Liberty Equipment & Supply Co Metals & Controls Corp	7905250373 7904300319	50-416	Unipax International	7905 7905	
	7904300238 7904300173		US Steel Corp. Hestinghouse Electric Corp.	7908 7905	
Helica U. H. A. , Inc	7904300341 7905250333		Maserindingse wisces to dails.	7902 7902	
Hetalforms, Inc.	7905150632 7905150626	71-312 71-312		790: 790:	
Hitsuiline Travel Service of America: Inc.	7905290139			7901 7901	
Honsanto Co.	7905300339 7905300332			790' 790	
Mitsubishi International Corp (subs of	7905220103 7905240010	71-9506		790 791	
Hitsubishi Çarp )	7905250037 7905140096 7905240005 7905250041			79 71	
M. J	7905250045				
National Annealing Box Co. Nuclear Fuel Bervices: Inc. (subs. of	7905100104 7905240419	71-127 50-201			
O+tty Dil Co. )	7908020425	70-149			
	7905240344 7905020214	70-143 50-201			
	7905150644 7905250535	70-143 70-143			
Mr. A. S. C. A	7905150024 7905100423	70~143 70~143			
Nissho-Iwai American Corp. M. Industrias: Inc.	7905290190 7905110021	70~1318			
M. Industries:NL Nuclear Div Nuclear Packaging: Inc.	7905250211 7905150786	71~9023 71~9132			
obsolete code	7905240497 7905240643	71~9116 71~216			
	7905240632	71-216			

AUTHOR AFFILIATION	ACCEBBION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
	7905110096 7905210146		Minnesota, State of	7905080411 7905080482	50-263 50-263
	7905190063 7905090366 7905150592	40.4440	Missouri, State of North Dakota, State of	7905080411 7905080482 7905160410 7905100398	50-263 50-263 50-483 71-288
Western Nuclear, Inc (subs of Phelps Dodge Corp )	7905170292 7905240457 7905240442	40-1162 40-1162 40-1162	New Hampshire. State of	7905100373 7905100393 7905250046 7905250044	71-268 50-309 50-309
Worthington Pump, Inc (subs of Studebaker-Worthington, Inc )	7905300147 7905150766	40-1162 71-309	New Jersey, State of New Mexico, State of	7905240954 7905240789 7905240542	50-272 50-272
Hydming Mineral Corp Yuba Heat Transfer Corp	7903150763 7905240267 7905250454	71-309 40-8502		7905070201 7905240377 7905150199	
PROFESSIONAL/INDUSTRIAL INSTITUTIONS, SOC			Nevada. State of New York. State of	7905090176 7905250463 7905030247	50-549
~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~				7905150271 7905250680	50~594 50~549
Atomic Industrial Forum	7905140086 7905250469	50-320		7905230613	50-201
Air Transport Association	7905140223 7905040313	50-320		7903150266 7905030239 7905190099	50-596 50-549 50-320
American Hining Congress American Nuclear Energy Council American Newspaper Publishers Association American Nuclear Bociety	7905300531	50-320		7905070467 7905010497 7905030350	50-596 50-244 50-349
American Gociaty of Mechanical Engineers Edison Electric Institute		50-320		7905290435 7905150732 7905250209	50-201 50-596
Health Physics Society	7905230577	20 220		7905290106	50-516
Industry Advisory Group	7905220034 7905190176	50-320	Ohio, State of Oklehome, State of	7905240433 7905240275	50~556
	7905230496 7905230468	50-320 50-320		7905150043 7905230759	50-556 50-556
	7905230026	50-320	Oregon, State of	7905250180	50-522
International Brotherhood of Electrical Workers	7905230065 7905230069 7905110026	50-320 50-320	Pennsylvania, State of	7905250519 7905190251 7905140092	50-320 50-320
Maine Merchants Association, Inc. Non-Destructive Testing Management Association	7905010549 7905150238	50-309	South Carolina, State of	7905250511 7905250453 7905250510	
Fortland Cement Association Special Instrument Group	7905080516 7905220453	50-482 50-320	Texas, State of Utah, State of	7905310111 7905140060 7905240200	50-466 50-466 40-3453
STATE GOVERNMENTS/AGENCIES				7905250042 7905150303 7905300508	40-8698 40-8698 40-8722
Arkansas, State of	7905250512			7905240425	40-8681
Arizona, State of	7905240410			7905250201 7905240301	40~9681 40~8681
della de maria	7905240401 7905240438 7905250470		Virginia, State of	7905240424 7905030330 7905250515	50-339
Galifornia, State of	7905030090 7905300270 7905300277	50-206 50-206	West Virginia, State of	7905300756 7905040265 7905290038	50-240
	7905010553 7905080028	50-361	Hyoming, State of	7905020280	40~299
	7905300651 7905240598	50-312 50-592	U B FEDERAL OUVERNMENT AND AGENCIES		
	7903300265 7905300651	50-206	Coast Quard, Transportation, Dept. of	7905250168	40-9481
	7905100364	50-312 50-320	Congress (Joint & Rotating Committees,	7905150055	50-320
Colorado, State of	7905240644 7905240713	50-312 50-275	Defense, Dept. of. Defense Nuclear Agency Agriculture, Dept. of	7905310356 7905090441	50~170 40-8698
Connecticut, State of	7905150342 7905250504			7905010577	40-B698
	7905250494 7905300647	50-245	1	7905090090 7905090345	50~522 50~592
Delaware, State of Florida, State of	7905250451	00 440	Commerce, Dept. of	7905310349 7905210062	50-592 50-320
Georgia, State of Iowa, State of	7905230497 7905230522		Army Dept. of. Corps of Engineers Army Dept of. Matls, & Mechanics Research	7505000000	50-546
•	790525044B 7905240417		Center Energy, Dept, of		50-47
Illinois, State of	7905230768 7905250372	50-295 27-39	chargy, pape, Qr	7905210032 7905150639	50-320 50-482
	7905030171	27-39		7905020264 7905300490	71-9785
	7905150521 7905150256	27-39 50-295		7905020270	71-5908 71-6387
	7905310392 7905310273	27-39		7905290071 7905300429	71~9010 50~344
	7905100190			7905140521 7905230778	
	7905150248 7905140153	50-295 50-115	Energy, Dept. of, Clinch River Breeder	7905060100	
	7905100089 7905110181	40-2061 27-39	Reactor Plant	7905020293	50-537
	7905100032 7905070364		Interior, Dept. of	7905300163 7905300154	40~8681 40~8698
Indiane, State of Kansas, State of	7905140158 7905250468	27-39	Interior, Dept, of, Fish & Wildlife Service	7903240258 7903310453	40-8681 50-466
Kentucky, State of Massachusetts, State of	7905240725 7905070026	50-546 50-443		7905040473	50-471
	7905240943	50-471	Interior, Dept. of: Geological Survey	79051504B1	50-274
	7905100326 7905090411	50-471 50-471	Justice, Dept. of	7905090364 7905240985	50-18 50-348
	7905240794 7905230396	50-471		7905300058 7905100288	50-445
Maine, State of Michigan, State of	7905300572	30-309	State, Dept. of	7905140070	50~445 50~499
- ·· ·· · ••	7905230504 7905140251	50-315 50-341	• • =•	7905240875 7905240883	
	7905310360 7905080139	50~329		7905240889 7905240897	
				7905250054	

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
State, Dept of, Bureau of Oceans &				7905160407	50-348
Internati Environ & Scientific Affai	7905150186			7905160414 7905300500	50-348 50-348
	7905150123 7905150183			7905300504	50~348
	7905150191			7905020242 7905070631	50-348 50-348
	7905230301 7905150095			7905230414	50-348
				7905150391 7905150357	50-348 50-348
	7905160234 7905150807			7905090075	50-348
	7905160228			7905170266 7905230414	50-348 50-348
	7905230559 7905230575		APL - Arkanses Power & Light Co	7905310376	50-348 50-313
	7905230597		Mr WARRINGS LONGL OF FIGUE CD	7905040019 7905070494	50-313
	7905230669 7905240431			7905170232 7905170259	50-368
	7905250442			7905170267	50-348
	7905230708 7905300677			7905170227 7905170234	50-348 50-313
Transportation, Dapt of	7905310422 7905140043	50-592		7905170239	50-348
Environmental Protection Agency	7905230175	50-320 50-320		7905150601 7905310387	50-368 50-368
	7905030080 7905100094	50-327 40-2061		7705100394	50-313
	7905040207	40-5001		7905030128 7905110010	50-313 50-368
	7905140222 7904180179	50-445		7905290494	50-313
	7905090431			7905110007 7905070490	50-348 50-313
Federal Energy Regulatory Commission Health, Education & Welfare, Dept. of	7905100407 7905090227	40-4602 50-320		7905140172	50-368
tisetim repreciol a methans pake. Ot	7905230175	50-320		7905140176 7905140182	50-348 50-348
	7905090229 7904170110	50-320 50-320		7905140185	50~36B
House of Rep	7905040299	50-320		7905150440 7905140250	50-313 50-313
	7905250335 7905020149	50-275 50-488		7905140263	50-313
	7705150061	40-8698		7905150572 7905150580	50-368 50-368
	7905300657 7905100075	50-320		7905150587	50-348 50-348
	7905300501	20-350		7905220398 7905220400	84E-08
	7905100013 7905100166	50-320 50-320		7705220405 7705270103	50-3å8 50-313
	7905230452	50-275		7905290109	50-313
	7905150675 7905220100	50~1 <i>0</i> 50-250		7905300509 7905300517	50-368 50-368
	7905290486	50-250		7905020343	8AE-05
	7905240964 7905020011	50-250 50-320		7905100294 7905070483	50-313 516-08
	7905020123	50-320		7705110082	50-313
	7905240273 7905100082	50-275 50-320		7905140279 7903190053	50-313 50-313
	7705240626	50-219		7905230020	50-313
	7905150455 7905290107	50-454		7905190167 7905100318	50-313 50-313
House of Rep . Government Operations	7905250337			7905020231	50-913
	7905250329 7905250336			7905150215 7905040008	50-313 50-313
House of Rep : Committee on Rules House of Rep.: Ways and Means	7905290478 7905300507			7905110066	50-313
Housing & Urban Development, Dept. of	7905110227	50-320		7905220249 7905210264	50-313 50-313
National Aeronautics & Space Admin, Commercs,Dept of, National Bureau of	7905250312 7905190064			7905210266	50-313
Standards	7100110001			7905240365 7905240712	50-313 50-313
Securities & Exchange Commission	7905240354 7905250245	50~184 50~568		7903290135 7903300488	50-313 50-313
mandiana a munitalika notimetastii	7905020466	50-330		7905300001	50-313
Senate	7905070166 7905250542	50-382 40-8498		7905150389 7905070491	50-313 50-368
	7905250131	50-269		7905170265	50-368
	7905300686 7905300244	50-309 50-320		7705300002 7705100268	60-369
	7905100040	50-320	AZPS - Arizona Public Service Co.	7905300292	50-592
	7905240512 7905250131	50-450 50-269		7905290056 7905290072	50-528 50-528
	7705020212	50-483		7905220386	50-528
	7905240718 7905300762	50-250 50-250		7905310378 7905300287	50-592 50-592
Veterans Administration	7905090197	00 - M 00		7905110150	
			BECO - Boston Edison Co.	7905290671 7905290660	50-471 50-471
TILITIES/HOLDING COMPANIES/INVESTOR ASS				7908290641	50-471
AEP - American Electric Power Co.: Inc.	7905300386	50-315		7903290643 7905290633	50-471 50-471
ALPR - Alabama Power Go.	7905150395 7905230362	50-349 50-349		440M4404	MA_471
	7905230362	50-348 50-348			
	7 <b>9</b> 05230777	50~348			
	7905140368 7905140357	50-348 50-348			
	7905100279	50~346			
	79051 50568 7905240443	50-348 50-348			
	7905300710	50-348			
	7908020247 7908020249	50-349 50-349			
	7705300554	50-348			
	7905250036 7905110242	50~348 50~348			
	7705110247	50-348 50-348			
	7905140306	50-348			
	7905140311 7905140403	50-348 50-348			
		2414			

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
				7905300480	50-237
	7905290100 7905300482	50-293 50-293		7905250215 7905150076	50-10 71-8
	7905300472	50-293		7905010523 7905020312	50-373 50-373
	7905300535 7905300543	50-293 50-293		7905010526 7905030366	50-254 50-10
	7905090501 7905290208	50-293 50-293		7905040502 7905090389	50-295
	7905290634 7905140435	50-471 50-471		7905070567	50-254 50-454
	7905150397	50-293		7905070396 7905110155	50-275 50-373
	7905220021 7905300011	50-471 50-471		7905140274 7905150351	50~249 50~454
	7905170230 7905010542	50-273 50-273		7905170237	50-275 50-577
	7905170235 7905310352	50-273 50-273		7905220102 7905290079	50-275
BOE - Baltimore Que & Electric Co.	7705300013 7705100348	50-471 50-317		7905310393 7905210262	50-599 50-254
DOE - BEIGIMOPE ONS & CIRCUPIC CU.	7905110122	50-317		7905090360 7905220337	50-577 50-456
	7905230359 7905230356	50-317 50-317		7905170246 7905240664	50-599 50-599
	790511011 <del>8</del> 7905010524	50-317 50-317		7905170264	50-599
	7905010528 7905290712	50-317 50-317		7904270366 7905190016	50-10 50-237
	7905300742	50-317		7905190097 7905250391	50-237 50-10
	7905080494 7905080555	50-318 50-317		7905250533 7905250391	50-254 50-10
	7905080541 7905090342	50-317 50-318		7905040603	50-237
	7905190080 7905190083	50-317 50-317		7905090370 7905140273	50-10 50-10
	7905220282	50-317		7905250391 7905310364	50-10 50-237
	7905290430 7905290426	50-317 50-317		7905070393 7905080396	50-373 50-373
	7905160325 7905090049	50-317 50-317		7905140312 7905300020	50-373
CEIL - Commonwealth Edison Co	7905090323 7905020320	50-295 50-373		7905310361	50-373 50-373
	7905070574	50-454		7905040482 7905150498	50-10
	7905160359 7905170255	50-10 50-295		7905250069 79051 <b>5</b> 0494	
	7905170260 7905220107	50-254 50-599	CENY - Consolidated Edison Co. of New York	7905170249	50-247
	7903250536 7903090322	50-254 50-295	IDFK	7905230367	30-3
	7905250460 7905160354	50-10		7905300358 7905220376	50-247 50-3
	7905170250	50-254		7905230365 7905220263	50-3 50-3
	7905020421 7905250280	50-10 50-10		7905220286	50~3
	7903250324 7905240633	50-10 50-10		7905220288 7905220291	50-3 50-3
	7905020272 7905020282	50-295 50-295		7903220294 7903220299	50-3 50-3
	7903080540	50-237		7905220302 7905220305	50-3 50-3
	7905100296 7905100297	50-254 50-254		7905220312 7905220313	50-3 50-3
	7905150148 7905040432	50-10 50-237	,	7905250246	50-3
	7903040561 7903080535	50-237 50-237		7905040004 7905040006	50-247 50-247
	7905100300 7905100302	50-304 50-304		7905040279 7905190015	50-247 50-3
	7905100306	50-304		7905190018 7905190021	50-3 50-3
1	7905100310 7905240678	50-304 50-245		7905190025 7905290185	50-3
	7905240687 7905300242	50-265 50-10		7905090287	50-3 50-247
	7905080548 7905080556	50-249 50-249		7905300354 7905070549	50-247 50-3
	7905240702 7905240707	50-265		7905170244 7905310396	50-247 50-247
	7905220257	50-265 50-237	GEPC - Central Electric Power Cooperativ	7905290124 7905030268	50-395
	7905220264 7905140318	50-237 50-249	e: Inc. GOEC - Cincinnati Cas & Electric Co		
	7905140324 7905160384	50-249 50-237	AAMA . AVIICTIIIIMET AND # ETSCELTE CO	7905100210 7905100222	50-358 50-358
	7905160385 7905240691	50-237 50-265		7905140083 7905290456	50-358 50-358
	7905240699	50~265		7905140111 7905020451	50-358 50-358
	7905240543 7905240546	50-295 50-295		7905290449	50-358
	7905240550 7905240555	50-304 50-304		7905080439 7905160434	50-358 50-358
	7905240538 7905240541	50-275 50-275		7905110146 7905300264	50-358 50-358
	7905170226	50-237	CPC - Consumers Power Co.	7905230104 7905250530	50-255 50-329
	7903240597 7903240603	50-254 50-254		7905090086	50~327
	7905170229 7905300435	50-237 50-373		7905030311 7905070501	50-32 <del>9</del> 50-329
	7905300567 7905300443	50-237 50-237		7905250528 7905150416	50-329 50-255
	7905300447 7905300465	50-237		7905300256 7905250478	80-329
	7905300499	50∽237 50-237		7905140219	50-329
	7905300573 7905300579	50-237 50-247		7908180414 7908300478	50-255 50-329
	7905300588 7905300697	50-249 50-249		7905090172 7905080539	50-255 50-255
	7905300705 7905300475	50-249		7905240309 7905310098	50-255 50-155
	E\#DUEGUE\	50-237		7905040386	50-255

3

	CO	nruna	IE SOURCE INDEX		
AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
	7905040407 7905090002	50-255 50-327		7905250413	50-325
	7905030327	50-329		7905250419 7905290219	50-325 50-261
	7905080480 7905080484	50-155 50-155		7705290230 7705290388	50-261 50-261
	7905080488 7905250364	50-155 50-255		7905300384	50-324
	7905080532 7905080537	30-329		7905300390 7905300425	50-329 50-325
	7905290276	50-255 50-155		7905300432 7905300371	50-325 50-324
	7905100249 7905100252	50~255 50~255		7905300375 7905300377	50-324 50-324
	7905100255 7905100259	50-255 50-255		7905300380	50~324
	7905150457	50-155		7905300387 7905300397	50-324 50-324
	7905150459 7905150615	50-155 50-255		7905300512 7905300518	50-325 50-325
	7905150625 7905220329	50-255 50-255		7905010517	30-261
	7905220335 7905220340	50-255		7905070475 7905090349	50-400 50-400
	7905220343	50-255 50-255		7905290380 7905040599	50-400 50-324
	7905300252 7905150484	50-329 50-155		7905040607 7905140337	50-324 50-261
	7905210125 7905250303	50-255 50-155		7905300449	
	7705250526	50-329		7905030353 7905040624	50-324 50-324
	7905150309 7905210150	50-255 50-255		7905080402 7905080417	50~324 50~324
	7905310449 7905010488	30-135		7905080436 7905010379	50-324 50-324
	7905040099 7905110085	50-155		7905210145	50-324
	7905140211	50-255 50-155		7905230544 7905290370	50~324 50~324
	7905220020 7905210143	50~255 50~155		7905190013 7905030331	50~261 50~261
	7905230052 7905230095	50-255 50-255		7905040084	50-261
	7905250095	50-155		7905010552 7905040032	50~261 50~261
	790503030B 790503035B	50-329 50-329		7905080437 7905150328	50~261 50~261
	7905030362 7905090307	50-329 50-329		7905250121 7905220346	50-261 50-261
	7905110207	50-329		7905290374	50~261
an	7905230761 7905090416		CEMS - Central & Southwest Bervices, Inc		50-241 50-554
CPL - Carolina Power & Light Co.	7905070480 7905150638	50-400 50-324	CYAP - Connecticut Yankou Atomic Power Co.	7905300327	50-213
	7905150426 7905190012	50-261 50-261		7905070544 7905210214	50-213 50-213
	7905250124 7905020333	50-261 50-261		7903210211	50-213
	7905150631	50-324		7903040070 7903240392	50-213 50-213
	7905150418 7905090302	50-261 50-324		7905040061 7905310473	50-213 50-213
	7905140419 7905230223	50-400 50-324		7905300323 7905310446	50-213 50-213
	7905080330	50-400		7905240503	50-213 50-213
	7905100241 7905230613	50-324 50-261	DAYP - Dairyland Power Cooperative	7905070342 7905090354	50-409
	7905230604 7905010557	50-261 50-261		7905160427 7905140234	50-409 50-409
	7905240192 7905250015	50-324 50-400		7905140231 7905020238	50-409 50-409
	7905030345	50-324		7905290336 7908010504	50-409 50-409
	7905030347 7905300283	50-324 50-324		7905010510	50-407
	7905040531 7905040535	50-261 50-261		7905010520 7905250407	50-407 50-407
	7905300296 7905060504	50-261 50-325		7905020243 7905240516	50-409 50-409
	7905080518	50~325		7905240698 7905150517	50-409 50-409
	7905090282 7905090289	50-324 50-324		7905150530 7905250404	50-409 50-409
	7905090311 7905090321	50-324 50-325		7905290417	50-409
	7905090324 7905090340	50-325 50-325		7905090043 7905310357	50-409 50-409
	7905090344	50~325		7905040373 7905090352	50-409 50-409
	7905150427 7905150432	50-325 50-325		7905160425	50~409 50~409
	7905150506 7905150518	50-325 50-325		7905220401 7905290086	50-409
	7905150450 7905150451	50-241 50-241		7905300012 7905300314	50~407 50~409
	7905150461	50-261	DE - Detroit Edison Co.	7905090355 7905150285	50-341 50-452
	7905150463 7905190010	50-261 50-261		7905090351 7905160443	50-341
	7905190027 7905190030	50-261 50-261		7905310451	50-341 50-16
	7905190086	50-261		7905230473 7905070442	50-452
	7905190088 7905220106	50-261 50-261	DL - Duqueane Light Co.	7905030344 7905010493	50-334 50-334
	7905220110 7905230615	50-261 50-324		7905010551	50-412
	7905220342 7905220345	50-325 50-325		7905010537 7905220099	50-334 50-334
	7905220361	50-325 50-325		7905220104 7905140302	\$0-334 \$0-334
	7905220367 7905220369	50-325		7905150269 7905140300	50-412 50-334
	7905220373 7905220406	50-325 50-324		7905310384	50-334
	7905220411 7905240630	50-324 50-325		7905250461	10-334 50-334
	7905240637	50-325		7903010541	50-412

7903010541 50-412

## OFFICE OF PRINT CO.   PRINT CO.   PRINT CO.   PRINT CO.	AUTHOR AFFILIATION	ACCESSION		AUTHOR	ACCEBBION	DOCKET
Proceedings		NUMBER	NUMBER	AFFILIATION	NUMBER	NUMBER
Proceedings		7903050440	50-324			
700000010		7905080468	50-334		7905160361	
PRO		7905080551	50-334		7905040352	
## 1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1		7905150536	50~334		7905080566	30-249
### PASS	7905240209	71-5450		7905110264	50-269	
### 100-0026   100-0026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-10026   1700-		7905010532	50-334		7905150317	50~264
Proceedings		7905090066	50-334		7905140365	50-269
## CPC - Data Pawer Co		7905080370	50-334			50-267
## 199320070   50-301   700320070   50-301   700320070   50-301   700320070   50-301   700320070   50-301   700320070   50-301   700320070   50-301   700320070   50-301   700320070   50-301   700320070   50-301   700320070   50-301   700320070   50-301   700320070   50-301   700320070   50-301   700320070   50-301   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070   700320070		7905110070			7905230543	50-267
prc - Date Power Ca		7905220093	50-334			50-297
Proposed	DPC - Duke Power Co	7905150267	50-412			20~374
1705100101		7905190106	50-413			50-369
770516000 770-022 770516040 770-023 770516040 770-023 770516040 770-023 770516040 770-023 770516040 770-023 770516040 770-023 770516040 770-023 770516040 770-023 770516040 770-023 770516040 770-023 770516040 770-023 770516040 770-023 770516040 770-023 770516040 770-023 770516040 770-023 770516040 770-023 770516040 770-023 770516040 770-023 770516040 770-023 770516040 770-023 770516040 770-023 770516040 770-023 770516040 770-023 770516040 770-023 770516040 770-023 770516040 770-023 770516040 770-023 770516040 770-023 770516040 770-023 770516040 770-023 770516040 770-023 770516040 770-023 770516040 770-023 770516040 770-023 770516040 770-023 770516040 770-023 770516040 770-023 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 770516040 77		7905190103	50-413		7905100299	
7403110327 7-7-252-25		7905110040	70~2623		7905100303 7905230541	
Tell		7905110037	70-2623	POSS - El Bana Plantala A	7905110129	
7001500164 30-042 7100500114 30-042 7100500114 30-042 7100500114 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 7100500144 30-042 710050014 30-042 710050014 30-042 710050014 30-042 710050014 30-042 710050014 30-042 710050014 30-042 710050014 30-042 710050014 30-042 710050014 30-042 710050014 30-042 710050014 30-042 710050014 30-042 710050014 30-042 710050014 30-042 710050014 30-042 710050014 30-042 710050014 30-042 710050014 30-042 710050014 30-042 710050014 30-042 710050014 30-042 710050014 30-042 710050014 30-042		7905250061	50-491	FPC - Florida Power Corp.	7905210154	50-592
7-00520470 70-2626 7700520181 80-302 7700520181 80-302 7700520181 80-302 7700520182 80-302 7700520182 80-302 7700520182 80-302 7700520144 7700520182 80-302 7700520144 7700511024 80-302 7700520144 7700511024 80-302 7700520144 7700511024 80-302 7700520144 7700511024 80-302 7700520144 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770052014 770		7905150262	50~369		7905300144	
7705104069		7905240470	70-2623		7905210153	
7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-09-24-07-24 7-		7905220365	50-269		7905010408	
790510264 50-269 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 77905100000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 77905100000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 7790510000 80-300 77905100000		7905240921			7905100238	
7-00510017		7905110264			7905040050	
7-00520770		7905110017	50~269		7905070602	
7-7051-01-01-01-01-01-01-01-01-01-01-01-01-01		7905230770	50~369		7905240802	
790530279		7905140506	50~297		7905040043	
7003140482 50-387 7705304052 50-302 7705304052 50-302 7705304052 50-302 7705304052 50-302 7705304052 50-302 7705304052 50-302 7705306045 50-329 7705306045 50-329 7705306045 50-329 7705306045 50-302 7705306045 50-329 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 50-302 7705306045 5		7905230279	50-269		7905040088	
7005000408 50-369 77005070977 50-302 7700507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 770507097 77050709		7905140483	50~267		7905040432 7905040430	
7905100044 50-269 7705370611 50-302 7705370614 50-302 7705370617 30-269 7705370617 50-302 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370617 50-402 7705370618 50-402 7705370618 50-402 7705370618 50-402 7705370618 50-402 7705370618 50-402 7705370618 50-402 7705370618 50-402 7705370618 50-402 7705370618 50-402 7705370618 50-402 7705370618 50-402 7705370618 50-402 7705370618 50-402 7705370618 50-402 7705370618 50-402 7705370618 50-402 7705370618 50-402 7705370618 50-402 7705370618 50-402 7705370618 50-402 7705370618 50-402 7705370618 50-402 7705370618 50-402 7705370618 50-402 7705370618 50-402 7705370618 50-402 7705370618 50-402 7705370618 50-402 7705370618 50-402 7705370618 50-402 7705370618 50-402 7705370618 5		7905020408	50~369			50~302 50~302
74051902344 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070 7005807070		7905100044	30~269			50-302
7905140167 30-513		7905150254	50~369		7903070652	50-302
7905240426 7905240426 7905240426 7905260305 7905260427 7905260427 7905260327 7905260427 7905260427 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428 7905260428		7905140167	50~413		7905060429	50~302
790340047 30-249 770310244 80-302 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278 7703090278			50~369			50-302
7905020340 50-269 790510241 50-302 7905100023 50-302 7905100023 50-302 790510268 50-269 790510023 50-302 790510026 50-269 790510023 50-302 790510036 50-270 790510023 50-302 790510036 50-270 790510036 50-270 790510036 50-302 790510036 50-269 790520303 50-302 790520303 50-302 790520303 50-302 790520303 50-302 790520303 50-302 790520303 50-302 790520303 50-302 790520303 50-302 790520303 50-302 790520303 50-302 790520303 50-302 790520303 50-302 790520303 50-302 790520303 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520304 50-302 790520037 50-302 790520037 50-302 790520037 50-302 790520037 50-302 790					7905090278	50-30≥
7908110268		7905020340			7905110241	50-302
7905150548		7905110268			7903230373	
7905230305 50-249 7905230349 50-302 7905280375 50-302 790528048 50-249 790528038 50-302 790528048 50-249 790528038 50-302 790528048 50-249 790528048 50-249 790528048 50-302 790528048 50-249 790528048 50-302 790531040 50-287 7905310410 50-287 7905310410 50-287 7905310410 50-320 7905310410 50-320 7905310410 50-320 7905310410 50-320 790530484 50-302 790530484 50-302 790530484 71-244 790530489 71-4498 790530489 71-4498 790530489 71-4498 790530489 71-4498 790530489 71-4498 790530489 71-4498 790530489 71-4498 790530489 71-4498 790530489 71-4498 790530489 71-4498 790530489 71-4498 790530489 71-4498 790530489 71-4498 790530489 71-4498 790530489 71-4498 790530489 71-4498 790530489 71-4498 790530489 71-4498 790530489 71-4498 790530489 71-4498 790530489 71-4498 790530489 71-4498 790530489 71-4498 790530489 71-4498 790530489 71-4498 790530489 71-4498 790530489 71-4498 790530489 71-4498 790530489 71-4498 790530489 71-4498 790530489 71-4498 790530489 71-4498 790530489 71-4498 790530489 71-4498 790530489 71-4498 790530489 71-4498 790530489 71-4498 790530489 71-4498 790530489 71-4498 790530489 71-4498 790530489 71-4498 790530489 71-4498 790530489 71-4498 790530489 71-4498 790530489 71-4498 790530489 71-4498 790530489 71-4498 790530489 71-4498 790530489 71-4498 790530489 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-4498 71-		7905150548			7905300303	50-302
790320428 50-269 790320427 50-269 790320428 50-302 790320427 50-269 790320427 50-302 790320427 50-269 790320427 50-302 790330440 50-287 7903300491 50-302 7903300491 50-302 7903300491 50-302 7903300491 50-302 7903300491 50-302 7903300491 50-302 7903300491 50-302 7903200491 50-302 7903200491 70-3020201 50-302 7903200491 70-3020201 50-302 7903200491 70-3020201 50-302 790310400 50-302 790310400 50-302 790310400 50-302 790310400 50-302 790310400 50-302 7903100350 50-269 7903100350 50-269 790310020276 50-302 7903100202 50-269 7903100202 50-302 7903100202 50-269 7903100202 50-302 7903100202 50-269 7903100202 50-302 7903100202 50-269 7903100202 50-302 7903100202 50-269 7903100202 50-302 7903100202 50-269 7903100202 50-302 7903100202 50-269 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 7903100202 50-302 79031002		7905230305	50-269		7905230349	50-302
790320427 50-269 790330497 50-302 790330497 50-302 790330497 30-287 790330497 50-302 790330491 30-287 790330491 50-302 790330491 30-302 790320301 30-302 790320301 30-302 790320463 70-2623 70-2623 70-2623 70-2623 70-269 7903300469 71-6698 70-302 7903300469 71-6698 70-302 7903300469 71-6698 70-302 7903300469 71-6698 70-302 7903300469 71-6698 70-302 790330023 50-269 790330023 50-269 790330023 50-269 790330023 50-269 790330024 50-302 7903500403 50-302 7903500403 50-302 7903500403 50-302 7903500403 50-269 7903300346 50-302 7903500405 50-269 7903300346 50-302 7903500405 50-269 7903300349 50-269 7903300349 50-269 7903300349 50-302 790350033 50-269 790350033 50-269 790350033 50-269 790350033 50-269 790350033 50-269 790350033 50-269 790350033 50-269 790350033 50-269 790350039 50-269 790350039 50-269 790350039 50-269 790350039 50-269 790350039 50-269 790350039 50-269 790350039 50-269 790350039 50-269 790350039 50-269 790350039 50-269 790350049 50-302 790350039 50-269 790350039 50-269 790350049 50-303 790350049 50-269 790350049 50-303 790350049 50-269 790350049 50-303 790350049 50-269 790350049 50-303 790350049 50-269 790350049 50-303 790350049 50-269 790350049 50-303 790350049 50-269 790350049 50-303 790350049 50-269 790350049 50-269 790350049 50-303 790350049 50-269 790350049 50-269 790350049 50-269 790350049 50-269 790350049 50-269 790350049 50-269 790350049 50-269 790350049 50-269 790350049 50-269 790350049 50-269 790350049 50-269 790350049 50-269 790350049 50-269 790350049 50-269 790350049 50-269 7903500044 50-280 7903500044 50-280 7903500044 50-280 7903500044 50-280 7903500044 50-280 7903500044 50-280 7903500044 50-280 7903500044 50-280 7903500044 50-280 7903500044 50-280 7903500044 50-280 7903500044 50-280 7903500044 50-280 7903500044 50-280 7903500044 50-280 7903500044 50-280 7903500044 50-280 7903500044 50-280 7903500044 50-280 7903500044 50-280 7903500044 50-280 7903500044 50-280 7903500044 50-280 7903500044 50-280 7903500044 50-280 7903500044 50-280 7903500044 50-280 7903500044 50-280 7903500044 50-280 79035000		7905250408	50-269		7905250385	50-302
7905310410 30-287 7905320301 50-364 7905320301 50-364 7905320453 70-2623 7905320453 70-2623 7905320454 70-2623 7905310403 50-302 7905310550 50-269 7905020283 50-269 7905020283 50-269 7905020283 50-269 7905020283 50-269 790502088 50-269 790502088 50-269 790502088 50-269 790502088 50-269 790502088 50-269 790502088 50-269 790502088 50-269 790502088 50-269 790502088 50-269 790502088 50-269 790502088 50-269 790502088 50-269 790502088 50-269 790502088 50-269 790502088 50-269 790502088 50-269 790502088 50-269 790502088 50-269 790502088 50-269 790502088 50-269 790502088 50-269 790502088 50-269 790502088 50-269 790502088 50-269 7905140288 50-269 7905140288 50-269 7905140288 50-269 7905140288 50-269 7905140288 50-269 7905140288 50-269 7905140288 50-269 7905120238 50-269 7905120238 50-269 7905120238 50-269 7905020238 50-269 7905020238 50-269 7905020238 50-269 7905000467 7905000467 7905000467 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047 790500047	•	7903250427	50-269		7905300497	50-302
790520463 70-2k23 790510321 71-2k6 7905010321 71-2k6 7905010321 50-2k9 7905010321 50-2k9 7905020283 50-2k9 7905040312 50-2k9 7905040312 50-2k9 7905040312 50-2k9 7905040312 50-2k9 7905040312 50-2k9 7905040315 50-2k9 7905140189 7905140189 7905140189 7905150317 7905140283 50-2k9		7905310410	50-297		7905300484	50~302
7905010521 50-269 7905010550 50-269 7905020283 50-269 7905020283 50-269 7905040352 50-269 7905040352 50-269 7905040352 50-269 7905040352 50-269 7905040368 50-269 7905040368 50-269 7905140189 7905140189 7905140189 7905140189 7905140283 50-269 7905140283 50-269 7905140283 50-269 7905140283 50-269 7905140283 50-269 7905140283 50-269 7905140283 50-269 7905140283 50-269 7905140284 50-269 7905140285 50-269 7905140285 50-269 7905140285 50-269 7905140288 50-269 7905140288 50-269 7905140288 50-269 7905140288 50-269 7905140288 50-269 7905140288 50-269 7905140289 7905140289 7905140289 7905140281 790520270 790530487 790520273 790530487 790520273 790520273 790520273 790520273 790520273 790520273 790520273 790520273 790520273 790520273 790520273 790520273 790520273 790520273 790520273 790520367 790520367 790520367 790520367 790520367 790520367 790520367 790520367 790520367 790520367 790520367 790520367 790520367 790520367 790520367 790520367 790520367 790520367 790520367 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 790520057 7905		7905220463	70-2623		7905310403	50-302
7905040283 50-269 790510298 50-302 7905040352 50-269 7905300546 50-302 7905070481 50-369 7908310399 50-302 7905240466 50-269 7908310399 50-302 7905140189 30-269 7905300158 30-302 7905140189 30-269 7905300158 30-302 7905140283 50-269 7905300158 30-302 7905140283 50-269 7908300185 30-302 7905140283 50-269 7908300185 30-302 7905140283 50-269 790840492 30-280 7905140284 50-280 7905140285 50-269 7908140225 30-280 7905140288 50-269 7908140285 30-303 7905140288 50-269 7908140285 30-303 790520270 50-269 7908240493 30-335 790520270 50-269 7908240493 30-335 790520391 30-269 7908240493 30-335 790520391 30-269 7908240493 30-335 790520391 30-269 7908240493 30-320 790520391 30-269 790800471 30-280 790520391 30-269 790800554 30-281 7905204075 50-287 790800567 30-281 7905204075 50-287 790800567 30-281 79052040475 50-287 79052040475 50-280 7905800567 50-281 7905800571 50-280		7905010521	50-269		7705020271	50-302
7905070481 50-369 7905080388 50-269 7905240466 50-269 7905240466 50-269 7905240231 50-269 790530317 50-269 790530317 50-269 790530317 50-269 790530317 50-269 790530317 50-269 790530317 50-269 790530317 50-269 790530317 50-269 790530317 50-269 790530317 50-269 790530317 50-269 790530317 50-269 790530317 50-269 790530317 50-269 790530317 50-269 790530317 50-269 790530317 50-269 790530317 50-269 790530317 50-269 790530317 50-269 790530317 50-269 790530317 50-269 790530317 50-269 790530317 50-269 790530317 50-269 790530317 50-269 790530317 50-269 790530317 50-269 790530317 50-269 790530317 50-269 790530317 50-269 790530317 50-280 790530317 50-280 790530317 50-280 790530317 50-280 790530317 50-280 790530317 50-280 790530317 50-280 790530317 50-280 790530317 50-280 790530317 50-280 790530317 50-280 790530317 50-280 790530317 50-280 790530317 50-280 790530317 50-280 790530317 50-280 790530317 50-280 790530317 50-280 790530317 50-280 790530317 50-280 790530317 50-280 790530317 50-280 790530317 50-281 790530317 50-281 790530317 50-281 790530317 50-281		7905020283	50-269	•	7905310298	50-302
7905240466 50-269 7905140189 50-269 7905140231 30-269 7905140231 30-269 7905140231 30-269 7905140265 50-269 7905140265 50-269 7905140265 50-269 7905140265 50-269 7905140265 50-269 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140268 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140475 7905140		79050704B1	50-369	•	7908310399	50-302
790540231 50-249 FPL - Florida Power & Light Co. 7905200185 50-302 7905150317 50-249 7905140283 50-250 7905140283 50-269 7905140285 50-269 7905140285 50-269 7905140285 50-269 7905140285 50-269 7905140285 50-269 7905140285 50-269 7905140389 50-269 7905140389 50-269 7905140389 7905202235 50-269 7905180249 50-335 7905180249 50-335 790520235 50-269 7905180247 50-250 7905200351 50-269 7905200351 50-269 7905800467 50-250 7905800467 50-250 7905800487 50-250 7905800487 50-250 7905800487 50-250 7905800487 50-250 7905800487 50-250 7905800487 50-250 7905800487 50-250 7905800487 50-250 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800584 50-251 7905800		7905240466	50~269	•	7705210272	80-302
7905140263 50-269 7905140265 50-281 7905140265 50-269 7905140225 50-281 7905140268 50-269 7905140225 50-282 7905140268 50-269 7905150249 50-335 7905120223 50-269 7905130247 50-335 7905220235 50-269 7905130247 50-280 7905220235 50-269 7905130247 50-280 7905220351 50-269 790500467 50-280 790520361 50-289 790500467 50-280 7905204045 50-280 790500467 50-280 7905204045 50-280 790500467 50-280 7905204045 50-280 790500467 50-280 7905204045 50-280 790500554 50-281 7905204045 50-287 790500554 50-281 7905204045 50-287 790500554 50-281 7905204045 50-287 790500554 50-281 7905204045 50-269 790500567 50-281 7905204045 50-269 790500567 50-281 7905204045 50-269 790500567 50-281		7905240231	50-249	FPL - Florida Bauer & Links an	7905300185	50~302
7905140248 50-269 7905290159 50-335 7905140248 50-269 7905150249 30-335 7905120270 50-269 7905150247 30-335 790520235 50-269 7905150247 30-250 790520235 50-269 7905180247 30-250 790520391 30-269 7905080471 30-250 790520391 30-269 7905080571 30-251 7905240593 50-287 7905080554 50-251 7905240593 50-287 7905080554 50-251 7905240593 50-269 7905080567 30-251 7905240475 50-269 7905080571 30-251		7905140283	50-269	;	7905240492	50-251
7905220270 50-269 7905240048 50-335 7905220235 50-269 7905180247 50-250 7905300541 50-269 7905000471 50-250 7905220351 50-269 7905000471 50-250 7905220351 50-269 7905000571 50-250 7905240593 50-287 7905000554 50-251 7905240593 50-287 7905000557 50-251 7905190100 50-413 790500057 790500057 50-251 7905240475 50-269 7905000571 30-281 7905240475 50-269 7905000571 30-280		7905140268	20-574		7903290159	30-335
790300541 50-269 7905080467 50-280 79032031 50-269 7905080471 50-280 7903230487 50-287 7905080545 50-281 7905240593 50-287 790508055 50-281 7905190100 50-413 7905080567 50-281 7905240475 50-269 7905080567 50-281 7905240475 50-269 7905080567 50-281		7905220270	50-269	7	7905240048	50-335
7905230487 50-287 7905080554 50-281 7905240593 50-287 7905080589 50-251 7905190100 50-413 7905080547 50-251 7905240475 50-269 790508057 50-251 7905310211 50-269 7905240434 30-250		7905300541	50-269	7	7905080467	50-250
7905190100 50-413 7905080367 30-231 7905240475 50-269 790508031 30-231 7905310211 50-269 7905240434 30-230		7905230487	50-287	7	905080554	50-251
7905310211 50-269 7903240434 30-230		7905190100	50-413	7	7905080567	50-251
				7	PC40434	30-520

AUTHOR AFFILIATION	ACCEBBION	POCKET	AUTHOR	ACCE8810N	DOCKET
	NUMBER	NUMBER	AFFILIATION	NUMBER	NUMBER
	7905090067	50-250			
	7905090072 7905090074	50-250 50-250		7905110389 7905110357	50-320 50-320
	7905090081 7905090062	50-250 50-335		7905110354 7905110401	50~320 50~320
	7905090064 7908220091	50-335 50-335		7905110397 7905110395	50-320 50-320
	7905220103 7905220113	50-250 50-250		7905110392 7905110393	50-320 50-320
	7905300015 7905220122	50-250 50-250		7903110406 7903110403	50~320 50~320
	7905220129 7905250388	50-250 50-250		7905110405 7905110402 7905110400	50~320 50~320 80~320
	7905250392 7905150241	50-250 50-335		7905110396 7905110385	50-320 50-320
	7905220098 7905250397	50-335 50-335		7905110384 7905110382	50-320 50-320
	7905250411 7905300040	50-250 50-250		7905110378 7905110376	50-320 50-320
	7905080412 7905140217	50-250 50-250		7905110373 7905110368	50-320 50-320
	7905140310 7905240486	50-335 50-251		7905110366 7905110337	50-320 50-320
	7905240547 7905250426	50-250 50-250		7905230117 7905230099	50-320 50-320
	7905040595 7905070410	50-335 50-335		7905230107 7905230110	50-320 50-320
	7905210121 7905220027	50-335 50-335		7903190118 7903190113	50-320 50-320
	7905310214 7905300014	50-335 50-335		7905190111 7905210228	50-320 50-320
	7905310305 7905310309	50-335 50-335		7905190093 7905190120	50-320 50-320
	7905140220 7905290143	50-250 50-250		7905190187 7905230009	50-320 50-320
QAP - Qeorgia Power Co.	7905150605 7905150348	50-366		7905230005 7905230006	50-320 50-320
	7905250462 7905150344	50-366		7905230103 7905220362	50-320 50-320
	7905080524 7905140316	50-321 50-321		7905210120 7905230082	50-320 50-320
	7905100244 7905010470	50-321 50-366		7905230011 7905230013	50-320 50-320
	7905010469 7905010502	50-366 50-321		7905230024 7905220368	50-320 50-219
	7905080546 7905080550	50-321 50-321		7905210270 7905230080	50-219 50-320
	7905290029 7905080473	50-321 50-321		7905090203 7905110374	50-320
	7905080479 7905080520	50-321 50-321	QBU ~ Qulf States Utilities Co	7905230808 7905150453	50-459 50-458
	7905070639 7905070646	50-366 50-366	HLP - Houston Lighting & Power Co	7905310429 7905080409	30-45 <del>8</del> 30-4 <i>9</i> 8
,	7905300309 7905240489	50-321 50-424		7905240693 7905030336	30-498 30-498
	7908150445 7905150447	50-366 50-366		7905090408 7905150236	50-498 50-498
	7903150519 7903150525	50-321 50-321	IELP - Iowa Electric Light & Power Co	7905250398 7905210224	30-466 30-331
	7903130543 7903130549	50-321 50-321		7905210220 7905110163	50-331 50-331
	7905290035 7905300627	50-321 50-321		7905150050 7905300272	50-331
	7905300638 7905300644	50-321 50-321		7905020251 7905020253	50-331 50-331
	7903300660 7903300683	50-321 50-321		7905250213 7905160363	50-331 50-331
	7905300591 7905300591	50-321 50-321		7905160366 7905160386	50-331 50-311
	7908300603 7908300664	50-321 50-321		7905160387 7905290182	50-331
	7905300674 7905250098	50-321 50-321		7905290191 7905100400	50-331 71-296
	7905190213 7905170234	50-321 50-321		7903040491 7903080469	50-331 50-331
	7905230047 7905230538	50-321 50-321		7905090368 7905080465	50-331 50-331 50-331
	7905270184 7905300006	50~366 50~321	Ann A Addition to Oc. 4 Plantain	7905310447 7905230522	50-331
	7905080427 7905240927	50-321 50-424 50-424	IIGE - Iowa-lilinois Gas & Electric ILPR - Illinois Power Co.	7905070406 7905290563 7905070437	50-441 50-315
	7905020241 7905230398	50-424	IMPR — Indiana & Michigan Power Go.	7905170252	50-315 50-315
QENP - General Public Utilities	7905190059 7905110234	50-321 50-320 50-320		7905170242 7905170248 7905170241	50-315 50-316
OMPC - Oreen Hountain Power Corp.	7905140065 7905170251	50~443 50~271		7905150156 7905250352	50-315 50-313
COLL AND CANADA C	7905310261 7905170253 7908330012	50~443 50~320		7905040001 7905040002	50-316 50-316
OPU - OPU Service Corp	7905230012 7905230010	50~320 50~320		7903150345 7903070583	50-313 50-314
	7905230007 7905230008 7905230438	20~320 20~320		7903070590 7903070598	50-315 5 <b>6-</b> 315
	7905220438 7905190140 7905230014	50-320 50-320		7903070604 7903070613	50-315 50-315
	7905230015 7905230001	50-320 50-320		7905250371 7905310469	50-315 50-315
	7905190009 7905140025	50-320 50-320		7903110120 7903110124	50-315 50-315
	7905210018 7905210021	50-320 50-320		7905150423 7905150430	50-315 50-315
	7905110370 7905110367	50-320 50-320		7905150438 7905150441	50-315 50-315
	. 1000 1 4000				



### Company of Company	AUTHOR AFFILIATION	ACCEBSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET
Production   Pro						~~~~~~
## 1991 00-20   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992   1992						
## Company   Proposed		7905150493	50-316		7905110176	
### Company		7905150501 7905210135				
Processor   Proc		7905210142				50-320
Productions		7905220326	50-315		7905190248	50-320
		7905220339	50-315		7905190243	50-320
Procession   Pro			50-316		7905080526	50~320
Pedal   16   16   16   16   16   16   16   1						
### PRODUCT   Proposed		7905070428	50-315			50-320
## 100210401   50-015   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310502   50-026   700310		7905290149	50-315		7905220371	50-287
1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   1000   10000   10000   10000   10000   10000   10000   10000   10000		7905310440	50-315		7905110333	50-320
Dec			50-315			
\$\frac{7}{7}001500279   \$\fr	JCPL → Jersey Central Power & Light Co	7903070470	50-363		7905090251	50-320
7-700210246 50-210 7-700200247 50-210 7-700200247 50-210 7-700200247 50-210 7-700200247 50-210 7-700200247 50-210 7-700200247 50-210 7-700200247 50-210 7-700200247 50-210 7-700200247 50-210 7-700200247 50-210 7-700200247 50-210 7-700200247 50-210 7-700200247 50-210 7-700200247 50-210 7-700200247 50-210 7-700200247 50-210 7-700200247 50-210 7-700200247 50-210 7-700200247 50-210 7-700200247 50-210 7-700200247 50-210 7-700200247 50-210 7-700200247 50-210 7-700200247 50-210 7-700200247 50-210 7-700200247 50-210 7-700200247 50-210 7-700200247 50-210 7-700200247 50-210 7-700200247 50-210 7-700200247 50-210 7-700200247 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 50-210 7-700200248 5		7905150277	50-219		7905190231	50-320
1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998		7905210269	50-217		7905210240	50-320
1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998   1998		7905250077	50-219			
7700307037 50-219 77003040476 77003040418 50-219 77003040418 50-219 77003040418 50-219 77003040418 50-219 77003040418 50-219 77003040418 50-219 77003040418 50-219 77003040418 50-219 77003040418 50-219 77003040418 50-219 77003040418 50-219 77003040418 50-219 77003040418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 7700340418 50-219 77003						
700040478					7903080521	50-320
7000000322 50-219 7000000325 50-219 7000100327 50-219 7000100327 50-219 7000100327 50-219 7000100327 50-219 7000100327 50-219 7000100327 50-219 7000100327 50-219 7000100327 50-219 7000100327 50-219 7000100327 50-219 7000100327 50-219 7000100327 50-219 7000100327 50-219 7000100327 50-219 7000100327 50-219 7000100327 50-219 7000100327 50-219 7000100327 50-219 7000100327 50-219 7000100327 50-219 7000100327 50-219 7000100327 50-219 7000100327 50-219 7000100327 50-219 7000100327 50-219 7000100327 50-219 7000100327 50-219 7000100327 50-219 7000100327 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032 50-219 700010032		7905040478	50-219		7905220318	50-289
19-03-10-23-2-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-		7905090332	50-217		7905290384	
7790110237			50-219			
790310472					7905110165	50-320
790180172		7905140243	50-217		7905110149	50-320
7900160374   50-219   7900200466   50-300   7900200466   50-300   7900200046   50-300   7900200046   50-300   7900200046   50-300   7900200046   50-300   7900200046   50-300   7900200046   50-300   7900200046   50-300   7900200046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-300   790020046   50-30		7905150472	50-219		7905190121	50-320
790510217 50-219 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520028 50-209 790520		7905160374	50-219		7905020468	50-320
77053C0274 30-219 77053C0287 30-219 77053C0287 30-209 77053C0287 30-209 77053C0288 30-219 77053C028 30		7905210217	50-217			
7903263618					7905070587	50-289
No.		7905220391	50-217		7905240558	50~289
10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   10-200   1		7905290014	50-219		7905190229	50-320
### ### ### ### ### ### ### ### ### ##		7905290023	50-219			
7903500174						
## FOOLING 150275   50-219   790330044   50-416   790330044   50-416   790330044   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   790320043   50-416   7				MPL - Mississippi Power & Light Co	7905140340	
1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905    1905		7905150275	50-219		7905300441	
7905210265 SO-219 7905290061 SO-416 7905210061 SO-416 7905210267 7905210267 7905210267 7905210267 7905200161 SO-416 7905200163 SO-416 7905200163 SO-416 7905200163 SO-416 7905200163 SO-416 7905200178 SO-219 7905200163 SO-416 7905200164 SO-219 7905200163 SO-416 7905200164 SO-219 7905200163 SO-416 7905200164 SO-219 7905200164 SO-209 7905200164 SO-309 7905		7905210174	50-219		7905020455	50-416
7903240313 50-219 79032404033 50-416 7903290178 50-219 7903290178 50-219 7903290178 50-219 7903290178 50-219 7903290178 50-219 7903290178 50-219 7903290391 50-219 7903290391 50-219 7903290391 50-219 7903290392 50-416 7903290392 50-416 7903290392 50-416 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392 50-219 7903290392		7905210265	50-219			50-416
7905290178   50-219   7905200343   50-416   7905200172   50-219   7905200343   50-416   7905200172   50-219   7905200343   50-416   7905200313   50-219   7905200313   50-219   7905200313   50-219   7905200313   50-219   7905200313   50-219   7905200313   50-219   7905200313   50-219   7905200313   50-219   7905200313   50-219   7905200313   50-219   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520032   790520033   790520033   790520032   790520033   790520033   790520033   790520033   790520033   790520033   790520033   790520033   790520033   790520033   790520033   790520033   790520033   790520033   790520033   790520033   790520033   790520033   790520033   790520033   790520033   790520033   790520033   790520033   790520033   790520033   790520033   790520033   790520033   790520033   790520033   790520033   790520033   790520033   790520033   790520033   790520033   790520033   790520033   790520033   790520033   790520033   790520033   790520033   790520033   790520033   790520033   79						
7905290172 7905290374 50-219 7905290375 30-309 7905290375 50-309 7905290376 50-219 7905290375 30-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7905290376 50-309 7						
## SO-219					7905080450	
KBGE - Kansas Oas & Electric Co 790310314 50-482 7903200626 7903300626 7903300626 7903300626 7903300626 7903300626 7903300626 7903300626 7903300626 7903300626 7903300626 7903300626 7903300626 7903300626 7903300626 7903300626 7903300626 7903300626 7903300626 7903300626 7903300626 7903300626 7903100311 50-482 7903200330 50-309 790310027 790310027 790310027 790310027 790310027 7903100262 7903100262 7903100262 7903100264 7903100264 7903100264 7903100264 7903100264 7903100264 7903100266 7903100266 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100260 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 7903100026 79031000		7905290394	50-219		7905090375	
79033006.26 50-482 7705303183 50-307 7705303183 50-307 7705303183 50-307 7705303183 50-307 7705303183 50-307 7705303183 50-307 770530314 50-482 7705320335 50-309 7705310311 50-482 770530335 50-309 7705310311 50-482 7705300433 50-309 7705310311 50-482 770530043 50-309 7705310323 50-309 7705310323 50-309 7705310323 50-309 7705310323 50-309 7705310313 50-382 770531043 50-309 7705310313 50-382 770531043 50-309 770531043 50-309 770531043 50-309 770531043 50-309 770531044 50-309 770531044 50-309 770531044 50-302 770531044 50-309 770531044 50-309 770531044 50-309 770531044 50-302 770532031 50-309 770532045 50-302 770532031 50-309 7705320464 50-302 770532031 50-309 7705320464 50-302 770532031 50-309 7705320464 50-302 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 770532031 50-309 7	KROF - Vaness Oss & Flank-in Ca	7905070466	50~363		7905240659	50-309
7905290364 50-482 7905290355 50-309 7905190311 30-482 7905290355 50-309 7905190311 30-482 79051903035 50-309 7905190311 30-482 7905190303 50-309 7905190303 50-309 7905190313 30-309 7905190433 50-309 7905190435 50-309 7905190435 50-309 7905190435 50-309 7905190435 50-309 7905190435 50-309 7905190435 50-309 7905190435 50-309 7905190435 50-309 7905190435 50-309 7905190435 50-309 7905190435 50-309 7905190435 50-309 7905190435 50-309 7905190435 50-309 7905190435 50-309 7905190435 50-309 7905190435 50-309 7905190435 50-309 7905190435 50-309 7905190435 50-309 7905190435 50-309 7905190435 50-309 7905190435 50-309 7905190435 50-309 7905190435 50-309 7905190435 50-309 790519045 50-309 790519045 50-309 790519045 50-309 790519045 50-309 790519045 50-309 790519045 50-309 790519045 50-309 790519045 50-309 790519045 50-309 790519045 50-309 790519045 50-309 790519045 50-309 790519045 50-309 790519045 50-309 790519045 50-309 790519045 50-309 790519045 50-309 790519045 50-309 790519045 50-309 790519045 50-309 790519045 50-309 790519045 50-309 790519045 50-309 790519045 50-309 790519045 50-309 790519045 50-309 790519045 50-309 790519045 50-309 7905190519 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 790519051 50-309 7	umag vanses ass a precedic co	7905300626	50-482			
LAPL - Louisiana Power & Light Co 790510322 50-382 790509033 50-309 790510322 790510323 50-309 790510323 50-309 790510323 50-309 790510323 50-309 790510323 50-309 790510323 50-309 790510323 50-309 790510323 50-309 790510323 50-309 790510323 50-309 790510324 50-309 790510324 50-309 790510324 50-309 790510324 50-309 790510260 50-382 790520341 50-309 790510260 50-382 790520341 50-309 790510260 50-382 790520341 50-309 790510260 50-382 790520361 50-309 790510260 50-382 790520361 50-309 7905204054 50-322 7905204054 50-322 790520361 50-309 7905204054 50-322 7905204054 50-322 790520365 50-309 7905204055 50-322 790520365 50-309 7905204055 50-322 790520365 50-309 7905204055 50-322 790520365 50-309 7905204055 50-322 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 790520365 50-309 79052		7905080514	50-492		7905250456	50-309
7905150273 50-382 7905150434 50-309 7905170231 50-382 7905210157 50-309 7905170231 50-382 7905210130 50-309 7905150264 50-382 7905220151 50-309 790517028 50-382 7905220341 50-309 790517028 50-382 7905220341 50-309 790517028 50-382 7905220341 50-309 790517028 50-382 7905230328 50-309 790517028 50-382 7905230328 50-309 790517028 50-382 7905230328 50-309 7905240645 50-322 7905240645 50-322 7905240645 50-309 7905240640 50-322 7905240646 50-322 7905240646 50-309 7905240640 50-322 7905240646 50-322 7905240646 50-309 7905240640 50-322 7905240646 50-309 7905240640 50-322 7905240646 50-309 7905240640 50-322 7905240647 50-309 7905240640 50-322 7905240647 50-309 7905240640 50-322 7905240647 50-309 7905240640 50-322 7905240647 50-309 7905240649 50-322 7905240647 50-309 7905240639 50-322 NENE - Northeast Nuclear Energy Co. 790510496 50-309 7905240369 50-322 NENE - Northeast Nuclear Energy Co. 790510496 50-245 7905240649 50-322 NENE - Northeast Utilities 7905040646 50-213 7905080697 50-322 NENE - Northeast Utilities 7905010466 50-213 7905080697 50-322 NENP - New England Power Co. 7905101037 7905080697 50-322 NENP - New England Power Co. 7905101037 7905080697 50-322 NENP - New England Power Co. 7905101037 790510406 50-225 NENP - Northeast Utilities 7905010466 50-213	LAPL - Louisiane Power & Light Co				7905090330	50-309
7905170231 50-382 7905210130 50-309 7905130244 50-382 7905250159 50-309 7905150464 50-382 7905220341 50-309 7905170228 50-382 7905220341 50-309 7905170228 50-382 7905220341 50-309 7905170248 50-382 7905220341 50-309 7905240654 50-322 790529061 50-309 7905240655 50-322 790529061 50-309 7905240648 50-322 7905240656 50-309 7905240650 50-322 7905240656 50-309 7905240650 50-322 7905240656 50-309 7905240376 50-322 790524067 50-309 7905240376 50-322 790524067 50-309 7905240376 50-322 790524067 50-309 7905240376 50-322 790524067 50-309 7905240376 50-322 790524067 50-309 7905240376 50-322 790524067 50-309 7905240376 50-322 7905240639 50-309 7905240376 50-322 7905240639 50-309 7905240376 50-322 7905240314 50-309 7905240376 50-322 NENE - Northeast Nuclear Energy Co. 7905010476 50-245 Nent - Northeast Utilities 7905010476 50-245 NENT - Northeast Utilities 7905010476 50-213 7905080497 50-321 NENP - New England Power Co 7905110137 7905080497 50-321 NENP - New England Power Co 790510305 50-321		7905150273	50-382		7905150434	50-309
7905150264 50-382 7705250159 50-309 7905170428 50-382 7705220341 50-309 7905170428 50-382 7705220341 50-309 7905170454 50-382 770520341 50-309 790510454 50-382 770520341 50-309 7905240645 50-382 770520061 50-309 7905240648 50-322 7705070366 50-309 7905240648 50-322 7705070366 50-309 7905240650 50-322 7705240665 50-309 7905240670 50-322 7705240665 50-309 7905240376 50-322 7705240670 50-309 7905240376 50-322 7705240670 50-309 7905240376 50-322 7705240670 50-309 7905240376 50-322 7705240670 50-309 7905240376 50-322 7705240670 50-309 7905240376 50-322 7705240670 50-309 7905240376 50-322 7705240670 50-309 7905240376 50-322 7705240670 50-309 7905240376 50-322 7705240670 50-309 7905240376 50-322 NENE - Northeast Nuclear Energy Co. 7905040514 50-309 7905240369 50-322 NENE - Northeast Nuclear Energy Co. 7905010496 50-245 7905240377 50-322 NENE - Northeast Utilities 7905010496 50-245 7905240437 50-322 NENP - New England Power Co. 7905110137 79052404377 50-321 NENP - New England Power Co. 7905100496 50-245 79052404377 50-321 NENP - New England Power Co. 7905100496 50-245 79052404377 50-321 NENP - New England Power Co. 7905100496 50-245 79052404377 50-322 NENP - New England Power Co. 7905100496 50-245 79052404377 50-322 NENP - New England Power Co. 7905100496 50-245 79052404377 50-322 NENP - New England Power Co. 7905100496 50-245 79052404377 50-322 NENP - New England Power Co. 7905100496 50-245		7905170231	50~382			
7905100408 50-382 790510260 50-382 790520358 50-309 7905170265 50-382 7905200654 50-309 7905240654 50-322 7905090382 50-309 7905240648 50-322 7905090382 50-309 7905240650 50-322 7905240666 50-309 7905240650 50-322 7905200019 50-309 7905240650 50-322 7905200019 50-309 790524067 50-322 7905200019 50-309 790524067 50-322 7905200019 50-309 790524067 50-322 790520019 50-309 790524067 50-322 790520019 50-309 7905240407 50-322 790520019 50-309 7905240407 50-322 790520019 50-309 7905240407 50-322 790520019 50-309 7905240407 50-322 790520019 50-309 7905240407 50-322 790520019 50-309 7905240369 50-322 NENE - Northeast Nuclear Energy Co. 790510495 50-309 7905240367 50-322 NENE - Northeast Utilities 7905010496 50-245 TOOS 100 100 100 100 100 100 100 100 100 10		7905150264	50-382			
790510240 50 -382 790504061 50-309 7905240645 50-309 7905240645 50-322 7905040645 50-309 7905240645 50-322 790504065 50-309 7905240650 50-322 7905240650 50-322 7905240650 50-322 7905240650 50-322 7905240650 50-322 790524067 50-309 790524067 50-322 790524067 50-309 790524067 50-322 790524067 50-309 790524067 50-322 790524067 50-309 790524067 50-322 790524067 50-309 790524067 50-322 790524067 50-309 790524067 50-322 790524067 50-309 790524067 50-322 790524067 50-309 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-322 790524067 50-		7905170228	50-382		7905220341	50-309
7905240645 50-322 790570366 50-309 7905240645 50-322 7905240656 50-309 7905240630 50-322 7905240636 50-309 7905240376 50-322 7905240377 50-309 7905240376 50-322 7905240377 50-309 7905240376 50-322 7905240376 50-309 7905240376 50-322 7905240376 50-309 7905240379 50-322 7905240379 50-309 7905240379 50-322 7905240379 50-309 7905040319 50-322 7905240379 50-309 7905040318 50-322 NENE - Northeast Nuclear Energy Co. 7905040314 50-309 7905240367 50-322 Nene - Northeast Nuclear Energy Co. 7905040314 50-309 7905240367 50-322 (Northeast Utilities) 7905240367 50-322 (Northeast Utilities) 790504037 50-321 NENP - New England Power Co. 790510496 50-245 7905040477 50-321 NENP - New England Power Co. 790510496 50-213 7905040477 50-321 NENP - New England Power Co. 790510496 50-213					7905090061	50-309
790524050 50-322 7905300019 50-309 7905240376 50-322 7905200019 50-309 7905240376 50-322 790520043 50-309 7905240976 50-322 7905240243 50-309 79052404039 50-322 7905240243 50-309 7905404039 50-322 7905240243 50-309 7905404039 50-322 7905240243 50-309 79052404039 50-322 NENE - Northeast Nuclear Energy Co. 7905010485 50-309 7905240369 50-322 (Northeast Utilities) 7905010496 50-245 Thority of 7905080308 50-321 NENP - New England Power Co 7905110137 7905804077 50-321 NENP - New England Power Co 790510037 7905004077 50-321 NENP - New England Power Co 790510037 7905004077 50-321 NENP - New England Power Co 790510037 7905004077 50-321 NENP - New England Power Co 790510037 7905004077 50-321 NENP - New England Power Co 790510037 7905004077 50-321 NENP - New England Power Co 790510037 7905004077 50-321 NENP - New England Power Co 790510037 7905004077 50-321		7905240645	50-322		7905090382	50-309
7905240376 50-322 7905190151 50-307 7905290210 50-322 7905190151 50-307 7905240976 50-322 7905220243 50-307 79052404039 50-322 7905230803 50-307 790590500 50-322 NENE - Northeast Nuclear Energy Co. 7905040514 50-307 7905240539 50-322 NENE - Northeast Utilities) 7905240539 50-322 (Northeast Utilities) 7905040539 50-322 NENP - New England Power Co 790510137 7905040549 50-321 NENP - New England Power Co 790510137 7905040549 50-321 NEUT - Northeast Utilities 7905070666 50-213		7905240650	50-322		7905300019	50-307
790524094 50-322 7905240243 50-309 79052404039 50-322 7905240251 50-309 7905040439 50-322 7905230803 50-309 7905080500 50-322 NENE - Northeast Nuclear Energy Co. 7905010495 50-245 7905240349 50-322 (Northeast Utilities) 7905010496 50-245 790504039 50-321 NENP - New England Power Co 7905110137 790504047 790504047 50-321 NEUT - Northeast Utilities 7905070466 50-213		7905240376	50-322			
7905040439 50-322 7905240603 50-309 7905040518 50-322 7905040514 50-309 7905040549 50-322 NENE - Northeast Nuclear Energy Co. 7905010485 50-245 7905240639 50-322 (Northeast Utilities) 7905010496 50-245 7905240639 50-322 7905010496 50-245 7905040639 50-321 NENP - New England Power Co 7905110137 7905080497 50-321 NEUT - Northeast Utilities 7905070666 50-213 7905080497 50-321 NEUT - Northeast Utilities 7905070666 50-326		7905240996	50-322		7905220243	50-309
790380300 50-322 NENE - Northeast Nuclear Energy Co. 7908010485 50-245 7908240369 50-322 (Northeast Utilities) 790804049 50-322 7908010496 50-245 790804049 50-322 7908010496 50-245 790804049 50-321 NENP - New England Power Co 7908110137 7908060497 50-321 NEUT - Northeast Utilities 7908060497 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060497 50-321 7908060					7905230803	50-309
7905240637 50-322 7905010496 50-245 thority of 7905080308 50-321 NENP - New England Power Co 7905110137 7705080497 50-321 NEUT - Northeast Utilities 790510666 50-213 7705080497 50-321 7905150305 50-336		7905080500	50-322			
THORITY OF 7405080509 50-321 NEMP - New England Power Co 7405110137 NEUT - Northeast Utilities 7405070666 50-213 7705080497 50-321 NEUT - Northeast Utilities 7405150305 50-336	ER	7905240639	50-322			50-245
7905080497 50-321 7905180505 50-336	thority of			NEMP - New England Power Co NEUT - Northeast Utilities	7905110137	50-213
				•		50~336

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
	7905220404	30-245		7905150468	50-282
	7905250523			7905210279	80~306
	7905150502 7905220395	50-336 50-245		7905210293 7905220114	50-306 50-306
	7905250446 7905080456	50-213 50-336		7705220118	50-306 50-263
	7905080461	50-336		7905230515 7905250429	50-263
	7905300452 7905300457	50-336 50-336		7905140104 7905020236	50-282 50-282
	7905300533 7905300544	50-245 50-245		7905040415	50-263
	7905290221	50-336		7905090369 7905010474	50-263 50-282
	7905290076 7905190075	71~9044 50~245		7905080413 7905010479	50-263 50-282
	7905040053	50-336		7905040530	50-263
	7905040135 7905070359	50-336 50-336		7905070366 7905070459	50-263 50-282
	7905080404 7905100320	50-334 50-334		7905150225 7905240560	50~263 50~263
	7905160262	50-334		7905240681	50-263
	7905140374 7905220114	50-336 50-336		790530040 <i>6</i> 7905230394	50~262 50~263
	7905290073	50-213 50-336		7905290093	50-263
	7705300009 7705300261	50~336		7903040517 7903040011	50-263 50-263
	7905310183 7905070621	50-336 50-243	NYEO - New York State Electric & Gas	7905190033 7905300477	50-263 50-596
	7905080562	50-245	Corp.		
	7903080454 7903290073	50-245 50-213		7905310342 7905010494	50-594 50-594
	7905300005 7905150439	50-245 50-423	NYSEO - New York State Electric & Oas	7905220120 7905240160	50-594 50-594
	7905070658	50-213	OPPD - Omena Public Power District	7905300353	50-285
NIPS - Northern Indiana Public Service	7905250513 7905210280	50-367		7905090363 7905140240	50-285 50-285
Ca.	7905010534	50-367		7905150319 7905310248	50-285 50-285
	7905140308	50-367		7905140238	50-285
	7905110306 7905220207	50-367 50-367		7905140494 7905140487	50-285 50-285
	7905210277	50-367		7905290222	50-285
NMP - Niagara Mohawk Power Corp	7905300329 7905020367	50-367 50-220		7905150211 7905230618	50-285 50-285
	7905150511 7905310221	50-220 50-220		7903070545 7905100128	50~285 50~285
	790515050日	50-220		7905240672	50-285
	7905100421 7905070401	50-220 50-220		7905290499 7905210259	50~285 50~285
	7905070411 7905160392	50-220 50-220		7905070541 7905210256	50-238 50-285
	7905160374	50-220		7905210268	50-265
	7905300496 7905300496	50-220 50-220		7905210271 7905220300	50-285 50-285
	7905150291	50-220		7903220304 7905300557	50-265 50-285
	7905230295 7905080414	50-220 50-220		7905300548	50-285
	7905230476 7905150597	50-220		7905160382 7905160406	50-265 50-265
NPPD - Nebraska Public Power District	7905080495	50-298		7905300349 7905230458	50-285 50-285
	7905150526 7905150522	50-298 50-298		7905090317	50-285
	7905020129 7905140335	50-298 50-298		790508044 <i>6</i> 790509004 <i>6</i>	50-285 50-285
	7905140336	50-278		7905100312 7905240562	50-265 50-265
	7905080487 7905150384	50-298 50-298	PACP - Pacific Power Co	7705090293	50-50B
	7905160127 7905140226	50~298 50~298		7903220304 7903230472	50-344 50-522
	7905020269	50-278	PASN - Power Authority State of New York		50~266
•	7905080478 7905150369	50-298 50-298		7903100161 7905100183	20-333 20-589
NSP Northern States Power Co.	7905230355 7905010511	50-278 50-282		7905150304 790510017 <i>9</i>	50-284 50-333
the 1967年11月1日 安安斯安亚 自日教育( 安日)	7905150231	50-263		7905110256 7905220380	50-333 50-286
	7905070380 7905040022	50-263 50-263		7905110254	50-333
	7905070372 7905150499	50-263 50-263		7903150302 7903030181	50-286 50-286
	7905090392	50-263		7905010584 7905250172	50-333
	7905010509 7905090388	50-263 50-263		7905220319	50-284 50-284
	7905150496	20-585		7905220322 7905220327	50-264 50-264
	7905070344 7905150575	50-262 50-263		7905220331	50-266
	7905290321 7905030364	50-263 50-282		7905220334 7905220338	50~264 50~264
	7905030367	50~282		7905250162 7905250241	50~333 50~286
	7905020462 7905040521	50-282 50-282		7905240290	50-333
	7905040604 7905080543	50-263 50-263		7905010499 7905010503	50-333 50-333
	7905080569	50~262		7905010505 7905010508	50-333 50-333
	7905080424 7905080438	50-263 50-263		7903250194	50-333
	7905290290	50~262		7905010516 7905010522	50-266 50-266
	7905110127 7905110191	50-282 50-282		7905090301	50-266
	7905140214 7905160352	50~282 50~282		7905090305 7905150475	50-284 50-333
	7905160358	50-282		7905150477 7905300411	50-333 50-333
	7905160379 7905160381	50-263 50-263		7905300416	50~333
	7905150466	50-292		7905300506	50-333

AUTHOR AFFILIATION	ACCEBSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
	7905300514	50-333		7905220311	80744
	7905300522	50-333		7905220314	50-344 50-344
	7905300527 7905070168	50-333 50-286		7905310350 7905020388	50-344 50-344
	7905100175 7905110175	50-333 50-333		7905220078 7905300426	50-344
	7905220387	50-333		7905020478	50-344 50-344
	7905040505 7905080565	50-333 50-333		7905040520 7905090291	50-344 50-344
	7905090315 7905090343	50-333 50-333		7905150387	50-344
	7905140307	50-333		7905230492 7905220187	50-344 50-344
	7905150452 7905190073	50-333 50-333		7905230407 7905110014	50-344 50-514
	7903230430 7905240697	50-333 50-333		7905080431	50-344
	7905040513	50-286		7905290042 7905090433	50-344
	7905100156 7905230551	50-284 50-286	PPL - Pennsylvania Power & Light Co.	7905040504 7905030149	50-387 50-387
	7905310394 7905310443	50-266 50-286		7905250186	50-387
	7905070417			7905110300 7905160424	50-387 50-387
PECO - Philadelphia Electric Co	7905140346 7905030352	50-277 50-277		7905250421 7905040146	50-387 50-387
	7905110076 7905170241	50-277 50-277		7905040304	50-397
	7905170236	50-277		7905240574 7905020262	50-367 50-367
	79052202 <del>9</del> 0 79052202 <del>9</del> 4	50-277 50-277		7905090365 7905150224	50-367 50-367
	7905080464 7905250152	50-277 50-277	SSS - Subtile Semiler Co	7905090346	50-387
	790504057B	50-277	PSC - Public Barvice Co of Colorado	7905010514 7905080457	50-267 50-267
	7905040077 7905040092	50-277 50-277		7905010507 7905080455	50-267 50-267
	7905140344 7905040581	50-277 50-277		7705140288	50-267
	7905150443	50-277		7905140294 7905140319	50-267 50-267
	7905230861 7905160383	50-277 50-277		7905140323 7905250464	50-267 50-267
	7905290214 7905290216	50-277 50-277		7905230637	50~267
	7903230710	50~277		7905300222 7905040374	50-267 50-267
	7905240184 7905030348	50-277 50-277		7905040376	50~267
	7905110073 7905220347	50-277 50-277		7905080544 7905080549	50-267 50-267
	7905020347	50-277		7905160367 7905160371	50-267 50-267
	7905020356 7905290345	50-277 50-277		7905160372	50-267
PEP - Potomac Electric Power Co	7905020538 7905090376	50-448		7905160377 7905230393	50-267 50-267
	7905090374	50~44B		7905230403 7905010361	50-267 50-267
PGE - Pacific Qua & Electric Co	7905300174 7905300529	50-133 50-133		7905150800	50-267
	7905150368 7905030244	50-275		7905160315 7905230025	50-267 50-267
	7905140554	50-275	PSEO - Public Service Electric & Gas Co.	7905030321 7905080483	50-267 50-311
	7905140556 7905150 <del>0</del> 03	50-275	of New Jersey		
	7905090319 7905190132	50-133 50-133		7905300421 7905150299	50-272 50-272
	7905300007	50-275		7905250471 7905080462	50-272 50-272
	7905300364 7905250490	50-275 50-275		7905080466	50-272
	7905020302 7905190130	50-275 50-133		7905300417 7905300431	50-272 50-272
	7905140303	50-133		7905080489 7905150295	50-272 50-272
	7905140304 7905150809	50-133 50-133		7905070140	50-272
	7905090380 7905240701	50-275 50-275		7905140230 7905290045	50-272 50-272
	7905290011	50-133	₩	7905290070 7905290495	50-272 50-272
	7905190054 7905300168	50-275 50-133		7905030360	50-272
	7905140406 7905300510	50-133 50-133		7905010525 7905010555	50-272 50-272
	7905090316	50-133		7905250441 7905040538	50-272 50-272
	7905020244 7905210172	50-275 50-275		7905040541	50-272
	7905210169 7905300361	50-275 50-275		7905040370 7905040371	50-272 50-272
POGE - Portland General Electric Co	7905250475 7905030158	50-344		7905080485 7905080525	50-272 50-272
	7905130722	50~344 50~344		7905140227	80-272
	7905090288 7905220298	50-500 50-344		7905250072 7905150444	50-272 50-272
	7905040523 7905110169	50-344		7905150446 7905150462	50-272 50-272
	7905240948	50-344 50-344		7905150464	50-272
	7905030361 7905240948	50-344 50-344		7905220127	80-272
	7905110167 7905290078	50-344 50-344		7905220132 7905220308	50-272 50-272
	7905040458	50-344		7905220314	50-272
	7905040449 7905150812	50-344 50-344		7905290408 7905080421	50-272 50-272
	7908240908	50-344		7905300363 7905070552	50-272 50-354
	7905100267 7905100270	50-344 50-344		7905070647	50-272
	7905170238 7905170247	50-344 50-344		7905170263 7905150280	50-272 50-272
	7905220289 7905220293	50-344 50-344		7905040519 7905080481	50-311 50-311
	FTENERUSTS	VV~274		7905090308	50-311

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
				***********	
	7905220349 7905250100	50-272 50-311		7905190134 7905110153	50-312 50-312
PSIN - Public Service Co of Indiana,	7905250415 7905140097	50-311 50-546		7905010477 7905110307	50-443 50-312
Inc.	7905250433	50-546		7905020306 7905100424	50-312 50-312
	7905160400 7905310420	50-546 50-546		7905150053	50-312
PSNH - Public Bervice Co of New	7905080415 7905290083	50-546 50-443	TOED - love's Edison Co	7905290067 7905140235	50-312 50-346
Hampshire PSOK — Public Service Co of Oklahoma	7905090359			7905150405 7905290422	50-346 50-346
Of CALMIUM	7905250029	50-556 50-556		7903240671 7903240586	50-346 50-346
DGG4 Burnet Brown Brown	7905230424 7905240393	50~556 50~556		7905140233 7905100380	50-346 50-346
PSPL - Puget Sound Power & Light Co.	7905090285 7905250465	50-509 50-522		7905100341 7905100345	50-346 50-346
	7903160356 7905160347	50-522 50-522		7405220125 7405020266	50-346 50-346
	7905250459 7905310372	50-522 50-522		7905240097 7905250198	50-346 50-346
ROE - Rochester Gas & Electric Corp	7905310393 7905030359	50~522 50~244		7905100286 7905020303	50-346 50-346
	7905220227 7905220223	50-244 50-244		7905020330 7905020418	50-346 50-346
	7905250181 7905040101	50-244 50-244		7905020438	50-346
	7905040147 7905040180	50-244 50-244		7905020488 7905020500	50-346 50-346
	7905040187	50-244		7905020427 7905020443	50-346 50-346
	7905040191 7905110101	50-244 50-244		7905040129 7905040132	50-346 50-346
	7905110104 7905310431	50-244 50-244		7905090269 7905090273	50-346 50-346
	7905310435 7905230417	50-244 50-244		7905150402 7905150455	50-346 50-346
	7905070486 7905070580	50-244 50-244		7905150456 7905160404	50-346 50-346
	7905100149 7905150393	50~244 50~244		7905160409 7905220124	50-346 50-346
	7905220377 7905220031	50-244 50-244		7905220094 7905220101	50-346 50-346
	7905300474 7905310395	50-244 50-244		7905220117	50-346
SCE - Southern California Edison Co.	7905150619			7905220121 7905250134	50-346 50-346
ace - doughern California Edison Co.	7905150404 7905090326	50-206 50-206		7905250142 7905110099	50-346 50-346
	7905090361 7905150411	50-206 50-206		7905110091 7905150121	50-346 50-346
	7905310426 7905150409	50-361 50-206		7905080416 7905300418	50-346 50-346
	7905290069 7905290500	50-206 50-206		7905090353 7905190031	50-346 50-346
	7905240073 7905040586	50-206 50-206	•	7905220095 7905230371	50-346 50-346
	7903040592 7903090277	50-206 50-361		7905240403 7905290419	30-346 50-346
	7905080418 7905080425	50-206 50-206		7905310450 7905300483	50-346 50-346
	7905110134 7905110139	50-204 50-206	TU - Texas Utilities Co.	7905310375 7905140284	50-346 50-445
	7905150503 7905150512	50-204 50-204	TUGC - Terms Utilities Generating Co.	7905140226 7905140224	50-445 50-445
	7905240689	50-206		7905240196	50-445
	7905310423 7905310439	50-361 50-206		7905300761 7905290648	50-445 50-445
	7905310444 7905240395	50-206 50-206		7905210192 7905030365	50-445 50-445
	7905090325 7905150400	50-206 50-206	TVA - Tennessee Valley Authority	7905090313 7905020159	50-445 50-320
	7905170257 7905210160	50-206 50-361		7905010567 7905160460	50-290
	7903090347 7903160319	50-206 50-206		7905140497 7905140481	
	7905150374 7905110035	50~204 50~204		7905290399 7905140482	
SCEO - Bouth Carolina Electric & Gas Co.	7905230514 7905300696	50-204 50-395		7905240874 7905140363	
2022 2021 01.0001 22.0001	7905090420 7905230605	50-375 50-375		7905140473 7905140491	
	7905010493	50-395 50-395		700517071	
	7905290105 7905300692	50-395			
SDGE - Sam Diego Gas & Electric Co	7905150406 7905190150	20~504 20~504			
BMUD - Bacramento Municipal Utility	7905090085 7905100282	50-592 50-312			
Dietrict	7905110004	50-312			
	7905100293 7905100281	50-312 50-312			
	7905100430 7905110032	50-312 50-312			
	7905110039 7905220445	50-312 50-312			
	7905250434 7905250437	50-312 50-312			
	7905290004	50-312			
	7905300405 7905300409	50-312 50-312			
	7905190156 7905240710	50-312 50-312			
	7905290369	50-312			



AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET HUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
					*******
	7905140352 7905230733	50-327 50-566		7905020519 7905240181	50-280 50-280
	7905080176 7905140468	50-259 50-327		7905010484 7905010487	50-281 50-281
	7905140490 7905140458	50-390 50-327		7905010492 7905010498	50-280 50-280
	7905140495 7905140503	50-327 50-390		7905020391 7905040626	50-33e 50-338
	7905250344 7905010481	50-259 50-390		7905300734 7905040396	50-338 50-338
	7905010518 7905300745	50-390 50-259		7905040414 7905070404	50~280 50~339
	7905030343 7905300253	50-259 50-327		7905070533 7905070659	50-336 50-336
	7905040562 7905090333	50-327 50-327		7905070662 7905070530	50-338 50-338
	7905090336 7905240652	50-327 50-259		7905070656 7905080511	50-338
	7905090314 7905090316	50-259 50-259		7905240481 7905300706	50-339 50-338
	7905110191 790511022B	50-327 50-390		7905080434 7905080444	50-280 50-339
	7905110196 7905110201	50-276 50-276		7905080447 7905080449	50-338 50-338
	7905110313 7905110318	50-260 50-260		7905080452	50-338 50-339
	7905160317 7905190197	50-390 50-327		7905090297 7905110147	50-339 50-338
	7905160303 7905190217	50-327 50-390		7905110152 7905110142	50-338 50-338
	7905230562	50-327 50-327		7905110157 7905110164	50-280 50-280
	7905230569 7905230078 7905230336	50-260		7905110214 7905160418	50~339 50~339
	7905230381	50-260 50-390		7905190123 7905190119	50~280 50~280
	7905230548 7905230557	50-438 50-438		7905210258 7905210260	50-338 50-338
	7905230645 7905310362	50-327 50-260		7905210275 7905220344	50~280 50~339
	7905310363 7905310425	50-260 50-296		7905220287 7905220296	50~338 50~338
	7905310427 7905310368	50-296 50-260		7905230060 7905230071	50-338 50-338
	7905310369 7905240972	50-260 50-25		7905230341 7905230344	50~281 50~281
	7905040345 7905040500	50-553 50-327		790525014 <u>1</u> 7905250150	50~280 50~280
	7905080541 7905140270	50-518 50-553		7905250154 7905250157	50~260 50~260
	7905140272 7905140371	50-327 50-259		7905290005 7905290010	50~280 50~280
	7905110024 7905170268	50-259 50-260		7905290032 7905290404	50~280 50~339
	7905300462 7905310314	50-518 50-327		7905300017 7905300018	50-339 50-280
	7905300305 7905010475	50-327 50-259		7905300401 7905300404	50~33B 50~33B
	7905110177 7905150322	50-259 50-296		7905300408 7905300412	50~33B 50~33B
	7905230378 7905110211	50-260 50-296		7905140432 7905160437	50~338 50~338
	7905150286 7905010364	50-518 50-390		7905160444 7905160454	50~338 50~338
	7905040348 7905070420	50-390 50-327		7903160458 7905020338	50~338 50~338
	7905110228 7905090341	50-390 50-327		7905040468 7905070473	50~280 50~280
	7905110008 7905230519	50-327 50-327		7905040036 7905040126	50-280 50-338
	7905290363 7905290390	50-327 50-390		7905240407 7905040380	50~338 50~280
1000	7905290503 7905290115			7905070637 7905080441	50~280 50~339
VEPC - Virginia Electric & Power Co	7903030207 7903030209	50-338 50-338		7905070460 7905070655	50~260 50~260
	7905110088 7905040472	50-280 50-260		7905100317 7905080443	50~338 50~338
		50~280 50~280		7905190062 7905110087	50-338 50-280
		780 780		7905150270 7905210176	50-338 50-338
		338 339		7905220111 7905220142	50~404 50~280
		339 339		7905230536 7905230022	50-338 50-338
		339 338		7905250108 7905290375	50-280 50-338
		338 336		7905250132 7905290001	50~280 50-280
		281 280		7905300312 7905240342	50~280 50~338
		339 336		7905240485 7905070479	50-280 50-280
		280 338		7905070610 7905080538	20~580 20~580
		338 338		7905250092 7905040448	50-290 50-290
		33 <del>6</del> 337	•	7905040360 7905110087	50-280 50-280
		338 338		7905250108 7905290001	50-280 50-280
		380 338		7905300312 7905220142	50-280 50-280

AUTHOR			TOOGROE INDEX		3
AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NURBER
	790302038 7903040126 7903240407 7903080428 79050800438 7905190062 7903110297 7905150270 7905220111 790523032 7905230227 790529029	50~338 50~338 50~339 50~338 50~338 50~438 50~404 50~338 50~404		7905300030 7905150330 7905290500 7905290500 7905150567 7905150567 7905300399 7905310365 7905300399 79053010365	50-303 50-303 50-303 50-303 50-303 50-303 50-305 50-305 50-305 50-305
VYNP - Vermont Yankes Nuclear Power Corp.	7905090435	50-280  50-271 50-271 50-271 50-271 50-271 50-271 50-271 50-271 50-271 50-271 50-271 50-271 50-271 50-271 50-271 50-271 50-271 50-271	WWPC - Washington Water Power Co YAE - Yankes Atomic Electric Co.	7905240384 790510028 7905900028 790590003 7905150337 7905240776 790529047 790529047 7905150428 7905150428 7905150429 7905150439 7905190128 7905190128 7905190128 7905190128 7905190128 7905190128 7905190128 7905190128	50-305 50-305 50-305 50-508 50-29 50-29 50-29 50-29 50-29 50-29 50-29 50-29 50-29 50-29 50-29 50-29 50-29
HIEP - Wisconsin Electric Power Co	7705070588 7705010480 7705070455 7705070455 7905070588 7905240613 7905010470 7905010515	50-271 50-271 50-271 50-271 50-271 50-271 50-502	REBEARCH INSTITUTIONS AND LABORATORIES	7905040039 7905110317 7905070548	50-29 50-271 50-29 50-29
	7903140345 7903140342 7903020209 7903020310 7903020310 790320075 7903240519 7903240519	50-266 50-266 50-301 50-301 50-266 50-266 50-266 50-301	Argonne National Laboratory  Battelle Memorial Institute, Columbus Laboratories	7905140164 7905240886 7905090406 790509040462 7905160058 7903150099 7905110348 7905250214	50-329 71-5795 50-320
	7905100263 7905240303 7905100314 7905100315 7905300316	50-301 50-266 50-301 50-361 50-266	Battelle Memorial Institute, Pacific Northwest Laboratory	7905100126 7905150814 7905240391 7905150140 7905030015	71-6038 70-8 30-6
	7705240831 7705240611 7705240627 7705290284 7705150378 7705010489 7705010513	50-266 50-266 50-266 50-266 50-301 50-502 50-502		7905030248 7905250133 7905300523 7905130777 7905310015 7905240113	50-360
	7905020271 7905080470 7905300453 7905230463 7905150349 7905150202 790515044E 7905240397 7905310359 790500453 7905030337	50-266 50-301 50-301 50-266 30-266 30-266 50-301 50-301 50-502	Brookheven National Leboratory	7903100243 7903130196 7903130219 7903130201 7903100233 7903240320 7903160415 7903300466 79030240529 7903100021 7903240427	50-27 50-272 50-309 50-286 50-254 50-266
Mrrs - Washington Public Power Supply System	7905150381 7905070319 7905090295 7905070456 7905040388 7905240901	50-502 50-397 50-508 50-397 50-508 50-813	Environmental Policy Institute Electric Power Research Institute Frantlin Institute Research Laboratory Henford Engineering Development	7903240415 7905240389 7905240199 7905240199 7905250106 7905100165	50-290
77 77 77 77 77 WPSC - Wisconsin Public Service Corp. 7	7905090073 7905110237 7905110049 790520467 7905204619 7905010478 790510047 7905190047 7905190047 7905190117 790504037 7905090284 7905090284 790509034 7905090497 790509034 7905090497 7905090497 7905090497 7905090497 7905090497 7905090497 7905090497 7905090497 7905090497 7905090497 7905090497 7905090497 7905090497 7905100292	50-397 50-397 50-397 50-397 50-397 50-397 50-397 50-397 50-398 50-308 50-308 50-308 50-397 50-397 50-397 50-397 50-397 50-397 50-397 50-397 50-397 50-397	Laboratory  Idaho National Engineering Laboratory  Kinetic Research, Inc. Lewrence Livermore Laboratory Lovelace Biomed & Environmental Research Institute Navy, Dept. of, Naval Research Laboratory  Oak Ridge National Laboratory	7905210187 7905210164 7905210184 7905210184 790510052 7905140573 790510055 790510071 7905000444 7905100213 7905240945 790520046 790500004 790520142 790514057 7905240545 7905240545 7905240545 7905240545 7905240545	50-320



AUTHOR	ACCESSION	DOCKET	AUTHOR	ACCEBSION	DOCKET
AFFILIATION	NUMBER	NUMBER	AFFILIATION	NUMBER	NUMBER
Sandia Laboratories	7905240346 7905230788 7905140149 7905110269 7905300061	50-320 50-320		7905140032 7905240553 7905240404 7905110267	50-320 50-320

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
Commission	7905300282		**************************************	7905220445	50-320
	7905090151 7905140125	50-320 50-320		7905110209 7905160056	50~320 50~320
	7905150009	30-320		7905230220	50-320
	7705150010 7705070111			7905110224 7905110190	50-320
	7905110213	50-320		7905160114	50-320
	7905020024 7905110197	50-320 50-320		7905160119 7905160132	50-320 50-320
	7905210044	50-320		7905160088	50-320
	7905110233 7905020046	50-320 50-320		7905160147 7905220445	50-320 50-320
	7905080070			7705300054	50-320
	7905100020 7905060125	50-320 50-320		790510001 <i>6</i> 7905160038	50-320 50-320
	7905030055	50-320		7905160097 7905160194	50-320 50-320
	7905090004 7905150003			7905160107	50-320
	7905160008 7905220079	50-320		7905160113 7905300211	50-320 50-320
	7905290008			7905160072	50-320
	7905190233 7905290003	50-320 50-219		7905160154 7905160177	50-320 50-320
	7905290031	50~309		7905110200	
	7905160042 7905160059	50-320 50-320		7905110230 7905160031	50-320 50-320
	7905190127	50~320		7905160056	50-320
	7905300300 7905300577	50-320		7905160077 79051600B1	50-320 50-320
	7905140020	50-320		7905190139 7905160169	50-320 50-320
	7905300543 7905300515			7905140184	50-320
	7905150139 7905300464			7905160073 7905160257	50-320 50-320
	7905250167			7905110245	50-320
	7905150005 7905300525			7905110417 7905160076	50-320 50-320
	7905140258	50-320		7905160110	50-320
	7905090239 7905110220	50~320 50~320		7905160121 7905160134	50-320 50-320
	7705300117	50~320		7905140140 7905090253	50-320 50-320
	7905300645 7905300101	50~245 50~320		7905110246	50-320
	7905100028 7905300103	50~320		7905210189 7905110249	50-320 50-320
	7705300128	50~320		7905140101	50-320
	7905300076 7905300123	50~320 50~320		7905110179 7905110215	50-320
	7905300548	50-309		7905300345	50-320
	7905300139 7 <del>7</del> 05300094	50-320 50-320		7905300606 7905090236	50-320
	7905300120	50-320		7905160003	50-320 50-320
	7905300126 7905300115	50-320 50-320		7905160007 7905160049	50-320
	7905250195 7905300134	50~596 50~320		7905140087 7905110235	50-320 50-32
	7905300137	50-320		7905110253	50-320
	7905140175 7905300144	50-320 50-320		7905230494 7905300096	50-320
	7905300124	50~320		7905110182	80-220
	7905300107 7905300135	50-320 50-320		7905110198 7905230494	50-320
	7905100322	50-502		7905110212 7905140137	50-320 50-320
	7905366131 7905366596	50-320		7905160225	50~320
	7905300672 7905090413			7905160035 7905100012	50-320 50-320
	7905300652			7905100159	50-320
	7905020038 7905250321			7905100212 7905100218	50-320 50-320
	7905090413			7905100043 7905100049	50-320 50-251
	7905020038 7905090413			7905100051	50-320
	7905020038 7905290445			7905100061 7905100091	50-320 50-320
	7905020036			7905100136	50-320
	7905300495 7905090413			7905100176 7905100190	50-320 50-320
	7905300460			7905100181	50-320
	7903160084 7903170270	50-320 50-320		79051 <i>0</i> 0206 7905240609	50-320 50-219
	7705110243	50-320 50-320		7905160021	50-320
	7705110230 7705140171	50-320			
	7905306681 7905020038	50-309			
	7905090413				
	7905020038 7905300562				
	7905090413				
	7905020038 7905230792	50-309			
	7705110198	50-320			
	7905160142 7905160079	50-320 50-320			
	7905160144 7905160175	50-320 50-320	Dffi		
	7905140125	50-320	META		
	7905110198 7905110202	50~320 50~320			
	7905110209	50-320			
	7905160056 7 <del>9</del> 05160119	50~320 50~320			
	7905160147	50-320			

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
	7905250326 7905090225 7905090230 7905090221 7905230470 7905090256 7905140163 7905140168 7905090223 7905090223 7905090223	50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320		7905150046 7905090276 7905090267 7905100379 7905110379 7905110379 7905090270 7905090023 7905090023 7905090028 7905040170 7905110274	50~10 50~320
	7905300319 7905220434 7905220436	50-320 50-320 50-320 50-320		7905030141 7905140019 7905140250 7905030210	50~320
Office of Inspector & Auditor	7905160103 7905160086 7905150130 7905220084	50-320 50-335 50-388		7905100052 7905290262 7905190235	50-320 50-320
Office of Public Affairs	7905020163 7905230242	50-320 50-320		7905240205 7905140014	50-320
Office of Policy Evaluations	7905230470	50-320		7905230476 7905230480	50-320 50-320
	7905090237 7905090239 7905090239 7905090234 7905090234 7905090217 7905160092 7905300342 7905300350	50-320 50-320 50-320 50-320 50-320 50-320		7908230471 7908230445 79082300432 7908020162 7908020165 7908090161 7908230787 7908100090	50-320 50-320
Office of the Secretary of the Commission	7905220416 7905160102 7905100047 7905090192	50-320 50-320 50-320		7905250084 7905230572 7905240090	
	7705070174 7705140033 7703230678 7705230646 7705230661 7705230573 7705240718	50-344 50-485 50-280 50-344 50-305 50-424		7905140022 7905140071 7905140031 7905140034 7905140048 7905140021 7905140037 7905140011	50-320 50-320 50-320 50-320 50-320 50-320 50-320
	7905150260 7905240510	50-599 50-338		7905230188	
	7905250479 7905250205	50-320 50-389		7905140026 7905140012	20-320 30-320
	7905300481 7905100408 7905300613 7905230701 7905230484	50-320		7905020155 7905140013 7905140015 7905140154 7905140023 7905300725	50-320 50-320 50-320 50-320
	7905230499 7905100026	50-320		7905300376	50-320
	7905090283 7905300268 7905250063 7905100056 7905240315 7905240820 7905240358 7905240366	50-313 50-320		7904140248 7905280189 7905040201 7905040257 7905040221 7905140053 7905140165 7905140167 7905140174	50-10 50-320 50-10 50-320
	7905250331 7905090215	50-320		7740140174	
	7905250165 7905140054	50-400 50-320	ATOMIC BAFETY BOARD(B) & PANEL(B)		
Atomic Energy Commission (Pre 1975)	7903240435 7903230334 7905250539 7904300342 7905140203 7905150669	70-1921	Atomic Bafety and Licensing Appeal Panel	7905090249 7905220070 7905100067 7905240135 7905240487	50-920 50-279 50-344 50-338 50-338
	7905230204 7905230386	40-2407		7905250318 7905150710	50-498
	7905230374 7905230201 7905230348 7905230342 7905230183 7905230164	40-2407 40-2407 40-2407 40-2407 40-2407 40-2407		7905140392 7905180293 7905180542 7905180542 7905240585 7905250035 7905080163	50-920 50-929 50-920 30-277 50-989
	7903230291 7905230280 7905230270 7905230255 7905230250 7905230150 7905230177 7905230470 7905230219 7905230139 7905230132 7905230132	40-2407 40-2407 40-2407 40-2407 40-2407 40-2407 40-2407 40-2407 40-2407 40-2407	Atomic Bafety and Licensing Board Panel	7905020232 7905090178 7905300032 7905020480 7905020187 7905240105 7905230649 7905310409 7905100381 790524017 7905290114 7905290131	50-445 50-592 50-456 50-445 50-484 50-389 50-272 50-466 50-235 50-250 50-275
	7905140200 7905140187			7905100327	50-471 50-410
irectorate of	7905300325 7905300285	50-320		7905240212 7905300690 7905100412 7905230853	50-510 50-358 50-445 50-445
	7905220392	50-528		7905250208 7905290108 7905290583	50-385 50-329 50-395
n Reactor	7905090014 7905090018 7905140248			7905140030 7905290576 7905230182 7905150716	50-522 50-369 50-466

# U.S. NUCLEAR REGULATURY CUIVING SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
	7905220048 7905230466 7905150663 7905150663 7905150667 7905150760 7905150760 7905150767 7905150767 7905150767 7905150767 7905150767 7905140567 7905140567 7905140567 7905140567 7905140567 7905140567 7905140567 7905140567 7905140567 7905140567 7905140567 7905140567 7905140567 7905140567 7905140567 7905140567 7905140567 7905140567 7905140567 7905140567 790524030 790524030 790524030 790524030 790524030 790524030 790524030 790524030 790524030 790524030 790524030 790524030 790524030 790524030 790524030 790524030 790524030 790524030 790524030 790524030 790524030 790524030 790524030 790524030 790524030 790524030 790524030 790524030 790524030 790524030 790524030 790524030 790524030 790524030 790524030 790524030 790524030 790524030 790524030 790524030 790524030 790524030 790524030 790524030	70-2423 70-2423 70-2423 70-2423 50-445 50-27 50-445 50-369 50-338 50-338 50-329 50-272 50-329 50-272 50-329 50-272 50-328 50-272 50-388 50-272 50-388 50-272 50-388 50-272 50-388 50-272 50-388 50-272 50-388 50-272 50-388 50-272 50-388 50-272 50-388 50-272 50-388 50-272 50-388 50-272 50-388 50-272 50-388 50-272 50-388 50-273 50-380 50-400 50-514	Administrative Contracts Branch  Gontract Policy Branch  Purchasing Saction  Research Contracts Branch	7905300161 7905300194 7905300194 7905300207 7905300280 7905300280 7905300280 7905300280 7905300280 7905300280 7905240111 7905240180 790500169 790500169 790500169 790500169 790500169 790500177 7905140179 7905140179 7905140179 7905140179 7905140179 7905140179 790500184 790500187 790500187 790500187 790500187 790500187 7905000287 7905000287 7905000287 7905000189 7905000287 7905000189 7905000189 790500180 790500180 790500180 790500180 790500180 790500180 790500196 7905040052 7905040064 7905040064 7905040064 7905040064 7905040064 7905040064 7905040064 7905040064 7905040064 7905040064 7905240400 7905240480 7905240480 7905240480 7905240480 7905240480 7905240480 7905240480	<b>50</b> -320
OFFICE OF EXECUTIVE DIRECTOR FOR OPERATION  Office of the Executive Director for Operations			Technical Assistance Contracts Branch	7905230702 7905240443 7905240447 7905230482 7905250299 7905020449	
	7903240183 7908240183 7908100278 7908100218 790810041 790810655 7908080190 7908230533 7908240202 790802015 790820089 7908290483	70-1821 27-39 50-482 30-250 50-275		7905020477 790310059 7903100182 7903110413 7905300178 7905300698 7905240107 7905240767 7905290231 7905300228 7905300228 7905300290	
	7908240334 7908090158 7908020210 7908140291 7908190198 7908190198 7908100278 7908300105 7908300105 7908300105 7908300105 7908300085 7908300085 7908300089 7908300089 7908300089 7908300089 7908300089 7908300089 7908300089 7908300089 7908300089 7908300089 7908300089 7908300089 7908300089 7908300089	50-454  50-483  50-272  50-480  50-320  50-320  50-320  50-320  50-320  50-320  50-320  50-320  50-320  50-320  50-320  50-320  50-320  50-320	Technical Information & Document Control Division of Facilities & Operations Telecommunications Branch License Fee Management Branch	790300303 790300414 7903300247 7905230717 7905290431 790525030 7904041	•
EDO ~ OFFICE OF ADMINSTRATION	7905160052	50-320			
Office of Administration  Division of Contracts	7905140579 7905150014 7905150660 7905300118 7905140108 7905250120	70-1821 50-320			

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCEBSION NUMBER	DOCKET NUMBER
Division of Security	7903150528 7903140102 7903100045 7903100045 7903010652 7903020084 790314039 7903104057 7903104057 7903104057 7903104057 7903104057 7903104015 7903140150 7903140160 7903140160 7903140160 7903140160 7903140160 7903140160 7903140160 7903140160 7903140160 7903140160 7903140160 7903140160 7903140160 7903140160 7903140160 7903140160 7903140160 7903140160 7903140004 7903140004 7903140004 7903140004 7903140004 7903140004 7903140004	50-320 50-320 50-320 50-320 50-320 40-2407 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320	Assistant Director for Export/Import & International Safeguards	7905300359 7905300356 7905160093 7905300370 7905300365 7905300356 7905230035 7905100230 7905100230 7905300365 7905300367 7905300367 7905300367 7905300367 7905300367 7905300367 7905300367 7905300367 7905300367 7905300367 7905300367 7905300367 7905300367 7905300367 7905300367 7905300367 7905300367 7905300367 7905300367 7905300367 7905300367 7905300367	50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320
Personnel Security Branch  .  EDO - OFFICE OF INTERNATIONAL PROGRAMS	790300347 7903160063 7903160006 7903160006 7903160007 7903160007 7903160160 790316017 790316017 790316017 790316017 790316017 790316017	50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320	n	7905230846 7905230826 7905230059 7905230059 7905020134 7905020349 7905020361 7905020361 7905020361 7905020361 7905030127 7905150158 7905150162 7905230427	70-21 <b>9</b> 8
Office of International Programs	7905240001 7905240037 7905240037 7905240147 7905240013 7905220051 7905230820 7905230820 7905100415 7905100053 7905100415 7905160015 7905160010 7905160010 7905160017 7905160017 7905160017 7905160017 7905160017 7905160017 7905160017 7905160017 7905160017 7905160017 7905160017 7905160017 7905160017 7905160017 7905160017 7905160017 7905160017 7905160017 7905160017 7905160017 790516017 790516017 790516017 790516017 790516017 790516017 790516017 790516017 790516017 790516017 790516017 790516017 790516017 790516017 790516017 790516017 790516017 790516017 790516017 790516017 790516017 790516017 790516017 790516017 790516017 790516017 790516017 790516017 790516017 790516017 790516017 790516017 790516017 790516017 790516017 790516017 790516017 790516017 7905160017 7905160017 7905160017 7905160017 7905160017 7905160017 7905160017 7905160017 7905160017 7905160017 7905160017 7905160017 7905160017 7905160017 7905160017 7905160017 7905160017 7905160017 7905160017 7905160017 7905160017 7905160017 7905160017 7905160017 7905160017 7905160017	40-8695  50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320 50-320		7905020388 790502049 790502059 790502050 790502050 790502050 790502050 790502050 790502050 7905020483 7905020483 7905020483 7905020483 7905020483 7905020483 7905020483 7905020483 7905020483 7905020483 7905020483 7905190030 7905190030 7905190030 7905190030 7905190030 7905190030 7905190030 7905190030 7905190030 7905190030 790519080 790519080 790519080 790519080 790519080 790519080 790519080 790519080 790519080 790519080 790519080 790519080 790519080 790519080 790519080 790519080 790519080 790519080 790519080 790519080 790519080 790519080 790519080 790519080 790519080 790519080 790519080 790519080 790519080 790519080 790519080 790519080 790519080 790519080 790519080 790519080 790519080 790519080 790519080 790519080 790519080 790519080 790519080 790519080 790519080 790519080 790519080 790519080 790519090 790519090 790519090 790519090 790519090 790519090 790519090 790519090 790519090 790519090 790519090 790519090 790519090 790519090 790519090 790519090	



AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
	7705310028 7705100157 7705110418 7705240278 7905100226 7905100215 7905100217 7905150240	50-327 50-275 50-320 50-516 50-556 50-556 50-56 50-327 50-327	Assistant Director for Emergency Preparedness  Assistant Director for Program Development	7905090214 7905250501 7905250517 7905250444 7905300082	90-320
	7905240154 7905150059 7905250053 7905080053	50-389 50-356 50-322 50-322	OFFICE OF INSPECTION & ENFORCEMENT Division of Reactor Construction	7905230857	50-482
	7905100370 7905170162 7905100402 7905230259 7905100130	50-275 50-3 50-387 50-556 50-387	Inspection Office of Inspection & Enforcement	7905240061 7905240058 7905240065 7905240053	
Notes	7905170162 7905150059 7905100370 7905160033	50-3 50-554 50-275 50-320 50-329		7905240051 7905100375 7905240047 7905110004 7905240035	50-346 50-312
Operations & Administrative Division Rulemaking & Enforcement Division Regulations Division	7905240493 7905310028 7905100406 7905160208 7905030207	50-327 50-329 50-320 50-320 50-338		7905240025 7905240031 7905190055 7905240028	** **
Anti-Trust Division	7905100269 7905100157 7905240978 7905100269 7905100273	50-348 50-275 50-348 50-348 50-443		7904170040 7905110200 7905150245 7905010083 7905110184	50-320 50-286 50-267 50-3 50-320
	7905100386 7905230622 7905100138 7905100106 7905150216	50-445 50-250 50-445 50-395		7905110009 7905140067 7905040406 7905020230 7905020260	50-312 50-320 50-320 50-320 50-320
	7905230446 7905250129 7905150232 7905240947 7905250191	50-445 50-445 50-387 50-445 50-498		7908040294 7908040340 7908040262 7908040368 7908040388	50-320 50-320 50-320 50-133 50-528
	7905020316 7905240502 7905240967 7905250129 7905240863	50-592 50-592 50-445 50-445		7905140253 7905230198 7905300250 7905300151 7905150656	50-320 50-320 50-320 50-320 50-482
	7905230743 7905150737 7905150740 7905150748 7905300537	50-395 50-452 50-466 50-592 50-592		7905240998 7905210276 7905190057 7905190135 7905230016	50-482 50-320 50-320 50-320 50-320
	7905100125 7905240641 7905110046 7905100122 7905240133	50-466 50-568 50-255 50-437 50-592		7905210253 7905210117 7905190170 7905290171 7905220412	50-320 50-320 50-320 50-320 50-320
	7905160039 7905150748 7905300537 7905240133 7905100372	50~320 50~592 50~592 50~592 27~39		7905220450 7905230516 7905210299 7905190160 7905190170	50-320 50-320 50-320 50-320 50-320
Branch 4	7905070021 7905090182 7905090438 7905090440 7905230766	50-554 50-556 70-2623 70-2623 70-2623		7905110361 7905110187 7905210110 7905210112 7905210056	50-320 50-320 50-320 50-320 50-320
EDO - OFFICE OF MANAGEMENT & PROGRAM ANAL	7905230775	70-2623		7905300192 7905110184	50-320 50-320
Office of Management and Program Analysi		50-320		7905300112 7905210314	50-320 50-320
	7905090224 7905100253	50-320		7905110187 7905210056	50-320 50-320
	7905090216 7905190199 7905140073	50-320 50-320 50-320		7905110184 7905110187 7905210056	50-320 50-320
EDQ OFFICE OF STATE PROGRAMS	7705140073	JU-SEV		7905110184 7905110187 7905110187 7905110184 7905110187 7905110184	50-320
				7905190196 7905230041 7905210072 7905210261 7905190060	50-320 50-320 50-320 50-320 50-320
				7905210308 7905110028 7905110416 7905210091 7905110218	50-320 50-320 50-320 50-320
			Division of Fuel Facility & Materials Safety	7905110361 7905210060	90-350 90-350
	7905140325 7905250525		Division of Reactor Operations Inspections	7905110421	50-329 50-329
	7905090248 7905090254	50-320 50-320		7905110420 7905250231 7905290162	50-327 50-255
	7905360083 7905140325 7905090241 7905250516	50-320 50-320		7905110413 7905140047 7905110413 7905140047	50-320 50-320 50-320 50-320

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
				,	
	7905110413 7905140047	50-320 50-320		7905030059 7905010641	50-213 50-213
	7905110413 7905140047			7905010105	50-334
	7905110413 7905140047			7905010106 7905010042	50-412 50-334
	7905160216 7905160209	50-320 50-320		7905010297 7905020039	50-334 50-334
NRC Regional Offices	7905100445 7905150820	50-346 50-315		7905020043 7905020346	50-412 50-334
Region 1, Philadelphia: Office of the Director	7905140210	50-317		7905020398 7905040014	50-412 50-412
	7905230385 7905230732	50-320 50-277		7905040018 7905040198 7905040200	50-334 50-334 50-412
	7905230750 7 <del>9</del> 05040156 7905040153	50-277 50-367 50-367		7905010079 7905030040	50-3 50-334
	7905110113 7905290196	30-6134 50-3		7905030063 7905010643	50-412 50-334
	7905070182 7905290193	50-284 50-3		7905010645 7905220461	50-412 50-320
	7905070177 7905070158	50-284 50-272		7905210052 7905010110	50-320 50-21 <i>9</i>
	7905110036 7905070149	70-820 50-272		7905010112 7905010046	50-343 50-219
	7905100374 7905090144	30-8535 50-213		7905010298 7905020045 7905020337	50-219 50-219 50-219
	7905070210 7905090140 7905230288	50-247 50-220 70-33		7905020337 7905020393 7905040020	50-363 50-363
	7905080110 7905020140	70-33 50-286 50-289		7905040025 7905040204	50-219 50-219
	7905100493 7905110217	50-387 50-217		7905030064 7905030065	50-219 50-363
	7905110371 7905110394	50-247 50-271	•	7905010646 7905010650	50-219 50-363
	7905240784 7905240437	70-135 50-287		7905190066 7905010116	50-219 50-322
	7905240704 7905300752	50-245 50-311		7905020051 7905020395 7905040038	50-322 50-322 50-322
	7905240306 7905240673	50-244 50-322		7905040208 7905030070	50-322 50-322
	7905240684 7905290166 7905290126	50-363 50-334 50-334		7905020263 7905010118	50-322 50-289
	7905290132 7905290145	50-277 50-245		7905010047 7905010300	50-289 50-289
	7905290173 7905290120	50-244 50-277		7905210036 7905210039	50-320 50-320
	7905290137 7905290157	50-309 50-334		7905020053 7905210040	20~350 20~584
	7905150514 7905150523	50-277 50-277		7905020377 7905040040	50-289 50-289
	7905300090 7905150298 7904210770	50-320 50-343		7908040210 7908030072	50-289 50-289
	7905100422 7905290165	30-6949 30-1873		7905020275 7905210252	50~299 50~320
	7905290186	30-1973		7905210319 7905230138	50-320 50-320
	7905150727 7905010080	70-2428 50-364	•	7905230154 7905230163	50-320 50-320
	7905010082 7905010086	50-201 70-1143		7905210284 7905010119 7905010050	50-320 50-309 50-309
	7905210245 7905210046	50~320 50~333		7905010301 7905020055	50-309 50-309
	7905220414 7905010100 7905030266	50-320 50-293 50-293		7905020342 7905040046	50-309 50-309
	7905010034 7905010282	50-293 50-293		7905040211 7905030075	50~309 50-309
	7905020026 7905020357	50~293 50~293		7905020276 7905010121	50~307 50~245
	7905030326 7905040167	50-293 50-293		7905010053 7905010304 7905020061	50~245 50~336 50~336
	7905030052 7905010632	50-293 50-293		7905020061 7905020066 7905020300	50-245 50-245
	7905140208 7905010101 7905030270	50-317 50-317 50-317		7905040049 7905040059	50-336 50-245
	7905010036 7905010286	50-317 50-317		7905040214 7905040224	50-336 50-245
	7905020030 7905020389	50-317 50-317		7905020077 7905020204	50-245 50-245
	7905030328 7905040174	50-317 50-317		7905010125 7905010126 7905010055	50-410 50-220 50-220
	7905030056 7905010633	50-317 50-317		7905010367 7905020069	50-220 50-220
	7905030272 7905020350 7905030373	50~3 50~3 50~3		7905020071 7905020329	50-410 50-410
	7905040183 7905040183	50-3 50-3 50-3		7905020332 7905040068	50-220 50-410
	7905010639 7905030392	50-247 50-3		7905040071 7905040235	50-220 50-410
	7905010103 7905030276	50-213 50-213		7905040237 7905030078	50-220 50-220 50-410
	7905010040 7905010290	50-213 50-213		7905030081 7905020288	50-220
	7905020036 7905020354 7905040010	50-213 50-213 50-213		7905020292 7905010127	50-410 50-333
	7905040110	50-213		7905010129	50-286



AUTHOR AFFILIATION

	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR Affiliation	ACCESSION NUMBER	DOCKET NVMBER
			16 of 18 11 11 11 11 11 11 11 11 11 11 11 11		
	~~~~~~~~			755774555	<b></b>
	7905030279 7905010058	50-266 50-286		7905210097 7905210102	20~330 20~330
	7905010060	50-333		7905210108	50~320
	7905010310 7905010313	50-333 50-284		7905190177 7905210144	50~320 50~320
	7905020072	50-333		7905210124	50~320
	7905020075 7905020295	50-286 50-286		7905300063 7905230038	50-320 50-320
	7905020321	50-333		7705170061	50-320
	7905040074 7905040078	50-333 50-286		790530010B 7905210305	50~320 50~320
	7903040245	50-286		7905300122	30-320
	7905040249 7905030083	50-333 50-333		7905210042 7905210034	50-320 50-320
	7905030084	50-286		7905210140	50-320
	7905020296 7905020298	50-333 50-284		7905220439 7905300187	50-320 50-320
	7905010131	50-277		7905230144	30-3 <u>2</u> 0
	7905010134 7 <del>9</del> 05010065	50-352 50-277		7905230194 7905210247	50-320 50-320
	7905010315	50-277		7905210246	50-320
	7905020077 7905020082	50-352 50-277		7905210095 7905190194	50-320 50-320
	7905290116	50-277		7905210273	50-320
	7905020323 7905020372	50-277 50-352		7905210293 7905210133	50-320
	7905040083	50-352		7905150287	50-343 50-343
	7905040087 7905040259	50-277 50-277	Region 1. Philadelphia. Reactor Construction & Engineering Support Bran	7905040156	50-387
	7905040264	50-352	and the state of t	7905100433	50-387
	7905030086 7905030088	50-352 50-277		7905240673	50-322
	7905020305	50-352		79052406B4 7905290132	50-343 50-277
	7905020309 7905010136	50-277 50-387	•	7905240679	50~943
	7905020085	50-397		7905240668 7905020135	50-322 50-287
	7905020402 7905040091	50-387 50-387		7905290134	50-309
	7905040269	50-387		7905290129	50-277
	7905030093 7905020314	50-387 50-387		7905040149	50-387
	7905010138	50-272		7905100428 7905040140	50-387 50-387
	7905010140 7905010069	50-311 50-272	Region 1. Philadelphia, Fuel Facility	7905030129	50~387
			& Materials Safety Branch	7905230750	50-277
	7905010320 7905020095	50-272 50-272		7905110113	30-6134
	7905020100	50-311		7905110105 7905290196	30-6134 50-3
	7905020369 7905040093	50-311 50-311		7705070140	50-220
	7905040095	50-272		7905110102 7905110072	30-6134 30-6134
	7905040273 7905040282	50-272 50-311		7905290188	50-3
	7905140103	50-272		7905290177 7905090134	20-550 20-3
	790503009B 7905030101	50-272 50-311		7905230724	50~2フツ
	7905020317	50-272		7905230 <u>6</u> 94 7905240294	50-277 50-244
	7905020322 7905010143	50-311 50-443	Region 1, Philadelphia, Reactor Operations Nuclear Support Branch	7705070182	50-286
	7905020103	50-443	-barasana whereas onblate biaucu	7905070158	50-272
	7905020364 7905040100	50-443 50-443		7905090146	50-213
	7905040284	50~443		7905070210 7905080110	50-247 50-286
	7905030105 7905020324	50-443 50-443		7705110217	20-514
	7905010145	50-495		7905110371 7905110394	50-247 50-271
	7905010148 7905010073	50-244 50-244		7905240704	50-245
•	7905010322	50-244		7905300752 7905290166	50-311 50-336
	7905290149 7905020106	50-244 50-244		7905290124	50-334
	7905020111	50-485		7905290145 7905290173	50-245 50-244
	7905020315 7905020360	50-244 50-485		7905290120	50-277
•	7905040104 7905040109	50-485		7905290157 7905150523	50-934 50-277
	7903040109 7903040295	50-244 50-485		7905070189	80-247
	7905030108	50-244		7905110362 7905090142	50-247 50-213
	7905030110 7905020331	50-485 50-485		7905290123	50-334
7	705020335	50-244		7905290154 7905110216	50-334
	705010150	50-271		7905240430	50-217 50-289
				7908240492 7908290140	50-245
				7905290160	50~245 50~336
				7905070172	
				7905080099	50-286 50-286
				7905070161 7905150507	50-286
				7905070145	50-277 50-272
				7905300743 7905070133	50-311
				7905110368	50-272 50-271
			manyan si kurradatbura Bataquarya	7905190175	50-320
			branch	7905220092	70-135
				7905110034 7905230288	70-820
				7905240784	70-33 70-135
				7905240267 7905240277	50-225
				7905240775	50-925 70~135

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
	7905240756	70-13 <b>5</b>		7905030290	50-348
	7905220087 7905220072	70-135 70-135		7905010093 7905010339	50-348 50-348
	7905230277	70-33		7905020124	50~348
Region 2, Atlanta, Office of the	7905110029 7905250410	70-820 50-302		7905040148 7905040298	50-348 50-346
Director	7905230503			7905040322 7905030137	50-348 50-348
	7905020087 7905020439	50-269 70-143		7905010331 7905020365	50~364 50-364
	7905020442 7905290170	50-327 50-335		7905020370 7905010168	50-348 50-261
	7905290174	50-335		7905030294	50-261
	7905010421 7905010471	50-302 50-302		7905010095 7905010346	50-261 50-325
	7905020102 7905020117	50-371 50-371		7905240461 7905020125	50-324 50-261
	7905240069 7905020049	50-335 50-280		7905040163 7905040281	50-261 50-261
	7905040124 7905230237	70-27 50-324		7905040329 7905150696	50-261 50-324
•	7905230243 7905020019	50-324 50-280		7905010324	50-400
	7905020471	50-339		7905030141	50-261
	7905020161 7905020423	70-1151 50-369		7905010324 7905020373	50-403 50-324
	7905070084 7905090132	50-327 50-338		7905020426 7905010177	50-261 50-269
	7905090135 7905230747	50-338 50-566		7905010183 7905030301	50-413 50-413
	7905230753	50-566		7905030307 7905010098	50-269 50-269
	7905240307 7905230592	50-327		7905010350	コローかんタ
	7905230641	50-261 50-302		7908040176 79080401#3	50-269 50-413
	7905290138 7905090056	50-338 50-339		7905040263 7905040266	50-269 50-413
	7905150107 7905230149	50-259 50-339		7905040346 7905040381	50-413 50-269
	7905230679 7905230689	50-338 70-143		7905010335 7905010356	50-36 <del>9</del> 50-413
1	7905290392 7905290398	50-281 50-281		7905030153	50-413
	7905230153	50-387		7905030160 7905010356	50-269 50-489
	7905290717	50-338 50-369		7905020429 7905020453	50~269 50~413
	7905250110 7905090426	50-321 50-375		7905020460 7905010418	50-367 50-302
	7905150081 7905150147	50-519 50-259		7905010192 7905020404	50-302 50-302
	7905020497 7905230614	50-321 50-261		7905010102 7905010353	50-302 50-302
	7905230623	50-261		7905310017	50~302
	7905250402 7905240336	50-302 70-1151,		7905010403 7905040209	50-302 50-302
	7905241005 7905241005	50-25		7905040306 7905040395	50-302 50-302
	7905290094 7905290099	70-1113 70-1113		7905030162 7905020463	50~302 50~302
	7905240312 7905240468	70-1151 50-395		7905010195 7905030310	50~250 50~250
	7905241003 7905240480	50-25 50-124		7905010104 7905010356	50~250 50~250
	7905250431 7905240491	50-508 50-327		7905020127	50~250
	7905240527	50~346		7905040141 7905040212	50~250 50~250
	7905240518 7905240534	50-348 50-339		7705040308 7705040404	50~250 50~250
	7905290117 7905240665	50-375 . 50-324		7905030164 7905010337	50~250 50~389
	7905070101 7905240507	70-1113 50-518		7905020465	50~335
	7905240537 7905150114	50-491 70-1201		7705270150 7705010200	50-335 50-321
	7905310024 7905240509	50-302 50-424		7905030312	50~321
	7905020033	50-280		7905010107 7905010360	50-321 50-321
	7909070283	70-1151		790304021 <i>6</i> 7903040304	50-321 50-321
	7905240361 7905250020	70~143 50~400		7905040413 7905010366	50~424 50~424
	7905300021 7905300026	70-1201 50-338		7905030165 7905020467	50-321 50-321
	7905010158 7905030323	50-437 50-437		7905010204	50-416 50-416
	7908030188	50-437		7905030314 7905040223	50-416
	7905040145 7905040457	50-437 50-437		7905040312 7905040420	50-416 50-416
	7905030133 7905070137	50-437 50-160		7905010371 7905030167	50-416 50-416
	7905070153 7905070146	50~538 50-111		7905020472 7905010205	50~416 50~395
	7905070152 7905070142	50-404 50-83		7905030317 7905290112	50-395 50-395
•	7905070148 7905070138	50-62 50-124		7905030199	50-395
	7905070156	50-129		7905040225 7905040424	50-395 50-395
	7905010132 7905070159	50-332 50-13		7905010374 7905030169	50-395 50-395
	7905010137 7905240352	70-143 70-143		7905020473 7905020475	50-395 50-395
	7905140095 7905010141	50-437 50-348		7905150103 7905010211	50~259 50~259
					,

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET	AUTHOR AFFICIATION	ACCEBBION NUMBER	DOCKET NUMBER
	7905010113 7905010343 7905010349 790504048 7905030368 7905040233 7905110345 7905130700 7905010341 7905030172 7905010341	50-259 50-259 50-518 50-259 50-259 50-327 50-259 50-321 50-259 50-391		7905020049 7905290243 7905020019 7905020471 7905020421 7905010264 7905010264 7905010275 7905203972 79052010467	50-280 50-324 50-280 50-339 50-338 50-338 50-338 50-338 50-339
	7905020495 7905010224 7905030319 7905010123 7905010369	50-327 50-280 50-280 50-280 50-280		7905090056 7905150107 7905250110 7905150147 7905150259	50-337 50-257 50-321 50-257 50-250
Region 2, Atlanta, Reactor Constructi on & Engineering Support Branch	7903020133 7903080334 7903040234 7903040271 7905010317 7903030191 7903020496 790302030 790302030 790502033	50-339 50-280 50-280 50-280 50-339 50-338 50-280 50-339 50-320 50-349		7903020497 7903240490 7903240491 790324034 790324034 7903240474 7903240474 7903230229 7903230323 7903230482 7903230482	50-321 50-124 50-327 50-348 50-339 50-124 50-324 50-324 50-324 50-324 50-261 50-269
	7905020352 7905020442 7905020117 7905070338 7905070118 7905230753 7905230169 7905230169 7905230689 7905290398	50-349 50-327 50-391 50-389 50-281 50-566 50-327 50-389 50-339 70-143 50-281		7908020412 7908270707 7908270173 7908280394 7908280381 7908290167 7908180281 7908280108 790820489 7908180138 7908180138	50-349 50-349 50-349 50-302 50-305 50-325 50-321 50-321 50-375 50-327
	7905230153 7905090426 7905150081 7905230752 7905240468 7905240518 7905240517 7905240507 7905240507 7905240507 7905250020	50-387 50-395 50-491 50-491 50-508 50-518 50-491 50-491 50-424 50-348	Region 2, Atlanta, Safeguards Branch	7705020040 7705020012 7705010255 7705090051 7705020458 7705020129 7705240530 7705240530 7705020087 7705020087 7705020439 7705020439	50-280 50-280 50-338 50-339 50-339 50-339 50-320 50-269 70-143 50-335
	790580312 790580325 790520032 790520326 7905240325 7905240325 790507032 790507032 790507032 790524030 790524030	50-400 50-400 50-491 50-491 50-491 50-491 50-369 50-419 50-389 50-389 50-424 50-424		7703040124 7703070239 7703070239 77030702033 7703070283 7703300021 7703300022 7703040118 7703040103 7703040103 7703040103	70-27 70-1201 70-1201 50-280 70-1151 70-1201 50-33B 70-27 70-1201 70-27 70-1201 70-1201
	790504044 7905020435	50-395 50-327 50-391 50-566 50-327 50-390 50-518		7905300016 7905230433 7905230484 7905020417 7905020156 7905240323 7905240293 7905220146 7905070247 7905020078 790523064 790523064	70-1201 70-143 70-143 70-143 70-1151 70-1151 70-1151 70-1151 50-269 50-269 50-302
			Region 3; Chicago, Office of the Director	7905240084 7905020025 7905300023 7905110108	50-335 50-280 50-338 50-346
			,	79051101:11 7905100362 7905110093 7905110094 7905020205 790502008 790503004 7905090390 7905090390 7905030061 7905030061	50-946 50-946 50-946 50-915 50-915 50-255 50-155 50-546 50-546 50-979
				7908010334 7908070023 7908070027 7908090149 7908090175 7908010181 7908010180 7908020172 7908020470 7908020470	50-155 50-373 50-373 50-331 50-409 50-266 50-266 50-329 50-500 50-461

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET
	7905150646	70-1379		7905010397 7905030219	50-329 50-329
	7905090131 7905230308	50-282 50-341		7905030220 7905080404	50-155 50-327
	7905110047 7905150805	50-182 50-570		7905080486 7905150355	50-155 50-155
	7905230426	50-331		7905240893	50-155
	7905230442 7905150419	70-1308 50-341		7905010251 7905090155	50-409 50-409
	7905080211 7905150129	50-331 50-331		7905040027 7905010165	50-409 50-409
	7905150134 7905150163	50-331 50-156		7905010394 7905030026	50-409 50-409
	7905150436 7905150413	50-331		7905010585 7905040384	50-409 50-409
	7905150429 7905150819	50-337 50-315		7905040440 7905040553	50-409 50-409
	7905150820 7905250296	50-315 50-329		7905030222 7905080490	50~409 50~409
	7905140087 7905150535	50-275 50-358		7905240896 7905010253	50-409 50-341
	7905240734 7905240748	50-329 50-456		7905040030 7905030029	50-341 50-341
	7905240454 7905290569	50-10 50-155		7905010586 7905040387	50-341 50-341
	7905290720	50-358 50-263		7905040460 7905040556	50-341 50-341
	7905290546 7905240716	50-373	•	7905010415 7905030224	50-341 50-341
	7905150775 7905040158	50-275 50-10		7905080492 7905240898	50-341 50-341
	7905150754 7905140492	70-1308 50-10		7905010256 7905040031	50-331 50-331
	7905100162 7905040368	50-16 50-358		7905150424	50-331 50-331
	7903010197 7903020321	70-1193 50-546		7905010167 790501039B	50-331
	7905240997 7905140213			7905030031 7905010508	50-331 50-331
	7905030006 7905040456	50-315 50-315		7905040389 7905040435	50-331 50-331
	7905040522 7905030204	50-315 50-315		7905040560 7905030227	50-331 50-331
	7905310466 7905010236	50-315 50-10		7905080496	50-331
	7905030370 7905010155	50-10 50-10		7905240902 7905010257	50-331 50-461
	7905010384 7905030007	50-10 50-295		7905040035 7905030033	50-461 50-461
	7905030013	50-10		7905010590 7905040394	50-461 50-461
	7905010569	50-10		7905040459 7905040566	50-461 50-461
	7905010372 7905040334	50-295 50-10		7905010426 7905030228	50-461 50-461
	7905040527 7905040529	50-295 50-10		7905080498 7905240906	50-461 50-461
	7905010380 7905030206	50-373 50-10		7905010233 7905040037	50=315 50-315
	7905010380 7908040142	50=45\$ 50-10		7905010171 7905010404	50-315 50-315
	7905140488 7905010242	50-10 50-356		7905010592 7905170089	50-315 50-315
	7905030372 7905030017	50-358 50-358		7905030204 7905080499	50-315 50-315
	7905010574 7905040351	50-356 50-358		7905010429	50-367 50-367
	7905040452 7905040534	50-358 50-359		7905010258 7905040041	50-367 50-367
	7905010400 7905030215	50-358 50-358		7905030036 7905010593	50-367 50-367
	7905080397 7905240887	50-358 50-358		7905040398 7905040568	50-367
	7905010246 7905040021	50-440 50-440		7905070164 7905030232	50-367 50-367
	7905030019	50-440 50-440		7905080502 7905240907	50-367 50-367
	7905010576 7905040392 7905040537	50-440 50-440	•	7905010261 7905010262	50-464 50-263
	7903070170	50-440		7905040045 790504004B	50-464 50-263
	7903010394 7905030217	50-440 50-440		7905010174 7905010410	50-263 50-263
	7905080400 7905240892	50-440 50-440		7905290534 7905030040	50-262 50-263
	7903020166 7905010247	50-32 <b>7</b> 50-155		7905030047 7905010597	50-494 50-494
	7905010249 7905040026	50-327 50-155		7905010599 7905010600	50-263 50-282
	7905080529 7905010162	50-329 50-155		7905040405 7905040418	50-263 50-484
	7905010390 7905030022	50-155 50-327		7905040445	5Q~4B4
	7905030023 7905030025	50-255 50-155		7905040451 7905040576	50-243 50-243
	7905010579 7905010583	50-155 50-329		7905040587 7905010419	50-484 50-484
	7905040324 7905040328	50-255 50-155		7905030235 7905030237	50-484 50-263
	7905040331	50-329		7905080503 7905080505	50-484 50-263
	7905040465 79 <b>0</b> 5040546	50-329 50-329		7905010265 7905040051	50-546 50-546
	7905040546 7905040546 7905040560	50-327 50-255 50-155	•	7905030049 7905010402	50-544 50-546
	7905070162	80-155		114451454	<b></b>

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
	7905040425 7905040589 7905070167 7905010411	50-546 50-546 50-546 50-546	Region G. Chicago. Reactor Operations Nuclear Support Branch	7905100357 7905110094 7905080086	50-344 50-344 50-255
	7905030241 7905080507 7905010267 7905040055	50-546 50-546 50-346 50-346		7905070027 7905240729 7905090149 7905090175	50-373 50-358 50-331 50-409
	7905010176 7905010413 7905240933 7905030053	50-346 50-346 50-346 50-346		7905150134 7905150143 7905040141 7905150159 7905020202	50-331 50-156 50-274 50-156
	7905010604 7905040427 7905040591 7905070174 7905030245	50-346 50-346 50-346 50-346 50-346		7905150152 7905070020 7905140084 7905240719	50-315 50-315 50-373 50-275 50-358
	7405080509 7405010248 7405040058 7405030058	50-346 50-483 50-483 50-483		7905080084 7905010333 7905090167 7905090173	50-255 50-155 50-255 50-409
	7903010610 7905040428 7905040461 7905040395 7905010405	50-483 50-483 50-483 50-483 50-483		7905090165 7905150126 7905250266 7905110100 7905100354	50-331 50-331 50-331 50-346 50-346
	7905030249 7905080512 7905010270 7905040060 7905010181	50-483 50-483 50-266 50-266 50-266		7905110097 7905110092 7905110089 7905150113	50-346 50-346 50-346 50-346
	7703010417 7703030062 7703010613 7903040431	50-266 50-266 50-264 50-266	Region 3, Chicago, Safaguards Branch	7905110047 7905150775 7905150754 7905160488	50-192 50-295 70-1308 50-114
	7905040438 7905040598 7905030253 7905080515	50~266 50~266 50~266 50~266		7905110041 7905150744 7905150297 7905150768 7905250204	50-182 70-1308 70-1308 50-295 50-10
	7903010273 7903040065 7903010186 7903030069 7903010615	50-305 50-305 50-305 50-305 50-305	Region 4. Dallas. Office of the Director	7905010391 7905010395 7905310001 7905070209	50-313 50-313 40-7086 50-445
	7905040434 7905040443 7905040400 7905030255	50-305 50-305 50-305 50-305		7905010304 7905010308 7905010312 7905010370	50-482 50-482 50-482 50-445
	7905080519 7905010191 7905290183 7905140534 7905210057	50-305 70-8 70-1379 50-264 50-320		7905010379 7905010383 7905150561 7905150570 7905150544	50-498 50-498 50-445 50-556 50-382
Region 3, Chicago, Reactor Constructi on & Engineering Support Branch	7905190096 7905020172 7905040349 7905150805	50-320 50-329 50-461 50-590		7905150550 7905150604 7905230268 7905020128 7905150584	50-382 50-188 50-285 50-320 50-112
	7905150419 7905150436 7905250296 7905150535	50-341 50-331 50-329 50-359		7905230481 7905150581 7905150077 7905010448	50-313 50-313
	7905030054 7905240740 7905240711 7905150529 7905070009	50-373 50-456 50-373 50-358 50-358		7905020441 7905020277 7905020419 7905020436 7905140152	50-313 50-313 50-313 50-313 50-313
	7905290699 7905140107 7905290330 7905250283	50-358 50-358 50-329 50-329		7905150045 7905140088 7905040488 7905040606	50-313 50-368 50-313 50-313
	7905240549 7905240724 7905290554 7905230302 7905150410	50-329 50-329 50-155 50-341 50-341		7905070043 7905010529 7905090094 7905030245	50-313 50-313 50-313 50-313
	7905080024 7905080204 7905040347 7905290048 7905090386	50-341 50-331 50-461 50-461 50-346		7905010538 7905010554 7905080346 7905080348 7905010367	50-313 50-313 50-313 50-368 50-313
Region 3, Chicago, Fuel Facility & Haterials Safety Branch	7905140091 7905020461 7905030046	50-546 50-500 50-155		7905010283 7905010277 7905010455 7905030131	50-528 50-458 50-458 50-458
HEARLYBY DELENA GLAUFS	7905010160 7905150640 7905230420 7905230426 7905290655	50-266 70-1379 50-331 50-331 40-3392		7905040489 7905040610 7905070050 7905010443 7905090098 7905030267	50-458 50-458 50-458 50-458 50-458 50-458
	7905230437 7905150817 7905240448 7905030041 7905230412	70-1300 50-315 50-10 50-155 50-331		7705010277 7705010277 7705010457 7705030138 7705040492 7705040413	50-498 50-498 50-498 50-498 50-498
	7905110159 7905090126 7905140100 7905010142 7905150635	50-331 50-282 50-282 50-266 70-1379		7905070055 7905010441 7905090099 7905030271 7905010280	50-498 50-498 50-498 50-498 50-482
	7905100071	40~2061		7905010459	50-482

AUTHOR	ACCESSION NUMBER	POCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKE NUMBEI
AFFILIATION					
		ma .402			
	7905030104 7905040494	50-482 50-482		79053102 <i>2</i> 6 7905240394	50-45B 50-45B
	7905040617 7905070062	50-482 50-482		7905010376	50~478 50~478
	7905090100	50-482		7905030094 7905030095	50~478
	7905030273 7905010446	50-482 50-482		7905030143 7905030118	50~498 50~498
	7905010276 7905010461	50-382 50-382		7905030169	50~498
	7905030134	50-382		7905030071 7905030240	50~498 50~498
	7905040496 7905040618	50-382 50-382		7705020514 7705020505	50-478 50-498
	7905070066 7905010435	50-382 50-382		7905040391 7905240686	50~320 50~498
	7905090101	50-382 50-382			
	7905030274 7905210030	50-320		7905070185 7905310216	50~498 50~498
	7905210035 7905150083	50-320 50-298		7905240385 7905010302	50~498 50~482
	7905010451	50-298 50-298		7705030097	50-482
	7905020444			7705030099 7705030146	50~402 50~402
	7905020273 7905020415	50-278 50-278		7905030119 7905030193	50~482 50~482
	7905020420	50-278 50-278		7905030057	50~482
	7905140148 7905150046	50-278		7905030249 7905020534	50~482 50~482
	7905040557 7905040621	50-298 50-298		7905020503 7905300621	50~482 50~482
	7905070072	50-298 50-298		7903040575	50~482
	7905010530 7905090103	50-278		7903070046 7903310206	50~482 50~482
	7905030277 7905010544	50-298 50-298		7905240418 7905150541	50~482 50~382
	7905010558 7905080352	50~278 50~278		7905030113	50-362
	7905010375	50-278		7905030102 7905030147	50-382 50-382
*	7905150065 7905010453	50~285 50~285		7905030122 7905030197	50-362 50-382
	7905020440 7905020268	50~285 50~285		7905030066 7905030250	50-382 50-382
	7905020413	50~285		7905020524	50~382
	7905020434 7905140146	20~283 20~283		7905020511 7905040579	50~362 50~382
	7905150049 7905040486	50~285 50~285		7905070188 7905310222	50-362 50-362
	7905040623	50-285		7905240374	50~3B2
	7905070073 7905010533	50-285 50-285		7903130364 7903070191	50-556 50-445
	7905090104 7905030280	50-285 50-285		7905010345 7905150556	50-445 50-445
	7905010546	50~285		7905030085	50-445
	7905010559 7905080354	50~205 50~285		7905030107 7905030151	50-445 50-445
	7905010401 7905010287	50~265 50~133		7905030124 7905030201	50-445 50-445
	7905010289	50~344 50~267		7905030076	50-445
	7905150086 7905010454	50-267		7905030254 7905020514	50-445 50-445
	7905020446 7905020279	50~267 50~267		7903020308 7903040380	50-445 50-445
	7905020411 7905020431	50~267 50~267		7905290631	50-445
	7905140143	50-267		7905070193	50-445
	7905150051 7905040498	50~267 50~267		7905310230 7905240399	80-445 80-445
	7905040627 7905070077	50~267 50~267	Region 4, Dallas, Fuel Facility & Materials Bafety Branch	7905230693	
	7905010535	50-267		7905100266	50-267
	7905090106	80-267	Region 4: Dallas, Reactor Operations	7905240451 7905010395	50-313 50-313
	7905030282 7905080355	50~267 50~267	Nuclear Hupport Branch	7905150310	50-285
	7905010406 7905010292	50~267 50~206		7905150604 7905230268	50-188 50-285
	7905010548	50-267		7905150584	50-112
	7905010291 7905010281	50~312 50~445		7905150596 7905150578	50-188 50-112
	7905010464 7905030140	50-445 50-445		7905010655 7905010385	50-72 50-913
	7905040501	50-445		7905020325	50-368
	7905040629 7905070080	50~445 50~445		7905130117 7905040106	50-313 50-313
	7905010440 7905090108	50~445 50~445		7905150253 790503000B	50-313 50-313
	7905030283	50~445		7905150096	50-313 50-298
Region 4. Dallas, Reactor Construction	7905010294 7905010395	50-397 50-313		7905020122 7905150120	50-278
& Engineering Support Branch	7905010312	50~492		7905040110 7905150258	50-278 50-278
	7905010383 7905150561	50~478		7905150097 7905240445	50-278 50-278
	7705030089	50~445 50~458		7905150306	50-285
	7905030091 7905030139	50~458 50~458		7905150122 7905040112	50-265 50-265
	7905030117 7905030186	50~458		7905180261 7905230257	50-265 50-265
	7905030073	50~458 50~458		7905150100	50-265
	7905030238 7905020528	50~458 50~458		7905240440 7905010354	50-285 50-247
	7905020499 7905040584	50~45B 50~45B		7905100241 7905150110	50-247 50-247
	7905070180	30-458 30-458		7905040115	50-267

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCEBBION NUMBER	DOCKET NUMBER
	7905150223	50-267		7905030293	50-344
	7905150795 7905150102	50-267 50-267		7905020529 7905010422	50-344 50-344
Region 4: Dalles: Vendor Inspection	7905240428 7905030150	50-267		7905080369	50-344 50-344
Branch	7905100360			7905010445 7905010458	50-344 50-344
	7905100366			7905090039 7905090054	50-344 50-344
	7905290104 7905290113			7905090116 7905070028	50-344 50-344
	7905110404			7905070010 7905010053	50-344 50-344
	7905150505 7905100413			7905010220 7905010431	50-204 50-206
	7905100418 7905150797			7903150064 7905150170	50~206 50~206
	7905230587 7905230593			7905040128 7905150145	50-206 50-206
	7905030144 7905100410			7905010020 7905010025	50-204 50-341
	7905100356 7905100343			7905030024 7905040511	50~204 50~204
	7905290097 7905290085			7905040512	50-361
	7905150792 79052305B1			7905040619 7905070104	50~204 50~204
Region 5: San Francisco: Office of the	7905110398	50-312		7903030296 7903030299	50-341 50-204
Director	7905020520	50-142		7905020532 7903010434	50~206 50~206
	7905150620	50-528		7905080371 7905010449	20~509 20~509
	7905150701 7905230664	70-1257 50-323		7903010462 7903090041	50~204 50~204
	7905230640 7905040366	50-275 50-344		7905090057 7905310012	50-206 50-361
	7905290152 7905010228	50-275 70-1257		7905090119 7905070031	50-206 50-206
	7905010234 7905010230	70-734 70-754	b	7905070012	50-206
	7905010239 7905040076	70-25 50-526		7905310044 7905010222	50-206 50-312
	7905150057 7905150165	50-528 50-528		7905010433 7905150065	50-312 50-312
	7905040121 7905150136	50-528 50-528		7905150171 7905040130	50-312 50-312
	7905010014 7905030050	50-528 50-528		7905010013 7905030028	50-312 50-312
	7905040507	30-528		7905040515 7905040622	50-312 50-312
	7905040614 7905070098	50-528 50-528		7905070108	50-312
	7905030286 7905020525	50-528 50-528		7905030300 7905020535	50-312 50-312
	7905010420 7905080345	50-528 50-528		7905010437 7905080374	80-312 50-312
	7905010442	50-528		7905010450	50-312
	7905010454 7905070038	50-528 50-528		7905010460 7905090045	50-312 50-312
	7905090053 7 <del>9</del> 05090115	50-528 50-528		790509005B 7905090120	50-312 50-312
	7905070025 7905040355	50-528 50-528		7905070033 7905070015	80-312 50-312
	7905310059 7905040081	50-528 50-133		7905310050 7905150069	50-312 50-397
	7905010216 7905010423	50-133 50-133		7905150173 7905040134	50-397 50-397
	7905150040 7905150167	50-133 50-133		7905150150 7905010015	50~397 50~397
	7905040123	50-133		7908030018 7908040816	50-397 50-397
	7905150141 7905010023	50-133 50-133		7905040625 7905070110	50-397 50-397
	7905030045 7905040508	50-133 50-133		7905030305 7905020536	50-377 50-377
	7905040509 7905070099	50-275 50-133		7905010439	50-397
	7903030298 7903030291	50-133 50-275		7905060376 7905010452	50-397 50-397
	7905020527 7905010425	50-133 50-133		7905010463 7905090047	50-397 50-397
	7905080346 7905080348	50-275 50-133		7905090059 7905090121	50-397 50-397
	7905010444 7904300484	50-133 50-320		7905070034 7905070018	50-460 50-460
	7905020227 7905020254	50-133 50-275		7905310037 7905240657	50-397 50-460
	7905090005 7905040359	50-133 50-320		7905010225 7905300352	70-984 50-320
	7905070007 7905170072	50-133 50-133	Region 5. Man Francisco. Reactor Construction & Engineering Support Branc	7905150620	50-520
	7905240651 7905040086	50-275 50-344	Region 5, Sam Francisco, Fuel Facility & Materials Bafety Branch	7903150409	50-528 50-142
	7905010218 7905010428	50-344 50-344	ன சடைகை இறைக்கி விகுது விகுது இது இது இது இது இது இது இது இது இது	7905150701	70-1257
	7905150062 7905150168	50-344 50-344		7905230664 7905240768	50-323 50-275
	7905040125 7905150142	50-344 50-344		7903040366 7903020513	50-344 50-142
	7905010027 7905030030	50-344 50-344		7905150686	70-1257
	7905040497 7905040616	50-344 50-344		7905230656 7905240747	50-323 50-275
	7905070102	50-344		7905040362 7905110086	50-344 50-312

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
Region 5, San Francisco, Reactor				7905240382	71-65
Operations Nuclear Support Branch	7905230640	50-275		7905020384 7905150149	71-213 71- <b>71</b>
	7905150539	50-312		7905110075	71-111 71-216
	7905290152 7905230617	50-275 50-275		7905020384 7905150178	71-166
	7905290147	50-275		7905150682	71-43 71-175
	7905110083 7905150533	50-312 50-312		7905020394 7905150205	71-168
Region 5, San Francisco, Safeguards	7905110044 7905150289	50-312 70-1257		7905240161 7905150574	71-143 71-9010
Branch				7905100340	71-215
Office of IME, Executive Officer for	7905100048 7905100022	70-734 50-320		7905150742 7905150169	71-126 71-189
Management & Amalysis				7905070279	71-103 71-131
Office of 1 & E Executive Officer for Operations Support	7905160201	50-320		7905140119 7905250066	71-234
				7905020193 7905240327	71-226 71-6697
OFFICE OF NUCLEAR MATERIAL SAFETY & SAFEQUA				7905070220	71-277
Office of Nuclear Material Safety &	7905100240			7905110081 7905170278	71-128 71-1
Safeguards				7905110199	71-260 71-2
	7905080082 7905020180	71-6698		7905240041 7904200311	71-110
	7905240404			7905070047	71-6058 71-86
	7905240413 7905310152	70-2423		7905020407 7905020198	71-34
	7905110172 7905080081	27-34		7905070075 7905070302	71-6144 71-6272
	7905310152	70-2423		7905240036	71-6400 71-6679
	7905160020 7905020176	50-320 71-6698		7905250305 7905110069	71-72
Division of Fuel Cycle & Material Safety	7905240658	40-8698 70-135		7905290041 7905070287	71-9009 71-130
	7905080027 7905220028	70-1318		7905070292	71-104
	7905290480 7905310132	40-2259 70-2623		7905240112 7905230847	71-6244 71-5805
Assistant Director for Fuel Cycle	7705080087	,,		7905110095	71-181 71-38
Safety & Licensing	7905080101			7905150329 7905150333	71-30
fuel frocess & Fab. Branch	7905300491 7905100044	40-8102 40-2061		7905240017 7905070272	71-4986 71-99
	7903090003	40-8027		7905240565	71-70 71-214
	7905290479 7905090265	40-8027 70-143		7905110967 7905240017	71-4984
	7905220029	40-8663 40-2259		7905290041 7905240327	71-9009 71-6697
	79052501 <i>76</i> 7905240592	40-8681		7905020376	71-220
	7905240080 7905250047	70-1319 40-8035		7905020399 7905020392	71-178 71-180
	7905090008	40-8027		7905100079	71-9079 71-24
Fuel Reprocess & Recycle Branch	7905150634 7905240383	40-8721 70-1308		7905240046 7905110063	71-156
, 200 (11)	7905290282	50-201 70-1309		7905100352 7905070257	71-257 71-519
	7905240370 7905090164	70-2623		7405150176	71-48
	7905290090 7905090139	50-269 70-2623		7905110045 7905240244	71-209 71-9070
	7905030035	50-201		7905150167 7905150318	71-168 71-50
	7905230704 7905250338	50-364		7905150223	71~50
	7903110258 7903160029	50-320 50-320		7905070282 7905240109	71-127 71-5364
Radioisotopes Licensing Branch (Pre	7905230193	40-2407		7903240156	71~121 71~6400
790501)	7905230177	40-2407		7905240036 7905240638	71-216
	7905230160 7905230145	40-2407 40-2407		7905110071 7905250227	71-74 71-217
	7705110142			7905110084	71-141 71-223
	7905110144 7905110171	50~320 50~320		7905240291 7905250219	71~4058
	7905220039	40-2259 40-2259		7905241000 7905250219	71-109 71-4058
	79052408 <b>4</b> 9 7905110160	50-320		7905020183	71~6
	7905110156 7905110174	50~320 50~320		7905240974 7905100347	71~241 71~255
	7905250011	40~2259		7905240140	71-39 71-6400
	7905240855 7905150806	40~8663 40~8502		7905240036 7905290096	71-251
	7905250012	40-8714 40-8681	•	7905100167 7905100342	71-238 71-235
Transportation Branch	7905310088 7905240569	71-70		7905020191	71-237
•	7905070081 7905070307	71-6144 71-6272		7905020196 7905070267	71-225 71-89
	7905070295	71-6771		7905100339 7905100448	71-268 71-273
	7905240020 7905240039	71 <b>-49</b> 登台 71 <b>-640</b> 0		7905110204	71-87
	7905250314 7905250226	71-6679 71-6058		7905110210 7905290255	71-114 71-261
	7903240845	71-264		7905230691	71~5790 71~9852
	7905240854 7905250344	71~8 71~6386		7905020170 7905080180	71-5957
	7905240318	71~6B		7905240128	71-6273 71-9506
	7905240839 7905290046	71-169 71-9009		7905240099 7905250341	71-6396
	7905240331 7905300434	71-6697 50-320		7905150574 7905290041	71~9009
	7905150739	71-47		7905240327	71-6697
	7905290318 7905150160	71- <b>287</b> 71-66		7905079973 7905070047	71-6058
	7905110078	71-120		7905070075 7905070302	71-6144
	7905010105 7905010169	71-162 71-167		7905070290	

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
	700500000	74.4744		7905150093	
	7905090009 7905250305	71-6744 71-6679		7905250025	50-331 50-434
	7905090089 7905240847	71-6744 71-8		7905240201 7905240455	50-424 50-280
	7905070290 7905240835	71-6771 71-266		7905080137 7905030027	
	7905240834	71-169		7905030157 7905240791	50-546
	7905150723 7905240017	71-296 71-4986		7905070450	50-272
	7905240311 7905070047	71-69 71-6058		7905220045 7905220024	50-447 50-263
	7905160053	71-5795		7905090144 7905300751	50~363 50~280
	7905070302 7905250305	71-6272 71-6679		7905020523	50-10
	7905250219 7905070290	71-605B 71-6771		7905250275 7905150075	50-335 50-424
	7905090089 7905240165	71~6744 71~77		7905150307 7905240850	50-331 50-456
Anti-back Diseases devillante Managemen	7905300433	50-320		7905020410 7905240189	50~443 50~280
Assistant Director for Waste Management (Pre 790501)				7905310033	50-280
	7905150616 7905150613	40-6659 40-299		7905300667 7905300216	50-322 50-320
	7905150624 7905140035	40-8584 50-320		7905300430 7905110271	50~320 50~320
Low Level Waste Branch (Pre 790501)	7905250232	27-47		7905210086	50~320
	7905160036 7905230771	50-320 70-1193		7905230053 7905230097	50-320 50-320
	7905240146 7905240139	70-1193 70-1193		7905140038 7905110138	50-320 50-320
	7905230756	70-1193 70-2838		7905110322 7905210263	50-320 50-320
	7905240180 7905070141			7905230002	50~320
	7905020041 7905240188	50-320 70-2939		7905210069 7905190114	50-320 50-320
Material Control Licensing Branch	7905020530 7905250184	70-364 70-1201		7905140051 7905190118	50~320 50~320
	7905300680 7905240222	70-754 70-1113		7905110251 7905190081	50-320 50-320
	7905140141	70-143		7905210049	50-320
	7905150135 7905230798	50-143 70-371		7905210323 7905080144	50-320
Physical Security Licensing Branch	7905230852 7905300583	70-1151 70-135		7905230278 7905190082	50-320 50-320
• • • • • • • • • • • • • • • • • • • •	7905300051 7905230844	70-1173 70-143		7905300259	50-320
	7905220032	70-820		7905230053 7905110296	50-320 50-320
Uranium Recovery Licensing Branch	7905240938 7905240496	70-2623		7905230086 7905230278	50-320 50-320
	7905250022 7905240398	40-8698		7905110295 7904270152	50-320 50-320
				7905230265 7905110126	50-320
OFFICE OF NUCLEAR REACTOR REGULATION				7905070005	50-320 50-320
Office of Nuclear Reactor Regulation	7905080031			7905230299 7905140051	50-320 50-320
	7905090093 7905020430	50-348 50-443		7905230278 7905080144	50-320
	7905100035 7905070347	30-336		7905190082 7905080144	50-320
	7905090117 7905300288	50-320		7905190082	50-320
	7905140046	50-320		7905230053 7905230094	50-320 50-320
	7905100140 7905300403	50-338 50-320		7905110151 7905230281	50-320 50-320
	7905140526 7905140529	50-266 50-266		7905140051 7905110064	50-320
	7905240204 7905070277	50-260 50-335		7905250322	
	7905090071	20-566		7905070005 7905300400	50-320
	7905250187 7905150111	50-293 50-267		7905300656 7905230035	50-322 50-320
	7905070127 7905250085	50-261 50-313		7905090280 7905230273	50-313 50-320
	7905240813 7905250027	50-546 50-331	Antitrust & Indomnity Group	7905110194 7905140281	50-320
	7905250439 7905150080	50-331	tines and an elizabilities alone	7905190171	50-72 50-30
	7905240211	50-424 50-424		7905150308 7905150302	50-18 70-754
	7905290559 7905020163	50-289 50-320		7905160297 7905150363	50-131 50-124
	7905090208 7905240329	50-244 50-292		7905190049	50-193
	7905310190 7905020128	50~267 50~320		7905220354 7905240675	50-267 50-406
	7905220030	50-263		7905030154 7905160276	50-445 50-146
	7905220033 7905250005	50-263 50-317		7905150375 7905160122	50-262 50-77
	790529001 <i>6</i> 7905110003	50-245 50-298		7905160238	50-208
	7905290060 7905110016	50-305 50-376		7905300038 7905160222	50-97 50-394
•	7905110279	50-320		7905300045 7905160106	50-160 50-166
	7905240461 7905230206	50-280 50-320		7905160334 7905160282	50-284 50-188
	7905300278 7905300295			7905150386	50-141
	7905190254 7905300716	50-320 50-275		7905160268 7905150377	50~223 50~199
	7905040003			7905160232 7905160240	50-538 50-274
	7905040343 7905150071	50-363 50-363		7905160189 7905160322	50-241 50-20
	7905140027	50-320		7905160326	50-104

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
	7905160117	50-150			
	7905160328	50-5		7905160298 7905160187	50-133
	7905160258 7905160265	50-182 50-288		7905160199	50-344 50-334
	7905160266	50-225		7905160176 7905150367	30-267
	7905160332	50-57		7903140186	50-272 50-244
	7905160254 7905160343	50~404 50~59		7905160314	50-204
	7905160203	50-113		7905310373 7905160193	50-361 50-395
	7905300052 7905160221	50-84 50-326		7905160243	50-312
	7905160235	50-142		7905160231 7905140462	50-344 50-259
	7905160219 7905160167	50-433 50-83		7905160230	50~327
	7705150370	50-151		7905140444 7905140523	50-280 50-338
	7905160160	50-146		7905160215	50-271
	7905150376 7905160341	50-166 50-166		7905140431 7905160273	50~266 50~305
	7905160336	50-123		7905140285	50-29
	7905160339 7905300069	50-184 50-8		7905300065 7905160233	50-6 50-360
	7905160329	50-252	Program Support Branch	7905110121	80~320
	7905140236 7905140260	50-112 50-173		7905110140	50-320
	7905160355	50-192	Technical Section	7905110119 7905100335	50-320 50-320
	7905230456 7905300034	50-62 50-72	Division of Site Safety & Environmental Analysis	7905240219	50-424
	7905160192	50-139	aniar data	7905160129	50-320
	7705160306 770516030B	50-154 50-124		7903240955	50-313
	7905160205	50-134		7905230591 7905020390	50-463 50-596
	7905140300 7905140207	50-27 50-127		7904170363	
	7905150373	50-127 50-170		7904130020 7905230141	50-320
	7905160100	50-131		7905230152	50-320
	7905300059 7905160116	50-32 70-364		7904130020 7905190107	50-320
	7703140148	70-824	Assistant Director for Site Analysis	7905020128	50-320
	7905300714 7905160357	50~13 50~264		7905100054 7905230118	50-320 50-320
	7905160123	70-1257		7905230165	50-320
	7905300202 7905160151	50-37 70-754		7903190226 7903210012	50-320 50-320
	7905300190	50-18		7905230130	50-320
	7905160311 7905160345	50-201 50-187		7905140287	50-524
	7905160320	50-94		7905150119 7905230178	50-320
	7905160348 7905160108	50-54 70-1143		7905190247	50-320 50-320
	7903160249	50-87		7905230029 7905230116	50-320 50-320
	7905160351 7905160311	50-22 50-201		7905230023	50-320
	7905160311	50-47		7905230029 7905230032	50-320 50-320
	7705160244	50-274		7905230040	50-320
	7905160280 7905160281	50-30 50-184		7905230116 7905230023	50-320 50-320
	7905160224	50-348		7705230029	50-320
	7905140489 7905160180	50-313 50-293		7905230126 7905230032	50-320 50-320
	7905140499	50-317		7905230040	50-320
	7905140275 7905140404	50-331 50-10		7903230178 7905230032	50-320 50-320
	7905140456	50~254		7905230040	50-320
	7903140470 7903140546	50-275 50-373		7905230023 7905230178	50-320 50-320
	7905140407	50-3	Effluent Treatment Systems Branch	7905230105	50-320
	7905160272 7905160275	50-358 50-331		7905230293 7905230074	50-320 50-320
	7905230632	50-329		7905230143	50-320
	7905160172 7905160291	50-255 50-155		7905230054 7905230074	50-320 50-320
	7905140508	50-324		7905210230	
	7905160193 7905160272	50-261 50-358		7905230143 7905230157	
	7905160289	50-213		7905230056	
	7905160157 7905160353	53-407 50-16		7905230074 790	
	7905160199	50-334	Assistant Director for Environmental		
	7905140415 7905140438	50-171 50-269	Projects Environmental Projects Branch 1		
	7905140438 7905140538	50-349	WATLOUWSMENT LLOTACER REGUCU ;		
	7905160272 7905160252	50-358			
	7905140449	50-302 50-250			
	7905160198	50-335			
	7705140493 7705160275	50-321 50-331			
	7705140456	50-254			
	7905140481 7905140486	50-315 50-289			
	7905160292	50-219			
	7905140486 7905160273	50-289 50-305	Environmental Projects Branch 2		
	7905150360	50-309			
	7905140422 7905160286	50-245 50-220			
	7905150365	50-298			
	7905140477	50-282			
	7905140170 7905140199	50-243 50-334			
	7905160164	50-285			
	7905160162 7905140415	50-333 50-171			
	7905140512	50-275	Geosciences Branch		

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
Cost Benefit Analysis Branch Division of Operating Reactors	7905100093 7905100338 7905230175	50-553 50-320 50-320	Reactor Safeguards Licensing Branch Assistant Director for Systems & Projects	7905240846 7905140520	50-259 50-266
graden de graden, no estado	7905030212 7905100054 7905070014 7905230849	50-320 50-320 50-295		7905110193 7905100073 7905150179 7905150808	50-320 50-280
	7905240990 7905230128 7905230125	50-320 50-320	Flant Systems Branch	7905140112 7905110130 7905110133	50-320 50-320 50-320
	7905230135 7905100158	50-320 50-280		7905150798 7905240253	50-335 50-334
	7905070017 7905140287 7905150119	50-309 50-524		7905040150 7905240471 7905090168	50-219 50-305
	7905230123 7905190194	50-320 50-320		7905240302 7905240421	50-206 50-10
	7905230081 7905230085 7905110114	50-320 50-320 50-312	Georgean Berger	7905240731 7905300718	50-255
	7905230801 7905210073	50-312	Operating Reactors Branch 1	7905070315 7905040309 7905070114	50-286 50-261
	7905110050 7905110180	50-312 50-312		7905070119 7905070124	50-250 50-250 50-250
	7905230081 7905230085	50-320 50-320		7905250435 7905140533	50-295 50-266
	7905080347 7905110050	50-280 50-312		7905240905 7905240911	50-305 50-305
	7905110180 7905080347	50-312 50-280		7905090068 7905090076	50-266 50-266
	7905090286 7905230081	50-313 50-320		7905250183 7905250190	50-295 50-295
	7905230085 7905150174	50-320 50-313		7905240378 7905240382	50-305 50-305
	7905210055 7905290552	50-320 50-276		7905070125 7905070130	50-261 50-261
Assistant Director for Engineers & Projects	7905090171			7905090080 7905090084	50-348 50-348
	7905080239 7905110231	50-271 50-320		7905100442 7905100446	50-266 50-266
Engineering Branch	7905230523 7905110117	50-320 50-312		7905240322 7905240333	50~282 50~282
Environmental Evaluation Branch	7905110123 7905230326	50-320 50-320		7905290054 7905290064	50~305 50~305
	7904260292 7905300255 7905230326	50~320 50~320 50~320		7905250432 7905250440	50-295 50-295
Operating Reactors Branch 3	7905090186 7905090189	50-320 50-331 50-366		7905230556 7905090079	50-286 50-348
	7905090199 7905090201	50-331 50-331		7905250425 7905040307	20-591 20-542
	7905110002 7905110005	50-278 50-278		7903070121 7903070109	50-261 50-250
	7905080141 7905300598	50-237 50-271		7905240308 7905070311	20-589 20-585
	7905030047 7905150108	50-10 50-324		7905140513 7905090065	20-544 20-544
	7905090183 7905150089	50-366 50-321		7905100439 7905240895 7905240373	50-266 50-305 50-305
	7905090194 7905110001	50-331 50-298		7905290050 7905020490	50-305 50-272
	7905080246 7905110023 7905240102	50-333		7905300010 7905290723	50-280 50-334
	7905230620 7905150822	50-325 50-325		790511005B 7905310402	50-250 50-261
Operating Reactors Branch 4	7905250018 7905250021	50-269 50-269		7905240229 7905150789	50-247 50-280
	7905070337 7905070351	50-336 50-336	Manadalan Manadana a	7905310472 7905290405	50-280 50-280
	7905070236 7905070299	50-335 50-335	Operating Reactors Branch 2	7905080069 7905080073	50-250 50-250
	7905250079 7905250090	50-313 50-313		7905080080 7905080382	50-250 50-245
	7908250003 7905250007	50-317 50-317		7905020450 7905020457 7905150707	50-204 50-204 50-155
	7905250055 7905250058	50-313 50-313		7905150715 7905090207	50-155 50-155 50-244
	7903230063 7903070011 7903240819	50-313 50-309		7905090263 7905300731	50-244 50-245
	7905090279 7905150772	50-309 50-77 50-128		7905290012 7905290019	50-245 50-245
•	790523083 <u>6</u> 7905090300	50-128 50-313		7905090160 7905080570	50-245 50-237
	7905250074 7905250049	50-313 50-313		7905080337 7905080339	50-10 50-237
	7905080123 7905150372	50-317 50-317		7905150648 7905090029	50-155 50-255
	7905250002 7905250014	50-317 50-269		7905240271 7905230602	50-155 50-255
	7905080130 7905240982	50-269 50-269		7905080158 7905250343 7805180488	50-255 50-255
	7903090200 7903070231	50-302 50-335		7905150489 7905090014 7905230599	50-155 50-213 50-409
	7905150278 7905250263	50-335 50-335		7905100132 7905290074	50-409 50-409
	7905290556 7905070332 7905030158	50-267 50-336		7905080063 7905100321	50-250 50-219
	7905030155 7905100330 7905070373	50-309 50-312 50-309		7905090024 7905080381	50-219 50-245
•	7905240367	50-307		7905080343 7905300729	50-245 50-245

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCEBBION NUMBER	DOCKET NUMBER
	7905290007	50~245	Light Water Reactors Branch 3	7905080114 7905300616	50-592
	7905030126 7905090026	50-244 50-244		7908040260	59-373
	7905020351 7905020363	50-244 50-29		7905100069 7905300372	50-476 50-476
	7905090205	50-244		7905250240 7903290044	50-548 50-074
	7905020449 7905090020	50-206 50-206		7905310444	50-576
	7903020219 7908090022	50~206 50~29		7905150794 7905300594	50-367 50-311
	7905110128	50-320		7903240226 7903300376	50-311 50-436
	7905150154 79051001 <b>74</b>	50~409		7905310461	50-499
	7905100324 7905100239	50~409 50~155		7905240218 7905020459	56~572 50-338
	7905250040	50-29		790524021 <b>8</b> 7905090180	50~572 5 <b>6~3</b> 72
Reactor Safety Branch	7905250097 7905030257	50-10		7905100224	90-367
Systematic Evaluation Programs Branch	7905290523 7905110154			7905230858 7905240804	50-462 50-367
	7905110196	50-320		7905290021 7905240869	50~973 50~496
Division of Project Management	7905110135 7905230582	50-320 50-275		7905230731	50-482
	79053003 <i>92</i> 7905180118	50-424 50-275	OFFICE OF NUCLEAR REACTOR REGULATION		
	7905240676 7905070452	50-532 50-495	Light Water Reactors Branch 4	7903100435	50-413 50-446
	7905140516	50-382		7903090299 7903100112	50~982
	7905230837 7905240662	50-594 50-344	•	790 <i>5070665</i> 7905150649	90-554 50-327
	7905290006	50-27		7905090304	50-336
	7905100325 7905210238	50-275 50-320		7905230795 7 <del>9</del> 05290415	50~997 50~329
	790511035B 79051003B4	50-320 50-320		7905130607 7905100171	96-377 50-546
	7905010664	50-576		7905100220	50-390
	7905240130 7905190252	50-920	Assistant Director for Quality Assurance & Operations	7905020493	
	790521023 <i>0</i> 790519025 <i>2</i>	90-320 50-320	Operator Licensing Branch	7903626482 7905306289	
	7905210238	80-320	பிக்கிடங்கள் Presidenta வி.கம்கம	7903140117	50-366
	7905300394 7905300381	50-320 50-320		7905300180 7905240166	90~252
Assistant Director for Light Water	7905190252 7905290015	30~3⊠Q		7905250204 7905070070	50~5047 56~566
Marianalle hisarens, in mikus wasan		E0 407	Quality Assurance Branch	7905070643 7905240979	50-213
	7905020420 7905230840	50~437 50~368		7905240337	
	7809050087 7905020424	50-457 50-440		7905070440 7905240411	#0~813 #0~8 <del>7</del> 7
	7905020437	50~45G 50~4BR		7905070553 7905100378	90~99 50~344
	7905020432 7905020406	50-362		7905250122	
	7905020400 7905020445	50-347 50-544	Advanced Reactors Branch	7905230207 7905310171	50~320 50~267
	7905020452 7905250126	50~554 50~522		7905310166 7905310160	<del>50-34</del> 7 50-267
	7905020414	50-395		7905300210	50-247 50-390
	7905160112 7905110143	50-320		79042 <i>7039</i> 9 7905010179	50-267
	7905110158 7905100395	50~320 50~320	Standardization Branch	790510 <i>0</i> 277 79051 <b>00</b> 117	50-964
	7905100392	50-320	Division of Systems Safety	7904246392 7905230070	50-580
	7905100390 7905100389	50-320 50-320		7905190172	50-320
	7905100388 7905080278	50-320		7905220455 7905210295	50-320 50-320
	7905090171 7905090217			79052300 <del>88</del> 7905230122	20-350
	7905060230				
	7905080259 7905160185	50-320			
	7905010156 7905080230	50-320			
	7903110414				
Light Water Reactors Branch 1	7905000217 7905090294				
Cities Market Manager and Market Street	7905230024	50-522			
	7903090290 7905250049	50-313			
	7905240372 7905290528	50-358 50-341			
	7905310083 7905100431	50~341 50~416			
	7905070674	50~275			
	7905230578 7905240 <del>8</del> 57	50~275 50~522			
	7905150430 7905010459	50~341 50~356			
	7903100258	50-322			
	7905230558 7905240359	50-322 50-370			
Light Water Reactors Branch #	7905150641 7905240977	50-556			
FIRE MEREL GERRERENT BLEUEU W	7905250050	W. A.			
	7903240934 7903140040	50-880 50-448	Structurel Engineering Branch		
	7905230484 7905230589	50-398 50-361	Assistant Director for Plant 84		
	7905240108	50-437			
	7905150787 7905240340				
	7905290411				

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
	7905110355	50-320		7905110293	50-320
	7905220457	50-320		7905110299 7905110301	50-320 50-320
	7905110349 7905110316	50-320		7905110302	20-350
Auxiliary Systems Branch	7905190203 7905040316	50-320 50-322		7905230453 7905160452	50-320
Containment Systems Branch	7905020235	50-219		7905110291	50-320
Electric, Instrumentation & Control	7905110331	50-320		7905090237 7905110248	50-320 50-320
Systems Branch	7904300123	50-320		7905110304	50-320
Assistant Director for Reactor Safety	790523004B 790501019B	50-320 50-320		7905230425 7905230441	
	7905230048	50-320		7905230413	
	7905230212 7905241001	50-320 50-548		7905240316 7905230036	50-320
	7905080361	50-491		7905240316 7905220043	
Analysis Branch	7905230037 7905110061	50-320		7905230741	
Mintfills of mores	7905110226			7905160131 7904300253	50-320
	7905110061 7905110068	50-269		7905110229	50-320
	7905110074	50-269		79051600B3 79051102B6	50-320 50-320
	7905070086 7905250113			7905220442	50-320
	7905110061 7905110226			7905110381 7905220432	50-320
Core Performance Branch	79051 40056			7905210027	50-320
Reactor Bystems Branch	7905290597 7905250210	50-255		7905160018 7905110319	50-320 50-320
	7905110060	20 600		7905110285	50-320
	7905230098 7905240476			790511030B 7905110285	50-320 50-320
	7905230087	50-255		7905110308	50-320
	7905250102 7905110055			7905110289 7905110285	50-320 50-320
			Probabilistic Analysis Branch	7905110308	50-320 50-320
OFFICE OF STANDARDS DEVELOPMENT			Schoolifizers Wardara acauses	7905160002 7905230419	30-320
				7904180171 7905230443	
Office of Standards Development	7905230460 7905090350			7905140064	50-320
	7905090354			7905230449 7904180171	
	7905080035 7905230508			7905110315	50-320
	7905230511 7905080082			7905110312 7905160139	50-320 50-320
	7905020142			7905160143	50-320
	7905290018 7905250483			7905160149 7905230434	50-320
	7905230608		Environmental Effects Research Branch	7904210061	#n_nna
	7905210015 7905100036	50-320	Systems Performance Branch	7905110275 7905110273	50-320 50-320
	7904270576	50-320	Division of Reactor Safety Research	7904170091 7905110323	50-320
	7905140136 7905140132	50-320 50-320		7905140017	50-320
	7905140129	50-320		7905110343 7905110328	50-320 50-320
	7905160096 7905140134	50-320 50-320		7905170277	
	7904270178 7905250322	50-320		7905110283 7905240264	
	7905230460		Assistant Director for Advanced Reactor		50-320
Division of Engineering Standards	7905160104 7905090228	50-320 50-320	Safety Research	7905110387	50-320
	7905090219	50-320		7905110255	50-320
Engineering Metholology Standards Branch	7905300428	50-320		7905110257 7905110263	50~320 50~320
Reactor Systems Standards Branch	7905300437	50-320	Experimental Fest Reactor Sefety Research	7905110255	50-320 50-320
	7905300374 7905090210	50-320	Branch Page Reactor Safety Research	7700110200	
Assistant Director for Materials Safety	7905230411		Experimental Gas-Cooled Reactor Safety	7905110266	50-320 50-320
Branch	7905160220	50-320	Research Branch		
Fuel Process Systems Standards Branch	7905160015 7905110261	50-320 50-320	Mechanical Engineering Branch RBR Field Office, Idaho	7905110281 7905110340	50-320 50-320
Transportation & Product Standards	7905150582	30-3 <b>4</b> 0	Fuel Behavior Branch	7705220468	
Branch	7905160068	50-320		7905110351 7905110343	50-320 50-320
	7905070035	50-320	Research Support Branch	7905080405	
Assistant Director for Siting Standards	7904180175 7904180171			7905110330 7904190311	50-320
	7905140052	50-320			
Environ Protect Standards Branch	7904180171 7905160202	50-320			
	7905190107	50-320			
Occupational Health Standards Branch Radiological Health Standards Branch	7905150702 7904270088	50-320			
• • • • • • • • • • • • • • • • • • • •	7905100018	50-320			
	79041B0377 7905100034	50-320 50-320	i.		
	7905100029 79050 <del>9</del> 0231	50-530 50-320			
	7905100017	50-320			
Safeguards Standarde Branch	7904210768 7905190153	50-320			
	, rows roadd				
OFFICE OF NUCLEAR REQULATORY RESEARCH					
*					
Office of Nuclear Regulatory Research	7905110272 7905110270	50-320 50-320	i .		
•	7905110280	50-320	ı		
	7905150315 7905110277	50-331 50-320	ı		

### REPORT NUMBER INDEX

45-79/K124AF 790320328 80-329 MAREO-0340 VI N3 790310063   45-79/K124AF 7903203030   50-329 MAREO-0340 VI N3 790510014   50-376   790520151 7905020151 7905020151   7905020154 7905020151   790500035 7905090031	REPORT NUMBER	ACCESSION NUMBER	DOCKET NUMBER	OTHER REPORT NUMBER	REPORT NUMBER	ACCESSION NUMBER	DOCKET NUMBER	OTHER REPOR
49-79/HIZARF   7703200350   50-327   MRE2-0330 VI NJ   7703100151   50-327   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151   770310151			50-329					
Tempor   T		7905250530	50-329				24 A31	
79008003154 7700800315 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770080035 770	7270-RP-16A51		50~437				20-3/6	
TYPOSE00033	7905020151				MUREQ-0553	7905090048		
700509031 700509031 PNL-MUREO 29835 PNESC-0850 70050328 PNL-2931 P					NUREQ-0558	7905300300	50~320	
700300163 790310043 PM.—PAMED 28035 MRED/CP—0303 VI NA 70030045 PM.—2731 MRED 28035 PM								
TYPOS   100343	7905090163				NUREO/CP-0003			
Propositional	7905100021				MUREO/CK~0040 VI N4			
Page				PNL-2931				TREE-1267
1-7001150140								PNL-2773 VOL
7905150777 7903100777 P303100777 P303100777 P30320040 790320040 790320040 P4 P30320040 P4 P30320					NUREG/CR-0446			E-SY-INU
1905230741		7905150777						1101 MPRF 8009
7-9052078B				<b>レドー5</b> 9	NUREO/CR-0486			
1905340513				only disens of	MUREO/CR-0513			BNL-NUREO-SOFC
7903240316 7903240316 7903240316 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320 7903240320				DRMC\U990\u2012		7905030246		PNL-2419
7903240320 7903240320 7903240320 7903240320 7903240320 7903240332 7903240332 7903240333 7903240333 7903240333 7903240333 7903240333 7903240333 7903240333 7903240333 7903240333 7903240333 7903240333 7903240333 7903240337 7903240447 7903240447 7903240447 7903240447 7903240447 7903240447 7903240447 7903240447 7903240487 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330 7903240330					MUREO/CR-0539	7905140572		ORNL/NUREO-53
7903240383 7905240393 7905240399 NMEEV/CR-0534 790140970 90-219 7903240404 7905240404 7905240404 NMEEV/CR-0642 790540572 90-219 7903240313 7905240317 NMEEV/CR-0645 790540576 NMEEV/CR-0646 790540576 NMEEV/CR-0646 790540576 NMEEV/CR-0647 790540576 NMEEV/CR-0646 790540576 NMEEV/CR-0647 790540576 NMEEV/CR-0652 7905300578 NMEEV/CR-0756 790500578 NMEEV/CR-0756		7905240320	50-286		NUREO/CR-0390	7705070408		
Typosardosas					NUREO/CR-0595	7705150213		
17903240404							90-219	CHENKE IN-SAL
1903240413								RFP-2888
7903240427 7905240427 79052404027					NUREO/CR-0643	7905100145		HEDL-THE-78-75
P905240340								
Property								TREE-1324
1905240553								
7905240556 7905240556 ORNL/FIR-966 MMREO/CR-0724 7905100287 7905240576 ORNL/FIR-966 MRECVCR-0724 7905090406 7905240587 ORNL/HABRD-33 MRECVCR-0754 7905090416 50-285 0RNL/HABRD-33 MRECVCR-0754 7905090417 50-285 0RNL/HABRD-33 MRECVCR-0756 7905100251 50-285 0RNL/HABRD-33 MRECVCR-0756 7905100251 50-285 0RNL/HABRD-33 MRECVCR-0756 7905100251 50-285 0RNL/HABRD-33 MRECVCR-0756 7905100251 50-285 0RNL/HABRD-32 ORNL/HABRD-32 ORNL/HABRD-32 0RNL/HABRD-32 0RNL/				CREARE TN-292				DRNL/NUREG/TH-C
1-950340376				ODNI /FIRMAGA				
1905240987								
TYPOSIZIO   TYPO		7905240587		ORNL/HABRD-33				
TYOURS   TYOUR   TYO				ORNL/FTR-581			50-285	
790329049B								67M A-4888
790310019 790310018 7903310018 PCBE-79137 790320820 APC1-7B-8 7905070317 50-397 8ECV-7P-255 790520820 APC1-7B-8 7905070317 50-397 8ECV-7P-6-13C 790520460 BECV-7P-6-13C 790520460 BECV-7P-6-24 790520460 BECV-7P-6-24 790520460 BECV-7P-0644 790520460 BECV-7P-0644 790520460 BECV-7P-0644 790520460 BECV-7P-102A 790520460 BECV-7P-102A 790520620 BECV-7P-207 7905100630 BCCV-7P-207 7905100630 BCCV-7P-208 BECV-7P-208 790520011 BECV-7P-208 790520011 BECV-7P-208 FCV-7P-208 790520011 BECV-7P-208 790520011 BCCV-7P-208 790520011 BCCV-7P-208 790520020 BCCV-7P-208 790520020 BCCV-7P-208 790520020 BCCV-7P-208 790520020 BCCV-7P-208 PCCV-7P-208 790520020 BCCV-7P-208 PCCV-7P-208 P				CC_GBAH\ INDO			50-420	LIN WARAN
APCI-78-8 7905070317 50-397 8ECV-79-855 790520822 BAH-1609B R3 79050302025 RAH-1633 79052032036 8ECV-78-6136 790520460 BECV-79-624 790520460 BECV-79-6346 790520460 BECV-79-6346 790520040 BECV-79-6346 790520051 BECV-79-6346 790520051 BECV-79-102A 7905240051 BECV-79-102A 7905240051 BECV-79-102A 7905240051 BECV-79-102A 7905240051 BECV-79-102A 7905240051 BECV-79-102A 7905240051 BECV-79-102A 7905240551 BECV-79-103A 7905250033 BECV-79-103A 7905250033 BECV-79-103A 7905250033 BECV-79-103A 7905250033 BECV-79-103A 7905250033 BECV-79-255 7905300403 BECV-79-255 7905300403 BO-320 BECV-79-255 7905300403 BECV-79-255 7905300403 BO-320 BECV-79-256 7905300403 BO-320 BECV-79-249 7905300403 BO-320 BECV-79-258 7905300403 BO-320 BECV-79-268 7905300403 BO-320 BECV-79-268 7905300403 BO-320 BECV-79-268 7905300403 BO-320 BECV-79-268 7905300403 BO-320 BECV-79-27 PO-320 BO-320 BECV-79-280 PO-320 BO-320 BECV-79-280 PO-320 BO-320 BO-320 BECV-79-280 PO-320 BO-320 BO-3				ONIACY WHOMP			P# 040	
## 1833			50-397			7905230822		
### NIL-MUREO-23021 7908190196 50-27								
SNL_HMREO_23021   790815019		7905210138				7905230460		
9NL_NUREO-0259RZ 7705150201 50-272 8ECY-79-180A 7905240059 NL_NUREO-0259RZ 7705100235 30-300 8ECY-79-183A 7905230820 GEN_107-(6)-NP 7905200239 50-317 8ECY-79-183 790500082 GEN_107-(6)-NP 7905310189 50-336 8ECY-79-207 7905100030 50-320 GEN_107-(7)-NP 7905310189 50-336 8ECY-79-235 7905100030 50-320 GEN_108(N)-NP 7905310189 50-336 8ECY-79-235 7905100030 50-320 GEN_108(N)-NP 7905310189 50-336 8ECY-79-235 7905100030 50-320 GEN_108(N)-NP 7905310189 50-336 8ECY-79-249 7905200103 50-320 GEN_108(N)-NP 7905320081 50-320 GEN_108(N)-NP 790532081 50-320 GEN_108(N			50-27		956V-79-100A			
BRNighto-23781	9NL-NUREQ-25582					7905240059		
CEN 107-(B)-NP 7905090035 50-317 CENPD-153 3-NP 7905310189 50-336 E80-79-7 7905100517 50-336 E80-79-7 7905000517 50-326 E80-79-7 7905100517 50-326 E80-79-7 7905100517 50-326 E80-79-79 80 7905100517 50-326 E80-79-79-80 7905100517 50-326 E80-79-79-80 7905100517 50-326 E80-79-79-80 790520051 7905100294 E80-79-280 790510045 50-260 79NED269 8ECY-79-288 790520264 40-8698 E80-79-79-80 790510045 50-260 79NED269 8ECY-79-70 7905100053 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 8ECY-79-727 790520051 700520051 8ECY-79-7288 790520051 700520051 700520051 8ECY-79-7288 790520051 700520051 8ECY-79-7288 790520051 700520051 700520051 700520051 700520051 7005200051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 700520051 70052	BNL-NUREQ-23781	7905100235			SECY-79-142A	7905230820		
CENPD-153 3-NP								
CENPD-193 3-NP							EA -07A	
## 19080817			907334					
FRN-790314 790810379 IAEA-BH-178/34 7908300289 LD-79-029 7908100294 RRH-79-3-BF2 790800289 RECY-79-289 7908200281 RECY-79-289 790820029 RECY-79-289 790820083 RECY-79-289 790820083 RECY-79-272 790820083 RECY-79-272 790820083 RECY-79-272 790820083 RECY-79-272 790820083 RECY-79-272 790820083 RECY-79-28914 790820083 RECY-79-28914 790820081 RECY-A-78-10 790820081 RECY-A-78-34 79082008 RECY-A-78-34 79082008 RECY-A-78-34 79082008 RECY-A-78-34 79082008 RECY-A-78-48 79082008 RECY-A-78-48 79082008 RECY-A-78-48 79082008 RECY-A-78-48 79082082 50-320 RECY-A-78-68 79082082 50-320 RECY-A-78-10 79082082 50-320 RECY-A-78-10 79082082 50-320 RECY-A-78-10			50-375				00 000	
D-79-029		7908110379			BECY-79-249	7905240173		
High-79-3-BF2	JAEA-8M-178/34					7905220051		
NEDE-23887 790380442 8ECY-79-289 7903100418 NEDD-24149A 7903170269 50-260 79NED268 8ECY-79-270 7905100418 8ECY-79-271 790520383 NU-0A-1 7908070666 50-213 8ECY-79-271 790520383 NU-0A-1 7908070666 50-213 8ECY-79-271 790520383 NU-0A-1 790820038 8ECY-79-2891 790820037 NU-0A-1 8ECY-A-78-10 790820037 NU-0A-1 8ECY-A-78-10 790890245 50-320 NU-0A-1 8ECY-A-78-14 790890245 50-320 NU-0A-1 8ECY-A-78-47 790890242 50-320 NU-0A-1 8ECY-A-78-48 790890242 50-320 NU-0A-1 8ECY-A-78-48 790890242 50-320 NU-0A-1 8ECY-A-78-68 790890242 50-320 NU-0A-1 8ECY-A-78-68 790890242 50-320 NU-0A-1 8ECY-A-78-68 790890242 50-320 NU-0A-1 8ECY-A-78-1 7908900109 NU-0A-1 8ECY-A-78-1 790		7903110294	90-290				40-0409	
NEDO-23169A 7905100253			GG. W.G.I				40.0010	
NUREG-0040 V1 N2			20~240	79NED240				
NUREG-0040 VI N3 7908240035 BECY-A-78-10 7908090235 50-320 NUREG-0040 VI N4 7908240031 BECY-A-78-10 7908090235 50-320 NUREG-0040-01 7908240031 BECY-A-78-47 7908090222 50-320 NUREG-0040-02 7908240041 BECY-A-78-47 7908090222 50-320 NUREG-0040-02 7908240045 BECY-A-78-48 7908090222 50-320 NUREG-0040-03 7908240045 TFBP-TR-209 79080109 NUREG-0040-05 7908240053 TR-39 79080109 NUREG-0040-07/2 7908240051 TR-39 7908170282 NUREG-0040-07/2 7908240051 TR-40 7908170282 NUREG-0040-07/2 7908240051 TR-40 7908170282 NUREG-0040-77/2 790801009 50-457 VEP-FRD-32 790804047 50-280 NUREG-0380 VI N4 7908100253 NUREG-0380 VI N4 7908100253 NUREG-0380 VI N4 7908100253 NUREG-0380 VI N4 7908100253 NUREG-0380 VI N4 79080051 PB-207432 NUREG-0380 790800079 50-320 NUREG-0484 790804046 NUREG-0811 VI 790824040	MU-GA-1		50-213		8ECY-79-271	7905230553		
NURED-0040 V2 N6 7903240031 BECY-A-78-10 790890325 50-320 NURED-0040 V3 N1 7903240038 BECY-A-78-34 790890225 50-320 NURED-0040-01 7903240038 BECY-A-78-47 790890222 50-320 NURED-0040-02 7903240038 BECY-A-78-47 790890222 50-320 NURED-0040-03 7903240035 TFB-TR-209 790890109 NURED-0040-03 7903240031 TR-39 79081009 79081009 NURED-0040-07/2 7908240031 TR-30 7908170282 NURED-0040-77/2 790840031 TR-40 7908170282 NURED-0040-77/2 790840031 TR-40 7908170282 NURED-0219 790840031 TR-40 790810087 50-280 NURED-0219 790840031 TR-30 79084072 50-280 NURED-0219 790840325 NURED-0219 790840325 NURED-0219 790840325 NURED-0382 NURED-0382 790840325 NURED-0382 NURED-0382 790840329 50-320 NURED-0484 790880031 FB-267432 NURED-0484 790880031 NURED-0484 NURED-0484 790880031 NURED-0484 NURED	NUREO-0040 V1 N2					7705230537		
NUREG-0040 V3 N1 7903240028 8ECY-A-78-34 7905970246 50-320 MUREG-0040-01 7903240061 8ECY-A-78-47 7905970226 50-320 MUREG-0040-02 7903240065 8ECY-A-78-68 7905090226 50-320 MUREG-0040-03 7905240065 TF89-TR-209 7905170279 7905170279 NUREG-0040-77/2 7905240083 TR-39 7905170282 7905170282 MUREG-0040-77/2 7905240081 TR-40 7905170282 7905170282 7905170282 7905170282 79050807 WEP-FRD-32 7905087 50-457 WEP-FRD-32 7905087 50-280 MUREG-0380 V3 N4 7905100253 MCAP-9402 (NF) 7905110098 7905110098 7905087 50-390 MUREG-0484 7905080051 PB-207432 MP-THI-003 7905100290 50-300 MUREG-0811 V1 7905240406 NP-207-27 7905100290 50-300 50-300 MUREG-0811 V1 7905240406	NUREO-0040 VI N3					7905240371	E0 046	
NUREC-0040-01   7908240061   BECY-A-78-47   7908090322   50-320     NUREC-0040-02   7908240089   BECY-A-78-88   7908090322   50-320     NUREC-0040-03   7908240085   TFBP-TR-209   790896109     NUREC-0040-04   7908240081   TR-39   7908170279     NUREC-0040-77/2   7908240081   TR-40   7908170282     NUREC-0219   7809050087   50-457   VEP-FRD-32   79084072   50-280     NUREC-0380   V3 N   790810087   7908240326   MCAP-9402   NEW NORCE-0382   7908240326   MCAP-9402   NUREC-0484   79080081   FB-287432   MP-THI-DO3   790879339   50-330     NUREC-0484   790880081   FB-287432   MP-THI-DO3   790879393   50-320     NUREC-081   V1   790824046   NUREC-081   790810089   50-305	MUREO-DOAD V2 NO							
NÜREQ-0040-02 790324005B 8ECV-A-78-68 7908090226 50-320 NÜREQ-0040-03 7903240065 1769-18-209 7908090226 50-320 NÜREQ-0040-05 7903240063 18-39 7908170279 NÜREQ-0040-77/2 7908240081 18-49 7908170282 NÜREQ-0040-77/2 7908240081 18-40 7908170282 NÜREQ-0219 780905087 50-457 VEP-FRD-32 79080472 50-280 NÜREQ-0380 V3 N4 7908100253 NC-NP-9402 (NF) 7908110098 NÜREQ-0382 7908240326 NC-NP-9402 (NF) 7908110098 NÜREQ-0484 79080081 PB-267432 NP-111-003 79080939 50-330 NÜREQ-0811 V1 7908240406 NP-111-003 7908100390 50-305					BECY-A-78-47			
NUREG-0040-03 7903240065 TEB-TR-209 79051009 NUREG-0040-05 7905240063 TR-39 7905170279 NUREG-0040-77/2 7905240051 TR-40 7905170282 NUREG-0219 7507050087 50-457 VEP-FRD-32 7905170282 NUREG-0380 VS N4 7905100253 NCAP-9402 (NF) 7905110098 NUREG-0380 VS N4 7905100253 NCAP-9402 (NF) 7905110098 NUREG-0484 790500051 PB-207432 NP-THI-003 79050939 50-320 NUREG-0511 V1 7905240406 NR-THI-003 79050090 50-305								
NUREO-0040-77/2 7903240081 TR-40 7903170282 NUREO-0219 7809050087 50-457 VEP-FRD-32 7905040472 50-280 NUREO-0380 V3 N4 7908100283 N6 AP-9402 (NF) 7903110098 NUREO-0382 7903240326 NR-281-185-101 7903270399 50-390 NUREO-0484 79080081 FB-287432 NR-181-003 790509039 50-390 NUREO-0811 V1 7908240406 NR-181-003 790509039 50-305	NUREQ-0040-03	7905240065						
NUREG-0219	NUREQ-0040-08	7905240053						
MUREO-03B0     V3 N4     7908100283     MCAP-9402 (NF)     790810028       NUREO-03B2     7908240326     MREO-03B2     790807039     50-390       NUREO-04B4     7908080051     FB-207432     MR-THI-003     790807039     50-320       NUREO-05I1     V1     7908240406     XN-NF-79-27     7908100290     50-305			60-A57		TR-40	7905170282	80-220	
NUREG-0382 7905240326 SH28-1-89-101 7905270399 50-390 NUREG-0484 7905080051 PB-207432 NP-THI-003 7905090339 50-320 NUREG-0811 V1 7905240406 NP-THI-003 7905090339 50-320			UU-447		MCAP-PAGO (NE)		20	
MMRE9-0484 7905080051 F8-287432 MP-TMI-003 7905090339 50-320 MMRE9-0511 V1 7905240404 XN-NF-79-27 7905100290 50-305						7905290399	50~390	
N/REG-0511 V1 7905240406 XN-NF-79-27 7905100290 50-305	NUREO-0484	7905080051		PB-207432	E00-1NT-4M	7905090339		
NUREO-0511 V2 7900240413 XN-NF-79-47 7900210179 50-219	NUREO-0511 VI							
	NUREQ-0511 V2	7900240413			XN-NF-79-47	7905210179	20-514	

		·

#### APPENDIX A

#### **DEFINITIONS OF DOCKET 50 CATEGORIES**

#### A. Application/Construction Stage Documents and Correspondence

This category follows the application from submission to the day preceding the issuance of an operating license. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are:

- 1. Correspondence and documents relating to unresolved design and construction issues.
- 2. Meeting announcements and summaries of meeting discussions on issues of item 1.
- 3. Correspondence regarding Preliminary and Final Safety Analysis Reports.
- 4. NRC questions, requests for additional information, and applicant responses.
- 5. Applicant's Quality Assurance Manual.
- 6. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 7. Federal Register notices that do not apply to other categories.
- 8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.).
- 9. Scheduling of license application submission or review.
- 10. Reports of site visits.
- 11. Backup technical documents (i.e., topical reports) submitted in support of the application.
- 12. Early site review information.
- 13. Construction Permit, amendments and correspondence relating to construction permit,
- 14. Environmental review information.
- 15. Construction permit.

#### B. Utility Preliminary Safety Analysis Report (PSAR) and Amendments

This category is strictly limited to the items listed below. All related c Category A.

- 1. Preliminary Safety Analysis Report (PSAR) submitted by
- 2. Amendments and changes to the PSAR.
- 3. Transmittal letters.
- 4. Letters acknowledging receipt.
- 5. Hazards Summary Report submitted by utility (now designated by utility (now designated)

- 6. Safety Analysis Report submitted by utility (now designated PSAR).
- 7. Certificates of Service of PSAR.

#### C. Utility Environmental Report (ER), Amendments and Correspondence

- 1. Environmental Report (ER) submitted by the utility.
- 2. Amendments and supplements to the ER.
- 3. Transmittal letters.
- 4. Information on scheduling of submittal or review of ER.
- 5. NRC questions, requests for additional information, and applicant responses.
- 6. Federal Register notice citing availability of items 1 and 2.
- 7. Correspondence relating to the review of ER.
- 8. Meeting announcements or reports of meetings where the primary subject of discussion is the ER.

### D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), Supplements and Correspondence

- 1. Draft and Final Environmental (Impact) Statements (DES and FES).
- 2. Supplements to DES and FES.
- 3. Correspondence relating to the DES or FES.
- 4. Comments from other federal, state, and local government agencies.
- 5. Transmittal letters.
- 6. Documents related to NRC review of environmental issues or of ER obtained for purposes of writing the environmental statements.
- 7. Backup technical documents submitted in connection with above.
- 8. Notices of availability of above.
- 9. Draft of detailed statement,

#### VRC Safety Evaluation Report (SER), Supplements and Correspondence

' Safety Evaluation Report (SER).

o SER.

- 4. Notices advising of the availability of 1 and 2.
- 5. Information on scheduling of SER submittals and review.
- 6. Requests for additional information for use in preparing SER; responses to such requests.
- 7. Meeting announcements or reports of meetings where the primary subject of discussion is the safety review or safety evaluation.
- 8. Transmittal letters.
- 9. Comments from other agencies relative to safety review.
- 10. NRC-AEC Hazard Analysis Reports (now designated SER).

#### F. Security, Medical, Emergency, and Fire-Protection Plans

All plans in this category are submitted separately. Information submitted for the PSAR or FSAR is excluded.

- 1. Correspondence relating to plans.
- 2. Supplements, changes, and revisions to plans.
- 3. Fire Hazard Protection Plan and Surveys.

#### G. Adjudicatory Correspondence

This category contains all documents on hearings, Atomic Safety and Licensing Board (ASLB) review, and opposition except word-for-word transcripts of ASLB hearings (Category T) and antitrust hearings (Category N).

- 1. ASLB hearing and review documents.
- 2. Correspondence to and from intervenors.
- 3. Correspondence to and from persons writing in opposition to the facility. Those writing for information or in support of the facility are in category H.
- 4. Board orders and decisions.
- 5. Requests to make appearances at hearings.
- 6. Transmittal of supporting documents (i.e., SER, FES) to the board.
- 7. Federal Register notices regarding hearings.
- 8. Requests for a hearing.
- 9. Petitions from participants (including petition for request for extension
- 10. Corrections to transcripts.
- 11. Professional qualifications, if presented at a hearing.

- 12. Memorandums and orders authorizing issuance of license, changes, and other issuances by the Atomic Safety and Licensing Board.
- 13. Hearing index.

#### H. General correspondence

This category includes documents with little or no bearing on the status of the application or license. Items that have no substantive technical content or meaning for the status of the license or application are included.

- 1. Qualification statements of new employees.
- 2. Change of address notifications.
- 3. Changes in organization.
- 4. Changes in service lists, "Certificate of Service" documents (without a document attached).
- 5. NRC requests to applicant for additional copies of documents.
- 6. Correspondence from the public in support of or requesting information about the facility.

1

- 7. Letters of "concern" (NOT "opposition") and response thereto.
- 8. Correspondence on strictly administrative matters.
- 9. Correspondence regarding the local Public Document Room.
- 10. Memoranda to Public Document Room regarding withholding a document (unaccompanied by that document).
- 11. Press releases from applicant.
- 12. Any other material that fits the criteria given above.
- 13. Professional qualifications (resumes).
- 14. Congressional correspondence and constituent letters.

#### ormation

- 1. Company annual reports.
- 2. Separately submitted financial information and related correspondence.

#### J. Insurance and Indemnity Information

- 1. All correspondence and documentation regarding indemnity and insurance.
- 2. Endorsements to insurance policies.
- 3. NELPIA Nuclear Energy Liability Property Insurance information.

#### K. Utility Final Safety Analysis Report (FSAR) and Amendments

This category is strictly limited to the items listed below. All related correspondence falls in category A or P.

- 1. Final Safety Analysis Report (FSAR).
- 2. Amendments and changes to the FSAR.
- 3. Transmittal letters.
- 4. Letters acknowledging receipt of items.
- 5. Hazards Final Summary Report (now designated FSAR).
- 6. Certificates of Service of FSAR.

#### L. Limited Work Authorization and Related Correspondence

This category is limited to items issued before the construction permit is granted.

- 1. Limited Work Authorizations.
- 2. Environmental exemptions.
- 3. Correspondence relating to 1 and 2.
- 4. All information concerning site preparation prior to the issuance of a construction permit.

#### M. Antitrust Correspondence

- 1. All material concerning antitrust except hearing transcripts (category N)
- All material marked with an A immediately following the docket number. The A signifies
  antitrust proceedings.

#### N. Antitrust Hearing Transcripts

This category contains only word-for-word transcripts of hearings in antitrust cases they will be marked with an A following the docket number. Related in category M.

#### O. Advisory Committee on Reactor Safeguards (ACRS) Reports and Correspondence

- 1. Correspondence and letter reports relating to ACRS reviews
- 2. Correspondence from ACRS
- 3. Announcements of ACRS meetings

- 4. Transmittal letters to ACRS
- 5. ACRS reports.

#### P. Operating License Stage Documents and Correspondence

This file assumes the position of the application file for general technical items dated on or after the issuance of the operating license. It includes:

- 1. Operating license, amendments, proposed amendments, and changes.
- 2. Technical specifications and changes.
- 3. Announcements of issuance of 1 and 2.
- 4. Transmittal letters.
- 5. All general technical correspondence relating to technical specifications or operating license.
- License conditions.
- 7. Operator licenses or administrative information bearing on the licensing of operators.
- 8. Meeting announcements or summaries of discussions where the main subject is technical specifications, operating license, or any technical issue arising after the issuance of the operating license.
- 9. Correspondence regarding codes (ASME), regulations, laws, or changes in policy that may affect plant operation or bear on the operating license.
- 10. Information on the Standard Review Plan (SRP).
- 11. Results of surveys or tests conducted in accordance with the technical specifications (NOT periodic reports, which fall in category R).
- 12. Requests for issuance of operating license.
- 13. Requests for copies of items 1 and 2 and responses.
- 14. Correspondence on generic technical issues.
- 15. Owner's group meeting announcements and reports.
- 16. Orders for modification of license.
- 17. Requests for extension date of license or license modification.
- 18. Quality assurance information.

Environmental matters (technical).

ore cooling system.

vaste information.

#### Q. Inspection Reports, IE Bulletins and Correspondence

- 1. Inspection reports.
- 2. Bulletins and Circulars of NRC Office of Inspection and Enforcement (IE).
- 3. Responses by applicant to IE correspondence.
- 4. Applicant's determination of proprietary nature of inspection reports.
- 5. Letters concerning areas of noncompliance.
- 6. Any correspondence relating to inspection and enforcement that does not specifically relate to incidents as defined in category S.
- 7. In-service inspections.
- 8. Regulatory Operations (RO) Bulletins.

#### R. Periodic Operating Reports and Related Correspondence

This category includes periodic reports of a routine nature.

- 1. Monthly, semiannual, or annual reports (other than financial).
- 2. Periodic environmental monitoring, effluent testing, or similar reports.
- 3. Gray Book Information.
- 4. Correspondence or other documents relating to the above listed items.

#### S. Reportable Occurrences, LERs and Related Correspondence

This category contains all materials relating to abnormal, unusual, reportable, nonroutine, or 10 CFR 50.55e occurrences. This includes:

- 1. All 24-hour, 10-day, 30-day, interim, final, and followup reports on these events.
- 2. Other related documents.

NOTE: Also called licensee event reports, incident reports, etc.

#### T. Hearing Transcripts on Non-Antitrust Matters

This category contains only word-for-word transcripts in non-antitrust matters. Related correspondence is in category G.

	•			
r				
				,
				A

NRC FORM 335 U.S. NUCLEAR REGULATORY COMMISSION		1. REPORT NUMBER	Assigned by DDCI
BIBLIOGRAPHIC DATA SHEET		NUREG-0540 Vo	1. 7 No. 5
4. TITLE AND SUBTITLE (Add Volume No., if appropriate)		2, (Leave blank)	
Title List of Documents Made Publicly Available	≘	3. RECIPIENT'S ACCE	SSION NO.
7, AUTHOR(S)		5. DATE REPORT CO	MPLETED
		June	1979
9, PERFORMING ORGANIZATION NAME AND MAILING ADDRESS (Include a	Zip Code)	DATE REPORT ISS	
Division of Technical Information and Document	Control	MONTH June	1979
U.S. Nuclear Regulatory Commission Washington, D. C. 20555		6. (Leave blank)	
		8. (Leave blank)	
12. SPONSORING ORGANIZATION NAME AND MAILING ADDRESS (Include	Zip Code)	10. PROJECT/TASK/W	ORK UNIT NO.
Division of Technical Information and Document	Control		onk on the
U.S. Nuclear Regulatory Commission Washington, D. C. 20555		11. CONTRACT NO	
13. TYPE OF REPORT	PERIOD COVER	ED (Inclusive dates)	
Monthly	May I tó	May 31, 1979	
15. SUPPLEMENTARY NOTES		14. (Leave blank)	
This document is a monthly publication con information received and generated by the includes (1) docketed material associated plants and other uses of radioactive mater material received and generated by NRC per regulatory agency. The docketed informati merly issued through U.S. DOE's Technical the title Power Reactor Docket Information replaces PRDI, which will no longer be pre Personal Author Index, Corporate Source In	U.S. NRC. Twith civiliatials and (2) tinent to it on includes Information (PRDI). The pared. It is	his information In nuclear power I nondocketed Is role as a Information for Center under Is document Is indexed by a	` `-
17 KEY WORDS AND DOCUMENT ANALYSIS	17a. DESCRIPTOF	as	
	140 00 00 00		la. 110 07 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7
18. AVAILABILITY STATEMENT	19. SECURIT	Y CLASS (This report)	21. NO. OF PAGES
Unlimited	20. SECURIT	Y CLASS (This page)	22. PRICE